

**Palm Beach County Fleet Management
Asset Maintenance History**

10189423 2012 TORO GRNDSMSTR 7200 Mower, Zero Turn Radius (Ztr) 72 In.

Workorder: 1208385 **Meter:** 6 **In Date:** 09/05/2012 **Closed:** 09/05/2012
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1309880 **Meter:** 250 **In Date:** 09/30/2013 **Closed:** 10/04/2013
Problem: P.M.SERVICE

- pm
 - svc hyd sys inspect lines hoses correct fluid level
 - wash eq
 - Shop Supplies

Parts List	Qty
Air Filter	1.00
Napagold Fuel Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Aw68 Bulk Sr	2.00
Shop Supplies	1.00

Hours 6.00 Labor: 360.00 Parts: 53.36 Total: 413.36
 :

Workorder: 1311605 **Meter:** 286 **In Date:** 11/18/2013 **Closed:** 11/27/2013
Problem: right side fuel leak

- C/c Fuel Leak. Verify Fuel Leak On Fuel Tank.clean&patch Crack On Tank.
 - Shop Supplies

Parts List	Qty
Napa Gas Tank Rep Kit	1.00
Shop Supplies	1.00

Hours 2.00 Labor: 120.00 Parts: 16.63 Total: 136.63
 :

Workorder: 1407852 **Meter:** 456 **In Date:** 08/11/2014 **Closed:** 08/14/2014
Problem: pm / fuel leak right side

- Pm
 - Perform Hyd Service
 - Cooling sys service
 - Ck for fuel leak, remove and clean area on right side tank. Leak from tank under manufacture warranty.
 - Clean, wash under deck
 - Shop Supplies

Parts List	Qty
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15-40 Oil	4.00
Napagold Fuel Filter	1.00
Aw68 Hydro Fluid Hydr	2.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00

Hours 7.00 Labor: 420.00 Parts: 57.14 Total: 477.14
 :

Workorder: 1410490 **Meter:** 556 **In Date:** 10/21/2014 **Closed:** 10/30/2014
Problem: flat tire small front right and back

- flat tire rr two front tires grease handle mount add n2
 - verify aire filter cover broken in stalll new filter cover
 - repair lr tire
 - Shop Supplies

Parts List	Qty
15-600-6 Nhs Str Rib 04	2.00
Air Cleaner Cover Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 3.00 Labor: 180.00 Parts: 197.70 Total: 377.70
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504293 **Meter:** 684 **In Date:** 04/27/2015 **Closed:** 04/30/2015
Problem: replace deck wheels on mower deck hard plastic

- replace anti scalp wheels	Parts List	Qty
- Shop Supplies	Nut	1.00
	Spacer-roller	1.00
	Roller,deck	1.00
	Bolt	1.00
	Flange Nut Ni	3.00
	Screw	3.00
	Tube-spanner	3.00
	Roller Scalp	3.00
	Tube Spacer	3.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 150.86
:		Total: 240.86

Workorder: 1504796 **Meter:** 700 **In Date:** 05/12/2015 **Closed:** 05/12/2015
Problem: scalping wheels back left on deck

- ck scalp wheel repair anti scalp wheel bracket	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1505435 **Meter:** 711 **In Date:** 05/29/2015 **Closed:** 06/04/2015
Problem: left front tire slow leak

- ck small leak replace two front tires hand mount add n2	Parts List	Qty
- Shop Supplies	Tire	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 68.78
:		Total: 188.78

Workorder: 1506537 **Meter:** 756 **In Date:** 06/30/2015 **Closed:** 07/08/2015
Problem: belt is smoking left rear tire slow leak plesasse ck tire pressure in all

- repair left rear tire	Parts List	Qty
- ck belt is smoking remove belt cover test drive inspect belts and pulley and was unable to verify concern at this time lube on spindles	Shop Supplies	1.00
- Shop Supplies		
Hours 2.50	Labor: 150.00	Parts: 2.00
:		Total: 152.00

Workorder: 1507381 **Meter:** 790 **In Date:** 07/23/2015 **Closed:** 07/30/2015
Problem: left front tire off bead

- repair left front tire	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1507567 **Meter:** 790 **In Date:** 07/29/2015 **Closed:** 07/30/2015
Problem: repair flat tire

	Parts List	Qty
- ck flat tire repair fl tire add n2		
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00 Parts: 2.00	Total: 62.00
:		

Workorder: 1508207 **Meter:** 824 **In Date:** 08/14/2015 **Closed:** 08/25/2015
Problem: P.M.SERVICE,FRONT TIRES,DECK NEEDS LEVELED,SCALPING WHEELS.

	Parts List	Qty
- pm		
- ck front tires rr front tires	Napagold Air Filter	1.00
- ck deck needs leveled scalp wheels ets	Napagold Fuel Filter	1.00
- svc hyd sys	Napagold Oil Filter	1.00
- wash eq	15w40 Bulk South Reg	4.00
- Shop Supplies	15-600-6 Nhs Str Rib 04	2.00
	Aw68 Bulk Sr	2.00
	Napa Hydraulic Filtr	1.00
	Nut	1.00
	Spacer-roller	1.00
	Roller,deck	1.00
	Bolt	1.00
	Flange Nut Ni	2.00
	Screw	1.00
	Tube-spanner	2.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	Yoke Clevis	2.00
	Tbar	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.00	Labor: 660.00 Parts: 348.95	Total: 1,008.95
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603529 **Meter:** 1089 **In Date:** 04/04/2016 **Closed:** 04/20/2016
Problem: Will not engage blades.Shut off.Panel cover wingnuts scalping right rear wheel.

<ul style="list-style-type: none"> - C/c blades wont engage.replace center spindle,belts,air cleaner assemble etc.. - Verify starts sometimes.found bad control module.replace module and test drive. - Test battery bad.check charging system.replace battery. - Wash equipment. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Control Module Assy Battery Air Cleaner Assy Knob Nut Retainer Double Spindle Assy V-belt Idler Pulley Flange Nut Ni Tube-spanner Roller Scalp Tube Spacer Screw Shop Supplies Freight Charge 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 2.00 2.00 2.00 2.00 2.00 1.00 1.00 	
Hours 6.75 :	Labor: 405.00	Parts: 1,484.54	Total: 1,889.54

Workorder: 1608513 **Meter:** 1274 **In Date:** 08/16/2016 **Closed:** 08/30/2016
Problem: PM Service.Drive shaft universal joint broken.Check tires,belt pulley and brakes.

<ul style="list-style-type: none"> - P.m.service - C/c Tires. Replace 4 Tires,mount Add N2 - C/c Drive Shaft C/k All. R/r Broken Drive Shaft,gear Box Brackets And Bushings,unseize Tensioners,lube All Pulleys & fittings,anti-scalp Wheels.ets...,test Mov. - C/c Brake Not Holding, Adjust Parking Brake. - Wash Equipment For Service And Repairs - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Fuel Filter 15w40 Bulk South Reg Napagold Oil Filter 24-1200-12b Turf M Carl Tire Tube Spacer Roller Scalp Tube-spanner Screw Flange Nut Ni Gearbox Bracket Rh Rubber Mount Bolt Gearbox Bracket Lh Driveshaft Switch Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 4.00 1.00 2.00 2.00 2.00 2.00 2.00 2.00 2.00 1.00 3.00 3.00 1.00 1.00 2.00 1.00 	
Hours 12.00 :	Labor: 720.00	Parts: 1,516.96	Total: 2,236.96

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1703390 **Meter:** 1507 **In Date:** 04/05/2017 **Closed:** 04/17/2017
Problem: ADJUST SEAT, TWO FRONT TIRES, ADJUST HAND BRAKE,- FRONT DECK ROLLERS.

- C/c front tires.replace two front tires.hand mount,add N2.grease and repack bearings.	Parts List	Qty
	Nut	1.00
- C/c all rollers.replace all anti scalp wheels,rollers and hardware.replace seat assm.	Spacer-roller	1.00
	Roller	1.00
- C/c adjust brake.verify bad proximity switch on E-brake.replace rear caliper/pads assembly.	Bolt	1.00
- Shop Supplies	Roller,deck	1.00
	Shaft,roller	1.00
	Seat	1.00
	Proximity Switch	1.00
	Left Brake Caliper	1.00
	Right Brake Caliper	1.00
	Tire	2.00
	Flange Nut Ni	2.00
	Screw	2.00
	Tube-spanner	2.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 2,464.27
:		Total: 2,884.27

Workorder: 1704388 **Meter:** 1533 **In Date:** 05/01/2017 **Closed:** 05/15/2017
Problem: Mower deck wheels

- Replace two anti scalp rollers.	Parts List	Qty
- Shop Supplies	Roller Scalp	2.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 31.67
:		Total: 91.67

Workorder: 1705604 **Meter:** 1560 **In Date:** 06/06/2017 **Closed:** 06/19/2017
Problem: Check /change belts and pulleys.Check deck wheels.

- C/c wheels and belt.unseize tensioners.r/r two deck belts.replace two scalp wheels.lube all.	Parts List	Qty
	V-belt	1.00
- Shop Supplies	V-belt	1.00
	Roller Scalp	2.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 179.14
:		Total: 419.14

Workorder: 1706539 **Meter:** 1568 **In Date:** 07/03/2017 **Closed:** 07/17/2017
Problem: RIGHT SIDE CUT TOO LOW.

- C/c right side scalps when cut on 1.adjust deck .test mow.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709050 **Meter:** 1657 **In Date:** 09/20/2017 **Closed:** 09/29/2017
Problem: P.M.SERVICE, TIRES,MOWER DESK CUT UNEVEN

- Pm Service.	Parts List	Qty
- Replace two front tires. Hand mount grease and add N2	Napagold Air Filter	1.00
- Service hyd.system.inspect all.correct fluid level	Napagold Fuel Filter	1.00
- Wash equipment	Napagold Oil Filter	1.00
- C/c deck cuts uneven.verify operating on lower than 2 inch.will scalp grass.	15w40 Bulk South Reg Tire	4.00 2.00
- Shop Supplies	Napa Hydraulic Filtr Aw68 Bulk Sr 15-600-6 Nhs Str Rib 04 Shop Supplies Tire Disposal Fee	1.00 2.00 2.00 1.00 2.00
Hours 8.25	Labor: 495.00	Parts: 204.00 Total: 699.00

Workorder: 1711607 **Meter:** 1755 **In Date:** 11/28/2017 **Closed:** 12/11/2017
Problem: Need battery

- Verify dead battery.test battery bad.replace.check charging system.	Parts List	Qty
- Shop Supplies	Battery Battery Shop Supplies	1.00 1.00 1.00
Hours 0.75	Labor: 45.00	Parts: 228.79 Total: 273.79

Workorder: 1801379 **Meter:** 1812 **In Date:** 02/05/2018 **Closed:** 02/12/2018
Problem: Deck belt broken.

- Verify needs two front tires.mount and add N2.grease and correct all N2 levels.	Parts List	Qty
- C/c deck belt.replace right hand deck belt.two rear scalp wheels and neutral safety switch on lever.	15-600-6 Nhs Str Rib 04 V-belt Switch Roller Scalp Shop Supplies Tire Disposal Fee	2.00 1.00 1.00 2.00 1.00 2.00
- Shop Supplies		
Hours 6.00	Labor: 360.00	Parts: 270.00 Total: 630.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1805092 **Meter:** 1916 **In Date:** 05/16/2018 **Closed:** 06/18/2018
Problem: Check PTO.. HYD deck wont syay up.Front left tire flat.

	Parts List	Qty
- C/c left tire.replace front left tire.mount,grease and add N2		
- C/c check Pto.replace Pto engage solenoid.correct hyd.fluid level.	15x6.00-6	1.00
	Aw68 Bulk Sr	2.00
- C/c deck wont stay up.verify deck lift valve falling down.replace internal seat.reseal valve assm.	Air Cleaner Assy	1.00
	Seal Kit	1.00
- Replace worn air cleaner assembly.	Disc	1.00
- Wash eqiipment.	Solenoid Assy	1.00
- Shop Supplies	Seat	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 9.00	Labor: 540.00	Parts: 813.83
:		Total: 1,353.83

Workorder: 1806464 **Meter:** 1942 **In Date:** 06/25/2018 **Closed:** 07/23/2018
Problem: Hydraulic oil leak.

	Parts List	Qty
- C/c Hyd.leak.found leaking Hyd. hose from cooler to lift valve.replace hose and correct fluid level.		
	Aw68 Bulk Sr	3.00
- Shop Supplies	Hyd Hose	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 3.00	Labor: 180.00	Parts: 146.27
:		Total: 326.27

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810666 **Meter:** 2093 **In Date:** 10/16/2018 **Closed:** 11/29/2018
Problem: PM Service.Check tires and bent wheel. Deck dropping by self. Need leveling

	Parts List	Qty
- Pm Service.		
- C/c Tires and front wheel bent.replace two rear tires.one tire and wheel assembly.	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
- C/c deck falling wont stay up.service Hyd system.replace filter.replace lift valve seat and o-rings.reassemble and correct fluid level.	15w40 Bulk South Reg	4.00
	Napagold Oil Filter	1.00
- C/c Deck needs level and wheels ,chute.replace all anti scalp wheel,chute,adjust deck linkage.replace tensioner arm and pulley.test mow.	15-6.00x6 Ribbed Tire	1.00
	15-600-6 Nhs Str Rib 04	1.00
- Wash equipment	24-1200-12b Turf M Carl	2.00
	O-ring	4.00
- Verify battery bad.recharge and tst good.	Napa Hydraulic Filtr	1.00
- Found loose belt on alternator.tighten charging system now working properly.	Aw68 Bulk Sr	2.00
- Shop Supplies	Tube Spacer	2.00
	Roller Scalp	2.00
	Tube-spanner	2.00
	Screw	2.00
	Shaft,roller	1.00
	Roller	1.00
	Bolt	1.00
	Roller,deck	1.00
	Spacer-roller	1.00
	Nut	1.00
	Idler Arm Assy	1.00
	Pulley	1.00
	Idler Spacer	1.00
	Locknut	4.00
	Nut	4.00
	Nut Retainer	2.00
	Knob	2.00
	Deflector	1.00
	O-ring	1.00
	Poppet	1.00
	Washer	2.00
	O-ring	2.00
	O-ring	1.00
	Seat	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	3.00
	Freight Charge	1.00
	Freight Charge	1.00

Hours 16.75 Labor: 1,122.2 Parts: 1,418.27 Total: 2,540.52
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1908019 **Meter:** 2365 **In Date:** 08/02/2019 **Closed:** 08/19/2019
Problem: The belts came off.ASAP.

- Replace front tires and bearing/seals in left front wheel.both front tires.	Parts List	Qty
	15-600-6 Nhs Str Rib 04	2.00
- Replace two drive belts and gear box mounting bushings.remove drive shaft and lube slip yoke.lube tensioner.	Spacer	2.00
	Bearing	2.00
- Shop Supplies	Seal	2.00
	Bolt	3.00
	Washer	3.00
	Rubber Mount	3.00
	V-belt	1.00
	V-belt	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 4.75	Labor: 318.25	Parts: 385.08
:		Total: 703.33

Workorder: 1909158 **Meter:** 2379 **In Date:** 09/05/2019 **Closed:** 09/16/2019
Problem: Replace front wheel.

- C/c replace front wheel.r/rfront left tire and wheel asm.	Parts List	Qty
- Shop Supplies	15-6.00x6 Ribbed Tire	1.00
	Shop Supplies	1.00
Hours 0.75	Labor: 50.25	Parts: 348.81
:		Total: 399.06

Workorder: 1912641 **Meter:** 2379 **In Date:** 12/10/2019 **Closed:** 12/10/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00