

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 744263 **Problem:** PRE-DELIVERY INSPECTION

| Meter Reading: 0 | Labor | Parts |
|---------------------------|-----------------------------|-------------|
| In Date: 09/18/2007 | Hours | Description |
| Close Date: 09/18/2007 | | Quantity |
| - Pre-Delivery Inspection | 2.00 | |
| Parts Charge: 0.00 | Labor Charge: 110.00 | |

Workorder: 744627 **Problem:** MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

| Meter Reading: 0 | Labor | Parts |
|--|---------------------------|-------------|
| In Date: 09/26/2007 | Hours | Description |
| Close Date: 09/26/2007 | | Quantity |
| - Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable. | 0.01 | |
| Parts Charge: 0.00 | Labor Charge: 0.55 | |

Workorder: 744799 **Problem:** MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

| Meter Reading: 0 | Labor | Parts |
|--|----------------------------|-------------|
| In Date: 09/28/2007 | Hours | Description |
| Close Date: 09/28/2007 | | Quantity |
| - Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable. | 1.00 | |
| Parts Charge: 0.00 | Labor Charge: 55.00 | |

Workorder: 748355 **Problem:** FLAG POLE

| Meter Reading: 0 | Labor | Parts |
|---|----------------------------|--------------------|
| In Date: 12/10/2007 | Hours | Description |
| Close Date: 12/13/2007 | | Quantity |
| - Fabricate,Weld,Install Flag Pole Assy. On Deck & Paint. | 1.50 | SHOP SUPPLIES 1.00 |
| - Shop Supplies | | |
| Parts Charge: 2.00 | Labor Charge: 90.00 | |

Workorder: 833318 **Problem:** 9950

| Meter Reading: 0 | Labor | Parts |
|--|----------------------------|--------------------|
| In Date: 01/28/2008 | Hours | Description |
| Close Date: 01/29/2008 | | Quantity |
| - Lubed Complete. Attached To 10155252 | 1.00 | SHOP SUPPLIES 1.00 |
| - Shop Supplies | | |
| Parts Charge: 2.00 | Labor Charge: 60.00 | |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

| | | | | |
|----------------------------|-------------------------------|----------------------|-----------------------------|-----------------|
| Workorder: 842299 | Problem: BLADES | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 08/01/2008 | Close Date: 08/12/2008 | Hours | Description | Quantity |
| - Replace Blades | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | W45327 BLADE JOHN DEERE MX5 | 2.00 |
| Parts Charge: | 58.28 | Labor Charge: | 60.00 | |

| | | | | |
|---|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 842727 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 08/12/2008 | Close Date: 08/21/2008 | Hours | Description | Quantity |
| - Lubed Complete.Ck Gear Box Oil Attached To 10155252 | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 | |

| | | | | |
|-----------------------------------|-------------------------------|----------------------|------------------------------------|-----------------|
| Workorder: 933767 | Problem: 9103 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 02/09/2009 | Close Date: 02/11/2009 | Hours | Description | Quantity |
| - Pm Service Attached To 10155253 | | 2.00 | 12345841 GEAR OIL SYNTHETIC 75W-90 | 2.00 |
| - Shop Supplies | | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 34.41 | Labor Charge: | 120.00 | |

| | | | | |
|----------------------------|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 941559 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 08/04/2009 | Close Date: 08/04/2009 | Hours | Description | Quantity |
| - On Site Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 | |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1004348 **Problem:** 9950

| Meter Reading: 0 | | Labor | Parts | |
|---------------------------|------------------------|----------------------------|---------------|----------|
| In Date: 04/27/2010 | Close Date: 04/29/2010 | Hours | Description | Quantity |
| - On Site Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | |

Workorder: 1005627 **Problem:** repair tail wheel

| Meter Reading: 0 | | Labor | Parts | |
|---------------------------|------------------------|----------------------------|---------------|----------|
| In Date: 05/28/2010 | Close Date: 06/03/2010 | Hours | Description | Quantity |
| - Repair Tail Wheel | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | |

Workorder: 1007039 **Problem:** replace skids

| Meter Reading: 0 | | Labor | Parts | |
|-------------------------------|------------------------|-----------------------------|-------------------|----------|
| In Date: 07/06/2010 | Close Date: 07/15/2010 | Hours | Description | Quantity |
| - Cut Weld And Fab Deck Skids | | 7.50 | WOODS SKID | 2.00 |
| - Test And Transport | | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | T-235 GRAY PRIMER | 1.00 |
| | | | FREIGHT | 1.00 |
| | | | 1360 GREEN PAINT | 1.00 |
| Parts Charge: 498.47 | | Labor Charge: 450.00 | | |

Workorder: 1008305 **Problem:** 9950

| Meter Reading: 0 | | Labor | Parts | |
|---------------------------|------------------------|----------------------------|---------------|----------|
| In Date: 08/03/2010 | Close Date: 08/05/2010 | Hours | Description | Quantity |
| - On Site Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: 2.00 | | Labor Charge: 60.00 | | |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1100616

Problem: pm service

| Meter Reading: 0 | Labor | Parts | |
|---------------------------------|--------|------------------------------------|----------|
| In Date: 01/14/2011 | Hours | Description | Quantity |
| - Pm Service | 4.50 | W45327 BLADE JOHN DEERE MX5 | 2.00 |
| - Replace Flag ,Pole And Holder | | W38054 BLADE BOLT JOHN DEERE | 2.00 |
| - Replace Blades | | W50958 BLADE LOCKNUT JOHN DEERE | 2.00 |
| - Shop Supplies | | W38627 BLADE WASHER JOHN DEERE MX5 | 2.00 |
| | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 204.85 | Labor Charge: | 270.00 |

Workorder: 1200235

Problem: P.M.

| Meter Reading: 0 | Labor | Parts | |
|----------------------|--------|------------------------------------|----------|
| In Date: 01/09/2012 | Hours | Description | Quantity |
| - Pm Service | 4.00 | SHOP SUPPLIES | 1.00 |
| - Replace Blades | | W45327 BLADE JOHN DEERE MX5 | 2.00 |
| - Replace Flag | | W38054 BLADE BOLT JOHN DEERE | 2.00 |
| - Shop Supplies | | W38627 BLADE WASHER JOHN DEERE MX5 | 2.00 |
| | | W50958 BLADE LOCKNUT JOHN DEERE | 2.00 |
| | | 8610 SAFETY FLAG (PAR-AIDE) | 1.00 |
| Parts Charge: | 241.94 | Labor Charge: | 240.00 |

Workorder: 1300517

Problem: 9950

| Meter Reading: 0 | Labor | Parts | |
|----------------------|-------|----------------------|----------|
| In Date: 01/14/2013 | Hours | Description | Quantity |
| - On Site Lube | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1302667

Problem: 9103

| Meter Reading: 0 | Labor | Parts | |
|----------------------------|--------------|-----------------------|-----------------|
| In Date: 03/19/2013 | Hours | Description | Quantity |
| - Pm Service | 3.50 | SHOP SUPPLIES | 1.00 |
| - Replace Blades | | W38627 BLADE WASHER J | 2.00 |
| - Shop Supplies | | W45327 BLADE JOHN DEE | 2.00 |
| | | W50958 BLADE LOCKNUT | 2.00 |
| | | W38054 BLADE BOLT JOH | 2.00 |
| | | 1/4 INCH LINK | 2.00 |
| Parts Charge: | 218.93 | Labor Charge: | 210.00 |

Workorder: 1306779

Problem: 9950

| Meter Reading: 0 | Labor | Parts | |
|----------------------------|--------------|----------------------|-----------------|
| In Date: 07/08/2013 | Hours | Description | Quantity |
| - On Site Lube | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

Workorder: 1311244

Problem: Broken Drive shaft

| Meter Reading: 0 | Labor | Parts | |
|----------------------------|--------------|----------------------|-----------------|
| In Date: 11/05/2013 | Hours | Description | Quantity |
| - R&R Pto Shaft | 4.00 | PTO UNIVERSAL SHAFT | 1.00 |
| - Fm To Mosquito Control | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 1,378.68 | Labor Charge: | 240.00 |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1401266

Problem: P.M.

| Meter Reading: 0 | Labor | Parts | |
|---|--------|------------------------|----------|
| In Date: 02/06/2014 | Hours | Description | Quantity |
| - Pm | 6.00 | 678131 1-4IN GRADE 4 | 33.00 |
| - Replace Flag Pole | | SHOP SUPPLIES | 1.00 |
| - Remove Old Chain Gaurd And Replace With New Chain | | 12345841 GEAR OIL SYN | 2.00 |
| - Test Run | | FLAG POLE FIBERGLASS 7 | 1.00 |
| - Shop Supplies | | 8610 SAFETY FLAG PAR- | 1.00 |
| Parts Charge: | 153.54 | Labor Charge: | 360.00 |

Workorder: 1402689

Problem: Tail Wheel

| Meter Reading: 0 | Labor | Parts | |
|--|--------|----------------------|----------|
| In Date: 03/20/2014 | Hours | Description | Quantity |
| - Replace Tail Wheel Assembly. Weld New Fork | 4.00 | SHOP SUPPLIES | 1.00 |
| - Fm To Lyons Raods | | WHEEL WASHER | 1.00 |
| - Shop Supplies | | WHEEL SUPPORT | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 173.96 | Labor Charge: | 240.00 |

Workorder: 1406013

Problem: On Site Lube

| Meter Reading: 0 | Labor | Parts | |
|-----------------------|-------|-----------------------|----------|
| In Date: 06/19/2014 | Hours | Description | Quantity |
| - Onsite Lube | 2.00 | 1CART PALLADIUM 2 GRS | 1.00 |
| - To Mosquito Control | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 6.93 | Labor Charge: | 120.00 |

Workorder: 1407504

Problem: 9950

| Meter Reading: 0 | Labor | Parts | |
|-----------------------|-------|----------------------|----------|
| In Date: 07/30/2014 | Hours | Description | Quantity |
| - On Site Lube | 2.00 | SHOP SUPPLIES | 1.00 |
| - To Mosquito Control | | | |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 120.00 |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

| | | | | |
|----------------------------|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 1409847 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 09/30/2014 | Close Date: 10/01/2014 | Hours | Description | Quantity |
| - Onsite Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 | |

| | | | | |
|----------------------------|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 1504918 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 05/14/2015 | Close Date: 05/14/2015 | Hours | Description | Quantity |
| - Onsite Lube | | 2.00 | SHOP SUPPLIES | 1.00 |
| - To Morikami Museum | | | | |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 120.00 | |

| | | | | |
|----------------------------|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 1508539 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 08/25/2015 | Close Date: 08/28/2015 | Hours | Description | Quantity |
| - Onsite Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 | |

| | | | | |
|----------------------------|-------------------------------|----------------------|--------------------|-----------------|
| Workorder: 1604672 | Problem: 9950 | | | |
| Meter Reading: 0 | | Labor | Parts | |
| In Date: 05/04/2016 | Close Date: 05/06/2016 | Hours | Description | Quantity |
| - Onsite Lube | | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 | |

1/3/2017
4:30:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171033 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1607336

Problem: Transition Prep Charge

| Meter Reading: 0 | Labor | Parts | Quantity |
|--------------------------|--------------------|-------------|----------|
| In Date: 07/19/2016 | Hours | Description | |
| - Transition Prep Charge | 2.00 | | |
| Parts Charge: 0.00 | Labor Charge: 0.00 | | |

| | | | | | |
|----------------------|-----------------|----------------------|-----------------|----------------------|-------------|
| Total Parts Charges: | 2,997.99 | Total Labor Charges: | 3,465.55 | Total Comm. Charges: | 0.00 |
|----------------------|-----------------|----------------------|-----------------|----------------------|-------------|