

**Palm Beach County Fleet Management
Asset Maintenance History**

10180770 2010 FORD RANGER Pickup, Compact

Workorder: 1002222 **Meter:** 0 **In Date:** 03/03/2010 **Closed:** 03/03/2010
Problem: Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1003813 **Meter:** 1054 **In Date:** 04/13/2010 **Closed:** 04/19/2010
Problem: cut spare key & program

- Cut Key Plug, Program And Test Ok
- Shop Supplies

Parts List Qty

Shop Supplies 1.00
164-r0475 Ign Key 2010-earlier (don't Reorder) 1.00

Hours 1.00 Labor: 60.00 Parts: 23.45 Total: 83.45
:

Workorder: 1008861 **Meter:** 3435 **In Date:** 08/17/2010 **Closed:** 08/30/2010
Problem: P.M. service and canceiver

- Perform pm service.
- Replace missing tag lamp lens with new.
- Rotate and balance all four tires.
- Shop Supplies

Parts List Qty

Shop Supplies 1.00
Ph9566 Oil Filter Use Fram Ph3614 1.00
5w20 Engine Oil 4.00
Nb-18 Wiper Blades 18" Anco 31-18 2.00
Tag Light Lens 1.00

Hours 3.25 Labor: 195.00 Parts: 39.33 Total: 234.33
:

Workorder: 1009057 **Meter:** 3435 **In Date:** 08/23/2010 **Closed:** 08/24/2010
Problem: reflash canceiver-spot # 214

- Flash Canceiver
- Shop Supplies

Parts List Qty

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1101881 **Meter:** 6262 **In Date:** 02/16/2011 **Closed:** 02/25/2011
Problem: Pm service

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts List Qty

Shop Supplies 1.00
Ph9566 Oil Filter Use Fram Ph3614 1.00
3424 Fuel Filter Frm 3424 Wix 33424 1.00
1066 White Lithium (crc 05037) 1.00
5w20 Engine Oil 5.00
Nb-18 Wiper Blades 18" Anco 31-18 2.00

Hours 3.00 Labor: 180.00 Parts: 35.61 Total: 215.61
:

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|--|---------------------|---|---------------------------|
| Workorder: 1108642 | Meter: 9596 | In Date: 08/16/2011 | Closed: 08/25/2011 |
| Problem: Pm service and driver door outside handle concern. | | | |
| - Perform pm service. | | Parts List | Qty |
| - Rotate and balance all four tires. | | Shop Supplies | 1.00 |
| - Diagnose driver door concern.inspect and adjust striker,hinges and latch to open and close door effectively. | | 1348 Oil Filter Frm Ph3614 Wix 51348 | 1.00 |
| - Shop Supplies | | Ca8243 Air Filter Lbf Af1658 Wix 46253 | 1.00 |
| | | 5w20 Engine Oil | 5.00 |
| | | Nb-18 Wiper Blades 18" Anco 31-18 | 2.00 |
| Hours 3.50 | Labor: 210.00 | Parts: 32.77 | Total: 242.77 |
| : | | | |
| Workorder: 1112400 | Meter: 11524 | In Date: 11/22/2011 | Closed: 11/30/2011 |
| Problem: Shift indicator inop. | | | |
| - Transport vehicle to dealer for defective shift indicator. | | Parts List | Qty |
| - Shop Supplies | | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
| : | | | |
| Workorder: 1201673 | Meter: 13113 | In Date: 02/21/2012 | Closed: 02/29/2012 |
| Problem: P.M. service. | | | |
| - P.m. Service. | | Parts List | Qty |
| - Replace and balance four tires. | | Shop Supplies | 1.00 |
| - Complete wheel alignment.test drive. | | 1348 Oil Filter Frm Ph3614 Wix 51348 | 1.00 |
| - Shop Supplies | | 3424 Fuel Filter Frm 3424 Wix 33424 | 1.00 |
| | | 5w20 Engine Oil | 5.00 |
| | | Nb-18 Wiper Blades 18" Anco 31-18 | 2.00 |
| | | 183482418 P225/70r15 Wrangler Sr-a 100s | 4.00 |
| | | Tire Disposal Fee | 4.00 |
| Hours 6.50 | Labor: 390.00 | Parts: 503.98 | Total: 893.98 |
| : | | | |
| Workorder: 1211205 | Meter: 18572 | In Date: 11/16/2012 | Closed: 11/30/2012 |
| Problem: Pm service. | | | |
| - Perform pm service. | | Parts List | Qty |
| - Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new. | | Filter | 1.00 |
| - Inspect ac vents for poor airflow.clean debris from clogged fresh air screen. | | 5w20 Engine Oil | 5.00 |
| - Rotate and balance all four tires. | | 31-18 Wiper Blades 18 | 2.00 |
| - Shop Supplies | | Steering Wheel Cover | 1.00 |
| | | Floor Mat-2pc Rub Bk | 1.00 |
| | | Group 59 Battery Mtc | 1.00 |
| | | Shop Supplies | 1.00 |
| Hours 4.50 | Labor: 270.00 | Parts: 204.32 | Total: 474.32 |
| : | | | |
| Workorder: 1211642 | Meter: 18572 | In Date: 12/03/2012 | Closed: 12/03/2012 |
| Problem: 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| - 1 - Detail Vehicle Wash Ticket(s) Issued | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1303557 **Meter:** 21526 **In Date:** 04/11/2013 **Closed:** 04/18/2013
Problem: Pm service.Check over all lights,see notes.

| | | |
|---|----------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Test and replace failed right side headlamp bulb with new.test and replace failed right taillamp bulb and tag lamp assemblies with new. | 5w20 Engine Oil | 5.00 |
| | Napagold Oil Filter | 1.00 |
| - Rotate and balance all four tires. | Wiper Blade | 2.00 |
| - Shop Supplies | Napagold Fuel Filter | 1.00 |
| | Halogen Capsule | 1.00 |
| | Bulb | 1.00 |
| | Lamp Asy | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 71.89 |
| : | | Total: 311.89 |

Workorder: 1311439 **Meter:** 26043 **In Date:** 11/13/2013 **Closed:** 11/27/2013
Problem: Pm servie and left headlamp inop.

| | | |
|---|----------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Test and replace failed left head lamp bulb with new. | screw and | 4.00 |
| - Replace failed left sill moulding and screws with new. | Wiper Blade | 2.00 |
| - Install two new tires to the front wheels.nitrogen fill and balance all four. | 5w20 Engine Oil | 5.00 |
| - Shop Supplies | Napagold Oil Filter | 1.00 |
| | Pedal Pad | 1.00 |
| | Halogen Capsule | 1.00 |
| | 183482418 P225-70r15 | 2.00 |
| | molding plate | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 5.00 | Labor: 300.00 | Parts: 383.87 |
| : | | Total: 683.87 |

Workorder: 1406115 **Meter:** 30024 **In Date:** 06/20/2014 **Closed:** 06/30/2014
Problem: Pm service.

| | | |
|--|----------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Inspect and replace missing right side taglamp with new. | 5w20 Engine Oil | 5.00 |
| - Inspect for oil leak.remove driveshaft and replace failed transmission output shaft seal with new. | Napagold Oil Filter | 1.00 |
| | Napagold Fuel Filter | 1.00 |
| - Install two new tires to the front wheels.nitrogen fill and balance all four. | Napagold Air Filter | 1.00 |
| - Shop Supplies | Wiper Blade | 2.00 |
| | Washer FI | 1.00 |
| | Lamp Asy | 1.00 |
| | 183482418 P225-70r15 | 2.00 |
| | Rear Trans Seal | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 5.50 | Labor: 330.00 | Parts: 396.53 |
| : | | Total: 726.53 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1500783 **Meter:** 34197 **In Date:** 01/22/2015 **Closed:** 02/09/2015
Problem: P.M. service and tag light.

| | | |
|---|---------------------|---------------|
| - Pm service. | Parts List | Qty |
| - Replace two rear defective tag lamp assemblies.replace defective third brake lamp bulb. | 5w20 Engine Oil | 5.00 |
| - Test starting and charging system.battery failed loadtest after recharge.replace defective battery. | Napagold Oil Filter | 1.00 |
| - Repair right rear tire.rotate and balance all four. | Wiper Blade | 2.00 |
| - Shop Supplies | Washer Fl | 1.00 |
| | Bulb | 2.00 |
| | Battery | 1.00 |
| | Tag Lamp | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 5.75 | Labor: 345.00 | Parts: 188.69 |
| : | | Total: 533.69 |

Workorder: 1502328 **Meter:** 34763 **In Date:** 03/04/2015 **Closed:** 03/06/2015
Problem: fuel odometer error

| | | |
|-----------------------------|-------------------|--------------|
| - Test and Remove Canceiver | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1508373 **Meter:** 39212 **In Date:** 08/20/2015 **Closed:** 09/30/2015
Problem: Pm service.

| | | |
|-----------------------------------|-----------------------|---------------|
| - P.m. Service. | Parts List | Qty |
| - Replace broken tailgate handle. | handle | 1.00 |
| - Rotate and balance all tires. | 5w20 Engine Oil | 10.00 |
| - Shop Supplies | Napagold Oil Filter | 2.00 |
| | Wiper Blade | 4.00 |
| | Napagold Fuel Filter | 2.00 |
| | Washer Fluid Concentr | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 3.50 | Labor: 210.00 | Parts: 110.78 |
| : | | Total: 320.78 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605164 **Meter:** 43692 **In Date:** 05/18/2016 **Closed:** 06/08/2016
Problem: P.M. Service.Tow in,dead battery.

| | | |
|---|----------------------|-----------------|
| - P.m. Service. | Parts List | Qty |
| - Replace and balance four new tires. | 5w20 Engine Oil | 5.00 |
| - Test battery and charging system.replace bad battery. | Napagold Oil Filter | 1.00 |
| - Replace bad alternator. | 18" wiper blades | 2.00 |
| - Replace serpentine belt. | Napagold Fuel Filter | 1.00 |
| - Replace front brake rotors,pads and calipers.flush and refill system. | 183482418 P225-70r15 | 4.00 |
| - Pressure test and inspect cooling system.flush and refill system. | Battery | 1.00 |
| - Complete wheel alignment.test drive. | Brake Rotor Hub | 2.00 |
| - Shop Supplies | Reman Brake Caliper | 1.00 |
| | Reman Brake Caliper | 1.00 |
| | B Fluid Dot 3-32oz | 1.00 |
| | Peak Global | 2.00 |
| | Brake Cleaner | 2.00 |
| | Alternator Assy | 1.00 |
| | V Belt | 1.00 |
| | Napa Oil Seal | 2.00 |
| | Stg Wheel Cov - Ford | 1.00 |
| | Radio Knob | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 14.00 | Labor: 840.00 | Parts: 1,404.33 |
| : | | Total: 2,244.33 |

Workorder: 1605314 **Meter:** 43502 **In Date:** 05/18/2016 **Closed:** 05/24/2016
Problem: alternator?

| | | | | |
|--|------------|-------------|-------------|-------------|
| - Tow From: haverhill s of dyer park To: vista | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| | : | | | |

Workorder: 1607953 **Meter:** 45604 **In Date:** 08/03/2016 **Closed:** 08/04/2016
Problem: Turn signals inop at times.

| | | |
|--|-----------------------|---------------|
| - Diagnodsev inop signal lights.test and replace turn signal switch and relay. | Parts List | Qty |
| - Shop Supplies | Flasher Relay | 1.00 |
| | multi function switch | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 180.14 |
| : | | Total: 270.14 |

Workorder: 1610757 **Meter:** 47763 **In Date:** 10/18/2016 **Closed:** 10/24/2016
Problem: needs new key

| | | |
|--------------------------------|-------------------------|--------------|
| - Make and program one new key | Parts List | Qty |
| - Shop Supplies | Ford Ignition Key Blank | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 28.61 |
| : | | Total: 88.61 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1611477 **Meter:** 48676 **In Date:** 11/07/2016 **Closed:** 11/29/2016
Problem: P.M. service and side wall damage left front tire.

| | Parts List | Qty |
|--|-----------------------|----------------------------------|
| - P.m. Service. | | |
| - Replace left headlamp bulb and right marker lamp bulb. | 5w20 Engine Oil | 5.00 |
| - Replace right rear tire,rotate and balance all four. | Napagold Oil Filter | 1.00 |
| - Service transmission.flush and refill system. | 18" wiper blades | 2.00 |
| - Inspect and service differential. | Washer Fluid Concentr | 1.00 |
| - Shop Supplies | Capsule | 1.00 |
| | Bulb | 1.00 |
| | Friction Modifier | 1.00 |
| | Pedal Pad | 1.00 |
| | 183482418 P225-70r15 | 1.00 |
| | Syn-atf Trans Fluid S | 14.00 |
| | Screen Asy | 1.00 |
| | 75w140 Ford Axle Lube | 2.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 1.00 |
| Hours 7.75 | Labor: 465.00 | Parts: 321.76 Total: 786.76 |
| : | | |

Workorder: 1706236 **Meter:** 53900 **In Date:** 06/23/2017 **Closed:** 07/10/2017
Problem: P.M. Service.

| | Parts List | Qty |
|---|-----------------------|----------------------------------|
| - P.m. service. | | |
| - R&r failed front shocks with new.front sway bar links failed R&r with new. | 5w20 Engine Oil | 5.00 |
| | Napagold Oil Filter | 1.00 |
| - Windshield washer pump failed R&r with new.left front door hinde worn.r&r door and install upper and lower higes. | Napagold Fuel Filter | 1.00 |
| | 18" wiper blades | 2.00 |
| - Left side rear tag lamp inop.remove wiring and socket.fabricate wiring.install new pigtail with bulb. | Washer Fluid Concentr | 1.00 |
| | Sensa-trac Lt Truck S | 2.00 |
| - Rotate and high speed balance all four tires. | Sway Bar Repair Kit | 1.00 |
| - Shop Supplies | Wire Asy | 1.00 |
| | Washer Pump | 1.00 |
| | Tag Lamp | 1.00 |
| | Wire Asy | 1.00 |
| | Bulb | 1.00 |
| | Wire Asy | 1.00 |
| | Hinge Ass | 1.00 |
| | Hinge Asy | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 412.37 Total: 982.37 |
| : | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1800045 **Meter:** 59225 **In Date:** 01/02/2018 **Closed:** 01/09/2018
Problem: P.M. service and check brake lights.

| | Parts List | Qty |
|--|----------------------|-----------------|
| - P.m. Service. | | |
| - Replace left brake lamp bulb. | 5w20 Engine Oil | 5.00 |
| - Replace and balance four new tires. | Napagold Oil Filter | 1.00 |
| - Complete wheel alignment.test drive. | 18" wiper blades | 2.00 |
| - Shop Supplies | Pedal Pad | 1.00 |
| | Bulb | 1.00 |
| | 183482418 P225-70r15 | 4.00 |
| | Ford Triton Pvc Swc | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 7.00 | Labor: 420.00 | Parts: 653.35 |
| : | | Total: 1,073.35 |

Workorder: 1806373 **Meter:** 63133 **In Date:** 06/21/2018 **Closed:** 07/25/2018
Problem: PM Service, TPMS light on.

| | Parts List | Qty |
|--|-----------------------|-----------------|
| - P.m. service. | | |
| - Rotate and high speed balance all four tires . Nitrofill tires. | Air Freshener | 1.00 |
| - A/c performance test . Recover system . Replace high side line and accumulator and orifice tube . Leak test and complete recharge to factory spec. Retest. | Tube Asy | 1.00 |
| | Accumulator | 1.00 |
| | Orifice Tube Filter | 1.00 |
| - Rebuild culumn shifter assembly . Replace shifter ,tube ,shaft and bushings . Retest. | O Ring | 3.00 |
| | Seal | 3.00 |
| - Remove all seats and floor mat and accessries to dry floor mat and floor board due to rear window leaking. | O Ring | 3.00 |
| | O-ring | 3.00 |
| - Transport to and from dealer for recall 16s26 . | O Ring | 3.00 |
| - Shop Supplies | Frig Oil | 1.00 |
| | Napagold Oil Filter | 1.00 |
| | 5w20 Engine Oil | 5.00 |
| | Napagold Fuel Filter | 1.00 |
| | 18" wiper blades | 2.00 |
| | Tube | 1.00 |
| | Clamp | 2.00 |
| | Gear Lunger | 2.00 |
| | F3tz7I278a Bushing Sh | 2.00 |
| | Pin | 1.00 |
| | Damper Assy | 1.00 |
| | Lever | 1.00 |
| | Freon Lv Shop 1 | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 15.00 | Labor: 900.00 | Parts: 550.46 |
| : | | Total: 1,450.46 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1806712 **Meter:** 63121 **In Date:** 06/29/2018 **Closed:** 07/18/2018
Problem: reseal back glass

| | | | |
|----------------------------|--------------|-------------------|--------------|
| - set up repairs & inspect | | Parts List | Qty |
| - Shop Supplies | | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 | Total: 62.00 |
| : | | | |

Workorder: 1810395 **Meter:** 64656 **In Date:** 10/09/2018 **Closed:** 10/11/2018
Problem: Left headlight inop.

| | | | |
|---|--------------|-------------------|--------------|
| - Test and replace left head light bulb . Retest. | | Parts List | Qty |
| | | Boxed Capsules | 1.00 |
| Hours 0.50 | Labor: 33.50 | Parts: 8.72 | Total: 42.22 |
| : | | | |

Workorder: 1903025 **Meter:** 67249 **In Date:** 03/19/2019 **Closed:** 04/03/2019
Problem: P.M. Service.Body damage.

| | | | |
|--|---------------|-----------------------|---------------|
| - P.m. service. | | Parts List | Qty |
| - Perform battery analyzing charge and load test . Battery failed load test . R&r defective battery . | | Napagold Oil Filter | 1.00 |
| - Diagnose tail lamp inop . Replace bulbs . Test and repair circuit to left side power outlet . | | 5w20 Engine Oil | 5.00 |
| - Replace one tire due nail in side wall . Rotate and high speed balance all four tires . Nitrofill all. | | Washer Fluid Concentr | 1.00 |
| - Shop Supplies | | 18" wiper blades | 2.00 |
| | | Battery | 1.00 |
| | | Boxed Miniatures | 2.00 |
| | | Napagold Fuel Filter | 1.00 |
| | | 183482418 P225-70r15 | 1.00 |
| | | Shop Supplies | 1.00 |
| | | Tire Disposal Fee | 1.00 |
| Hours 6.00 | Labor: 402.00 | Parts: 302.74 | Total: 704.74 |
| : | | | |

Workorder: 1904551 **Meter:** 67249 **In Date:** 04/04/2019 **Closed:** 04/26/2019
Problem: damage to left rear fender & tailgate rust

| | | | |
|--|-------------|-------------|-------------|
| - damage to left rear fender & tailgate rust | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1911249 **Meter:** 68869 **In Date:** 10/29/2019 **Closed:** 10/29/2019
Problem: Transition Prep Charge

| | | | |
|--------------------------|---------------|-------------|---------------|
| - Transition Prep Charge | | | |
| Hours 2.00 | Labor: 146.00 | Parts: 0.00 | Total: 146.00 |
| : | | | |