10174390 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: Problem:	838176 PRE-DELIV	<b>Meter:</b> ERY INSPE	-			In Date:	05/07/2008	Closed:	05/07/20	800
- Pre-delivery	Inspection									
	Ho :	urs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	847978 P.M.SERVI	Meter:	3799			In Date:	12/09/2008	Closed:	12/12/20	800
- Pm Service					Parts Li	ist				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
					G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Er	ngine Oil				8.00
					Nb-19 \	Niper Blade	s 19" Anco 3'	1-19		2.00
	Ho :	urs 2.75		Labor:	165.00	Parts:	71.10	Total:	236.10	
Workorder: Problem:	940409 P.M.SERVI	Meter:	6244			In Date:	07/07/2009	Closed:	07/07/20	009
- p.m.service					Parts Li	ist				Qty
- install no sm	oking decals	3			Shop Supplies					1.00
- repair nail in	L/front tire				1372 O	il Filter Frm	Ph2 Wix 51	372		1.00
- Shop Suppli	es				5w20 Er	ngine Oil				8.00
	Ho	urs 3.25		Labor:	195.00	Parts:	43.46	Total:	238.46	
Workorder:	1000876 P.M.SERVI	Meter:	9655			In Date:	01/22/2010	Closed:	01/26/20	010
- P. M.		-			Parts Li	ist				Qty
- R/r two Lt24	5 75 R17 wra	angler Sra. r	nount. balanc	e. add	Shop St					1.00
N2, & balance			,	,	1372 Oil Filter Frm Ph2 Wix 51372					1.00
- Verify, left re		rake light ou	t. R/r one tail	light	G10166 Fuel Filter Mtc Fg1083 Wix 33243					1.00
bulb, repair so					5w20 Er		8.00			
- Shop Suppli	es				3157 Ta	ail Light Bulb	os			1.00
					1796364	492 Lt245/7	5r17 Wrangle	r Sr-a E		2.00
					Tire Dis	posal Fee				2.00
	Ho	urs 5.25		Labor:	315.00	Parts:	435.22	Total:	750.22	
Workorder: Problem:	1007099 MISSING A	Meter: M/FM RADIO	13417 O ANTENNA			In Date:	07/07/2010	Closed:	07/08/20	010
- R&r missing	Am/fm radio	antenna.			Parts Li	ist				Qty
	,	33				Radio Anten	na			1.00
	Но	urs 0.25		Labor:			30.18	Total:	45.18	
	:	-			-				-	

Workorder: Problem:	1008288 P.M.SERVI	Meter:	13797		I	n Date:	08/03/2010	Closed:	08/09/20	010
- P. M.					Parts List	:				Qty
- R&r signal b	ulb. R&r cer	iter brake bu	lb.		Shop Sup	plies				1.00
- Disassemble					1372 Oil I	Filter Frm	n Ph2 Wix 51	372		1.00
- Tire repair.	J				Ca10262	Air Filter I	Mtc Fa1883 W	ix 49883		1.00
- Installed driv	ving decal.				5w20 Eng					8.00
- Shop Suppli	•				Ū		d Fire Extings	hers		1.00
5op 50.pp					3157 Tail		•			1.00
	Ho	urs 6.00		Labor:	360.00	-	67.25	Total:	427.25	1100
Workorder: Problem:	1014102 Rear tire, pa	Meter: assenger sid	16181 e, has a nail	in it.	ı	n Date:	12/28/2010	Closed:	12/30/20	010
- C/c: Nail in I	R/r tire. Verif	v. Remove	nail, dismour	nt, patch,	Parts List					Qty
mount, balanc		,	,	, , , , , ,	Shop Sup					1.00
- Shop Suppli	es				- 1 MP					
	Ho	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1100228 FLASH CAN	Meter:	16282		ı	n Date:	01/06/2011	Closed:	01/11/20	011
- Reflash Car	ceiver & repi	rogram			Parts List	:				Qty
- Shop Suppli	-	Ü			Shop Sup	plies				1.00
,,,		urs 1.00		Labor:		Parts:	2.00	Total:	62.00	
	:									
Workorder: Problem:	1101417 P.M.SERVI	Meter: CE	16729		I	n Date:	02/04/2011	Closed:	02/18/20	011
- P. M.					Parts List	·				Qty
- R&r bulb for	light assy.				Shop Sup	plies				1.00
- Freed & lub	ed vise.				1372 Oil l	Filter Frm	n Ph2 Wix 513	372		1.00
- R&r and bal	anced 2 tires				G10166 Fuel Filter Mtc Fg1083 Wix 33243					1.00
- Strobes inte	rmittant, ched	ck pack & wi	ring. Repair	ed	5w20 Engine Oil					8.00
connection at	switch.				Nb-19 Wi	per Blade	s 19" Anco 31	-19		2.00
- Shop Suppli	es				Used Fire	x Refurbe	d Fire Extings	hers		1.00
					3157 Tail	Light Bulk	os			1.00
						-	5r17 Wrangle	r Sr-a E		2.00
					Tire Dispo		3			2.00
	Ho	urs 6.75		Labor:	405.00		447.25	Total:	852.25	
Workorder: Problem:	1103259 DAMAGE F	Meter: LOOR MAT	17981		ı	n Date:	03/25/2011	Closed:	04/11/20	011
- Transport &			er. (defective	e Floor	Parts List	:				Qty
Mat).	•		,		Shop Sup					1.00
D I T. D			-4		-11					
	eplace Defec	tive Floor M	at.							
- Dealer To R - Shop Suppli	es	ctive Floor M urs 2.00	at.	l ahor	120.00	Parts:	2.00	Total·	122.00	

Problem: P. M.	064 <b>Meter:</b> SERVICE	19777		ln	Date:	08/02/2011	Closed:	08/05/20	011
- Performed service.				Parts List					Qty
- R&r center brake b		ght & cleaned		Shop Suppl	ies				1.00
connections.	,	•				n Ph2 Wix 513	372		1.00
- Repaired Lf tire.				Ca10262 Ai	r Filter I	Mtc Fa1883 W	ix 49883		1.00
- Straightened pipe 8	& rehung hanger, (d	damaged).		5w20 Engin	e Oil				8.00
- Installed driving de	cal.			_		d Fire Extings	hers		1.00
- Shop Supplies						s 19" Anco 31			2.00
				3156 Wagn					1.00
	Hours 6.00		Labor:	360.00	Parts:	73.14	Total:	433.14	
Workorder: 12012 Problem: P. M.		22140		In	Date:	02/07/2012	Closed:	02/14/20	012
- P. M. Service.				Parts List					Qty
- Shop Supplies				Shop Suppl	ies				1.00
				1372 Oil Fi	lter Frm	n Ph2 Wix 513	372		1.00
				G10166 Fue	el Filter	Mtc Fg1083 W	Vix 33243		1.00
				1066 White	Lithium	n (crc 05037)			1.00
				5w20 Engin	e Oil				8.00
	Hours 2.75		Labor:	165.00	Parts:	44.26	Total:	209.26	
Workorder: 12114 Problem: pm	90 Meter:	25741		In	Date:	11/29/2012	Closed:	12/07/20	012
- pm				Parts List					Qty
- nail in Ir tire dismou	unt patch mount bal	ance add ne		Ph2 Oil Filte		n			1.00
- Shop Supplies				Napa Quart					8.00
				31-19 Wipe		s 19			
				Shop Suppl	ies				
	Hours 3.75 :		Labor:	-	ies	50.05	Total:	275.05	2.00 1.00
	:	28832 nt wheels pos		Shop Suppl 225.00	Parts:	50.05	Total:	275.05	1.00
	: 240 <b>Meter:</b>			Shop Suppl 225.00	Parts:	50.05			1.00
Problem: grinding	: 240 <b>Meter:</b> ng sound in the from	nt wheels pos		Shop Suppl 225.00 In	Parts:  Date: or faulty	50.05			1.00 013 <b>Qty</b>
<ul><li>Problem: grinding</li><li>- P. M. Service.</li></ul>	: 240 Meter: ng sound in the fron	nt wheels pos		Shop Suppl 225.00  In  Ity bearings of Parts List	Date: or faulty bil Filter	50.05			1.00
Problem: grinding - P. M. Service Replace both rear to	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In  Ity bearings of the parts List  Napagold Control of the parts List	Date: or faulty bil Filter 5w20	50.05 05/29/2013 rotors, pm			1.00 013 <b>Qty</b> 1.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer wheel	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart	Date: or faulty bil Filter 5w20 r Blades	50.05 05/29/2013 rotors, pm			1.00 013 Qty 1.00 8.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer whee - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe	Date: or faulty Dil Filter 5w20 r Blades uel Filte	50.05 05/29/2013 rotors, pm			1.00 013 Qty 1.00 8.00 2.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer whee - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe Napagold F	Date: or faulty bil Filter 5w20 r Blades uel Filte thium G	50.05 05/29/2013 rotors, pm			1.000 013 Qty 1.000 8.000 2.000 1.000
Problem: grinding - P. M. Service Replace both rear to - Repack outer whee - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe Napagold F Mac Wite Li	Date: or faulty bil Filter 5w20 r Blades uel Filte thium G	50.05  05/29/2013 rotors, pm			1.00 Qty 1.00 8.00 2.00 1.00 1.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer whee - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe Napagold F Mac Wite Li Napagold A	Date: Date: Date: Dil Filter Sw20 r Blades uel Filte thium G ir Filter Refurbe	50.05  05/29/2013 rotors, pm  3.19 er eres ed F			1.00 Qty 1.00 8.00 2.00 1.00 1.00 1.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer wheeler - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe Napagold F Mac Wite Li Napagold A Used Firex	Date: Date: or faulty  Filter Sw20 r Blades uel Filter thium G ir Filter Refurbe Lt245-7	50.05  05/29/2013 rotors, pm  3.19 er eres ed F			1.00 013 Qty 1.00 8.00 2.00 1.00
Problem: grinding - P. M. Service Replace both rear to - Repack outer wheeler - Fill all tires with nitres.	: 240 Meter: ng sound in the from tires & rotate to the bl bearrings & torqu	nt wheels pos		Shop Suppl 225.00  In Ity bearings of Parts List Napagold C Napa Quart 31-19 Wipe Napagold F Mac Wite Li Napagold A Used Firex 179636492	Date: Date: or faulty Dil Filter 5w20 r Blades uel Filter thium G ir Filter Refurbe Lt245-7 ies	50.05  05/29/2013 rotors, pm  3.19 er eres ed F			1.000 013 Qty 1.000 2.000 1.000 1.000 1.000 2.000

Workorder: Problem:	1307080 will not start	Meter:	29540		I	In Date:	07/16/2013	Closed:	07/25/20	013
- ck dead batt	ery verify bad	batt replac	e battery ck	charging	Parts Lis	t				Qty
sys					Battery					1.00
- Shop Suppli	es				Shop Sup	plies				1.00
	Hour	s 0.75		Labor:	45.00	Parts:	117.97	Total:	162.97	
Workorder: Problem:	1403179 pm	Meter:	32078		I	In Date:	04/01/2014	Closed:	04/11/20	014
- pm					Parts Lis	t				Qty
- Shop Suppli	es				Napagold	Oil Filter				1.00
					Napa Qua	art 5w20				8.00
					Wiper Bla					2.00
					Shop Sup	plies				1.00
	Hour	s 2.75		Labor:	165.00	•	44.78	Total:	209.78	
Workorder:	1406075	Meter:	33538		ļ	In Date:	06/20/2014	Closed:	07/07/20	014
Problem:	wipers blow fu	uses, abs t	reak light co	me on						
	w fuse perform				Parts Lis	t				Qty
	ed internal repla	•		•	Motor Asy	/				1.00
	is on scan and				Sensor As	sy				2.00
	n pinpoint test t sensor replac				Shop Sup	plies				1.00
	miles before a									
- Shop Suppli			•							
111		s 8.25		Labor:	495.00	Parts:	330.07	Total:	825.07	
Workorder: Problem:	1408404 wont fuel	Meter:	33906		!	n Date:	08/22/2014	Closed:	08/28/20	014
- Test and rer	nove Canceive	er issue fue	el card		Parts Lis	t				Qty
- Shop Suppli					Shop Sup	plies				1.00
элэр эарра		s 1.00		Labor:		Parts:	2.00	Total:	62.00	
Workorder: Problem:	1410694 pm	Meter:	35744			In Date:	10/27/2014	Closed:	10/31/20	014
	•				Dorto Lie	4				O4
- Pm	na Whool Noo	de Cover l	notall Cover		Parts List		r			<b>Qty</b>
-	ing Wheel Nee	us Cover II	nstall Cover		Napagold		I			1.00
- Shop Suppli	es				Napagold					1.00
					Napa Qua		al			8.00
					-	l Cov - Fo	ra			1.00
					Shop Sup	•	0.4.00			1.00
	Hour	s 3.25		Labor:	195.00	Parts:	61.63	Total:	256.63	

Workorder: 1504685 Meter: 38755 Problem: pm		In C	Date:	05/08/2015	Closed:	05/19/20	15
- pm		Parts List					Qty
- replace both rear tires and rotate to the front		Napagold Oil	Filter				1.00
- replace pintle pin		Napa Quart 5	5w20				8.00
- repair 3rd brake light		Wiper Blade					2.00
- fill tire with nitrogen		Washer FI					1.00
- Shop Supplies		Napagold Fu	el Filte	r			1.00
		Napagold Air	Filter				1.00
		Used Fire X	Refurbi	ished			1.00
		Drain Plug					1.00
		179636492 L	.t245-7	5r17			2.00
		Pintle Pin W/	chain				1.00
		Shop Supplie	es				1.00
		Tire Disposa	Fee				2.00
Hours 5.50 :	Labor:	330.00	Parts:	606.42	Total:	936.42	
Workorder: 1510893 Meter: 45317 Problem: pm, install water cooler bracket		In C	Date:	10/28/2015	Closed:	10/30/20	)15
- pm		Parts List					Qty
- repair bed light on top of cab		Napagold Oil		1.00			
- install fire ext bracket		Napa Quart 5		8.00			
- Shop Supplies		Washer Fluid	Conce	entr			1.00
		Shop Supplie	es				1.00
Hours 4.25 :	Labor:	255.00	Parts:	36.82	Total:	291.82	
Workorder: 1602307 Meter: 49147 Problem: Left tail lamp inop.		In E	Date:	03/04/2016	Closed:	03/07/20	)16
- Test and replace defective left tail lamp bulb.		Parts List					Qty
		Bulb					1.00
Hours 0.50	Labor:	30.00	Parts:	0.78	Total:	30.78	

<b>Workorder:</b> 1602709 <b>Meter:</b> 49681	In Date: 03/15/2016 Closed:	03/31/2016
Problem: Pm service.Check engine light on.Misfires.Nois	se in front end when turning.	
- Pm service.	Parts List	Qty
- Replace all six worn body mounts.	Napagold Oil Filter	1.00
- Replace two front shocks.	5w20 Engine Oil	8.00
- Replace front and rear bump stops.	Wiper Blade Anco	2.00
- Replace two front tires.rotate and balance all four.	Body Mount Kit	2.00
- Computer diagnose Cel and misfire.replace all eight spark	Body Mount Kit	4.00
plugs and # 8 ignition coil.clear codes and test drive.	Gas Grande Fleet Shoc	2.00
- Perform intake decarb.clean fuel system and flush injectors	· bumper	2.00
- Shop Supplies	179636492 Lt245-75r17	2.00
	Spark Plug	8.00
	Coil	1.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Napagold Air Filter	1.00
	Stg Wheel Cov - Ford	1.00
	Real Suspension Bumpstops	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 18.75 Labor:	1,125.0 Parts: 1,482.75 Total: 0	2,607.75

Workorder: 1610213 Meter: 53476 Problem: PM. Service.Check engine light.	In Date: 09/29/2016 Closed:	10/20/2016
- P.m. Service.	Parts List	Qty
- Replace vdefective blower resistor.	5w20 Engine Oil	8.00
- Test b attery and charging system.replace bad battery.	Napagold Oil Filter	1.00
- Pressure test and inspect cooling systerm.flush and refill	Napagold Fuel Filter	1.00
cooling system.	Used Fire X Refurbished	1.00
- Service transmission.flush and refill system.	Napagold Air Filter	1.00
- Diagnose check engine light.p2272.perform pin point test.replace oxygen sensor.clear codes.	Wiper Blade Anco	2.00
- Replace both headlamps.	Non-chlor Brake Clnr	1.00
- Resurface front and rear brake rotors.replace pads and	Blower Resistor	1.00
calipers.flush and bleed system.	Battery	1.00
- Rotate and balance tires.	Fuse	1.00
- Shop Supplies	Peak Global Antifrz	2.00
	Syn-atf Trans Fluid S	20.00
	Halogen Lamp	2.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Caliper w/ Hardware - Left Rear (eclipse	1.00
	Caliper w/ Hardware - Right Rear (eclips	1.00
	B Fluid Dot 3-32oz	2.00
	Brake Pads Front	1.00
	Pads	1.00
	Rear Pads	1.00
	Trans Filter	1.00
	O2 Sensor Downstream	1.00
	Bulb	1.00
	Shop Supplies	1.00
Hours 21.75 Labor	r: 1,305.0 Parts: 1,059.65 Total: 0	2,364.65
Workorder: 1704179 Meter: 57598 Problem: P.M. service, mount GPS pole,mount comput	In Date: 04/26/2017 Closed: ter stand ,left rear tire going flat.	05/11/2017
- P.m. Service.	Parts List	Qty
- Replace right headlamp.	5w20 Engine Oil	8.00
- Replace and rewire corroded trailer plug.	Napagold Oil Filter	1.00
- Inspect and service rear differential.	Used Fire X Refurbished	1.00
- Assemble and install laptop stand.fabricate and install Gps	•	2.00
mounting pole.	Halogen Lamp	1.00
	trailer plug	1.00
- Repair left rear tire,rotate and balance all four.		2.00
- Shop Supplies	75w140 Ford Axle Lube	3.00
•	75w140 Ford Axle Lube Ptex Ultra Grey 3oz	1.00
•		
•	Ptex Ultra Grey 3oz	1.00
•	Ptex Ultra Grey 3oz Friction Modifier	1.00 2.00

Workorder: Problem:	1800526 P.M. service.	Meter:	60867			In Date:	01/17/2018	Closed:	01/25/2018	
Problem: P.M. service.  - P.m. service. Install spot mirrors.  - Check and replace both rear defective shock absorbers.  - Replace two front tires.balance and rotate all four .  - Check and replace defective right headlamp sealed beam bulb.  - Complete front end alignment and road test.  - Shop Supplies						Parts List 2-pk 3in Spot Mirror Halogen Lamp 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished Napagold Fuel Filter 22" Wiper Blade Reflex Truck Shock 179636492 Lt245-75r17 Shop Supplies				
	Hour	s 8.75		Labor:	525.00	posal Fee Parts:	638.61	Total:	2.00 1,163.61	
Workorder:	1903298 PM Service	Meter:	71755			In Date:	03/26/2019	Closed:	04/15/2019	
- Pm Service.	PIVI Service				Parts Li	iet			Qty	
	it rear brake lig	ht socket :	and hulh		Napago	1.00				
	rear tires.bala			to front		uart 5w20			8.00	
•	e shaft.resurfa				22" Wip	2.00				
calipers,pads			ai iotois.iep	iace	-	1.00				
- Shop Suppli						ld Air Filter re X Refurb			1.00	
									1.00	
					•	TI Lgt Sock	eı			
						/liniatures	E.47		1.00	
						492 Lt245-7	5r17		2.00	
					Brake P				1.00	
						or Brake Cli			1.00	
					· ·		e - Left Rear (	-	1.00	
					•		e - Right Rear	(eclips	1.00	
					Shop Su				1.00	
						posal Fee			2.00	
	Hour :	s 10.50		Labor:	703.50	Parts:	832.39	Total:	1,535.89	
Workorder: Problem:	1906152 1 - Key(s) issu	Meter: ued	71755			In Date:	06/11/2019	Closed:	06/11/2019	
- 1 - Key(s) is:	sued				Parts Li	ist			Qty	
-3(-)						e Vehicle K	evs		1.00	
	Hour	s 0.30		Labor:		Parts:	-	Total:	23.10	
	:	0.00			_0		0.00		_00	
Workorder: Problem:	1906331 1 - Key(s) issu	Meter: ued	71755			In Date:	06/17/2019	Closed:	06/17/2019	
- 1 - Key(s) is:	sued				Parts Li	ist			Qty	
1 10y(3) 13	J404					e Vehicle K	OVE		1.00	
	Hour	s 0.30		Labor:		e venicie k Parts:	-	Total:	23.10	
	•									

Hours 2.00

Workorder: 1911168 Meter: 73572 Problem: PM Service.Dead battery in WUD parking lot.	In Date: 10/28/2019 Closed: 10/31/2019				
- Pm Service.	Parts List Qty				
- Jump start vehicle in Wud parking lot.replace	Napa Quart 5w20 8.00				
battery.service cables and tray.	Napagold Oil Filter 1.00				
- Replace left reverse lamp.	Battery				
- Rotate and balance four tires.	Boxed Miniatures 1.0				
- Clean engine compartment.	Shop Supplies 1.00				
- Shop Supplies					
Hours 6.25 Labor:	456.25 Parts: 185.28 Total: 641.53				
Workorder: 1912849 Meter: 74596 Problem: Transition Prep Charge	In Date: 12/17/2019 Closed: 12/17/2019				
- Transition Prep Charge					

Labor: 146.00

Parts: 0.00

Total: 146.00