

**Palm Beach County Fleet Management
Asset Maintenance History**

10174418 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 839354 **Meter:** 0 **In Date:** 06/03/2008 **Closed:** 06/03/2008
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 839883 **Meter:** 316 **In Date:** 06/11/2008 **Closed:** 07/21/2008
Problem: INSTALL TOOL BOX & STROBE KIT

- Install Tool Box
 - Fabricate & Install Light Bar & Control Panel.
 - Mount Spray Rig In Bed Of Truck.
 - Shop Supplies

Parts List	Qty
Shop Supplies	1.00
80865 Fuseholder Imperial 80865	1.00
06133 3m Electric Tape Stock #832260101	1.00
Led Light Kit	1.00
Led Light Kit	1.00
Tool Box	1.00
Pcc6rfl Switch Box (whelen)	1.00
Sx2aaaa Light Bar Led 54" Amber (whelen)	1.00

Hours 12.00 Labor: 720.00 Parts: 3,577.09 Total: 4,297.09
 :

Workorder: 841105 **Meter:** 434 **In Date:** 07/09/2008 **Closed:** 07/25/2008
Problem: FAB ENGINE COVER

- Fabricate And Install Pressure Washer Cover With Hinge
 And Pressure Washer Hose Reel Mount.
 - Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1/4x3x20 Alum Flat Bar 6063	5.00
1/8 4x8 Alum Plate	3.00
1/4x2x4x20 Alum Angle 6063	2.00
1/8x1x1x20 Alum Angle Architectural	5.00
1"x24' Square Alum Tube With Radius 1/8 Wall	1.00
Hinge	1.00

Hours 10.00 Labor: 600.00 Parts: 67.20 Total: 667.20
 :

Workorder: 846100 **Meter:** 3238 **In Date:** 10/23/2008 **Closed:** 10/31/2008
Problem: CHECK ENGINE LIGHT ON

- Run Evap Monitor Test,locate Leak,repair Damage Evap
 Canistrand Rerun Test.
 - To/fr Dealer For R/f 4x4 Hub
 - Shop Supplies

Parts List	Qty
Shop Supplies	1.00
21425 Locktite Epoxy Pack Of 10 Kits	1.00

Hours 3.50 Labor: 210.00 Parts: 3.99 Total: 213.99
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 848444	Meter: 4588	In Date: 12/19/2008	Closed: 12/24/2008
Problem: P.M SERVICE			
- Pm Service		Parts List	Qty
- Balance 4 Tires.nitro Fill		Shop Supplies	1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil	7.00
Hours 3.75	Labor: 225.00	Parts: 40.11	Total: 265.11
:			
Workorder: 848468	Meter: 4521	In Date: 12/19/2008	Closed: 12/22/2008
Problem: CHECK CANCEIVER			
- Diagnose No Flashing Light On Canceiver-reprogram		Parts List	Qty
Canceiver Repair Fuse		Shop Supplies	1.00
- Test At Fuel Sight			
- Shop Supplies			
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			
Workorder: 934665	Meter: 6398	In Date: 03/03/2009	Closed: 03/16/2009
Problem: LOW OIL LEVEL.HOOD STRUTS NOT HOLDING.			
- Transport Vehicle To Dealer For Excessive Oil		Parts List	Qty
Consumption And Defective Hood Strut.		Shop Supplies	1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 938785	Meter: 8028	In Date: 06/09/2009	Closed: 06/11/2009
Problem: EXCESSIVE OIL CONSUMPTION.P.M. SERVICE.			
- Pm Service		Parts List	Qty
- Rotate & Hi Speed Balance 4 Tires. Fill W/nitrogen.		Shop Supplies	1.00
- Shop Supplies		Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 3.75	Labor: 225.00	Parts: 20.69	Total: 245.69
:			
Workorder: 942090	Meter: 9664	In Date: 08/13/2009	Closed: 08/17/2009
Problem: R/R tire flat			
- Mount, balance & nitro fill one new tire on R/r.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		245/75r17 Tire	1.00
Hours 1.00	Labor: 60.00	Parts: 180.77	Total: 240.77
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 944786	Meter: 10727	In Date: 10/20/2009	Closed: 10/21/2009
Problem: right front tire flat side wall damage beyond repairs			
- Mount, balance & nitro fill two new front tires.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		179636492 Lt245/75r17 Wrangler Sr-a E	2.00
		Tire Disposal Fee	2.00
		Tr416 Valve Stem	2.00
Hours 1.50	Labor: 90.00	Parts: 377.03	Total: 467.03
:			
Workorder: 946560	Meter: 11706	In Date: 12/02/2009	Closed: 12/14/2009
Problem: P.M service			
- P.m service.		Parts List	Qty
- Remove/reinstall items from cab for dealer warrenty of floor mat.		Shop Supplies	1.00
- Alignment.		1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate & balance all four tires.		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- To/from Dealer for warrenty floor mat & battery.		5w20 Engine Oil	7.00
- Shop Supplies		31-20 Wiper Blades 20" Blade	2.00
		Floor Mat Set	1.00
Hours 9.25	Labor: 555.00	Parts: 104.84	Total: 659.84
:			
Workorder: 1003455	Meter: 12813	In Date: 04/02/2010	Closed: 04/02/2010
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1006444	Meter: 13857	In Date: 06/18/2010	Closed: 06/24/2010
Problem: Pm service.also see notes on water leak and detail vehicle.			
- Perform pm service.		Parts List	Qty
- Diagnose ac concern.evaporator icing and clutch will not cycle out. Replace failed low cycle switch and orifice tube with new.vacume and recharge system to specs.ac performance test.		Shop Supplies	1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
		5w20 Engine Oil	7.00
		Orifice Tube Filter	1.00
		7090blk Frt Floor Mats (rubber Queen)	1.00
		Used Firex Refurbed Fire Extingshers	1.00
		R134a Refrigerant	2.00
		A/c Low Cycling Switch	1.00
Hours 5.50	Labor: 330.00	Parts: 126.40	Total: 456.40
:			
Workorder: 1006690	Meter: 13857	In Date: 06/25/2010	Closed: 06/25/2010
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1014061	Meter: 15536	In Date: 12/27/2010	Closed: 12/28/2010
Problem: Pm service,also see notes on detail vehicle			
- Perform pm service.		Parts List	Qty
- Rotate and balance all four tires.		Shop Supplies	1.00
- Test and replace failed dome lamp bulb with new.		Big G Degreaser Stock# 485180002	1.00
- Shop Supplies		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		5w20 Engine Oil	7.00
		31-20 Wiper Blades 20" Blade	2.00
Hours 4.25	Labor: 255.00	Parts: 39.66	Total: 294.66
:			
Workorder: 1014094	Meter: 15546	In Date: 12/28/2010	Closed: 01/05/2011
Problem: flash canceiver			
- Reflash Canceiver and reprogram		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1100051	Meter: 15556	In Date: 01/03/2011	Closed: 01/03/2011
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued			
- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1105878	Meter: 18751	In Date: 06/03/2011	Closed: 06/08/2011
Problem: needs oil in spray pump			
- Top off pump oil			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
Workorder: 1105881	Meter: 18752	In Date: 06/03/2011	Closed: 06/06/2011
Problem: Right rear tire flat.Vehicle in roads and bridges parking lot.			
- Repair flat right rear tire.nitrogen fill and balance same.had to go to roads and bridges parking lot with air tank to air up tire and drive vehicle back to lv shop for tire repairs.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1107315	Meter: 19329	In Date: 07/12/2011	Closed: 07/13/2011
Problem: Pm service and reset oil life reminder			
- Perform pm service.		Parts List	Qty
- Rotate and balance all four tires.		Shop Supplies	1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
		61a P/steering Fluid	1.00
		5w20 Engine Oil	7.00
		31-20 Wiper Blades 20" Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
Hours 3.75	Labor: 225.00	Parts: 54.05	Total: 279.05
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1108800	Meter: 19802	In Date: 08/19/2011	Closed: 08/22/2011
Problem: Right front headlight inop.			
- Replace right headlamp.		Parts List	Qty
		H6054 Sealed Beam	1.00
Hours 0.50	Labor: 30.00	Parts: 8.62	Total: 38.62
:			
Workorder: 1201391	Meter: 21636	In Date: 02/10/2012	Closed: 02/13/2012
Problem: Canceiver problem			
- Reconnect and resecure data link connector to harness and verify operation		Parts List	Qty
		Shop Supplies	1.00
- Shop Supplies			
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1203050	Meter: 22207	In Date: 03/29/2012	Closed: 04/04/2012
Problem: Pm service.			
- P.m. Service.		Parts List	Qty
- Replace two tires,rotate and balance all four.		Shop Supplies	1.00
- Shop Supplies		1372 Oil Filter Frm Ph2 Wix 51372	1.00
		G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
		5w20 Engine Oil	7.00
		31-20 Wiper Blades 20" Blade	2.00
		Used Firex Refurbed Fire Extingshers	1.00
		179636492 Lt245/75r17 Wrangler Sr-a E	2.00
		Tire Disposal Fee	2.00
		Tr416 Valve Stem	2.00
Hours 4.75	Labor: 285.00	Parts: 427.62	Total: 712.62
:			
Workorder: 1207860	Meter: 22449	In Date: 08/17/2012	Closed: 08/22/2012
Problem: A/C is inop.			
- A/c performance test.evcuate sytem,add oil and dye.vacuum and recharge system to spec.		Parts List	Qty
		Shop Supplies	1.00
- Shop Supplies			
Hours 2.50	Labor: 150.00	Parts: 2.00	Total: 152.00
:			
Workorder: 1209782	Meter: 22611	In Date: 10/12/2012	Closed: 10/12/2012
Problem: No start/PM Service			
- Tow From: Road and Bridge Warehouse (2555 Vista Pkwy) To: Lv Shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1209827	Meter: 22742	In Date: 10/15/2012	Closed: 10/25/2012
Problem: Towed in PM. service and crank but no start.			
- P.m. Service.	Parts List		Qty
- Diagnose no start.test fuel pressure.drain fuel tank and replace defective fuel pump.refill tank and test drive.	5w20 Engine Oil		7.00
- Replace linkage clips on tailgate latch.replace broken right side running board.	Ph2 Oil Filter Lbf Ph		1.00
- Rotate and balance all tires.	G10166 Fuel Filter Mt		1.00
- Shop Supplies	31-20 Wiper Blades 20		2.00
	Used Firex Refurbed F		1.00
	Fuel Pump W/sender		1.00
	Door Clip		2.00
	Gasket		1.00
	Step Asy		1.00
	Shop Supplies		1.00
Hours 10.75	Labor: 645.00	Parts: 979.36	Total: 1,624.36
:			
Workorder: 1210473	Meter: 23072	In Date: 10/31/2012	Closed: 11/09/2012
Problem: Right front headlight inop.			
- Replace right head light bulb.	Parts List		Qty
	H6054 Sealed Beam		1.00
Hours 0.50	Labor: 30.00	Parts: 14.27	Total: 44.27
:			
Workorder: 1302436	Meter: 23365	In Date: 03/12/2013	Closed: 03/15/2013
Problem: Had to jump start in A/M.			
- Test battery and charging system.replace bad battery.	Parts List		Qty
- Shop Supplies	Battery 65		1.00
	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 145.61	Total: 205.61
:			
Workorder: 1303270	Meter: 23598	In Date: 04/04/2013	Closed: 04/05/2013
Problem: Right rear tire going flat.			
- Repair flat right rear tire.nitrogen fill and balance same.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1304711	Meter: 23683	In Date: 05/10/2013	Closed: 05/22/2013
Problem: P.M. service.			
- P.m. Service.	Parts List		Qty
- Replace center brake light bulb.	5w20 Engine Oil		7.00
- Rotate and balance all tires.	Napagold Oil Filter		1.00
- Shop Supplies	31-20 Wiper Blades 20		2.00
	Used Fire X Refurbished		1.00
	Shop Supplies		1.00
Hours 4.25	Labor: 255.00	Parts: 52.28	Total: 307.28
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1312842 **Meter:** 24258 **In Date:** 12/27/2013 **Closed:** 01/09/2014
Problem: P.M. service.

- Perform pm service.	Parts List	Qty
- Inspect and replace failed props for tool box in bed of truck.	5w20 Engine Oil	7.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Computer diagnose for no power on accel.perform fuel	Wiper Blade	2.00
pressure test and replace failed fuel pump in tank with	Napagold Fuel Filter	1.00
new.remove fuel and clan fuel tank.clear codes with scan tool	Used Fire X Refurbished	1.00
and road test.	Support	2.00
- Test and replace failed left headlamp seal beam with new.	Fuel Pump W/sender	1.00
- Shop Supplies	Gasket	1.00
	Halogen Lamp	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 695.21
:		Total: 1,310.21

Workorder: 1405199 **Meter:** 25546 **In Date:** 05/28/2014 **Closed:** 05/30/2014
Problem: Right front tire has nail.

- Repair and balance right front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1406495 **Meter:** 25916 **In Date:** 07/01/2014 **Closed:** 07/08/2014
Problem: Both rear tires going flat.

- Repair both left and right rear tires flat.nitrogen fill and	Parts List	Qty
balance both.	Shop Supplies	1.00
- Shop Supplies		
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1406835 **Meter:** 25962 **In Date:** 07/11/2014 **Closed:** 07/14/2014
Problem: P.M. service.

- Perform pm service.	Parts List	Qty
- Rotate and balance all four tires.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 225.00	Parts: 33.92
:		Total: 258.92

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1410395 **Meter:** 25985 **In Date:** 10/16/2014 **Closed:** 10/31/2014
Problem: Check engine light on,runs rough and no power.

- Diagnose check engine light.p0308,p0304.replace spark plugs and #8,#4, & #3 coils.clear codes.	Parts List	Qty
	408 Fuel Injection CI	1.00
- Ceck fuel quality.water contaminated.r&r fuel tank and clean water.refill tank.clean fuel lines,replace water filled vapor canister.	Napagold Fuel Filter	1.00
	Cannister	1.00
- A/c blower does not operate on #1 speed. Diagnose and replace defective blower resistor.	Stg Wheel Cov - Ford	1.00
	Blower Resistor	1.00
- Shop Supplies	Coil	3.00
	Spark Plug	8.00
	Shop Supplies	1.00
Hours 12.00	Labor: 720.00	Parts: 538.04
:		Total: 1,258.04

Workorder: 1411390 **Meter:** 26208 **In Date:** 11/14/2014 **Closed:** 11/25/2014
Problem: Pm service.Lower reaiator hose slip out and coolant.

- Pm service.	Parts List	Qty
- Diagnose right alley lamp inop.replace defective bulb.disassemble light bar to access and drill out broken screw and fabricate new mounting .	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
- Pressure test and inspect cooling system.replace defective lower radiator hoses and thermostat.flush and refill coolant,	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
- Replace two tires.rotate and balance all four.	Stg Wheel Cov - Ford	1.00
- Shop Supplies	17189e Bulb Mr11-12v	1.00
	Curved Radiator Hose	1.00
	Curved Radiator Hose	1.00
	Thermostat	1.00
	Peak Global	2.00
	179636492 Lt245-75r17	2.00
	Tr416 Valve Stem	2.00
	lower hose	1.00
	Thermostat	1.00
	Radiator Hose To Engine	1.00
	Thermostat Seal	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 9.85	Labor: 591.00	Parts: 921.48
:		Total: 1,512.48

Workorder: 1412457 **Meter:** 26208 **In Date:** 11/19/2014 **Closed:** 12/12/2014
Problem: damage to rgt door

- damage to rgt door			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1503017 **Meter:** 26413 **In Date:** 03/24/2015 **Closed:** 03/31/2015

Problem: Check engine light on.

<ul style="list-style-type: none"> - Computer diagnose for check engine light on.code P0191.pinpoint test and test fuel pressure.drain fuel tank and replace defective fuel pump assembly,filter and fuel rail pressure sensor.clear code with scan tool and retest. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Fuel Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Fuel Pump W/sender</td><td></td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td></td><td align="right">1.00</td></tr> <tr><td>Fuel Sensor</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Fuel Filter		1.00	Fuel Pump W/sender		1.00	Gasket		1.00	Fuel Sensor		1.00	Shop Supplies		1.00
Parts List		Qty																	
Napagold Fuel Filter		1.00																	
Fuel Pump W/sender		1.00																	
Gasket		1.00																	
Fuel Sensor		1.00																	
Shop Supplies		1.00																	
Hours 5.50 :	Labor: 330.00 Parts: 720.88 Total: 1,050.88																		

Workorder: 1506198 **Meter:** 26783 **In Date:** 06/19/2015 **Closed:** 06/25/2015

Problem: Pm service.Check ac blows warm air.

<ul style="list-style-type: none"> - Pm service. - Performance test Ac system.charge low.inspect for leaks.replace accumulator-service port leak.evacuate and recharge.retest-ok. - Replace two failed front body mounts. - Rotate and balance four tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>5w20 Engine Oil</td><td></td><td align="right">7.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Bulb</td><td></td><td align="right">1.00</td></tr> <tr><td>Pedal Pad</td><td></td><td align="right">1.00</td></tr> <tr><td>Wd40 16oz</td><td></td><td align="right">1.00</td></tr> <tr><td>R134a Lv Shop 2</td><td></td><td align="right">2.00</td></tr> <tr><td>Body Mount Kit</td><td></td><td align="right">2.00</td></tr> <tr><td>Accumulator</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	5w20 Engine Oil		7.00	Napagold Oil Filter		1.00	Wiper Blade		2.00	Bulb		1.00	Pedal Pad		1.00	Wd40 16oz		1.00	R134a Lv Shop 2		2.00	Body Mount Kit		2.00	Accumulator		1.00	Shop Supplies		1.00
Parts List		Qty																																
5w20 Engine Oil		7.00																																
Napagold Oil Filter		1.00																																
Wiper Blade		2.00																																
Bulb		1.00																																
Pedal Pad		1.00																																
Wd40 16oz		1.00																																
R134a Lv Shop 2		2.00																																
Body Mount Kit		2.00																																
Accumulator		1.00																																
Shop Supplies		1.00																																
Hours 8.75 :	Labor: 525.00 Parts: 252.20 Total: 777.20																																	

Workorder: 1508213 **Meter:** 27361 **In Date:** 08/17/2015 **Closed:** 08/25/2015

Problem: Check fuel gauge not reading full.Strobe light inop.Install cooler rack.

<ul style="list-style-type: none"> - Diagnose fuel gauge not working properly.test circuits.replace defective fuel pump/sender unit.remove and install fuel tank.to acess.add fuel. - Diagnose strobe lamp in light bar not working.replace defective in line fuse holder.replace one switch in control box.fabricate wiring as needed. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Fuel Pump W/sender</td><td></td><td align="right">1.00</td></tr> <tr><td>Gasket</td><td></td><td align="right">1.00</td></tr> <tr><td>Fuse Holder</td><td></td><td align="right">1.00</td></tr> <tr><td>Rocker Switch</td><td></td><td align="right">1.00</td></tr> <tr><td>Water Cooler Holder</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Fuel Pump W/sender		1.00	Gasket		1.00	Fuse Holder		1.00	Rocker Switch		1.00	Water Cooler Holder		1.00	Shop Supplies		1.00
Parts List		Qty																				
Fuel Pump W/sender		1.00																				
Gasket		1.00																				
Fuse Holder		1.00																				
Rocker Switch		1.00																				
Water Cooler Holder		1.00																				
Shop Supplies		1.00																				
Hours 6.00 :	Labor: 360.00 Parts: 649.25 Total: 1,009.25																					

Workorder: 1510725 **Meter:** 27551 **In Date:** 10/23/2015 **Closed:** 10/28/2015

Problem: Left front tire flat.

<ul style="list-style-type: none"> - Inspect and replace left front tire.hole in side wall. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>179636492 Lt245-75r17</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	179636492 Lt245-75r17		1.00	Shop Supplies		1.00	Tire Disposal Fee		1.00
Parts List		Qty											
179636492 Lt245-75r17		1.00											
Shop Supplies		1.00											
Tire Disposal Fee		1.00											
Hours 0.50 :	Labor: 30.00 Parts: 261.87 Total: 291.87												

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1601761 **Meter:** 27772 **In Date:** 02/19/2016 **Closed:** 02/24/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.	5w20 Engine Oil	7.00
- Inspect and replace both defective front suspension bump stops.	Napagold Oil Filter	1.00
- Inspect and perform transmission flush and replace filter.	20" Wiper Blade	2.00
- Rotate and balance all four wheels.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished bumper	1.00
	Syn-atf Trans Fluid S	20.00
	Atp Filter	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 7.75	Labor: 465.00	Parts: 311.36
:		Total: 776.36

Workorder: 1609214 **Meter:** 28525 **In Date:** 09/02/2016 **Closed:** 10/18/2016
Problem: P.M. service and towed in die on road.

- P.m. Service.	Parts List	Qty
- Check fuel pressure,below specs.r&r fuel tank and replace fuel pump module.refill tank.	5w20 Engine Oil	7.00
- Replace four rear worn out body mounts.	Napagold Oil Filter	1.00
- Replace rear axle bounce stoppers.	Napagold Fuel Filter	1.00
- Rotate and balance tires.	20" Wiper Blade	2.00
- Diagnose computer system.p0191.perform pin [oint test.replace defective fuel pump and driver modulr.replace melted connector.clear codes.	Used Fire X Refurbished	1.00
- Shop Supplies	Fuel Pump W/sender	1.00
	Gasket	1.00
	Bumper	2.00
	Body Mount Kit	4.00
	Fuel Pump Drive Module	1.00
	Fuel Pig Tail Connector	1.00
	Shop Supplies	1.00
Hours 17.25	Labor: 1,035.00	Parts: 1,307.78
:	0	Total: 2,342.78

Workorder: 1609223 **Meter:** 28119 **In Date:** 09/02/2016 **Closed:** 09/02/2016
Problem: Died while driving

- Tow From: Linton Blvd west of Jog Rd. To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1609765 **Meter:** 28506 **In Date:** 09/16/2016 **Closed:** 09/19/2016
Problem: hesistates

- Tow From: sansbury way just n of Belvedere To: lv shp			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701106 **Meter:** 28525 **In Date:** 02/02/2017 **Closed:** 02/09/2017
Problem: remove canceiver

- Remove Canceiver Issue Fuel Card	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00 Parts: 2.00	Total: 62.00
:		

Workorder: 1704558 **Meter:** 29619 **In Date:** 05/05/2017 **Closed:** 05/22/2017
Problem: P.M. Service.

- P.m. service.	Parts List	Qty
- Replace missing toolbox linkage bolt on driverside handle of box.	Napagold Oil Filter	1.00
- Replace missing license plate bulb cover and burned out bulb.	5w20 Engine Oil	7.00
- Replace front fades asset number.	Mac Wite Lithium Gres	1.00
- High speed balance all four tires.nitro filled tires.	20" Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Lamp Asy	1.00
	Bulb	1.00
	kimball hardware	1.00
	Shop Supplies	1.00
Hours 5.25	Labor: 315.00 Parts: 192.11	Total: 507.11
:		

Workorder: 1707811 **Meter:** 30654 **In Date:** 08/09/2017 **Closed:** 08/15/2017
Problem: Left rear tail light out.

- Replace left rear marker light bulb.	Parts List	Qty
	Signal Stop Lamp	1.00
Hours 0.50	Labor: 30.00 Parts: 1.83	Total: 31.83
:		

Workorder: 1708217 **Meter:** 30757 **In Date:** 08/21/2017 **Closed:** 08/25/2017
Problem: tire

- R/r left rear tire	Parts List	Qty
- Shop Supplies	179636492 Lt245-75r17	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00 Parts: 259.75	Total: 319.75
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711057 **Meter:** 30781 **In Date:** 11/08/2017 **Closed:** 11/15/2017
Problem: Right rear tail light out, PM Service

<ul style="list-style-type: none"> - Replace failed light bulb for right rear tail light. - P.m. service. - Replace right side seal beam headlamp. - Rotate and high speed balance all four tires. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Bulb 5w20 Engine Oil Napagold Oil Filter 20" Wiper Blade Used Fire X Refurbished Stg Wheel Cov - Ford Halogen Lamp Napagold Fuel Filter Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 2.00 7.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 	
Hours 4.75 :	Labor: 285.00	Parts: 79.10	Total: 364.10

Workorder: 1804876 **Meter:** 32961 **In Date:** 05/10/2018 **Closed:** 05/22/2018
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Replace one tire on left front .rotate and high speed balance all four tires.nitrofill. - Inspect and service transfer case .drain and refill. - Test and replace right side alley light bulb in light bar. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> 5w20 Engine Oil Napagold Oil Filter Napagold Air Filter 22" Wiper Blade Mac Wite Lithium Gres Ford Transfer Case Fluid Used Fire X Refurbished 179636492 Lt245-75r17 Halogen Bulb 20" Wiper Blade Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 7.00 1.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00 2.00 1.00 1.00 	
Hours 6.75 :	Labor: 405.00	Parts: 310.74	Total: 715.74

Workorder: 1806071 **Meter:** 33274 **In Date:** 06/14/2018 **Closed:** 06/20/2018
Problem: Left rear signal out.

<ul style="list-style-type: none"> - Replace left tail light bulb and socket. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Boxed Miniatures Socket Asy Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 1.00 	
Hours 0.75 :	Labor: 45.00	Parts: 24.98	Total: 69.98

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1811335 **Meter:** 34073 **In Date:** 11/01/2018 **Closed:** 11/06/2018
Problem: PM Service

- P.m. service.	Parts List	Qty
- Replace left headlight bulb . Due to moisture in bulb.	Napagold Oil Filter	1.00
- Diagnose rattle in rear of vehicle . R&r defective rear shocks .	Napa Quart 5w20	7.00
	Washer Fluid Concentr	1.00
- Diagnose tire pressure light . Replace defective sensor in left front tire . Rotate and balance all four tires . Nitrogen fill tires and reset Tpms.	22" Wiper Blade	2.00
	Napagold Fuel Filter	1.00
- Shop Supplies	Halogen Sealed Beams	1.00
	Gas Grande Shock	2.00
	Tpms5 Sensor Tire Pre	1.00
	Shop Supplies	1.00
Hours 6.25	Labor: 418.75	Parts: 304.68
:		Total: 723.43

Workorder: 1904592 **Meter:** 34668 **In Date:** 04/26/2019 **Closed:** 04/30/2019
Problem: PM Service

- P.m. service.	Parts List	Qty
- Rotate and balance all four tires . Nitrofill all and reset Tpms .	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.75	Labor: 251.25	Parts: 43.95
:		Total: 295.20

Workorder: 1905402 **Meter:** 34890 **In Date:** 05/17/2019 **Closed:** 05/22/2019
Problem: Right front wheel/brake issue.

- Test drive to duplicate concern . Resurface both front brake rotors . Replace calipers , pads and both front brake hoses . Flush and bleed brake system . Road test .	Parts List	Qty
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Pads	1.00
	Brake Hose	1.00
	Brake Sohe	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 335.00	Parts: 300.77
:		Total: 635.77

Workorder: 1905496 **Meter:** 34986 **In Date:** 05/23/2019 **Closed:** 05/29/2019
Problem: Had to jump start .

- Charge battery fully . Test battery and charging system . R&r defective battery .	Parts List	Qty
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 128.01
:		Total: 195.01

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1907112	Meter: 35380	In Date: 07/10/2019	Closed: 07/16/2019
Problem: Low tire pressure light on .			
- Replace two tire on rear and balance . Nitrofill all.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		Lt245/75r17 Tire	2.00
		Tire Disposal Fee	2.00
Hours 1.00	Labor: 67.00	Parts: 246.97	Total: 313.97
:			
Workorder: 1908627	Meter: 35862	In Date: 08/16/2019	Closed: 08/19/2019
Problem: Tire shake/vibration.			
- Balance and road force and index all four tires . Road test .		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 67.00	Parts: 3.00	Total: 70.00
:			
Workorder: 1911028	Meter: 36405	In Date: 10/25/2019	Closed: 10/29/2019
Problem: Right brake light inop .			
- Test and replace right brake light bulb and socket .		Parts List	Qty
		Stp Trn TI Lgt Socket	1.00
		Boxed Miniatures	1.00
Hours 0.50	Labor: 36.50	Parts: 10.11	Total: 46.61
:			
Workorder: 1911805	Meter: 36810	In Date: 11/14/2019	Closed: 11/18/2019
Problem: P.M. service.			
- P.m. service.		Parts List	Qty
- Rotate and high speed balance all four tires . Nitrofill all .		Napagold Oil Filter	1.00
- Shop Supplies		5w20 Engine Oil	7.00
		20" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		Napagold Fuel Filter	1.00
		Washer Nozzle	2.00
		Shop Supplies	1.00
Hours 3.75	Labor: 273.75	Parts: 56.56	Total: 330.31
:			
Workorder: 1912982	Meter: 36810	In Date: 12/18/2019	Closed: 12/18/2019
Problem: Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			