

**Palm Beach County Fleet Management
Asset Maintenance History**

10189449 2012 TORO GRNDSMSTR 7200 Mower, Zero Turn Radius (Ztr), 72 In.

Workorder: 1208587 **Meter:** 1 **In Date:** 09/11/2012 **Closed:** 09/11/2012
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1210677 **Meter:** 1057 **In Date:** 11/01/2012 **Closed:** 11/08/2012
Problem: need nut and washer to hold up deck

- reattached deck bolt and adj

Hours 0.50 Labor: 30.00 Parts: 0.00 Total: 30.00
 :

Workorder: 1212337 **Meter:** 1057 **In Date:** 12/26/2012 **Closed:** 01/10/2013
Problem: NEEDS NEW CHUTE,R/FRONT TIRE COMES OF RIM

- ck new chute verify complaint replace chute

Parts List **Qty**

- ck tire off rim clean bead rim rr valve stem remount add n2

Deflector 1.00

- Shop Supplies

Shop Supplies 1.00

Freight Charge 1.00

Hours 1.50 Labor: 90.00 Parts: 75.31 Total: 165.31
 :

Workorder: 1301741 **Meter:** 174 **In Date:** 02/20/2013 **Closed:** 03/13/2013
Problem: right front tire flat, right back tire losing air, chain on deck come apart right side of deckck...

- ck chains fell off verify complaint replace multiple deck linkage coimponents adj and test mow

Parts List **Qty**

Nut 2.00

- ck two flat tires fr and rr repair two tires add n2

Clevis Pin 2.00

- Shop Supplies

Rue Ring Pin 2.00

Locknut 2.00

T Bar Assembly 2.00

Shop Supplies 1.00

Freight Charge 1.00

Hours 4.50 Labor: 270.00 Parts: 75.14 Total: 345.14
 :

Workorder: 1303097 **Meter:** 197 **In Date:** 03/29/2013 **Closed:** 04/10/2013
Problem: right front tire flat,, deck bolts and nuts are loose left side ck all nuts and bolts

- ck deck bolts and adjust replace muliple linkage components adj and test mow

Parts List **Qty**

Nut 10.00

- ck fr tire flat dismount clean bead and rim rr valve stem add n2

Locknut 10.00

- Shop Supplies

Clevis Pin 5.00

Rue Ring Pin 5.00

T Bar Assembly 2.00

Shop Supplies 1.00

Hours 3.00 Labor: 180.00 Parts: 173.41 Total: 353.41
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1307497 **Meter:** 413 **In Date:** 07/26/2013 **Closed:** 09/12/2013

Problem: p.m.service,fuel cap,tires,hinge on top broke,see note

	Parts List	Qty
- pm		
- ck front tires replace two front tires mount add n2 replace whee lbearings	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
- ck fuel cap deck etc replace multiple deck linkage components fuel cap etc test mow	Napagold Oil Filter	1.00
	15w40 Bulk South Reg	4.00
- Shop Supplies	15-600-6 Nhs Str Rib 04	2.00
	Fuel Cap	1.00
	Yoke Clevis	2.00
	Clevis Pin	2.00
	Rue Ring Pin	2.00
	T Bar Assembly	2.00
	Roller Scalp	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 10.00	Labor: 600.00	Parts: 271.79 Total: 871.79
:		

Workorder: 1311090 **Meter:** 502 **In Date:** 10/31/2013 **Closed:** 11/14/2013

Problem: REPLACE FRONT TIRE/FIX DECK CHAIN R/SIDE BACK

	Parts List	Qty
- ck replace all tires replace front and rear tires mount add n2	Tire	2.00
- repair deck linkage and adjust	24-1200-12b Turf M Carl	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 3.00	Labor: 180.00	Parts: 386.52 Total: 566.52
:		

Workorder: 1402647 **Meter:** 647 **In Date:** 03/19/2014 **Closed:** 03/27/2014

Problem: replace front tires, flap , missing wing nuts on deck, adjustable height right side, one deck chain

	Parts List	Qty
- ck front tires hand mouint add n2 grease wheel bearings	Tire	2.00
- ck pin chute adj chain	Rubber Deflector Assy	1.00
- Shop Supplies	Knob	2.00
	Nut Retainer	2.00
	Clevis Pin	4.00
	Rue Ring Pin	4.00
	Pin Hoc	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 276.58 Total: 606.58
:		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1403321 **Meter:** 655 **In Date:** 04/04/2014 **Closed:** 05/28/2014
Problem: front deck will not stay up positoin, hyd leak replace wiring nuts deck

- install new knobs replace knobs	Parts List	Qty
- ck hyd leak deck wont stay up replace leaking hyd pump	Knob	1.00
rebuild hyd cyl replace valve assm correct fluid level test run	Gear Pump Assy	1.00
- Shop Supplies	O-ring	1.00
	Seal Kit	1.00
	Aw68 Bulk Sr	5.00
	Spline Coupler	1.00
	Valve	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 7.50	Labor: 450.00	Parts: 1,437.05
:		Total: 1,887.05

Workorder: 1405628 **Meter:** 657 **In Date:** 06/06/2014 **Closed:** 06/12/2014
Problem: FIX DECK SCREW,NUT,CHAIN/FLAT TIRE

- Replace Damaged Lr Tire Dismount Mount Add N2	Parts List	Qty
- ck screw on deck repair deck linkage adjust	24-1200-12b Turf M Carl	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 2.50	Labor: 150.00	Parts: 164.05
:		Total: 314.05

Workorder: 1407615 **Meter:** 729 **In Date:** 08/01/2014 **Closed:** 08/19/2014
Problem: FIX DECK AND TWO NEW TIRES IN THE FRONT

- ck tires repair fl and rr tire grease bearings add n2	Parts List	Qty
- ck repair deck repair linkage on deck adj and test mow	Shop Supplies	1.00
- Shop Supplies		
Hours 4.00	Labor: 240.00	Parts: 2.00
:		Total: 242.00

Workorder: 1410262 **Meter:** 832 **In Date:** 10/14/2014 **Closed:** 10/23/2014
Problem: P.M.SERVICE,WONT START.

- pm	Parts List	Qty
- svc hyd sys inspect lines hoses replace filter correct fluid level	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
- wash eq	Napagold Oil Filter	1.00
- ck wont start found blown fuses replace fuse clean connections test drive multiple times	15w40 Bulk South Reg	4.00
- Shop Supplies	Napa Hydraulic Filtr	1.00
	Aw68 Bulk Sr	2.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 58.13
:		Total: 478.13

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1411846	Meter: 841	In Date: 11/24/2014	Closed: 12/04/2014
Problem: WILL NOT START/TIRE FRONT DECK			
- will not start verify fuel shut off solenoid bad replace solenoid test run	Parts List		Qty
	Stop Solenoid		1.00
- replace two front tires mount add n2 grease bearings	15-600-6 Nhs Str Rib 04		2.00
- Shop Supplies	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 3.50	Labor: 210.00	Parts: 483.00	Total: 693.00
:			
Workorder: 1503078	Meter: 905	In Date: 03/25/2015	Closed: 04/07/2015
Problem: 4 new tires front rims			
- ck 4 new tires and rims replace two rear tires front tires and rim assm	Parts List		Qty
	Tire & Wheel Assy		2.00
- Shop Supplies	24-1200-12b Turf M Carl		2.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 2.00	Labor: 120.00	Parts: 732.33	Total: 852.33
:			
Workorder: 1505888	Meter: 955	In Date: 06/12/2015	Closed: 06/19/2015
Problem: bolt broken on deck			
- broken bolt on deck verify complaint remove gear box assm drill out broken bolts reassemble adj all test mow	Parts List		Qty
	Shop Supplies		1.00
- Shop Supplies			
Hours 5.00	Labor: 300.00	Parts: 2.00	Total: 302.00
:			
Workorder: 1509773	Meter: 1080	In Date: 09/28/2015	Closed: 10/20/2015
Problem: pm, make sure all grease fittings are on mower, air filter cover, need a new shout			
- pm	Parts List		Qty
- ck chut replace discharge chute anti scalp wheels and air filter cover	Napagold Air Filter		1.00
	Napagold Fuel Filter		1.00
- svc hyd sys inspect lines hoses correct fluid level	Napagold Oil Filter		1.00
- wash eq	15w40 Bulk South Reg		4.00
- Shop Supplies	Mac Battery Protect		1.00
	Air Cleaner Cover Assy		1.00
	Valve-actuator		1.00
	Deflector		1.00
	Roller Scalp		2.00
	Tube-spanner		2.00
	Tube Spacer		2.00
	Screw		2.00
	Flange Nut Ni		2.00
	Shop Supplies		1.00
Hours 8.00	Labor: 480.00	Parts: 300.49	Total: 780.49
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1601966 **Meter:** 1162 **In Date:** 02/25/2016 **Closed:** 03/17/2016

Problem: new front tires , fix crank fender, new knob for inspeciton plates

- ck front tires had mount 2 front tires grease	Parts List	Qty
- ck knob replace knob and bushing buckets on gear box test mow	15-600-6 Nhs Str Rib 04	2.00
	Knob	2.00
- ck jump start test battery bad replace battery ck charging sys	Nut Retainer	2.00
	Grommet	4.00
- Shop Supplies	Gearbox Bracket Lh	1.00
	Gearbox Bracket Rh	1.00
	Rubber Mount	4.00
	Bolt	3.00
	Group 26 Delco	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.25	Labor: 375.00	Parts: 444.06
:		Total: 819.06

Workorder: 1606865 **Meter:** 1279 **In Date:** 07/07/2016 **Closed:** 07/29/2016

Problem: Check belt on blades noisy.Deck cuts uneven.Grease fittings.

- C/c belt,blades,uneven etc..replace both belts.bracket,bushings.all linkage.hardware and adjust .lube all,test mow.	Parts List	Qty
	Yoke Clevis	4.00
	Nut	4.00
- Shop Supplies	Clevis Pin	4.00
	Rue Ring Pin	4.00
	Locknut	4.00
	Flange Nut Ni	3.00
	Rubber Mount	3.00
	Bolt	3.00
	V-belt	1.00
	V-belt	1.00
	Idler Pulley	1.00
	Tbar	4.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 383.20
:		Total: 713.20

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612130 **Meter:** 1446 **In Date:** 11/28/2016 **Closed:** 12/08/2016
Problem: pm/ tires/ wheel/ fender/ chute/ see notes

	Parts List	Qty
- Pm		
- Hyd Service	Air Cleaner Assy	1.00
- Replace All tires and 1 wheel	Napagold Oil Filter	1.00
- R&r side chute and straightened all mounting brackets and Replace. Rubber deflector. R&r hood to install reinforce brackets behind hood crack and repair 1 hood latch	Napagold Fuel Filter	1.00
	15-40 Oil	4.00
- Replace 3 blades	Napa Hydraulic Filtr	1.00
- Shop Supplies	24-1200-12b Turf M Carl	2.00
	15-600-6 Nhs Str Rib 04	1.00
	Rotary Blade	3.00
	Tire & Wheel Assy	1.00
	Deflector	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	3.00
Hours 11.50	Labor: 690.00	Parts: 1,300.01
:		Total: 1,990.01

Workorder: 1701763 **Meter:** 1532 **In Date:** 02/17/2017 **Closed:** 03/13/2017
Problem: BLADE BELT BROKEN, L/WHEEL GOING BAD, FRONT BEARINGS

	Parts List	Qty
- C/c belts,bearings,etc..replace all deck rollers,r/h belt.install new R/h deck roller.lube all pulleys and tensioners	V-belt	1.00
- Verrify two front rims bent.replace two front tires and wheel assm.add N2 and test run.	Flange Nut Ni	2.00
- Shop Supplies	Screw	2.00
	Tube-spanner	2.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	15-6.00x6 Ribbed Tire	2.00
	cover deck rh	1.00
	Nut	1.00
	Spacer-roller	1.00
	Roller,deck	1.00
	Bolt	1.00
	Roller	1.00
	Shaft,roller	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 1,000.99
:		Total: 1,330.99

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1702614 **Meter:** 1541 **In Date:** 03/14/2017 **Closed:** 03/31/2017
Problem: Hydraulic leak.Check rollers front deck.

- C/c hyd. leak.verify hyd.hose leaking.replace hose and multi o-rings.refill hyd. system.test run.	Parts List	Qty
- Replace front rollers,pins,shaft.lube all spindles and tensioners	O-ring	3.00
- Wash equipment for diagnosis and repair.	Clevis Pin	4.00
- Shop Supplies	Rue Ring Pin	4.00
	Flange Nut Ni	1.00
	Roller	1.00
	Shaft,roller	1.00
	Screw	1.00
	Hose Assy	1.00
	Fitting	1.00
	O Ring	3.00
	Aw68 Bulk Sr	14.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 6.50	Labor: 390.00	Parts: 405.63
:		Total: 795.63

Workorder: 1704427 **Meter:** 1564 **In Date:** 05/02/2017 **Closed:** 05/15/2017
Problem: NEEDS FRONT TIRES

- C/c needs front tires. Replace front tires.hand mount.add N2.repack wheel bearings.	Parts List	Qty
- Shop Supplies	Tire	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 70.73
:		Total: 190.73

Workorder: 1705294 **Meter:** 1585 **In Date:** 05/30/2017 **Closed:** 06/12/2017
Problem: Two new front tires.

- C/c front tires.replace front tires.hand mount.add N2.repack wheel bearings.	Parts List	Qty
- Shop Supplies	Tire	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 70.73
:		Total: 190.73

Workorder: 1706315 **Meter:** 1611 **In Date:** 06/27/2017 **Closed:** 06/30/2017
Problem: Two front tires.

- C/c two front tires.replace two front tires,hand mount,lube and add N2	Parts List	Qty
- Replace two rear anti-scalp wheels	15-600-6 Nhs Str Rib 04	2.00
- Shop Supplies	Flange Nut Ni	2.00
	Screw	2.00
	Tube-spanner	2.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	9"x14tpi Sawzall	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 3.75	Labor: 225.00	Parts: 187.67
:		Total: 412.67

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1707879 **Meter:** 1651 **In Date:** 08/11/2017 **Closed:** 08/21/2017

Problem: Broken front rim.Replace chute.

	Parts List	Qty
- C/c front left tire.r/r front left tire/wheel assm.		
- C/c chute.replace chute assm.	15-6.00x6 Ribbed Tire	1.00
- Shop Supplies	Rubber Deflector Assy	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 487.30
:		Total: 607.30

Workorder: 1710335 **Meter:** 1726 **In Date:** 10/20/2017 **Closed:** 11/13/2017

Problem: Gearbox,motor mount,bolt on blade deck.Left side broken deck hinge.

	Parts List	Qty
- C/c pin,bolts,gear box etc...install new deck pin.r/r gear box,bracket and bushings.lube all.	Pin Retainer	1.00
- Replace two deck belts.	Spacer	1.00
- Replace air cleaner assembly.	Screw	1.00
- Wash equipment.	Nut	1.00
- Shop Supplies	Gearbox Bracket Rh	1.00
	Gearbox Bracket Lh	1.00
	Washer	3.00
	Rubber Deflector Assy	1.00
	Flange Nut Ni	3.00
	Rubber Mount	3.00
	Bolt	3.00
	V-belt	1.00
	V-belt	1.00
	Air Cleaner Assy	1.00
	Shop Supplies	1.00
Hours 9.25	Labor: 555.00	Parts: 824.72
:		Total: 1,379.72

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711585 **Meter:** 1737 **In Date:** 11/27/2017 **Closed:** 12/11/2017
Problem: PM Service,Seat belt.Right small wheel.

	Parts List	Qty
- Pm Service.		
- Service hyd.system.inspect lines,hoses etc.. Correct fluid level.	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
- C/c wheels and seat belt.replace seat belt assembly.	Napagold Oil Filter	1.00
- Wash equipment.	15w40 Bulk South Reg	4.00
- Replace right front tire.hand mount and add N2.	15-600-6 Nhs Str Rib 04	1.00
- Shop Supplies	Seat Belt Kit	1.00
	Rubber Mount	6.00
	Grommet	8.00
	Plate Roller	1.00
	Locknut	3.00
	323-11 Screw Toro	3.00
	Flange Nut Ni	2.00
	Screw	2.00
	Tube-spanner	2.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00

Hours 9.50 Labor: 570.00 Parts: 605.26 Total: 1,175.26
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1804885 **Meter:** 1910 **In Date:** 05/10/2018 **Closed:** 05/30/2018

Problem: Need all new tires,new left front wheel,bushing and bolts for gearbox and chute

	Parts List	Qty
- C/c R/r four tires.replace four tires.mount and add N2		
- Replace Chute,bolts,wheels,brackets and bushings etc..	15-6.00x6 Ribbed Tire	1.00
- Replace Pto idler pulley and lube all.	15x6.00-6	1.00
- Install caliper service kit for E-brakes.	24x12.00-12 Turf Trac 6p Tire	2.00
- Wash equipment for service.	V-belt	1.00
- Shop Supplies	V-belt	1.00
	Roller	1.00
	Roller Scalp	2.00
	Tube Spacer	2.00
	Gearbox Bracket Rh	1.00
	Rubber Deflector Assy	1.00
	Rubber Mount	3.00
	Washer	3.00
	Bolt	3.00
	Gearbox Bracket Lh	1.00
	Grommet	4.00
	Shaft,roller	1.00
	Nut	1.00
	Spacer-roller	1.00
	Roller,deck	1.00
	Bolt	1.00
	Screw	2.00
	Tube-spanner	2.00
	Idler Spacer	1.00
	Idler Pulley	1.00
	Flange Nut Ni	5.00
	Rear Brake Pad Kit	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours 9.00

:

Labor: 540.00

Parts: 1,842.35

Total: 2,382.35

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1807970 **Meter:** 2039 **In Date:** 08/03/2018 **Closed:** 09/28/2018
Problem: Gear box bushings and front tires.

<ul style="list-style-type: none"> - Replace front tire.mount,grease.add N2 - C/c gear box.replace gear box bushings/brackets and fabricate due to mounting holes on deck worn out.change gear box oil.lube shaft.r/r wheels etc.. - Repair right rear tires. - Wash equipment. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>15-600-6 Nhs Str Rib 04</td><td align="right">1.00</td></tr> <tr><td>V-belt</td><td align="right">1.00</td></tr> <tr><td>Washer</td><td align="right">3.00</td></tr> <tr><td>Rubber Mount</td><td align="right">3.00</td></tr> <tr><td>Bolt</td><td align="right">3.00</td></tr> <tr><td>Flange Nut Ni</td><td align="right">3.00</td></tr> <tr><td>Gearbox Bracket Lh</td><td align="right">1.00</td></tr> <tr><td>Gearbox Bracket Rh</td><td align="right">1.00</td></tr> <tr><td>Deflector</td><td align="right">1.00</td></tr> <tr><td>Pulley</td><td align="right">1.00</td></tr> <tr><td>Roller Scalp</td><td align="right">2.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> <tr><td>Tire Disposal Fee</td><td align="right">1.00</td></tr> </tbody> </table>	Parts List	Qty	15-600-6 Nhs Str Rib 04	1.00	V-belt	1.00	Washer	3.00	Rubber Mount	3.00	Bolt	3.00	Flange Nut Ni	3.00	Gearbox Bracket Lh	1.00	Gearbox Bracket Rh	1.00	Deflector	1.00	Pulley	1.00	Roller Scalp	2.00	Shop Supplies	1.00	Tire Disposal Fee	1.00
Parts List	Qty																												
15-600-6 Nhs Str Rib 04	1.00																												
V-belt	1.00																												
Washer	3.00																												
Rubber Mount	3.00																												
Bolt	3.00																												
Flange Nut Ni	3.00																												
Gearbox Bracket Lh	1.00																												
Gearbox Bracket Rh	1.00																												
Deflector	1.00																												
Pulley	1.00																												
Roller Scalp	2.00																												
Shop Supplies	1.00																												
Tire Disposal Fee	1.00																												
Hours 6.00 :	<table border="0"> <tr> <td>Labor: 360.00</td> <td>Parts: 588.46</td> <td>Total: 948.46</td> </tr> </table>	Labor: 360.00	Parts: 588.46	Total: 948.46																									
Labor: 360.00	Parts: 588.46	Total: 948.46																											

Workorder: 1810015 **Meter:** 2089 **In Date:** 09/27/2018 **Closed:** 11/19/2018
Problem: Hydraulic oil leak under seat area.

<ul style="list-style-type: none"> - Replace o-rings on transmission lines.seat in hyd.lift valve due to deck not staying up.correct fluid level.replace hyd.hose. - Wash equipment. - Adjust deck linkages and re-secure gear box bushings.remove tensioners and lube. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Seat</td><td align="right">1.00</td></tr> <tr><td>O Ring</td><td align="right">4.00</td></tr> <tr><td>O-ring</td><td align="right">4.00</td></tr> <tr><td>Aw68 Bulk Sr</td><td align="right">3.00</td></tr> <tr><td>O-ring</td><td align="right">1.00</td></tr> <tr><td>O-ring</td><td align="right">1.00</td></tr> <tr><td>Washer</td><td align="right">2.00</td></tr> <tr><td>Poppet</td><td align="right">1.00</td></tr> <tr><td>O-ring</td><td align="right">2.00</td></tr> <tr><td>O Ring</td><td align="right">1.00</td></tr> <tr><td>Oring</td><td align="right">1.00</td></tr> <tr><td>Hose Assy</td><td align="right">1.00</td></tr> <tr><td>O-ring</td><td align="right">1.00</td></tr> <tr><td>Fitting</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> <tr><td>Freight Charge</td><td align="right">1.00</td></tr> <tr><td>Freight Charge</td><td align="right">1.00</td></tr> </tbody> </table>	Parts List	Qty	Seat	1.00	O Ring	4.00	O-ring	4.00	Aw68 Bulk Sr	3.00	O-ring	1.00	O-ring	1.00	Washer	2.00	Poppet	1.00	O-ring	2.00	O Ring	1.00	Oring	1.00	Hose Assy	1.00	O-ring	1.00	Fitting	1.00	Shop Supplies	1.00	Freight Charge	1.00	Freight Charge	1.00
Parts List	Qty																																				
Seat	1.00																																				
O Ring	4.00																																				
O-ring	4.00																																				
Aw68 Bulk Sr	3.00																																				
O-ring	1.00																																				
O-ring	1.00																																				
Washer	2.00																																				
Poppet	1.00																																				
O-ring	2.00																																				
O Ring	1.00																																				
Oring	1.00																																				
Hose Assy	1.00																																				
O-ring	1.00																																				
Fitting	1.00																																				
Shop Supplies	1.00																																				
Freight Charge	1.00																																				
Freight Charge	1.00																																				
Hours 8.00 :	<table border="0"> <tr> <td>Labor: 536.00</td> <td>Parts: 350.16</td> <td>Total: 886.16</td> </tr> </table>	Labor: 536.00	Parts: 350.16	Total: 886.16																																	
Labor: 536.00	Parts: 350.16	Total: 886.16																																			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1812190 **Meter:** 2096 **In Date:** 11/29/2018 **Closed:** 12/12/2018
Problem: pm/ deck belt keeps comming off

- pm service	Parts List	Qty
- hydraulic service	Napagold Oil Filter	1.00
- test and replace battery	15-40 Oil	4.00
- replace damaged deck with good surplus deck	Napagold Air Filter	1.00
- wash equipment	Napagold Fuel Filter	1.00
- Shop Supplies	Non-chlor Brake Clnr	4.00
	Napa Hydraulic Filtr	1.00
	Aw68 Hydro Fluid Hydr	4.00
	Battery	1.00
	Shop Supplies	1.00
Hours 12.00	Labor: 804.00	Parts: 205.50
:		Total: 1,009.50

Workorder: 1900569 **Meter:** 2132 **In Date:** 01/15/2019 **Closed:** 01/22/2019
Problem: Check all front tires for flat.

- Inspect all tires.correct N2 levels.replace valve stem covers.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 0.75	Labor: 50.25	Parts: 3.00
:		Total: 53.25

Workorder: 1903334 **Meter:** 2164 **In Date:** 03/27/2019 **Closed:** 03/29/2019
Problem: Hydraulic oil leak.

- Replace o-ring on top of hyd.pump.correct fluid level Clean hyd.fluid off of unit verify no leaks.	Parts List	Qty
- Shop Supplies	Aw68 Bulk Sr	10.00
	Shop Supplies	1.00
Hours 2.75	Labor: 184.25	Parts: 22.80
:		Total: 207.05

Workorder: 1906783 **Meter:** 2254 **In Date:** 06/27/2019 **Closed:** 07/22/2019
Problem: PTO inop.Check all tires.Engine cover latch.

- C/c check tires.	Parts List	Qty
- C/c latches etc..replace latches,scalp wheels,grommets,etc...test mow.	Screw	2.00
- C/c pto wont engage.unable to duplicate complain at this time.	Rubber Latch	2.00
- Shop Supplies	Tube Spacer	2.00
	Roller Scalp	2.00
	Tube-spanner	2.00
	Screw	2.00
	Flange Nut Ni	2.00
	Bolt	3.00
	Rubber Mount	3.00
	Grommet	2.00
	15-600-6 Nhs Str Rib 04	2.00
	24x12.00-12/4 Turf Master	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 4.00	Labor: 268.00	Parts: 554.98
:		Total: 822.98

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1907714 **Meter:** 2270 **In Date:** 07/25/2019 **Closed:** 08/19/2019
Problem: belts keeps jumping off.

- C/c belt jumping off.replace gear box bushings tensioner arm and pulley.install new belt on right hand side.install new drive shaft asm.	Parts List	Qty
- Shop Supplies	Pulley	1.00
	Snao Ring	1.00
	Idler Spacer	1.00
	Idler Arm Assy	1.00
	V-belt	1.00
	Rubber Mount	3.00
	Driveshaft	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 3.00	Labor: 201.00	Parts: 1,339.45
:		Total: 1,540.45

Workorder: 1908969 **Meter:** 2289 **In Date:** 08/27/2019 **Closed:** 10/15/2019
Problem: Seat sensor.Seat gets hot.

- C/c Seat gets hot.verify hole in muffler..replace muffler assembly.drill out and retap broken studs.	Parts List	Qty
- C/c seat switch.replace bottom section of seat,	Nut	4.00
- Replace Pto switch.turning off intermittently.	Gasket	1.00
- Shop Supplies	Wd40 Spr	1.00
	Locknut	2.00
	Cap Screw	2.00
	Pto Switch	1.00
	Muffler	1.00
	Stud	4.00
	Bottom Cushion Kit	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 4.50	Labor: 328.50	Parts: 1,068.95
:		Total: 1,397.45

Workorder: 1911551 **Meter:** 2338 **In Date:** 11/06/2019 **Closed:** 11/25/2019
Problem: BATTERY/ LIGHT/AIR FILTER HOUSING.

- Dead battery.recharge and load test.battery.battery tested good.	Parts List	Qty
- C/c light on dash.found alternator not charging.test alt.bad.r/r alternator.	Powersport Alternator	1.00
- Replace engine V-belt.	V-belt	1.00
- Repair hood latch.	Shop Supplies	1.00
- Shop Supplies		
Hours 6.00	Labor: 438.00	Parts: 369.36
:		Total: 807.36

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1912472 **Meter:** 2356 **In Date:** 12/05/2019 **Closed:** 12/06/2019

Problem: broken air filter cover

- replace filter cover
- Shop Supplies

Parts List

	Qty
Valve-actuator	1.00
Air Cleaner Cover Assy	1.00
Shop Supplies	1.00

Hours 0.50

Labor: 36.50

Parts: 144.25

Total: 180.75

:

Workorder: 1912478 **Meter:** 2338 **In Date:** 12/05/2019 **Closed:** 12/05/2019

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00

Labor: 146.00

Parts: 0.00

Total: 146.00

: