

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 552436

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 08/08/2005	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge:	0.00	Labor Charge:	100.00

Workorder: 554715

Problem: HYD. LEAK

Meter Reading: 2	Labor	Parts	
In Date: 09/09/2005	Hours	Description	Quantity
- Oil On Top Of Tank Fill Area-Check Fitting And Lines For Leak. System Was Overfilled	2.50	SHOP SUPPLIES	1.00
- Wash			
- Test Run			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	125.00

Workorder: 644678

Problem: P.M.

Meter Reading: 2	Labor	Parts	
In Date: 08/25/2006	Hours	Description	Quantity
- Pm Service	7.50	49-2500 OIL FILTER TORO L/F LFP791 WIX 51261	1.00
- Travel To And From Road And Bridge Warehouse		SHOP SUPPLIES	1.00
- Wont Start Remove Carb. And Clean Solenoid Valve		091343 CARB CLEANER	2.00
- Hydraulic Service		AW100 HYDRAULIC FLUID	2.00
- Shop Supplies		3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00
		BKR5E SPARK PLUG 7938	2.00
		51056 OIL FILTER USE FRAM PH8172	1.00
		10W30 MOTOR OIL	2.00
Parts Charge:	36.47	Labor Charge:	55.00

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 837263

Problem: P.M.

Meter Reading: 11	Labor	Parts	
In Date: 04/21/2008	Hours	Quantity	
Close Date: 04/23/2008	Description		
- Pm Service	6.50	51056 OIL FILTER USE FRAM PH8172	1.00
- Hyd Service		3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00
- Test Run		PH36A OIL FILTER LBF PH6715 WIX 51774	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		BKR5E SPARK PLUG 7938	2.00
		10W30 MOTOR OIL	2.00
Parts Charge:	25.62	Labor Charge: 30.00	

Workorder: 838880

Problem: RIGHT TIRE LOW

Meter Reading: 11	Labor	Parts	
In Date: 05/22/2008	Hours	Quantity	
Close Date: 05/27/2008	Description		
- Ck For Leak And Refill Tire	0.50		
Parts Charge:	0.00	Labor Charge: 30.00	

Workorder: 933770

Problem: NO START

Meter Reading: 11	Labor	Parts	
In Date: 02/10/2009	Hours	Quantity	
Close Date: 02/17/2009	Description		
-			
Parts Charge:	0.00	Labor Charge: 0.00	

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 936357

Problem: P.M./ON TRAILER 10172303 @ ROADS

Meter Reading: 11	Labor	Parts
In Date: 04/10/2009	Hours	Quantity
Close Date: 04/29/2009	Description	
- Pm Unit	7.50	10W30 MOTOR OIL 2.00
- Replace Damaged Foward /Reverse Lever Protective Boot		4788303 AIR FILTER KIT KOHLER 1.00
- Rebuild 2 Frt Wheel Assy Bearings Failed		BKR5E SPARK PLUG 7938 2.00
- Clean Unit		BOOT 1.00
- Shop Supplies		51056 OIL FILTER USE FRAM PH8172 1.00
		FREIGHT \$14.34 1.00
		RACE 2.00
		SEAL 2.00
		SEAL 2.00
		RACE 2.00
		BUSHING 4.00
		SHOP SUPPLIES 1.00
		3032 FUEL FILTER 5/16" FRM G2 WIX 33032 1.00
		BEARING 4.00
		TUBE 4.00
Parts Charge:	234.08	Labor Charge: 450.00

Workorder: 1001996

Problem: DEAD BATTERY

Meter Reading: 11	Labor	Parts
In Date: 02/25/2010	Hours	Quantity
Close Date: 02/26/2010	Description	
- Charge And Ck Battery	1.00	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1003933

Problem: PM

Meter Reading: 11	Labor	Parts	
In Date: 04/16/2010	Hours	Description	Quantity
- Pm	4.00	10W30 MOTOR OIL	2.00
- Repair 2 Tires		51056 OIL FILTER USE FRAM PH8172	1.00
- Shop Supplies		2488303 AIR FILTER KIT KOHLER, JDEER GY20576	1.00
		3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00
		BKR5E SPARK PLUG 7938	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	36.02	Labor Charge:	240.00

Workorder: 1006793

Problem: NO START

Meter Reading: 11	Labor	Parts	
In Date: 06/29/2010	Hours	Description	Quantity
- Remove, Clean Charge, Test Battery-Replace Battery	2.00	BATTERY	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	76.85	Labor Charge:	120.00

Workorder: 1011111

Problem: 2 flat tires

Meter Reading: 11	Labor	Parts	
In Date: 10/08/2010	Hours	Description	Quantity
- Replace Two Front Tires Nitro All Two Tires	2.00	TIRE DISPOSAL FEE	2.00
- Travel To Roads 4X Worked On Vermeer Root Cutter		303408581 16-750-8 TURF CHIEF 4PLY	2.00
Tractor Take Off Front Safety Shield Take Off Two Front Tires Remove Axle Pins And Regrease Rebuild Buck		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	149.23	Labor Charge:	120.00

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1103203

Problem: pm service / needs new teeth

Meter Reading: 24		Labor	Parts	
In Date: 03/24/2011	Close Date: 03/29/2011	Hours	Description	Quantity
- Pm Root Cutter		7.50	FREIGHT	1.00
- Hydraulic Sys Service			NUTS	20.00
- Replace All Teeth, Pockets And Bolts			3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00
- Replace Fuel Line From Pump To Carb (Dry Rotted)			10W30 MOTOR OIL	2.00
- Shop Supplies			BKR5E SPARK PLUG 7938	2.00
			PH36A OIL FILTER LBF PH6715 WIX 51774	1.00
			SHOP SUPPLIES	1.00
			PH8172 OIL FILTER LBF PH2814 WIX DON'T USE	1.00
			LEFT TOOTH	4.00
			STRAIGHT TOOTH	3.00
			POCKETS	10.00
			RIGHT TOOTH	3.00
			BOLT	20.00
	Parts Charge: 333.90	Labor Charge: 450.00		

Workorder: 1202822

Problem: PM

Meter Reading: 29		Labor	Parts	
In Date: 03/23/2012	Close Date: 03/29/2012	Hours	Description	Quantity
- Pm		4.00	5041B FUEL ADDITIVE	1.00
- Drain, Flush Fuel Sys, Add Fuel W Stabil			09997 BRAKE CLEAN	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
			PH8172 OIL FILTER LBF PH2814 WIX DON'T USE	1.00
			10W30 MOTOR OIL	2.00
			3032 FUEL FILTER 5/16" FRM G2 WIX 33032	1.00
	Parts Charge: 27.77	Labor Charge: 240.00		

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1305658

Problem: pm service

Meter Reading: 31		Labor		Parts	
In Date: 06/07/2013	Close Date: 06/14/2013	Hours	Description		Quantity
- Pm		7.50	OIL FIL		1.00
- R/R Teeth Pockets, Bolts			10W30 MOTOR OIL		2.00
- Drain And Flush System R/R Carb And Adjust			TOOTH-RIGHT		3.00
- Shop Supplies			LOCK NUTS		18.00
			"PRO" POCKET		10.00
			SHOP SUPPLIES		1.00
			TOOTH-STRAIGHT		3.00
			BOLT/SCREW		20.00
			M38-15 STARTING FLUID		1.00
			TOOTH-LEFT		4.00
Parts Charge:		336.65	Labor Charge:	450.00	

Workorder: 1308721

Problem: no start

Meter Reading: 31		Labor		Parts	
In Date: 08/29/2013	Close Date: 09/23/2013	Hours	Description		Quantity
- R/R Clean Carb And Adjust Needle Sticks After Fittings		4.50	CARBURTOR GASKET		1.00
- R/Rr Carb (New) And Adjust			AIR CLEANER GASKET		1.00
- R/Rbattery And Cables			KNOB W/SEAL KIT		1.00
- R/R Battery And Cables			SHOP SUPPLIES		1.00
- Shop Supplies			Freight Charge		1.00
			FUEL CAP - RED		1.00
			26/70A BATTERY		1.00
			CARBURETOR W/GASKETS		1.00
			INTAKE PORT O-RING		2.00
Parts Charge:		760.55	Labor Charge:	270.00	

Workorder: 1311708

Problem: wont start

Meter Reading: 31		Labor		Parts	
In Date: 11/20/2013	Close Date: 11/25/2013	Hours	Description		Quantity
- Service Call To Roads Dept		2.00	SHOP SUPPLIES		1.00
- Check Over Equipment Start And Operate, Check Out Ok					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	120.00	

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1400739

Problem: wont start at Roads Dept

Meter Reading: 31	Labor	Parts	Quantity
In Date: 01/23/2014	Hours	Description	
- Service Call To Roads Dept	2.00	SHOP SUPPLIES	1.00
- Ck For No Start-No Fuel In Lines Due To Sitting-Reprime Fuel Sys And Test Run			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1405701

Problem: pm/ no start

Meter Reading: 31	Labor	Parts	Quantity
In Date: 06/10/2014	Hours	Description	
- Pm	5.50	10W30 MOTOR OIL	2.00
- R/R Carb To Free Up Struck Float		NAPAGOLD FUEL FILTER	1.00
- Loosen Up Frozen Dept Control Handle		OIL FIL	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		AIR FILTER	1.00
Parts Charge:	23.90	Labor Charge:	330.00

Workorder: 1408680

Problem: flat tire at Road Dept

Meter Reading: 33	Labor	Parts	Quantity
In Date: 08/28/2014	Hours	Description	
- Replace 2 Rear Tires	2.50	23X10.50-12 TRU POWER TIRE	2.00
- Service Call To Roads Dept		SHOP SUPPLIES	1.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
Parts Charge:	386.20	Labor Charge:	150.00

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1501825

Problem: wont start

Meter Reading: 33	Labor	Parts
In Date: 02/20/2015	Hours	Quantity
Close Date: 02/26/2015	Description	
- Service Call To Roads Ck Batt Fuel Ign Bring Eqpt To Fleet	4.00	NAPAGOLD FUEL FILTER STARTRON 8OZ FUEL TRT 1.00
- Service Fuel Sys, For Filter Flush Tank Clean Carb		CLEAN-R-CARB 20OZ 1.00
- Ign Tune Up		SPARK PLUG 2.00
- Shop Supplies		SHOP SUPPLIES 1.00
Parts Charge: 25.42	Labor Charge: 240.00	

Workorder: 1507543

Problem: pm/ wont start/ at Roads warehouse overhang

Meter Reading: 33	Labor	Parts
In Date: 07/29/2015	Hours	Quantity
Close Date: 07/31/2015	Description	
- Pm Service	9.50	SHOP SUPPLIES 1.00
- Test Batery & Replace		NAPA 10W30 QT 2.00
- Clean & Ahjust Carb, Clean Fuel Tank, Add Stabilizer		OIL FIL 1.00
- Replace Filter & Hose		BRAKE CLEANER 1.00
- Tune Up Ignition, R & R Valve Cover To Clean Housing		BATTERY 1.00
- Travel To Roads & Start Equipment		CLEAN-R-CARB 20OZ 1.00
- Shop Supplies		NAPAGOLD FUEL FILTER 1.00
		SPARK PLUG 2.00
		STARTRON 8OZ FUEL TRT 1.00
		FUEL LINE HOSE 3.00
		FUEL LINE HOSE 3.00
		BATTERY 1.00
Parts Charge: 166.83	Labor Charge: 570.00	

1/3/2017
4:37:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161705 2005 VERMEER RT200 Root Cutter, Walk Behind,

Workorder: 1508793

Problem: running rough

Meter Reading: 35 In Date: 09/01/2015	Close Date: 09/30/2015	Labor Hours	Description	Parts	Quantity
- Ck Runs Rough -Compression Test, Ign Sys. R&R Engine		16.00	SPARK PLUG		2.00
To Replace Camshaft And Lifters. Ck Elect Sys For			FUEL LINE HOSE		2.00
Controls. Replace Relays And Repair Grounds			CAMSHAFT		1.00
- Shop Supplies			5068 PENETRATING OIL		1.00
			YELLOW O RING		2.00
			NAPA 10W30 QT		2.00
			SWITCH-ROLLER-PLUNGER		1.00
			OIL FIL		1.00
			LIFTER		4.00
			AL76702 RELAY JOHN DE		2.00
			SHOP SUPPLIES		1.00
			BRAKE CLEANER		2.00
			JB WELD KWIK WELD		1.00
			Freight Charge		1.00
			PTEX ULTRA GREY 3OZ		1.00
	Parts Charge: 414.85	Labor Charge: 960.00			

Workorder: 1607173

Problem: Transition Prep Charge

Meter Reading: 35 In Date: 07/14/2016	Close Date: 07/14/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
	Parts Charge: 0.00	Labor Charge: 0.00			

Total Parts Charges:	3,042.34	Total Labor Charges:	5,230.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------