10181493 2010 FORD E250 Van, Cargo, 3/4 Ton

Workorder: Problem:	1011302 Pre Delivery In	Meter:	0			In Date:	10/13/2010	Closed:	10/13/2010
- Pre Delivery	Inspection								
	Hours :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00
Workorder: Problem:	1104384 P.M. service.	Meter:	1855			In Date:	04/25/2011	Closed:	04/29/2011
- P.m. Service	Э.				Parts L	ist			Qty
- Rotate and I	balance all tires				Shop Si	upplies			1.00
- Shop Suppli	ies				1372 O	il Filter Frm	Ph2 Wix 513	372	1.00
					5w20 E	ngine Oil			7.00
					1066 W	hite Lithium/	(crc 05037)		1.00
	Hours :	5.00		Labor:	300.00	Parts:	23.91	Total:	323.91
Workorder: Problem:	1107669 R/R FLat tire	Meter:	2600			In Date:	07/01/2011	Closed:	07/21/2011
- Ne corner o	f Park Ln and K	irk Rd							
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1107674 service	Meter:	2600			In Date:	07/16/2011	Closed:	07/21/2011
- Kirk and Par	rk Ln								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1111040 Pm service	Meter:	3218			In Date:	10/17/2011	Closed:	10/27/2011
- P.m Service	).				Parts L	ist			Qty
- Dismount sp	pare and mount	on rim to	match other		Shop Si	upplies			1.00
	d balance all fou	ur.			1372 O	il Filter Frm	Ph2 Wix 513	372	1.00
- Shop Suppli	ies				5w20 E	ngine Oil			7.00
					Wd40 S	pray Lube S	Stock# 405540	0002	1.00
					31-20 V	/iper Blades	20" Blade		2.00
					Used Fi	rex Refurbe	d Fire Extings	hers	1.00
	Hours :	6.00		Labor:	360.00	Parts:	52.27	Total:	412.27
Workorder:	1112368	Meter:	3218			In Date:	10/26/2011	Closed:	11/21/2011
Problem:	damage to righ	nt side do	ors, rear quart	er & den	ts on both	n sides of ro	of		
- damage to r sides of roof	ight side doors,	rear quar	ter & dents or	both					
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	1204703 P.M. service.	Meter:	4590			In Date:	05/17/2012	Closed:	05/30/20	012
- P.m. Service	Э.				Parts L	ist				Qty
- Rotate and	balance all tires	<b>3.</b>			Shop St	upplies				1.00
- Shop Suppl	ies						n Ph2 Wix 51:	372		1.00
					5w20 Eı	ngine Oil				7.00
						_	d Fire Extings	hers		1.00
	Hour :	s 5.00		Labor:	300.00		38.12		338.12	
Workorder: Problem:	1204948 1 - Detail Vehi	Meter: icle Wash	4371 Ticket(s) Issue	ed		In Date:	05/29/2012	Closed:	05/29/20	012
- 1 - Detail Ve	ehicle Wash Tic	ket(s) Issu	ued							
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1212202 Pm service.	Meter:	6713			In Date:	12/19/2012	Closed:	01/08/20	013
- Perform pm	service.				Parts L	ist				Qty
- Rotate and	balance all four	tires.			5w20 Eı	ngine Oil				7.00
- Shop Suppl	ies				Ph2 Oil	Filter Lbf Ph	า			1.00
					31-20 W	/iper Blades	3 20			2.00
					Shop St	upplies				1.00
	Hour :	s 5.00		Labor:	300.00	Parts:	40.52	Total:	340.52	
Workorder: Problem:	1300161 1 - Detail Vehi	Meter: cle Wash	6593 Ticket(s) Issue	ed		In Date:	01/04/2013	Closed:	01/04/20	013
- 1 - Detail Ve	ehicle Wash Tic	ket(s) Issu	ued							
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1312190 Pm service an	Meter: ad check e	10366 engine light on.			In Date:	12/05/2013	Closed:	12/13/20	013
- Perform pm	service.				Parts L	ist				Qty
	iagnose for che				Napago	ld Oil Filter				1.00
replace failed and roadtest.	gas cap with ne	ew.clear c	odes with scan	tool	5w20 E			7.00		
	and charging	system ha	ttery failed load	dtest	Napago		1.00			
	replace failed				Wiper B	lade				2.00
- Rotate and	balance all four	tires.			Mac Wit	te Lithium G	res			1.00
- Shop Suppl	ies				Battery					1.00
					fuel cap	asy				1.00
					Shop St	upplies				1.00
	Hour	s 8.00		Labor:	480.00	Parts:	192.88	Total:	672.88	

Workorder:	1402951	Meter:	10528			In Date:	03/26/2014	Closed:	03/26/2014	
Problem:	2 - Key(s) issue	ed								
- 2 - Key(s) is	sued				Parts Li	ist			Q	ty
					Duplicat	te Vehicle K	eys		2.0	00
	Hours	0.40		Labor:	24.00	Parts:	6.00	Total:	30.00	
Workorder:	1405090	Meter:	11426			In Date:	05/27/2014	Closed:	06/02/2014	_
Problem:	P.M. Service.B	rake peda	al goes to floor	·.						
- P.m. Service	Э.				Parts Li	ist			Q	ty
	s.replace leakir	ng left rea	r brake washe	rs.flush	5w20 Er	ngine Oil			7.0	00
and bleed sys					Napago	ld Oil Filter			1.0	00
<ul> <li>A/c does not blow on all speeds.diagnose and replace defective blower switch and burnt connector.</li> <li>Rotate and balance all tires.</li> </ul>						6oz	1.0	00		
						Washer			2.0	00
- Rotate and balance all tires Shop Supplies					Brake F	1.0	00			
опор оцррп	00				Brake C	leaner			1.0	00
					Switch				1.0	00
					Wire As	у			1.0	00
					Wiper B	lade			2.0	00
					Shop Su	upplies			1.0	00
	Hours	8.00		Labor:	480.00	Parts:	104.26	Total:	584.26	
Workorder:	1500517	Meter:	18276			In Date:	01/14/2015	Closed:	01/23/2015	_
Problem:	Pm service.									
- Pm service.					Parts Li	ist			Q	ty
- Rotate and I	palance all four t	tires.			5w20 Er	ngine Oil			7.0	00
- Shop Suppli	es				Napagold Oil Filter 1.					00
					Used Fi	re X Refurbi	ished		1.0	00
					Shop Su	upplies			1.0	00
	Hours	5.00		Labor:	300.00	Parts:	41.24	Total:	341.24	
Workorder:	1501169	Meter:	18276			In Date:	01/20/2015	Closed:	02/02/2015	_
Problem:	damage to lft fr	t fender 8	door, right si	de & botl	n bumpei	rs				
- damage to l	t frt fender & do	or, right s	ide & both bur	npers						
	Hours	-		Labor:	0.00	Parts:	0.00	Total:	0.00	
Moulcondon	1500000	Motor	26202			In Deter	00/20/2045	Classifi	00/20/2045	_
Workorder: Problem:	1509888 Flat Tire on Lef	<b>Meter:</b> ft Rear.	26302			In Date:	09/28/2015	Closed:	09/29/2015	
- Tire Service Tire on Left Re	157 Yacht Club ear.	Way, Hy	poluxo Fl 3346	62 - Flat						
	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

:

	1510200 Pm service.Ch	Meter: eck tires	26756 flat. Body dan	nage,sen	d to body	In Date:	10/07/2015	Closed:	10/27/2015
- Pm service.			·		Parts Li	ist			Qty
- Replace both	defective high	mount b	rake lamp bul	bs.	Mirror	1.00			
- Replace and	balance all fou	r tires.			5w20 Er		7.00		
- Replace dam	age left side re	arview m	irror assembl	y.	Napago	1.00			
<ul><li>Complete front end alignment and test drive.</li><li>Shop Supplies</li></ul>					Napago		1.00		
					Used Fi	re X Refurbi	ished		1.00
					Wiper B	lade			2.00
					Wd40 1	6oz			1.00
					Bulb				2.00
					Lt245/7	5r16 Mic Tir	е		4.00
					Shop St	upplies			1.00
					Tire Dis	posal Fee			4.00
	Hours	10.00		Labor:	600.00	Parts:	1,316.86	Total:	1,916.86
	1511734 damage torigh	<b>Meter:</b> t rear bod	26777 ly			In Date:	10/21/2015	Closed:	11/17/2015
- damage torig	ht rear body								
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1606026 bolt in tire	Meter:	33479			In Date:	06/09/2016	Closed:	06/13/2016
- Tire Service	Wud #2 2956	Pinehurst	Dr - bolt in tir	e					
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	1606027 Emergency Se	Meter: rvice	33479			In Date:	06/10/2016	Closed:	06/13/2016
- Tire Service Service	water plant #2	pinehurst	dr - Emergen	су					
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder:	1607729	Meter:	34997			In Date:	07/28/2016	Closed:	08/16/2016
Problem:	Tow in,no brak	es.P.M S	ervice.						
- P.m. Service	).				Parts Li	ist			Qt
•	tire and one de		oms.rotate a	nd	Napago		1.0		
	s.reset sensors				5w20 Er		7.0		
•	wheel bearings.				Washer	1.0			
-	king rear brake		d system.		20" Wip	2.0			
<ul><li>Replace worn out rear asset #.</li><li>Shop Supplies</li></ul>					Napago	1.0			
					Used Fi	1.0			
					Mac Wit	te Lithium G	res		1.0
					Lt245/7	5/16 Tire Mi	С		1.0
					Brake H	lose			1.0
					Tpms12	Sensor Tire	e Pr		1.0
					Shop St	upplies			1.0
					Tire Dis	posal Fee			1.0
	Hours	8.50		Labor:	510.00	Parts:	431.44	Total:	941.44
	1607867 brake fluid leak	•	34858			In Date:	07/28/2016	Closed:	08/01/2016
- Iow From: w	rtp2 pinehurst -		vista						
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1609015 Repair flat tire	Meter:	35616			In Date:	08/30/2016	Closed:	08/31/2016
- Repair 1 tire	and balance .m	nount on I	eft rear .nitro	gen fill all	Parts Li	ist			Qt
tires.					Shop Su	upplies			1.0
- Shop Supplie	es								
	Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	1612251 unlock	Meter:	39497			In Date:	11/21/2016	Closed:	11/30/2016
- Tow From: 1	130 Santurary	dr pga							
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: 1702449 Meter: 44852 Problem: P.M. service and spare tire flat.	In Date:	03/09/2017	Closed:	04/12/2017
- P.m. Service.	Parts List			Qty
- Resurface rear brake rotors,replace calipers and	Caliper Washer			4.00
pads.service and adjust parking brakes.flush and bleed	5w20 Engine Oil		7.00	
system.	Napagold Oil Filter	1.00		
- Service transmission.flush and refill system.	22" Wiper Blade	2.00		
- Replace spare tire,rotate and balance all.	Mac Wite Lithium G	1.00		
- Shop Supplies	Semi Losded Calipe	1.00		
	Semi Loaded Calipe			1.00
	B Fluid Dot 3-32oz	<b>7</b> 1		1.00
	Non-chlor Brake Clr	or.		1.00
	Syn-atf Trans Fluid			18.00
	Filter	J		1.00
	Brake Pads			1.00
	Shop Supplies			1.00
	Lt245/75r16 Tire			1.00
Hours 12.00 Labor:		498.77	Total:	1,218.77
:		20/20/20/2		00/10/00/5
Workorder: 1702522 Meter: 43151  Problem: Damage to front bumper, grille & left front tire	In Date:	02/09/2017	Closed:	03/13/2017
- Damage to front bumper, grille & left front tire				
Hours 0.00 Labor:	0.00 Parts:	0.00	Total:	0.00
:	0.00 Parts:	0.00	Total:	0.00
<u>:</u>	In Date:	09/27/2017	Closed:	
: <b>Workorder:</b> 1709427 <b>Meter:</b> 50413	In Date:	09/27/2017	Closed:	10/31/2017
:  Workorder: 1709427 Meter: 50413  Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both	In Date: ch light came on ,dar Parts List	09/27/2017	Closed:	
:  Workorder: 1709427 Meter: 50413  Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.	In Date: ch light came on ,dar Parts List	09/27/2017	Closed:	10/31/2017 <b>Qty</b> 7.00
: Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer - P.m. service Check and replace broken right rear tail lamp lens and both headlamp bulbs Perfrom engine coolant flush and refill.	In Date: ch light came on ,dar Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi	09/27/2017 nage on right	Closed:	10/31/2017 Qty 7.00 1.00
: Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer - P.m. service Check and replace broken right rear tail lamp lens and both headlamp bulbs Perfrom engine coolant flush and refill Check ,pinpoint test.replace defective blower motor resistor	In Date: ch light came on ,dar Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi	09/27/2017 nage on right	Closed:	10/31/2017 <b>Qty</b> 7.00 1.00
:  Workorder: 1709427 Meter: 50413  Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.	In Date: ch light came on ,dar Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi	09/27/2017 nage on right	Closed:	10/31/2017 <b>Qty</b> 7.00 1.00 1.00 1.00
: Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer - P.m. service Check and replace broken right rear tail lamp lens and both headlamp bulbs Perfrom engine coolant flush and refill Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector Computer diagnoise .perform hydraulic pressure test .test	In Date: ch light came on ,dar  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi Drain Plug	09/27/2017 nage on right	Closed:	10/31/2017 <b>Qty</b> 7.00 1.00 1.00 2.00
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer - P.m. service Check and replace broken right rear tail lamp lens and both headlamp bulbs Perfrom engine coolant flush and refill Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly	In Date: ch light came on ,dar  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi Drain Plug 22" Wiper Blade	09/27/2017 nage on right	Closed:	10/31/2017 <b>Qty</b>
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer - P.m. service Check and replace broken right rear tail lamp lens and both headlamp bulbs Perfrom engine coolant flush and refill Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly	In Date: ch light came on ,dar  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi Drain Plug 22" Wiper Blade Halogen Lamp Peak Global Antifrz	09/27/2017 nage on right	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 2.00
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.	In Date: ch light came on ,dar  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbi Drain Plug 22" Wiper Blade Halogen Lamp Peak Global Antifrz	09/27/2017 nage on right	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 2.00 1.00 1.00
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 2.00 1.00
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 2.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 2.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter  Lamp Asy	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter  Lamp Asy  Tramission Assy	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter  Lamp Asy  Tramission Assy  Oil Cooler  Blower Motor Resist	09/27/2017 mage on right shed	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter  Lamp Asy  Tramission Assy  Oil Cooler  Blower Motor Resist  Connector Blower Resister	09/27/2017 nage on right shed shed tor Resistor	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1
Workorder: 1709427 Meter: 50413 Problem: P.M. service, bounces at highway speeds.wer  - P.m. service.  - Check and replace broken right rear tail lamp lens and both headlamp bulbs.  - Perfrom engine coolant flush and refill.  - Check ,pinpoint test.replace defective blower motor resistor and corroded pig tail connector.  - Computer diagnoise .perform hydraulic pressure test .test circuits,check fluid .replace defective transmission assembly and cooler.retest.  - High speed balance and road force and rotate all four tires.	In Date: ch light came on ,dar  Parts List  5w20 Engine Oil  Napagold Oil Filter  Used Fire X Refurbi  Drain Plug  22" Wiper Blade  Halogen Lamp  Peak Global Antifrz  Blower Resistor  Tram Piston And  Syn-atf Trans Fluid  Filter  Lamp Asy  Tramission Assy  Oil Cooler  Blower Motor Resist	09/27/2017 nage on right shed shed tor Resistor	Closed:	10/31/2017  Qty 7.00 1.00 1.00 2.00 2.00 1.00 1.00 1.00 1

**Workorder:** 1711672 **Meter:** 50413 **In Date:** 10/26/2017 **Closed:** 11/29/2017

Problem: Damage to front & rear bumper, right rear fender & right front side door

- Damage to front & rear bumper, right rear fender & right

front side door

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

**Workorder:** 1805219 **Meter:** 56619 **In Date:** 05/21/2018 **Closed:** 06/12/2018

**Problem:** P.M. service and had to jump start.

- P.m. service.	Parts List	Qty
- Inspect and service rear differential.	Lever	1.00
- Check battery and charging system .battery failed load test	Gear Lunger	1.00
.r&r defective battery .	F3tz7l278a Bushing Sh	2.00
- Inspect loose gear shifter .replace shift tube and shaft and all bushings and dampener and shifter handle. Retest.	Tube	1.00
- Test and adjust left front door ajar switch . replace bulbs in	Damper Asy	1.00
dome light and thrid brake light .retest all .	Napagold Oil Filter	1.00
- Repair right rear tire .rotate and high speed balance all four	5w20 Engine Oil	7.00
tires. Nitrofill.	Used Fire X Refurbished	1.00
- Shop Supplies	Napagold Air Filter	1.00
	20" Wiper Blade	2.00
	Pedal Pad	1.00
	Friction Modifier	2.00
	Napa Gear 80w-90 Qt	3.00
	Battery 65	1.00
	Bulb	1.00
	Bulb	1.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours 13.00 Labor:	780.00 Parts: 447.56	Total: 1,227.56

<ul> <li>- P.m. service.</li> <li>- Inspect all brakes . Replace front brake pads and calipers .</li> <li>Resurface both front rotors . Repack front wheel bearings .</li> <li>Flush nand bleed brake system . Road test.</li> </ul> Parts List 5w20 Engine Oil 5w20 Engine Oil	
Resurface both front rotors . Repack front wheel bearings . 5w20 Engine Oil Flush nand bleed brake system . Road test.	Qty
Flush nand bleed brake system . Road test.	1.00
Flush nand bleed brake system . Road test.	7.00
Washer Fluid Concentr	1.00
- Inspect all tires . Replace two worn tires . Rotate and high speed balance all four tires Nitrofill all.	2.00
- Test and replace back up alarm . Reman Brake Caliper	1.00
- Test and replace left rear tail light bulb.  Reman Brake Caliper	1.00
- Perform complete front end alignment. Replace both front Front Brake Pad	1.00
caster camber adjusting bushings . Non-chlor Brake Clnr	1.00
- Shop Supplies B Fluid Dot 3-32oz	1.00
Lt245/75/16 Tire Mic	2.00
Alarm	1.00
Long Life Small Bulb	1.00
Caster-camber Bushing	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Hours 15.10 Labor: 1,011.7 Parts: 851.19 Total: 1,8	862.89
Workorder:         1901263         Meter:         67171         In Date:         02/01/2019         Closed:         02/01/2019           Problem:         Replace tire.	2/07/2019
- Replace two rear tires and balance . Nitrofill all.	Qty
<ul> <li>Replace two rear tires and balance . Nitrofill all.</li> <li>Shop Supplies</li> <li>Lt245/75/16 Tire Mic</li> </ul>	<b>Qty</b> 2.00
	-
- Shop Supplies Lt245/75/16 Tire Mic	2.00
- Shop Supplies Lt245/75/16 Tire Mic Shop Supplies	2.00 1.00 2.00
- Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54	2.00 1.00 2.00
- Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54	2.00 1.00 2.00 14.55
- Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Meter: 67926 In Date: 02/25/2019 Closed: 03  Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch  Napagold Oil Filter	2.00 1.00 2.00 14.55 3/06/2019
- Shop Supplies  Chapter Shop Supplies  Tire Disposal Fee  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher  Lt245/75/16 Tire Mic Shop Supplies  Tire Disposal Fee  67.00 Parts: 477.55 Total: 54  In Date: 02/25/2019 Closed: 03  Parts List Napagold Oil Filter  5w20 Engine Oil	2.00 1.00 2.00 14.55 3/06/2019 Qty
- Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Meter: 67926 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher bracket .  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee In Date: 02/25/2019 Closed: 03  Parts List Napagold Oil Filter 5w20 Engine Oil 20" Winer Blade	2.00 1.00 2.00 14.55 3/06/2019 <b>Qty</b> 1.00
- Shop Supplies  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Meter: 67926 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher bracket Rotate and high speed balance all four tires . Nitrofill all.  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee In Date: 02/25/2019 Closed: 03  Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Fire Ext Mount Strap Style	2.00 1.00 2.00 14.55 3/06/2019 Qty 1.00 7.00
- Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies Tire Disposal Fee Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Meter: 67926 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher bracket Rotate and high speed balance all four tires . Nitrofill all.	2.00 1.00 2.00 14.55 3/06/2019 <b>Qty</b> 1.00 7.00 2.00
- Shop Supplies  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Meter: 67926 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher bracket Rotate and high speed balance all four tires . Nitrofill all Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies  Tire Disposal Fee  In Date: 02/25/2019 Closed: 03  Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Fire Ext Mount Strap Style	2.00 1.00 2.00 44.55 3/06/2019 Qty 1.00 7.00 2.00 1.00
- Shop Supplies  Hours 1.00 Labor: 67.00 Parts: 477.55 Total: 54  Workorder: 1902046 Problem: P.M. service and back cargo door inop.  - P.m. service Diagnose right rear cargo door inop . Replace latch assembly and retest . Replace broken fire extinguisher bracket Rotate and high speed balance all four tires . Nitrofill all Shop Supplies  Lt245/75/16 Tire Mic Shop Supplies  In Date: 02/25/2019 Closed: 03  Parts List Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Fire Ext Mount Strap Style Used Fire X Refurbished	2.00 1.00 2.00 14.55 3/06/2019 Qty 1.00 7.00 2.00 1.00

Workorder: 19091 Problem: P.M. s	76 <b>Meter:</b> service and slow c	74732 rank .	ln l	Date:	09/05/2019	Closed:	09/16/201	9
- P.m. service.			Parts List			Qty		
<ul> <li>A/c performance to Replace defective A/vacuum hose as nee</li> <li>Check battery and battery . R&amp;r defecti</li> <li>Balance and rotate</li> <li>Shop Supplies</li> </ul>	c vacuum reservoi ded . Retest syste charging system a ve battery .	Napagold Oil Filter 5w20 Engine Oil 20" Wiper Blade Used Fire X Refurbished W W Vacuum Tubing Vacuum Resevoir A/c Valve Battery				7 2 1 5 1 1	1.00 7.00 2.00 1.00 5.00 1.00 1.00	
	Hours 10.40	Labor:	Shop Suppli 696.80		221.27	Total:	918.07	1.00
Workorder: 19123 Problem: Side of	Meter: cargo doors inop .	75959	In I	Date:	12/02/2019	Closed:	12/04/201	9
- Diagnose side doo door forward . Retest - Shop Supplies	:. '	Door Remot Shop Suppli	es			1	<b>Qty</b> 1.00 1.00	
	Hours 1.10 :	Labor:	80.30	Parts:	61.74	Total:	142.04	
	ition Prep Charge	76462	In I	Date:	01/30/2020	Closed:	01/30/202	0
- Transition Prep Ch	arge Hours 2.00 :	Labor:	146.00	Parts:	0.00	Total:	146.00	