

**Palm Beach County Fleet Management
Asset Maintenance History**

10194200 2014 FORD F150 Pickup, 1/2 Ton

Workorder: 1403297 **Meter:** 0 **In Date:** 04/04/2014 **Closed:** 04/04/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1409524 **Meter:** 4352 **In Date:** 09/23/2014 **Closed:** 10/03/2014
Problem: P.M. service.

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List

	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 66.68 Total: 246.68
 :

Workorder: 1504312 **Meter:** 10057 **In Date:** 04/28/2015 **Closed:** 05/07/2015
Problem: Pm service.

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List

	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Bigg Degreaser	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 29.98 Total: 209.98
 :

Workorder: 1511130 **Meter:** 14963 **In Date:** 10/30/2015 **Closed:** 11/09/2015
Problem: Pm service.Right tail lamp broken.

- Pm service.

- Test and replace defective right side tag lamp bulb and socket.replace broken right tail lamp assembly..

- Replace and balance all four tires.

- Complete alignment.test drive.

- Shop Supplies

Parts List

	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Bulb	2.00
Hankook P235 75r17 Dp At	4.00
Socket Asy	1.00
Lamp Assembly	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours 7.50 Labor: 450.00 Parts: 1,034.88 Total: 1,484.88
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600523 **Meter:** 17142 **In Date:** 01/15/2016 **Closed:** 01/19/2016
Problem: Left front tire flat.

- Repair and balance left front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1604143 **Meter:** 20067 **In Date:** 04/20/2016 **Closed:** 04/26/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace broken trim cover on driver seat.	5w20 Engine Oil	6.00
- Replace and rewire trailer plug.	Napagold Oil Filter	1.00
- Test battery and charging system.recharge and retest battery,failed load test.replace defective battery.	Napagold Air Filter	1.00
- Resurface front brake rotors to correct pulsation.service and lube calipers.	22" Wiper Blade	2.00
- Rotate and balance all tires.	seatpanel shield asy	1.00
- Shop Supplies	trailer plug	1.00
	Battery 65	1.00
	Shop Supplies	1.00
Hours 8.25	Labor: 495.00	Parts: 284.26
:		Total: 779.26

Workorder: 1612348 **Meter:** 24849 **In Date:** 12/01/2016 **Closed:** 12/14/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace right front seat recliner handle.	5w20 Engine Oil	6.00
- Replace corroded trailer plug.fabricate wiring.	Napagold Oil Filter	1.00
- Rotate and balance tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Stg Wheel Cov - Ford	1.00
	22" Wiper Blade	2.00
	trailer plug	1.00
	Dielect Silicone Comp	1.00
	Handle	1.00
	Shop Supplies	1.00
Hours 4.75	Labor: 285.00	Parts: 117.53
:		Total: 402.53

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706144 **Meter:** 29790 **In Date:** 06/21/2017 **Closed:** 07/03/2017
Problem: P.M. Service.

<ul style="list-style-type: none"> - P.m. Service. - A/c blow does not work on #1 setting.diagnose and replace defective blower resistor. - Flush and refill transmission. - Replace two tires,rotate and balance all four. - Complete wheel alignment.test drive. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Blower Resistor Syn-atf Trans Fluid S Hankook P235 75r17 Dp At 5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Concentr Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 12.00 2.00 6.00 1.00 2.00 1.00 1.00 2.00 	
Hours 9.00 :	Labor: 540.00	Parts: 549.93	Total: 1,089.93

Workorder: 1800187 **Meter:** 34664 **In Date:** 01/04/2018 **Closed:** 02/05/2018
Problem: P.M. Service.Check a/c.

<ul style="list-style-type: none"> - P.m. service. - Resurface both front rotors, service calipers and replace brake pads with new .flush and bleed brake system.road test. - Performance check A/c system.evacuate system .replace evaporator case .replace drier with new .complete recharge system .retest A/c performance. - Replace two worn tires and valve stems .rotate and balance all four tires. - Transport to and from dealer for airbag light code B0096. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Evaporator Asy Freon Lv Shop 1 accumulator Kit O Tire Pressure Monitoring System Sensor (Hankook P235 75r17 Dp At 5w20 Engine Oil Napagold Oil Filter Washer Fluid Concentr Used Fire X Refurbished 22" Wiper Blade Brake Pad B Fluid Dot 3-32oz Non-chlor Brake Clnr E8 A/c Oil Univ W Dye Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 2.00 1.00 1.00 2.00 2.00 6.00 1.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00 2.00 	
Hours 22.80 :	Labor: 1,368.00	Parts: 1,021.02	Total: 2,389.02

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1807374 **Meter:** 38443 **In Date:** 07/19/2018 **Closed:** 07/30/2018
Problem: P.M. service and door ajar light on.

<ul style="list-style-type: none"> - P.m. service. - Computer diagnose door ajar light . Remove left front door panel to replace inner door harness. Retest. - Remove and replace left broken outside mirror glass. - Pressure test cooling system . R&r leaking upper radiator hose . Flush and refill cooling system . retest. - Rotate and balance all four tires. Nitrogen fill tires. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>5w20 Engine Oil</td><td></td><td align="right">6.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>22" Wiper Blade</td><td></td><td align="right">2.00</td></tr> <tr><td>Anti Freeze Motorcraft</td><td></td><td align="right">1.00</td></tr> <tr><td>Wire Asy</td><td></td><td align="right">1.00</td></tr> <tr><td>Mirror</td><td></td><td align="right">1.00</td></tr> <tr><td>Hose Clamp</td><td></td><td align="right">2.00</td></tr> <tr><td>Rad Hose</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napagold Oil Filter		1.00	5w20 Engine Oil		6.00	Washer Fluid Concentr		1.00	22" Wiper Blade		2.00	Anti Freeze Motorcraft		1.00	Wire Asy		1.00	Mirror		1.00	Hose Clamp		2.00	Rad Hose		1.00	Shop Supplies		1.00	<p align="right">Hours 8.30 Labor: 498.00 Parts: 224.92 Total: 722.92</p>
Parts List		Qty																																	
Napagold Oil Filter		1.00																																	
5w20 Engine Oil		6.00																																	
Washer Fluid Concentr		1.00																																	
22" Wiper Blade		2.00																																	
Anti Freeze Motorcraft		1.00																																	
Wire Asy		1.00																																	
Mirror		1.00																																	
Hose Clamp		2.00																																	
Rad Hose		1.00																																	
Shop Supplies		1.00																																	

Workorder: 1811572 **Meter:** 41068 **In Date:** 11/09/2018 **Closed:** 11/26/2018
Problem: Check brakes, Parking brake stuck on.

<ul style="list-style-type: none"> - Diagnose and inspect brake system . Replace both front brake hoses and washers . Flush and bleed brake system . Road test. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Non-chlor Brake Clnr</td><td></td><td align="right">1.00</td></tr> <tr><td>B Fluid Dot 3-32oz</td><td></td><td align="right">1.00</td></tr> <tr><td>Caliper Washer</td><td></td><td align="right">4.00</td></tr> <tr><td>Lf Brake Hose</td><td></td><td align="right">1.00</td></tr> <tr><td>Rf Brake Hose</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Non-chlor Brake Clnr		1.00	B Fluid Dot 3-32oz		1.00	Caliper Washer		4.00	Lf Brake Hose		1.00	Rf Brake Hose		1.00	Shop Supplies		1.00	<p align="right">Hours 2.00 Labor: 134.00 Parts: 50.85 Total: 184.85</p>
Parts List		Qty																					
Non-chlor Brake Clnr		1.00																					
B Fluid Dot 3-32oz		1.00																					
Caliper Washer		4.00																					
Lf Brake Hose		1.00																					
Rf Brake Hose		1.00																					
Shop Supplies		1.00																					

Workorder: 1811573 **Meter:** 41063 **In Date:** 11/09/2018 **Closed:** 11/09/2018
Problem: burning smell like brakes

<ul style="list-style-type: none"> - Tow From: 14200 us 1, juno To: Iv shop 	<p align="right">Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00</p>
--	--

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1813110 **Meter:** 42355 **In Date:** 12/31/2018 **Closed:** 01/10/2019
Problem: P.M. service and slow crank .

<ul style="list-style-type: none"> - P.m. service. - Replace two tires . Rotate and high speed balance all four tires. Nitrogen fill tires . - Pressure test and inspect cooling system . Replace leaking water pump ,thermostat,radiator and gaskets . Flush and refill cooling system . Replace belts . - Resurface both rear brake rotors and service calipers . Replace brake pads and service parking brakes . Flush and bleed brake system . Road test. - Check starting and charging systems . Battery failed load test . Replace defective battery . - Replace broken left front seat side trim . - Perform complete front end alignment and road test. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter Napa Quart 5w20 22" Wiper Blade Used Fire X Refurbished Ford Triton Pvc Swc Hankook P235 75r17 Dp At Center Cap V Belt Anti Freeze Motorcraft Gasket B Fluid Dot 3-32oz Non-chlor Brake Clnr Brake Pad Battery 65 Radiator Tmermostat Housing Water Pump seatpanel shield asy Housing Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 1.00 6.00 2.00 1.00 1.00 2.00 1.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 2.00 	
Hours 19.90 :	Labor: 1,333.30	Parts: 1,601.70	Total: 2,935.00

Workorder: 1902856 **Meter:** 44185 **In Date:** 03/07/2019 **Closed:** 03/14/2019
Problem: Emergency Service

- Tire Service Juno Beach - Emergency Service

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1902857 **Meter:** 44185 **In Date:** 03/07/2019 **Closed:** 03/14/2019
Problem: Tire replaced at Juno Beach

- Tire Service Tires - Tire replaced at Juno Beach

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1908016 **Meter:** 48453 **In Date:** 08/02/2019 **Closed:** 08/15/2019
Problem: PM Service

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	6.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 4.00	Labor: 268.00	Parts: 494.71
:		Total: 762.71

Workorder: 2001483 **Meter:** 52707 **In Date:** 02/11/2020 **Closed:** 02/11/2020
Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			