

**Palm Beach County Fleet Management
Asset Maintenance History**

10169424 2008 FORD F250 Pickup, 3/4 Ton, W/Winch, Tow Pkg

Workorder: 742637 **Meter:** 0 **In Date:** 08/07/2007 **Closed:** 08/07/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 110.00 Parts: 0.00 Total: 110.00
:

Workorder: 833504 **Meter:** 3784 **In Date:** 02/01/2008 **Closed:** 02/05/2008
Problem: INSTALL APS DIESEL TANK

- Install Fuel Tank,secure Cable And Rewired Sys.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Hours 4.50 Labor: 270.00 Parts: 2.00 Total: 272.00
:

Workorder: 835242 **Meter:** 4137 **In Date:** 03/10/2008 **Closed:** 03/12/2008
Problem: P.M. SERVICE.

- Pm Service

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

Hours 2.00 Labor: 120.00 Parts: 19.21 Total: 139.21
:

Workorder: 846114 **Meter:** 6694 **In Date:** 10/23/2008 **Closed:** 10/31/2008
Problem: P.M SERVICE

- Pm Service

Parts List **Qty**

- Fab & Install New Hold Down Hardware To Correct Loose
Aps Fuel Tank.service Aps Pump.

Shop Supplies 1.00

24006 Fuel Filter Diesel And Gas 1.00

- Service Rear Power Liftgate.

Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00

- Rotate & High Speed Balance.all 4 Tires.nitro Fill Tires To
Specs.

1372 Oil Filter Frm Ph2 Wix 51372 1.00

- Shop Supplies

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 7.00

Used Firex Refurbed Fire Extingshers 1.00

Hours 6.75 Labor: 405.00 Parts: 73.99 Total: 478.99
:

Workorder: 937628 **Meter:** 9068 **In Date:** 05/11/2009 **Closed:** 06/09/2009
Problem: P.M SERVICE

- Pm Service

Parts List **Qty**

- R&r Leaking Lift Gate Cylinder.repair Return Hose And
Adjustlinkages

Shop Supplies 1.00

Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00

- Rotate And Hi Speed Balance All 4 Tires.

1372 Oil Filter Frm Ph2 Wix 51372 1.00

- R&r Floor Mats And Fire Extinguisher Bracket.

5w20 Engine Oil 7.00

- Short In Trailer Harness When In Reverse. Repair Wiring
To Correct Problem.

31-20 Wiper Blades 20" Blade 2.00

- Transport Vehicle To And From Dealer For Warranty
Repair To Floor Carpet.

Floor Mat Set 1.00

- Shop Supplies

Hours 10.25 Labor: 615.00 Parts: 95.84 Total: 710.84
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 946674 **Meter:** 13537 **In Date:** 12/04/2009 **Closed:** 12/14/2009
Problem: P.M service, check tool box locks

- P.m service.	Parts List	Qty
- Inspect & service aux fuel tank & pump.	Shop Supplies	1.00
- Inspect & service power lift gate.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Repair & adjust tool box latches & lubricate.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	24006 Fuel Filter Diesel And Gas	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.75	Labor: 345.00	Parts: 63.71
:		Total: 408.71

Workorder: 1004378 **Meter:** 17066 **In Date:** 04/20/2010 **Closed:** 04/28/2010
Problem: left rear tire flat

- milatary/gunclub @ Cvs store	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1004379 **Meter:** 17066 **In Date:** 04/20/2010 **Closed:** 04/28/2010
Problem: Tires

- gunclub/military Cvs	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1006018 **Meter:** 17666 **In Date:** 06/08/2010 **Closed:** 06/14/2010
Problem: P.M. Service.

- Perform pm service.	Parts List	Qty
- Install three new tires and balance all four.	Shop Supplies	1.00
- Test and replace two front failed strobe lamp and third brake lamp bulbs with new.fabricate and repair wiring for strobes.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Install new hitch safety pin and service rear power tailgate lift.	24006 Fuel Filter Diesel And Gas	1.00
	5w20 Engine Oil	7.00
- Service auxiliary fuel tank and replace fuel filter.	Wd40 Spray Lube Stock# 405540002	1.00
- Perform wheel alignment complete.	Used Firex Refurbed Fire Extingshers	1.00
- Shop Supplies	S30hacp Strobe Bulb For Kit S660cccc	2.00
	179636492 Lt245/75r17 Wrangler Sr-a E	3.00
	Tire Disposal Fee	3.00
	2560 Hitch Pin/clip	1.00
Hours 12.00	Labor: 720.00	Parts: 684.86
:		Total: 1,404.86

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1013566 **Meter:** 18738 **In Date:** 12/09/2010 **Closed:** 12/16/2010
Problem: Pm service.

- Perform pm service.	Parts List	Qty
- Test starting and charging system.battery failed load test after recharge.replace failed battery with new.	Shop Supplies	1.00
- Inspect and service power winch.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all four tires.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	D3tz2457b Brake Pedal Pad	1.00
	15319476 Fuse 20 Amp Gmc	1.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
Hours 5.75	Labor: 345.00	Parts: 175.45
:		Total: 520.45

Workorder: 1106965 **Meter:** 19927 **In Date:** 06/30/2011 **Closed:** 07/13/2011
Problem: Pm service.

- Perform pm service.	Parts List	Qty
- Perform auxiliary fuel tank service and install new fuel filter.	Shop Supplies	1.00
- Inspect and service power tailgate.	24006 Fuel Filter Diesel And Gas	1.00
- Rotate and balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.75	Labor: 345.00	Parts: 57.42
:		Total: 402.42

Workorder: 1200521 **Meter:** 20822 **In Date:** 01/17/2012 **Closed:** 01/25/2012
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Inspect and service auxillary fuel tank.	Shop Supplies	1.00
- Inspect and service lift gate.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all tires.	24006 Fuel Filter Diesel And Gas	1.00
- Shop Supplies	5w20 Engine Oil	7.00
Hours 5.75	Labor: 345.00	Parts: 27.99
:		Total: 372.99

Workorder: 1204930 **Meter:** 21434 **In Date:** 05/29/2012 **Closed:** 05/30/2012
Problem: Blown fuse

- Field Service	Parts List	Qty
- Replace Fuse Holder	Shop Supplies	1.00
- Shop Supplies	80865 Fuseholder Imperial 80865	1.00
Hours 2.00	Labor: 120.00	Parts: 8.98
:		Total: 128.98

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1207892 **Meter:** 21867 **In Date:** 08/20/2012 **Closed:** 08/31/2012
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Inspect and service liftgate.	Shop Supplies	1.00
- Rotate and balance all tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 4.75	Labor: 285.00	Parts: 51.34
:		Total: 336.34

Workorder: 1302137 **Meter:** 22576 **In Date:** 03/01/2013 **Closed:** 03/12/2013
Problem: P.M. service .

- P.m. Service.	Parts List	Qty
- Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.	5w20 Engine Oil	7.00
- Inspect and service aux. fuel system.inspect and service lift gate.	1372 Oil Filter	1.00
- Rotate and balance all tires.	31-20 Wiper Blades 20	2.00
- Shop Supplies	Used Firex Refurbed F	1.00
	Battery 65	1.00
	Fuel Filter	1.00
	Shop Supplies	1.00
Hours 6.75	Labor: 405.00	Parts: 203.35
:		Total: 608.35

Workorder: 1309021 **Meter:** 23980 **In Date:** 09/06/2013 **Closed:** 09/20/2013
Problem: Pm service.

- P.m. Service.	Parts List	Qty
- Inspect and service aux. fuel system.	5w20 Engine Oil	7.00
- Inspect and service lift gate.	Napagold Oil Filter	1.00
- Rotate and balance all tires.	31-20 Wiper Blades 20	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Bigg Degreaser	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 5.75	Labor: 345.00	Parts: 54.08
:		Total: 399.08

Workorder: 1404733 **Meter:** 24698 **In Date:** 05/14/2014 **Closed:** 05/28/2014
Problem: Pm service

- Perform pm service.	Parts List	Qty
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Fabricate and replace missing hitch safety pindle with new.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Wiper Blade	2.00
	Napagold Fuel Filter	1.00
	Pintle Pin W/chain	1.00
	Shop Supplies	1.00
Hours 5.25	Labor: 315.00	Parts: 54.68
:		Total: 369.68

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1409916 **Meter:** 25530 **In Date:** 10/02/2014 **Closed:**
Problem: Gas cap missing.

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1412102 **Meter:** 25832 **In Date:** 12/03/2014 **Closed:** 12/16/2014
Problem: P.M. Service.

- Pm service.	Parts List	Qty
- Inspect and service auxiliary fuel tank.	5w20 Engine Oil	7.00
- Flush and refill transmission fluid.	Napagold Oil Filter	1.00
- Replace one tire.rotate and balance all four.	Wiper Blade	2.00
- Inspect and service power tailgate.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Syn-atf Trans Fluid S	16.00
	Shop Supplies	1.00
	Lt245/75r17 Tire/wheel Assy	1.00
Hours 7.50	Labor: 450.00	Parts: 260.42
:		Total: 710.42

Workorder: 1505935 **Meter:** 26849 **In Date:** 06/15/2015 **Closed:** 06/25/2015
Problem: P.M. service and replace inside mirror.

- Pm service.	Parts List	Qty
- Inspect and service Aps fuel system.	5w20 Engine Oil	7.00
- Check and diagnose interior dome light inop.voltage ok.replace burnt bulb.	Napagold Oil Filter	1.00
- Inspect and replace inside rear view mirror-discoloration in lens.	Wiper Blade	2.00
	Pintle Pin W/chain	1.00
- Inspect and service power tailgate.	Napagold Fuel Filter	2.00
- Rotate and balance all four wheels.	Napagold Fuel Filter	1.00
- Shop Supplies	Bulb	1.00
	Inside Real Mirror	1.00
	Ptex Rview Mir Adh Cd	1.00
	Shop Supplies	1.00
Hours 6.75	Labor: 405.00	Parts: 106.54
:		Total: 511.54

Workorder: 1511630 **Meter:** 27708 **In Date:** 11/13/2015 **Closed:** 11/24/2015
Problem: Install electric trailer brake controller.

- Fabricate and install trailer brake controller and replace defective trailer harness connector.	Parts List	Qty
- Shop Supplies	Brk Ctrl	1.00
	Jumper	1.00
	Vinyl Electrical Tape	1.00
	Female Conn Socket	1.00
	Shop Supplies	1.00
Hours 4.00	Labor: 240.00	Parts: 211.69
:		Total: 451.69

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1512634 **Meter:** 27898 **In Date:** 12/15/2015 **Closed:** 12/31/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace all six defective body mounts.	5w20 Engine Oil	7.00
- Inspect and service auxiliary fuel tank.	Napagold Oil Filter	1.00
- Inspect and pressure test cooling system.flush with new antifreeze.	20" Wiper Blade	2.00
- Inspect and service tail lift gate.	Used Fire X Refurbished	1.00
- Rotate and balance all four tires.	Washer Fluid Concentr	1.00
- Shop Supplies	Body Mount Kit	2.00
	Body Mount Kit	4.00
	Napagold Fuel Filter	1.00
	Peak Global	2.00
	Shop Supplies	1.00
Hours 13.75	Labor: 825.00	Parts: 573.14
:		Total: 1,398.14

Workorder: 1606190 **Meter:** 29026 **In Date:** 06/16/2016 **Closed:** 07/01/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace front suspension bump stoppers.	Napagold Oil Filter	1.00
- Inspect and service aux. fuel system.	5w20 Engine Oil	7.00
- Inspect and service liftgate.	20" Wiper Blade	2.00
- Rotate and balance all tires.	bumper	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Air Filter	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 59.02
:		Total: 389.02

Workorder: 1606821 **Meter:** 29026 **In Date:** 07/06/2016 **Closed:** 07/12/2016
Problem: Left rear tire bubble on side of tire.

- Replace and balance two rear tires.	Parts List	Qty
- Shop Supplies	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.00	Labor: 60.00	Parts: 506.58
:		Total: 566.58

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612980 **Meter:** 30449 **In Date:** 12/20/2016 **Closed:** 01/03/2017
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	7.00
- Replace worn out rear bump stoppers.	Napagold Oil Filter	1.00
- Replace missing pintle pin.	20" Wiper Blade	2.00
- Inspect and service aux. fuel system.	Used Fire X Refurbished	1.00
- Inspect and service crane.	179636492 Lt245-75r17	2.00
- Complete wheel alignment.test drive.	Bumper	2.00
- Shop Supplies	Pintle Pin W/clip	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.25	Labor: 615.00	Parts: 628.13
:		Total: 1,243.13

Workorder: 1706505 **Meter:** 33039 **In Date:** 06/30/2017 **Closed:** 07/10/2017
Problem: P.M. Service.

	Parts List	Qty
- P.m. service.		
- Inspect and service auxiliary fuel tank and secure electric wire with wire loom.	Vinyl Electrical Tape	1.00
	Fab/loom	5.00
- Check battery and charging system.battery failed R&r with new.	Pintle Pin W/clip	1.00
	5w20 Engine Oil	7.00
- Pintle pin missing.fabricate and install new.	Napagold Oil Filter	1.00
- Rotate and high speed balance all four tires.	Mac Wite Lithium Gres	1.00
- Inspect and service rear power lift tail gate.	Washer Fluid Concentr	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	20" Wiper Blade	2.00
	Napagold Fuel Filter	1.00
	Battery	1.00
	Shop Supplies	1.00
Hours 7.45	Labor: 447.00	Parts: 180.46
:		Total: 627.46

Workorder: 1706671 **Meter:** 33039 **In Date:** 07/07/2017 **Closed:** 07/17/2017
Problem: repair rusted liftgate

	Parts List	Qty
- Fab weld and install new mounting plate for liftgate		
- Shop Supplies	Plate 55"x14"x3/16"	1.00
	Glos Blk	2.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 150.95
:		Total: 510.95

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1800030 **Meter:** 36046 **In Date:** 01/02/2018 **Closed:** 01/16/2018
Problem: P.M. service and check engine light on and hard to fuel.

- P.m. service.	Parts List	Qty
- Removed and replaced leaking left headlight.	5w20 Engine Oil	7.00
- Remove and replace left front door lower door weatherstrip.	Napagold Oil Filter	1.00
- Computer diagnose check engine light and hard to fuel.replace purge and evap canister.retest evap system .	20" Wiper Blade	2.00
- Service and inspect auxiliary fuel tank and replace filter.	Napagold Fuel Filter	1.00
- Remove and replace damaged front bumper and left headlight bracket and minor body work to left front fender.	Bulb Tun	1.00
- Serviced and inspected power liftgate.	Weatherstr	1.00
- Rotated and balanced all four tires.nitrogen filled tires.	Valve	1.00
- Shop Supplies	Cannister	1.00
	Ford Triton Pvc Swc	1.00
	Front Bomber Assy	1.00
	Front Bomber Cover	1.00
	Bumper Panel	1.00
	Bumper Bezel	1.00
	Bumper Bezel	1.00
	Housing Head Light	1.00
	Hook Tow	1.00
	Bolt	6.00
	Bumper Bracket	1.00
	Bumper Bracket	1.00
	Shop Supplies	1.00
Hours 15.05	Labor: 903.00	Parts: 1,283.90
:		Total: 2,186.90

Workorder: 1801253 **Meter:** 36154 **In Date:** 01/10/2018 **Closed:** 02/01/2018
Problem: repaint front bumper

- repaint front bumper

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809455 **Meter:** 38732 **In Date:** 09/13/2018 **Closed:** 10/02/2018
Problem: P.M. service ,door ajar light on and liftgate leaking oil.

- P.m. service.	Parts List	Qty
- Check and service auxiliary fuel tank.	Napagold Oil Filter	1.00
- Check and replace right headlight bulb .	5w20 Engine Oil	7.00
- Replace bent pintle pin.	20" Wiper Blade	2.00
- Test and check power liftgate . Remove right cylinder for rebuild . reinstall and adjust . fill hydrolic fluid and service liftgate.	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
- Computer diagnose door ajar light on . remove right front door panel to remove latch assembly to replace door ajar switch and retest.	Napagold Fuel Filter	1.00
	Napagold Fuel Filter	1.00
- Rotate and high speed balance all four wheels . Nitrofill all.	Halogen Sealed Beams	1.00
- Shop Supplies	Switch	1.00
	Pintle Pin W/clip	1.00
	Repair Cylinder	1.00
	Syn-atf Trans Fluid S	3.00
	Shop Supplies	1.00
Hours 9.55	Labor: 639.85	Parts: 623.15
:		Total: 1,263.00

Workorder: 1904119 **Meter:** 41539 **In Date:** 04/16/2019 **Closed:** 04/22/2019
Problem: P.M. service and needs rear shocks .

- P.m. service.	Parts List	Qty
- Inspect and service auxiliary fuel tank .	Napagold Oil Filter	1.00
- Inspect and replace defective rear shocks .	5w20 Engine Oil	7.00
- Test and replace both front strobe bulbs . Diagnose tag light inop . Repair circuit and retest .	20" Wiper Blade	2.00
	Mac Wite Lithium Gres	1.00
- Rotate and high speed balance all four tires . Nitrofill all.	Ford Triton Pvc Swc	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Gas Grande Shock	2.00
	Hide Away Strob	2.00
	Shop Supplies	1.00
Hours 7.25	Labor: 485.75	Parts: 304.19
:		Total: 789.94

Workorder: 2000956 **Meter:** 43459 **In Date:** 01/28/2020 **Closed:** 01/28/2020
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00