10169450 2008 FORD F350 Pickup, 1 Ton, W/Crew Cab, Tow Pkg

Workorder: Problem:	741199 PRE-DELIVER	Meter: Y INSPE	0 CTION			In Date:	07/10/2007	Closed:	07/10/20	007
- Pre-delivery	Inspection									
	Hours :	2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	832888 P.M. SERVICE	Meter:	2409			In Date:	01/17/2008	Closed:	01/30/20	800
- Pm Service					Parts Li	st				Qty
- Diag And Re Stroblight Ret	emv Right Frt Ma	arker Ligh	nt To Test & R	Replace	Shop Su	• •	n Ph2 Wix 513	372		1.00 1.00
- Rotate And	High Speed Bala	ance All 4	Tires.nitro F	ill Tires.		ngine Oil	TITIZ VVIX OT	512		7.00
- Shop Suppli	es					•	ner Don't Red	order		1.00
						•	lb For Kit S66			1.00
	Hours	5.50		Labor:	330.00		60.86		390.86	
	833377 FLOOR MATT					In Date:	01/29/2008	Closed:	02/12/20	
	e To And Fr Dea			•	Parts Li					Qty
	ay Radio & Fire Varranty,reinstal			all Nw	Shop Su	ıpplies				1.00
- Shop Suppli	es									
	Hours :	2.90		Labor:	174.00	Parts:	2.00	Total:	176.00	
Workorder: Problem:	841192 P.M. SERVICE	Meter: :.CHECK	4846 TRAILER PL	UG.		In Date:	07/10/2008	Closed:	07/21/20	800
- Pm Service					Parts Li	st				Qty
	ailer Harness W			wire	Shop Su	upplies				1.00
	ler Plug Connec		-		Ca1026	2 Air Filter N	∕ltc Fa1883 W	ix 49883		1.00
 Rotate & High To Spec. 	gh Speed Baland	ce All 4 T	ires.nitro Fill A	All Tires	1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- Shop Suppli	es						Mtc Fg1083 V	Vix 33243		1.00
						ngine Oil				7.00
						/iper Blades				2.00
						male Conne		_		1.00
	Hours	6.00		Labor:	360.00	Parts:	74.41	Total:	434.41	

Workorder: 933730 Problem: P.M SEI	Meter: RVICE	7168		I	n Date:	02/09/2009	Closed:	03/30/20	009
- Pm Service				Parts List	:				Qty
- Replace Left Front St	robe Bulb.			Shop Sup	plies				1.00
- Replace Broken Extir			install	1372 Oil I	372		1.00		
Accessories For Dealer		ŭ		5w20 Eng	ine Oil				7.00
- To/from Dealer For W	/arranty Floor Ma	at.		31-20 Wip	er Blades	20" Blade			2.00
- Shop Supplies				Floor Mats	3				1.00
				Custom5lb	Bracket	Firex Stock #	340060300		1.00
				S30hacp S	Strobe Bu	lb For Kit S66	Осссс		1.00
	Hours 7.50 :		Labor:	450.00	Parts:	195.39	Total:	645.39	
Workorder: 934756 Problem: ALVIN N		0 NT & BODY		I	n Date:	02/23/2009	Closed:	03/05/20	009
- Alvin Matthews Paint	& Body								
	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: 940649 Problem: Brakes	Meter: stay on trailer wh	7902 en pluged in		I	n Date:	07/13/2009	Closed:	07/14/20	009
- Repair Wiring In Trail	er Plug			Parts List	:				Qty
- Shop Supplies				Shop Sup	plies				1.00
	Hours 1.50		Labor:	90.00	Parts:	2.00	Total:	92.00	
Workorder: 944249 Problem: pm serv	Meter:	8862		I	n Date:	10/06/2009	Closed:	10/15/20	009
- P.m service.				Parts List	:				Qty
- Test starting & chargi	ing system, test &	& replace batte	ery.	Shop Sup	plies				1.00
- Replace both tag ligh	t lamps & dome	light bulb.		1372 Oil I	Filter Frm	Ph2 Wix 513	372		1.00
- Cup holder will not st	ay closed.replace	e defective cu	p holder	Ca10262	Air Filter N	/Itc Fa1883 W	ix 49883		1.00
assemble.				C40400 E			liv 22242		
				G10166 F	uel Filter l	Mtc Fg1083 W	/IX 33243		1.00
- Rotate & balance all	four tires.			5w20 Eng		Mtc Fg1083 W	/IX 33243		1.00 7.00
	four tires.				ine Oil	VItc Fg1083 W	/IX 33243		
- Rotate & balance all	four tires.			5w20 Eng Cup Holde	ine Oil er	Mtc Fg1083 W 20" Blade	/IX 33243		7.00 1.00 2.00
- Rotate & balance all	four tires.			5w20 Eng Cup Holde 31-20 Wip Group 65	ine Oil er er Blades	·			7.00 1.00 2.00 1.00
- Rotate & balance all				5w20 Eng Cup Holde 31-20 Wip Group 65 Tag Light	ine Oil er er Blades Battery (n	20" Blade ntc Bxt-65-850			7.00 1.00 2.00
- Rotate & balance all	four tires. Hours 7.50		Labor:	5w20 Eng Cup Holde 31-20 Wip Group 65	ine Oil er er Blades Battery (n	20" Blade))	696.59	7.00 1.00 2.00 1.00
- Rotate & balance all	Hours 7.50 : 6 Meter:	9657	Labor:	5w20 Eng Cup Holde 31-20 Wip Group 65 Tag Light 450.00	ine Oil er er Blades Battery (n	20" Blade ntc Bxt-65-850))	696.59	7.00 1.00 2.00 1.00 1.00
- Rotate & balance all to - Shop Supplies Workorder: 1000346	Hours 7.50 : Meter: h ticket(s) issued		Labor:	5w20 Eng Cup Holde 31-20 Wip Group 65 Tag Light 450.00	ine Oil er er Blades Battery (n Parts:	20" Blade ntc Bxt-65-850 246.59)) Total:		7.00 1.00 2.00 1.00 1.00

Workorder:	1001830	Meter:	10089			In Date:	02/22/2010	Closed:	02/22/20	10
Problem:	Throttle sticki	ng								
- From: Jp Ma	aint To: Lv S	hop								
	Houi :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1001833	Meter:	10136			In Date:	02/22/2010	Closed:	02/25/20	10
Problem:	Throttle sticki	ng								
	aler for sticking	throttle co	mplaint. Deale	r states	Parts Li	st				Qty
no problem ev					Shop Su	ıpplies				1.00
- Shop Suppli		rs 2.00		Lobori	120.00	Parts:	2.00	Totalı	100.00	
	: Hou	15 2.00		Labor.	120.00	raits.	2.00	i Olai.	122.00	
Workorder:	1004367	Meter:	10883			In Date:	04/28/2010	Closed:	05/03/20	10
Problem:	P.M service,	check glove	e box latch.							
- P.m service.					Parts Li	st				Qty
- Remove glo	ve box & repla	ce broken l	atch.		Shop Su	ıpplies				1.00
- Shop Suppli	es				1372 Oi	il Filter Frm	Ph2 Wix 513	372		1.00
					5w20 Er	ngine Oil				7.00
					31-20 W	iper Blades	20" Blade			2.00
					Glove Bo	ox Latch / 8	c3z1506072a	а		1.00
					Used Fir	ex Refurbe	d Fire Extings	hers		1.00
	Hou	rs 5.00		Labor:	300.00	Parts:	51.61	Total:	351.61	
	:									
Workorder:	1101869	Meter:	13506			In Date:	02/16/2011	Closed:	02/25/20	111
	: 1101869 P.M. service a					In Date:	02/16/2011	Closed:	02/25/20	11
	P.M. service				Parts Li		02/16/2011	Closed:	02/25/20	11 Qty
Problem: - Perform pm - Test and rep	P.M. service a service. blace failed righ	and hazzar	d lights inop. p seal beam,ri	ght front		st	02/16/2011	Closed:	02/25/20	
Problem: - Perform pm - Test and repstrobe lamp be	P.M. service a service. place failed right alb and cargo I	and hazzar nt headlam amp bulb a	d lights inop. p seal beam,riq ill with new.		Shop Su	st ipplies	02/16/2011 Ph2 Wix 513		02/25/20	Qty
Problem: - Perform pm - Test and repstrobe lamp bu - Install two ne	P.M. service a service. blace failed righ ulb and cargo I ew tires to the	and hazzar nt headlam amp bulb a	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi	st ipplies il Filter Frm		372	02/25/20	Qty 1.00
Problem: - Perform pm - Test and repstrobe lamp be - Install two nebalance all fou	P.M. service a service. blace failed righ ulb and cargo I ew tires to the ir.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262	st Ipplies Il Filter Frm 2 Air Filter N	Ph2 Wix 513	372	02/25/20	Qty 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262	st Ipplies Il Filter Frm 2 Air Filter M hite Lithium	Ph2 Wix 513 //tc Fa1883 W	372	02/25/20	Qty 1.00 1.00
Problem: - Perform pm - Test and repstrobe lamp be - Install two nebalance all fou	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er	st pplies I Filter Frm Air Filter N hite Lithium ngine Oil	Ph2 Wix 513 //tc Fa1883 W	372 'ix 49883	02/25/20	Qty 1.00 1.00 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir	st pplies I Filter Frm Air Filter N hite Lithium ngine Oil	Ph2 Wix 513 Itc Fa1883 W (crc 05037) d Fire Extings	372 'ix 49883	02/25/20	Qty 1.00 1.00 1.00 1.00 7.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245	st pplies Filter Frm Air Filter N hite Lithium ngine Oil Fex Refurbe	Ph2 Wix 513 Itc Fa1883 W (crc 05037) d Fire Extings edal Pad	372 'ix 49883	02/25/20	Qty 1.00 1.00 1.00 1.00 7.00 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245 31-20 W	st Ipplies Il Filter Frm 2 Air Filter M hite Lithium Ingine Oil Fex Refurbe 7b Brake P	Ph2 Wix 513 Itc Fa1883 W (crc 05037) d Fire Extings edal Pad	372 /ix 49883 hers	02/25/20	Qty 1.00 1.00 1.00 1.00 7.00 1.00 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245 31-20 W S30hacp	st Ipplies Il Filter Frm 2 Air Filter M hite Lithium Ingine Oil Fex Refurbe 7b Brake P	Ph2 Wix 513 Mtc Fa1883 W (crc 05037) d Fire Extings edal Pad 20" Blade lb For Kit S66	372 /ix 49883 hers	02/25/20	Qty 1.00 1.00 1.00 7.00 1.00 1.00 2.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245 31-20 W S30hacp H6054 S	st Ipplies Il Filter Frm 2 Air Filter M hite Lithium Ingine Oil Fex Refurbe 7b Brake P Tiper Blades 5 Strobe Bu Sealed Bear	Ph2 Wix 513 Mtc Fa1883 W (crc 05037) d Fire Extings edal Pad 20" Blade lb For Kit S66	372 fix 49883 hers 0cccc	02/25/20	Qty 1.00 1.00 1.00 7.00 1.00 1.00 2.00 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245 31-20 W S30hacp H6054 S 1795354	st Ipplies Il Filter Frm 2 Air Filter M hite Lithium Ingine Oil Fex Refurbe 7b Brake P Tiper Blades 5 Strobe Bu Sealed Bear	Ph2 Wix 513 Itc Fa1883 W (crc 05037) d Fire Extings edal Pad 20" Blade lb For Kit S66	372 fix 49883 hers 0cccc	02/25/20	Qty 1.00 1.00 1.00 7.00 1.00 1.00 1.00 1.00
Problem: - Perform pm - Test and repstrobe lamp bu - Install two nubalance all four	P.M. service a service. blace failed right ulb and cargo I ew tires to the ur.	and hazzar nt headlam amp bulb a front whee	d lights inop. p seal beam,riq ill with new.		Shop Su 1372 Oi Ca10262 1066 W 5w20 Er Used Fir D3tz245 31-20 W S30hacp H6054 S 1795354 Tire Disp	st Ipplies Il Filter Frm 2 Air Filter N Thite Lithium Ingine Oil Tex Refurbe 7 b Brake P Tiper Blades 5 Strobe Bu Sealed Bear	Ph2 Wix 513 Itc Fa1883 W (crc 05037) d Fire Extings edal Pad 20" Blade lb For Kit S66	372 fix 49883 hers 0cccc	02/25/20	Qty 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0

Workorder: Problem:	1106768 Left rear tire	Meter: flat.	14682		In	Date:	06/27/2011	Closed:	06/28/2	011
- Replace and	d balance both	rear tires.			Parts List					Qty
- Shop Suppli	es				Shop Supp	lies				1.00
					179535492	Lt265/7	0r17 Wrangle	r Sr-a E		2.00
					Tire Dispos	al Fee				2.00
					Tr416 Valve	e Stem				2.00
	Hou	rs 1.00		Labor:	60.00	Parts:	387.41	Total:	447.41	
Workorder: Problem:	1107644 Has to jump	Meter: start all the	14844 time.		In	Date:	07/20/2011	Closed:	07/22/2	011
	and charging			oadtest	Parts List					Qty
after recharge	•	battery with	n new.		Shop Supp	lies				1.00
- Shop Suppli	es				•	attery (r	ntc Bxt-65-850	0)		1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	130.75	Total:	190.75	
Workorder: Problem:	1111026 Pm service.	Meter:	15574		In	Date:	10/17/2011	Closed:	10/27/20	011
- P.m. Service	Э.				Parts List					Qty
- Rotate and I	oalance all tire	s.			Shop Supp	lies				1.00
- Shop Suppli	es				1372 Oil Fi	ilter Frm	n Ph2 Wix 51	372		1.00
					G10166 Fu	el Filter	Mtc Fg1083 V	Vix 33243		1.00
					5w20 Engir	ne Oil				7.00
					31-20 Wipe	r Blades	20" Blade			2.00
					Used Firex	Refurbe	d Fire Extings	hers		1.00
	Hou	rs 5.00		Labor:	300.00	Parts:	51.65	Total:	351.65	
Workorder: Problem:	1203853 P.M. service.	Meter:	17242		In	Date:	04/24/2012	Closed:	05/07/20	012
- Perform pm	service.				Parts List					Qty
	and charging		st and replac	ce failed	Shop Supp	lies				1.00
alternator asse	-				1372 Oil Fi	ilter Frm	n Ph2 Wix 51	372		1.00
	ght rear tire.ni	trogen fill a	nd balance	all four.	5w20 Engir	ne Oil				7.00
- Shop Suppli	es				31-20 Wipe	r Blades	20" Blade			2.00
					Alternator					1.00
						_				

Labor: 450.00 Parts: 269.83

Total: 719.83

Hours 7.50

Workorder: 12 Problem: Pm	12346 service.	Meter:	19535			In Date:	12/27/2012	Closed:	01/16/2013
- P.m. Service.					Parts Li	ist			Qty
- Replace front st				mp	5w20 Er	ngine Oil			7.00
assemble.replace	•	•			1372 Oi	l Filter			1.00
- Repack and adj	ust both fror	nt wheel b	earings.		Used Fi	rex Refurbe	d F		1.00
- Remount county	•				Ford Fu	el Filter			1.00
- Rotate and bala	nce all four	tires.			31-20 W	/iper Blades	20		2.00
- Shop Supplies					05088 E	Brake Clean			1.00
					S30hac	o Strobe Bu	lb F		1.00
					Parking	Ligth			1.00
					Shop Su	upplies			1.00
	Hours :	8.00		Labor:	480.00	Parts:	352.91	Total:	832.91
Workorder: 130 Problem: P.N	07571 <i>I</i> I. service.	Meter:	21827			In Date:	07/30/2013	Closed:	08/20/2013
- P.m. Service.					Parts Li	ist			Qty
- Replace left hea	ıdlamp				Lift Supp	port			2.00
- Replace toolbox	lid struts.				5w20 Er	ngine Oil			7.00
- Rotate and bala	nce all tires				Napago	ld Oil Filter			1.00
- Shop Supplies					31-20 W	/iper Blades	20		2.00
					Haloger	Lamp			1.00
					Shop St	upplies			1.00
	Hours	4.75		Labor:	285.00	Parts:	212.26	Total:	497.26
Workorder: 140 Problem: P.M	D2157 И.	Meter:	23773			In Date:	03/05/2014	Closed:	
-	Hours	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

:

Workorder: 1402172 Meter: 23913 Problem: P.M. service.	In Date : 03/05/2014 Closed : 04/03/2014
- P.m. Service.	Parts List Q
- R&r front seat and send to upholstery shop for repairs.	5w20 Engine Oil 7.0
- Replace right head lamp.	Napagold Oil Filter 1.0
- Replace broken glove box latch and missing tail gate	Napagold Fuel Filter 1.0
cap.replace and rewire trailer plug.	Wiper Blade 2.0
- Rotate and balance all tires.	Used Fire X Refurbished 1.0
- Shop Supplies	Fuse 1.0
	Halogen Lamp 1.0
	Trailer Conn Plug 1.0
	Trailer Conn Socket 1.0
	Moulding 1.0
	Lock Asy 1.0
	Seat R And R 1.0
	Shop Supplies 1.0
Hours 9.10 Labo	: 546.00 Parts: 805.40 Total: 1,351.40
Workorder: 1406720 Meter: 25273 Problem: Left rear tire has bubble in sidewall.	In Date: 07/08/2014 Closed: 07/10/2014
- Install two new tires to the rear wheels.nitrogen fill and	Parts List Q
balance both.	179535492 Lt265-70r17 2.0
- Shop Supplies	Tr416 Valve Stem 2.0
	Shop Supplies 1.0
	Tire Disposal Fee 2.0
Hours 1.00 Labo	: 60.00 Parts: 528.48 Total: 588.48

Workorder: Problem:	1502824 Pm service.	Meter:	28024		In [Date:	03/18/2015	Closed:	04/08/2015	
- Pm service.					Parts List				Qty	
- Check charg	ging and elect	rical system	.battery failed lo	oadtest	5w20 Engine	e Oil			7.00	
after recharge.					Napagold Oil	1.00				
- Replace two	tires.rotate a	nd balance	all four.		Napagold Air				1.00	
- Diagnose ra					Napagold Fu	Napagold Fuel Filter				
radio.diagnose tow/haul switch inop.replace defective switch/lever assembly.diagnose driver door adjar message o					Wiper Blade				2.00	
dash.replace o				Jago o	Used Fire X	Refurbi	shed		1.00	
- Shop Supplies					Floor Mat-2p	c Rub l	Bk		1.00	
					Stg Wheel C	ov - Fo	rd		1.00	
					Pintle Pin W/	/chain			1.00	
					Battery				1.00	
					179535492 L	_t265-7	0r17		2.00	
					Tr416 Valve	Stem			2.00	
					Lever				1.00	
					Radio				1.00	
					Switch Asy				1.00	
					Shop Supplie				1.00	
					Tire Disposa	l Fee			2.00	
	Hou	ırs 9.00		Labor:	540.00	Parts:	1,244.91	Total:	1,784.91	
Morkordor	1601170	Motori	21212		In F)oto:	02/02/2016	Classel	02/24/2016	
	1601172 Pm service.1	Meter: Fowed in for	31212 no start.			Date:	02/03/2016	Closed:	02/24/2016	
Problem: - Pm service.	Pm service.1	Fowed in for	no start.	rm	Parts List		02/03/2016	Closed:	Qty	
Problem: - Pm service.	Pm service.T	Γowed in for grand grand starting grand starting grand starting grand starting grand gran	no start.	rm		rcraft	02/03/2016	Closed:	Qty 1.00	
Problem: - Pm service Diagnose ba	Pm service.1 attery,charging nd replace de	Fowed in for g and startin fective start	no start. g system.perfoer motor.	rm	Parts List Starter Motor	rcraft e Oil	02/03/2016	Closed:	Qty 1.00 7.00	
Problem: - Pm service Diagnose ba pinpoint test ar	Pm service.1 attery,charging nd replace de eplace left rea	Fowed in for g and startin fective start ar turnsigna	no start. g system.perfo er motor. I lamp bulb.	rm	Parts List Starter Motor 5w20 Engine	rcraft e Oil I Filter	02/03/2016	Closed:	Qty 1.00 7.00 1.00	
Problem: - Pm service Diagnose bapinpoint test and received and rec	Pm service.1 attery,charging nd replace de eplace left rea smission fluid ine coolant fluid	Fowed in for g and starting fective start ar turnsignal of the flush and r	no start. g system.perfo er motor. I lamp bulb.		Parts List Starter Motor 5w20 Engine Napagold Oil	rcraft e Oil I Filter ade		Closed:	Qty 1.00 7.00 1.00 2.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform tran - Perform engand gasketre	Pm service.1 attery,charging nd replace de eplace left rea esmission fluic ine coolant flu fill.	Fowed in for g and startin fective start ar turnsigna d flush and r ush.replace	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla	rcraft e Oil I Filter ade nall Bull	b	Closed:	Qty 1.00 7.00 1.00 2.00 1.00	
Problem: - Pm service Diagnose bapinpoint test and reference transport tr	Pm service.T attery,charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de	Fowed in for g and startin fective start ar turnsigna d flush and r ush.replace	no start. g system.perfo er motor. I lamp bulb. efill.		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm	rcraft e Oil I Filter ade nall Bull s Fluid	b	Closed:	Qty 1.00 7.00 1.00 2.00 1.00 20.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform traneled. - Perform engund gasketreeled. - Check and received.	Pm service.1 attery,charging nd replace de eplace left rea esmission fluic ine coolant fluic fill. eplace two de palance all fou	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans	rcraft e Oil I Filter ade nall Bull s Fluid	b	Closed:	Qty 1.00 7.00 1.00 2.00 1.00 20.00 2.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global	rcraft e Oil I Filter ade nall Bull s Fluid	b	Closed:	02/24/2016 Qty 1.00 7.00 1.00 2.00 2.00 2.00 1.00 1.00 1.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform traneled. - Perform engund gasketreeled. - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal	b	Closed:	Qty 1.00 7.00 1.00 2.00 1.00 20.00 1.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit	b S	Closed:	Qty 1.00 7.00 1.00 2.00 1.00 2.00 1.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit	b S	Closed:	2.00 1.00 2.00 1.00 20.00 2.00 1.00 2.00	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount Napagold Fu	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit uel Filte	b S	Closed:	Qty 1.00 7.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 1	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea smission fluid ine coolant fluid fill. eplace two de palance all fou d secure tailga	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm		Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount Napagold Fu Moulding	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit lel Filte	b S	Closed:	20.00 1.00 2.00 2.00 1.00 2.00 1.00 2.00 1.00 1	
Problem: - Pm service. - Diagnose bapinpoint test and received. - Check and received. - Perform transpared gasketre - Check and received.	Pm service. I attery, charging nd replace de eplace left rea esmission fluid ine coolant fluid fill. eplace two de palance all fou di secure tailga es	Gowed in for g and starting fective start ar turnsignal d flush and rush.replace efective fron ur tires.	no start. g system.perfo er motor. I lamp bulb. efill. defective therm	nostat	Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount Napagold Fu Moulding Female Conf	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit uel Filte n Socke	b S		Qty 1.00 7.00 1.00 2.00 2.00 1.00 2.00 1.00 1.00 1	
Problem: - Pm service. - Diagnose bapinpoint test and received and received and gasketre - Check and received and gasketre - Check and received and gasketre - Rotate and be - Replace and ceived and serviced and gasket.	Pm service.1 attery,charging nd replace de eplace left reassmission fluid ine coolant fluid ine coolant fluid eplace two de palance all four secure tailgates Hou	g and starting fective start ar turnsignal diffush and rush.replace efective from artires. The cap. We sate cap. Meter:	no start. g system.perfo er motor. I lamp bulb. efill. defective therm	nostat Labor:	Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount Napagold Fu Moulding Female Conr Shop Supplie 828.00	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit uel Filte n Socke	b S		2ty 1.00 7.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00 1	
Problem: - Pm service. - Diagnose bapinpoint test and received and received and gasketre - Check and received and gasketre - Check and received and gasketre - Rotate and be - Replace and ceived and serviced and gasket.	Pm service.1 attery,charging nd replace left reasonission fluid ine coolant fluid ine coolant fluid ine coolance all food secure tailgates Hou : 1601194 Turns over b	g and starting and starting fective start ar turnsignared flush and rush.replace efective from ar tires. The cap. Weter: Towed in for a starting and starting arturnsignared flush and rush.replace efective from artifes. The cap.	g system.perfo er motor. I lamp bulb. efill. defective therm t body mounts.	nostat Labor:	Parts List Starter Motor 5w20 Engine Napagold Oil 20" Wiper Bla Long Life Sm Syn-atf Trans Peak Global Super Therm Thermostat S Body Mount Napagold Fu Moulding Female Conr Shop Supplie 828.00	rcraft e Oil I Filter ade nall Bull s Fluid nostat Seal Kit lel Filte n Socke	b S r et 574.67	Total:	Qty 1.00 7.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1	

Workorder: 1610151 Meter: 33116 Problem: P.M. service and A/C blows warm.	In Date: 09/28/2016 Closed:	10/14/2016
- P.m. Service.	Parts List	Qty
- Replace left side head lamp and right front strobe bulb.	Napagold Oil Filter	1.00
- Check a/c system.add freon and leak test.r&r dash board	5w20 Engine Oil	7.00
and replace leaking evaporator,accumulator and orifice.replace two broken vents.vacuum and recharge	Used Fire X Refurbished	1.00
system to specs.	Washer Fluid Concentr	1.00
- Replace right and left side upper and lower ball joints.	20" Wiper Blade	2.00
- Rotate and balance all tires.	Napagold Air Filter	1.00
- Complete wheel alignment.test drive.	Halogen Lamp	1.00
- Shop Supplies	Hide Away Strob	1.00
	Evapotator Core	1.00
	Accumulator	1.00
	O Ring	1.00
	Tube Filter	1.00
	Seal Kits	1.00
	Seal	1.00
	E8 A/c Oil Univ W Dye	1.00
	Freon Lv Shop 2	2.00
	High Side Schrader Valve	1.00
	Upper Ball Joint	2.00
	Lower Ball Joint	2.00
	Louvre Asy	2.00
	A/cline Assy Motorcraft	1.00
	Shop Supplies	1.00
Hours 25.50 Labor:	: 1,530.0 Parts: 1,018.64 Total: 0	2,548.64

Workorder: 1706088 Meter: 36182 Problem: P.M. Service.	In Date: 06/20/2017	Closed:	07/06/2017
- P.m. Service.	Parts List		Qty
- Test battery and charging system.replace bad battery.	Air Hose		1.00
- Replace right head light.repair broken strobe light	5w20 Engine Oil	7.00	
wire.replace rear marker lamp bulbs.	Napagold Oil Filter	1.00	
- Replace two tires,rotate and balance all four.	Napagold Air Filter	1.00	
- Replace broken intake air duct.	20" Wiper Blade		2.00 1.00 1.00
- Replace blower resistor.	Used Fire X Refurbished		
- Adjust right side of front bumper.	Stg Wheel Cov - Ford		
- Shop Supplies	Battery		1.00
	Halogen Lamp		1.00
	179535492 Lt265-70r17		2.00
	Tr416 Valve Stem		2.00
	Napagold Fuel Filter		1.00
	Rpl Bulb		2.00
	Blower Resistor		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 11.25 Labor:	675.00 Parts: 1,087.28	Total:	1,762.28
Workorder: 1804139 Meter: 38650 Problem: PM Service	In Date: 04/20/2018	Closed:	04/30/2018
- P.m. service.	Parts List		Qty
- Computer diagnoise check engine light ,p0446.perform	5w20 Engine Oil		7.00
evap test . R&i vapor canister assembly and retest. Clear codes.	Napagold Oil Filter		1.00
	Napagold Fuel Filter		1.00
 Inspect all tires .replace two worn tires .rotate and high speed balance all four wheels .nitro fill all. 	Washer Fluid Concentr		1.00
- Inspect and replace front and rear bump stops that were	22" Wiper Blade		2.00
missing.	Used Fire X Refurbished		1.00
- Inspect and replace trailer plug connector assembly.	179535492 Lt265-70r17		2.00
- Inspect and replace both sealed beam headlight bulbs for	bumper		2.00
water intrusion.	Bumper		2.00
- Perform complete front end alignment. Road test.	trailer plug	1.00	
- Shop Supplies	Halogen Sealed Beams		2.00
	Cannister		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours 14.00 Labor:	840.00 Parts: 871.32	Total:	1,711.32

:

Workorder: 181146 Problem: PM Se		40439			In Date:	11/07/2018	Closed:	11/15/2018
- P.m. service.				Parts Li	st			Qty
- Replace damaged r	unning board on le	eft side .		Napago	ld Oil Filter			1.00
- Replace missing pir	•				uart 5w20			7.00
- Rotate and high spe	•	ır tires.			ld Air Filter			1.00
- Shop Supplies				22" Wip				2.00
				Pedal P	ad			1.00
				Pintle Pi	n W/clip			1.00
				Step As	sy			1.00
				Shop Su	ıpplies			1.00
	Hours 6.10 :		Labor:	408.70	Parts:	633.05	Total:	1,041.75
Workorder: 19048 ² Problem: P.M. se		42142			In Date:	05/02/2019	Closed:	05/16/2019
- P.m. service.				Parts Li	st			Qty
- Rotate and high spe	eed balance all fou	ır tires . Nitrof	fill all.	Napago	ld Oil Filter			1.00
- Shop Supplies				5w20 Er	ngine Oil			7.00
				22" Wip	er Blade			4.00
				Napago	ld Fuel Filte	r		1.00
				Ford Tri	ton Pvc Sw			1.00
					re X Refurbi	shed		1.00
				Shop Su				1.00
	Hours 5.00 :		Labor:	335.00	Parts:	79.70	Total:	414.70
Workorder: 190917 Problem: Towed		43318			In Date:	09/05/2019	Closed:	09/11/2019
- Charge battery fully	. Test charging sy	stem . Perfoi	rm	Parts Li	st			Qty
alternator circuit test.				Alternate	or			1.00
oelt .	Called Land Conf	Donald Cod		Belt				1.00
- Test battery . batter	y falled load test.	R&r detective	e battery	Battery				1.00
- Road test and diagr	nose noise over bu	ımns R&rbo	oth	Shock A	bsorber			2.00
defective shocks . Ref	test.			Shop Su	ıpplies			1.00
Onop oupplies	Hours 3.90		Labor:	261.30	Parts:	505.50	Total:	766.80
Workorder: 190926 Problem: Possib		43289 es per Dept			In Date:	09/05/2019	Closed:	09/09/2019
- Tow From: Jpp Mair	nt. Compound To	: Lv shop						
	Hours 0.00 :	-	Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: 191182 Problem: Transit		43716			In Date:	11/14/2019	Closed:	11/14/2019
- Transition Prep Cha	ırge							
-,	Hours 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00