



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V068

In Date: 10/06/2005 Meter Reading:
Close Date: 10/07/2005

Problem?
WATER TANK LEVEL GAUGE INOP, RE-42

Task performed:	<u>Parts</u> _____	<u>Quantity</u> _____
	NO PARTS USED	

Workorder: V144

In Date: 10/12/2005 Meter Reading:
Close Date: 10/13/2005

Problem?
FOAM TANK LEVEL GAUGE INOP, RE-42

Task performed:	<u>Parts</u> _____	<u>Quantity</u> _____
	WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352 1	

Workorder: V295

In Date: 10/19/2005 Meter Reading:
Close Date: 10/20/2005

Problem?
L/SIDE QUARTZ LIGHT SHUTS OFF AFTER 10 MIN. THEN COMES BACK ON RE-42

Task performed:	<u>Parts</u> _____	<u>Quantity</u> _____
	NO PARTS USED	

Workorder: V311

In Date: 10/19/2005 Meter Reading:
Close Date: 10/20/2005

Problem?
COOLANT LEAK, A/C BELT MAKES NOISE, RE-42

Task performed:	<u>Parts</u> _____	<u>Quantity</u> _____
	NO PARTS USED	



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V605

In Date: 11/17/2005

Meter Reading:

Close Date: 11/30/2005

Problem?

SPOT LIGHT KNOCKED OFF BY TREE BRANCH RE-42

Task performed:

Parts	Quantity
620122SPOT LIGHT REMOTE	1
65-72BXT65750 BATTERY	2

Workorder: V626

In Date: 11/18/2005

Meter Reading:

Close Date: 11/30/2005

Problem?

SPOT LIGHT COVER KNOCKED OFF RE42

Task performed:

Parts	Quantity
620122SPOT LIGHT REMOTE	1

Workorder: V708

In Date: 11/28/2005

Meter Reading:

Close Date: 12/12/2005

Problem?

MAP LIGHT INOP, RE-42

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V731

In Date: 11/29/2005

Meter Reading:

Close Date: 12/12/2005

Problem?

L/REAR DOOR LATCH DOES NOT CLOSE PROPERLY RE-42

Task performed:

Parts	Quantity
18-45484-000LATCH L/H	2
377R054FEET - HURST TOOL	2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V822

In Date: 12/06/2005

Meter Reading:

Close Date: 12/12/2005

Problem?

UNABLE TO DRAFT FROM FRONT INTAKE, RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V906

In Date: 12/12/2005

Meter Reading:

Close Date: 12/15/2005

Problem?

hurst cutter female fitting "o" ring leaking E42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V868

In Date: 12/09/2005

Meter Reading:

Close Date: 12/19/2005

Problem?

WILL NOT DRAFT FROM FRONT SUCTION, RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1224

In Date: 01/19/2006

Meter Reading:

Close Date: 01/24/2006

Problem?

SUCTION LEAKING, RE-42

Task performed:

Parts

Quantity

7460967AIR FILTER 17210-ZE2-515 HONDA

1

BPR5ESSPARK PLUG 7734

4



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V1317

In Date: 01/26/2006

Meter Reading: 28,191.00

Close Date: 02/22/2006

Problem?

B INSPECTION RE42

Task performed:

See B Inspection pre-printed form

Parts	Quantity
038-1550-00VALVE CHECK HALE 1/4"	1
12105QUICK DRAIN	1
18-29935-001RH DOOR LATCH NEW	1
52-24WIPER BLADES ANCO 24	2
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	1
5462300020VALVE KIT SS VALVE 3 IN	1
6806970098SEAL DOOR	2
6808300074VENT A/C LH	1
6808300174VENT A/C RH	2
72R311018-2640 VENT A/C NEW # 1719	1
78R536078R5360M 2PK FILTER AIR COND	1
9447BELT	1
9470BELT	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
BPR5ESSPARK PLUG 7734	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
S777COUPLING NIPPLE	1
UMVS162511STRAP	2

Workorder: V1844

In Date: 03/14/2006

Meter Reading:

Close Date: 03/15/2006

Problem?

PUMP SHIFT LEAKING AIR, RE-42

Task performed:

Parts	Quantity
546-0370-50546-0370-50 REPAIR KIT	2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V1664

In Date: 02/28/2006

Meter Reading:

Close Date: 03/21/2006

Problem?

NEED WINDSHIELD WIPER BLADES, RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1721

In Date: 03/03/2006

Meter Reading:

Close Date: 03/27/2006

Problem?

TRUCK HAS AIR LEAK, RE-42

Task performed:

Parts

Quantity

800034VALVE PARKING BRK.

1

Workorder: V1836

In Date: 03/13/2006

Meter Reading:

Close Date: 04/05/2006

Problem?

SMALL CRACK UNDER LEFT HEADLIGHT, RE-42

Task performed:

Parts

Quantity

52-624SWITCH DOOR

2

Workorder: V2104

In Date: 04/05/2006

Meter Reading:

Close Date: 04/07/2006

Problem?

D/DOOR NOT CLOSING, RE-42

Task performed:

Parts

Quantity

18-45484-000LATCH L/H

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V1772

In Date: 03/04/2006
Close Date: 04/11/2006

Meter Reading:

Problem?

flat repair (OUTSIDE VENDER TCI TIRE CENTER) E42

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: TCI

Workorder: V2501

In Date: 05/05/2006
Close Date: 05/10/2006

Meter Reading:

Problem?

FOAM GAUGE INOP, RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3082

In Date: 06/22/2006
Close Date: 06/23/2006

Meter Reading:

Problem?

PUMP PANEL LIGHT INOP, RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3350

In Date: 07/08/2006
Close Date: 07/12/2006

Meter Reading:

Problem?

Right side rear passanger door latch sticks at times. Right side air horn does not work E42

Task performed:

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V3437

In Date: 07/12/2006
Close Date: 07/14/2006

Meter Reading:

Problem?

on call tire repair

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: VC-15214

Workorder: V3430

In Date: 07/12/2006
Close Date: 07/17/2006

Meter Reading:

Problem?

pump discharge gauge on pump panel..last digit of LED unreadable e42

Task performed:

Parts	Quantity
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V3453

In Date: 07/13/2006

Meter Reading: 34,913.00

Close Date: 07/25/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED E42

Task performed:

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	1
200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1
35200-YLIGHT MARKER LEDAMBER	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
6809880678STUD DZ	2
6809940145CLIP	2
6819634283068-1963428-30 LENS CLR	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
HR149460107MOUNT VIBRATION (NEWER POWER UNITS	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1

Workorder: V3682

In Date: 07/18/2006

Meter Reading:

Close Date: 07/28/2006

Problem?

REPLACE HOSE BED COVER E42

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: CENT0002



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V3633

In Date: 07/25/2006

Meter Reading:

Close Date: 07/31/2006

Problem?

PRIMER ON PUMP PANEL NOT WORKING ,PRESSURE RELIEF VALVE NOT WORKING PROPERLY E42

Task performed:

Parts	Quantity
200-2450-00NC SWITCH OK TO PUMP	1
546-0852-01SWITCH OLD # 200-0020-00	1

Workorder: V3690

In Date: 07/30/2006

Meter Reading:

Close Date: 08/02/2006

Problem?

one of two bulbs not working E42

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3853

In Date: 08/09/2006

Meter Reading:

Close Date: 08/23/2006

Problem?

pully damaged on engine, belts came off

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3968

In Date: 08/17/2006

Meter Reading: 35,537.00

Close Date: 08/23/2006

Problem?

A INSPECTION AND REPAIRS AS NEEDED E42

Task performed:

Parts	Quantity
194BULB	1
52-24WIPER BLADES ANCO 24	2
91513AMBER LENS	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V3919

In Date: 08/14/2006
Close Date: 09/08/2006

Meter Reading:

Problem?

REPLACE TIRES AT CALLAGHAN TIRE R36

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214

Workorder: V4278

In Date: 09/06/2006
Close Date: 09/11/2006

Meter Reading: 35,997.00

Problem?

CHECK AND REPAIR TRANS LEAK E42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3916

In Date: 08/14/2006
Close Date: 09/27/2006

Meter Reading:

Problem?

FAN HUB AND PULLEY BROKEN, E-42 (CUMMINS)

Task performed:

Parts

Quantity

1. VEHICLE SENT FOR REPAIRS, OUTSIDE AGENCY

NO PARTS USED

Workorder: V3869

In Date: 08/10/2006
Close Date: 09/28/2006

Meter Reading:

Problem?

tow to shop from station 42 (outside service-sisters towing)

Task performed:

Parts

Quantity

1. VEHICLE TOWED TO SHOP FROM STN 42.

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V4023

In Date: 08/20/2006

Meter Reading:

Close Date: 09/28/2006

Problem?

left side scene light has one bulb burned out or not working E42

Task performed:

1. TRAVELED TO STN 42 REPLACED BULB IN SCENE LIGHT.

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1

Workorder: V4421

In Date: 09/13/2006

Meter Reading:

Close Date: 09/28/2006

Problem?

Left scene light burned out. This has now been over a month since first reported. RE42

Task performed:

1. INSTALLED NEW BULB IN SCENE LIGHT.

Parts

52-624SWITCH DOOR

Quantity

3

Workorder: V4491

In Date: 09/19/2006

Meter Reading:

Close Date: 09/28/2006

Problem?

Door ajar light going off continuously. Will be especially distracting for the driver at night. The buzzer is also going off. Needs immediate repair.

Task performed:

1. REPLACED RIGHT SIDE REAR CAB DOOR SWITCH. DOOR NOW IN GOOD WORKING ORDER.

Parts

52-624SWITCH DOOR

Quantity

1

Workorder: V4728

In Date: 10/04/2006

Meter Reading: 1,587.00

Close Date: 10/26/2006

Problem?

Driver's side mirror is loose and needs to be fixed or tightened. E-42

Task performed:

1. TRAVELED TO STN 42. REPAIRED DRIVERS SIDE MIRROR.

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V4790

In Date: 10/07/2006
Close Date: 10/26/2006

Meter Reading: 1,587.00

Problem?

Front Intake Drain valve handle appears to be broken off and valve is not operational. E42

Task performed:

Parts

Quantity

1. TRAVELED TO STN 42. DRAIN HANDLE IS NOT ON FRONT INTAKE.

NO PARTS USED

Workorder: V4794

In Date: 10/08/2006
Close Date: 10/26/2006

Meter Reading: 1,587.80

Problem?

WASH button (lower button) on windshield wiper panel is not working properly it gets stuck and wipers stay on and spray. RE42

Task performed:

Parts

Quantity

1. TRAVELED TO STN 42. WASH BUTTON ON WINDSHIELD WIPER PANEL WRITTEN UP AS, IS NOT WORKING PROPERLY, NO PROBLEM COULD BE FOUND/ WINDSHIELD WIPERS WORKING PROPERLY.

NO PARTS USED

Workorder: V5047

In Date: 10/24/2006
Close Date: 10/30/2006

Meter Reading: 38,035.00

Problem?

REPAIR DRIVERS CAB DOOR RE42

Task performed:

Parts

Quantity

1. TRAVELED TO STN 42. ADJUSTED DRIVER CAB DOOR THAT WAS NOT CLOSING.

NO PARTS USED

Workorder: V5450

In Date: 11/20/2006
Close Date: 11/20/2006

Meter Reading: 39,213.00

Problem?

ON CALL WARNING LT FOR SCENE LT GOING OFF E42

Task performed:

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V5386

In Date: 11/14/2006
Close Date: 11/28/2006

Meter Reading: 2,118.00

Problem?

rear tires on engine are worn need replacement e 42 callaghan ent

Task performed:

1. replace 6 tires on e42

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN TIRE

Workorder: V5659

In Date: 12/04/2006
Close Date: 12/06/2006

Meter Reading: 2,225.00

Problem?

foam leaking e42

Task performed:

1. TRAVELED TO SNT 42. REPLACED FOAM PICK-UP PUMP.

Parts

4300-505PUMP FLOJET 12V

Quantity

1

Workorder: V4285

In Date: 09/06/2006
Close Date: 12/19/2006

Meter Reading: 35,997.00

Problem?

REPLACE BAD LIFT PUMP AT 42 CUMMINS POWER SOUTH E42

Task performed:

1. UNIT SENT TO CUMMINS POWER SOUTH TO REPLACE BAD LIFT PUMP.

Parts

397795FILTER AIR BRIGGS STRATTON

BPR5ESSPARK PLUG 7734

J19LMUSE 1147 NGK SPARK PLUG

Quantity

1

1

1

Vendor?: CUMMINS POWER SOUTH

Workorder: V6355

In Date: 01/19/2007
Close Date: 01/29/2007

Meter Reading: 1,589.50

Problem?

battery is reading abnormal reading of 11.8, and the battery indicator is flashing on and off. E42

Task performed:

1. TRAVELED TO STN 42. REPLACED ALTENATOR AND REPLACED BATTERIES. TEST/ OK.

Parts

4867JB320 UPGRADE ALTERNATOR

65-72BXT65750 BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

HP-31DBATTERY 950CCA HP-31D

Quantity

1

1

5

4



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V5466

In Date: 11/21/2006

Meter Reading: 1,589.00

Close Date: 02/07/2007

Problem?

lens cover on driver side red clearance light broke. held on with piece of tape re42

Task performed:

1. Repaired marker light

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V7072

In Date: 03/06/2007

Meter Reading: 43,614.00

Close Date: 03/15/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED E42

Task performed:

1. B Inspection
2. Change gear oil drum
3. Service t-case
4. Service rear axle
5. Torque u-bolts
6. Change out coolant drum
7. Serviced batteries. Replaced battery cables. Clean and protect ends
8. Replaced shop drop light
9. Pressure check cooling system. Found leak at metal lines feeding air comp. Removed fuel filter housing secured loose lines and reinstalled filter housing
10. Service cooling system
11. Adjusted belts
12. Serviced small engines and equipment
13. Lubricated all latches. Tightened and adjusted latches as needed
14. Repair spot light hanger and crimp cable
15. Replaced RPM cable and housing
16. Rebuild left and right intake drains. Rebuild primer valve. R&R primer pump. Replaced sensing valve check valve. Perform dry vacume test. Replaced foam fill pump. Replaced left intake cap chain
17. Replaced door seals
18. Replaced flag decals
19. Replaced left rear clearance light. Replaced bulbs in rear and a/c selector light
20. Diagnose air leaks. Found leaks at parking brake valve, and primary gauge hose connection. Replaced valve and hose connection. Repaired defroster cable
21. Check all codes
22. Union meeting
23. Clean work area
24. Adjust air horns

Parts

Quantity

040114003SEAL SVS DRAIN VALVE	4
042-0091-00SPRING PRIMER	1
073004100PISTON	1
372000082CHROME MARKER LIGHT MOUNT	1
3920773WASHER DRAIN PLUG	1
4300-505PUMP FLOJET 12V	1
45124CABLE SPEEDO INNER	1
67BULB 12 VOLT	6
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
800034VALVE PARKING BRK.	1
A0631087000CABLE BATT. POS.	1
ACX-84534LUG NUT COVER PK10	5
BPR5ESSPARK PLUG 7734	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
REDG6S14023 GASKET 6 IN	1
UMVS254411STRAP 46 IN	3



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V7086

In Date: 03/06/2007

Meter Reading: 43,614.00

Close Date: 03/20/2007

Problem?

replace hose bed cover central auto trim e42

Task performed:

Parts

Quantity

Replaced hose bed cover Central Auto Trim E42

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM

Workorder: V7397

In Date: 03/27/2007

Meter Reading: 44,273.00

Close Date: 04/03/2007

Problem?

RE42 oil leak from filter

Task performed:

Parts

Quantity

Repaired oil filter leak

HPH6349AOIL FILTER 51748

1

Workorder: V7603

In Date: 04/09/2007

Meter Reading: 1,684.00

Close Date: 04/24/2007

Problem?

Reporting foam in the water tank. re42

Task performed:

Parts

Quantity

Monitored system, found no foam in tank

0381570000038-1570-06-0 VALVE CHECK 3 IN 9003-1

1

0460050000GASKET

4

Workorder: V8061

In Date: 05/02/2007

Meter Reading: 1,700.30

Close Date: 05/08/2007

Problem?

hooks placed into engine for firefighter and lieutenant' helmets E-42

Task performed:

Parts

Quantity

Installed hook in cab

NO PARTS USED

Adjusted tank to pump valve linkage



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V8125

In Date: 05/06/2007
Close Date: 05/18/2007

Meter Reading: 1,713.00

Problem?

Drivers side low beam headlight not working E-42

Task performed:

Replaced headlight

Parts

NO PARTS USED

Quantity

Workorder: V8154

In Date: 05/08/2007
Close Date: 05/18/2007

Meter Reading: 1,713.00

Problem?

Relief valve on E42 does not reset after being activated, does not work properly.

Task performed:

Ran pump and teste opn; tested ok

Parts

NO PARTS USED

Quantity

Workorder: V8478

In Date: 05/30/2007
Close Date: 06/05/2007

Meter Reading: 46,697.00

Problem?

REPAIR HURST UNIT E42

Task performed:

1. repalce spark plug at scene

Parts

BPR5ESSPARK PLUG 7734

Quantity

4

Workorder: V8693

In Date: 06/09/2007
Close Date: 06/19/2007

Meter Reading: 47,262.00

Problem?

puncture/tear to drivers seat in need of repair, E-42

Task performed:

1. Will repair at B inspection. Will monitor tear

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V8875

In Date: 06/16/2007
Close Date: 07/03/2007

Meter Reading: 47,504.00

Problem?

relief drain valve slow drip/leak, backflushed pump yesterday and noticed leak, shut all valves completely and still small leak E42

Task performed:

Checked for leaks; ran pump; chkd ok

Parts

NO PARTS USED

Quantity

Workorder: V8884

In Date: 06/17/2007
Close Date: 07/03/2007

Meter Reading: 47,504.00

Problem?

when left turning signal is engage the reverse warning sound is also engage. E42

Task performed:

Fnd no problem with turn signals

Parts

NO PARTS USED

Quantity

Workorder: V8936

In Date: 06/20/2007
Close Date: 07/03/2007

Meter Reading: 47,620.00

Problem?

having difficulty open/close gate on right rear. Unable to close it completely after open.E42

Task performed:

Chkd problem w/valve & fnd under pressure drain valves & rechkd; tested ok

Parts

NO PARTS USED

Quantity

Workorder: V8960

In Date: 06/22/2007
Close Date: 07/03/2007

Meter Reading: 1,737.00

Problem?

gauge on water tank showing less than full when tank is full, tank shows 3/4 when full E42

Task performed:

fND WATER TANK NOT FULL; HAD DRIVER TOP OFF TANK

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V8990

In Date: 06/24/2007

Meter Reading:

Close Date: 07/06/2007

Problem?

Map light on E42 is broke at base

Task performed:

1. Installed new style map light and rewired unit

Parts

Quantity

038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.

1

18753-0455H7935-1 SPOT LIGHT BULB SPT6008

1

3320-0027CHECK VALVE 1/2 FOAMPRO

1

772SK12-H772SK12-H SPOT LIGHT

1

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V9091

In Date: 07/02/2007

Meter Reading: 47,751.00

Close Date: 07/06/2007

Problem?

WATEREAK, RE-42

Task performed:

1. Relief valve leaking- hooked up to hydrant and reset/ checked for leaks

Parts

Quantity

NO PARTS USED

Workorder: V8713

In Date: 06/11/2007

Meter Reading: 1,736.00

Close Date: 08/20/2007

Problem?

digital gauge on pump panel need to be replace due to rpm illumination. E42

Task performed:

Installed new gauge

Parts

Quantity

PBA101-A00PUMP BOSS GOVERNOR

1

Workorder: V10039

In Date: 08/21/2007

Meter Reading: 1,743.00

Close Date: 09/11/2007

Problem?

siren speaker 2 light not illuminating on system check. 2 separate led emergency flashers not fully illuminating on officers side. rear tires need to be inspected for tread wear. e42

Task performed:

1. Installed three LED light that were not working
2. Replc rear tires
3. Fnd no problem w/siren

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6

4



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V10050

In Date: 08/22/2007

Meter Reading: 1,743.00

Close Date: 09/12/2007

Problem?

REPLACE REAR TIRES AT STA 42 E 42 CALLAGHAN

Task performed:

Replace tires - Callaghan

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V10366

In Date: 09/11/2007

Meter Reading: 1,743.00

Close Date: 09/24/2007

Problem?

PASS SIDE SIREN SPEAKER NOT WORKING AT ALL E42

Task performed:

1. DROVE FROM STA 36 TO STA 42 FOUND SIREN SPEAKER ON RIGHT SIDE OUT. R/R SIREN SPEAKER, TEST O.K. FOUND BROKEN LENS COVER ON RIGHT FRONT TURN SIGNAL, R/R LENS

Parts

91513AMBER LENS

SD-210RXSIREN DRIVER SMALL

Quantity

1

1

Workorder: V10534

In Date: 09/19/2007

Meter Reading: 1,743.00

Close Date: 09/25/2007

Problem?

hydrant wrench is broken E-42

Task performed:

1. Dropped off wrench
2. Chkd brakes; driver claims brakes smoking; fnd retarder not turned on

Parts

NO PARTS USED

Quantity

Workorder: V10600

In Date: 09/21/2007

Meter Reading: 509,733.00

Close Date: 09/27/2007

Problem?

E42 electric siren not working on last call. The siren was operable on morning check but 10-7 on last emergency response. Dispatch notified of vehicle o.o.s.

Task performed:

1. REPLACED LEFT SIDE SIREN SPEAKER.
2. WATER LEVEL GAUGES INOP- RECALABRATED GAUGES.

Parts

SD-210RXSIREN DRIVER SMALL

Quantity

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V10648

In Date: 09/25/2007

Meter Reading: 511,511.00

Close Date: 10/01/2007

Problem?

SPOTLIGHT INOP, RE-42

Task performed:

1. R/R SPOTLIGHT
2. FOAM GAUGE INOP- RECALIBRATED FOAM GAUGE
3. FOAM LEAK FOUND LEAK AT FOAM FILTER, REPAIRED

Parts

Quantity

620122SPOT LIGHT REMOTE

1

Workorder: V10719

In Date: 09/28/2007

Meter Reading: 51,226.00

Close Date: 10/01/2007

Problem?

chain saw 10-7e42

Task performed:

1. DROPPED OFF SAW BLADES
2. CLEANED CARB AND INSTALLED NEW BLADE

Parts

Quantity

NO PARTS USED

Workorder: V10739

In Date: 09/28/2007

Meter Reading: 1,743.00

Close Date: 10/02/2007

Problem?

unable to set on board hale foam system from default, foam system works just won't adjust off .05% E42

Task performed:

1. CHECKED PROBLEM WITH FOAM SYSTEM, NO PROBLEM FOUND
2. ADJUSTED CAB DOOR LATCH THAT WAS NOT CLOSING AND HARD TO OPEN

Parts

Quantity

NO PARTS USED

Workorder: V10748

In Date: 09/30/2007

Meter Reading: 51,226.00

Close Date: 10/02/2007

Problem?

Water is leaking into medical cabinet passenger side on E42

Task performed:

1. RESEALED COMPARTMENT

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V4711

In Date: 10/03/2006

Meter Reading: 37,269.00

Close Date: 10/15/2007

Problem?

OFFICERS SEAT BELT 10-7 E42

Task performed:

1. officer seatbelt inop

Parts

IMMF11358SEAT BELTS

Quantity

1

Workorder: V8031

In Date: 05/01/2007

Meter Reading: 45,624.00

Close Date: 10/15/2007

Problem?

flat repair E42 (outside agency-callaghan tire)

Task performed:

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V10830

In Date: 10/04/2007

Meter Reading: 51,477.00

Close Date: 10/22/2007

Problem?

repair water leak re42

Task performed:

- checked for water leak coming from top of truck. maybe tank will monitor.
- drivers seat belt doe not retract. readjusted seat belt arm.

Parts

NO PARTS USED

Quantity

Workorder: V11324

In Date: 10/30/2007

Meter Reading: 51,767.00

Close Date: 11/13/2007

Problem?

repair seat central auto trim

Task performed:

repair seat central auto trim

Parts

NO PARTS USED

Quantity

Vendor?: CENTRAL AUTO TRIM CO



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V11138

In Date: 10/19/2007

Meter Reading: 51,767.00

Close Date: 11/14/2007

Problem?

b inspection and repairs as needed e42

Task performed:

Parts

Quantity



3/2/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

1. R+R rear brakes.	0100080010STRAINER	2
2. R+R Trans cooler and pressure test coolant system.	038-1550-00VALVE CHECK HALE 1/4"	1
3. R+R Air dryer	040114003SEAL SVS DRAIN VALVE	6
4. Rebuild Trans. retarder accumulor and replace air valve.	05-17223-000CAP RADIATOR 10 LB	1
5. Remove driver seat for repair. Tistal new seat.	101291029FLUSH LOCK	1
6. R+R right rear discharge valve/ test found drain leak, repaired drain hose.	107796DRYER KIT AD9 -NEW	1
7. Filled truck with water after tank repair.	107800VALVE CHECK AD9	1
8. Remove hose bed so tank repairman could repair tank. Flush tank twice after repair. put hose bed back and loaded hose.	1160033 IN FLANGE ADPT W/ HOLES P2S	1
9. R+R clearance light both upper rear and left middle lower yellow clearance light.	130001001VANE ROTOR	4
10. R+R rear tail board.	14022-1-5COOLER 14032	1
11. Install R and L crosslay preconnect nets	17211-ZE7-W03HONDA AIR FILTER	1
12. Repair Comp. door latch below R/S crosslay	22-49905-000CABLE HEATER	1
13. Repaired backup alarm connector.	23920-9213UTILITY PUMP	1
14. R+R R/S body warning LT below comp R-1	2952271729552377 VALVE ASSY.ACCUM	1
15. B Service	29535973ACCUM.KIT	1
16. R+R batterys and repair battery box latch	35200-YLIGHT MARKER LEDAMBER	1
17. Found water in T case drain and flash, ran pump, check for leaks no leak found and no noise in bearing.	3576REAR BRAKE DRUMS	2
18. Repaired drain valve on #2 discharge, did vaccum test and Failed, did presure test found hose reel valve leaking. R+R hose reel valve, tested. R+R Inlet relief and check valve and retest, rebuild primer pump and past test.	372000084MARKER LIGHT	2
	50R03ZRRLIGHT 500 TIR LED	1
	546126000TPM/QG HALE REPAIR KIT	1
	5462270020VALVE KIT SS 546-2270-02-0	1
	56415CIG. LIGHTER ACCES.	1
	580-237580-237 SEAL	2
	6806970098SEAL DOOR	1
	7460967AIR FILTER 17210-ZE2-515 HONDA	1
	800405PURGE VALVE KIT	1
	883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
	9447BELT	1
	9470BELT	1
	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	4
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	BPR5ESSPARK PLUG 7734	2
	CA8193AIR FILTER 46744 WIX	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	HP-31DBATTERY 950CCA HP-31D	4
	HPH6349AOIL FILTER 51748	1
	K080716BELT	1
	PR338324070 WIX FILTER WATER	1
	R90PFILTER FUEL 33231	1
	REDG6S14023 GASKET 6 IN	2
	RTBASSYREAR TAIL BRD OUT 91 IN	1
	S777COUPLING NIPPLE	2
	SS-25SC5025 SUCTION SCREEN	2
	XK3014707QPUSE XK4034707QPM QPLUS BRAKE SHOES	2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V11500

In Date: 11/07/2007

Meter Reading: 51,767.00

Close Date: 11/14/2007

Problem?

Foam system does not work, Display shows multiple numbers and does not respond e42

Task performed:

1. Replaced foam display head and calabrated system.
2. Repaired slid out tray that was lose.

Parts

168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE

Quantity

1

Workorder: V11592

In Date: 11/14/2007

Meter Reading: 52,313.00

Close Date: 11/14/2007

Problem?

comp door hard to open r36

Task performed:

1. Side entry door hard to open adjusted door hinge.
2. Vista shows node 4 short, traced out wiring and found shorted wirh and rear light.

Parts

194BULB

Quantity

10

Workorder: V11477

In Date: 11/06/2007

Meter Reading: 51,767.00

Close Date: 11/26/2007

Problem?

replace tire E42 (outside agency-callaghan tire)

Task performed:

Replace tire E42 - Callghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLGHAN

Workorder: V11549

In Date: 11/09/2007

Meter Reading: 1,748.00

Close Date: 11/29/2007

Problem?

drivers side tele-light has one bulb out, light is only half functional e42

Task performed:

1. Replaced bulb in left side spot light.
2. Roof mounted spot light inop- removed light head and cleaned contacts on relay.

Parts

76062-15-NCSWITCH PRESS

76575-4-NOSWITCH

Quantity

1

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V12316

In Date: 01/02/2008
Close Date: 01/08/2008

Meter Reading: 54,099.00

Problem?

repair generator e42

Task performed:

Repair generator E42 - Regans Small Eng

j

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL ENG

Workorder: V6811

In Date: 02/18/2007
Close Date: 01/14/2008

Meter Reading: 42,973.00

Problem?

on call air leak re42

Task performed:

Parts

800405PURGE VALVE KIT

Quantity

1

Workorder: V12315

In Date: 01/02/2008
Close Date: 01/16/2008

Meter Reading: 54,099.00

Problem?

repair ram fan e42

Task performed:

Repair ram fan E42 - Regans Small Eng

j

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL ENG

Workorder: V12700

In Date: 01/19/2008
Close Date: 01/29/2008

Meter Reading: 54,949.00

Problem?

bulb need to be replace in telescope scene light E42

Task performed:

1. Checked out scene light and found unit working.

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V12647

In Date: 01/17/2008

Meter Reading:

Close Date: 02/01/2008

Problem?

engine 42 panel lights not operational, tele lights not operational, relief valve light not operational but valve is working, emergency lights are working, side hood emergency light broken, no impact visible

Task performed:

1. Chkd out pump panel lights; fnd no lights out
2. Frnt LED inop; replc LED light j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V12784

In Date: 01/24/2008

Meter Reading: 1,748.00

Close Date: 02/04/2008

Problem?

remote spotlight bulb out, spotlight will turn but not light up e42

Task performed:

Rep bad conn in spotlight. j

Parts

NO PARTS USED

Quantity

Workorder: V239

In Date: 10/17/2005

Meter Reading: 23,584.00

Close Date: 02/07/2008

Problem?

BOTH FRONT TURN SIGNAL REFLECTORS CRACKED RE-42

Task performed:

Parts

91513AMBER LENS

Quantity

2

Workorder: V2832

In Date: 06/01/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

repair or replace hard suction due to severe air leak during drafting evolution, tried to tighten collars with no improvement.

Task performed:

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V3576

In Date: 07/21/2006

Meter Reading:

Close Date: 02/07/2008

Problem?

HOSE BED COVER AT CENTRAL AUTO TRIM E42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V9074

In Date: 01/01/1900

Meter Reading: 47,751.00

Close Date: 02/07/2008

Problem?

WATER LEAK RE-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V13181

In Date: 02/11/2008

Meter Reading: 55,658.00

Close Date: 02/13/2008

Problem?

hurst power unit out of service. leaking hydraulic fluid from tank area. e42

Task performed:

Parts

Quantity

1. Sent to shop for repair

NO PARTS USED

Workorder: V13579

In Date: 02/28/2008

Meter Reading: 56,212.00

Close Date: 03/05/2008

Problem?

REPAIR TURN SIGNAL E42

Task performed:

Parts

Quantity

1. Turn signals inop, repaired bad connection

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V13951

In Date: 03/18/2008

Meter Reading: 56,788.00

Close Date: 03/20/2008

Problem?

repair coolant leak e42

Task performed:

Parts

Quantity

- Coolent leak, replaced hose that was leaking
- Foam guage inop, recalabrate foam guage and tester

NO PARTS USED

Workorder: V14255

In Date: 04/03/2008

Meter Reading: 1,764.00

Close Date: 04/10/2008

Problem?

Hurst power unit mounts are broken. e42

Task performed:

Parts

Quantity

- installed new hurst feet.

377R054FEET - HURST TOOL

1

Workorder: V14034

In Date: 03/21/2008

Meter Reading: 1,748.00

Close Date: 04/11/2008

Problem?

Need 9 lugnut covers for front driver side wheel on E42.

Task performed:

Parts

Quantity

- e 42 needs 9 lugnut covers on rear wheels. installed lug nut covers on rear wheels.

NO PARTS USED

Workorder: V14510

In Date: 04/16/2008

Meter Reading: 1,799.00

Close Date: 04/30/2008

Problem?

24 ft. extension ladder needs to be serviced, halliard/pulleys and rope inoperable due to pulleys ceasing to spin and rope uncontrollably jumping the pulley track E42

Task performed:

Parts

Quantity

- repaired pollys on ladder and tested.

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V14584

In Date: 04/21/2008

Meter Reading: 58,083.00

Close Date: 04/30/2008

Problem?

E42's intake pressure relief discharge is leaking.

Task performed:

Parts

Quantity

1. checked for leaks-ran pump at hyrent and found no leak

NO PARTS USED

Workorder: V13981

In Date: 03/19/2008

Meter Reading: 56,788.00

Close Date: 05/05/2008

Problem?

repair hurst unit team equip e42

Task performed:

Parts

Quantity

Repair Hurst unit (E42) - %Team Equipment

j

NO PARTS USED

Vendor?: TEAM EQUIPMENT

Workorder: V14909

In Date: 05/07/2008

Meter Reading: 58,176.00

Close Date: 05/14/2008

Problem?

oil leak e42

Task performed:

Parts

Quantity

1. swaped out truck and will send to out to repair

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V15291

In Date: 05/23/2008

Meter Reading: 58,645.00

Close Date: 06/10/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED E42

Task performed:

- B-Inspection
 - 5/27/08 3.0 hrs
 - 5/28/08 3.0 hrs Total 6.0 hrs
- 2. Eng oil leak/oil pan gskt; cldn out; run eng & tightened pan bolts.
- 3. Starter worn out; replc starter.
- 4. Drive line noise/diff pinion hsng; reinstallation of diff.
 - 5/29/08 5.0 hrs
 - 6/2/08 5.0 hrs Total 10.0 hrs
- 5. Diff/pinion hsng; Fab tool fixture for trans jack; reinstallation of diff.
 - 5/29/08 8.0 hrs
 - 6/2/08 5.0 hrs Total 13.0 hrs
- 6. Tail board lights inop; light assy bad; isntalled new light asy.
- 7. A/C registers brkn; isntalled new registers.
- 8. Several dash lights & compt lights inop; installed bulbs as needed.
- 9. Slight pull to the right-tires; swapped tires; road tested ok.
 - 5/30/08 .5 hrs
 - 6/2/08 .5 hrs Murray Total 1.0 hrs
 - 5/30/08 .5 hrs
 - 6/2/08 .5 hrs Larson Total 1.0 hrs
- 10. Relief valve sticking; trash stuck in valve; blew out w/hydrant pressure.
- 11. Traffic cones/holders; installed new straps.
- 12. No communication w/trans ECM; data link fuse blown; rep data link & reset fast adapt; road test-ok.
- 13. Spotlight hanger inop; clip brokn; made new clip.
- 14. Btry box & trash line latches siezed; lcn, lubed & adj.
- 15. Foam guage inop-out of calibration & connector corroded; rep wiring conn & calibrated foam gauge.
- 16. Extenda lights inop-seized; cldn, lubed & adj lights.
- 17. L-door window trims & L/R door gskt worn out; also door panel; installed new trim gskt & rep panel. j

Parts

Quantity

10461769STARTER 38MT 12T	1
15W40BSYN OIL BULK QTS	24
35200-RLIGHT MARKER LED RED	3
401581GASKET AXLE FL80 R002435	2
6808300074VENT A/C LH	2
6808300174VENT A/C RH	3
A1834388002MOLD L/H	2
ACX-84534LUG NUT COVER PK10	20
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
REBUILT-DIFF3RD MEMBER COMPLETE	1
UMVS162511STRAP	1
UMVS254411STRAP 46 IN	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V14330

In Date: 04/07/2008

Meter Reading: 1,779.00

Close Date: 06/17/2008

Problem?

When battery is turned on back up warning signal comes on automatically, even with vehicle in neutral, drive, or reverse and stays on e42

Task performed:

Parts

Quantity

1. back up alarm stays on . traced out problem found connection full of water. removed / replaced

NO PARTS USED

Workorder: V15453

In Date: 06/02/2008

Meter Reading: 58,645.00

Close Date: 06/19/2008

Problem?

REPLACE TIRES AT SHOP E42

Task performed:

Parts

Quantity

Replace tires at shop E42 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V16156

In Date: 07/04/2008

Meter Reading: 59,118.00

Close Date: 07/18/2008

Problem?

top mounted spotlight will not move with remote control, appears to be stuck E-42

Task performed:

Parts

Quantity

rep bad connection in spotlight. j

NO PARTS USED

Workorder: V16246

In Date: 07/09/2008

Meter Reading: 59,118.00

Close Date: 07/21/2008

Problem?

REPLACE FRONT TIRES AT ST 36

Task performed:

Parts

Quantity

Replace front tires at Stn36 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V16298

In Date: 07/11/2008

Meter Reading: 59,118.00

Close Date: 07/30/2008

Problem?

The toggle that controls the overhead spot light is broken and needs to be replaced. e42

Task performed:

Waiting for E-One to repair. j

Parts

NO PARTS USED

Quantity

Workorder: V16704

In Date: 07/30/2008

Meter Reading: 1,924.00

Close Date: 08/05/2008

Problem?

emergency lights above rear wheels on the L and R side do not work properly E42

Task performed:

Chkd lights; fnd (1) LED light out in light; will replc when all are out. j

Parts

NO PARTS USED

Quantity

Workorder: V16810

In Date: 08/04/2008

Meter Reading: 1,932.00

Close Date: 08/14/2008

Problem?

-flashing light / officers side / not blinking -"ok to pump" indicator light is out E42

Task performed:

Replaced (2) LED lights. j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

2

Workorder: V17193

In Date: 08/20/2008

Meter Reading: 1,947.00

Close Date: 08/22/2008

Problem?

spot light won't move E42

Task performed:

Rep motor; had plate stuck in it. j

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V17553

In Date: 09/07/2008

Meter Reading: 1,973.00

Close Date: 09/29/2008

Problem?

broken speaker bracket for mobile radio speaker R-42

Task performed:

Parts

Quantity

Install new bracket for radio.

NO PARTS USED

Workorder: V17408

In Date: 08/30/2008

Meter Reading: 1,969.90

Close Date: 09/30/2008

Problem?

Driver side spot light bulb is out E42

Task performed:

Parts

Quantity

Repaired bad connection in light.

NO PARTS USED

Workorder: V17425

In Date: 09/01/2008

Meter Reading: 1,969.90

Close Date: 09/30/2008

Problem?

The foam display on the panel just flashes, Foam tank is full. Also the digital Tach on the panel drops the first number (thousands) Resch E-42

Task performed:

Parts

Quantity

Re-calibrate foam gauge and test.

NO PARTS USED

Workorder: V17450

In Date: 09/02/2008

Meter Reading: 1,969.90

Close Date: 09/30/2008

Problem?

Passenger side Quartz light lock nut is stripped and the drivers side sensor is malfunctioning. E42

Task performed:

Parts

Quantity

repaired quartz light handle that was not locking
foam guage inop-recalibrate

LT510-OCOUTER POLE

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V18148

In Date: 10/06/2008

Meter Reading: 62,303.20

Close Date: 10/15/2008

Problem?

REPLACE FRONT TIRES, E-42

Task performed:

Parts

Quantity

1-Replaced front tires on rescue.

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V18463

In Date: 10/21/2008

Meter Reading: 2,025.00

Close Date: 10/28/2008

Problem?

Inside door handle of the drivers compartment fell off. cannot open door.

Task performed:

Parts

Quantity

water level gauge inop; recalibrated unit. j

NO PARTS USED

Workorder: V18464

In Date: 10/21/2008

Meter Reading: 62,714.10

Close Date: 10/28/2008

Problem?

inside door handle broken E42

Task performed:

Parts

Quantity

1. Replc handle that was broken in L-1 c ompt.
2. Foam pickup pump inop; rep melted fuse holder & tested. j

6807200575HANDLE DOOR

2

HA24016HA24016 LATCH

2

Workorder: V18671

In Date: 10/28/2008

Meter Reading: 2,025.00

Close Date: 11/07/2008

Problem?

drive belt on K-12 saw snapped in half, saw is currently inoperable without belt, need replacement belt sent out asap, asset#10173645 E42

Task performed:

Parts

Quantity

Belt broken on K12; ordered new belt. j

K1200K1200 BELT

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V18904

In Date: 11/06/2008

Meter Reading: 63,112.00

Close Date: 12/01/2008

Problem?

relief valve drain has a slow/steady leak e42

Task performed:

Parts

Quantity

Chk pump for water leak; fnd none; ran pump & chkd opn & tested ok. j

NO PARTS USED

Workorder: V18913

In Date: 11/07/2008

Meter Reading: 2,029.00

Close Date: 12/01/2008

Problem?

Relief valve does not close/reset after activation. E-42

Task performed:

Parts

Quantity

Tested relief valve & tested ok. j

NO PARTS USED

Workorder: V19012

In Date: 11/12/2008

Meter Reading: 2,029.00

Close Date: 12/01/2008

Problem?

relief valve leaking, both water and foam slowly leaking from relief drain E42

Task performed:

Parts

Quantity

1. Ran pump & flushed out relief valve; tested valve & tested ok.

NO PARTS USED

2. Foam going into pump; replc foam; chk valve.

j

Workorder: V19199

In Date: 11/20/2008

Meter Reading: 2,031.00

Close Date: 12/01/2008

Problem?

One of four hydraulic hoses split the entire length into two lines.

Task performed:

Parts

Quantity

Hurst hoses split; dropped off Hurst hoses. j

3530016HOSE HURST 16 ORANGE

2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V19191

In Date: 11/19/2008
Close Date: 12/02/2008

Meter Reading: 2,031.00

Problem?

lower left edge of hood on E42 is cracking and falling apart. Placed in IBEM per BC Wells request.e42

Task performed:

1. Turn signals inop; fnd bad connection at node 3; rep/tested.
2. Chkd hood & will repair at B. j

Parts

NO PARTS USED

Quantity

Workorder: V19349

In Date: 11/26/2008
Close Date: 12/02/2008

Meter Reading: 63,337.60

Problem?

REPAIR AIR LEAK E42

Task performed:

- Air leak; replcd pump shifter. j

Parts

5460370530VPS SHIFT KIT 546-0370-53-0

Quantity

1

Workorder: V19469

In Date: 12/02/2008
Close Date: 01/05/2009

Meter Reading: 63,337.60

Problem?

right lock on 24' extension ladder sticks and ladder won't lower. e42

Task performed:

1. Ladder locks inop; replcd ladder locks.
2. Ram fan feet msng; replcd (2) feet. j

Parts

NO PARTS USED

Quantity

Workorder: V19626

In Date: 12/09/2008
Close Date: 01/05/2009

Meter Reading: 63,874.00

Problem?

gas powered fan needs new rubber ground mount, chain saw needs 1 bolt on front chain guard e42

Task performed:

- installed new rubber feet on fan. j

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V19785

In Date: 12/16/2008

Meter Reading: 2,037.50

Close Date: 01/06/2009

Problem?

Air filter guage broken off E42

Task performed:

Filter minder broken; replaced. j

Parts

22-51374-000SENSOR AIR RESTRICTION

Quantity

1

Workorder: V19816

In Date: 12/17/2008

Meter Reading: 63,874.00

Close Date: 01/06/2009

Problem?

AIR FILTER INDICATOR LIGHT IS ON. E42

Task performed:

Filter minder brkn; ordered part; installed on another W/O. j

Parts

NO PARTS USED

Quantity

Workorder: V19934

In Date: 12/23/2008

Meter Reading: 64,251.50

Close Date: 01/06/2009

Problem?

water leak from pump area e42

Task performed:

Fnd dump valve leaking; back flushed pump & tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V20021

In Date: 12/30/2008

Meter Reading: 64,333.50

Close Date: 01/06/2009

Problem?

E42 leaking from intake pressure relief pipe and front Cpt's side blinker is out e42

Task performed:

1. water leak/fitting for foam inlet; rem fitting; clnd threads & resealed.

2. R/F turn signal inop; installed new bulb.

3. Relief valve sluggish-sticking; replcd w/rebuilt valve.

j

Parts

0100080010STRAINER

Quantity

2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V20143

In Date: 01/05/2009

Meter Reading: 64,723.00

Close Date: 01/15/2009

Problem?

officer side headlight burned out. E-42

Task performed:

Installed new headlight. j

Parts

NO PARTS USED

Quantity

Workorder: V20160

In Date: 01/06/2009

Meter Reading: 2,080.00

Close Date: 01/27/2009

Problem?

headlight on e42 had just been fixed, but the station 42 is going to need a few extra headlight lamp more as supply thank you.

Task performed:

1- Dropped off spare head lights.

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

6

Workorder: V20429

In Date: 01/18/2009

Meter Reading: 2,082.00

Close Date: 01/28/2009

Problem?

bleeder valve handle sheared off on passenger side midship underside E-42

Task performed:

1- Repaired valve that was missing on front suction

Parts

34BVVALVE DRAIN CLASS1

Quantity

2

Workorder: V20053

In Date: 12/31/2008

Meter Reading: 64,333.50

Close Date: 02/04/2009

Problem?

left upper scene light out e42

Task performed:

Scene light inop; bulb burnt & wiring converter bad; replcd bulb & wiring. j

Parts

60F000RRLIGHT 600 SERIES

681181363356811813633S LENS CLEAR

Quantity

1

1

Loose connector - rep connector. j



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V20452

In Date: 01/19/2009

Meter Reading: 2,085.50

Close Date: 02/10/2009

Problem?

"TankVision" LED display on pump panel does not light up. I visually checked foam tank (full) but display showed only a funky blinking top and bottom light on the display. E-42

Task performed:

1. Foam tank gauge inop.
2. Frnt intake bleeder inop; defective valve; replc drain valve.
3. Hurst feet worn; replaced; also (2) mounts.
4. L/R/I low pressure; air up; fnd leak @ valve stem; tightened stem; still leaking; called out Callaghan tire to replace stem. j

Parts

Quantity

5269LPVM-5 SM MOUNT	3
ABM-1BASE MOUNT ALUMINUM	2
LPVM-7LG MOUNT	3
SAHSVS2510STRAP	3
UMVS111611STRAP	3
WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352	1

Workorder: V20415

In Date: 01/16/2009

Meter Reading: 64,813.10

Close Date: 02/17/2009

Problem?

service hurst power unit e42

Task performed:

1. Hurst unit runs rough; dirt in carb; cldn out carb & replcd eng oil & spark plug.
2. Foam gauge inop; recalibrated but lost calibration the next day; truck is at shop now. j

Parts

Quantity

377R054FEET - HURST TOOL	1
BPR6ESSPARK PLUG 7131	2

Workorder: V20392

In Date: 01/15/2009

Meter Reading: 64,813.10

Close Date: 02/19/2009

Problem?

repair saw, repair blower sta 42 (outside agency-Regan's small engine service)

Task performed:

Repair saw, repair blower Stn42 - Regans j

Parts

Quantity

NO PARTS USED

Vendor?: REGANS SMALL ENG



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V21024

In Date: 02/10/2009

Meter Reading: 65,561.00

Close Date: 02/19/2009

Problem?

REPLACE 2 SCBA SEATS, E-42

Task performed:

Parts

Quantity

Replace (2) SCBA seats E42 - Central Auto Trim

NO PARTS USED

j

Vendor?: CENTRAL AUTO TRIM



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V20843

In Date: 02/03/2009

Meter Reading: 65,561.00

Close Date: 02/26/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED E42

Task performed:

Parts

Quantity



3/2/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

C-Inspection.	0100080010STRAINER	2
2. C-Inspection; replcd oil plug gskt.	040114003SEAL SVS DRAIN VALVE	2
3. Assist radio shop on lifting cab on Q57	040155000O RING	1
4. Cln btry cables & hold down.	0769027STRAINER 2.5 IN	1
5. Tighten tool brkts, strikers & latches.	0913912CHARGER 2000	1
6. Replcd wipers.	0915520120AUTO EJECT 20 AERO OTL3925	1
7. Replcd belts.	100R4FOAM HOSE AS PER SAMPLE	1
8. P/S svc.	107796DRYER KIT AD9 -NEW	1
9. Add washer fluid.	108-12FBEADED CHAIN W/CONN 12	3
10. Cln btry slides & lube; cln latches & lube.	13-7108GASKET AXLE	2
11. Cln trash line slide tracks & latches & lube.	15W40BSYN OIL BULK QTS	24
12. Replc drivers door weatherstrip.	168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
13. T-Case svc.	200-2450-00NC SWITCH OK TO PUMP	2
14. Trans Svc.	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	2
15. Dryer Svc.	284358GOVERNOR D-2	1
16. Retrofit deck gun from hale to Akron; re build tank fill #2 discharge drain valve; replcd sensing chk valve.	29526898 29548988 TRANS FILTER ALLISON	1
17. Perform dry vac test; replcd L-intake strainer; install msgng discharge cap screens.	338-25338-25 ADAPT.SUCTION	1
18. Rebuild side primer valve.	35200-RLIGHT MARKER LED RED	2
19. Replcd press & suction pump screens.	35200-YLIGHT MARKER LEDAMBER	1
20. Assist Jeff in repairs. - McIntosh	372000030BATTERY ON DISPLAY	1
21. Dia foam level gauge problem; tried to recalibrate-NG; drain foam tank & replcd sensor & refill tank; calibrate gauge - ok.	3920773WASHER DRAIN PLUG	1
22. Replcd master pump gauge.	52-24WIPER BLADES ANCO 24	2
23. R/R rear seats for upholstery repair.	5462270020VALVE KIT SS 546-2270-02-0	1
24. Dia foam fill pump inop; fnd bad swtch; replcd swtch.	55021-07SWITCH	1
25. Replcd cloth foam hose.	6806970098SEAL DOOR	1
26. Paint fuel cap & dipstick.	68118164443068-11816444-30 LENS	1
27. Help Ed. E. with training fire fighters & Snap-On dem of new scanner.	7460967AIR FILTER 17210-ZE2-515 HONDA	1
28. install auto-eject, btry charger, & display.	78R536078R5360M 2PK FILTER AIR COND	1
29. Replcd L-rear & R-rear marker lights; replcd rear right reflector & btry on light in dash.	800405PURGE VALVE KIT	1
30. Replcd brkn L-rear light bar lenses & sec base; cut lenses to size.	8126482-2106 TOGGLE GUARD	1
31. Rep R-side marker.	883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
32.Repair foam leak at fitting; R/R valve linkage & foam hose for access.	9447BELT	1
33. Install license plate.	9470BELT	1
34. Drain overfull on oil level.	98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
35. Dia & rep various air leaks; replcd gov, fittings & lines.	9UCAPCC9UCAPCC END CAP CLEAR	1
36.Replcd R-intake coupling.	CA8193AIR FILTER 46744 WIX	1
37. Replcd rear A/C vent.	FG87904MFG3937557S FILTER P/S NEW STYLE	1
38. Fill water tank, calibrate foam pump for water flow; tried to calibrate for foam flow-NG; dia sys; replcd foam flow sensor & adj; cln cables at distribution box & motor.	FGQ79699GASKET-P/S FILTER NEW STYLE	1
39. Work on calibrating foam pump.	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
40. Calibrate foam sys; cld not reach capacitybypass control head & test pump sys; still cld not reach capacity; either wrong model; worn pumper motor too slow.	HPH6349AOIL FILTER 51748	1
	I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT	1
	K080716BELT	1
	PR338324070 WIX FILTER WATER	1
	PVG-KITORING KIT	1
	R90PFILTER FUEL 33231	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

- 41. Replcd control head; calibrate water flow; tried to calibrate foam; only (4) gals; instead 055; ok per Ed Ehrke.
- 42. Help Hoover with fuel tank.
- 43. Pump engage & ok to pump not coming on; replcd switches at T-Case.
- 44. Install msng #4 discharge drain hose.
- 45. T-Case oil leak; fnd leak at RPM cable; tightened cable.
- 46. Replcd rear A/C vent. j

XE-WLPT1-S0CTANK SENSOR FOR TANK VISION

1

Workorder: V20790

In Date: 02/02/2009 Meter Reading: 65,561.00
 Close Date: 02/28/2009

Problem?

REPAIR TIRE E-42

Task performed:

Repair tire E42 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V21022

In Date: 02/10/2009 Meter Reading: 65,561.00
 Close Date: 02/28/2009

Problem?

REPLACE HOSE BED COVER, E-42

Task performed:

Replace hose bed cover E42 - Central Auto j

Parts

Quantity

NO PARTS USED

Vendor?: CENTRAL AUTO

Workorder: V21023

In Date: 02/10/2009 Meter Reading: 65,561.00
 Close Date: 02/28/2009

Problem?

REPLACE 4 REAR TIRES, BVD E-42

Task performed:

Replace (4) rear tires E42 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V21456

In Date: 03/02/2009
Close Date: 03/03/2009

Meter Reading: 65,843.00

Problem?

repair saw E42, repair float pump B47 (outside agency-regan's small engine service)

Task performed:

Repair saw E42 & float pump B47 - Regans j

Parts

NO PARTS USED

Quantity

Vendor?: REGANS SMALL ENG

Workorder: V21475

In Date: 03/02/2009
Close Date: 03/09/2009

Meter Reading: 65,843.00

Problem?

INSTALL BATTERY CHARGER AND AUTO EJECT, E-42

Task performed:

Unit was done at shop. j

Parts

1677004C9133232 FILTER SEPERATOR

1685210C91LIGHT TURN SIGNAL

BCPR5ESSPARK PLUGS 6130

Quantity

1

1

4

Workorder: V21371

In Date: 02/26/2009
Close Date: 03/12/2009

Meter Reading: 65,843.00

Problem?

ac belt squeels e42

Task performed:

1. Fnd A/C belt was wrong size; rem belt & installed new one.
2. Installed correct belt. j

Parts

6817200037HINGE UPPER

9440BELT

Quantity

1

1

Workorder: V21962

In Date: 03/20/2009
Close Date: 04/06/2009

Meter Reading: 66,496.00

Problem?

relief valve sticking E42

Task performed:

1. Rel valve sticking control head; replcd control head.
2. Pump testing. j

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V22422

In Date: 04/09/2009

Meter Reading: 66,778.00

Close Date: 05/04/2009

Problem?

REPAIR LEAKING VALVE E42

Task performed:

- #1 crosslay leaking-valve worn; replcd valve.
- Mansavers worn; installed new mansaver pads.
- Relief valve sticking; write up; working ok; flushed out sys; tested ok. j

Parts

Quantity

11133MIRROR MOUNT	2
546-0200-50QD REL.VALVE KIT	1
5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	1
5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	1
58525852 COUPLING	1
MSA150-A20MANSAYER COVER	2

Workorder: V22722

In Date: 04/21/2009

Meter Reading: 2,264.00

Close Date: 05/04/2009

Problem?

rear suspension is still terrible, worst of any engine I've driven in the county. E42's rear suspension easily bottoms out while driving over speed bumps.

Task performed:

- Chkd rear suspension; springs loosing arch; chkd springs-road tested bottoms over speed bump; springs shld be rearched.

Parts

Quantity

NO PARTS USED

Workorder: V22720

In Date: 04/21/2009

Meter Reading: 2,264.00

Close Date: 05/08/2009

Problem?

steering doesn't feel right, seems to grab on right turns. E42

Task performed:

- Chk steering; poss intermittent reduction in power assist; chkd frnt end components & lubed; road tested; replcd fluid & inspected filter. j

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V23361

In Date: 05/18/2009

Meter Reading: 67,702.00

Close Date: 06/16/2009

Problem?

water in fuel lt on e 42

Task performed:

1. Water in fuel; sensor defective; replcd water in fuel sensor & filter.
2. Cab A/C inop; switch & wiring burnt; replcd switch & rep wiring.
3. Mnt NY hook & sledge mnted. j

Parts

Quantity

50R03ZCRLIGHT LED RED TIR 6

2

ABPN8332229011-3050 SWITCH BLOWER

1

Workorder: V23680

In Date: 05/31/2009

Meter Reading: 626.00

Close Date: 06/19/2009

Problem?

E42 IS UNABLE TO START. POSS ELECTRICAL PROBLEM

Task performed:

No start; replcd starter solenoid. j

Parts

Quantity

ESX120105112STARTER RELAY ESX-120-105112

1

Workorder: V23719

In Date: 06/01/2009

Meter Reading: 68,740.00

Close Date: 06/24/2009

Problem?

REPAIR STROBE LT E42

Task performed:

(2) warning LED's inop - defective; replcd bulbs. j

Parts

Quantity

NO PARTS USED

Workorder: V23852

In Date: 06/05/2009

Meter Reading: 626.00

Close Date: 06/24/2009

Problem?

High pitch engine noise and front breaks are making a load noise upon aplying the brakes. E42

Task performed:

1. Chk for eng noise; fan belt glzed; chk all belts; adj A/C belts; chk pulley beari ngs; ordered new belts & tensioner.
2. Brake squeel; brake out; rem backing plates & cleaned brakes w/soap/water; road tested brakes; ok. j

Parts

Quantity

39768315259022 GROOVED TENSIONER OLD#3936213

1

9440BELT

1

9470BELT

1

K080716BELT

1



3/2/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V24201

In Date: 06/18/2009
Close Date: 07/01/2009

Meter Reading: 69,133.60

Problem?

deck gun alarm going off e42

Task performed:

1. Deck gun alarm going off; sensor out of ajd; adj sensor & road tested.
2. R/R top marker inop; connector corroded; rep connection. j

Parts	Quantity
122A217ASWITCH TOGGLE FOR NIGHT FIGHTER	1
372000082CHROME MARKER LIGHT MOUNT	1
372000084MARKER LIGHT	1
4007BULB NIGHT FIGHTER	1
8126482-2106 TOGGLE GUARD	2
XG840-KITEXTENDA GUN SWITCH	1

Workorder: V24687

In Date: 07/10/2009
Close Date: 08/05/2009

Meter Reading: 69,902.90

Problem?

EXTENDA GUN WARNING ACTIVATES INTERMITTENTLY

Task performed:

- Extenda gun activates intermittently; ordered new sensor & installed on another W/O. j

Parts	Quantity
XG840-KITEXTENDA GUN SWITCH	1

Workorder: V24746

In Date: 07/13/2009
Close Date: 08/05/2009

Meter Reading: 69,133.60

Problem?

RAM FAN STALLS

Task performed:

1. Ram fan stalls; carb jets clogged; cind out jets; replcd fuel, plug & eng oil.
2. Deck gun warning activates intermittently; replcd sensor & cind out all connectors; road tested. j

Parts	Quantity
17210ZE6505FILTER AIR HONDA	1
BCPR5ESSPARK PLUGS 6130	1
BPM8YSPRK PLUG BLOWER	2

Workorder: V25988

In Date: 09/03/2009
Close Date: 09/21/2009

Meter Reading: 71,082.50

Problem?

Secure hi-rise pack in compartment E42

Task performed:

- Secure hi-rise pack; installed strap. j

Parts	Quantity
NO PARTS USED	



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V26308

In Date: 09/17/2009

Meter Reading: 71,618.80

Close Date: 10/05/2009

Problem?

Hurst power unit mounts and feet broken E42

Task performed:

1. Hurst feet/mnts brkn; replcd feet/mounts.
2. Air leak line @ gov fitting; replcd fitting; epld hoses.
j
3. Chk/replc Hurst hoses-chaffed; r

Parts

Quantity

353R091USE 353R403 HURST HOSE 16 GREEN

1

377R054FEET - HURST TOOL

1

HR149460107MOUNT VIBRATION (NEWER POWER UNITS)

4

Workorder: V26865

In Date: 10/14/2009

Meter Reading: 72,062.90

Close Date: 10/27/2009

Problem?

install probar e42

Task performed:

Install pro bar - requirement. j

Parts

Quantity

5269LPVM-5 SM MOUNT

2

UMVS254411STRAP 46 IN

2

Workorder: V27299

In Date: 10/30/2009

Meter Reading: 72,403.40

Close Date: 11/16/2009

Problem?

replace 2 front tires-E42 at sta 42 (outside agency-callaghan tire)

Task performed:

Replc (2) frnt tires E42 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V27404

In Date: 11/04/2009

Meter Reading: 72,403.40

Close Date: 11/16/2009

Problem?

repair vent saw (outside agency-regan)

Task performed:

Repair vent saw - Regan j

Parts

Quantity

NO PARTS USED

Vendor?: REGAN SMALL ENG



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27020

In Date: 10/20/2009

Meter Reading: 72,403.40

Close Date: 11/25/2009

Problem?

b inspection and repairs as needed e42

Task performed:

- B-Inspection
- 2. Suspension bottoms out over bumps; Cab air susp valve defective; replc leveling valve/shocks; also reinstalled support brkt.
- 3. Eng oil leak - frnt crank seal; replc frnt crank seal.
- 4. Replc tank-to-pump & tank fill - leaking; installed new Hale valve kits.
- 5. Drivers door difficult to operate; latch bad; also outer handled mnt bent inside door; replcd latch asy & rep handle mntng.
- 6. Turn exh ____ frm medic cabinet; Stn request rem rusted & seized pipe & turned.
- 7. Replc brkn door trim L/F R/R; Replc ____ & tapped new thrds for R/R arm rest.
- 8. Noise in L/F wheel; brkn spring; isntalled new spring kit.
- 9. Mansavers loose; tightened mansavers.
- 10. Foam sys inop; metering wheel clogged up; cldd pump body.
- 11. Compt door struts worn; replc body struts & svc doors/panels.
- 12. Replc wipers, worn; replcd wipers; top off fluid & cln spray nozzle.
- 13. Frnt A/C compressor mnt bolt brkn; R/R brkn mntng bolt.
- 14. Water leak. deck gun fitting bad; replc deck gun fitting & rerouted tubing.
- 15. Water leak - instake relief debris; cldd out intake & installed new cable.
- 16. Reflectors cracked; replc reflectors as needed.
- 17. Drivers air seat inop; press protection valve clsd; chkd seat opn; airs up properly after PPV valve closes.
- 18. Svc gen.
- 19. Reflectors cracked; replc rear bumper reflectors. j

Parts

Quantity

101291015434 LATCH TRIGGER S/O	2
15W40BSYN OIL BULK QTS	24
2258Y1273BRAKE SPRING- SUIT CASE STYLE	2
4025270FRONT CRANK SEAL	1
52-24WIPER BLADES ANCO 24	2
5462270020VALVE KIT SS 546-2270-02-0	1
5462300020VALVE KIT SS VALVE 3 IN	1
6803230300 65482 SHOCK FRONT ENGINE	2
A1834388002MOLD L/H	2
E-2769MKT4515QB BRAKE KIT	2
EAA-8350-30UGSS1783UQ STRUT-LIFT	8
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LML-1201-0054CAB SHOCKS	2
LML-1350-0113AIR RIDE VALVE (CAB)	1
LML-1500-0071RUBBER PAD(CAB AIR RIDE)	1
R90PFILTER FUEL 33231	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V27718

In Date: 11/16/2009

Meter Reading: 72,799.30

Close Date: 11/30/2009

Problem?

LEFT CAB SIDE WARNING LED INOP

Task performed:

L/side warning inop-defective LED; replcd lamp asy. j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

1

Workorder: V28020

In Date: 11/30/2009

Meter Reading: 72,896.00

Close Date: 12/07/2009

Problem?

DRIVERS DOOR WONT OPEN FROM THE OUTSIDE E42

Task performed:

Drivers door cont open frm outside; linkage & ___ pin out of adjustment; adjusted. j

Parts

NO PARTS USED

Quantity

Workorder: V27947

In Date: 11/25/2009

Meter Reading: 992.00

Close Date: 12/21/2009

Problem?

Replace the piston on the left side of the engineers compartment door E42

Task performed:

Door strut berkn; replc door strut engineers compt. j

Parts

508RED58EC20RU STROBE-RED SURFACE MOUNT

AVMSE300A40PGSS1728UA STRUT S/O

EAA-8350-30UGSS1783UQ STRUT-LIFT

Quantity

1

1

1

Workorder: V28492

In Date: 12/20/2009

Meter Reading: 1,062.00

Close Date: 01/05/2010

Problem?

driver side headlight out E42

Task performed:

Headlight out - replcd. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V28609

In Date: 12/28/2009
Close Date: 01/12/2010

Meter Reading: 73,615.00

Problem?

INTERMITTENT BELT SQUEEL UPON ACCELERATION

Task performed:

Belt squeals; replcd tensioner; road tested. j

Parts

NO PARTS USED

Quantity

Workorder: V28872

In Date: 01/06/2010
Close Date: 02/22/2010

Meter Reading: 1,062.00

Problem?

LDH has pin size hole in it, it's been tagged and removed from service. A replacement from the bay has been put into service and onto engine 42.

Task performed:

1. Dropped off new hose.
2. Air leak; rep air leaks. j

Parts

NO PARTS USED

Quantity

Workorder: V28866

In Date: 01/06/2010
Close Date: 02/25/2010

Meter Reading: 73,615.00

Problem?

Repair ram fan E42 (outside agency-regan's small engine service)

Task performed:

rep ram fan E42 - Regan j

Parts

NO PARTS USED

Quantity

Vendor?: REGAN SMALL ENG

Workorder: V29971

In Date: 02/15/2010
Close Date: 03/04/2010

Meter Reading: 75,215.00

Problem?

rear OIC side compartment door (generator compartment) the hydraulic door piston is broken. E42

Task performed:

replc R/side rear door piston. j

Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

Quantity

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V30027

In Date: 02/17/2010

Meter Reading: 75,643.30

Close Date: 03/04/2010

Problem?

REPLACE BROKEN PRE-CONNECT NOZZLE HOLDERS, E-42

Task performed:

install new preconnect nozzle holder on R/side & L/side.

j

Parts

NO PARTS USED

Quantity

Workorder: V29972

In Date: 02/15/2010

Meter Reading: 75,215.00

Close Date: 03/10/2010

Problem?

OIC side halogen scene light bulb is out. E42

Task performed:

Replc bulb on L/S scene light. j

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1

Workorder: V30456

In Date: 03/04/2010

Meter Reading: 75,643.30

Close Date: 03/25/2010

Problem?

Tire low on air E42

Task performed:

Right rear outer tire had loose valve stem; tightened stem

j

Parts

NO PARTS USED

Quantity

Workorder: V30792

In Date: 03/17/2010

Meter Reading: 76,543.00

Close Date: 03/26/2010

Problem?

REPLACE HEADLIGHT, E-42

Task performed:

Replace headlight. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V30585

In Date: 03/09/2010

Meter Reading: 75,643.30

Close Date: 04/22/2010

Problem?

replace damaged tire e42

Task performed:

Parts

Quantity

Replace damaged tire E42 - Boulevard j

NO PARTS USED

Vendor?: KBOULEVARD TIRE

Workorder: V31347

In Date: 04/07/2010

Meter Reading: 76,646.00

Close Date: 04/28/2010

Problem?

1. Officer side running board emergency flasher OOS. 2. Telescopic scene lights OOS. 3. Brake pedel goes almost to floor. e42

Task performed:

Parts

Quantity

Brake pedal travel excessive; adj pedal rod travel.
Telsopic scene lite 10-7; fnd loose corroded grn
connection; cln connection & secure grnd cable. j

NO PARTS USED

Workorder: V31412

In Date: 04/09/2010

Meter Reading: 76,646.00

Close Date: 04/28/2010

Problem?

seals on discharge relief handle leaking. e42

Task performed:

Parts

Quantity

replc o-rings on #4 discharge valve; drain o-rings were
msng. j

NO PARTS USED

Workorder: V31880

In Date: 04/29/2010

Meter Reading: 76,646.00

Close Date: 05/05/2010

Problem?

Replace pully on 3 piece ground ladder E42

Task performed:

Parts

Quantity

replace pulley on 3-piece ladder. j

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V32304

In Date: 05/19/2010 Meter Reading: 78,210.00
Close Date: 05/28/2010

Problem?

L-3 COMPT. DOOR HOLD OPEN BROKEN, E-42

Task performed:

Task performed:	Parts	Quantity
Replace broken L-3 Compt door hold open. j	EAA-8350-30UGSS1783UQ STRUT-LIFT	1

Workorder: V32766

In Date: 06/09/2010 Meter Reading: 78,803.00
Close Date: 06/21/2010

Problem?

piston on medical compartment door broken. L-! compt door door swings loosely. E42

Task performed:

Task performed:	Parts	Quantity
Replc door strut on L-2 compt door. j	200-2450-00NC SWITCH OK TO PUMP	2
	EAA-8350-30UGSS1783UQ STRUT-LIFT	1

Workorder: V31769

In Date: 04/25/2010 Meter Reading: 76,646.00
Close Date: 07/14/2010

Problem?

Red emergency strobe just below medical compartment door is inop. E42

Task performed:

Task performed:	Parts	Quantity
R/R red LED light under R-1 compt door. j	50R03ZCRLIGHT LED RED TIR 6	1

Workorder: V33576

In Date: 07/16/2010 Meter Reading: 79,308.00
Close Date: 08/11/2010

Problem?

Driver seatbelt lock broken E42

Task performed:

Task performed:	Parts	Quantity
Replc driver side seat belt latch. ja	IMMF11358SEAT BELTS	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V33998

In Date: 08/03/2010

Meter Reading: 80,073.00

Close Date: 08/30/2010

Problem?

C inspection and repairs as needed e 42

Task performed:

1. Install pulley tensioner off of old unit and install on e-42 it needed a different belt could not adjust.
2. C-Inspection
3. Rem fan, belts, turbo, exh sys, exh manifold; rem brkn bolts frm cyl head; rem alt to get to one of the brkn bolts.
4. R/R wtr pump, belt tensioner; replc all eng belts; install fan/pulleys; replc A/C belt idler pulley; adj belts to spec.
5. Rebuilb dryer.
6. Replc wiper blades.
7. Replc R/side top rear 7 R/side bottom rear & L/side top rear LED red lights; had rows of LED lights out.
8. Svc T-case.
9. Svc cooling sys.
10. Replc pump walkway lights; LED's were out.
11. replc cab A/C filter.
12. Replc pump panel compt latches on R/side pump panel.
13. Install exh manifod, turbo, coolant hoses, exh pipes, turbo pipes; run eng; rechk all connections.
14. R/side marker turn & R/side rear t-signal inop; trace wiring frm cab to rear of veh; ck nodes; fnd weather pack connection on frame rail bad; rep ok.
15. Install screen on radio compt fan.
16. Replc L/side telescoping light bulb.
17. Replc L/side middle marker/turn signal LED's - burnt out.
18. Replc (3) discharge cap chain.
19. Extend a gun light comes on; rem sensor & cln; chk wiring; seems ok now. ja

Parts

Quantity

0106837849C8COMP LIGHT WHITE LED 200	2
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	3
15W40BSYN OIL BULK QTS	24
3519807TURBO GASKET	1
35200-YLIGHT MARKER LEDAMBER	1
3818824TURBO NUT	4
39013563901356 EXH.GASKET	1
3943841EXHAUST MANIFOLD	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
40896474309418 PUMP-WATER ISC REBUILT	1
52-24WIPER BLADES ANCO 24	2
60A00TARLED TURN SIGNAL LAMP	1
60R00FRR600 SERIES RED LED W/O FLANGE	2
60R00XRRBRAKE/TAILIGHT LED	1
65-72BXT65750 BATTERY	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9440BELT	1
9447BELT	1
9470BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	1
CA8193AIR FILTER 46744 WIX	1
EXO3AH00015SPLUG RAD. DRAIN	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
LB-D30BULB QUARTZ HAL. 12V 150W	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V34607

In Date: 08/30/2010
Close Date: 08/30/2010

Meter Reading: 79,308.00

Problem?

K-12 SAW PULL CORD BROKEN, E-42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V28429

In Date: 12/16/2009
Close Date: 09/09/2010

Meter Reading: 1,062.00

Problem?

THE HALARD FOR THE 24FT EXTENTION LADDER ON E42 IS BEGINING TO FRAY.

Task performed:

Parts

Quantity

Chk ladder rope & cut rope end off that was frayed.

NO PARTS USED

Workorder: V34913

In Date: 09/13/2010
Close Date: 09/14/2010

Meter Reading: 79,308.00

Problem?

The tint inthe frontcab of E42 is delaminating and making it difficult to see through windows at night

Task performed:

Parts

Quantity

1. clean windows of cab with windex, can see out of windows now per. capt. peterson. next time vehicle is in for a PM have windows tinted.

NO PARTS USED

Workorder: V34619

In Date: 08/30/2010
Close Date: 10/20/2010

Meter Reading: 79,308.00

Problem?

TIC charger is not charging the tic or any batteries. The lights of the charger are not coming on and acknowledging anything is connected. E42

Task performed:

Parts

Quantity

Replc power fuse for charger. j

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V36218

In Date: 11/05/2010

Meter Reading: 79,308.00

Close Date: 11/05/2010

Problem?

OUTER RIGHT REAR TIRE NEEDS REPLACEMENT. OUTER PORTION OF TIRE IS WEARING THIN. E42

Task performed:

Parts

Quantity

1. checked tire, still had 9/ 32nds on tire. spoke with the driver and told him to monitor the tire and there was no need to replace now...

NO PARTS USED

Workorder: V36504

In Date: 11/16/2010

Meter Reading: 79,308.00

Close Date: 12/03/2010

Problem?

REPLACE TIRE E 42 BOULEVARD

Task performed:

Parts

Quantity

Replc tire E42 - Boulevard j

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V37300

In Date: 12/20/2010

Meter Reading: 82,784.00

Close Date: 12/20/2010

Problem?

replace extinguisher e42

Task performed:

Parts

Quantity

parts only no labor

UMVS162511STRAP

1

Workorder: V30649

In Date: 03/11/2010

Meter Reading: 75,643.30

Close Date: 12/22/2010

Problem?

Discharge valves 1,2,3,and 4 (2.5 inch) are all leaking. Right Rear 2.5 may leak slightly as well; it lost 30-40 psi over 5 minutes. e4

Task performed:

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V34977

In Date: 09/15/2010
Close Date: 12/22/2010

Meter Reading: 79,308.00

Problem?

foam system not working properly. used during brush fire. it would flow for approx two minutes and shut off followed by (NO PR) c foam display panel. e42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V35607

In Date: 10/13/2010
Close Date: 12/22/2010

Meter Reading: 79,308.00

Problem?

possible short on battery switch. had to play with it turning it off and on a few times in order to get the batteries turned on. Thanks. E42

Task performed:

Parts

Quantity

(1) POSSIBLE SHORT ON BATTERY SWITCH. HAD TO MOVE IT ON AND OFF A FEW TIMES TO GET IT TO TURN ON. REPAIRED LOOSE CONNECTION ON BATTERY SWITCH. OK. J.W.

NO PARTS USED

Workorder: V35648

In Date: 10/14/2010
Close Date: 12/22/2010

Meter Reading: 79,308.00

Problem?

Side lense on drivers side front blinker is cracked. E42

Task performed:

Parts

Quantity

(1) FRONT DRIVER SIDE BLINKER LENS IS CRACKED ON E42. REPLACED LENS AS NEEDED. OK. J.W.

NO PARTS USED

Workorder: V36480

In Date: 11/16/2010
Close Date: 12/22/2010

Meter Reading: 79,308.00

Problem?

COOLANT LEAK E42

Task performed:

Parts

Quantity

(1) TRAVELED TO ST 42 TO REPAIR COOLANT LEAK ON E42. REPAIRED HOSECLAMP, OK. J.W.

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V37382

In Date: 12/22/2010

Meter Reading: 82,784.00

Close Date: 12/22/2010

Problem?

a/c blower inop, E-42

Task performed:

Parts

Quantity

1. check blower motor, remove dash replace connectors for blower motor switch

NO PARTS USED

Workorder: V38688

In Date: 02/22/2011

Meter Reading: 87,338.00

Close Date: 02/25/2011

Problem?

ON CALL E 42VPS PUMP SHIFT LEAKS

Task performed:

Parts

Quantity

Broke down @ training; stuck in pump gear shift o-ring; replcd o-ring. j

5460370530VPS SHIFT KIT 546-0370-53-0

1

Workorder: V38138

In Date: 01/29/2011

Meter Reading: 85,629.00

Close Date: 03/08/2011

Problem?

Replace all 6 tires E 42 (outside agency-TCI Tire)

Task performed:

Parts

Quantity

Replc all (6) tires e42 - TCI Tire j

NO PARTS USED

Vendor?: TCI TIRE



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V38698

In Date: 02/22/2011

Meter Reading: 87,464.00

Close Date: 03/15/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 42

Task performed:

1. B-Inspection
2. Replc btrys - (1) failed.
3. Trans slams into gear sometimes; need reprogramming/refast adapter
4. Stud loose on primer pump; retorqued power stud.
5. Replc wiper blades - worn; top off washer fluid.
6. Cab evap filter dirty; replc.
7. Trans retarder switch brkn; replc switch.
8. A/C condensor dirty; washed A/C condensor.
9. Eng oil leak pan gskt/breather; locate leak; will rep during C-inspection.
10. A/C sticks on defrost; evap box doors sticking; lube/adj cables/doors.
11. A/C deflectors brkn (2); replc deflectors.
12. Rainbow gauges - several LEDs inop; ordered new LEDs.
13. Hose bed cvr torn; R/R, also rep holddown. j

Parts

Quantity

15W40BSYN OIL BULK QTS	24
23-11345-710SCREW DASH	6
52-24WIPER BLADES ANCO 24	2
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
A2241425020SW ROCKER RETARDER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V39406

In Date: 03/24/2011

Meter Reading: 82,858.00

Close Date: 03/24/2011

Problem?

Vacuum test failed during pump test. Also right intake relief valve handle was damaged while tightening steamer cap. Doesnt alwa stay in position when pulled out. E42

Task performed:

1. replace # 3 discharge drain, driver hit it with rubber mallot when installing steamer cap...

Parts

Quantity

012-0010-00KNOB DRAIN	1
040114003SEAL SVS DRAIN VALVE	2
073-0180-00OSVS VALVE PISTON	1

Workorder: V39382

In Date: 03/23/2011

Meter Reading: 82,858.00

Close Date: 04/06/2011

Problem?

While checking oil, pulled dip stick out and hit an air hose which in turn started leaking air. It looks like the leak is near the fitting. E 42

Task performed:

1. Air leak; rep air fitting that was leaking.
2. Oil leak, cln pan & will monitor. j

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V39725

In Date: 05/16/2011

Meter Reading: 89,951.00

Close Date: 05/17/2011

Problem?

ON CALL E 42 HEADLIGHT 10-7

Task performed:

Headlight out; had no headlight at stn; rem/install new headlight. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V40830

In Date: 05/24/2011

Meter Reading: 89,951.00

Close Date: 05/24/2011

Problem?

screws missing from diamond plate cover for pre-connects, front intake not opening, E-42

Task performed:

1. screws missing from diamond plate cover for preconnects, replace the 8 screws missing
2. front intake not opening, check air valve and air switch and work it, found intake does open but very slow, replace air switch

Parts

NO PARTS USED

Quantity

Workorder: V40790

In Date: 05/23/2011

Meter Reading: 89,951.00

Close Date: 05/25/2011

Problem?

ON CALL ALT 10-7 E42

Task performed:

1. Go to Stn42; E42 smelled something, loss of power, stop eng; fnd alt bad; replc alt - ok at this time.
2. Restock vehicle. j

Parts

4867JB320 UPGRADE ALTERNATOR

Quantity

1

Workorder: V40099

In Date: 04/23/2011

Meter Reading: 89,342.60

Close Date: 06/02/2011

Problem?

Sawzall broken, the plastic shell is broken almost in half e42

Task performed:

DC will order new one. j

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V40779

In Date: 05/22/2011

Meter Reading: 89,951.00

Close Date: 06/09/2011

Problem?

RPM and MPH gauges not working E42

Task performed:

Tested gauges & road tested; all tested ok. j

Parts

NO PARTS USED

Quantity

Workorder: V41565

In Date: 06/23/2011

Meter Reading: 91,027.50

Close Date: 06/23/2011

Problem?

brakes smoking, E-42

Task performed:

1. check brakes, front @ 70% and rear @ 90% road test vehicle found retarder in off position. advised driver to look at retarder to make sure it is on.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

HP-31D BATTERY 950CCA HP-31D

2

2

Workorder: V41129

In Date: 06/06/2011

Meter Reading: 90,591.00

Close Date: 06/28/2011

Problem?

PTO handle is making a hissing sound and the green light will not go off. tried resetting twice and still the same air hissing sound. Sta 42.

Task performed:

pump shifter leaking repaired
pump shaft taht was loose repaired and tested ak

Parts

NO PARTS USED

Quantity

Workorder: V42446

In Date: 08/01/2011

Meter Reading: 91,844.00

Close Date: 08/02/2011

Problem?

Foam level gauge on pump panel is not working. Sta 42.

Task performed:

1. foam level gauge inop, check tranducer, check wiring, check gauge, found gauge bad, drain foam tank, install new gauge, and calibrate refill foam tank.
2. replace r-3 compt. door strut.

Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352

1

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V42823

In Date: 08/15/2011

Meter Reading: 92,411.00

Close Date: 08/15/2011

Problem?

check engine lite on, truck runs sluggish. E-42

Task performed:

1. check for codes, found 3 codes 268,451,459 for the fuel pressure sensor, remove sensor and remove gasket that was stuck in the fuel line, install new sensor and road test truck, check engine lite not on and truck runs ok..

Parts

4025130FUEL PRESS SENSOR

Quantity

1

Workorder: V42752

In Date: 08/11/2011

Meter Reading: 92,411.00

Close Date: 08/18/2011

Problem?

When going over speed bumps the cab sounds like it is going to break. if there is an airbag system for the cab it is not working. ju: happened on last call. thanks.

Task performed:

1. check air ride for cab, bags fully inflated, road test vehicle could not reproduce problem

Parts

NO PARTS USED

Quantity

Workorder: V42792

In Date: 08/14/2011

Meter Reading: 92,411.00

Close Date: 08/18/2011

Problem?

passenger headlight is not working R 42

Task performed:

1. w/o was written up for R-42 with asset # for E-42 check both units and headlights were working ok, low and high beam

Parts

NO PARTS USED

Quantity

Workorder: V43423

In Date: 09/05/2011

Meter Reading: 93,280.00

Close Date: 09/07/2011

Problem?

right headlight out. E42

Task performed:

1. r/side headlight inop, replace headlight, had power to headlight but no ground found wig wag ground bad. repalce wig-wag flasher

Parts

030126FLASHER SHO-ME

H6054USE CV TYPE SEALED BEAM

Quantity

1

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V43620

In Date: 09/13/2011

Meter Reading: 93,635.60

Close Date: 09/13/2011

Problem?

Hurst tool/ generator will not run for more than 30 secs. E 42

Task performed:

1. check unit for stalling, drain gas and add fresh gas, replace spark plug, still will not run call c/shop to send down a spare...

Parts

BPR5ESSPARK PLUG 7734

Quantity

1

Workorder: V43141

In Date: 08/29/2011

Meter Reading: 93,049.00

Close Date: 09/19/2011

Problem?

Water in fuel light came on. Sta 42.

Task performed:

found no light on and checked for water

Parts

NO PARTS USED

Quantity

Workorder: V43621

In Date: 09/13/2011

Meter Reading: 93,635.60

Close Date: 09/29/2011

Problem?

Right headlight goes out when turned to " bright" . e 42

Task performed:

1. check r/side headlight trace wiring to bulk head connector on firewall will wait till pm to repair

Parts

NO PARTS USED

Quantity

Workorder: V44009

In Date: 09/29/2011

Meter Reading: 93,972.50

Close Date: 09/29/2011

Problem?

spot light does not work on top of cab. driver hand light does not work. Sta 42.

Task performed:

1. check l/side quartz light, replace bulb, check driver side hand light charger ok, replace handlight. add 3 qts of motor oil

Parts

LB-H15150W 12V HID BULB

Quantity

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V44256

In Date: 10/10/2011

Meter Reading: 94,276.00

Close Date: 11/04/2011

Problem?

FF passenger officer side, light box recharger is inop. E 42

Task performed:

work completed on w/o 44265 for c insp.

Parts

Quantity

NO PARTS USED

Workorder: V41642

In Date: 06/28/2011

Meter Reading: 91,027.50

Close Date: 11/07/2011

Problem?

Left scene light out. station has no bulbs. Sta 42.

Task performed:

work completed on wo 44009 per Ed Orlando via email to Alicia on 11-7-11 at 1538

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V44265

In Date: 10/11/2011

Meter Reading: 94,354.00

Close Date: 11/07/2011

Problem?

C INSPECTION AND REPAIRS E 42

Task performed:

Parts

Quantity



3/2/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

1. C insp.	10206120FT HARNESS	1
2. batt. lite on dash inop, ing. lite on dash inop, replace both green lites	102161TRANSDUCER 500 PSI	1
3. 2 dash lites inop, replace bulbs	102190111667 DIGITAL DISPLAY PRESSURE	1
4. replace cab a/c filter	107796DRYER KIT AD9 -NEW	1
5. total of 4 a/c dash vents broken, replace all 4	107800VALVE CHECK AD9	1
6. all 4 cab door top window trim broken, replace all 4 moldings	15W40BSYN OIL BULK QTS	26
7. handlight chargers in cab inop, both in f/f seats, trace wiring found bad crimps at batt. cut out connectors and install new connectors.	17211-ZE7-W03HONDA AIR FILTER	1
8. fill windshield washer w/fluid	1878042C91FUEL FILTER 2008 HORTON	1
9. R-3 compt. hold open broken replace door strut	2506656C124316 WIX CAB A/C FILTER	1
10. r/side rear upper and lower red LED lites 1/2 out program and replace both warning lites	29526898 29548988 TRANS FILTER ALLISON	1
11. l/side rear upper and lower red LED lites 1/2 out program and replace both warning lites	35200-RLIGHT MARKER LED RED	2
12. ground ladder heat sensors expired, replace	372000030BATTERY ON DISPLAY	1
13. r/side upper bullet type clearance lit inop, replace lite assy.	372000031IGNITION ON DISPLAY	1
14. r/side pump panel lite lens missing, replace	3938160OIL PAN GASKET C SREIES	1
15. l/side pump panel lite lens cracked, replace lens	3944293GASKET GEAR CASE	1
16. r/side headlight is dim and goes out when high beams are turned on, trace wiring to bulk head connector at fire wall all ok, remove fuse panel in cab and found wire's loose on postive stud at fire wall inside cab. tighten connector	39768315259022 GROOVED TENSIONER OLD#3936213	1
17. l/side cab roof amber marker light inop, replace light assy.	4024883FRONT CRANK SEAL 6C	1
18. discharge relief valve inop, rebuild relief valve	52-24WIPER BLADES ANCO 24	2
19. FRC master intake and pressure LED lites 1/2 lite and face is cracked, cut pump panel out, make face plate for panel and install Class-1 LED gauges, install pressure and vac. transducer's and install wiring, fill water tank and calibrate gauges	5774457744XD OIL FILTER	1
20. FRC throttle excel LED's 1/2 lite up, replace throttle excel, unit turned on check engine and stop engine lites on dash and set engine codes, trouble shoot problem found throttle excel unit n/g, had another unit sent down and installed, check engine lites went out, erease engine codes all ok now	60R00FRR600 SERIES RED LED W/O FLANGE	4
21. failed vac. test. adjust all hale valves to assure they were closing, re-test passed ok.	6535SPARK PLUG CR5HSB	1
22. r/r discharge handle hard to open when flowing deck gun, found rod to short and was installed at the lowest hole on valve handle, cut new rod to size and thread rod, install on the farthest hole on valve handle and test ok.	6803230300 65482 SHOCK FRONT ENGINE	2
23. crank shaft seal leaking, remove fan,belts,pully's, balancer, and remove front engine cover, r&r crankshaft seal and install cover	6808300074VENT A/C LH	2
24. repalce all engine belts	6808300174VENT A/C RH	3
25. replace belt tensioner	7460967AIR FILTER 17210-ZE2-515 HONDA	1
26. service p/s	75W90GEAR OIL SYN QT	28
27. service T case	76062-15-NCSWITCH PRESS	1
	76072-15-DC76072-15-DC SWITCH SW76072	1
	78R536078R5360M 2PK FILTER AIR COND	1
	800034VALVE PARKING BRK.	2
	800405PURGE VALVE KIT	1
	9447BELT	1
	9470BELT	1
	A06-40578-000TOP CLEARANCE LIGHT M2	1
	A1834388002MOLD L/H	2
	A1834388003MOLD R/H	2
	BPR5ESSPARK PLUG 7734	2
	CA8193AIR FILTER 46744 WIX	2
	EAA-8350-30UGSS1783UQ STRUT-LIFT	4
	ELA101-ATHROTTLER EXCEL CUMMINS IS SERIES	2
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1
	K080716BELT	1
	PSISDIDITAL VACUUM GAUGE KIT	1
	RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

28. service air drier	REDG6S14023 GASKET 6 IN	1
29. service transmission	TRANSYNDALLISON TRANS FLUID GAL	5
30. found oil pan gasket leaking, remove pan and replace gasket		
31. service rear axel		
32. check for air leaks with soap and water, found fitting on foot valve leaking replace fitting, recheck and found dash brake valve leaking, remove dash and valve and replace recheck for leaks seems ok held air pressure overnight.		
33. refill coolant tank		
34. paint fuel cap..		
35. found water in fuel lite disconnected at raycor filter, hook back up and the water in fuel lite came on in the dash, replace sensor in fuel bowl, erease codes ok		
36. oil pressure sender leaking at the oil filter housing, replace sender		
37. r&r wiper blades		
38. r/side tri-lock on pump panel inop, replace tri-lock		
39. r/side and l/side red marker lite inop, replace lite assy's		
40. replace front shocks		
41. pump test, passed, filled out paper work will pass on to the proper personnel		
42. service generator		
43. service hurst tool		

Workorder: V46242

In Date: 01/03/2012 Meter Reading: 95,995.00
 Close Date: 01/06/2012

Problem?

replace rear tires boulevard

Task performed:	Parts	Quantity
REPLACE REAR TIRES BOULEVARD.	NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE

Workorder: V46010

In Date: 12/21/2011 Meter Reading:
 Close Date: 01/17/2012

Problem?

Left and right outside rear tire needs replacement. Tread is even with the wear tabs. Sta 42

Task performed:	Parts	Quantity
1. check rear tires, needs tires order tires	NO PARTS USED	



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V46184

In Date: 12/30/2011

Meter Reading:

Close Date: 01/17/2012

Problem?

SPOT LIGHT ON TOP OF CAB BURNT OUT. E42

Task performed:

1. replace l/side headlight

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V46525

In Date: 01/11/2012

Meter Reading:

Close Date: 01/17/2012

Problem?

Main spot light on roof of cab is burnt out. Sta 42

Task performed:

1. replace roof mounted spotlight,

Parts

620122SPOT LIGHT REMOTE

Quantity

1

Workorder: V47495

In Date: 02/22/2012

Meter Reading: 97,613.00

Close Date: 02/28/2012

Problem?

ON CALL HURST UNIT 10-7

Task performed:

- TRAVEL TO SHOP PICK SPARE HURST UNIT TAKE TO STATION 42.

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2

Workorder: V48014

In Date: 03/16/2012

Meter Reading: 98,351.00

Close Date: 03/16/2012

Problem?

front intake will not open, E-42

Task performed:

1. check front intake, found air switch inop, remove switch and transferr fittings to new valve and test ok

Parts

MJTV5 VALVE AIR CONTROL

Quantity

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V49421

In Date: 05/17/2012

Meter Reading: 100,108.00

Close Date: 05/17/2012

Problem?

ON CALL FLAT TIRE E 42

Task performed:

TRAVEL TO SHOP - MEET TIRE COMPANY AND GIVE HIM A TIRE TO SERVICE A FLAT ON E-42.

Parts

NO PARTS USED

Quantity

Workorder: V49265

In Date: 05/11/2012

Meter Reading: 99,900.30

Close Date: 05/25/2012

Problem?

When the brakes are depressed, there is a hissing sound of air. air stops when brake released.

Task performed:

REPLACED AIR SENDER IN DASH.

Parts

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

Quantity

1

Workorder: V49560

In Date: 05/17/2012

Meter Reading: 100,108.00

Close Date: 05/29/2012

Problem?

FLAT TIRE E 42

Task performed:

TRAVEL TO SHOP - MEET TIRE COMPANY AND GIVE HIM A TIRE TO SERVICE A FLAT ON E-42.

Vendor?: BOULEVARD TIRE CENTE

Parts

292850BRIDGESTONE 12R22.5 TIRE

Quantity

1

Workorder: V49996

In Date: 06/08/2012

Meter Reading: 100,721.00

Close Date: 06/12/2012

Problem?

replace front tires

Task performed:

REPLACE FRONT TIRES

Vendor?: ELPEX

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V49997

In Date: 06/08/2012

Meter Reading: 100,721.00

Close Date: 06/13/2012

Problem?

replace front tires service only e 42

Task performed:

Parts

Quantity

REPLACE FRONT TIRES SERVICE ONLY E 42.

NO PARTS USED

Vendor?: ELPEX

Workorder: V49992

In Date: 06/08/2012

Meter Reading: 100,721.00

Close Date: 06/15/2012

Problem?

driver side tire is worn inner wall. E42

Task performed:

Parts

Quantity

TIRES ARE BEING REPLACED.

NO PARTS USED

Workorder: V50147

In Date: 06/15/2012

Meter Reading: 100,937.60

Close Date: 06/25/2012

Problem?

RT HEADLIGHT OUT!

Task performed:

Parts

Quantity

REPLACED LIGHT AND REPAIRED WIRE.

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V50284

In Date: 06/21/2012

Meter Reading: 100,937.60

Close Date: 06/29/2012

Problem?

B INSPECTION E 42

Task performed:

1. B INSPECTION.
2. R&R STEERING COLUMN MOUNTS R&R DASH DISASSEMBLE BACK COVER TO R&R GAUGE BULB.
3. R&R 2 FRONT MARKER LIGHT BULBS AND ONE LENS.
4. R&R CAB ROOF MARKER LIGHT LENS R&R BULB
5. REPAIR WIRING AND CONNECTOR AT TRANS SENSOR AND SECURE WIRING.
6. DIAGNOSE WHY ALL REAR STEP LIGHTS OUT.
7. CAB AUX A/C SYSTEM REPAIRS.
8. CAB AUX A/C SYSTEM REPAIRS.
9. R&R FAN MOTOR ON REAR UNDER VEHICLE CONDENSER ASSY.
10. REPAIR L/R CAB DOOR INNER DOOR PANEL - FALLING OFF AND LOOSE.
11. R&R BANJO BOLT AT FUEL INJ PUMP. CHECK SEALING WASHERS REPLACE SEALS AND TEST.
12. R&R DOOR HOLD OPEN ON R/R COMPART DOOR.
13. Q.A. VEHICLE AFTER REPAIRS.

Parts

Quantity

16-3007TAPE 8990	1
160012-2012A EXPANSION VALVE 71R8301	1
4412S08-6963BS FITTING A/C	1
4923090025DASH BULB VDO	1
6806890001LOCK DASH	1
6808310398SEAL AIR DUCT	1
6809880278TURN PLUG	6
71R755011-2624 TRINARY SWITCH A/C 1560	1
74R258607-2613A RED DOT DRIER 7127	1
78R536078R5360M 2PK FILTER AIR COND	2
91513AMBER LENS	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1

Workorder: V47419

In Date: 02/19/2012

Meter Reading:

Close Date: 07/09/2012

Problem?

Hurst spare power unit will not run higher than idle. E 42

Task performed:

1. check power unit, replace spark plug drain gas and refill, run unit and make adjustments.

Parts

Quantity

NO PARTS USED

Workorder: V48322

In Date: 04/01/2012

Meter Reading:

Close Date: 07/09/2012

Problem?

foam gauge on pump panel is not functioning properly. Door buzzer going off intermittently on the rear large compartment. E42

Task performed:

1. check compt. doors found switch for rear compt. door inop, replace switch

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V50519

In Date: 07/01/2012

Meter Reading:

Close Date: 07/09/2012

Problem?

Pressure relief light bulb does not light up when activated. E 42

Task performed:

Parts

Quantity

1. check relief valve operation, no problem found lite works ok

NO PARTS USED

Workorder: V50520

In Date: 07/01/2012

Meter Reading:

Close Date: 07/09/2012

Problem?

Air system has an audible leak. E 42

Task performed:

Parts

Quantity

1. use soap and water to check for air leaks, found leaks at foot valve and air tank, replace fittings and recheck for leaks, none found

NO PARTS USED

Workorder: V50572

In Date: 07/03/2012

Meter Reading:

Close Date: 07/09/2012

Problem?

On a fire, foam system did not work properly. The panel read "no pr." It worked intermittently. Also the foam level guage is not working. E42

Task performed:

Parts

Quantity

1. check foam gauge found flashing empty, try to recalibrate n/g, check wiring, empty foam system replace sensor, refill foam tank and recalibrate, gauge now wroks ok.

WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352

1

2. check foam system with driver, flow foam from booster hose then with preconnect line, no problem found with system,

Workorder: V50768

In Date: 07/11/2012

Meter Reading:

Close Date: 07/11/2012

Problem?

air breacks are leaking on E42

Task performed:

Parts

Quantity

1. check for air leak with soap and water, found fitting for red line on air tank leaking, replace fitting and recheck, no leaks found at this time

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V50974

In Date: 07/19/2012

Meter Reading:

Close Date: 07/30/2012

Problem?

Drivers side top rear warning flasher lights up but does not flash. Several LED bulbs in the light are also inop.

Task performed:

Parts

Quantity

1. replace l/side rear upper red LED

60R00FRR600 SERIES RED LED W/O FLANGE

1

Workorder: V52409

In Date: 09/16/2012

Meter Reading:

Close Date: 09/18/2012

Problem?

E42 takes a while to start up when you turn the key.... possible starter problem

Task performed:

Parts

Quantity

1. check for hard starting, check battery's, ok, hook up laptop no codes found, vehicle starts ok no problem found

NO PARTS USED

Workorder: V52423

In Date: 09/17/2012

Meter Reading: 103,598.00

Close Date: 10/04/2012

Problem?

AIR LEAK E 42

Task performed:

Parts

Quantity

1. check for air leak, use soap and water, could not find leak

NO PARTS USED

Workorder: V52586

In Date: 09/23/2012

Meter Reading:

Close Date: 10/16/2012

Problem?

Engine is slow to start. Battery seems strong, but it takes about 10-20 revolutions before it starts. E 42

Task performed:

Parts

Quantity

1. check for hard starting, hook up laptop no codes found, check lift pump, ok check wiring to lift pump and ECM, could not find problem

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V53667

In Date: 11/09/2012

Meter Reading: 105,120.00

Close Date: 11/19/2012

Problem?

replace 4 rear tires

Task performed:

Parts

Quantity

REPLACE 4 REAR TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V53572

In Date: 11/06/2012

Meter Reading:

Close Date: 11/28/2012

Problem?

CHECK REAR TIRES E 42

Task performed:

Parts

Quantity

NEED TIRES WILL BE INSTALLED 11/6/12.

NO PARTS USED

Workorder: V54056

In Date: 11/28/2012

Meter Reading:

Close Date: 11/29/2012

Problem?

MSA THERMAL IMAGER CHARGING STATION .. RUBBER HOLD DOWN STRAP BROKEN.. E42 SCHEDULED FOR SWAP TOMORROW.. UNSURE IF MSA MOUNT IS IN NEW ENGINE OR NOT, PRIORITY DEPENDS ON SUTPHEN TIC CHARGER ALREADY MOUNTED OR NOT E42

Task performed:

Parts

Quantity

1. mount new charger

NO PARTS USED

Workorder: V55854

In Date: 02/19/2013

Meter Reading: 106,050.00

Close Date: 02/20/2013

Problem?

dead batteries

Task performed:

Parts

Quantity

CHARGED BATTERIES INYARD. (DEAD) BROUGHT TRUCK INTO SHOP, LOAD TESTED. FOUND BATTERIES BAD. REPLACED ALL FOUR BATTERIES, CLEANED ALL TERMS AND CHECKED CHARGING SYSTEM.

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31D BATTERY 950CCA HP-31D

4



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V56268

In Date: 03/08/2013
Close Date: 03/11/2013

Meter Reading: 106,158.00

Problem?

RRI Flat Boulevard tire

Task performed:

RRI FLAT BOULEVARD TIRE.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V47644

In Date: 02/29/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

Passenger side headlight is out.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V52635

In Date: 09/26/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

severe audible air leak. drains tanks and takes several minutes to be able to disengage the brakes. E 42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V53644

In Date: 11/08/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

significant air leak. four hours of sitting in the bay will drain both tanks to well below 60psi.

Task performed:

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V53816

In Date: 11/16/2012

Meter Reading:

Close Date: 04/08/2013

Problem?

Spare battery charger for TIC is broken... missign/broken charging pins E42

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V52844

In Date: 10/04/2012

Meter Reading:

Close Date: 04/11/2013

Problem?

E42 has a significant air leak.

Task performed:

Parts

Quantity

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V56762

In Date: 04/01/2013

Meter Reading: 106,354.80

Close Date: 04/19/2013

Problem?

c INSPECTION SE 4

Task performed:

1. C-INSPECTION.
2. L/REAR INNER DUAL ONLY HAD 20 PSI - AIR TO CHECKFOR LEAK - NG - TIRE WOULD NOT TAKE AIR - REMOVE TIRE AND WHEEL - VALVE CORE WAS DAMAGED INSIDE VALVE STEM - WORK CORE TO FINALLY EXTRACT - INSTALL NEW CORE NOW AIR UP T IRE - REINSTALL WHEEL AND TIRE.
3. ENGINE RUNS ROUGH AND HARD START - FOUND A BAD FUEL LEAK AT INJECTOR PUMP BANGED FITTINGS - DISASSEMBLE FUEL LINES - CHECK WITH PARTS FOR NEW SEALS - NG (HAD TO ORDER)
4. 3 ZERKS ON HALE VALVES BAD - REPLACE.
5. SERVICE AIR DRYER HAD TO CUT OFF BOTH MOUNTING BOLTS. CROSS THREADED.
6. REMOVE, CLEAN AND LUBE, BATTERY 2 TRASH LINE SLIDE OUT LATCHES.
7. R&R TRANSMISSION COOLER.
8. CHECK FOR AIR LEAKS, REPLACE TANK, FITTINGS, MAKE UP AND INSTALL NEW AIR LINE FROM BRAIDED LINE TO DRYER.
9. TROUBLESHOOT AIR DRYER NOT PURGING, CHECK LINES GOING TO DRYER OK, REPLACE GOVERNOR OK.
10. START TROUBLESHOOT FAILED VACUUM TEST, GREASE AND CHECK VALVE LINKAGES.
11. TROUBLESHOOT FAILED VACUUM TEST, REMOVE AND REBUILD INTAKE RELIEF VALVE AND CHECK VALVE.
12. TROUBLESHOOT PUMP, REBUILD CONTROLLER AND 2 VALVES.
13. TIGHTEN MANSAVER MOUNTS.
14. TROUBLESHOOT PUMP STEP LIGHTS INOP. FOUND WIRE PULLED OUT OF CONNECTER, REPLACED CONNECTOR.
15. REPLACE DOOR MOLDINGS.
16. ADJUST DRIVER'S DOOR LATCH AND OFFICERS LATCH.
17. TROUBLESHOOT L/R EMERGENCY LIGHT INOP. FOUND WIRES UNPLUGGED, PLUG BACK IN AND SECURE WITH WIRE TIE.
18. CHECK PUMP ANODE, OK.
19. CHECK COOLANT LEAK, AIR COMPRESSOR COOLING LINES LAKING, R&R SEALS.
20. Q & A VEHICLE.

Parts	Quantity
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
073-0190-01PISTON TPM RELIEF VALVE	1
082-2007-00-0GREASE ZERK W/CHECK VLV	3
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
14022-1-5COOLER 14032	1
15W40BSYN OIL BULK QTS	27
211-2BULB	1
284358GOVERNOR D-2	1
372000084MARKER LIGHT	1
3863988SEALING WASHER 14MM	4
39181903918190 WASHER	2
52-24WIPER BLADES ANCO 24	2
546126000TPM/QG HALE REPAIR KIT	1
5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	3
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
S1003-A3103015 SEAL	4
UMVS111611STRAP	1



3/2/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V57355

In Date: 04/30/2013
Close Date: 05/02/2013

Meter Reading:

Problem?

2 missing 2.5" intake valve handles. On board foam system malfunctions & flashes "no prime". E 91

Task performed:

1. TRAVEL TO ST 91 REPLACE HANDLES GET BROKEN PIECE OUT OF VALVE TEST OK.
2. CHECK FOAM SYSTEM AND RUN FOAM FREE UP PADDLE WHEELS IN FOAM PUMP FLOW OK.

Parts	Quantity
012-1510-01-OSVS HANDLE 6.75	2
012-1510-05-0KNOB	2

Workorder: V57578

In Date: 05/08/2013
Close Date: 05/20/2013

Meter Reading:

Problem?

DRIVERS DOOR INTERIOR HANDLE BROKEN r91

Task performed:

- TRAVEL TO ST 91 WAIT FOR TRUCK R&R DRIVER SIDE DOOR HANDLE.

Parts	Quantity
6807200575HANDLE DOOR	1

Workorder: V57953

In Date: 05/24/2013
Close Date: 05/30/2013

Meter Reading:

Problem?

Captain's door does not shut every time. Needs adjusting. S.E.@91

Task performed:

- TRAVEL TO ST 01 CHECK OUT DOOR ADJUST NEEDS NEW UPPER HINGE ORDER HINGE.

Parts	Quantity
NO PARTS USED	

Workorder: V58348

In Date: 06/12/2013
Close Date: 06/13/2013

Meter Reading: 107,245.10

Problem?

replace door hinge E91

Task performed:

- TRAVEL TO ST 91 R&R UPPER DOOR HINGE ON PASS SIDE FRONT DOOR AND ADJUST DOOR.

Parts	Quantity
681-720-01-37HINGE ASSY R/H DOOR	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V57980

In Date: 05/27/2013
Close Date: 06/14/2013

Meter Reading: 107,085.60

Problem?

Officer's door often does not latch when closing. It takes several tries and has to be slammed. E91 is in spare

Task performed:

READJUSTED DOOR LATCH AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V58202

In Date: 06/04/2013
Close Date: 06/14/2013

Meter Reading: 107,245.10

Problem?

DRIVERS SIDE TURN SIGNAL NOT WORKING E 91

Task performed:

1. REPAIRED BROKEN WIRE AT SWITCH.
2. REPAIRED REAR BACK UP LIGHTS THAT WERE OUT.

Parts

NO PARTS USED

Quantity

Workorder: V58132

In Date: 06/02/2013
Close Date: 06/17/2013

Meter Reading: 107,245.10

Problem?

primer pump not working, no sound at all E91

Task performed:

1. REPLACED SOLENOID FOR PRIMER.
2. REPLACED NUMBER SIGN.

Parts

501-3090-00PRIMER PUMP MOTOR
L PLACARD INSERTLARGE PLACARD INSERT CARD
SS598STARTER SOLENOID FORD TYPE

Quantity

1
1
1

Workorder: V58614

In Date: 06/22/2013
Close Date: 07/19/2013

Meter Reading: 107,572.80

Problem?

crosslay 1 discharge gauge not working properly. Stuck at 130psi and never moved until I brought water in from the hydrant. e91

Task performed:

TRAVEL TO ST 91 TK AT SHOP.

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V59148

In Date: 07/16/2013
Close Date: 07/19/2013

Meter Reading: 107,852.00

Problem?
repair flat

Task performed:

REPAIR FLAT.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V59905

In Date: 08/19/2013
Close Date: 08/20/2013

Meter Reading: 108,001.30

Problem?
spare broken hose mount tailboard, right side scene light 1 bulb out, cross lay nets broken, suction gage won't read negative, two dc struts broken driver side, e17

Task performed:

1. REPLACED 2 1/2" TRI LAK BROKEN ON REAR.
2. REPLACED SCENE LIGHT BULB.
3. TRAVEL TO 17 REPLACED CROSSLEY NETS FROM ONE TRUCK TO ANOTHER.
4. REPLACED BROKEN DOOR STRUTS.

Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT
LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

4
1

Workorder: V59977

In Date: 08/22/2013
Close Date: 09/06/2013

Meter Reading: 108,001.30

Problem?
spare engine air leak both tanks at o by morning, TIC won't charge e17

Task performed:

TRAVEL TO 17 DRIVER COMPLAIN OF AIR LEAKS NO FOUND.

Parts

NO PARTS USED

Quantity

Workorder: V59450

In Date: 07/30/2013
Close Date: 09/15/2013

Meter Reading: 107,852.00

Problem?
remove license plate and install on Bat 1 spare remove tag from bat 1 spare and install on this unit

Task performed:

REMOVED LICENSE PLATE FROM SPARE AT SHOP
TRAVEL TO 15 INSTALLED ON SPARE UNIT AT 15.

Parts

NO PARTS USED

Quantity



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V60976

In Date: 10/03/2013
Close Date: 10/11/2013

Meter Reading: 108,001.30

Problem?

A inspection on SE4

Task performed:

1. A SERVICE.
2. REPAIRS AIR LEAK ALL OVER TRUCK UPS SEATS TANKS DASHES.
3. REPLACE LIGHTS INSIDE OF PUMP PANEL SIDE LED LIGHT OUT FOR TURN R&L BOTH, REMOVE AND TOP OUT HOLE FOR NEW SCREW, OK.
4. REAR STEP LIGHT OUT TAG LIGHT OUT REPLACE OK.
5. DRIVER DOOR LATCH BAD REPLACE, ALSO HANGES ON TOP OF DOOR BOLT BROKEN OFF ON TOP REMOVE HINGES DRIVE OUT AND TOP REPAIR AND REINSTALLED.
6. CHECK AND REPAIR SHORE LINE BATTERY CHARGER. REMOVE WIRING TO OLD CHARGER, REWIRE THE RIGHT WAY.
7. WORK ON CHARGING SYSTEM SHORE LINE REWIRE SYSTEM REINSTALLED NEW CHARGER CHECK OUT AFTER INSTALL ALL WORKING.

Parts

Quantity

0913912CHARGER 2000	1
15W40BSYN OIL BULK QTS	2
35200-YLIGHT MARKER LEDAMBER	1
5-20PHBL5366C 20AMP PLUG	2
5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	1

Workorder: V61604

In Date: 10/29/2013
Close Date: 10/30/2013

Meter Reading:

Problem?

SWAPPED INTO SPARE ENGINE AND THERE IS NO CONSTANT HOT POWER OUTLET TO CHARGE TRIPTIX TABLET E28

Task performed:

TRAVEL TO 28 DRIVER COMPLAINT NO POWER PAINT IN ENGINE DISTALLED POWER POINT IN REAR.

Parts

Quantity

56415CIG. LIGHTER ACCES.	1
--------------------------	---

Workorder: V61674

In Date: 10/31/2013
Close Date: 11/04/2013

Meter Reading:

Problem?

SCBA bracket in officers seat is falling off and needs to be secured. E28

Task performed:

TRAVEL TO 28 DRIVER COMPLAINT SCBA BRACKET LOOSE. SECURED SCBA BRACKET.

Parts

Quantity

NO PARTS USED	
---------------	--



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V61687

In Date: 10/31/2013

Meter Reading:

Close Date: 11/14/2013

Problem?

UNABLE TO OPEN DRIVERS DOOR FROM OUTSIDE HANDLE. SE@28

Task performed:

TRAVEL TO 28 DRIVER COMPLAINT DOOR WILL NOT OPEN ADJUSTED DOOR LATCH AND LUBRICATED. LATCHES NEED REPLACEMENT.

Parts

Quantity

6807600070HANDLE DOOR EXT L/H

2

Workorder: V61745

In Date: 11/04/2013

Meter Reading:

Close Date: 12/12/2013

Problem?

AIR BRAKE SYSTEM LEAKS DOWN QUICKLY. E28

Task performed:

DRIVER COMPLAINT AIR LEAKS DOWN. REBUILT UPS SHIFTER ON T-CASE.

Parts

Quantity

5460370530VPS SHIFT KIT 546-0370-53-0

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V62980

In Date: 12/27/2013

Meter Reading: 108,339.50

Close Date: 01/13/2014

Problem?

B inspection SE4

Task performed:

1. S INSP.
2. ASSIST NORRIS WITH B-INSP.
3. FAILED LOAD TEST- REPLACED ALL 4 BATT.
4. ASSIST NORRIS WITH ABOVE REPAIR- BATT.
5. REPLACED ENG AIR FILTER- REMOVED COMPLETE AIR FILTER HOUSING AND REINSTALLED WITH NEW FILLTER.
6. REMOVE FRT RIGHT SEAT FOR REPAIR. MOVE VEHICLES SWAP HOIST LIFT. INSTALL SEAT BACK FROM CENTRAL AUTO TRIM.
7. REPLACED R FRT DOOR TRIM. REPLACED STRIPPED SCREWS WITH LARGER SHEET METAL. SECURE ALL OTHER DOOR TRIM PIECES.
8. CHECKED SEAT BELTS. SEAT BELTS OK ONLY SMALL ABRASIONS IN WEBBING. NOT A SAFETY ISSUE.
9. REPLACED #3 DISCHARGE GUAGE.
10. SPLICE IN DOOR WEATHERSTRIPS ON ALL CAB DOORS. VACUUM DEBRIS FROM ROCKERS. REPLACED L REAR ROCKER PANEL.
11. DIAGNOSE AIR LEAKS REPAIR AND REPLACE LEAKING FITTINGS. TEST SYSTEM NOW OK.
12. REMOVE DECALS AND GLUE FROM BODY.
13. Q.A.
14. STEAMER CAP MISSING- RECIEVE DNI CAP FROM WAREHOUSE SUPPLY- INSTALL.
15. STREAM LIGHT CHARGE TABS BROKEN- REMOVE STREAM LIGHT CHARGER BOX- INSTALL AND REWIRE NEW CHARGER IN PLACE.
16. CAB MARKER LIGHT OUT- REMOVE LEASE REMOVE BLOWN BULB, INSTALL NEW BULB AND REMOUNT LEASE.
17. A/C FILTER CLOGGED- BLOW OUT FILTER AND REINSTALL.
18. HOSE BED COVER SUPPORT STRAPS- REMOVE PIECES, INSTALL 4 NEW STRAP AND CLIPS.
19. R/REAR SIDE REFLECTOR KNOCK OFF- REMOVE BROKEN SCREWS, RETAP AND INSTALL NEW REFLECTION AND SCREWS.
20. TRANSMISSION SHIFTING HARD- ALLISON FAST ADAPTER RESET AND ROAD TEST- SHIFTING NORMAL.
21. PA INOP- REMOVE PA CONTROL LEAD, INSTALL A REBUILT HEAD UNIT NOW WORKS.

Parts

Quantity

6806840018DOOR SILL L/H	1
6806970098SEAL DOOR	1
91553940GAUGE 0-400 WHITE COMP	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1
A1834388003MOLD R/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V63432

In Date: 01/15/2014

Meter Reading:

Close Date: 01/16/2014

Problem?

headlight out on passenger side. fixed by rob leavy before i could put it in the computer. E26

Task performed:

TRAVEL TO 26 DRIVER COMPLAINT NO RF HEADLIGHT R&R LIGHT BULB.

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V59611

In Date: 08/06/2013

Meter Reading:

Close Date: 02/21/2014

Problem?

1) Relief valve leaks air, had to cap it t do dry vacuum test and pull draft. 2)#2 Discharge drain leaks,will not completely close. 3)Relief valve light not working

Task performed:

REPAIRED ON SCENE.

Parts

NO PARTS USED

Quantity

Workorder: V64988

In Date: 03/17/2014

Meter Reading:

Close Date: 03/20/2014

Problem?

two of the bolts holding the tray to the track fell out and wouldn't let the drawer go in untill we knocked them out with a hammer an screw driver. now only one bolt is holding drawer to rack on left side. E33

Task performed:

INSTALL NEW SCREWS FOR DRAW SLIDE THAT WERE MISSING.

Parts

NO PARTS USED

Quantity

Workorder: V65103

In Date: 03/21/2014

Meter Reading: 109,238.00

Close Date: 03/24/2014

Problem?

Replace R/F tire

Task performed:

REPLACED R/F TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V60041

In Date: 04/18/2014
Close Date: 04/18/2014

Meter Reading: 108,001.30

Problem?

SPARE ENGINE 4-RELIEF VALVE LEAKS AIR-HAD TO CAP IT TO PULL DRAFT TO PASS DRY VACUUM. #2 DISCHARGE DRAIN LEAKS, WILL NOT COMPLETELY CLOSE. RELIEF LIGHT NOT WORKING.

Task performed:

Parts

Quantity

SPARE ENGINE 4-RELIEF VALVE LEAKS AIR-HAD TO CAP IT TO PULL DRAFT TO PASS DRY VACUUM. #2 DISCHARGE DRAIN LEAKS, WILL NOT COMPLETELY CLOSE. RELIEF LIGHT NOT WORKING. REPAIRS COMPLETE.

NO PARTS USED

Workorder: V66506

In Date: 05/15/2014
Close Date: 05/21/2014

Meter Reading: 110,581.00

Problem?

A inspection

Task performed:

Parts

Quantity

A INSP AND TELESCOPING LIGHTS INOP- PINCHED WIRE.

NO PARTS USED

Workorder: V64986

In Date: 03/17/2014
Close Date: 05/22/2014

Meter Reading:

Problem?

no stream straightener on deck gun on spare E33.

Task performed:

Parts

Quantity

TRUCK BACK AT SHOP.

NO PARTS USED

Workorder: V65366

In Date: 04/01/2014
Close Date: 06/09/2014

Meter Reading:

Problem?

Foam level gauge not working. The light on gauge continously scrolls up and down. E33

Task performed:

Parts

Quantity

Repaired on another wo

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V67244

In Date: 06/16/2014

Close Date: 06/27/2014

Meter Reading: 110,581.00

Problem?

A inspection SE4

Task performed:

A SERVICE.
lights, cab a/c inop belt.

Parts

Quantity

39768315259022 GROOVED TENSIONER OLD#3936213	1
532703-0602 COMPRESSOR U4735 4471	1
716907-0610A DRYER	1
8201L17-3428 ESTER OIL E7	1
9440BELT	1
9447BELT	1
9470BELT	1
A2241332074A22-41332-074 HOSE ASSY.	1
K080716BELT	1
LB-D30BULB QUARTZ HAL. 12V 150W	2

Workorder: V65818

In Date: 04/19/2014

Close Date: 07/18/2014

Meter Reading:

Problem?

Reciprocating saw is cracked in the middle and is loose. It needs to be repaired or replaced if possible. Thank you. E33

Task performed:

request filled by Warehouse

Parts

Quantity

NO PARTS USED

Workorder: V68669

In Date: 08/14/2014

Close Date: 08/14/2014

Meter Reading: 111,581.40

Problem?

Oil fill cap stripped

Task performed:

Delivered new cap

Parts

Quantity

EG-3500OIL CAP HONDA	1
----------------------	---



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V68603

In Date: 08/12/2014

Meter Reading:

Close Date: 08/21/2014

Problem?

retaining clip on radio mic is broken and will not stay plugged in. SE@34

Task performed:

Parts

Quantity

forwarded to radio shop

NO PARTS USED

Workorder: V68696

In Date: 08/15/2014

Meter Reading:

Close Date: 08/22/2014

Problem?

Air leak cab sitting on steps. Front air intake valve not working. Light boxes chargers not working.

Task performed:

Parts

Quantity

front intake inop, tested valve at hydrante and tested ok was opening and closing. traced out air leaks and repaired will monator leaks.

NO PARTS USED

Workorder: V68675

In Date: 08/14/2014

Meter Reading:

Close Date: 09/08/2014

Problem?

Portable light box charger on center console are not charging flaslights. SE @ 34

Task performed:

Parts

Quantity

REPLACED HEAD LIGHT AND TESTED OK.

NO PARTS USED



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V69499

In Date: 09/19/2014

Meter Reading: 111,924.90

Close Date: 10/20/2014

Problem?

C inspection SE4

Task performed:

1. C Inspection.
2. C Inspection.
3. Loosen fan belt to align with pulley grooves.
4. Repair and replace pump anode.
5. Repair and replace cab auxilliary A/C filter.
6. L/R cab door light out. Test light OK. Trace wiring harness. Find open circuit. Repair hot and ground wires at door jamb.
7. R & R L-3 compartment door hold open.
8. Diagnose and repair windshield washers.
9. Remove and tag hose bed cover.
10. R & R 6" front suction screen.
11. Clean, lube and adjust battery tray latches and control. Clean, lube and adjust trashline tray latches and control.
12. Overhaul AD-9 dryer assembly. R & R check valve assembly.
13. Service cooling system and replace radiator cap.
14. Inflate 4 rear tires to 115 psi.
15. R & R all broken and bent hose bed cover quarter turn snaps.
16. Rear step grab bar spins when you grab it. Retap all holes and install new hardware on stanchions.
17. Re-install hose bed cover.

Parts

Quantity

029-0511-00-0ANODE ONLY	1
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	21
75W90GEAR OIL SYN QT	4
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	1
EXO3AH00015SPLUG RAD. DRAIN	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
SPR-W58-1TEE PLASTIC	1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V69960

In Date: 10/06/2014

Meter Reading: 112,151.60

Close Date: 10/28/2014

Problem?

primer lever stuck on passenger side of the truck.

Task performed:

Parts

Quantity

1. Travel to 26. Driver complaint primer stuck on side panel. Lubricated primer valve and tested OK.

NO PARTS USED

Workorder: V69846

In Date: 10/02/2014

Meter Reading: 112,049.00

Close Date: 10/30/2014

Problem?

Significant audible air leak under vehicle. Not coming from drain valves.

Task performed:

Parts

Quantity

Check out air system for leaks none found at this time , no audible leak.

NO PARTS USED

Workorder: V69800

In Date: 09/30/2014

Meter Reading:

Close Date: 11/07/2014

Problem?

Bleeders on discharge 1 and 4 leaking badly.

Task performed:

Parts

Quantity

Drive to station 26. Remove and replace pressure release valve sensor.

040114003SEAL SVS DRAIN VALVE

6

200226200200-2262-50 SWITCH-PROXIMITY QG VALVE

1

Travel to station 26 , rebuild bleeder valves on left side of truck. Discharge on P/P



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V71616

In Date: 12/13/2014

Meter Reading: 113,064.00

Close Date: 12/29/2014

Problem?

A inspection SE4

Task performed:

1. A inspection
2. Inflate all six tires to proper pressure-install missing stem cap 4RO
3. R/R tailboard light assy. R/R 2 light fixtures
4. R/R lens, R/R bulb and clean corrosion off contacts and reinstall bulb and retest ok.
5. Check for air leaks cab airbags leaking
6. R/R 2 cab air bags

Parts

Quantity

35200-RLIGHT MARKER LED RED

2

LML-1102-0023CAB AIR BAG IS4007

2

Workorder: V70060

In Date: 10/10/2014

Meter Reading: 113,064.00

Close Date: 12/31/2014

Problem?

intake relief valve leaking causing dry vacuum test to fail.

Task performed:

- Intake relief valve leaking/dry vacuum failed
 Repaired leak and retested

Parts

Quantity

NO PARTS USED

Workorder: V72688

In Date: 01/28/2015

Meter Reading: 113,290.00

Close Date: 02/03/2015

Problem?

A-inspection

Task performed:

1. A Inspection.
2. R & R door hold open air spring.

Parts

Quantity

EAA-8350-30UGSS1783UQ STRUT-LIFT

1

EAA-8350-60UGSS6557UP STRUT-LIFT

1



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V73160

In Date: 02/14/2015

Meter Reading:

Close Date: 02/24/2015

Problem?

Auto ejector for shoreline cord on SE4 at St 68 not working

Task performed:

Travel to ST 68. check out auto-eject inop. Check charger - ok. Check eject sticking in plug. Loosen up auto-eject and plug. Test - ok.

Parts

NO PARTS USED

Quantity

Workorder: V73406

In Date: 02/25/2015

Meter Reading: 113,560.40

Close Date: 03/11/2015

Problem?

Repair I-s slide out tray

Task performed:

1. A Inspection.
2. Left side work light inop. Found light assembly damaged. remove and rewire new light. Assemble in place. Right rear wheel warning light inop. Remove and install new LED assembly.
3. Driver door window molding damage. Remove and install new molding.
4. Repair door slider bottom. No screws. Install new screws and lap nuts secure and adjust slider. It's good now.

Parts

50R03ZCRLIGHT LED RED TIR 6
 A1834388002MOLD L/H
 FCA100-V15LED SCENELIGHT HEAD
 LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1
1
1
1

Workorder: V73702

In Date: 03/06/2015

Meter Reading: 113,683.90

Close Date: 03/17/2015

Problem?

A inspection SE4

Task performed:

1. A- Inspection
2. L-3 Door strut missing- install (2) new strut on door.
3. Right side pump panel light inop- Remove bad light and install new light assembly.

Parts

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE
 EAA-8350-60UGSS6557UP STRUT-LIFT

Quantity

1
2



3/2/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155560

1250 GPM PUMPER FIRE DEPARTMENT PUMPER NFPA

Workorder: V74399

In Date: 04/03/2015

Meter Reading:

Close Date: 04/20/2015

Problem?

bendix air brake release is leaking air.

Task performed:

Replaced Parking Brake Valve.

Parts

800034VALVE PARKING BRK.

Quantity

1

Workorder: V73574

In Date: 03/02/2015

Meter Reading:

Close Date: 04/28/2015

Problem?

Spear Engine (48), the primer got stuck this morning during morning check. Tommy replaced the primer already. This is for documentation purpose.

Task performed:

1. Removed and replaced primer handle.

Parts

NO PARTS USED

Quantity



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10155560) 2004 - FERRARA FL80 1250 Gpm Pumper

10155560

CSHOP-2015-1288

Comments: **ON-CALL E45 - AIR LEAK AND NO AIR HORN**

Date Opened 6-22-2015 Date Finished 6-23-2015 Meter 1 Reading: 114,555

TASKS PERFORMED

Q PARTS

BODY EXTERIOR

6 9IP; SS0001 CPI SHELF BRACKET ONE HOLE 2005 E

CSHOP-2015-1291

Comments: **SPARE ENGINE AT 45 DOOR OPEN ALAR SOUNDING ALL THE TIME**

Date Opened 6-22-2015 Date Finished 6-23-2015 Meter 1 Reading: 114,655

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

CSHOP-2015-1438

Comments: **E45 CHECK ENGINE LIGHT**

Date Opened 6-29-2015 Date Finished 7-7-2015 Meter 1 Reading: 114,655

TASKS PERFORMED

Q PARTS

ALARM-BUZZER-WARNING LIGHT

1 FILTER; FILTER FUEL 33231
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM

CSHOP-2015-1695

Comments: **AC INOP SPARE ENGINE @45 TIC CHARGER DOES NOT CHARGE CHECK ENGINE LAMP ON FOR AUX THROTTLE**

Date Opened 7-10-2015 Date Finished 9-3-2015 Meter 1 Reading: 115,320

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

1 THROTTLE; THROTTLE EXCEL CUMMINS IS SERIES

GOVERNOR

1 SOLENOID; SOLENOID AIR HORN WAS

COOLING SYSTEM

1 VALVE; 90555409 VALVE CHECK PRESSURE PROTECTED

AIR SYSTEM

1 A/C; FREON LB

SAFTEY-EMERGENCY EQUIPMENT

1 SWITCH; 1498 SWITCH BINA

AIR CONDITIONING

Asset Work Order History 10155560

CSHOP-2015-2120

Comments: SPOT LIGHT ON TOP OF CAB INOP.SPARE E @ ST16 ON-CALL TECH TOOK SPARE GEN TO STATION OVER THE WEEKEND

Date Opened 8-4-2015 Date Finished 9-14-2015 Meter 1 Reading: 115,444

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SPOT LIGHTS
ALTERNATOR-GENERATOR

1 LIGHT; SPOT LIGHT REMOTE

CSHOP-2015-2121

Comments: REPLACE TIRE

Date Opened 8-4-2015 Date Finished 8-4-2015 Meter 1 Reading: 114,655

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2015-2927

Comments: SPOTLIGHT WILL NOT TURN OFF FROM CAB ACTUATOR E16

Date Opened 9-16-2015 Date Finished 9-18-2015 Meter 1 Reading: 115,444

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

09/16/2015 LIGHTS / 38: SHORTED / INSPECT
SPOTLIGHT WILL NOT TURN OFF FROM CAB ACTUATOR

CSHOP-2015-3475

Comments: B INSPECTION SE4

Date Opened 10-16-2015 Date Finished 10-19-2015 Meter 1 Reading: 116,638

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FILTER FUEL 33231
1 FILTER; OIL FILTER 51748
3 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM

Asset Work Order History 10155560

CSHOP-2015-3476

Comments: **SE4 REPAIRS FROM PM**

Date Opened 10-16-2015

Date Finished

12-8-2015

Meter 1 Reading:

117,236

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	2	9IP; SHORT SENSOR GEARS
PUMP PANEL	1	ORING; ORING KIT
PRIMING PUMP FIRE PUMP	1	GASKET; 14023 GASKET 6 IN
FIRE PUMP	1	NEWPART; FUEL LINE ISC #4
HOSE BED BODY	1	FILTER; 24070 WIX FILTER WATER
HOSES-LINES & FITTINGS	1	9IP; SCREW SHUTOFF VALVE
HANGER-CLAMP	2	9IP; O-RING WATER SHUT OFF
COOLING SYSTEM	1	9IP; SHAFT SHUT-OFF VALVE
SPOT LIGHTS	1	9IP; GASKET 4942874
PARK-CLEARANCE LIGHTS	1	9IP; O-RING SHUT-OFF VALVE
SWITCH-ELECTRICAL	1	9IP; 4940547 SHAFT SHUT-OFF VALVE
TRANSFER CASE	1	CUMMINS; 4940575 HEAD CORROSION RESISTER
WHEEL COVERS	6	SCREW; SCREW DASH
REAR TIRES	10	NEWPART; SCREW
FRONT SPRING	1	NEWPART; A PILLAR POST
BRAKES	1	LIGHT; LIGHT MARKER LEDAMBER
AIR SYSTEM	2	SWITCH; SWITCH COVER
SIREN	1	9IP; PLUG DRAIN REAR END FREIGHTLINER
AIR HORN	2	9IP; LUG NUT COVER PK10
FENDER	2	9IP; FRONT DRUM M2 ENGINE
SEAT REAR	-1	9IP; SEAL 35066
A/C FILTER SCREENS	1	9IP; SEAL 35066
	1	9IP; HUB COVER GASKET
	1	NEWPART; HUB ASSY
	2	GAUGE; VAC PRESSURE GUAGE PIERCE 0-400
	2	9IP; BRAKE SHOES FRONT M2
	2	DRAIN; DRAIN COCK
	1	PUMP; VPS SHIFT KIT 546-0370-53-0
	1	9IP; 1712554004 SHIELD SPLASH R/H

CSHOP-2015-4476

Comments: **SE4 AT 27 PRIMER INOP**

Date Opened 12-14-2015

Date Finished

12-28-2015

Meter 1 Reading:

117,014

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP

Service Requests:

12/14/2015

ENGINE / 38: SHORTED / PRIMER SHORTED BURNED WIRES
PRIMER PUMP CAME ON BY ITSELF AND WOULD NOT SHUT OFF, POSSIBLY BURNED OUT

Asset Work Order History 10155560

CSHOP-2015-645

Comments: **GENERATOR NEEDS A FUEL CAP AND AIR FILTER E25**

Date Opened 5-14-2015 Date Finished 5-28-2015 Meter 1 Reading: 114,455

TASKS PERFORMED

Q PARTS

ALTERNATOR-GENERATOR

1 CAP; HONDA FUEL CAP

CSHOP-2015-815

Comments: **SE4 FRONT A/C NOT WORKING**

Date Opened 5-26-2015 Date Finished 5-28-2015 Meter 1 Reading: 114,000

TASKS PERFORMED

Q PARTS

BATTERY

4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D

CSHOP-2015-819

Comments: **A INSPECTION SE4**

Date Opened 5-26-2015 Date Finished 5-28-2015 Meter 1 Reading: 114,455

TASKS PERFORMED

Q PARTS

A INSPECTION

1 LIGHT; LIGHT MARKER LED RED

OIL

1 LIGHT; LIGHT MARKER LEDAMBER

PARK-CLEARANCE LIGHTS

1 FILTER; 78R5360M 2PK FILTER AIR COND

TRANSMISSION

1 SWITCH; 11-3050 SWITCH BLOWER

FRONT TIRES

A/C FILTER SCREENS

HOSES-LINES & FITTINGS

CSHOP-2016-1065

Date Opened 3-7-2016 Date Finished 3-7-2016 Meter 1 Reading: 117,316

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BRAKES

Service Requests:

03/07/2016 BRAKES / 11: BINDS/STICKS / INSPECT

CSHOP-2016-1982

Date Opened 4-26-2016 Date Finished 4-26-2016 Meter 1 Reading: 118,417

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HANDLES INSIDE-OUTSIDE

Service Requests:

04/26/2016 BODY / 11: BINDS/STICKS / LUBRICATE

Asset Work Order History 10155560

CSHOP-2016-2334

Comments: SE@ ST32

Date Opened 5-16-2016 Date Finished 5-25-2016 Meter 1 Reading: 119,555

TASKS PERFORMED

NO PARTS USED

ELECTRICAL
AIR CONDITIONING

Service Requests:

05/15/2016 LIGHTS / 18: LEAKING / Q
THE 12 VOLT PLUG IS NOT CHARGING THE SAFETY PAD, UNLESS THE ENGINE IS RUNNING.

CSHOP-2016-2575

Comments: E32 GEN SWITCH HOUSING LOOSE PRIMER STUCK ON

Date Opened 5-27-2016 Date Finished 8-1-2016 Meter 1 Reading: 120,245

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
PRIMING PUMP FIRE PUMP

Service Requests:

06/03/2016 AIR RIDE / 17: INSUFFICIENT LUBRICANT / Y
AIR TANK ON SPARE ENGINE LEAKING ASS# 10155560 STATION /32

05/27/2016 SERVICE REQUEST / 18: LEAKING / U
THE GENERATOR ON E32 HAS A LOOSE HOUSING WERE THE SWITCHES AND OUTLETS ARE LOCATED.

CSHOP-2016-2695

Comments: E32

Date Opened 6-6-2016 Date Finished 6-8-2016 Meter 1 Reading: 119,685

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 PUMP; VPS SHIFT KIT 546-0370-53-0

Service Requests:

06/05/2016 SERVICE REQUEST / 18: LEAKING / V
CONTINUOUS AIR LEAK AT THE PUMP POWER SHIFT CONTROL IN THE CAB OF SPARE E32.

CSHOP-2016-2868

Comments: SPARE ENGINE @ ST32

Date Opened 6-15-2016 Date Finished 6-26-2016 Meter 1 Reading: 120,097

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

06/14/2016 LIGHTS / 19: LOOSE / REPAIR
EMERGENCY LIGHT ON DRIVER SIDE UPPER REAR IS LOOSE.

Asset Work Order History 10155560

CSHOP-2016-2909

Date Opened 6-17-2016

Date Finished

8-30-2016

Meter 1 Reading:

120,309

TASKS PERFORMED

FIRE PUMP PLUMBING
WIPERS-WASHER
HOSES-LINES & FITTINGS
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
TRANSFER CASE
AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT
AIR CONDITIONING

Q

PARTS

2	WIPER; WIPER BLADES ANCO 24
1	NEWPART; FUEL LINE ISC #4
1	9IP; WASHER
1	REFLECTOR; 41032-3 RED REFLECTOR OVAL REFLECTOR
1	9IP; AIR RIDE VALVE (CAB)
1	DRAIN; DRAIN COCK
1	PUMP; VPS SHIFT KIT 546-0370-53-0
1	VALVE; PURGE VALVE KIT
1	VALVE; VALVE CHECK AD9
1	DRYER; DRYER KIT AD9 -NEW
24	DECAL; LADDER OUT OF SERVICE STICKER
1	9IP; 01-2616 MOTOR 12V 73R-0542 3512
2	VALVE; 8915 VALVE CORE A/C 3544706C1
3	A/C; FREON LB
1	FILTER; 78R5360M 2PK FILTER AIR COND

Service Requests:

07/26/2016 SERVICE REQUEST / 18: LEAKING / REPAIR

06/16/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
SPARE IS LEAKING WATER FROM BENEATH THE PUMP. LEAK VARIES FROM A STEADY TRICKLE TO A STEADY DRIP.

CSHOP-2016-4071

Comments: **C SERVICE BY H2**

Date Opened 8-17-2016

Date Finished

8-18-2016

Meter 1 Reading:

120,309

TASKS PERFORMED

PM SERVICE C

Q

PARTS

1	FILTER; AIR FILTER 46744 WIX
1	FILTER; 24070 WIX FILTER WATER
1	FILTER; OIL FILTER 51748
32	FLUID; SYN OIL BULK QTS
1	FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1	FILTER; FILTER FUEL 33231

VENDOR? H2 FIRE SERVICES

CSHOP-2016-4306

Date Opened 9-2-2016

Date Finished

9-2-2016

Meter 1 Reading:

120,245

TASKS PERFORMED

FIRE APPARATUS
COOLING SYSTEM

Q

PARTS

1	GAUGE; VAC PRESSURE GUAGE PIERCE 0-400
---	--

Asset Work Order History 10155560

CSHOP-2016-4497

Comments: **WATER LEAK AT DISCHARGE PIPE ENGINE OIL CAP OFF**

Date Opened 9-15-2016 Date Finished 9-16-2016 Meter 1 Reading: 120,595

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
ENGINE AND ACCESSORIES

1 CAP; CAP OIL FILL ISL

CSHOP-2016-4534

Date Opened 9-19-2016 Date Finished 9-19-2016 Meter 1 Reading: 120,595

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-4560

Comments: **SPARE ENGINE AT 35**

Date Opened 9-19-2016 Date Finished 9-26-2016 Meter 1 Reading: 121,096

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
CAB-INTERIOR ACCESSORIES

2 HANDLE; HANDLE DOOR

Service Requests:

09/17/2016 DOOR / 19: LOOSE / REPAIR
VEHICLE DOORS- DRIVERS SIDE BACK PASSENGER DOOR BROKE FROM THE INSIDE. FIREFIGHTER CANNOT GET OUT

CSHOP-2016-820

Comments: **PRIMER INOP**

Date Opened 2-19-2016 Date Finished 3-1-2016 Meter 1 Reading: 117,014

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP
CONNECTOR
WIRING
SWITCH-ELECTRICAL
ELECTRICAL

1 SOLENOID; STARTER SOLENOID FORD TYPE

CSHOP-2017-1136

Date Opened 2-23-2017 Date Finished 3-7-2017 Meter 1 Reading: 123,750

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

1 LMP; HALOGEN LAMP

Asset Work Order History 10155560

CSHOP-2017-1396

Comments: **ON-CALL NO START**

Date Opened 3-7-2017 Date Finished 3-11-2017 Meter 1 Reading: 123,750

TASKS PERFORMED

Q PARTS

STARTER

1 STARTER; 6808 38MT 12T STARTER

CSHOP-2017-2047

Comments: **SPARE ENGINE AT 54 BOX LIGHTS NOT WORKING**

Date Opened 4-7-2017 Date Finished 5-17-2017 Meter 1 Reading: 125,567

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

Service Requests:

04/07/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
2 BOX LIGHTS ARE NOT WORKING

CSHOP-2017-2056

Date Opened 4-8-2017 Date Finished 4-10-2017 Meter 1 Reading: 124,850

PRIMER MOTOR STUCK ON

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP

1 SOLENOID; STARTER SOLENOID EONE
1 VALVE; VALVE PRIMER PUMP W/HARDWARE

CSHOP-2017-2396

Comments: **AT 54**

Date Opened 4-24-2017 Date Finished 5-4-2017 Meter 1 Reading: 125,325

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

04/23/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
RAM FAN DOES NOT START

CSHOP-2017-2728

Date Opened 5-9-2017 Date Finished 5-23-2017 Meter 1 Reading: 125,719

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

05/09/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
PRESSURE RELIEF VALVE NOT WORKING CORRECTLY.

Asset Work Order History 10155560

CSHOP-2017-2883

Date Opened 5-15-2017 Date Finished 5-15-2017 Meter 1 Reading: 125,567

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2017-3731

Date Opened 6-23-2017 Date Finished 7-12-2017 Meter 1 Reading: 126,069

TASKS PERFORMED

Q PARTS

PM SERVICE B

24 90C; SYN 15W40
-24 90C; SYN 15W40
1 FIL; FUEL WATER SEPARATOR
24 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10155560

CSHOP-2017-3849

Comments: **REPAIRS FROM PM**

Date Opened 6-29-2017

Date Finished 7-28-2017

Meter 1 Reading: 126,069

TASKS PERFORMED

COMMERCIAL WORK - OUTSIDE AGENCY
WATER TANK LEVEL LIGHTS
FOAM SYSTEM
WIPERS-WASHER
AIR FILTER
RADIATOR
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
REPAIR FROM PM - POWER STEERING
STEERING
AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT
DOOR
INTERIOR TRIM-MOLDINGS-UPHOLS
UPHOLSTERY
A/C FILTER SCREENS
AIR CONDITIONING

Q PARTS

1 5FF; SWITCH
1 NONSTOCK; FREIGHT CHARGE
1 9IP; WASHER PUMP W/GROMMET
1 FIL; NAPAGOLD AIR FILTER
1 2DD; RADIATOR FL80
1 TENSIONER; GROOVED TENSIONER OLD#3936213
1 9IP; BELT
1 NBH; V-BELT
1 2CU; PULLEY
1 BELT; BELT
-1 TFW; HD WATER PUMP
1 TFW; HD WATER PUMP
1 TFW; HD WATER PUMP
1 BRG; ALTERNATOR BEARING
6 9XX; AC FREON 10174676
1 9IP; BULB
1 9IP; GASKET-P/S FILTER NEW STYLE
-2 9OC; BULK TRANS SYN
2 9OC; BULK TRANS SYN
2 9IP; ALLISON TRANS FLUID GAL
1 FIL; NAPA HYDRAULIC FILTER
2 5EF; MANSAVER COVER
1 9IP; MAP LIGHT LED 18 IN
2 9IP; MOLD R/H
1 9IP; 78R5360M 2PK FILTER AIR COND
32 FLUID; COOLANT ANTIFREEZE GAL
1 VALVE; 12-0615A VALVE EXPANSION FTRLNR 1606
-32 9OC; COOLANT
32 9OC; COOLANT
1 9HY; AC HOSE
1 TEM; FILTER DRIER

VENDOR? CENTRAL AUTO TRIM CO.

CSHOP-2017-437

Date Opened 1-19-2017

Date Finished 1-20-2017

Meter 1 Reading: 122,971

TASKS PERFORMED

A INSPECTION
LIGHTING SYSTEM

Q PARTS

1 LIT; LIT
1 9IP; AMBER LENS
2 9IP; BULB

Asset Work Order History 10155560

CSHOP-2017-4965

Date Opened 8-23-2017 Date Finished 8-24-2017 Meter 1 Reading: 126,399

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
ENGINE AND ACCESSORIES
FRONT TIRES
BODY EXTERIOR

2 MAC; NON-CHLOR BRAKE CLNR

CSHOP-2017-5057

Date Opened 8-28-2017 Date Finished 8-28-2017 Meter 1 Reading: 126,335

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-5289

Comments: **E68**

Date Opened 9-11-2017 Date Finished 9-25-2017 Meter 1 Reading: 126,450

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS

Service Requests:

09/10/2017 TIRES / 12: BROKEN / REPAIR
BAD TIRES; OUTER REAR TIRES ARE NEAR WEAR MARKS

CSHOP-2017-612

Date Opened 1-27-2017 Date Finished 2-10-2017 Meter 1 Reading: 123,465

TASKS PERFORMED

NO PARTS USED

A INSPECTION

CSHOP-2017-6506

Comments: **CALL OUT ON E33, QUARTZ LIGHT**

Date Opened 11-13-2017 Date Finished 11-13-2017 Meter 1 Reading: 127,409

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

CSHOP-2017-6573

Comments: **TRANS NOT SHIFTING**

Date Opened 11-14-2017 Date Finished 11-14-2017 Meter 1 Reading: 127,409

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

Asset Work Order History 10155560

CSHOP-2017-6664

Comments: **ON-CALL E33 BRAKE TROUBLE**

Date Opened 11-20-2017 Date Finished 12-12-2017 Meter 1 Reading: 128,658

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM	1	9IP; GE37 BULB
TIRE	1	9IP; 4 1/8 IN VALVE EXT
BRAKE CHAMBER	1	9HD; 3030STD BRAKE CHAMBER
AIR SYSTEM	3	2TP; BRAKE DIAPHRAM
	1	2DD; SWITCH

Service Requests:

11/28/2017 BRAKES / 12: BROKEN / REPAIR
BRAKES ARE HORRIBLE. DIFFICULT TO STOP AND PEDDLE ALMOST TO THE FLOOR

CSHOP-2017-6852

Date Opened 11-30-2017 Date Finished 2-22-2018 Meter 1 Reading: 128,840

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	1	NONSTOCK; FREIGHT CHARGE
REPAIR FROM PM - GENERATOR	1	NONSTOCK; FREIGHT CHARGE
INSTRUMENTS-GAUGES-WARNING &	1	2FR; INSPECT REPAIR

Service Requests:

11/30/2017 SERVICE REQUEST / 12: BROKEN / FOAM FLOW IN-OP DIAGNOSE FAULT FOUND METERING SEN
FOAM SYSTEM INTERMITTENT. RPMS DO NOT DISPLAY ON THROTTLE CONTROL PANEL. WRONG MASTER DISCHARGE
NUMBER.

12/03/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
TEMP READING AND OIL PRESSURE INDICATOR BY PUMP THROTTLE NOT WORKING. ALSO, KIDS POINT AND LAUGH
AT US WHILE DRIVING DOWN ROAD IN SPARE.

12/03/2017 SERVICE REQUEST / 12: BROKEN / PORTABLE GENERATOR NOT ON UNIT
GENERATOR PULL CORD BROKEN

CSHOP-2018-1242

Comments: **CALLAGHAN NOTIFIED ON 3-1-18**

Date Opened 3-1-2018 Date Finished 3-2-2018 Meter 1 Reading: 128,840

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

02/28/2018 TIRES / 16: GLAZED / EXCHANGE - NEW
BAD TIRES ALL 4 REAR, BELOW WEAR BAR

Asset Work Order History 10155560

CSHOP-2018-1244

Date Opened 3-1-2018 Date Finished 4-16-2018 Meter 1 Reading: 129,146

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
AIR SYSTEM

1 TWD; PP-1VALVE CONTROL
1 2FL; NORM CLSD 2 WIRE PRES SW

Service Requests:

02/28/2018 SERVICE REQUEST / 19: LOOSE / REPAIR
TIC CHARGER - BACK-UP BATTERY CHARGER NOT WORKING - APPEARS PINS ARE BROKEN INTERNALLY

CSHOP-2018-1541

Date Opened 3-15-2018 Date Finished 3-15-2018 Meter 1 Reading: 129,146

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-1882

Comments: **SPARE ENGINE AT 38**

Date Opened 4-4-2018 Date Finished 4-30-2018 Meter 1 Reading: 129,146

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS
DOOR PROP CYLINDER
WIPER BLADES

4 5AH; GAS SPRING
2 1AN; WIPER BLADE

Service Requests:

04/03/2018 WATER LEAK / 12: BROKEN / INSPECT
THERE IS A SMALL WATER LEAK COMING FROM ABOVE THE REAR DRIVER SIDE WHEEL.

04/05/2018 SERVICE REQUEST / 12: BROKEN / INSPECT
HAND LIGHT NOT WORKING

CSHOP-2018-2362

Date Opened 4-30-2018 Date Finished 5-1-2018 Meter 1 Reading: 130,223

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 9ME; VPS POWER SHIFT & CONTROL KIT

Asset Work Order History 10155560

CSHOP-2018-2560

Comments: **SPARE ENGINE AT 29**

Date Opened 5-9-2018 Date Finished 5-31-2018 Meter 1 Reading: 130,407

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR
INSTRUMENTS-GAUGES-WARNING &

Service Requests:

05/09/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION SPARE ENGINE AT 29 -FOAM LEVEL LIGHT READING ZERO BUT FOAM IN THE TANK
-AIR HORN BUTTON AT THE ENGINEER PANEL DOES NOT WORK UNABLE TO USE EVACUATION TONES FROM THE
PANEL -NEW SMALL ENGINE FUEL CAP FOR THE HYDRAULICS SAFETY CONCERN DUE TO IT LEAKING. HIGH
PROBABILITY OF INJURY OR EQUIPMENT DAMAGE -REQUESTING A SMALL GENERATOR TO RUN ELECTRICAL LIGHT,
FAN, REP. SAW

05/10/2018 ALARMS / 21: MISADJUSTED / ADJUST
ALARM SIGNALS, WARNING ALARM WHILE DRIVING. ALL DOORS AND COMPARTMENTS ARE SHUT. COMES ON IN AND
OUT

CSHOP-2018-2608

Date Opened 5-12-2018 Date Finished 5-15-2018 Meter 1 Reading: 130,322

TASKS PERFORMED

NO PARTS USED

TRANSFER CASE

CSHOP-2018-2902

Comments: **E29**

Date Opened 5-25-2018 Date Finished 5-31-2018 Meter 1 Reading: 130,407

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

Service Requests:

05/24/2018 SERVICE REQUEST / 23: NOT CONNECTED / REPAIR
TIC CHARGING STATION INDICATES IT HAS POWER, BUT WILL NOT CHARGE THE TIC OR THE SPARE BATTERY.

CSHOP-2018-3050

Comments: **SPARE ENGINE AT 29**

Date Opened 6-4-2018 Date Finished 6-6-2018 Meter 1 Reading: 130,407

TASKS PERFORMED

NO PARTS USED

TANK-RESERVOIR
TURN SIGNAL LIGHTS

Service Requests:

06/01/2018 SERVICE REQUEST / 18: LEAKING / INSPECT
TANK WATER LEAKING FROM BEHIND DRIVERS SIDE REAR WHEEL.

06/01/2018 SERVICE REQUEST / 19: LOOSE / REPAIR
RIGHT FRONT DIRECTIONAL NOW WORKING..

Asset Work Order History 10155560

CSHOP-2018-3137

Comments: **SPARE ENGINE AT STATION 29**

Date Opened 6-6-2018 Date Finished 6-12-2018 Meter 1 Reading: 130,407

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 5TN; VPS SHIFT CONTROL PUMP KIT

Service Requests:

06/06/2018 AIR RIDE / 18: LEAKING / REPAIR
AIR BUILD UP TAKES A LONG TIME. DELAYING OUR RESPONSE TIME.

CSHOP-2018-3160

Date Opened 6-6-2018 Date Finished 6-6-2018 Meter 1 Reading: 130,407

TASKS PERFORMED

NO PARTS USED

TRANSFER CASE

Service Requests:

06/06/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
OCCASIONALLY WHEN TAKING THE TRUCK OUT OF PUMP THERE IS A GRINDING SOUND AND CANNOT GET OUT OF
DRIVE. HAVE TO SHUT DOWN THE TRUCK THEN TRY AGAIN.

CSHOP-2018-3645

Date Opened 6-28-2018 Date Finished 7-2-2018 Meter 1 Reading: 130,814

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FIL; NAPA COOLANT FILTER
25 4PC; 15W40 PREMIUM BLUE OIL
1 NCB; CHKETHRTTLEBDYCLNR
1 FIL; NAPAGOLD OIL FILTER
1 9IP; WASHER
1 FIL; NAPAGOLD AIR FILTER
1 FIL; FUEL WATER SEPARATOR
1 FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 1015560

CSHOP-2018-3714

Comments: **PM FOLLOW UPS**

Date Opened 7-2-2018

Date Finished

8-24-2018

Meter 1 Reading:

130,834

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	2	9IP; GASKET 2 1/2"
CONTROL VALVE FIRE PUMP	14	9AP; HEAT SENSOR LADDER LABELS
EQUIPMENT MOUNTING BRACKETS	1	2TK; FILTER
HOSE BED BODY	1	9IP; 182640VENTACNEW1719
REPAIR FROM PM - FIRE PUMP SYS	1	BK; RADIATORCAP
REPAIR FROM PM - GROUND LADDERS	1	9IP; BULB
CAP	2	LIT; LED M C LAMP
LIGHTING SYSTEM	4	1AD; BATTERY 31 SERIES
BATTERY TRAY	1	5TN; LATCHASSYFORULLH
CRANKING SYSTEM	1	TWD; AD-9KIT
BRAKES	1	TWD; AD-9KIT MINOR
AIR DRIER	1	9IP; MOLD R/H
LIGHT BAR	1	2FL; MOLDING LH
DOOR	1	MAC; SILICONE SPRAY 10OZ
CAB-INTERIOR ACCESSORIES		
HEATING AND VENTILATION		

CSHOP-2018-4961

Comments: **PUMP TEST FOLLOW-UP REPAIRS FAILED VACUUM TEST RELIEF VALVE HOUSING HAS SMALL LEAK ON PASSENGER SIDE THROTTLE CONTROL MODULE ON PUMP PANEL NOT DISPLAYING DIGITAL READINGS #1 DISCHARGE AND RIGHT REAR DISCHARGE GAUGES LOW ON OIL, RECOMMEND REPLACING MASTER DRAIN VALVE**

Date Opened 8-31-2018

Date Finished

12-6-2018

Meter 1 Reading:

130,920

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT	3	5HP; HALE 2.5 VALVE REPAIR KIT
CONTROL VALVE FIRE PUMP	1	9IP; VALVE KIT SS 546-2270-02-0
RELIEF VALVE FIRE PUMP	1	9IP; GASKET SEAL KIT P25/30
DISCHARGE GAUGE	1	9IP; HALE RELIEF VALVE W VULCANIZED SEAT
REPAIR FROM PM - PUMP PANEL CONTROLS	1	9IP; PMD CONTROL VALVE
REPAIR FROM PM - FIRE PUMP SYS	1	9IP; 121368 12 PORT MASTER DRAIN SUPTHEN
	1	9IP; GREASE ZERK WCHECK VLV
	4	5TN; GAUGE, 3.5 0-400 WH

Service Requests:

08/31/2018

SERVICE REQUEST / 18: LEAKING / REPAIRED REPLACED VALVE ASSEMBLY

FAILED PUMP TEST PRESSURE RELIEF VALVE ACTS LIKE IT OPENS AND CLOSES ON ITS OWN DURING 100% TEST NO OIL PRESSURE, NO WATER TEMP, NO RPM ON STATUS CENTER ON PUMP PANEL

CSHOP-2018-5197

Comments: **REMOVED HOSE BED ,FOUND LEAKING TANK REAR MIDDLE OF TANK.. WAIT ON VENDOR**

Date Opened 9-12-2018

Date Finished

10-3-2018

Meter 1 Reading:

130,916

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Asset Work Order History 10155560

CSHOP-2019-1097

Comments: **SPARE ENGINE AT ST55**

Date Opened 2-28-2019 Date Finished 3-7-2019 Meter 1 Reading: 131,642

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

02/28/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
SHORE LINE DAMAGED- WIRES EXPOSED

CSHOP-2019-1533

Comments: **CHCK TRANSMISSION WHEN COLD WILL DROP DOWN TO 2ND GEAR AND GETS STUCK , WILL LOG A CODE**

Date Opened 3-25-2019 Date Finished 3-26-2019 Meter 1 Reading: 132,265

TASKS PERFORMED

NO PARTS USED

FIRE PUMP
HANDLIGHT
LIGHTING SYSTEM
ALTERNATOR-GENERATOR
TRANSMISSION

Service Requests:

03/23/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
PUMP PANEL LIGHT AND RIGHT / LEFT TELESCOPIC SCENE LIGHTS INTERMITTENTLY WORKING.

03/23/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
STREAM LIGHT BOXES INSIDE CAB NOT CHARGING

03/24/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - USED
GENERATOR 20A OUTLET BROKEN AND UNUSABLE. ENTIRE BREAKER BOX IS FALLING OFF OF GENERATOR FRAME.

03/24/2019 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
ELECTRONIC THROTTLE ON PUMP PANEL PERIODICALLY WILL NOT TURN ON WHEN PUMP ENGAGED. HAVE TO SHUT DOWN TRUCK AND RESTART TO GET IT TO OPERATE

CSHOP-2019-1647

Comments: **SPARE ENGINE AT ST55**

Date Opened 3-29-2019 Date Finished 4-16-2019 Meter 1 Reading: 132,679

TASKS PERFORMED

NO PARTS USED

LID-SCREEN
TRANSMISSION

Service Requests:

03/29/2019 SERVICE REQUEST / 43: WEAK / INSPECT
OK TO PUMP LIGHT DOES NOT COME ON BUT TRUCK PUMPS JUST FINE

Asset Work Order History 10155560

CSHOP-2019-1753

Date Opened 4-4-2019 Date Finished 4-9-2019 Meter 1 Reading: 132,679

TASKS PERFORMED

Q PARTS

TRANSMISSION

1 ATP; SENSOR
1 ATP; ATP SENSOR

Service Requests:

04/04/2019 TRANSMISSION / 12: BROKEN / EXCHANGE - NEW
SHIFTS ONLY INTO SECOND GEAR WHEN ENGINE IS COLD.

CSHOP-2019-1762

Date Opened 4-5-2019 Date Finished 4-9-2019 Meter 1 Reading: 132,679

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

Service Requests:

04/05/2019 TRANSMISSION / 12: BROKEN / INSPECT
TRANSMISSION STILL STAYING STUCK IN 2ND GEAR WHEN MOTOR IS COLD. SHUTTING OFF THE BATTERY NO
LONGER WILL RESET IT.

CSHOP-2019-198

Date Opened 1-11-2019 Date Finished 1-30-2019 Meter 1 Reading: 131,003

TASKS PERFORMED

NO PARTS USED

PUMP

CSHOP-2019-929

Date Opened 2-19-2019 Date Finished 2-27-2019 Meter 1 Reading: 131,456

TASKS PERFORMED

NO PARTS USED

TRANSMISSION

Service Requests:

02/19/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
TRUCK WOULD NOT SHIFT OUT OF SECOND GEAR AND CHECK TRANSMISSION LIGHT CAME ON. WAS ABLE TO
RESET BY SHUTTING DOWN TRUCK AND BATTERIES AND RESTARTING.

Asset Work Order History 10155560

RADIO-2018-352

Comments: **REMOVAL OF 10141496, INSTALL OF 10205868 INTO SE4 - 10155560**

Date Opened 4-20-2018

Date Finished 4-20-2018

Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

04/20/2018

RADIO / /

REMOVAL & INSTALL OF NEW MOTOROLA MOBILE RADIO INTO SPARE ENGINE 4
