10169497 2007 FORD E350 Van, 1 Ton, Cargo

Workorder: Problem:	741256 PRE-DELIVE	Meter: RY INSPE	0 CTION			In Date:	07/11/2007	Closed:	07/11/20	007
- Pre-delivery	Inspection									
	Hour :	s 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	832352 P.M. SERVIC	Meter: E.	2208			In Date:	01/07/2008	Closed:	01/14/20	800
- Pm Service					Parts Lis	st				Qty
- Shop Suppli	ies				Shop Su	pplies				1.00
					1372 Oi	l Filter Frm	Ph2 Wix 51	372		1.00
					5w20 En	igine Oil				7.00
					10020 In	jector Clea	ner Don't Red	order		1.00
					31-20 W	iper Blades	20" Blade			2.00
					Used Fir	ex Refurbe	d Fire Extings	shers		1.00
	Hour :	s 4.00		Labor:	240.00	Parts:	46.74	Total:	286.74	
Workorder:	841029 P.M SERVICI	Meter:	4187			In Date:	07/08/2008	Closed:	07/11/20	800
Problem:	P.IVI SERVICE	_ '								
- Pm Service	P.W SERVICE	_			Parts Lis	st				Qty
- Pm Service	High Speed Ba		4 Tires.nitrof	fill Tires.	Parts Lis					-
- Pm Service	High Speed Ba		4 Tires.nitrof	fill Tires.	Shop Su	pplies	of G6593 Wix	33595		1.00
- Pm Service - Rotate And	High Speed Ba		4 Tires.nitrof	fill Tires.	Shop Su G8018 F	pplies uel Filter Ll	of G6593 Wix i Ph2 Wix 51			1.00
- Pm Service - Rotate And	High Speed Ba		4 Tires.nitrof	fill Tires.	Shop Su G8018 F	pplies uel Filter Ll I Filter Frm				1.00
- Pm Service - Rotate And	High Speed Ba		4 Tires.nitrof		Shop Su G8018 F 1372 Oi 5w20 En 31-20 W	pplies uel Filter Ll I Filter Frm	Ph2 Wix 51			1.00 1.00 1.00 7.00
- Pm Service - Rotate And	High Speed Ba ies		4 Tires.nitrof		Shop Su G8018 F 1372 Oi 5w20 En	pplies uel Filter Ll I Filter Frm gine Oil iper Blades	Ph2 Wix 51	372	333.66	1.00 1.00 1.00 7.00
- Pm Service - Rotate And - Shop Suppli	High Speed Ba ies	alance All 4	6402	Labor:	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W	pplies uel Filter Ll I Filter Frm gine Oil iper Blades	Ph2 Wix 51:	372	333.66	1.00 1.00 1.00 7.00 2.00
- Pm Service - Rotate And - Shop Suppli	High Speed Baies Hour : 932373	alance All 4	6402	Labor:	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W	pplies Tuel Filter Li I Filter Frm Igine Oil Iper Blades Parts: In Date:	Ph2 Wix 51: 20" Blade 33.66	372 Total:		Qty 1.00 1.00 7.00 2.00
- Pm Service - Rotate And - Shop Suppli - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewii	High Speed Baies Hour : 932373 P.M SERVICE	es 5.00 Meter: E,CHECK	6402 TRAILER PI	Labor: LUG Battery	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00	pplies Tuel Filter Li I Filter Frm Igine Oil Iper Blades Parts: In Date:	Ph2 Wix 51: 20" Blade 33.66	372 Total:		1.00 1.00 1.00 7.00 2.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys.	High Speed Bailes Hour : 932373 P.M SERVICE re Trailer Harne	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su	pplies Fuel Filter Li I Filter Frm Igine Oil Iper Blades Parts: In Date: st pplies	Ph2 Wix 51: 20" Blade 33.66	Total:		1.00 1.00 7.00 2.00 2.00 Qty
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039	pplies Tuel Filter Li I Filter Frm Igine Oil Iper Blades Parts: In Date: st pplies Air Filter Lb	Ph2 Wix 51: 20" Blade 33.66 01/06/2009	Total: Closed:		1.00 1.00 7.00 2.00 009 Qty 1.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi	pplies Fuel Filter Li I Filter Frm Igine Oil Iiper Blades Parts: In Date: st Ipplies Air Filter Frm	Ph2 Wix 51: 20" Blade 33.66 01/06/2009	Total: Closed: 46418 372		1.00 1.00 7.00 2.00 2.00 009 Qty 1.00 1.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys.	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi G8018 F	pplies Fuel Filter Li I Filter Frm Igine Oil Iiper Blades Parts: In Date: st Ipplies Air Filter Frm	20" Blade 33.66 01/06/2009 of Af1615 Wix Ph2 Wix 51: of G6593 Wix	Total: Closed: 46418 372		1.00 1.00 7.00 2.00 2.00 009 009 1.00 1.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi G8018 F	pplies Fuel Filter Lifer Frm Igine Oil Iper Blades Parts: In Date: st Ipplies Air Filter Lifer Frm Fuel Filter Lifer Frm Fuel Filter Lifer Lifer Rake Clean	20" Blade 33.66 01/06/2009 of Af1615 Wix Ph2 Wix 51: of G6593 Wix	Total: Closed: 46418 372		1.00 1.00 7.00 2.00 2.00 1.00 1.00 1.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewin Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi G8018 F 09997 E 5w20 En	pplies Fuel Filter Lifer Frm Igine Oil Iper Blades Parts: In Date: st Ipplies Air Filter Lifer Frm Fuel Filter Lifer Frm Fuel Filter Lifer Lifer Rake Clean	20" Blade 33.66 01/06/2009 of Af1615 Wix Ph2 Wix 51: of G6593 Wix	Total: Closed: 46418 372		1.00 1.00 7.00 2.00 2.00 1.00 1.00 1.00 7.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewir Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi G8018 F 09997 E 5w20 En 31-20 W	pplies Fuel Filter Life Frm Igine Oil Iper Blades Parts: In Date: St Ipplies Air Filter Life Frm Fuel Filter Life Frm Fuel Filter Life Frake Clean Igine Oil Iper Blades	20" Blade 33.66 01/06/2009 of Af1615 Wix Ph2 Wix 51: of G6593 Wix	Total: Closed: 46418 372 33595		1.00 1.00 7.00 2.00 2.00 1.00 1.00 1.00 7.00 2.00
- Pm Service - Rotate And - Shop Suppli Workorder: Problem: - Pm Service - Fab & Rewir Charging Sys Rotate & Hi	High Speed Baies Hour : 932373 P.M SERVICE re Trailer Harne . Replace Corre Speed Balance	es 5.00 Meter: E,CHECK ess To Ena	6402 TRAILER Pl able Trailer E Socket With	Labor: LUG Battery n New.	Shop Su G8018 F 1372 Oi 5w20 En 31-20 W 300.00 Parts Lis Shop Su Ca8039 1372 Oi G8018 F 09997 E 5w20 En 31-20 W Used Fir	pplies Fuel Filter Life Frm Igine Oil Iper Blades Parts: In Date: St Ipplies Air Filter Life Frm Fuel Filter Life Frm Fuel Filter Life Frake Clean Igine Oil Iper Blades	Ph2 Wix 51: 20" Blade 33.66 01/06/2009 of Af1615 Wix Ph2 Wix 51: of G6593 Wix	Total: Closed: 46418 372 33595		1.00 1.00 1.00 7.00 2.00 009

- Rotate, High Speed Balance All 4 Tires. Nitro Fill To Specs. Shop Supplies 1.00 - Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 1.00 - Workorder: 1000166 Meter: 11486 In Date: 01/05/2010 Closed: 01/12/2010 - Problem: pm service - Parts List Ca8039 Air Filter Lbf Af1615 Wix 46418 1.00 - Shop Supplies 1.00 - Shop Supplies 1.00 - Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 1.00 - Problem: pm service - Parts List Ca8039 Air Filter Lbf Af1615 Wix 46418 1.00 - Shop Supplies 1.00 - Sw20 Engine Oil 31-20 Wiper Blades 20" Blade 2.00 - Used Firex Refurbed Fire Extingshers 1.00 - Sw20 Engine Oil 31-20 Wiper Blades 20" Blade 2.00 - Used Firex Refurbed Fire Extingshers 1.00 - Sw20 Engine Oil 31-20 Wiper Blades 20" Blade 351-20 - Problem: Nail in R/F tire - Parts List Shop Supplies 1.00 - Shop Supplies Shop Supplies 1.00 - Shop Supplies Shop Supplies 1.00 - Parts: 51.20 Total: 351-20 - Problem: Pm service. Also see notes on installing a cone rack Perform pm service Parts List Shop Supplies 1.00 - Shop Supplies 1.00 - Shop Supplies 1.00 - Shop Supplies 1.00	Workorder: Problem:	939175 PM SERVICE.	Meter:	8416			In Date:	06/18/2009	Closed:	06/26/20	009
Shop Supplies	- Pm Service					Parts Li	st				Qty
Norkorder: 1000166 Meter: 11486 In Date: 01/05/2010 Closed: 01/12/2010	- Rotate, High	n Speed Balanc	e All 4 Tire	es. Nitro Fill	To Specs.	Shop Su	ıpplies				1.00
Hours 5.00 Labor: 300.00 Parts: 32.96 Total: 332.96 Total: 332.96	- Shop Suppli	ies				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
Hours 5.00 Labor: 300.00 Parts: 32.96 Total: 332.96						5w20 Er	ngine Oil				7.00
Norkorder: 1000166 Meter: 11486 In Date: 01/05/2010 Closed: 01/12/2010 Problem: pm service Parts List Qty - P.m. service Parts List Shop Supplies Shop Suppli						Used Fir	ex Refurbe	ed Fire Extings	hers		1.00
Problem: pm service - P.m service - P.m service - Rotate & balance all four tires - Shop Supplies - 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Shop Supplies - 1372 Oil Filter Lbf Af1615 Wix 46418 1.00 - G8018 Fuel Filter Lbf G6593 Wix 33595 1.00 - Sw20 Engine Oil 7.00 - 31-20 Wiper Blades 20" Blade 2.00 - Used Firex Refurbed Fire Extingshers 1.00 - Used Firex Refurbed Fire Extingshers 1.00 - Problem: Nail in R/F tire - Repair R/f tire. Parts List Qty - Shop Supplies Shop Supplies 1.00 - Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 - Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 - Problem: Pm service. Parts List Qty - Rotate and balance all four tires. Shop Supplies 1.00 - Profferm pm service. Parts List Qty - Rotate and balance all four tires. Shop Supplies 1.00 - Problem: Pm service. Shop Supplies 1.00 - Shop		Hours :	s 5.00		Labor:	300.00	Parts:	32.96	Total:	332.96	
- Rotate & balance all four tires. Shop Supplies 1.00 - Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 1.00 - Ca8039 Air Filter Lbf Af1615 Wix 46418 1.00 - G8018 Fuel Filter Lbf G6593 Wix 33595 1.00 - Sw20 Engine Oil 7.00 - 31-20 Wiper Blades 20" Blade 2.00 - Used Firex Refurbed Fire Extingshers 1.00 - Hours 5.00 Labor: 300.00 Parts: 51.20 Total: 351.20 - Workorder: 1002882 Meter: 12225 In Date: 03/22/2010 Closed: 03/22/2010 - Problem: Nail in R/F tire - Repair R/f tire. Parts List Qty - Shop Supplies Shop Supplies 1.00 - Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 - Workorder: 1007444 Meter: 13918 In Date: 07/14/2010 Closed: 07/26/2010 - Problem: Pm service. Also see notes on installing a cone rack Perform pm service. Parts List Qty - Rotate and balance all four tires. Shop Supplies 1.00 - Shop Supplies 1.0	Workorder: Problem:		Meter:	11486			In Date:	01/05/2010	Closed:	01/12/20	010
- Shop Supplies	- P.m service					Parts Li	st				Qty
Ca8039 Air Filter Lbf Af1615 Wix 46418	- Rotate & ba	lance all four tire	es.			Shop Su	ıpplies				1.00
G8018 Fuel Filter Lbf G6593 Wix 33595 1.00	- Shop Suppli	ies				1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
Sw20 Engine Oil						Ca8039	Air Filter L	of Af1615 Wix	46418		1.00
Norkorder: 1002882 Meter: 12225 In Date: 03/22/2010 Closed: 03/22/2010 Problem: Nail in R/F tire - Repair R/f tire. Parts List Chapter: 1007/444 Meter: 13918 In Date: 07/14/2010 Closed: 07/26/2010 Problem: Pm service. Also see notes on installing a cone rack. - Perform pm service. Parts List Chapter: 07/14/2010 Closed: 07/26/2010						G8018 F	uel Filter L	bf G6593 Wix	33595		1.00
Used Firex Refurbed Fire Extingshers 1.00						5w20 Er	ngine Oil				7.00
Hours 5.00						31-20 W	iper Blades	s 20" Blade			2.00
Sepair R/f tire Parts List Qty						Used Fir	ex Refurbe	ed Fire Extings	hers		1.00
Problem: Nail in R/F tire Repair R/f tire. Shop Supplies Shop Supplies Shop Supplies Porkorder: 1007444 Meter: 13918 In Date: 07/14/2010 Closed: 07/26/2010 Problem: Pm service. Also see notes on installing a cone rack. Perform pm service. Rotate and balance all four tires. Shop Supplies		Hours :	s 5.00		Labor:	300.00	Parts:	51.20	Total:	351.20	
Shop Supplies Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Norkorder: 1007444 Meter: 13918 Problem: Pm service.Also see notes on installing a cone rack. Perform pm service. Parts List Shop Supplies 1.00 Qty - Rotate and balance all four tires. Shop Supplies 1.00 Shop Supplies Shop Supplies 1.00 Sw20 Engine Oil 7.00	Workorder: Problem:			12225			In Date:	03/22/2010	Closed:	03/22/20	010
Shop Supplies Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Norkorder: 1007444 Meter: 13918 In Date: 07/14/2010 Closed: 07/26/2010 Problem: Pm service.Also see notes on installing a cone rack. Perform pm service. Parts List Shop Supplies 1.00 1.00 1.00 1.00 2.00 1.00 2.00 1.00 2	- Repair R/f ti	re.				Parts Li	st				Qty
: Norkorder: 1007444 Meter: 13918 In Date: 07/14/2010 Closed: 07/26/2010 Problem: Pm service. Also see notes on installing a cone rack. - Perform pm service. Parts List Qty - Rotate and balance all four tires. Shop Supplies 1.00 - Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 1.00 5w20 Engine Oil 7.00	- Shop Suppli	ies				Shop Su	pplies				1.00
Problem: Pm service. Also see notes on installing a cone rack. - Perform pm service. Parts List Qty - Rotate and balance all four tires. Shop Supplies 1.00 - Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 1.00 5w20 Engine Oil 7.00		Hours	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
- Rotate and balance all four tires Shop Supplies 1.00 - Shop Supplies 1.00 5w20 Engine Oil 7.00	Workorder: Problem:				ing a cone	rack.	In Date:	07/14/2010	Closed:	07/26/20	010
- Rotate and balance all four tires Shop Supplies 1.00 - Shop Supplies 1.00 5w20 Engine Oil 7.00	- Perform pm	service.				Parts Li	st				Qty
5w20 Engine Oil 7.00	•		tires.			Shop Su	ıpplies				1.00
5w20 Engine Oil 7.00	- Shop Suppli	ies				1372 O	il Filter Frm	n Ph2 Wix 510	372		1.00
Hours 5.00 Labor: 300.00 Parts: 17.44 Total: 317.44						5w20 Er	ngine Oil				7.00
		Hours	s 5.00		Labor:	300.00	Parts:	17.44	Total:	317.44	

Workorder: Problem:	1100412 Pm service	Meter ce.	: 16930		In Date:	01/11/2011	Closed:	01/20/20	011
- Perform pm	service.				Parts List				Qty
- Test starting		aina system.	batterv failed	load test	Shop Supplies				1.00
after recharge					1372 Oil Filter Fr		1.00		
- Install four n	new tires.ni	itrogen fill an	d balance all	four.	Ca8039 Air Filter I		1.00		
- Perform who	eel alignme	ent complete			G8018 Fuel Filter				1.00
- Shop Suppli	ies				5w20 Engine Oil				7.00
					Used Firex Refurb	ed Fire Exting	shers		1.00
					31-20 Wiper Blade	· ·	511010		2.00
					Group 65 Battery		O)		1.00
					179747492 Lt245/	•	•		4.00
					Tr416 Valve Stem	•	i ora L		4.00
		Hours 0.50		Lobori	Tire Disposal Fee	. 027.52	Totalı	1 107 E	4.00
	:	Hours 9.50 :		Labor:	570.00 Parts	s: 837.52	i otai:	1,407.5	2
Workorder: Problem:	1100849 Pad lock	Meter on rear door			In Date:	01/21/2011	Closed:	02/03/2	011
- Remove fail	ed padlock	k from rear d	oor.fabricate l	holes in	Parts List				Qty
bracket and in					Shop Supplies				1.00
- Shop Suppli	ies				Security Lock				1.00
	I	Hours 0.75		Labor:	•	s: 38.98	Total:	83.98	
Workorder:	1106406	Meter	: 19195			00/47/0044	Classel	00/00/0	
	Left front		. 19195		In Date:	06/17/2011	Closed:	06/22/20	011
Problem:	Left front	tire flat.	. 19195			06/17/2011	Ciosea:	06/22/20	
Problem: - Repair and I	Left front balance lef	tire flat.	. 19193		Parts List	06/17/2011	Closea:	06/22/20	Qty
Problem:	Left front balance lef ies	tire flat.	. 19193	Labor:	Parts List Shop Supplies				
Problem: - Repair and I	Left front balance lef ies	tire flat.	. 19193	Labor:	Parts List Shop Supplies	06/17/2011 s: 2.00		62.00	Qty
Problem: - Repair and the shop Supplication Workorder:	Left front balance lef ies	tire flat. ft front tire. Hours 1.00 : Meter		Labor:	Parts List Shop Supplies				Qty 1.00
Problem: - Repair and because of the state o	Left front balance lefties ! 1107527 P.M. Ser	tire flat. ft front tire. Hours 1.00 : Meter		Labor:	Parts List Shop Supplies 60.00 Parts	s: 2.00	Total:	62.00	Qty 1.00
Problem: - Repair and the Shop Supplication - Shop Supplication - Shop Supplication - Perform pm	Left front balance left ies 1107527 P.M. Ser service.	tire flat. ft front tire. Hours 1.00 : Meter	: 19969		Parts List Shop Supplies 60.00 Parts In Date: Parts List	s: 2.00	Total:	62.00	Qty 1.00 011 Qty
Problem: - Repair and the Shop Supplication - Shop Supplication - Workorder: - Problem: - Perform pm - Front wheel	Left front balance lefties 1107527 P.M. Ser service. bearings left	tire flat. ft front tire. Hours 1.00 : Meter	: 19969		Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies	o7/19/2011	Total:	62.00	Qty 1.00 011 Qty 1.00
Problem: - Repair and the Shop Supplication - Shop Supplication - Workorder: - Problem: - Perform pm - Front wheel	Left front balance left ies 1107527 P.M. Ser service. bearings lefts.	tire flat. ft front tire. Hours 1.00 : Meter vice. oose.repack	: 19969		Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr	s: 2.00 07/19/2011 m Ph2 Wix 51	Total:	62.00	Qty 1.00 011 Qty 1.00 1.00
Problem: - Repair and B - Shop Suppli Workorder: Problem: - Perform pm - Front wheel wheel bearing - Rotate and B - Test lighter of	Left front balance lefties 1107527 P.M. Ser service. bearings lefts balance all circuit for	tire flat. It front tire. Hours 1.00: Meter vice. oose.repack	: 19969 and adjust bo	oth front	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies	s: 2.00 07/19/2011 m Ph2 Wix 51	Total:	62.00	Qty 1.00 011 Qty 1.00
Problem: - Repair and because A supplied of the supplied of the supplied open fuse with a supplied open fuse open fuse with a supplied open fuse open fuse with a supplied open fuse open	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for in new.	tire flat. It front tire. Hours 1.00: Meter vice. oose.repack	: 19969 and adjust bo	oth front	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu	m Ph2 Wix 51 m (crc 05037)	Total:	62.00	Qty 1.00 011 Qty 1.00 1.00 2.00
Problem: - Repair and B - Shop Suppli Workorder: Problem: - Perform pm - Front wheel wheel bearing - Rotate and B - Test lighter of	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for in new. ies	tire flat. It front tire. Hours 1.00: Meter vice. oose.repack	: 19969 and adjust bo	oth front d replace	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade	m Ph2 Wix 51 m (crc 05037)	Total: Closed:	62.00	Qty 1.00 011 Qty 1.00 1.00 2.00 7.00
Problem: - Repair and because A shop Supplied Workorder: - Problem: - Perform pmeter of the shop Supplied Problem: - Test lighter of the shop Supplied Workorder:	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for in new. ies	tire flat. It front tire. Hours 1.00 Meter vice. oose.repack four tires. power and g Hours 6.75 Meter	: 19969 and adjust bo	oth front d replace	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade	m Ph2 Wix 51 m (crc 05037)	Total: Closed:	62.00	Qty 1.00 011 Qty 1.00 1.00 2.00 7.00 2.00
Problem: - Repair and be Shop Suppli Workorder: Problem: - Perform pme Front wheel wheel bearinger Rotate and been fuse wither open fuse wither shop Suppli Workorder: Problem:	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for in new. ies 1108154 Install lad	tire flat. It front tire. Hours 1.00 Meter vice. oose.repack four tires. power and g Hours 6.75 Meter der rack	and adjust be round.test and	oth front d replace	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade 405.00 Parts In Date:	s: 2.00 07/19/2011 m Ph2 Wix 51 m (crc 05037) es 20" Blade s: 37.64	Total: Closed: 372 Total:	62.00 07/27/20 442.64	Qty 1.00 011 Qty 1.00 2.00 7.00 2.00
Problem: - Repair and B - Shop Suppli Workorder: Problem: - Perform pm - Front wheel wheel bearing - Rotate and B - Test lighter open fuse with - Shop Suppli Workorder: Problem: - Remove old	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for period new. ies 1108154 Install lad	tire flat. It front tire. Hours 1.00 Meter vice. oose.repack four tires. power and g Hours 6.75 Meter der rack	and adjust be round.test and	oth front d replace	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade 405.00 Parts In Date:	s: 2.00 07/19/2011 m Ph2 Wix 51 m (crc 05037) es 20" Blade s: 37.64	Total: Closed: 372 Total:	62.00 07/27/20 442.64	Qty 1.00 011 Qty 1.00 1.00 2.00 7.00 2.00
Problem: - Repair and be Shop Suppli Workorder: Problem: - Perform pme Front wheel wheel bearinger Rotate and been fuse wither open fuse wither shop Suppli Workorder: Problem:	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for period new. ies 1108154 Install lad	tire flat. It front tire. Hours 1.00 Meter vice. oose.repack four tires. power and g Hours 6.75 Meter der rack	and adjust be round.test and	oth front d replace	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade 405.00 Parts In Date: Parts List Shop Supplies	s: 2.00 07/19/2011 m Ph2 Wix 51 m (crc 05037) es 20" Blade s: 37.64	Total: Closed: 372 Total:	62.00 07/27/20 442.64	Qty 1.00 011 Qty 1.00 2.00 7.00 2.00
Problem: - Repair and B - Shop Suppli Workorder: Problem: - Perform pm - Front wheel wheel bearing - Rotate and B - Test lighter open fuse with - Shop Suppli Workorder: Problem: - Remove old	Left front balance left ies 1107527 P.M. Ser service. bearings lefts balance all circuit for properties. 1108154 Install ladder racties	tire flat. It front tire. Hours 1.00 Meter vice. oose.repack four tires. power and g Hours 6.75 Meter der rack	and adjust be round.test and	oth front d replace Labor:	Parts List Shop Supplies 60.00 Parts In Date: Parts List Shop Supplies 1372 Oil Filter Fr 1066 White Lithiu 5w20 Engine Oil 31-20 Wiper Blade 405.00 Parts In Date: Parts List Shop Supplies Ladder Rack	s: 2.00 07/19/2011 m Ph2 Wix 51 m (crc 05037) es 20" Blade s: 37.64	Total: Closed: Total: Closed:	62.00 07/27/20 442.64	Qty 1.00 011 Qty 1.00 2.00 7.00 2.00 011 Qty 1.00 1.00

Workorder: Problem:	1110784 damage to frt	Meter: bumper &	20629 frlft fender			In Date:	09/27/2011	Closed:	10/11/20)11
- damage to fr	t bumper & frlf	t fender								
	Hour :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1200225 Pm service ar	Meter:	21433 afety cone,holo	der see r	notes.	In Date:	01/06/2012	Closed:	01/19/20	12
- Perform pm					Parts L	ict				Qty
-		mer supplie	ed new cone h	older to	Shop Si					1.00
front bumper a		пог саррії	sa now cono n	oldol to			Ph2 Wix 513	372		1.00
- Rotate and b	alance all four	r tires.					of G6593 Wix			1.00
- Shop Supplie	es				1066 W	/hite Lithium	(crc 05037)			1.00
					5w20 E	ngine Oil	,			7.00
					31-20 W	Viper Blades	20" Blade			2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
	Hour :	s 6.00		Labor:	360.00	Parts:	52.92	Total:	412.92	
Workorder: Problem:	1206556 Pm service.	Meter:	24152			In Date:	07/13/2012	Closed:	07/25/20)12
- P.m. Service).				Parts L	ist				Qty
- Rotate and b	alance all tires	3.			Shop Si	upplies				1.00
- Shop Supplie	es				1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					5w20 E	ngine Oil				7.00
					31-20 V	Viper Blades	20" Blade			2.00
	Hour :	s 5.00		Labor:	300.00	Parts:	32.06	Total:	332.06	
Workorder: Problem:	1300229 P.M. service a	Meter: and detail.	26214			In Date:	01/07/2013	Closed:	01/17/20	13
- P.m. Service).				Parts L	ist				Qty
- Rotate and b		S.			5w20 E	ngine Oil				7.00
- Shop Supplie	es				1372 Oi	_				1.00
					31-20 W	Viper Blades	20			2.00
					Napago	ld Fuel Filte	r			1.00
					Used Fi	rex Refurbe	d F			1.00
					Shop Si	upplies				1.00
	Hour	s 5.00		Labor:	300.00	Parts:	60.67	Total:	360.67	
Workorder: Problem:	1300610 1 - Detail Veh	Meter: icle Wash	26185 Ticket(s) Issue	ed		In Date:	01/16/2013	Closed:	01/16/20)13
- 1 - Detail Ve	hicle Wash Tid	cket(s) Issu	ıed							
		rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1306714 Pm service.	Meter:	28897		In	Date:	07/05/2013	Closed:	07/25/2013
- P.m. Service).			Pa	arts List				Qty
- Replace brol	ken extinguish	er bracket.		5v	v20 Engir	ne Oil			7.00
- A/c not cold,	check a/c syst	em.replace	eleaking	Na	apagold (Dil Filter			1.00
		orfice tube	vacuum and recha	rge Ca	a8039 Air	Filter Lb	of		1.00
system to specRotate and b		.		31	-20 Wipe	er Blades	20		2.00
- Shop Supplie		5.		5lb	o Bracket	Firex St	0		1.00
- Shop Supplie	55			Co	ondenser				1.00
				Se	eal Kits				2.00
				Ac	ccumaltor				1.00
				A/	c Orifice	Tube			1.00
				R1	134a Lv S	Shop 1			2.00
				Sh	nop Supp	lies			1.00
	Hou	rs 10.50	Lat	or: 63	80.00	Parts:	520.49	Total:	1,150.49
Workorder: Problem:	1400439 Pm service	Meter:	31657		In	Date:	01/14/2014	Closed:	01/29/2014
- P.m. Service).			Pa	arts List				Qty
- Test battery	and charging	system.rep	lace bad battery.	5v	v20 Engir	ne Oil			7.00
- Replace two	tires,rotate ar	nd balance	all four.	Na	apagold (Dil Filter			1.00
- Shop Supplie	es			Ac	cufit Cor	nventiona	al		2.00
				Na	apagold F	Fuel Filte	r		1.00
				Ba	attery				1.00
				17	9747492	Lt245-7	5r16		2.00
				Tr	416 Valv	e Stem			2.00
				Sh	nop Supp	lies			1.00
				Tir	re Dispos	al Fee			2.00
	Hou	rs 7.00	Lab	or: 42	20.00	Parts:	613.23	Total:	1,033.23
Workorder: Problem:	1406947 Pm service	Meter:	34674		In	Date:	07/15/2014	Closed:	07/25/2014
				D.	arts List				Qty
- P.m. Service).			Pa	ม เอ เเอเ				~-,
- P.m. Service		cooling sys	tem.flush and refill		v20 Engir	ne Oil			7.00
- P.m. Service - Pressure tes system.	t and inspect	0,		5w					•
P.m. ServicePressure tes system.Replace two	t and inspect of tires,rotate ar	nd balance		5v Na	v20 Engir	Dil Filter			7.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na	v20 Engir apagold (Dil Filter Air Filter	shed		7.00 1.00
P.m. ServicePressure tes system.Replace two	t and inspect of tires,rotate ar neel alignment	nd balance		5v Na Na Us	v20 Engir apagold (apagold <i>l</i>	Dil Filter Air Filter K Refurbi	shed		7.00 1.00 1.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na Us W	v20 Engir apagold (apagold <i>F</i> sed Fire)	Dil Filter Air Filter K Refurbi	shed		7.00 1.00 1.00 1.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na Us W	v20 Engir apagold (apagold / sed Fire) d40 16oz eak Globa	Dil Filter Air Filter K Refurbi	shed		7.00 1.00 1.00 1.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na Us W Pe Bu	v20 Engir apagold (apagold / sed Fire) d40 16oz eak Globa	Oil Filter Air Filter K Refurbi Z			7.00 1.00 1.00 1.00 1.00 2.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na Us W Pe Bu 17	v20 Engir apagold (apagold A sed Fire) d40 16oz eak Globa	Oil Filter Air Filter K Refurbi Z al			7.00 1.00 1.00 1.00 1.00 2.00
P.m. ServicePressure tes system.Replace twoComplete wh	t and inspect of tires,rotate ar neel alignment	nd balance		5w Na Na Us W Pe Bu 17	v20 Engir apagold (apagold / sed Fire) d40 16oz eak Globa ulb	Dil Filter Air Filter K Refurbi al Lt245-7 lies			7.00 1.00 1.00 1.00 2.00 2.00 2.00

Workorder: Problem:	1500426 Pm service.	Meter:	36915			In Date:	01/13/2015	Closed:	02/05/20)15
- P.m. Service	Э.				Parts Lis	st				Qty
	ront and frear				B Fluid D	ot 3-32oz				1.00
rear pads.servand tgest drive		calip[ers.flus	sh and bleed	d system	Caster-ca	amber Bus	hing			1.00
•	er/caster adju	et on both c	sidos comple	oto whool	Loaded	Cal				1.00
alignment.test		St OII DOUI S	nues.comple	ME WITEET	Loaded (Cal				1.00
- Rotate an d	balance all tir	es			pad brak	е				1.00
- Shop Suppli	es				5w20 En	gine Oil				7.00
					Napagolo	d Oil Filter				1.00
					Napagolo	d Fuel Filte	r			1.00
					Accufit C	onventiona	al			2.00
					Reman E	Brake Calip	er			2.00
					Reman E	Brake Calip	er			2.00
					Retainer					2.00
					Shop Su	pplies				1.00
	Ηοι :	urs 17.00		Labor:	1,020.0 0	Parts:	761.21	Total:	1,781.21	
Workorder: Problem:	1507656 P.M. Service	Meter:	39712			In Date:	07/31/2015	Closed:	08/14/20)15
- Pm service.					Parts Lis	st				Qty
- Inspect and	replace both t	front shocks	s-bushings n	nissing.	5w20 En	gine Oil				7.00
- Rotate and I	balance all fou	ır wheels.			Napagolo	d Oil Filter				1.00
- Shop Suppli	es				Washer I	Fluid Conce	entr			1.00
					20" Wipe	er Blade				2.00
					Shock - 0	Gas Grand	e Fleet - Front			2.00
					Shop Su	pplies				1.00
	Hou :	urs 6.00		Labor:	360.00	Parts:	148.87	Total:	508.87	
Workorder: Problem:	1512131 Had to jump	Meter: start.	41555			In Date:	12/01/2015	Closed:	12/09/20)15
Charge bett	ery fully.test b	attery and (charging		Parts Lis	st				Qty
- Charge ball	Cry runy.toot b	allery and c								•
system.replac					Battery					1.00
	e defective ba				Battery Shop Su	pplies				1.00 1.00
system.replac	e defective ba			Labor:	Shop Su		120.41	Total:	180.41	

:

Workorder: 1600958 Meter: 4227 Problem: P.M. Service.	' 4	In Date:	01/28/2016	Closed:	02/08/2016
- Pm service.		Parts List			Qty
- Check battery and charging system.full cha		5w20 Engine Oil			7.00
battery.alternator failed.replace defective alte	rnator assembly	Napagold Oil Filter			1.00
and serpentine belt.Perform transmission fluid flush and refill.		Napagold Fuel Filte	er		1.00
		Napagold Air Filter			1.00
- Rotate and balance all four tires.		Used Fire X Refurb	ished		1.00
- Shop Supplies		20" Wiper Blade			2.00
		Syn-atf Trans Fluid	S		14.00
		Alternator			1.00
		Serpentine Belt			1.00
		Drain Plug			1.00
		Shop Supplies			1.00
Hours 8.50	Labor:	510.00 Parts:	326.54	Total:	836.54
Workorder: 1607861 Meter: 4291 Problem: P.M. service.	2	In Date:	08/01/2016	Closed:	08/22/2016
- P.m. Service.		Parts List			Qty
- Replace loose right upper and lower ball jo	ints.	5w20 Engine Oil			7.00
- Repair right rear tire, rotate and balance all	four.	Napagold Oil Filter			1.00
- Complete wheel alignment.test drive.		20" Wiper Blade			2.00
- Shop Supplies		Upper Ball Joint			1.00
		Lower Ball Joint			1.00
		Ct =: \\ \/ \ = = = \ C = :	ord		1.00
		Stg Wheel Cov - Fo	лu		1.00
		Stg wheel Cov - For Shop Supplies	ла		1.00

Workorder:	1700249	Meter: 44949			In Date:	01/09/2017	Closed:	01/31/2017
Problem:	P.M. service a	and noise from tran	smission and i	rear cargo	door inop	and check str	obes.	
- P.m. Service	э.			Parts Lis	t			Q
		mission concern.r&		5w20 Eng	gine Oil			7.0
		s in pan.replace tra install new cooler.	ansmission	Napagold	Oil Filter			1.0
	ŕ	id balance all four.		20" Wiper	Blade			2.0
•	front strobe bu			Washer F	luid Conc	entr		1.0
•		er and lower latch a	ssemble	Used Fire	X Refurb	ished		1.0
•		ing.perform comple		Napagold	Fuel Filte	r		1.0
alignment.test		9·h		Transmis				1.0
- Shop Suppli	es			Lt245 75r				2.0
				Super Glu	ıe			1.0
				Cooler				1.0
				Hide Awa	•			1.0
				Door Late				1.0
				Door Han				1.0
				Caster-ca		· ·		1.0
				Syn-atf Ti		5		4.0
				Shop Sup				1.0
				Tire Dispo		2 002 00	Total	2.0 5,103.09
	Нош	·c 20 00	Lahor:	1 200 0	Darte.			0.100.03
Workorder:	1706199	Meter: 48232		1,200.0	Parts:	3,903.09	Closed:	07/10/2017
Problem:	: 1706199 Left rear door ssenger side re		utside.	0	In Date:	06/22/2017		
Problem: - Replace pas	: 1706199 Left rear door ssenger side re	Meter: 48232 won't open from ou	utside.	0 Parts Lis	In Date: t remote c	06/22/2017		07/10/2017 Q
Problem: - Replace pas	: 1706199 Left rear door ssenger side re	Meter: 48232 won't open from ou	utside.	Parts Lis door latch Shop Sup	In Date: t remote copplies	06/22/2017	Closed:	07/10/2017 Q 1.0
Problem: - Replace pas - Shop Suppli	: 1706199 Left rear door ssenger side re es Hour :	Meter: 48232 won't open from ou ear door latch asser	utside. mbly.retest.	Parts Lis door latch Shop Sup 75.00	t remote coplies Parts:	06/22/2017 ontrol 99.46	Closed:	07/10/2017 Q 1.0 1.0 174.46
Problem: - Replace pas - Shop Suppli Workorder:	: 1706199 Left rear door ssenger side re	Meter: 48232 won't open from ou ar door latch asser	utside. mbly.retest.	Parts Lis door latch Shop Sup 75.00	In Date: t remote copplies	06/22/2017 ontrol	Closed:	07/10/2017 Q 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem:	: 1706199 Left rear door ssenger side re ies Hour : 1707515 P.M. service.	Meter: 48232 won't open from ou ear door latch asser	utside. mbly.retest.	Parts Lis door latch Shop Sup 75.00	In Date: t n remote copplies Parts: In Date:	06/22/2017 ontrol 99.46	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service.	Meter: 48232 won't open from out ear door latch asser es 1.25 Meter: 48551	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00	t remote copplies Parts:	06/22/2017 ontrol 99.46	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service.	Meter: 48232 won't open from ou ear door latch asser	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng	t n remote coplies Parts: In Date: t	06/22/2017 ontrol 99.46	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four.	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service.	Meter: 48232 won't open from out ear door latch asser es 1.25 Meter: 48551	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold	t remote coplies Parts: In Date: t Oil Filter	06/22/2017 ontrol 99.46	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four.	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper	t remote coplies Parts: In Date: t Oil Filter	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper	t remote coplies Parts: In Date: t oil Filter Blade	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire	In Date: t n remote coplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F	t remote coplies Parts: In Date: t on Parts: In Date: t on Parts: X Refurb on Parts:	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F Lt245 75r	t remote coplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb Fluid Concide New Stem	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0 2.0 2.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F Lt245 75r Tr416 Val	t remote coplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb Fluid Concort 16	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0 2.0 2.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F Lt245 75r Tr416 Val Hose Win	t remote coplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb Fluid Concort 16	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0 2.0 1.0 1.0 2.0 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F Lt245 75r Tr416 Val Hose Win Washer N	In Date: t n remote copplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb Fluid Conce 16 Ive Stem Iozzle	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0 2.0 1.0 1.0 2.0 1.0
Problem: - Replace pas - Shop Suppli Workorder: Problem: - P.m. service - Replace two four Replace faile	: 1706199 Left rear door ssenger side re ses Hour : 1707515 P.M. service. c) tires and rotated	Meter: 48232 won't open from outer door latch asserts: 1.25 Meter: 48551 te and high speed be	utside. mbly.retest. Labor:	Parts Lis door latch Shop Sup 75.00 Parts Lis 5w20 Eng Napagold 20" Wiper Used Fire Washer F Lt245 75r Tr416 Val Hose Win Washer N Kit Jet	In Date: t n remote coplies Parts: In Date: t gine Oil Oil Filter Blade X Refurb Fluid Conce 16 live Stem lozzle oplies	06/22/2017 ontrol 99.46 08/01/2017	Closed:	07/10/2017 Q 1.0 1.0 174.46 08/16/2017 Q 7.0 1.0 2.0 1.0 2.0 1.0 2.0 2.0 1.0 2.0

Workorder: Problem:	1801257 P.M. service	Meter: and left fro	50735 nt tire going	flat.	In D	ate:	02/01/2018	Closed:	02/06/20)18
- P.m. service).				Parts List					Qty
- Rotated and	l balanced all f	our tires .n	itrogen filled	tires	5w20 Engine	Oil				7.00
remove screw	v in drivers fror	nt tire and r	epair.		Napagold Oil					1.00
- Shop Suppli	es				Napagold Fue		r			1.00
					Hose Clamp					1.00
					20" Wiper Bla	ıde				2.00
					Shop Supplies					1.00
	Hou	rs 6.00		Labor:			33.13	Total:	393.13	
Workorder: Problem:	1802406 Side cargo do	Meter: oor inop.	50902		In D	ate:	03/05/2018	Closed:	03/06/20)18
	ide door opera	tion .r&r fa	iled latch ass	sembly on	Parts List					Qty
side cargo dod	or front.retest.				door latch rem	note co	ontrol			1.00
- Shop Suppli	es				Shop Supplies	s				1.00
	Hou	rs 1.10		Labor:	66.00 F	Parts:	99.46	Total:	165.46	
Workorder:	1808037	Meter:	52981		In D	ate:	08/06/2018	Closed:	08/15/20)18
Problem:	P.M. service	and back c	argo door in	op.						
- P.m. service).				Parts List					Qty
OL L A /										
	nd blower ope	ration . R&	r defective b	lower	Napagold Oil	Filter				1.00
resistor .					Napagold Oil 5w20 Engine					
resistor . - R&r right se	aled beam hea	adlight due	to water intr	usion.		Oil				7.00
resistor . - R&r right sea - Test side ca	aled beam hea	adlight due	to water intr	usion.	5w20 Engine	Oil ide	entr			7.00 2.00
resistor R&r right se - Test side ca assemblies . F - Perform fror	aled beam hea	adlight due inop . Repla	to water intr ace latch and	rusion. d cable	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R	Oil ide Conce Refurbi	shed			7.00 2.00 1.00 1.00
resistor R&r right se: - Test side ca assemblies . F - Perform fror Test drive.	aled beam hea rgo door rear i Retest. nt end alignme	adlight due nop . Repla	to water intrace latch and	rusion. d cable off center .	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor	Oil Ide Conce Refurbi Resis	shed tor			7.00 2.00 1.00 1.00 1.00
resistor R&r right sector - Test side cactor assemblies . For Perform from Test drive Rotate and I	aled beam heargo door rear in Retest. In the end alignment of the speed bal	adlight due nop . Repla	to water intrace latch and	rusion. d cable off center .	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal	Oil Ide Conce Refurbi Resis	shed tor			7.00 2.00 1.00 1.00 1.00
resistor R&r right se: - Test side ca assemblies . F - Perform fror Test drive.	aled beam heargo door rear in Retest. In the end alignment of the speed bal	adlight due nop . Repla	to water intrace latch and	rusion. d cable off center .	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch	Oil Ide Conce Refurbi Resis	shed tor			7.00 2.00 1.00 1.00 1.00 1.00
resistor R&r right sector - Test side cactor assemblies . For Perform from Test drive Rotate and I	aled beam heargo door rear in Retest. In the end alignment of the speed bal	adlight due nop . Repla	to water intrace latch and	rusion. d cable off center .	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch	Oil de Conce Refurbi Resisi	shed tor			7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right se Test side ca assemblies . F - Perform fror Test drive. - Rotate and I	aled beam heargo door rear in Retest. In end alignmentigh speed bales	adlight due inop . Repla nt due stea	to water intrace latch and	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies	Oil ide Conce Refurbi Resisi ed Bea	shed tor ams	Total:	970 46	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right second right second rest side cate assemblies . For the rest drive Rotate and the rest drive.	aled beam heargo door rear in Retest. In end alignmentigh speed bales	adlight due nop . Repla	to water intrace latch and	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies	Oil ide Conce Refurbi Resisi ed Bea	shed tor	Total:	870.46	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right ser - Test side ca assemblies . F - Perform fror Test drive Rotate and I - Shop Suppli	aled beam heargo door rear in Retest. Internal end alignment in the speed ballies Hou 1810178	adlight due inop . Repla nt due stea	to water intrace latch and	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies	Oil Ide Conce Refurbi Resis ded Bea	shed tor ams	Total:	870.46	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sector Test side cactor assemblies . For a from from the control of t	aled beam heargo door rear in Retest. Internal end alignment in the speed balles Hou 1810178 No Start	adlight due inop . Replant due ster ance all for meter:	to water intrace latch and ering wheel our wheels Ni	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00	Oil Ide Conce Refurbi Resis ded Bea	shed tor ams 255.46			7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sec Test side ca assemblies . F Perform fror Test drive Rotate and I Shop Suppli Workorder: Problem:	aled beam heargo door rear in Retest. Internal end alignment in the end	adlight due inop . Replant due ster ance all for meter: Walker 62	to water intrace latch and ering wheel our wheels Ni 53708	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00	Oil Ide Conce Refurbi Resis ded Bea	shed tor ams 255.46			1.00 7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sear Test side cate assemblies . For the cate and the cate a	aled beam heargo door rear in Retest. Internal alignment align speed balles Hou 1810178 No Start Contact: Eric 1215 Cherry red	adlight due inop . Replant due ster ance all for meter: Walker 62: Wypb To:	to water intrace latch and ering wheel our wheels Ni 53708	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00	Oil Ide Conce Refurbi Resis led Bea	shed tor ams 255.46 10/01/2018	Closed:	10/01/20	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sear right sear right sear right sear rest side can assemblies . For each rest drive Rotate and For each rest right ri	aled beam heargo door rear in Retest. Internal alignment align speed balles Hou 1810178 No Start Contact: Eric 1215 Cherry red	adlight due inop . Replant due ster ance all for meter: Walker 62	to water intrace latch and ering wheel our wheels Ni 53708	rusion. d cable off center . trofill all.	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00	Oil Ide Conce Refurbi Resis ded Bea	shed tor ams 255.46 10/01/2018		10/01/20	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sean - Test side can assemblies . For the rest drive Rotate and For the shop Suppliar - Shop Suppliar - Tow From: 4	aled beam heargo door rear in Retest. Internal alignment align speed balles Hou 1810178 No Start Contact: Eric 1215 Cherry red	adlight due inop . Replant due ster ance all for meter: Walker 62 l, Wpb To: rs 0.00 Meter:	to water intrace latch and ering wheel our wheels Ni 53708	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00	Oil Ide Conce Refurbi Resisi ded Bea s Parts:	shed tor ams 255.46 10/01/2018	Closed:	10/01/20	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sear - Test side can assemblies . For the rest drive Rotate and For the same supplies and the same supplies are restricted by the same supplies are	aled beam heargo door rear is Retest. Int end alignme high speed bales Hou: 1810178 No Start Contact: Erick 1215 Cherry rd Hou: 1810184 Towed in for ery fully . Test	adlight due inop . Replant due ster ance all for meter: Walker 62 I, Wpb To: rs 0.00 Meter: no start. battery and	to water intrace latch and ering wheel our wheels Ni 53708 8-4175 Lv shop	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00 In D	Oil Ide Conce Refurbi Resisi ded Bea s Parts:	shed tor ams 255.46 10/01/2018 0.00	Closed:	0.00	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor . - R&r right sea. - Test side ca assemblies . F. - Perform from Test drive. - Rotate and I. - Shop Suppli Workorder: Problem: - Tow From: 4 Workorder: Problem: - Charge batto	aled beam heargo door rear is Retest. Int end alignme high speed bales Hou: 1810178 No Start Contact: Erick 1215 Cherry rd Hou: 1810184 Towed in for ery fully . Test	adlight due inop . Replant due ster ance all for meter: Walker 62 I, Wpb To: rs 0.00 Meter: no start. battery and	to water intrace latch and ering wheel our wheels Ni 53708 8-4175 Lv shop	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00 In D	Oil Ide Conce Refurbi Resisi ded Bea s Parts:	shed tor ams 255.46 10/01/2018 0.00	Closed:	0.00	7.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1
resistor R&r right sear right sear right sear right sear rest side can assemblies . For each rest drive Rotate and For rest drive Shop Suppliable workorder: - Problem: - Tow From: 4	aled beam heargo door rear in Retest. Internal end alignment in the end i	adlight due inop . Replant due ster ance all for meter: Walker 62 I, Wpb To: rs 0.00 Meter: no start. battery and	to water intrace latch and ering wheel our wheels Ni 53708 8-4175 Lv shop	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00 In D Parts List Battery	Oil Ide Conce Refurbi Resist ded Bea s Parts: Parts:	shed tor ams 255.46 10/01/2018 0.00	Closed:	0.00	7.00 2.00 1.00 1.00 1.00 1.00 1.00
resistor R&r right sear Test side cate assemblies . For the Perform from Test drive Rotate and For the Shop Suppliaries Tow From: 4 Workorder: Problem: - Tow From: 4 Workorder: Problem: - Charge batter Battery failed I	aled beam heargo door rear in Retest. Internal end alignment in the end	adlight due inop . Replant due ster ance all for meter: Walker 62 I, Wpb To: rs 0.00 Meter: no start. battery and	to water intrace latch and ering wheel our wheels Ni 53708 8-4175 Lv shop	rusion. d cable off center . trofill all. Labor:	5w20 Engine 22" Wiper Bla Washer Fluid Used Fire X R Blower Motor Halogen Seal latch latch Shop Supplies 615.00 In D Parts List Battery Shop Supplies	Oil Ide Conce Refurbi Resisi ed Bea s Parts: Parts:	shed tor ams 255.46 10/01/2018 0.00	Closed: Total: Closed:	0.00	7.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1

Problem:	1811913 Coolant leak.	Meter:	54381		Ir	n Date:	11/21/2018	Closed:	11/29/20	018
- Leak test A/	c system ,recov	ver feon .re	eplace leaking		Parts List					Qty
evaperator coi	re, accumulato	r and orfic	e tube . Evacu		Freon Lv S	Shop 2				2.00
syetm and cor performance .	mplete recharge	e . Test for	leaks and		Wire Assy	'				1.00
- Shop Suppli					Evaporato	r Core				1.00
- Onop Suppli	163				A/c Accum					1.00
					Orifice Tub	e Filter				1.00
					Rapid Sea	l Kit				1.00
					Frig Oil					1.00
					Shop Supp	olies				1.00
	Hour :	s 5.80		Labor:	388.60	Parts:	515.45	Total:	904.05	
Workorder: Problem:	1901473 P.M. service.	Meter:	55204		İr	n Date:	02/07/2019	Closed:	02/20/20	019
- P.m. service) .				Parts List					Qty
- R&r both left	t and right brok	en motor r	mounts .		Napagold (Oil Filter				1.00
- Rotate and b	balance all four	tires . Nitr	ofill all.		5w20 Engi	ne Oil				7.00
- Shop Suppli	ies				Washer Flo	uid Conc	entr			1.00
					20" Wiper	Blade				2.00
					Napagold I	Fuel Filte	r			1.00
					Drv Tech E	Engine M	ount			1.00
					Drv Tech E	Engine M	ount			1.00
					Shop Supp	olies				1.00
	Hour	s 8.00		Labor:	536.00	Parts:	128.12	Total:	664.12	
	:									
	1905031 New "Hows m	Meter: y driving"	56400 sticker is need	led.	lr	n Date:	05/09/2019	Closed:	05/13/20	019
Problem:	1905031	y driving"	sticker is need			n Date:	05/09/2019	Closed:	05/13/20	019
Problem:	: 1905031 New "Hows m ng "hows my dr	y driving"	sticker is need			n Date: Parts:		Closed:		019
Problem: - Install missin	: 1905031 New "Hows m ng "hows my dr	y driving" riving " stices of the state of t	sticker is need ker to left rear 57454	bumper	6.70					
Problem: - Install missin Workorder: Problem: - P.m. service	: 1905031 New "Hows m ng "hows my dr Hour : 1907668 P.M. service a	y driving" riving " stice s 0.10 Meter: and check	sticker is need ker to left rear 57454 A/C .	bumper Labor:	6.70	Parts:	0.00	Total:	6.70	019 Qt y
Problem: - Install missin Workorder: Problem: - P.m. service - A/c performa	: 1905031 New "Hows m ng "hows my dr Hour : 1907668 P.M. service a	y driving" riving " stice s 0.10 Meter: and check	sticker is need ker to left rear 57454 A/C .	bumper Labor:	6.70 Ir Parts List 5w20 Engi	Parts: n Date: ne Oil	0.00	Total:	6.70	019 Qty 7.00
Problem: - Install missin Workorder: Problem: - P.m. service - A/c performation	: 1905031 New "Hows my dr "Hour": 1907668 P.M. service ance test . Test	y driving" riving " stice s 0.10 Meter: and check	sticker is need ker to left rear 57454 A/C .	bumper Labor:	6.70 Parts List 5w20 Engi Napagold	Parts: 1 Date: ne Oil Oil Filter	0.00	Total:	6.70	O19 Qty 7.00 1.00
Problem: - Install missin Workorder: Problem: - P.m. service - A/c performation of the colower motor Test and rep	: 1905031 New "Hows my dr "Hour": 1907668 P.M. service ance test . Test Retest .	y driving" riving " stices 0.10 Meter: and check blower circles strobe light	sticker is need ker to left rear 57454 A/C .	bumper Labor:	6.70 Parts List 5w20 Engi Napagold Used Fire	Parts: n Date: ne Oil Oil Filter X Refurb	0.00	Total:	6.70	O19 7.00 1.00 1.00
Problem: - Install missin Workorder: Problem: - P.m. service - A/c performation blower motor Test and repeplace blown	: 1905031 New "Hows my dr "Hour": 1907668 P.M. service ance test . Test	y driving" riving " stice s 0.10 Meter: and check blower circle strobe lighter	sticker is need ker to left rear 57454 A/C . Touit and replant bulb . Test a Retest .	bumper Labor:	6.70 Parts List 5w20 Engi Napagold Used Fire 22" Wiper	Parts: ne Oil Oil Filter X Refurb Blade	0.00 07/24/2019 ished	Total:	6.70	7.00 1.00 2.00
Problem: - Install missin Norkorder: Problem: - P.m. service - A/c performation of the problem	: 1905031 New "Hows my dr Hour : 1907668 P.M. service a e. ance test . Test Retest . blace right front fuse for cigare balance all four	y driving" riving " stice s 0.10 Meter: and check blower circle strobe lighter	sticker is need ker to left rear 57454 A/C . reuit and replant bulb . Test a Retest .	bumper Labor:	6.70 Parts List 5w20 Engi Napagold Used Fire 22" Wiper Ford Tritor	Parts: ne Oil Oil Filter X Refurb Blade n Pvc Sw	0.00 07/24/2019 ished	Total:	6.70	7.00 1.00 1.00 2.00 1.00
Problem: - Install missin Norkorder: Problem: - P.m. service - A/c performation of the problem	: 1905031 New "Hows my dr Hour : 1907668 P.M. service a e. ance test . Test Retest . blace right front fuse for cigare balance all four	y driving" riving " stice s 0.10 Meter: and check blower circle strobe lighter	sticker is need ker to left rear 57454 A/C . reuit and replant bulb . Test a Retest .	bumper Labor:	Parts List 5w20 Engi Napagold Used Fire 22" Wiper Ford Tritor Blower Mo	Parts: ne Oil Oil Filter X Refurb Blade n Pvc Swetor Assy	0.00 07/24/2019 ished	Total:	6.70	7.00 1.00 1.00 2.00 1.00
Problem: - Install missin Workorder: Problem: - P.m. service - A/c performation of the problem	: 1905031 New "Hows my dr Hour : 1907668 P.M. service a e. ance test . Test Retest . blace right front fuse for cigare balance all four	y driving" riving " stice s 0.10 Meter: and check blower circle strobe lighter	sticker is need ker to left rear 57454 A/C . reuit and replant bulb . Test a Retest .	bumper Labor:	6.70 Parts List 5w20 Engi Napagold Used Fire 22" Wiper Ford Tritor Blower Mo Hide Away	Parts: ne Oil Oil Filter X Refurb Blade n Pvc Switor Assy	0.00 07/24/2019 ished	Total:	6.70	7.00 1.00 1.00 1.00 1.00 1.00
Workorder: Problem: - P.m. service - A/c performation motor Test and repreplace blown	: 1905031 New "Hows my dr Hour : 1907668 P.M. service a a. ance test . Test Retest . blace right front fuse for cigare balance all four	y driving" riving " stice s 0.10 Meter: and check blower circle strobe lighter	sticker is need ker to left rear 57454 A/C . reuit and replant bulb . Test a Retest .	Labor:	Parts List 5w20 Engi Napagold Used Fire 22" Wiper Ford Tritor Blower Mo	Parts: ne Oil Oil Filter X Refurb Blade n Pvc Switor Assy	0.00 07/24/2019 ished	Total:	6.70	019 Qty 7.00

Workorder: Problem:	1909053 A/C blows o	Meter: ut defrost ve	57462 ents at times	and right	front strol	In Date: be inop.	08/29/2019	Closed:	09/09/2019
- A/c performa check valve au - Shop Supplie	nd vacuum h			tank and	Parts Li A/c Valv	е			Q 1.0
отор опри						Resevoir			1.0
	Ho	urs 4.40		Labor:	Shop Su 294.80		31.76	Total:	1.0 326.56
Workorder:	2000609	Meter:	59166			In Date:	01/17/2020	Closed:	01/30/2020
	PM Service,					in Date.	01/17/2020	Oloscu.	01/30/2020
- P.m. service	<u>.</u>				Parts Li	st			Q
- Replace two	tires . Balan	ce and rotat	e all four tire	s . Nitrofill	Drain Pl	ug			1.0
all.					Napagol	d Oil Filter			1.0
- Diagnose no					5w20 Er	ngine Oil			7.0
belt and tensio Relocate exha					Napagol	d Fuel Filte		1.0	
Road test .		,	,		Napagol	d Air Filter			1.0
- Shop Supplie	es				20" Wipe	er Blade			2.0
					Lt245/75	5/16 Tire Mi	С		2.0
					Idler Pul	ley			1.0
					Dr Blt Te	ensioner As	sy		1.0
					Belt				1.0
					Shop Su	ıpplies			1.0
					Tire Disp	osal Fee			2.0
	Ho	urs 7.80		Labor:	569.40	Parts:	611.92	Total:	1,181.32
Workorder: Problem:	2003161 Transition P	Meter: rep Charge	59812			In Date:	03/27/2020	Closed:	03/27/2020
- Transition Pr	ep Charge								
		urs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00