

**Palm Beach County Fleet Management
Asset Maintenance History**

10175091 2009 FORD F350 Utility Body, 1 Ton, W/ Vise, Tow Pkg

Workorder: 936890 **Meter:** 0 **In Date:** 04/22/2009 **Closed:** 04/22/2009
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
:

Workorder: 944912 **Meter:** 2354 **In Date:** 10/22/2009 **Closed:** 10/30/2009
Problem: PM SERVICE

| | Parts List | Qty |
|-------------------------------|---|------------|
| - P.m.service | Shop Supplies | 1.00 |
| - Unsieze & Lube Vise | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Tighten Body Bolts | Cs10263 Fuel Filter (use Cs10263a) | 1.00 |
| - Repair Ground For Tag Light | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| - Shop Supplies | 15/40 Oil | 15.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| Hours 7.00 | Labor: 420.00 Parts: 236.97 Total: 656.97 | |
| : | | |

Workorder: 1004651 **Meter:** 4770 **In Date:** 05/05/2010 **Closed:** 05/10/2010
Problem: P. M. SERVICE

| | Parts List | Qty |
|--|---|------------|
| - P. M. | Shop Supplies | 1.00 |
| - Take down light out, disassembled light bar & repaired connection to bulb. | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Repaired ground to body light. Remove triple gang light assy & repaired ground, & reinstalled. | Cs10263 Fuel Filter (use Cs10263a) | 1.00 |
| - Unsiezed & lubed vise & hook assy. | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| - Retightened body bolts. | 15/40 Oil | 15.00 |
| - Installed driving sticker. | | |
| - Shop Supplies | | |
| Hours 9.25 | Labor: 555.00 Parts: 215.64 Total: 770.64 | |
| : | | |

Workorder: 1010001 **Meter:** 6840 **In Date:** 09/13/2010 **Closed:** 09/13/2010
Problem: Vehicle stalled, won't re-start

- From: Wud, Hagen Ranch & Woolbright To: Sr Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1010003 **Meter:** 6840 **In Date:** 09/13/2010 **Closed:** 09/13/2010
Problem: Vehicle stalled, won't re-start

- From: Wud, Hagen Ranch & Woolbright To: Sr Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---|----------------------------|---------------------------|
| Workorder: 1010006 | Meter: 7270 | In Date: 09/13/2010 | Closed: 09/15/2010 |
| Problem: Truck stalled & will not start | | | |
| - Travel to Woolbright to check broken down vehicle. | Parts List | | Qty |
| - Check vehicle, won't start, perform pinpoint test & found vehicle out of fuel. Return to shop for fuel, fuel vehicle & bleed air from system. Test drive. | Shop Supplies | | 1.00 |
| - Shop Supplies | | | |
| Hours 4.00 | Labor: 240.00 | Parts: 2.00 | Total: 242.00 |
| : | | | |
| Workorder: 1010152 | Meter: 7370 | In Date: 09/16/2010 | Closed: 09/24/2010 |
| Problem: Needs pintle pin | | | |
| - C/c: Needs pintle pin. Verify. Install pintle pin. | Parts List | | Qty |
| | 18410 Pintle Pin | | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 1.98 | Total: 16.98 |
| : | | | |
| Workorder: 1010196 | Meter: 7270 | In Date: 09/16/2010 | Closed: 09/16/2010 |
| Problem: Vehicle broke down, won't run, & dash panel will not light up. | | | |
| - From: Wud, So.co.reg.pk, by Cypress Pavillion Shop | To: Sr | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1010198 | Meter: 7421 | In Date: 09/16/2010 | Closed: 09/29/2010 |
| Problem: Towed in, stalled out, won't start. | | | |
| - Bleed system through lower filter housing & upper housing. Fueled both tanks up, road tested (ran out of fuel). | Parts List | | Qty |
| - Installed lap top for codes, no applicable codes. | Shop Supplies | | 1.00 |
| - Shop Supplies | | | |
| Hours 4.00 | Labor: 240.00 | Parts: 2.00 | Total: 242.00 |
| : | | | |
| Workorder: 1012217 | Meter: 7743 | In Date: 11/01/2010 | Closed: 11/18/2010 |
| Problem: P. M., & Check Gas gauge, not working, sucks gas out of front tank only | | | |
| - P. M. | Parts List | | Qty |
| - Repaired two body light grounds & wiring to backup. | Shop Supplies | | 1.00 |
| - Disassembled light bar & repaired wiring to alley light. | 7312 Oil Filterfrm Ch9549 Wix 57312 | | 1.00 |
| - Unsiezed & lubed vise & hitch. | Cs10263 Fuel Filter (use Cs10263a) | | 1.00 |
| - Retightened body hold downs, replaced one. | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | | 1.00 |
| - Tire repair. | 15/40 Oil | | 15.00 |
| - Shop Supplies | Used Firex Refurbed Fire Extingshers | | 1.00 |
| | 31-22 Wiper Blades 22" Wiper Blade | | 2.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 151.33 | Total: 721.33 |
| : | | | |
| Workorder: 1100316 | Meter: 9119 | In Date: 01/07/2011 | Closed: 01/14/2011 |
| Problem: ROAD CALL, RAN OUT OF FUEL | | | |
| - C/s: Vehicle ran out of fuel. Travel to vehicle, add fuel, bleed air from system, & test drive. | Parts List | | Qty |
| - Shop Supplies | Shop Supplies | | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---|----------------------------|---------------------------|
| Workorder: 1100427 | Meter: 9256 | In Date: 01/11/2011 | Closed: 02/28/2011 |
| Problem: WILL NOT DRAW FUEL FROM THE REAR TANK | | | |
| - Dealer to replace rear fuel tank sender unit & selector valve. | Parts List | | Qty |
| | Shop Supplies | | 1.00 |
| - Transport & pick up vehicle at dealer. (engine won't accept fuel from rear tank when running on rear tank front tank goes empty). | | | |
| - Shop Supplies | | | |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
| : | | | |
| Workorder: 1104185 | Meter: 10859 | In Date: 04/18/2011 | Closed: 04/20/2011 |
| Problem: Need Pintle Pin | | | |
| - Replaced pintle pin. | Parts List | | Qty |
| | 18410 Pintle Pin | | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 1.98 | Total: 16.98 |
| : | | | |
| Workorder: 1105288 | Meter: 11540 | In Date: 05/18/2011 | Closed: 05/18/2011 |
| Problem: 1 - Key(s) issued | | | |
| - 1 - Key(s) issued | Parts List | | Qty |
| | Duplicate Vehicle Keys | | 1.00 |
| Hours 0.20 | Labor: 12.00 | Parts: 3.00 | Total: 15.00 |
| : | | | |
| Workorder: 1105314 | Meter: 11567 | In Date: 05/18/2011 | Closed: 05/27/2011 |
| Problem: P. M. SERVICE | | | |
| - Performed service. | Parts List | | Qty |
| - Repaired grounds for body lights. | Shop Supplies | | 1.00 |
| - Disassembled light & repaired connections & tightened. | 7312 Oil Filterfrm Ch9549 Wix 57312 | | 1.00 |
| - Tire repair. | 3963 Fuel Filter Frm Cs10263a Wix 33963 | | 1.00 |
| - Unsiezed & lubed vise. | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | | 1.00 |
| - Retightened body bolts. | 15/40 Oil | | 16.00 |
| - Shop Supplies | 31-22 Wiper Blades 22" Wiper Blade | | 2.00 |
| Hours 8.50 | Labor: 510.00 | Parts: 136.38 | Total: 646.38 |
| : | | | |
| Workorder: 1110330 | Meter: 15448 | In Date: 09/27/2011 | Closed: 09/29/2011 |
| Problem: ENGINE LIGHT COMES ON AND OFF. | | | |
| - Transport &pick Up Veh. At Dealer For Warranty Repairs. | Parts List | | Qty |
| - Dealer To Reprogram The Pcm/tcm/ic. | Shop Supplies | | 1.00 |
| - Shop Supplies | | | |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
| : | | | |
| Workorder: 1111487 | Meter: 16500 | In Date: 10/31/2011 | Closed: 10/31/2011 |
| Problem: Need pintle pin | | | |
| - Replace pintle pin. | Parts List | | Qty |
| | 18410 Pintle Pin | | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 1.98 | Total: 16.98 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1113228 **Meter:** 18132 **In Date:** 12/16/2011 **Closed:** 12/30/2011
Problem: P. M. SERVICE

| | | |
|---|---|-----------------|
| - P. M. Service. | Parts List | Qty |
| - Replace 6 tires & fill with nitrogen. | Shop Supplies | 1.00 |
| - Service & adjust ladder rack. | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Adjust & tighten tail gate bolts. | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| - Transport & pick up vehicle at dealer. (defective front crank seal & low pressure oil pump gasket). | 15/40 Oil | 16.00 |
| - Shop Supplies | Used Firex Refurbed Fire Extingshers | 1.00 |
| | 179636492 Lt245/75r17 Wrangler Sr-a E | 6.00 |
| | Tire Disposal Fee | 6.00 |
| Hours 11.50 | Labor: 690.00 | Parts: 1,310.82 |
| : | | Total: 2,000.82 |

Workorder: 1203462 **Meter:** 22514 **In Date:** 04/12/2012 **Closed:** 04/20/2012
Problem: dead battery, ck ac system turn on and off

| | | |
|---|-------------------|---------------|
| - test charging and starting sys battery failed load test after recharg send vehicle to dealer for battery warranty | Parts List | Qty |
| - transport and pick up vehicle at deler for battery warrenty | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

Workorder: 1204540 **Meter:** 23573 **In Date:** 05/14/2012 **Closed:** 05/16/2012
Problem: pm service, pinal pin

| | | |
|--|---|---------------|
| - pm service | Parts List | Qty |
| - installed pinal pin and unseized and lubed hook and vise | Shop Supplies | 1.00 |
| - repaired ground for running light also repaired open wire to marker | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - repaired connection to take down line in light bar | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| - tighten body hold downs | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| - repired l/r tire | 15/40 Oil | 16.00 |
| - ck ac operation ck pressure rd tested 440 at idle & 44 driving ambient temp 82 no problem at this time | 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| - Shop Supplies | 18411 Pinal Pin, 2 3/4" New # 66063 | 1.00 |
| Hours 10.50 | Labor: 630.00 | Parts: 134.41 |
| : | | Total: 764.41 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1209130 **Meter:** 28185 **In Date:** 09/24/2012 **Closed:** 09/27/2012
Problem: pm, ac does not cool

| | Parts List | | | Qty |
|--|---|---------------|---------------|---------------|
| - pm | | | | |
| - reopen center brake light socket replaced grounds for two running lights | Shop Supplies | | | 1.00 |
| - disassembled light bar repaired wiring to alley light repaired connection to take down light | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | | | 1.00 |
| - unsiezed and lubed hook and vise | 3963 Fuel Filter Frm Cs10263a Wix 33963 | | | 1.00 |
| - tightened body bolts | 7312 Oil Filterfrm Ch9549 Wix 57312 | | | 1.00 |
| - tire repaired right rear tire | 15/40 Oil | | | 16.00 |
| - battery failed load recharged retested and passed | 1066 White Lithium (crc 05037) | | | 1.00 |
| - checked ac operation 44 deg at pressure both at idle good road tested ac no problem found | 31-22 Wiper Blades 22" Wiper Blade | | | 2.00 |
| - Shop Supplies | | | | |
| | Hours 12.50 | Labor: 750.00 | Parts: 138.41 | Total: 888.41 |
| | : | | | |

Workorder: 1211679 **Meter:** 29309 **In Date:** 12/04/2012 **Closed:** 12/07/2012
Problem: PINTLE PIN

| | Parts List | | | Qty |
|----------|-------------------|--------------|-------------|--------------|
| - rr pin | Lock Pin | | | 1.00 |
| | Hours 0.50 | Labor: 30.00 | Parts: 1.44 | Total: 31.44 |
| | : | | | |

Workorder: 1300614 **Meter:** 30748 **In Date:** 01/16/2013 **Closed:** 03/22/2013
Problem: over heating, yellow light on, turbo kicks on and off, ac 1/2 way

| | Parts List | | | Qty |
|---|-------------------|--------------|-------------|--------------|
| - transport and pick up vehicle at dealer replace upper and lower rad hose and thermostat | Shop Supplies | | | 1.00 |
| - Shop Supplies | | | | |
| | Hours 1.50 | Labor: 90.00 | Parts: 2.00 | Total: 92.00 |
| | : | | | |

Workorder: 1302546 **Meter:** 30748 **In Date:** 03/13/2013 **Closed:** 03/22/2013
Problem: P.M.SERVICE

| | Parts List | | | Qty |
|--|-----------------------|---------------|---------------|-----------------|
| - pm | | | | |
| - repaired grounds for running light | Napagold Air Filter | | | 1.00 |
| - repaired connectin at switch in control box | Napagold Oil Filter | | | 1.00 |
| - unseized and lubed vise hitch | Napagold Fuel Filter | | | 1.00 |
| - tighened body mounts | 15w40 Bulk South Reg | | | 16.00 |
| - straightened tail gate alignment and adj striker | 31-22 Wiper Blades 22 | | | 2.00 |
| - rr and balance two tires | Used Firex Refurbed F | | | 1.00 |
| - tire repair r rear | 179636492 Lt245-75r17 | | | 2.00 |
| - Shop Supplies | Shop Supplies | | | 1.00 |
| | Tire Disposal Fee | | | 2.00 |
| | Hours 10.75 | Labor: 645.00 | Parts: 652.04 | Total: 1,297.04 |
| | : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---------------------|----------------------------|---------------------------|
| Workorder: 1308804 | Meter: 35198 | In Date: 08/30/2013 | Closed: 08/30/2013 |
| Problem: wont fuel | | | |
| - install shorter screws for plug and zip tie back up underneath the dash and repair connections | | Parts List | Qty |
| - Shop Supplies | | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 | Total: 62.00 |
| : | | | |
| Workorder: 1309604 | Meter: 35986 | In Date: 09/23/2013 | Closed: 09/24/2013 |
| Problem: wont fuel | | | |
| - Test and remove canceiver | | Parts List | Qty |
| - Shop Supplies | | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 | Total: 62.00 |
| : | | | |
| Workorder: 1309708 | Meter: 36276 | In Date: 09/25/2013 | Closed: 10/04/2013 |
| Problem: pm | | | |
| - pm | | Parts List | Qty |
| - repaired two groiunds for lights | | Napagold Air Filter | 1.00 |
| - disassembled light bar repaired wiring for both alley lights | | Napagold Oil Filter | 1.00 |
| - unsiezed and lubed hitch and vise | | Napagold Fuel Filter | 1.00 |
| - removed shock and straightened mounts and reinstalled shock | | 15-40 Oil | 16.00 |
| - rr and balanced two tires | | Wiper Blade | 2.00 |
| - tire repair lr tire | | Washer FI | 1.00 |
| - Shop Supplies | | 179636492 Lt245-75r17 | 2.00 |
| | | 15w40 Bulk South Reg | 16.00 |
| | | Shop Supplies | 1.00 |
| | | Tire Disposal Fee | 2.00 |
| Hours 11.00 | Labor: 660.00 | Parts: 680.28 | Total: 1,340.28 |
| : | | | |
| Workorder: 1310061 | Meter: 36583 | In Date: 10/04/2013 | Closed: 10/23/2013 |
| Problem: truck blew fuse for tariler hook up | | | |
| - ck truck has blown fuse for trailer plug verify concern perform pin point test and found shorted wire harness under truck and blown fuse repair wire harness and replace fuse | | Parts List | Qty |
| - Shop Supplies | | Shop Supplies | 1.00 |
| Hours 2.50 | Labor: 150.00 | Parts: 2.00 | Total: 152.00 |
| : | | | |
| Workorder: 1312332 | Meter: 38213 | In Date: 12/11/2013 | Closed: 12/17/2013 |
| Problem: pintal pin | | | |
| - replace pintle pin | | Parts List | Qty |
| | | Pintle Pin W/chain | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 2.61 | Total: 17.61 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1404419 **Meter:** 41669 **In Date:** 05/06/2014 **Closed:** 05/19/2014
Problem: pm ,

| | Parts List | Qty |
|---|-------------------------|-----------------|
| - pm | | |
| - repaired grounds for running lights rr bulb for cargo light rr bulb for clip light | Napagold Air Filter | 1.00 |
| - disassebled light repaired connection at coil and light assy | Fuel Filter Ford Only | 1.00 |
| - removed tank skid plate lowered tank to access hose tightened clamp and reinstalled | Napagold Oil Filter | 1.00 |
| - unsiezed and lubed vise and hook | 15w40 Bulk South Reg | 16.00 |
| - rr and balanced two tires | Wiper Blade | 2.00 |
| - tire repair and r rear | Washer FI | 1.00 |
| - removed fender well to access washer bottle repaired line to bottle and reinstalled | Used Fire X Refurbished | 1.00 |
| - Shop Supplies | 179636492 Lt245-75r17 | 2.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 14.00 | Labor: 840.00 | Parts: 693.30 |
| : | | Total: 1,533.30 |

Workorder: 1408444 **Meter:** 44250 **In Date:** 08/25/2014 **Closed:** 08/29/2014
Problem: pintle pin

| | Parts List | Qty |
|----------------------|--------------------|--------------|
| - replace pintle pin | | |
| | Pintle Pin W/chain | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 2.61 |
| : | | Total: 17.61 |

Workorder: 1410446 **Meter:** 45210 **In Date:** 10/20/2014 **Closed:** 10/23/2014
Problem: P.M.SERVICE

| | Parts List | Qty |
|---|-----------------------|-----------------|
| - pm | | |
| - rr running light assy repaired two grounds for rear running lights | Napagold Air Filter | 1.00 |
| - repaired bracket for light bar and reattached | Fuel Filter Ford Only | 1.00 |
| - un siezed and lubed vice and hook | Napagold Oil Filter | 1.00 |
| - repaired lr tire | 15w40 Bulk South Reg | 16.00 |
| - removed shock straightened mount and reinstalled shock | Wiper Blade | 2.00 |
| - rr all engine idler pulleys and tensioners repaired all pieces of old belt behind pumps and dampiners | Washer FI | 1.00 |
| - rr belts | M C Lamp | 1.00 |
| - Shop Supplies | Idler Pulley Smooth | 1.00 |
| | Idler Pulley | 1.00 |
| | Belt Tensioner | 1.00 |
| | Belt Tensioner | 1.00 |
| | Drive Belt | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 18.00 | Labor: 1,080.00 | Parts: 569.92 |
| : | 0 | Total: 1,649.92 |

Workorder: 1503242 **Meter:** 48481 **In Date:** 03/30/2015 **Closed:** 03/31/2015
Problem: dead battery

| | Parts List | Qty |
|--|-------------------|---------------|
| - ck dean battery test batteries bad ck charging sys replace two batteries | | |
| | Battery | 2.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 238.82 |
| : | | Total: 358.82 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504096 **Meter:** 48985 **In Date:** 04/21/2015 **Closed:** 04/23/2015
Problem: pm

| | | |
|---|-------------------------|-----------------|
| - pm | Parts List | Qty |
| - repaired open in cabinet and repaired grounds | Napagold Air Filter | 1.00 |
| - repaired wiring to switch | Napagold Oil Filter | 1.00 |
| - rr frt and rear brakes and remove shell rock from componets parts | Fuel Filter Ford Only | 1.00 |
| | 15w40 Bulk South Reg | 16.00 |
| - rr two tires and balanced | Wiper Blade | 2.00 |
| - repaired l rear tire | Used Fire X Refurbished | 1.00 |
| - removed door panel and adj and lubed and reattached assy | Brake Pads | 1.00 |
| - lubed hook and unsiezed lubed vise | Brake Pad | 1.00 |
| - Shop Supplies | B Fluid Dot 3-32oz | 1.00 |
| | Brake Cleaner | 2.00 |
| | 179636492 Lt245-75r17 | 2.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 21.00 | Labor: 1,260.00 | Parts: 901.68 |
| : | 0 | Total: 2,161.68 |

Workorder: 1506362 **Meter:** 50432 **In Date:** 06/25/2015 **Closed:** 06/30/2015
Problem: pintle pin

| | | |
|-------------------------------|--------------------|--------------|
| - install pintle pin on hitch | Parts List | Qty |
| | Pintle Pin W/chain | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 2.61 |
| : | | Total: 17.61 |

Workorder: 1510689 **Meter:** 53186 **In Date:** 10/22/2015 **Closed:** 10/29/2015
Problem: pm

| | | |
|--|-----------------------|-----------------|
| - pm | Parts List | Qty |
| - repaired socket and wire to center brake repaired grounds for runnig light | Napagold Air Filter | 1.00 |
| | Napagold Oil Filter | 1.00 |
| - disassembled light bar and repaired connections to pack | Fuel Filter Ford Only | 1.00 |
| - rr two tires | 15w40 Bulk South Reg | 16.00 |
| - tire repair | Wiper Blade | 2.00 |
| - unsiezed lubed hitch | 179636492 Lt245-75r17 | 2.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 9.50 | Labor: 570.00 | Parts: 694.53 |
| : | | Total: 1,264.53 |

Workorder: 1511928 **Meter:** 53717 **In Date:** 11/23/2015 **Closed:** 11/30/2015
Problem: SCREW IN L/REAR OUTER TIRE

| | | |
|---|-------------------|--------------|
| - lr tire repair mojnt and balance nitro all ck all tires | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1600365 **Meter:** 54918 **In Date:** 01/12/2016 **Closed:** 01/15/2016
Problem: pintle pins

| | | |
|----------------------|-------------------|--------------|
| - install pintle pin | Parts List | Qty |
| | Lock Pin | 1.00 |
| Hours 0.50 | Labor: 30.00 | Parts: 1.44 |
| : | | Total: 31.44 |

Workorder: 1603814 **Meter:** 57232 **In Date:** 04/12/2016 **Closed:** 04/26/2016
Problem: Pm service.

| | | |
|---|-----------------------|---------------|
| - Pm service. | Parts List | Qty |
| - Repaired ground for running lights and repaired socket for cargo light. | Napagold Air Filter | 1.00 |
| - Repaired feed wire for light bar. | Fuel Filter Ford Only | 1.00 |
| - Repaired right rear tire. | Napagold Oil Filter | 1.00 |
| - Unseized and lube vise and hook. | 15w40 Bulk South Reg | 16.00 |
| - Readjust cabinet door and latch assy. | U-groove Spark Plug | 1.00 |
| - Shop Supplies | Washer Fluid Concentr | 1.00 |
| | 22" Wiper Blade | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 9.00 | Labor: 540.00 | Parts: 190.34 |
| : | | Total: 730.34 |

Workorder: 1606354 **Meter:** 59707 **In Date:** 06/22/2016 **Closed:** 09/26/2016
Problem: Check engine light on and runs rough

| | | |
|---|-----------------------|-----------------|
| - Diagnose for engine noise.r&r both valve covers and replace eight worn rocker arms,injector lines and harness also replace four bridges | Parts List | Qty |
| - Diagnose for no fuel transfer pressure.replace defective fuel condition module and fuel rail pressure sensor. | Roacker Arm | 8.00 |
| - Diagnose for excessive exhaust back pressure.remove exhaust system.dismantle and clean D.p.f.perform Regen. with scan tool. | Injector Harness | 1.00 |
| - Computer diagnose for check engine light on.code P0187.too low fuel line pressure.test and replace bad starter assy.replace defective high pressure fuel pump assembly and gaskets.clear code with scan tool and road test. | Gasket Kit | 1.00 |
| - Shop Supplies | Valve Guide Kit | 4.00 |
| | Injector Tube | 4.00 |
| | Pump | 1.00 |
| | Cover | 1.00 |
| | Fuel Filter Ford Only | 1.00 |
| | Reman Starter | 1.00 |
| | Exha | 1.00 |
| | Napagold Oil Filter | 1.00 |
| | 15w40 Bulk South Reg | 16.00 |
| | Pump Asy | 1.00 |
| | Sensor | 1.00 |
| | Hardware | 1.00 |
| | Washer | 4.00 |
| | Exhaust Gasket | 3.00 |
| | Gasket | 2.00 |
| | Stg Wheel Cov - Ford | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 37.50 | Labor: 2,250.00 | Parts: 3,113.41 |
| : | 0 | Total: 5,363.41 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610826 **Meter:** 60994 **In Date:** 10/20/2016 **Closed:** 11/21/2016
Problem: PM service.Flat rear tires.

| | | |
|---|---|---|
| <ul style="list-style-type: none"> - Pm service. - Repair utility bedlight and tag light. - Replace left head light. - Erplace two left rear tires.rotate to the fronts. - Replace damage tail.gate with good used one and adjust tailgate. - Travel to Vista to swap out damage tailgate for good used one. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Fuel Filter Ford Only Napagold Oil Filter 15w40 Bulk South Reg Washer Fluid Concentr 22" Wiper Blade Used Fire X Refurbished Floor Mat-2pc Rub Bk Bulb Bulb Halogen Lamp 179636492 Lt245-75r17 Cement Tfx Brs1 Repair Seal Shop Supplies Tire Disposal Fee | <p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 16.00 1.00 2.00 1.00 1.00 2.00 2.00 1.00 2.00 1.00 1.00 2.00 |
| <p>Hours 10.50 :</p> | <p>Labor: 630.00 Parts: 746.10 Total: 1,376.10</p> | |

Workorder: 1703168 **Meter:** 66689 **In Date:** 03/30/2017 **Closed:** 04/10/2017
Problem: PM Service

| | | |
|---|---|---|
| <ul style="list-style-type: none"> - Pm Service. - Fabricate and replace three piece clearance light bar. - Rotate and balance all six tires. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Napagold Air Filter Napagold Oil Filter Fuel Filter Ford Only 15w40 Bulk South Reg 22" Wiper Blade Washer Fluid Concentr Used Fire X Refurbished Led Id Bar 6 Ctrs Shop Supplies | <p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 1.00 16.00 2.00 1.00 1.00 1.00 1.00 |
| <p>Hours 6.50 :</p> | <p>Labor: 390.00 Parts: 251.99 Total: 641.99</p> | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709127 **Meter:** 72415 **In Date:** 09/21/2017 **Closed:** 09/29/2017
Problem: PM Service.Check for noise under vehicle

| | Parts List | Qty |
|---|-------------------------|-----------------|
| - Pm Service | Used Fire X Refurbished | 1.00 |
| - Replace right brake/tail lamp. | Napagold Air Filter | 1.00 |
| - Replace six body mounts. | Napagold Oil Filter | 1.00 |
| - Mount four tires.rotate and balance six. | 15w40 Bulk South Reg | 16.00 |
| - Replace brake pedal pad. | Fuel Filter Ford Only | 1.00 |
| - Repair left middle cabinet ,catch latch was missing.replace catch with new bolt and nut.adjust to close properly. | 22" Wiper Blade | 2.00 |
| - Perform battery service on both batteries and clean trays. | Washer Fluid Concentr | 1.00 |
| - Shop Supplies | Wd40 Spr | 1.00 |
| | Led Sup Mdl 44 42 Dio | 1.00 |
| | Body Mount Kit | 2.00 |
| | Body Mount Kit | 4.00 |
| | 179636492 Lt245-75r17 | 4.00 |
| | Pedal Pad | 1.00 |
| | Dewalt Saw Blades | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 19.75 | Labor: 1,185.00 | Parts: 1,825.69 |
| : | 0 | Total: 3,010.69 |

Workorder: 1804360 **Meter:** 76930 **In Date:** 04/26/2018 **Closed:** 05/14/2018
Problem: PM Service

| | Parts List | Qty |
|---|-----------------------|-----------------|
| - Pm Service. | Napagold Air Filter | 1.00 |
| - Replace roof marker lamp bulb also right side cabinet front yellow and rear red marker lamps with base. drill out and rivet in new lamps. | Napagold Oil Filter | 1.00 |
| - Replace hydrobooster and top off power steering fluid. | 15w40 Bulk South Reg | 16.00 |
| - Rotate and balance six tires. | Fuel Filter Ford Only | 1.00 |
| - Replace missing bolts to vise.service and lube vise. | 22" Wiper Blade | 2.00 |
| - Shop Supplies | Washer Fluid Concentr | 1.00 |
| | Boxed Miniatures | 2.00 |
| | Mount | 2.00 |
| | M C Base Mount Kit | 1.00 |
| | M C Base Mount Kit | 1.00 |
| | Reman Brake Booster | 1.00 |
| | Syn Atf Bulk South | 2.00 |
| | Non-chlor Brake Clnr | 1.00 |
| | M C Lamp | 1.00 |
| | M C Lamp | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 12.50 | Labor: 750.00 | Parts: 368.57 |
| : | | Total: 1,118.57 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1806006 **Meter:** 77810 **In Date:** 06/12/2018 **Closed:** 06/18/2018
Problem: Right rear outside tire flat.

- Repair and balance right rear out side tire.nitrogen fill all. **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1806409 **Meter:** 78175 **In Date:** 06/22/2018 **Closed:** 07/23/2018
Problem: BATTERY BLEW UP

- Replace two batteries and check starting and charging system.wash and clean off acid spilled in engine compartment. **Parts List** **Qty**
Battery 2.00
- Shop Supplies Shop Supplies 1.00

Hours 2.50 Labor: 150.00 Parts: 259.28 Total: 409.28
:

Workorder: 1809260 **Meter:** 80326 **In Date:** 09/10/2018 **Closed:** 09/18/2018
Problem: Broken pintle pin .Trailer lights not working.

- Replace broken hitch pin **Parts List** **Qty**
- Repair wiring for truck lights and replace open fuses Pintle Pin W/clip 1.00
- Shop Supplies Atc30 5.00
Atc-30 Fuse 5.00
Shop Supplies 1.00

Hours 2.75 Labor: 165.00 Parts: 15.56 Total: 180.56
:

Workorder: 1812091 **Meter:** 82635 **In Date:** 11/28/2018 **Closed:** 11/30/2018
Problem: HEAD LIGHTS AND R/REAR SIGNAL LIGHT INOP.

- Repair both head light and right rear turnsignal light. **Parts List** **Qty**
- Shop Supplies Led Sup Mdl 44 42 Dio 1.00
Halogen Sealed Beams 2.00
Shop Supplies 1.00

Hours 2.50 Labor: 167.50 Parts: 84.60 Total: 252.10
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1901129 **Meter:** 85496 **In Date:** 01/30/2019 **Closed:** 02/28/2019
Problem: PM Service.Drain water seperator message on dash.

| | | |
|--|-------------------------|-----------------|
| - Pm Service. | Parts List | Qty |
| - Mount two tires.rotate and balance 6 tires. | Used Fire X Refurbished | 1.00 |
| - Replace left rear Led brake lamp. | Napagold Air Filter | 1.00 |
| - R and R and recondition fuel condition module. | 15w40 Bulk South Reg | 16.00 |
| - Vacume debris from engine compartment. | Napagold Oil Filter | 1.00 |
| - Shop Supplies | Fuel Filter Ford Only | 1.00 |
| | Washer Fluid Concentr | 1.00 |
| | 22" Wiper Blade | 2.00 |
| | 179636492 Lt245-75r17 | 2.00 |
| | Led Sup Mdl 44 42 Dio | 1.00 |
| | Seal Kit | 1.00 |
| | Napagold Air Filter | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 11.75 | Labor: 787.25 | Parts: 836.77 |
| : | | Total: 1,624.02 |

Workorder: 1906063 **Meter:** 85496 **In Date:** 06/10/2019 **Closed:** 07/22/2019
Problem: No Power

| | | |
|---|-------------------|---------------|
| - Computer diagnose with lds.reset fuel controls with lds and clean fuel lines and filter housings. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.50 | Labor: 234.50 | Parts: 3.00 |
| : | | Total: 237.50 |

Workorder: 1909857 **Meter:** 85496 **In Date:** 09/24/2019 **Closed:** 10/31/2019
Problem: PM Service

| | | |
|---|-----------------------|---------------|
| - Pm Service. | Parts List | Qty |
| - Repair right front tire.rotate and balance all six. | Napagold Oil Filter | 1.00 |
| - Remove and clean fuel condition module. | 15w40 Bulk South Reg | 16.00 |
| - Shop Supplies | Fuel Filter Ford Only | 1.00 |
| | Washer Fluid Concentr | 1.00 |
| | Wd40 Spr | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 8.00 | Labor: 584.00 | Parts: 164.25 |
| : | | Total: 748.25 |

Workorder: 1912077 **Meter:** 85283 **In Date:** 11/21/2019 **Closed:** 11/25/2019
Problem: Right rear inside tire flat.

| | | |
|---|-------------------|--------------|
| - Repaired and balance right rear inner tire. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 73.00 | Parts: 4.00 |
| : | | Total: 77.00 |

Workorder: 2000649 **Meter:** 85496 **In Date:** 01/17/2020 **Closed:** 01/17/2020
Problem: Transition Prep Charge

| | | |
|--------------------------|---------------|---------------|
| - Transition Prep Charge | | |
| Hours 2.00 | Labor: 146.00 | Parts: 0.00 |
| : | | Total: 146.00 |