



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V417

In Date: 11/02/2005
Close Date: 11/03/2005

Meter Reading:

Problem?

LIGHT INOP, ON D/SIDE STEAMER PANEL, NOISE IN FRONT END, MISSING 220 MALE TO 110 FEMALE CORD, RE-18

Task performed:

Parts	Quantity
03W125FLASHER HEADLIGHT	1
52-624SWITCH DOOR	1
87141USE LED MAP LIGHT 24"	1

Workorder: V427

In Date: 11/01/2005
Close Date: 11/04/2005

Meter Reading:

Problem?

A INSPECTION CHECK BRAKES RE18

Task performed:

Parts	Quantity
ACX-8453LUG CAPS WHEELED COACH # CH27321 OLD	1

Workorder: V574

In Date: 11/18/2005
Close Date: 11/22/2005

Meter Reading:

Problem?

rear sign off,needs reattached-relocate hose clamp bracket E18

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V865

In Date: 12/09/2005
Close Date: 12/15/2005

Meter Reading:

Problem?

D/SIDE DOOR OUT OF ALIGNMENT, RE-18

Task performed:

Parts	Quantity
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1215

In Date: 01/18/2006
Close Date: 01/24/2006

Meter Reading:

Problem?

MAP LIGHT COVER MISSING, D/SIDE SCENE LIGHT INOP, PUMP HOT LIGHT STAYS ON, RE-18

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1148

In Date: 01/09/2006
Close Date: 01/26/2006

Meter Reading: 3,076.00

Problem?

MAP,LIGHT INOP, E-18

Task performed:

Parts	Quantity
200256000SWITCH PRESS. 7 PSI	1
LB-D30BULB QUARTZ HAL. 12V 150W	1
LF18TS-LEDMAP LIGHT LED 18 IN	1

Workorder: V1795

In Date: 03/09/2006
Close Date: 03/20/2006

Meter Reading:

Problem?

NEED 2 HURST TOOL HOSES, RE-18

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V1910

In Date: 03/21/2006
Close Date: 03/23/2006

Meter Reading:

Problem?

REAR A/C SHUTS ON AND OFF, RE-18

Task performed:

Parts	Quantity
54-53030055-30BX CIRCUIT BREAKER	1
71R08521109 ROCKER OFF/ON/ON	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1902

In Date: 03/18/2006 Meter Reading:
Close Date: 03/29/2006

Problem?
engine cut off (On-call) E18

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V2046

In Date: 03/31/2006 Meter Reading:
Close Date: 04/03/2006

Problem?
HOLDER FOR HURST CUTTER BROKEN, RE-18

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Workorder: V2323

In Date: 04/21/2006 Meter Reading:
Close Date: 04/27/2006

Problem?
AIR HORN BUTTON ON PUMP PANEL INOP, RELIEF VALVE LIGHT INOP, RE-18

Task performed:	<u>Parts</u>	<u>Quantity</u>
	180R002HURST HYD. FLUID QT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2569

In Date: 05/11/2006

Meter Reading: 11,062.00

Close Date: 05/25/2006

Problem?

B INSPECTION, CHECK STEERING WHEEL FOR ALIGNMENT, AND NOISE E-18

Task performed:

See B Inspection pre-printed form

<u>Parts</u>	<u>Quantity</u>
048009000SPEEDCOUNTER PUMP PANEL	1
100R4FOAM HOSE AS PER SAMPLE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
17531BELT	1
23-12337002RIVET PLASTIC	8
3818885O-RING WATER SHUT OFF	2
3937367GASKET 4942874	1
39437394940547 SHAFT SHUT-OFF VALVE	1
3943740SHAFT SHUT-OFF VALVE	1
39438574989614 SEAL O-RING SHUT-OFF VALVE	1
39444543977737 SCREW SHUTOFF VALVE	1
5-280XU-JOINT	1
5-675XU JOINT	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
7460967AIR FILTER 17210-ZE2-515 HONDA	1
78R536078R5360M 2PK FILTER AIR COND	5
800405PURGE VALVE KIT	1
A1205Q2591OIL SEAL PINION A11205A2731 NEW #	1
BPR5ESSPARK PLUG 7734	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
M456PROSPLINT, LEG - LARGE	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2642

In Date: 05/16/2006 Meter Reading:
Close Date: 06/06/2006

Problem?
REPAIR ROOF CRACKS, REPAINT ROOF E-18 (SEBOKS AUTO BODY)

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Vendor?: SEBOK

Workorder: V2908

In Date: 06/08/2006 Meter Reading:
Close Date: 06/12/2006

Problem?
REPLACE HEADLIGHT, E-18

Task performed:	<u>Parts</u>	<u>Quantity</u>
	H6054USE CV TYPE SEALED BEAM	6

Workorder: V2638

In Date: 05/16/2006 Meter Reading:
Close Date: 06/23/2006

Problem?
INSTALL NEW HOSE BED COVER, E-18 (CENTRAL AUTO)

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Vendor?: CENT0002

Workorder: V2639

In Date: 05/16/2006 Meter Reading:
Close Date: 06/23/2006

Problem?
1 SEAT REPAIR E-18 (CENTRAL AUTO)

Task performed:	<u>Parts</u>	<u>Quantity</u>
	NO PARTS USED	

Vendor?: CENT0002



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3027

In Date: 06/16/2006 Meter Reading:
Close Date: 06/26/2006

Problem?
Minor oil leak coming from hose under engine

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V3272

In Date: 07/03/2006 Meter Reading:
Close Date: 07/06/2006

Problem?
slight cooling system leak/small amount of fluid found on bay floor E18

Task performed:	Parts	Quantity
	3818885O-RING WATER SHUT OFF	2
	3937367GASKET 4942874	1
	39437394940547 SHAFT SHUT-OFF VALVE	1
	3943740SHAFT SHUT-OFF VALVE	1
	39438574989614 SEAL O-RING SHUT-OFF VALVE	1
	39444543977737 SCREW SHUTOFF VALVE	1
	PR338324070 WIX FILTER WATER	1

Workorder: V3440

In Date: 07/12/2006 Meter Reading:
Close Date: 07/21/2006

Problem?
pump overheat light stays on e18

Task performed:	Parts	Quantity
	200256000SWITCH PRESS. 7 PSI	1

Workorder: V3698

In Date: 07/31/2006 Meter Reading:
Close Date: 08/18/2006

Problem?
electrcal problem on call re18

Task performed:	Parts	Quantity
	75907SWITCH - BATTERY -MASTER	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4013

In Date: 08/18/2006
Close Date: 08/21/2006

Meter Reading:

Problem?

E18 Electrical power was cutting off the lights, resetting the computer and almost stalling out the engine while driving.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V4093

In Date: 08/24/2006
Close Date: 08/24/2006

Meter Reading:

Problem?

ON CALL E 18 ELECTRICAL PROBLEM

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V4109

In Date: 08/24/2006
Close Date: 08/25/2006

Meter Reading:

Problem?

ENGINE RUNS POORLY ON CALL

Task performed:

Parts	Quantity
4025130FUEL PRESS SENSOR	1
4921597OUTBOARD SPEED SENSOR	1

Workorder: V4623

In Date: 09/27/2006
Close Date: 10/10/2006

Meter Reading: 7,731.00

Problem?

ON CALL CHECK ENGINE LIGHT ON E18

Task performed:

1. ON CALL, TRAVELED TO STN 18 HOOK UP LAPTOP FOUND CODES 328. CLEAR INACTIVE CODES & ROAD TEST. CALLED CUMMINS.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4704

In Date: 10/03/2006 Meter Reading: 561.00
Close Date: 10/16/2006

Problem?
SMOKE EJECTOR (GAS) SPUTTERING UNIT ON E-18

Task performed:	Parts	Quantity
1. TRAVELED TO STN R/R SPARK PLUG. TEST/ OK, IN GOOD WORKING ORDER NOW.	NO PARTS USED	

Workorder: V6223

In Date: 01/11/2007 Meter Reading: 1,612.00
Close Date: 01/17/2007

Problem?
driver side scene flood light/ one bulb burned out E18

Task performed:	Parts	Quantity
Replaced bulb tested ok	NO PARTS USED	

Workorder: V6261

In Date: 01/13/2007 Meter Reading: 1,612.00
Close Date: 01/23/2007

Problem?
Pump overheating light stuck in the ON position. E18

Task performed:	Parts	Quantity
1. TRAVELED TO SNT 18. FOUND LINE FROM OVER HEAT AND HOOK TO DRAIN LINE AND MADE TO MANUFACTURERS SPIKES. TEST OK.	NO PARTS USED	

Workorder: V6437

In Date: 01/24/2007 Meter Reading: 716.00
Close Date: 01/30/2007

Problem?
Inspection of rear outside tires on engine have excessive wear on them. Inside tires still good.E18

Task performed:	Parts	Quantity
1. TRAVELED TO STN 18. DRIVE TO STN INSPECT TIRES CALLED SHOP FOR 4 REAR TIRES AND SIZE.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6452

In Date: 01/24/2007 Meter Reading: 9,581.00
 Close Date: 02/21/2007

Problem?
 replace tires at sta 18 callaghan ent e18

Task performed:	Parts	Quantity
replace 4 rear tires-callaghan	NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V6705

In Date: 02/11/2007 Meter Reading: 750.00
 Close Date: 03/02/2007

Problem?
 center of passenger side rear wheel (chrome) came loose. sitting on top of yellow flammable storage cabinet E18

Task performed:	Parts	Quantity
installed hub cap	NO PARTS USED	

Workorder: V7106

In Date: 03/08/2007 Meter Reading: 10,181.00
 Close Date: 03/09/2007

Problem?
 repair map light e18

Task performed:	Parts	Quantity
Repaired broken dash light wire in dash	NO PARTS USED	

Workorder: V7578

In Date: 04/07/2007 Meter Reading: 10,839.00
 Close Date: 04/13/2007

Problem?
 Right rear center simulator hub missing after returning from a call. E18

Task performed:	Parts	Quantity
Installed rear hub cap	CR1110SSCENTER HUB CAP	1



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7627

In Date: 04/10/2007 Meter Reading: 842.00
Close Date: 04/13/2007

Problem?

Wiper blades need replaced on E 18.

Task performed:

Drive to station. R&R wiper blades

Parts	Quantity
52-24WIPER BLADES ANCO 24	2

Workorder: V7280

In Date: 03/20/2007 Meter Reading: 782.00
Close Date: 05/03/2007

Problem?

on board foam system not working e18

Task performed:

1. Test foam system; no foam; rem pump cover, counter wheels bad; send parts that are NG to shop; order parts; installed parts-test; wheels not moving free;
2. Rebuild foam pump-test; control head loose setting; will bring to shop
3. Wait for truck; cut out pump panel and wire in new control head; test-ok

Parts	Quantity
040154000O-RING FOR HALE FOAM PUMP	1
168-0380-51USE 168-0380-56-0 OLD CONTROL UNIT HALE	1
501-3130-00PUMP HALE FOR FOAMMASTER	1
91553941GAUGE	1

Workorder: V7930

In Date: 04/25/2007 Meter Reading: 873.00
Close Date: 05/03/2007

Problem?

Need pressure gauge on pump panel replaced. E18

Task performed:

Installed new pressure & vac display; test ok

Parts	Quantity
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1

Workorder: V8072

In Date: 05/03/2007 Meter Reading: 887.00
Close Date: 05/21/2007

Problem?

pump discharge guage not working E-18

Task performed:

- Replc sender & wiring; call factory-no help; gauge in panel bad; parts on order.
Foam pump leaking; R/R foam pump-test ok
Charge gauge & senders-test ok

Parts	Quantity
4300-505PUMP FLOJET 12V	1
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8900

In Date: 06/18/2007 Meter Reading: 1,279.20
Close Date: 07/03/2007

Problem?

The foam level gauge not working. E-18

Task performed:

1. Drive to station; chk gauge; power/sender ok; need new gauge
2. Drive to station; installed new gauge; drilled new holes; calibrate; test ok

Parts	Quantity
WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352	1

Workorder: V9064

In Date: 06/28/2007 Meter Reading: 967.00
Close Date: 07/03/2007

Problem?

tractor abs warning light activated/ ECU130 code activated e18

Task performed:

1. DRIVE TO STATION. R/R TOOTH COUNT- OFF. CLEAR CODES. CHECK TWO TIMES. CLEAR CODES. CHECK TRANS NEUTRAL SIGNAL- TWO COUNT. CLEAR CODES.

Parts	Quantity
NO PARTS USED	

Workorder: V9455

In Date: 07/21/2007 Meter Reading: 1,008.00
Close Date: 07/27/2007

Problem?

Map light in cab broken. E-18

Task performed:

- Drive to station; installed map light; test-ok

Parts	Quantity
87141USE LED MAP LIGHT 24"	1

Workorder: V9457

In Date: 07/21/2007 Meter Reading: 1,008.00
Close Date: 07/27/2007

Problem?

Smoke ejector throttle does not adjust rpm's. Unit is always on full speed. Moving the throttle arm has no effect. E-18

Task performed:

- Drive to stn; rework carb; test ok

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9497

In Date: 07/23/2007 Meter Reading: 1,008.00
Close Date: 07/27/2007

Problem?
door shocks need replacing, led map light e18

Task performed:	Parts	Quantity
Drive to station; R/R? map light; replc all shocks for door; test	101281021GSS1917UY 90# STRUT-LIFT LF18TS-LEDMAP LIGHT LED 18 IN	11 1

Workorder: V9464

In Date: 07/23/2007 Meter Reading: 12,747.00
Close Date: 07/31/2007

Problem?
ON CALL E18 POWER STEERING 10-7

Task performed:	Parts	Quantity
1. DRIVE TO 18. CHECK VEHICLE- NO LEAKS, ALL HOSES OK.R&R TOP OF RESEVOIR TO CHECK OBSTRUCTIONS TO HOSES- NONE FOUND. ROAD TEST- DRIVES FINE. LEAVE IN SERVICE.	NO PARTS USED	

Workorder: V10033

In Date: 08/21/2007 Meter Reading: 13,403.00
Close Date: 09/11/2007

Problem?
deck gun alarm going off re18

Task performed:	Parts	Quantity
Replaced deck gun sensor	NISENSORNI-SENSOR SENSOR DECK GUN USE XG840-K	1

Workorder: V10067

In Date: 08/22/2007 Meter Reading: 13,500.00
Close Date: 09/11/2007

Problem?
A inspection and related repairs E18

Task performed:	Parts	Quantity
Drive to Stn; do A-Inspection & do repairs	194BULB	10



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10313

In Date: 09/07/2007

Meter Reading: 13,793.00

Close Date: 09/24/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED E18

Task performed:

Parts

Quantity



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. B INSPECTION AND ROAD TEST. FILL WATER TANK
2. SCHEDULE BATTERY REPLACEMENT SERVICE, LOAD SHEDING DUE TO BAD BATTERY.
3. HURST TOOL SERVICE FOUND TOOL LEAKING AT DUMP SWITCH *HURST DEALER REPAIRING*CHECK ALL OTHER RELATED EQUIPMENT NEED 1 NEW HOSE
4. SERVICE AND RUN GENERATOR
5. AIR DRYER SERVICE
6. CHECK TOUNGE ON FRONT AND REAR U BOLTS.
7. EXHAUST HANGERS LOOSE, SECURE ALL LOOSE HANGERS
8. RADIATOR CAP BAD- INSTALL NEW CAP
9. A/C FILTER DAMAGE- R/R NEW FILTER
10. PUMP FAILED VACUUM TEST. FOUND BAD INTAKE RELIEF CHECK VALVE. DECK GUN VAVLE R/R NEW CHECK VALVE, REBUILD DECK GUN VALVE, RE-TEST, PASS VACUUM TEST.
11. DOOR HOLD OPEN BRACKET LOOSE, DOOR SEAL DAMAGED, WINDOW MOLDING BROKEN, MADE NECESSARY REPAIRS.
12. PUMP REPAIR COUNTER INOP, FOUND DRRIVER BROKEN AND CABLE SNAPPED, REMOVED AND MADE UP NEW CABLE AND CABLE TRUNK , INSTALL NEW DRIVER.
13. PUMP WILL NOT SHIFT TO PUMP THROTTLE-DIAGNOSIS FOUND LOOSE GROUND ON RELAY PUMP SHIFT AND ON GAUGE SWITCH CONNECT FAUTTS. O.K. TO PUMP, AT PUMP SWITCH OPERATING SPURADICLY. REPAIRED
14. LIGHTING ON UNIT INOP- REMOVE AND CLEAN GROUND CONNECTIONS.
15. MARKER LIGHT OUT - GROUND CONNECTIONS CORRODED CLEANED ALL CONTACTS.
16. PUMP LEFT SIDE PANEL LIGHT LENSE BROKEN-R/R NEW LENS COVER
17. SERVICE POWER STEERING SYSTEM
18. FOAM FLOW NEEDED ADJUSTMENT- FLUSH FOAM LINE, CLEAN STRAINER, OPERATE FOAM SYSTEM, FLOW FOAM SYSYSTEM OPERATING WITHIN NORMAL RANGE.
19. PRIMER VALVE STICKING- REMOVE AND INSTALL NEW PRIMER.
20. SERVICE TRANSMISSION- OIL SLOW TO PUMP SYSTEM WEAK.
21. MOUNT STRAPS FOR CONES ON TAIL BOARD.
22. T- CASE SERVICE.
23. DISCONNECT ATF LINE FROM SUPPLY TANK TO FILL 1 GALLON JUGS TO FILL TRANSMISSION.
24. REMOVE EXPIRED GROUND LADDER HEAT SENSOR STICKER, INSTALL NEW UP TO DATE SENSOR STICKERS.

038-1550-00VALVE CHECK HALE 1/4"	1
05-17223-002RAD CAP 20 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
180R002HURST HYD. FLUID QT	1
291525END STANCHION	2
29526898 29548988 TRANS FILTER ALLISON	1
3530016HOSE HURST 16 ORANGE	1
538028052VALVE PRIMER PUMP W/HARDWARE	1
5462300020VALVE KIT SS VALVE 3 IN	1
67BULB 12 VOLT	10
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
A1834388003MOLD R/H	1
ACX-84534LUG NUT COVER PK10	11
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
CYBS27299011 STRAP 36IN	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10200

In Date: 08/31/2007 Meter Reading: 13,273.00
Close Date: 09/28/2007

Problem?
replace front tires at sta 18 callaghan

Task performed:	Parts	Quantity
REPLACE FRONT TIRES AT STA 18 (CALLAGHAN)	NO PARTS USED	

Vendor?: CALLAGHAN TIRE

Workorder: V10345

In Date: 09/10/2007 Meter Reading: 13,793.00
Close Date: 09/28/2007

Problem?
replace hose bed cover e18 central auto trim

Task performed:	Parts	Quantity
Replc hose bed cover - Central Auto Trim	NO PARTS USED	

Vendor?: CENTRAL AUTO

Workorder: V10780

In Date: 10/02/2007 Meter Reading: 14,090.00
Close Date: 10/22/2007

Problem?
install tic charger in unit e18

Task performed:	Parts	Quantity
drive to station. installed charger and wire to truck. move glove box to rear of a/c. test ok.	NO PARTS USED	

Workorder: V11409

In Date: 11/03/2007 Meter Reading: 2,070.20
Close Date: 11/13/2007

Problem?
need new trilock for rear of E18. Hose couple won't lock in, just shakes off. E18

Task performed:	Parts	Quantity
1. drive to station R/R trilock rear of truck test OK j	373-1.5E-Z LOK BRACKET	1
	373-2.5E-Z LOK BRACKET	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11488

In Date: 11/07/2007

Meter Reading: 14,746.00

Close Date: 11/26/2007

Problem?

flat repair callaghan ent e18

Task performed:

Parts

Quantity

Flat repair - Callaghan E18 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V13263

In Date: 02/14/2008

Meter Reading: 1,334.00

Close Date: 02/15/2008

Problem?

Dash indicator shows ABS brake light is on.....brakes seem to work fine, but light on. Lt. JP Maxson e18

Task performed:

Parts

Quantity

1. Drive to station, hooked up lap top, right front chadder, rework sender, test drive, OK

NO PARTS USED

Workorder: V13630

In Date: 03/02/2008

Meter Reading: 1,396.00

Close Date: 03/03/2008

Problem?

siren stopped working on way to a call E18

Task performed:

Parts

Quantity

Travel to Stn18; replc both siren speakers; chk operationn-NPF. j

SD-210RXSIREN DRIVER SMALL

2

Workorder: V13428

In Date: 02/22/2008

Meter Reading: 1,363.00

Close Date: 03/05/2008

Problem?

HURST CUTTERS MISSING ONE OF THREE SCREWS OUT OF HANDLE.. E18

Task performed:

Parts

Quantity

1. drive to station, installed screws in hurst tool handle

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13676

In Date: 03/04/2008

Meter Reading:

Close Date: 03/07/2008

Problem?

water leaking from pump e18

Task performed:

Parts

Quantity

- | Task performed: | Parts | Quantity |
|--------------------------------------|---------------|----------|
| 1. Drive to station, R/R drain lines | NO PARTS USED | |

Workorder: V13975

In Date: 03/19/2008

Meter Reading: 2,326.00

Close Date: 03/24/2008

Problem?

PULL ROPE ON GENERATOR BROKE AND PIN (FOR HYDRAULIC STRUT) ON MEDICAL DOOR MISSING e18

Task performed:

Parts

Quantity

- | Task performed: | Parts | Quantity |
|--|---------------|----------|
| 1. r/r generator rope. replaced med door strut . | NO PARTS USED | |

Workorder: V14052

In Date: 03/24/2008

Meter Reading: 29,005.00

Close Date: 03/28/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED E18

Task performed:

Parts

Quantity

- | Task performed: | Parts | Quantity |
|--|---|----------|
| 1. Perform "B" service | 1160033 IN FLANGE ADPT W/ HOLES P2S | 1 |
| 1A Continue with "B" service | 15W40BSYN OIL BULK QTS | 24 |
| 2. Safety meeting | 35200-YLIGHT MARKER LEDAMBER | 1 |
| 3. Serviced batteries | 404-100 VALVE CORE | 1 |
| 4. Serviced loose exhaust clamp | 52-24WIPER BLADES ANCO 24 | 2 |
| 5. Replaced mid body marker | 546126000TPM/QG HALE REPAIR KIT | 1 |
| 6. Replaced both T/S side lenses | 715000000501 1/2 IN VALVE SS 715-0000-00-50 | 1 |
| 7. Replaced wiper blades | 72500000050VALVE SS 2 1/2 | 2 |
| 8. Replaced rear A/C filter | 78R536078R5360M 2PK FILTER AIR COND | 1 |
| 9. Mounted hose clamps & strap to left rear compartment door | 883088301201 3 IN SLO-CLOZ W/R1 HANDLE | 1 |
| 10. Changed right rear discharge (valve) from hale to Akron. | 91513AMBER LENS | 2 |
| 11. Replaced deck gun valve | FS1022FILTER FUEL WIX 33422 PS8689 FRAM | 1 |
| 12. Replaced valve for #2 discharge | HPH6349AOIL FILTER 51748 | 1 |
| 13. Replaced #1 discharge valve (leaking) | PR338324070 WIX FILTER WATER | 1 |
| 14. Replaced tank fill/recirculate valve. (leaking) | R90PFILTER FUEL 33231 | 1 |
| 15. Rebuilt intake relief valve and replaced check valve | SAHSVS2510STRAP | 1 |
| 16. Clean shop | | |



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14133

In Date: 03/27/2008

Meter Reading: 29,005.00

Close Date: 04/18/2008

Problem?

replace tires at shop callaghan ent

Task performed:

Replace tire - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V15329

In Date: 05/26/2008

Meter Reading: 19,239.00

Close Date: 06/09/2008

Problem?

air hose nozzle leaking-broken E18

Task performed:

1. Build air hose 25'.
Drive to Stn; drop off hose; work on cone holder. j

Parts

1654-8FERRULE .718
S116BLO-GUN
S506USE 501 GAUGE AIR
S602CARD MALE CONN. 3/8 IN HOSE
S693AIR CHUCK

Quantity

2
1
1
2
1

Workorder: V15389

In Date: 05/29/2008

Meter Reading: 87,838.00

Close Date: 06/09/2008

Problem?

air leak, hurst power unit feet need replaced E18

Task performed:

Drive to Stn; replc motor mnt on Hurst tool & rep air line;
test ok. j

Parts

HR149460107MOUNT VIBRATION (NEWER POWER UNITS

Quantity

8

Workorder: V13528

In Date: 02/26/2008

Meter Reading: 17,295.00

Close Date: 06/17/2008

Problem?

Discharge #1,#2, & rear discharge leak under dry vac. test e18

Task performed:

1. Drive to station to try to adjust valve, slow down leak,
will wait until PM per Ed E

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15831

In Date: 06/19/2008 Meter Reading: 19,852.00
 Close Date: 06/23/2008

Problem?
 ON CALL E 18 BACK ALARM COMES ON WITH HEADLIGHTS

Task performed:	Parts	Quantity
6-18 On call found wiring issue; disconnected repaired harness next day	NO PARTS USED	
6-19 Drove to station repaired wiring harness tested OK		

Workorder: V15434

In Date: 06/01/2008 Meter Reading: 87,838.00
 Close Date: 07/07/2008

Problem?
 relief valve light is not coming on e18

Task performed:	Parts	Quantity
1. drive to station. replace sender . still inop, unit had a call	200226200200-2262-50 SWITCH-PROXIMITY QG VALVE	1

Workorder: V16056

In Date: 06/30/2008 Meter Reading: 1,614.20
 Close Date: 07/10/2008

Problem?
 need headlights for e18

Task performed:	Parts	Quantity
1. drive to station r/r head light test = ok	35200-RLIGHT MARKER LED RED	1
	H6054USE CV TYPE SEALED BEAM	2

Workorder: V15699

In Date: 06/12/2008 Meter Reading: 0.02
 Close Date: 07/17/2008

Problem?
 electronics box [cab] fan cover broken, needs replacement e18

Task performed:	Parts	Quantity
Drive to Stn; installed new cover; test ok. j	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15973

In Date: 06/25/2008

Meter Reading: 0.02

Close Date: 07/17/2008

Problem?

Need 2- 2-1/2" appliance holders inside D/O compartment K.C. e18

Task performed:

drive to Stn; installed holder; test ok. j

Parts

373-2.5E-Z LOK BRACKET

Quantity

2

Workorder: V16099

In Date: 07/02/2008

Meter Reading: 1,615.00

Close Date: 07/17/2008

Problem?

E18 has problem with main computer control panel located in the cab. It shows nothing but blurred lines, and emergency lights are out.

Task performed:

1. Drive to Stn;; call factory; hookup laptop node 35 dead; bring to shop; swap out; take out node #5, send for repairs. j
2. reprogram and install new vista screen.

Parts

6201-0010-00VISTA I

Quantity

1

Workorder: V16414

In Date: 07/17/2008

Meter Reading: 1,615.00

Close Date: 07/22/2008

Problem?

left rear marker light and tailboard light not working e18

Task performed:

drive to Stn; R/R marker light; test ok. j

Parts

35200-RLIGHT MARKER LED RED

372000084MARKER LIGHT

Quantity

1

1

Workorder: V16434

In Date: 07/18/2008

Meter Reading: 20,212.00

Close Date: 07/28/2008

Problem?

quartz lts and pump panel lts 10-7

Task performed:

Drive to Stn; chk noes & lights; test ok. j

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16967

In Date: 08/11/2008 Meter Reading: 1,650.00
Close Date: 08/12/2008

Problem?

extenda gun warning switch activated while in drive and break released e18

Task performed:

drive to Stn; rework grnd for sender; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V16951

In Date: 08/10/2008 Meter Reading: 1,650.00
Close Date: 08/21/2008

Problem?

aluminum hinge piece for the rear door for the rear compartment on passenger side broken. Won't push button E18

Task performed:

1. drive to station rework and replace hinge test = ok

Parts

101305001BRACKET LEFT DH0008-5
52-624SWITCH DOOR

Quantity

1
1

Workorder: V17144

In Date: 08/19/2008 Meter Reading: 1,658.00
Close Date: 08/28/2008

Problem?

bungie handle strap that holds spreaders in compartment is broken E18

Task performed:

Drive to Stn; rep strap; test ok. j

Parts

T69-15.5 STRAP FOR TOOL HOLDER

Quantity

2

Workorder: V17430

In Date: 09/01/2008 Meter Reading:
Close Date: 09/22/2008

Problem?

left side pump panel lights/some out E-18

Task performed:

drive to Stn; R/R LED pump panel light. test ok. j

Parts

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE

Quantity

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17496

In Date: 09/03/2008 Meter Reading:
Close Date: 09/22/2008

Problem?
led strobe on right hood area not strobing E18

Task performed:	Parts	Quantity
Drive to Stn; installed new light; test ok j	50R03ZRRLIGHT 500 TIR LED	1

Workorder: V17577

In Date: 09/08/2008 Meter Reading: 2,606.00
Close Date: 09/29/2008

Problem?
Compartment door Strut-Lift cyl. mount on body missing . One on other side loose . K.C. E18

Task performed:	Parts	Quantity
Drive to Stn; R/R mount; test ok. j	NO PARTS USED	

Workorder: V17429

In Date: 09/01/2008 Meter Reading:
Close Date: 09/30/2008

Problem?
K12 not starting E-18

Task performed:	Parts	Quantity
Install new spark plug in K12; change fuel adjust carb and test; OK	4626BPMR7A SPARK PLUG	2

Workorder: V17431

In Date: 09/01/2008 Meter Reading:
Close Date: 09/30/2008

Problem?
rear cab a/c missing a vent E-18

Task performed:	Parts	Quantity
R & R AC Vent. Gauges at pump panel sticking, clean lines, test OK.	72R311018-2640 VENT A/C NEW # 1719	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17810

In Date: 09/19/2008 Meter Reading: 21,304.40

Close Date: 10/03/2008

Problem?

calibrate foam system e18

Task performed:

	Parts	Quantity
--	-------	----------

1. Calibrate foam system, calibrated system @ station.	NO PARTS USED	
--	---------------	--

(R.T.)

Workorder: V18104

In Date: 10/03/2008 Meter Reading: 21,467.60

Close Date: 10/14/2008

Problem?

right (officer's side) spot light bulb burned out e18

Task performed:

	Parts	Quantity
--	-------	----------

1- Drive to sta, R/R floodlite test ok.	LB-D30BULB QUARTZ HAL. 12V 150W	1
---	---------------------------------	---

Workorder: V18489

In Date: 10/21/2008 Meter Reading: 22,059.50

Close Date: 10/29/2008

Problem?

rear top left compartment buzzer broken, light and buzzer in cab will not shut off e18

Task performed:

	Parts	Quantity
--	-------	----------

Drive to Stn; replace STW for door; test ok. j	SWT1277EL57755 SWITCH DOOR 2PCS	2
---	---------------------------------	---

Workorder: V18584

In Date: 10/24/2008 Meter Reading: 2,679.80

Close Date: 10/31/2008

Problem?

air horn on LT. side of truck not working. Left rear upper compartment buzzer going off intermitantly, problem was corrected on 10-22 or 10-23-08 but is broken again e18

Task performed:

	Parts	Quantity
--	-------	----------

1. Adj/sec rear door switch.	NO PARTS USED	
2. Ad air horn. j		



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18779

In Date: 11/01/2008
Close Date: 11/14/2008

Meter Reading: 22,241.10

Problem?
door ajar light coming on randomly and possible air pressure leak E18

Task performed:

Drive to stn; installed parking brake & rebuild pump shift & fnd short in wiring; test all ok. j

Parts	Quantity
52-624SWITCH DOOR	3
5460370530VPS SHIFT KIT 546-0370-53-0	1
60R00FRR600 SERIES RED LED W/O FLANGE	1
800034VALVE PARKING BRK.	1
ABPN8332229011-3050 SWITCH BLOWER	1

Workorder: V18990

In Date: 11/10/2008
Close Date: 11/19/2008

Meter Reading: 1,793.00

Problem?
Light boxes X 2 in back seat not recharging . (no lights are on when flashlight is in the charger). K.C. E18

Task performed:

drive to Stn; replc wiring going to lights; test ok. j

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19074

In Date: 11/14/2008

Meter Reading: 22,241.10

Close Date: 12/10/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED E18

Task performed:

- 1. C-Inspection
- 2. Svc rear diff; change fluid.
- 3. Svc T-Case; change fluid.
- 4. Air dryer svc.
- 5. Coolant filter hsng leaking; rebuild hsng asy & reinstall; refill coolant.
- 6. Air tanks loose; rem all mnt boltster nuts; replcd nuts/washers for tank rods; tightened tanks; drilled/remounted drain cords; ck ok.
- 7. P/S svc; replcd filter; drained fluid; filled sys; ran/rechk level; ck ok.
- 8. Primer sticking; diss, rebuild, lube & reassemble; valve operating normal now.
- 9. Replc eng belts; rem fan, (2) A/C belts, eng belt & tensioner; replcd bolts/tensioner; installed fan, A/C belt too short; R/I fan; replcd belt; ck ok.
- 10. Brake retarder inop; rem control solenoid; swapped fittings; replcd solenoid asy; reinstalled lines/plugs; ck opn; ck ok.
- 11. Mansavers loose; tightened mounts.
- 12. Rear door alarms erratic; rem display panels; reinstall buzzer; replcd magnetic swtchs with plugs & swtchs; wired; ck sys; ck ok; wiggled wiring in rear corner; ck ok.
- 13. C-Inspection electrical test.
- 14. Go to surplus & get eng; replcd (2) btry; brought to shop; rewired (2) btry & charged btry; rem all "T" handles, pump to tank flange, discharge flange; wrong flanges; reinstalled flanges, rods & "T" handles; reinstalled all parts.
- 15. #4 discharge valve leaking; diss/install new valve asy; adj valve stop.
- 16. Transport training personnel to new facility.
- 17. Rear back board compt door alarm short; rem damaged door alarm swtch & install new swtch & secure
- 18. Replc deckgun valve; rem Hale valve & flange; replcd pipe flange; replcd w/Akron valve; repositioned level; drilled & used Hale flange; rechk vac test; ck ok; adj linkage; ck for leaks; ck ok. j

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	2
1160033 IN FLANGE ADPT W/ HOLES P2S	1
15W40BSYN OIL BULK QTS	24
2952271729552377 VALVE ASSY.ACCUM	1
3818885O-RING WATER SHUT OFF	2
3937367GASKET 4942874	1
39438574989614 SEAL O-RING SHUT-OFF VALVE	1
39444543977737 SCREW SHUTOFF VALVE	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
440-5 VALVE EXT.	1
52-624SWITCH DOOR	2
72500000050VALVE SS 2 1/2	1
800405PURGE VALVE KIT	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	1
9440BELT	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
SWT1277EL57755 SWITCH DOOR 2PCS	1
9480BELT	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
K080716BELT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19521

In Date: 12/04/2008

Meter Reading: 22,241.10

Close Date: 12/23/2008

Problem?

REPAIR DOOR AJAR LIGHT AND BUZZER, E-18

Task performed:

Rep door buzzer going off when all doors shut. j

Parts

NO PARTS USED

Quantity

Workorder: V19687

In Date: 12/11/2008

Meter Reading: 22,897.20

Close Date: 01/02/2009

Problem?

mount misc. equipment E18

Task performed:

1. Rem hyd brckt off old unit at shop; drive to Stn; installed on truck; see what they need; get parts from shop.
2. Drive to Stn; mnt nozzles, hose brkts; move hose clamp; work on air leak under truck; fitting loose; tighten; test ok. j

Parts

ABM-1BASE MOUNT ALUMINUM

UMVS056511STRAP

UMVS111611STRAP

Quantity

3

4

4

Workorder: V19784

In Date: 12/16/2008

Meter Reading: 709.00

Close Date: 01/02/2009

Problem?

Filter minder broken (needs replacement) #2 bolt loose on A.C. compresor nut missing) E18

Task performed:

drive to Stn; replc air minder; test ok. j

Parts

22-51374-000SENSOR AIR RESTRICTION

Quantity

1

Workorder: V20037

In Date: 12/30/2008

Meter Reading: 23,227.00

Close Date: 01/06/2009

Problem?

repair electrical problem E18

Task performed:

Drive to Stn; replcd both PTO swtch on T-Case; test ok. j

Parts

200-2450-00NC SWITCH OK TO PUMP

Quantity

2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19450

In Date: 12/02/2008

Meter Reading: 22,241.10

Close Date: 01/14/2009

Problem?

replace hose bed cover e18

Task performed:

Parts

Quantity

Replace hose bed cover E18 - Central Auto Trim j

NO PARTS USED

Vendor?: CENTRAL AUTO TRIM

Workorder: V20434

In Date: 01/18/2009

Meter Reading:

Close Date: 02/12/2009

Problem?

Oil fill cap stripped out . Honda # GX-240 E-18

Task performed:

Parts

Quantity

1- Drive to sta. replace cap, test run ok.

EG-3500OIL CAP HONDA

1

Workorder: V20570

In Date: 01/24/2009

Meter Reading:

Close Date: 02/12/2009

Problem?

Drip at site on pump where deck gun pressure gauge line connects into piping(above main pump manifold). Leaks only water until level is below pressure gauge line and does not leak directly from pump. e18

Task performed:

Parts

Quantity

1- Drive to sta, replaced fittings for gauge test ok.

NO PARTS USED

Workorder: V20712

In Date: 01/30/2009

Meter Reading: 2,832.00

Close Date: 02/13/2009

Problem?

Diesel fuel leak when engine is running . 60 drops a min. or so . K.C. E18

Task performed:

Parts

Quantity

Drive to Stn; cln eng; tighten fuel lines; fnd leak at fuel pump; had Cummins repair; test ok. j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21147

In Date: 02/17/2009 Meter Reading: 1,973.00
Close Date: 02/24/2009

Problem?
Hale FoamLogix #10064 display is reading LO-SP e18

Task performed:	Parts	Quantity
drive to Stn; rewire foam sys; had bad grnd; test ok. j	NO PARTS USED	

Workorder: V21149

In Date: 02/17/2009 Meter Reading: 1,973.00
Close Date: 02/24/2009

Problem?
Water flowsensor is reading under true flow on Hale # 107064 e 18

Task performed:	Parts	Quantity
driv e to stn; bring pefow gauge; adjuster flow test ok. j	NO PARTS USED	

Workorder: V20782

In Date: 02/02/2009 Meter Reading: 24,055.00
Close Date: 02/28/2009

Problem?
repair station 18 blower (outside agency-regan's small engine service)

Task performed:	Parts	Quantity
rep Stn81 blower - Regans j	NO PARTS USED	

Vendor?: REGANS SMALL ENG

Workorder: V17845

In Date: 09/21/2008 Meter Reading: 2,619.40
Close Date: 03/02/2009

Problem?
engine losing power at higher rpm E18

Task performed:	Parts	Quantity
1. Drive to Sta-18 connect to laptop/R&R fuel pressure switch.	4025130FUEL PRESS SENSOR	1

(R.T.)



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V21621

In Date: 03/07/2009 Meter Reading: 25,084.00
Close Date: 03/13/2009

Problem?
REPLACED HEADLAMP ON E18 NEED A SPARE HEADLAMP.

Task performed:	Parts	Quantity
Drop off bulb. j	NO PARTS USED	

Workorder: V21789

In Date: 03/13/2009 Meter Reading: 2,027.00
Close Date: 03/27/2009

Problem?
A.B.S. Tractor warning light on dash lit . Enging runs fine and stop fine . K.C. #6318 e18

Task performed:	Parts	Quantity
Drive to Stn; hookup laptop; R/F wheel sender out of adjustment; adj; test drive ok. j	NO PARTS USED	

Workorder: V22347

In Date: 04/06/2009 Meter Reading: 2,972.00
Close Date: 04/16/2009

Problem?
I would like to get mounts for 6' roof hook . It can be mounted on side of right side step under frount capt's door . K.C. # 6318 cell : 262-8349 E18

Task performed:	Parts	Quantity
Drive to Stn; mount roof hook. j	5269LPVM-5 SM MOUNT	3

Workorder: V22237

In Date: 03/31/2009 Meter Reading: 2,056.00
Close Date: 04/17/2009

Problem?
AC belt on E18 has begun to slip and is squealing. St 18 can also use 2 spare headlights as E18 lights have both been replaced in the past two weeks.

Task performed:	Parts	Quantity
Drive to Stn; had light on; hood inop; replc; tighten both belts on eng; test ok. j	50R03ZRRLIGHT 500 TIR LED	1
	H6054USE CV TYPE SEALED BEAM	2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22405

In Date: 04/08/2009

Meter Reading: 2,972.00

Close Date: 04/23/2009

Problem?

right rear red strobe not working. e18

Task performed:

Drive to Stn; installed new light; test ok. j

Parts

50R03ZRRLIGHT 500 TIR LED

Quantity

1

Workorder: V22716

In Date: 04/21/2009

Meter Reading: 2,103.00

Close Date: 04/28/2009

Problem?

Head light out (Mike fixed it) K.C. # 6318 E18

Task performed:

Installed lite; test ok. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V22721

In Date: 04/21/2009

Meter Reading: 2,103.00

Close Date: 04/28/2009

Problem?

marker light dim and 1/2 lit 1- top right and 2- low K.C. # 6318 E18

Task performed:

Drive to Stn; isntalled lite; test ok. j

Parts

35200-RLIGHT MARKER LED RED

372000084MARKER LIGHT

Quantity

3

1

Workorder: V22798

In Date: 04/25/2009

Meter Reading: 2,103.00

Close Date: 05/04/2009

Problem?

coolant leak noted on officer side of E-18, small amount but keeps leaking

Task performed:

Drive to Stn; press chk coolant lines for air compressor leaking; drain coolant; wait for part frm shop; replc seals; fill coolant; test ok. j

Parts

ANTICOOLANT ANTIFREEZE GAL

S1003-A3103015 SEAL

Quantity

3

4



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22900

In Date: 04/29/2009 Meter Reading: 2,103.00
Close Date: 05/05/2009

Problem?
gas powered exhaust fan needs 4 new frame "feet"/rubber vibration pads. E-18

Task performed:	Parts	Quantity
Drive to Stn; isntalled new feet; test ok. j	FZ51368FEET RUBBER RAM-FAN	4

Workorder: V22962

In Date: 05/01/2009 Meter Reading: 3,014.70
Close Date: 05/14/2009

Problem?
Need replacement disk for deck gun locking lever. E18

Task performed:	Parts	Quantity
Drive to Stn; replc lock; test ok. j	X170DECK GUN ROTATION LOCK INSERT	1

Workorder: V19679

In Date: 12/11/2008 Meter Reading: 22,897.20
Close Date: 05/26/2009

Problem?
DOOR OPEN ALARM INTERMITENT E18

Task performed:	Parts	Quantity
1. Drive to Stn; fnd node w/rear upper door disabled wire; will see if alarm still goes off. 2. Drive to Stn; disconnected; R/R door from node; crews will report to me if lights still comes on. j	NO PARTS USED	

Workorder: V23695

In Date: 06/01/2009 Meter Reading: 27,087.70
Close Date: 06/04/2009

Problem?
repair flat tire callaghan

Task performed:	Parts	Quantity
	NO PARTS USED	

Vendor?: CALLAGHAN



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24503

In Date: 07/01/2009 **Meter Reading:** 27,626.50
Close Date: 07/20/2009

Problem?
 repair K950 vent saw (e18) and chain saw sta 19) (outside agency-regan's small engine service)

Task performed:	<u>Parts</u>	<u>Quantity</u>
Repair K950 vent saw E18 & chain saw Stn19 - Regans j	NO PARTS USED	
Vendor?: REGANS		

Workorder: V24669

In Date: 07/09/2009 **Meter Reading:** 2,216.00
Close Date: 07/22/2009

Problem?
 L bracket on driver's side mirror broken (lower L-bracket) one quartz bulb out in officer side scene light...

Task performed:	<u>Parts</u>	<u>Quantity</u>
Drive to Stn; R/R bulb & brkt; test ok. j	11133MIRROR MOUNT	1
	LB-D30BULB QUARTZ HAL. 12V 150W	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25012

In Date: 07/23/2009

Meter Reading: 28,059.00

Close Date: 08/03/2009

Problem?

B-INSPECTION E18

Task performed:

- B-Inspection
- 2. Replcd grille & reinstalled lights.
- 3. Added coolant.
- 4. Secured strikers in all copts.
- 5. Replcd ign on light on dash.
- 6. Secured brkts in L1 compt.
- 7. Replcd marker lights.
- 8. Replcd amber lite & green bulb on master intake valve
- 9. Replcd rubber covers on push button switches.
- 10. Replcd flasher.
- 11. Add brake pedal free travel.
- 12. Replcd wiper blades.
- 13. Replcd drivers door seal.
- 14. Sec seat belt on drivers seat.
- 15. Adj tire press.
- 16. replcd frt tires.
- 17. Chkd all foam sys connections at head/pump; fnd grnd connection on computed brkn; R/R comuter & tested ok.
- 18. 45-63 code in trans on solenoid open; replc d solenoid ckt; still opn; tested wiring; fnd plug at solenoid bad; rewired plug & tested ok; clnd codes; put dash back tog.
- 19. Adj frt brakes & replcd frt tires for wheel pull to right; road tested. ok.
- 20. Replcd hold open in hose reel compt.
- 21. Chkd for intermittent door ajar pbrem; chd all swtchs & wire continuity; rewired hose reel & bottom; door switches; road tested ok; cld not dupe problem. j

Parts

Quantity

101281011GSS6297UM 60# DOOR STRUT QUINT	2
101305001BRACKET LEFT DH0008-5	1
101305002DH0007-5 BRACKET RIGHT	1
15W40BSYN OIL BULK QTS	24
1891BULB	1
2000540080INDICATOR GREEN LIGHT	1
2002501500DISTRIBUTION BOX	1
25-358SWITCH COVER	2
2952271729552377 VALVE ASSY.ACCUM	1
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	1
372000031IGNITION ON DISPLAY	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
6808880023GRILLE FRTLNR. A17-14766-000	1
EL12FLASHER ELECTRONIC	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1

Workorder: V25612

In Date: 08/18/2009

Meter Reading: 28,565.80

Close Date: 09/03/2009

Problem?

lightbar mounted spotlight bulb burned out E18

Task performed:

- 1 Drive to Stn; replcd night fighter bulb; need new head; replc floodlight bulb.
- 2. Drive to Stn; replcd top mntd spotlight; test ok.
- j

Parts

Quantity

620122SPOT LIGHT REMOTE	1
LB-D30BULB QUARTZ HAL. 12V 150W	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26279

In Date: 09/16/2009 **Meter Reading:** 29,018.10
Close Date: 09/24/2009

Problem?
door open warning lt on E18

Task performed:

Fnd rear door ajar going off; chk doors;/longers; alarm going on/off; cld not get problem to stay on; reprogrammed nodes; ck ok; returned to shop. j

Parts	Quantity
351000005DOOR OPEN PANEL ENGINE	1

2. Drive to Stn; rem wires on node 3 & 4; still alarm going off.
3. Drive to HQ; work on board in cab; follow back to stn; called OME; need to bring in shop.
4. Work in shop on rfewiring node 3 & 4; test drive; 2-1/2 hour light stayed off; crew PU; need component & rewired. j

Workorder: V25713

In Date: 08/22/2009 **Meter Reading:** 2,306.00
Close Date: 09/30/2009

Problem?
E18 TIC NOT WORKING. BATTERIES SHOWING FULLY CHARGED BUT SCREEN STAYING ALL WHITE.

Task performed:

1. Drive to stn; bring to shop for rep.
2. Chk fan blades & torque nut.
3. Move TIC to top & light down; rewire. j

Parts	Quantity
NO PARTS USED	

Workorder: V26369

In Date: 09/21/2009 **Meter Reading:** 2,354.00
Close Date: 09/30/2009

Problem?
Rear door ajar warning light comes on intermintently . K.C. e18

Task performed:

Drive to Stn; rem node 6 & wires for upper/lower rear door; test drive (2) back doors; need new wires. j

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26888

In Date: 10/14/2009

Meter Reading: 21,889.50

Close Date: 11/16/2009

Problem?

replace 2 tires E18 loose wheels @ vista (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Replace (2) tires E18, loose wheels - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V27370

In Date: 11/02/2009

Meter Reading: 2,395.00

Close Date: 11/17/2009

Problem?

1- Tank to pump, or tank fill ball valve is leaking . 2- 1" hose reel cuppling is leaking and has moved from fitting . K.C.E18

Task performed:

Parts

Quantity

drive to Stn; replcd tank fill valve. j

5462270020VALVE KIT SS 546-2270-02-0

1

Workorder: V27387

In Date: 11/03/2009

Meter Reading: 2,395.00

Close Date: 11/18/2009

Problem?

tailboard lights and driver side running light 10-7 r18

Task performed:

Parts

Quantity

Went to Stn18; chk lights; fnd all lights working; wiggled wiring; ck ok. j

NO PARTS USED

Workorder: V27827

In Date: 11/20/2009

Meter Reading: 33,802.00

Close Date: 11/30/2009

Problem?

hose reel coupling bent and leaking, need to fix asap, its near the point of seperation. E18

Task performed:

Parts

Quantity

1. cut hose off; reinstalled hose end; installed hose; ran/ck for leaks; ck ok.
2. Drille/installed screws for K-12 saw holding box; ck ok. j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25489

In Date: 08/12/2009
Close Date: 12/03/2009

Meter Reading: 2,288.00

Problem?

right side extenda-light halogen bulb burned out[one of two]. E18

Task performed:

see 25612

Parts

Quantity

NO PARTS USED

Workorder: V27834

In Date: 11/20/2009
Close Date: 01/15/2010

Meter Reading: 30,507.30

Problem?

replace 4 rear tires E18 (outside agency-callaghan tire)

Task performed:

Replace (4) rear tires E18 - Callaghan

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V28962

In Date: 01/10/2010
Close Date: 01/27/2010

Meter Reading: 2,501.00

Problem?

Right side Telelight out . Thanks K.C. E18

Task performed:

1. R/S tele light inop; chkd NPF; fnd they will notify if any further problems.
2. L/side warning LED inop; replcd LED lamp asy. j

Parts

Quantity

50R03ZRRLIGHT 500 TIR LED

1

Workorder: V30890

In Date: 03/19/2010
Close Date: 04/05/2010

Meter Reading: 33,317.00

Problem?

steering wheel horn/siren button not activating sounding devices sr at 18

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31281

In Date: 04/05/2010
Close Date: 04/28/2010

Meter Reading: 10.00

Problem?

need engine oil at station 18

Task performed:

Dropped off oil. j

Parts

Quantity

15W40QSYN OIL QT

12

Workorder: V31310

In Date: 04/06/2010
Close Date: 04/28/2010

Meter Reading: 33,758.40

Problem?

need new cabin a/c filter[metal screen type].....falling apart E18

Task performed:

Went to Stn18; gave stn operator filter. j

Parts

Quantity

78R536078R5360M 2PK FILTER AIR COND

1

Workorder: V31344

In Date: 04/07/2010
Close Date: 04/29/2010

Meter Reading: 33,802.00

Problem?

Fire pump not holding vacuum long , posable leak in intake valve or preconect 1-3/4 " valve . K.C. E18

Task performed:

Drain pump; work all valves; pull dry vac; test drop 2" in 10 min; cld have had valve open a little. j

Parts

Quantity

NO PARTS USED

Workorder: V31858

In Date: 04/28/2010
Close Date: 05/10/2010

Meter Reading: 34,135.00

Problem?

Booster hose broke at coupling and needs to be re-attached E18

Task performed:

Went to Stn28 from Stn20; fnd coupling off o hose; cut hose; installed coupling; ck ok. j

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31165

In Date: 03/30/2010

Meter Reading: 33,802.00

Close Date: 05/11/2010

Problem?

repair hose bed cover central

Task performed:

Parts

Quantity

Repair hose bed cover - Central Auto j

NO PARTS USED

Vendor?: CENTRAL AUTO

Workorder: V31916

In Date: 05/02/2010

Meter Reading: 34,135.00

Close Date: 05/17/2010

Problem?

generator's oil is milking in color and has slight smell of gas. E18

Task performed:

Parts

Quantity

Fnd level high & gas mixed; drained oil & replcd. j

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31348

In Date: 04/07/2010

Meter Reading: 33,802.00

Close Date: 06/07/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E18

Task performed:

1. C-Inspection
2. R/R btrys; cln cables & tray.
3. Lube drawer slides.
4. R/R R/side intake screen.
5. R/R bulb in master intake unit; retest.
6. Tighten up lower latch hardware on R-1 compt rear door.
7. Tighten up lower rear door handle & upper pin.
8. R/R rear hose reel door shocks.
9. R/R & R R door shocks onr ear doors of trk lower.
10. R/R toggle boot on side pump panel boot had rip.
11. R/R A/C filter.
12. R/R A/C vents on dash; old ones brkn.
13. R/R belts - C-Inspection.
14. R/R belt tensioner per Ed Ehrke on belt; replcmnt.
15. R/R idler bearing on A/C belt per Ed Ehrke; belt replacement.
16. R/R brake hose - cut on frame; rerun line out of way; tie up.
17. Rebuilt dryer; replc filter; reinstall on unit.
18. Svc trans.
19. Svc t-case; water in oil.
20. R/R seat belt on pass frnt seat.
21. R/R hose bed cover; has rips in it; send out for rep; chk clips; replc brkn clips.
22. R/R driver seat; has rip in it; send for rep; reinstall.
23. Tighten up R/R seat latch on box.
24. R/R washer tube tee; cln out plugged up sprayer.
25. R/R door arm rest moldings; all were brkn.
26. R/R door gskts on (30 doors; were ripped open.
27. R/R t-signal switch; old one was sticking.
28. R/R window glass gskts; old ones falling off.
29. Hood support arm bolts loose on cab; tighten up bolts.
30. Work on door open warn sys; lites on all the time; C/O wiring; fnd node #3 sending ___ vista; C/O nodes; rep swtch/wiring on back board compt; flash node #3 still inop; replc node #3; test drive.
31. Assist w/foam sys calibration - Levy.
32. Light on FRC pump panel gauge dim; didn't have a replacement; need to ___; fill later.
33. Fnd sound going up dash; chk rad support mnts; rad mnts move; arms arnd try to space amrs appart; still no luck; fnd A/C compressor. j

Parts	Quantity
101281011GSS6297UM 60# DOOR STRUT QUINT	1
101281012GSS6298UH STRUTS 90#	1
107796DRYER KIT AD9 -NEW	3
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
1891BULB	1
203FFBEARING PULLEY	1
29526898 29548988 TRANS FILTER ALLISON	1
356672HOSE ASSY	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	1
600000003NODE HERCULES V-MUX	1
6737200054673-720-00-54 SEAL WINDOW	5
6805450124SWITCH TURN SIGNAL	1
6806970098SEAL DOOR	1
6808300174VENT A/C RH	1
72R311018-2640 VENT A/C NEW # 1719	1
800405PURGE VALVE KIT	1
8126482-2106 TOGGLE GUARD	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CA8193AIR FILTER 46744 WIX	1
EAA-8350-60UGSS6557UP STRUT-LIFT	1
EAA-8350-90UGSS6558UK STRUT-LIFT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
IMMF11358SEAT BELTS	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
S777COUPLING NIPPLE	1
SPR-W58-1TEE PLASTIC	1
SS-25SC5025 SUCTION SCREEN	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32138

In Date: 05/11/2010 Meter Reading: 34,432.10
Close Date: 06/21/2010

Problem?
pull cord on k-12 (10163569) will not retract e18

Task performed:	Parts	Quantity
Diss side cvr & pull start; fnd cord spool crkd & needs to be replcd; reassem; saw tagged; brought to shop for repair. j	NO PARTS USED	

Workorder: V32747

In Date: 06/08/2010 Meter Reading: 34,879.30
Close Date: 06/22/2010

Problem?
unit throttle not working properley E18

Task performed:	Parts	Quantity
1. C/O truck, hi-idle coming on when startup; chk eng code & V-mux all ok; disconnect cruise control switch; C/O ok; run code & test drive. 2. Left/frnt headlight out; installed new on 6054; all work ok at this time. j	NO PARTS USED	

Workorder: V33081

In Date: 06/23/2010 Meter Reading: 35,446.70
Close Date: 06/25/2010

Problem?
officer's scba bracket broken/will not lock E18

Task performed:	Parts	Quantity
Went to Stn18; fnd bad latch on SCBA bracket; R/R latches on brkt. j	101-124-000CRASH RESTRAINT STRAPS FHLP-6TANK CLIP	1 2

Workorder: V28936

In Date: 01/08/2010 Meter Reading: 10.00
Close Date: 07/08/2010

Problem?
need engine oil at station 18

Task performed:	Parts	Quantity
completed on another wo	15W40QSYN OIL QT	6



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V33854

In Date: 07/28/2010 Meter Reading: 36,107.00
 Close Date: 08/12/2010

Problem?
 pump panel lights 10-7 E18

Task performed:	Parts	Quantity
1. Fnd panel lights out; rep wires at lights; ck ok.	LF18TS-LEDMAP LIGHT LED 18 IN	1
2. Fnd maplight out; R/R maplight; ck ok. ja		

Workorder: V33668

In Date: 07/20/2010 Meter Reading: 35,998.00
 Close Date: 08/13/2010

Problem?
 repair K950 saw (E18) Bat 1 (outside agency-Regan)

Task performed:	Parts	Quantity
Repair K950 saw - Regan ja	NO PARTS USED	

Vendor?: REGAN

Workorder: V35066

In Date: 09/20/2010 Meter Reading: 36,984.30
 Close Date: 09/28/2010

Problem?
 electrical light and indicator switch on left rear door of E18 10-7 (red light and buzzer in cab on all the time)

Task performed:	Parts	Quantity
Went to 18; fnd L/rear door switch brkn; R/R switch; ck opn-ck ok. j	52-624SWITCH DOOR	1

Workorder: V35016

In Date: 09/17/2010 Meter Reading: 36,984.30
 Close Date: 10/05/2010

Problem?
 The tire on the front / driver's side has a significant piece of rubber missing from it on the tread part of the tire. E18

Task performed:	Parts	Quantity
Went to 18; fnd small rubber piece msng; ok. j	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31861

In Date: 04/28/2010 Meter Reading: 34,135.00
Close Date: 10/19/2010

Problem?

1" booster reel cuppling came off . (it was fixed today) . Pump Presure display is missing some parts of numbers . thanks K.C.

Task performed:

Completed j

Parts	Quantity
NO PARTS USED	

Workorder: V32930

In Date: 06/16/2010 Meter Reading: 35,300.60
Close Date: 11/08/2010

Problem?

rope pulled out of k-12 (knot came undone) E18

Task performed:

- Went to 18; diss pull start cvr; fnd cord spool cracked/damaged; was not replc on recent rep; tagged saw & brought to shop.
- DIvrd shop spare J3382 SN 9510096 j

Parts	Quantity
NO PARTS USED	

Workorder: V35282

In Date: 09/30/2010 Meter Reading: 37,274.00
Close Date: 12/22/2010

Problem?

repair ele problem e 18

Task performed:

- TRAVELED TO ST18 TO REPAIR ELE PROBLEM ON E18. FOUND THE PUMP PANEL AND TELESCOPIC LIGHTS FLASHING. FOUND A BAD CONNECTION AT THE SOLENOID AND REPAIRED IT. OK J.W.

Parts	Quantity
NO PARTS USED	

Workorder: V35350

In Date: 10/02/2010 Meter Reading: 37,274.00
Close Date: 12/22/2010

Problem?

k-12 10-7 unable to crank , changed spark plug still 10-7.... E18

Task performed:

- TRAVELED TO ST 18 TO CHECK OUT K12 SAW ON E18 THAT WOULD NOT START. CHANGED THE SPARK PLUG BUT STILL WOULD NOT START. TAGGED THE SAW AND BROUGHT BACK TO THE SHOP. DELIVERED SAW TO ST18. J.W.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V35743

In Date: 10/19/2010
Close Date: 12/22/2010

Meter Reading: 3,778.10

Problem?

Valve broken.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V37160

In Date: 12/14/2010
Close Date: 01/11/2011

Meter Reading: 38,117.10

Problem?

Shore Power Receptical and Battery Charger for engine 18 needs to be installed.

Task performed:

Parts

Quantity

(1) TRAVELED TO ST-18 TO INSTALL SHORELINE POWER ON E18. INSTALLED SHORELINE BATTERY CHARGER, WIRED IT IN, DRILLED & MOUNTED CHARGER IN CENTER CONSOLE.

0913912CHARGER 2000

1

(1) INSTALLED & WIRED AUTO EJECT, CUT & MOUNTED BATTERY CHARGING GAUGE.
J.W.

0915520120AUTO EJECT 20 AERO OTL3925

1

Workorder: V37587

In Date: 01/03/2011
Close Date: 01/18/2011

Meter Reading: 38,117.10

Problem?

replace rear tires boulevard

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37375

In Date: 12/22/2010
Close Date: 02/22/2011

Meter Reading: 38,117.10

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 18

Task performed:

- B-Service
- 2. Fnd trans/eng retard leaking; rem lines, wires & accumlator asy; rebuild retarder; installed; filled trans, test drove; ck ok; rechk level.
- 3. Ck for air leaks; fnd park valve leaking; R/R park valve asy; air compressor fitting leaking; resealed fitting; rep leaks at air gov; ck ok.
- 4. Fnd compt lights out; R/R door switches; ck ok.
- 5. Fnd "A" piller cvr off; rep cvr; R/R wiper blades.
- 6. Fnd compt doors loose; adj/tightened doors - ck ok.
- 7. Fill wtr tank; R/R drivers intake screen.
- 8. Quality check. j

Parts

Quantity

15W40BSYN OIL BULK QTS	24
29535973ACCUM.KIT	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	3
800034VALVE PARKING BRK.	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
SS-25SC5025 SUCTION SCREEN	1

Workorder: V39014

In Date: 03/07/2011
Close Date: 03/21/2011

Meter Reading: 39,281.00

Problem?

the brake is making noise when stopping E18

Task performed:

- 1. Went to 18; test drove; fnd brakes squeeking; ck shoes - ck ok; hoses off brake shoes; test drove; ck ok.
- 2. Went to 18; fnd frnt brakes chattering; adj; test drove; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V38718

In Date: 02/23/2011
Close Date: 03/23/2011

Meter Reading: 39,131.50

Problem?

gas found in oil in the generator power unit. the oil was changed and still oil is cloudy..

Task performed:

- 1. Travel to 18; chk gen - fuel getting into oil with shut off off; will bring spare unit.
- 2. Travel to 18; swapout gen w/spare to get unit rep. j

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38790

In Date: 02/27/2011
Close Date: 03/23/2011

Meter Reading: 39,281.00

Problem?

left front headlight out E18

Task performed:

Replcd headlight. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

2

Workorder: V39489

In Date: 03/28/2011
Close Date: 04/04/2011

Meter Reading: 41,799.70

Problem?

short in wiring on pump panel, unable to turn on p/p lights or scene lights E18

Task performed:

Travel to 18; chk for short in lights - NPF; reprogrammed node & told driver to watch. j

Parts

Quantity

NO PARTS USED

Workorder: V39215

In Date: 03/15/2011
Close Date: 04/08/2011

Meter Reading: 39,281.00

Problem?

REPLACE FRONT TIRE SUPPLIED BY SHOP

Task performed:

Replace front tire - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V39635

In Date: 04/03/2011
Close Date: 04/13/2011

Meter Reading: 41,799.70

Problem?

tailboard door missing 3 out of 4 screws that hold locking mechanism in place are missing therefore the door will not open. E18

Task performed:

Travel to 18; replc msng screws in door latch & handles. j

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39816

In Date: 04/10/2011 Meter Reading: 41,799.70
Close Date: 04/14/2011

Problem?

supplement to last work request: headlights work. BUT, when high beam is turned on, driver's side headlight goes out. R 18

Task performed:	Parts	Quantity
Travel to stn; replc blown headlight asy. j	NO PARTS USED	

Workorder: V40221

In Date: 04/28/2011 Meter Reading: 42,433.00
Close Date: 05/03/2011

Problem?

steering wheel horn/siren controller not functioning properly. difficult to start and stop when needed. R18

Task performed:	Parts	Quantity
Clnd contact for horn button. j	NO PARTS USED	

Workorder: V40294

In Date: 04/30/2011 Meter Reading: 42,433.00
Close Date: 05/13/2011

Problem?

request 2 key's for medical compartment on E18 (tm 700) lock #

Task performed:	Parts	Quantity
Travel to 18; drop off key. j	NO PARTS USED	

Workorder: V40324

In Date: 05/02/2011 Meter Reading: 42,433.00
Close Date: 05/27/2011

Problem?

REPLACE TIRE E18

Task performed:	Parts	Quantity
Replace tire E18 - Tiresoles j	NO PARTS USED	

Vendor?: TIRESOLE



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39814

In Date: 04/10/2011 Meter Reading: 41,799.70
 Close Date: 06/10/2011

Problem?

When battery switch is on, both headlights work. However, turn ignition on, the driver's side headlight goes out.

Task performed:	<u>Parts</u>	<u>Quantity</u>
work completed on WO 39816	NO PARTS USED	

Workorder: V41599

In Date: 06/25/2011 Meter Reading: 42,477.60
 Close Date: 06/30/2011

Problem?

pump panel lights working intermitenly E 18

Task performed:	<u>Parts</u>	<u>Quantity</u>
Chkd pump panel lights - NPF. j	NO PARTS USED	

Workorder: V40578

In Date: 05/12/2011 Meter Reading: 42,433.00
 Close Date: 08/05/2011

Problem?

case motor oil and two quarts of hurst tool hydraulic fluids.

Task performed:	<u>Parts</u>	<u>Quantity</u>
picked up oil and hurst fluid dropped to station	15W40QSYN OIL QT	12
	180R002HURST HYD. FLUID QT	2

Workorder: V42670

In Date: 08/09/2011 Meter Reading: 44,839.10
 Close Date: 08/11/2011

Problem?

Foam not working.....E18. Cpt JP Maxson, Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
foam system needs calibration	NO PARTS USED	

calibrated foam system



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42712

In Date: 08/10/2011

Meter Reading: 44,839.10

Close Date: 08/12/2011

Problem?

pa on radio inop. Sta 18.

Task performed:

travel to 18 replaced siren head

Parts

Quantity

295SLSA1SIREN

1

Workorder: V42583

In Date: 08/05/2011

Meter Reading: 43,053.40

Close Date: 08/15/2011

Problem?

BUNGEE CORD THAT HOLDS THE CUTTERS IN PLACE IS BROKEN. Sta 18.

Task performed:

R/R bungee for Hurst Tool. j

Parts

Quantity

T69-15.5 STRAP FOR TOOL HOLDER

1



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42860

In Date: 08/17/2011

Meter Reading: 56,153.00

Close Date: 08/29/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 18

Task performed:

Parts

Quantity



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

WARRANTY

Rem all body mnts & replc w/new mnts supplied by Horton. j(8/22/11)

2. C-Inspection
3. Diff svc.
4. T-case svc.
5. R-1 pull out step bolts loose; secure loose nut/bolt; chk remaining nut/bolts.
6. Btry tray lock sticking; cln/lube/free up locking mechanism.
7. Trash try froze up; cln/lube/free up locking mechanism.
8. Retorque frnt/rear u-bolts.
9. Fail vac test; intake press relief valve leaking; rem valve; rebuild valve & reinstall; replc chk valve; rem intake/discharge screen; screen clogged; replc screen/retest; prassed 22" to 20.5" five minutes.
10. Air dryer svc.
11. Btry tray has not wtr drain ports; drill drain ports in tray.
12. FRC IO digital PSI suction & discharge asy LED 10-7; rem/diss/swap out face plate; reassem/install; operate console.
13. Rear A/C vent lever msng; rem pieces/install new vent lever asy.
14. A/C filter msng; install new filter asy.
15. Windshield wiper blade & fluid level svc.
16. (1) discharge/intake cap msng & cap chains brkn; isntall replacement caps & chain.
17. Pump panel light lens brkn; rem/install new light lens cvr.
18. Svc gen; chk spark plug(good); chk air clnr (good); chk fuel & tank - good; change eng oil; operate unit & chk output - good.
19. P/S svc.
20. install crosslay net.
21. Rem hose bed cvr for repair; install/rep hose bed cvr to mnt rear straps; replc sev damaged holddown clips.
22. Eng belt svc & tensioners replc.
23. Both A/C belt svc & idler/tensioner pulley bearing svc.
24. Rear brakes svc; replc shoes/drums. road test after brake svc.
25. Rear spring stop support holes at frame rusting. told to cln/inspect & apply rust inhibitor to surface as per E. Ehrke.
26. Driver window molding brkn; rem/install replacement
27. R-1 holdopen loose; rem plate, redrill & tap screw hole & secure holdopen.
28. Deck gun warning inop; fnd wire harness cut & spliced at multiple points; fnd loose grnd in one connector; mk rep & test alarm; working normal.

0100080010STRAINER	2
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	4
203FFBEARING PULLEY	1
35200-RLIGHT MARKER LED RED	1
3576REAR BRAKE DRUMS	2
372000031IGNITION ON DISPLAY	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
546126000TPM/QG HALE REPAIR KIT	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
72R311018-2640 VENT A/C NEW # 1719	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9440BELT	1
9480BELT	1
A1834388002MOLD L/H	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT	1
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
K080716BELT	1
R90PFILTER FUEL 33231	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 29. Heat sealers on grnd ladders all expired; rem sensors & install new heat sensors.
- L-1 compt lock loose; secure loose screws to support door lock.
- 31. Fill wtr tank.
- 32. Tank to pump grease fitting leaking; rem defective grease fittin; install new fitting.
- 33. Tailboard light 10-7; marker light bulb blown; rem/install new bulb.
- 34. ign on indicator out; blown switch bad; replc LED switch asy.
- 35. Pump PSI alarm intermittent; fnd intake PSI (inducer) faulty; rem/install new PSI alarm switch; operate pump - working normal at this time.
- 36. ok to pump light flickering; chk sys - light operating normal & is on as unit runs; no fault fnd.
- 27. Quality check. j(8/30/11)

Workorder: V43184

In Date: 08/31/2011 **Meter Reading:** 43,521.80
Close Date: 09/07/2011

Problem?

Gas powered Ram Fan won't stay running. Will only run when on choke and will not run when trottle is increased. Asset #10155563 Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
travel to 18 picked up ram fan	NO PARTS USED	

Workorder: V43458

In Date: 09/06/2011 **Meter Reading:** 43,521.80
Close Date: 09/08/2011

Problem?

Discharge # 3 lever disconnected, all rods are present. The bolt connecting the rod to the valve is missing, Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
replaced missing bolt in linkage	NO PARTS USED	

Workorder: V43459

In Date: 09/06/2011 **Meter Reading:** 43,521.80
Close Date: 09/08/2011

Problem?

Right rear marker light not working. Red bullet shaped LED light, top right rear. Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
travel to 18 r&r marker light	372000084MARKER LIGHT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V43535

In Date: 09/09/2011

Meter Reading: 43,521.80

Close Date: 09/12/2011

Problem?

Hurst power unit not running. Sta 18.

Task performed:

Parts

Quantity

travel to st 18 try to clean out carb air clean plug still cant get going call rob to bring spair unit return to shop

NO PARTS USED

travel to st 18 drop off spa-hurst unit

Workorder: V43460

In Date: 09/06/2011

Meter Reading: 43,521.80

Close Date: 09/15/2011

Problem?

Headliner in the rear of the cab is saging down. All clips are missing. Sta 18.

Task performed:

Parts

Quantity

travel to 18 replaced missing support pins for head liner

22-51950-000HEADLINER RETAINER PLUG

6

23-12337002RIVET PLASTIC

6

Workorder: V43712

In Date: 09/16/2011

Meter Reading: 43,979.10

Close Date: 09/19/2011

Problem?

Right side spot light at pump panel inop, door alarm going off when parking brake released. Sta 18.

Task performed:

Parts

Quantity

1. Travel to 18; dia/rep wet connection to sensor.

353R091USE 353R403 HURST HOSE 16 GREEN

1

2. Rep spotlight on drivers side; installed new bulbs.

LB-D30BULB QUARTZ HAL. 12V 150W

2

j

Workorder: V43810

In Date: 09/20/2011

Meter Reading: 43,979.10

Close Date: 09/26/2011

Problem?

hurst unit inop also need hurst oil e 18

Task performed:

Parts

Quantity

TRAVEL TO 18 UNIT RUNS FINE ???

180R002HURST HYD. FLUID QT

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44194

In Date: 10/06/2011 Meter Reading: 44,341.00
Close Date: 10/07/2011

Problem?
ON CALL ELECTRICAL PROBLEM E 18

Task performed:	<u>Parts</u>	<u>Quantity</u>
TRAVEL TO ST 18 DIAGNOSE PROBELM WITH LIGHTS FOUND #2 NODE BAD INSTALL NEW NODE AND DOWNLOAD PROGRAM TEST SYTEM OK TRAVEL HOME	600000003NODE HERCULES V-MUX	1

Workorder: V44253

In Date: 10/10/2011 Meter Reading: 44,341.00
Close Date: 10/18/2011

Problem?
pump panel lights and telescopic lights flickering when pump is engaged E 18

Task performed:	<u>Parts</u>	<u>Quantity</u>
TRAVEL TO 18 FOUND MOISTURE IN CONNECTORS	NO PARTS USED	

Workorder: V44326

In Date: 10/12/2011 Meter Reading:
Close Date: 10/18/2011

Problem?
need diesel engine coolant, Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
DROPPED OFF COOLENT TO STATION	NO PARTS USED	

Workorder: V44338

In Date: 10/12/2011 Meter Reading:
Close Date: 10/18/2011

Problem?
pump panel lights and telescopic lights not working while pump is engaged, Sta 18.

Task performed:	<u>Parts</u>	<u>Quantity</u>
SEE RIO # V44253	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44379

In Date: 10/14/2011

Meter Reading:

Close Date: 10/18/2011

Problem?

right-side headlight out (works with highbeam only). no replacement lamps in station. Sta 18.

Task performed:

R&R HEADLIGHT LEFT SPARE AT STATION

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

3

Workorder: V44416

In Date: 10/16/2011

Meter Reading:

Close Date: 10/18/2011

Problem?

pump panel lights, and telescopic scene lights not working when pump is engaged. E 18

Task performed:

travel to 18 check out light problem check out node, y connector, etc. check interlocker R&R park brake switches on brake valv test ok

Parts

76577-4-NC76577-4-NC SWITCH

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

Quantity

1

1

Workorder: V44682

In Date: 10/25/2011

Meter Reading:

Close Date: 10/28/2011

Problem?

Need to replaced to tire pressure gauge doesn't work. Sta 18.

Task performed:

travel to st 18 replaced air gauge

Parts

516TIRE INFLATOR

7ELTUBE7ELTUBE LINEAR STROBE REF

S777COUPLING NIPPLE

TURB6HALSTROBE

Quantity

1

1

1

1

Workorder: V45071

In Date: 11/09/2011

Meter Reading: 46,563.20

Close Date: 11/10/2011

Problem?

REPLACE TIRES BOULEVARD

Task performed:

Replace tires - Boulevard

j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45187

In Date: 11/15/2011 Meter Reading:
Close Date: 11/21/2011

Problem?
Tank to pump handle broke off. Sta 18.

Task performed:	Parts	Quantity
found bolt holding linkage broken off repaired retapped hole installed new bolt	NO PARTS USED	

Workorder: V45377

In Date: 11/23/2011 Meter Reading:
Close Date: 11/30/2011

Problem?
Need engine coolant, put in what we had here at the station. That was not enough to bring up to the sight glass ! Sta 18

Task performed:	Parts	Quantity
delievered coolant to station	NO PARTS USED	

Workorder: V45342

In Date: 11/21/2011 Meter Reading:
Close Date: 12/05/2011

Problem?
The LED for the spare battery charger on the TIC cradle is not illuminating- possibly not charging. Thanks. Sta 18.

Task performed:	Parts	Quantity
travel to 18 replaced tic charger	NO PARTS USED	

Workorder: V45746

In Date: 12/09/2011 Meter Reading:
Close Date: 12/15/2011

Problem?
Air brake system is leaking down rapidly. Sta 18

Task performed:	Parts	Quantity
TRAVEL TO 18 REPAIRED AIR LINE LEAK.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45983

In Date: 12/20/2011 Meter Reading: 47,599.70
Close Date: 12/20/2011

Problem?
Replace coolant filter assembly.

Task performed:	Parts	Quantity
DRAINED COOLANT, REPLACED COOLANT, FILTER HOUSING, REFILLED COOLING SYSTEM AND LEAK CHECKED.	PR338324070 WIX FILTER WATER	1

Workorder: V45747

In Date: 12/09/2011 Meter Reading:
Close Date: 12/21/2011

Problem?
Adding approx. 1 quart of engine coolant evry other shift. Sta 18

Task performed:	Parts	Quantity
CHECKED COLLANT LEAK AND ORDERRED PARTS.	3937367GASKET 4942874	1
	39437384940575 HEAD CORROSION RESISTER	1
	39437394940547 SHAFT SHUT-OFF VALVE	1
	3943740SHAFT SHUT-OFF VALVE	1
	39438574989614 SEAL O-RING SHUT-OFF VALVE	1
	39444543977737 SCREW SHUTOFF VALVE	1
	4989614O-RING SHUT-OFF VALVE	2
	ANTICOOLANT ANTIFREEZE GAL	8

Workorder: V41634

In Date: 06/27/2011 Meter Reading: 42,477.60
Close Date: 12/22/2011

Problem?
digital pressure gauge inop. Sta 18.

Task performed:	Parts	Quantity
ORDERED PARTS.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V46148

In Date: 12/28/2011

Meter Reading: 47,749.70

Close Date: 12/29/2011

Problem?

Coolant leak

Task performed:

REMOVED FILTER HOUSING FOUND O-RING NOT SEATED DUE TO SCREW BEING TO LONG. DRILLES SCREW HOLE DEEPER. REINSTALLED. CHECKED OK.

Parts

Quantity

3937367GASKET 4942874	1
39444543977737 SCREW SHUTOFF VALVE	1
PR338324070 WIX FILTER WATER	1

Workorder: V47019

In Date: 02/01/2012

Meter Reading: 59,681.00

Close Date: 02/02/2012

Problem?

front a.c. fan blower not working, Sta 18

Task performed:

TRAVEL TO STA 18. WAIT FOR ENGINE TO ARRIVE REMOVED DASH FOUND BURNT WIRE AND SWITCH TERMINAL. REPLACED SWITCH AND CRIMP NEW TERMINAL ON WIRE. CUT AWAY TERMINAL BLOCK FOR CLEARANCE ON NEW WIRE TERMINAL. INSTALL DASH AND TEST (OK). REPLACED PART FROM PARTS COUNTER AND RESTOCK SERVICE TRUCK.

Parts

Quantity

6805450828PLUG A/C BLR	1
7821-3440TERM END A/C BLOCK	2
ABPN8332229011-3050 SWITCH BLOWER	1

Workorder: V47103

In Date: 02/06/2012

Meter Reading: 59,795.00

Close Date: 02/28/2012

Problem?

one of the air horns is out.Sta 18

Task performed:

ADJUSTED AIR HORNS.

Parts

Quantity

1094KIT-AIR HORN-GROVER	2
-------------------------	---



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47136

In Date: 02/06/2012
Close Date: 02/28/2012

Meter Reading: 59,795.00

Problem?

backup alarm stuck on

Task performed:

1. TRAVEL TO STA 18 FROM 27. REMOVE COVERS TO CHECK ELECTRICAL. E18 CALLED OUT. TRAVEL TO 19 AND BACK TO 18. INSTALL COVERS OK FOR TONIGHT.
2. TRAVEL TO STATION CHECK WIRING FOUND WATER IN PLUG IN HARNESS REPAIRED.

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V47260

In Date: 02/13/2012
Close Date: 02/28/2012

Meter Reading: 60,054.00

Problem?

leaking water again from l side 3" intake suction. Continuous leak to bay floor. Cpt JP Maxson #7796 E 18

Task performed:

COULD NOT DUPLICATE.

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V47372

In Date: 02/16/2012
Close Date: 02/29/2012

Meter Reading: 59,012.00

Problem?

started engine this morn, one air bank low. ran engine for several minutes. started engine 3 hrs later, both air banks totally empty. this is new. E18's air banks have not been a problem in the past. E18

Task performed:

CHECKED UNIT FOUND VALVE FOR AIR DRAIN NOT SHUT. A/C THE WAY CLEANED CHECKED OK.

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V47613

In Date: 02/28/2012
Close Date: 03/06/2012

Meter Reading: 60,452.00

Problem?

left-side rear compartment door latch 10-7. only right-side latch is holding doors closed. R18

Task performed:

FOUND BOLTS HOLDING NADER PIN MISSING DRILLED NEW HOLES TAPPED AND REBOLTED.

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47616

In Date: 02/28/2012 Meter Reading: 60,452.00
Close Date: 03/06/2012

Problem?
right and left scene lights not working properly. lights on when battery switch turned on, and lights switch in "off" position. when yo turn lights to "on", they turn off. E 18

Task performed:	Parts	Quantity
FOUND SWITCHES NOT IN RIGHT POSITION - CHECKED WIRING ON OPERATION.	NO PARTS USED	

Workorder: V47729

In Date: 03/03/2012 Meter Reading: 60,551.00
Close Date: 03/08/2012

Problem?
right rear outside tire low on tread. At or below wear bars. E 18

Task performed:	Parts	Quantity
RIGHT REAR OUTSIDE TIRE LOW ON TREAD. AT OR BELOW WEAR BARS. E 18	NO PARTS USED	
Vendor?: BOULEVARD TIRE CENTE		

Workorder: V45979

In Date: 12/20/2011 Meter Reading: 47,599.70
Close Date: 03/12/2012

Problem?
Replace pressure guages on pump panel. Sta 18

Task performed:	Parts	Quantity
	10206120FT HARNESS	2
	PSISDIDITAL VACUUM GAUGE KIT	2

Workorder: V47803

In Date: 03/07/2012 Meter Reading: 60,551.00
Close Date: 03/19/2012

Problem?
need 2 cases of oil for sta 18 E/R, Sta 18

Task performed:	Parts	Quantity
DELIVERED OIL	15W40QSYN OIL QT	12



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48405

In Date: 04/03/2012 Meter Reading: 61,191.00
Close Date: 04/10/2012

Problem?
rt headlight high beam does not work when emergency lts are on.works when emer.lts are off. r18

Task performed:	Parts	Quantity
REPLACED HEADLIGHT BULB LEFT SPARE BULB FOR STATION.	H6054USE CV TYPE SEALED BEAM	2

Workorder: V48625

In Date: 04/12/2012 Meter Reading: 61,318.80
Close Date: 04/25/2012

Problem?
breaks bleed down to zero. both tanks. not always but twice today. E 18

Task performed:	Parts	Quantity
INSTALLED NEW PURGE VALVE.	NO PARTS USED	

Workorder: V48746

In Date: 04/18/2012 Meter Reading: 61,419.00
Close Date: 04/25/2012

Problem?
rubber hold down strap for jaws is broken. E 18

Task performed:	Parts	Quantity
REMOVED BROKEN STRAP INSTALLED NEW STRAF	NO PARTS USED	

Workorder: V48807

In Date: 04/22/2012 Meter Reading: 61,536.00
Close Date: 04/25/2012

Problem?
driver's side: side emergency light (located between the two scba compartments) not working. E18

Task performed:	Parts	Quantity
1. TRAVEL TO 18 CHECKED ????? ALARM. WORKING FINE COULD NOT DUPLICATE PROBLEM. 2. CHECKED EMERGENCY LIGHTS FOUND LEFT ??? ??? LIGHT OUR REPAIRED LIGHT AND TESTED OK.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48838

In Date: 04/23/2012
Close Date: 04/25/2012

Meter Reading: 61,536.00

Problem?

Back up alarm stuck on

Task performed:

CHECKED ALL MULTIPLEX COMM CONNECTORS FOR WATER R&R NODE 4 AND CHECK CONNECTIONS AT NODE.

Parts

NO PARTS USED

Quantity

Workorder: V48947

In Date: 04/27/2012
Close Date: 04/30/2012

Meter Reading: 61,536.00

Problem?

rt side telescoping It has 1 halagon bulb out. E18

Task performed:

REPLACED BLOWN BULB IN LEFT TELE LIGHT.

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1

Workorder: V48530

In Date: 04/09/2012
Close Date: 05/07/2012

Meter Reading: 61,191.00

Problem?

halogen bulb out on rt side scene It. rt side head light does not work on high beam when emergency lts on.

Task performed:

CHECKED DOME LIGHTS INSTALLED NEW BULB AND HEADLIGHT.

Parts

030126FLASHER SHO-ME

360HLOBSOLETE FLASHER

Quantity

1

1



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49083

In Date: 05/03/2012

Meter Reading: 61,536.00

Close Date: 05/29/2012

Problem?

B INSPECTION E18

Task performed:

1. PERFORM "B" SERVICE.
2. B-SERVICE AND CHECK PUMP FOR VAC FAIL.
3. ADJUST AND TIGHTEN A/C BELTS, TIGHTEN A/C BOLTS ON COMPRESSOR. LOOSE. REMOVE REAR SEAT FOR REWORK RIPPED.
4. REPAIR WIRES TO TRANS TEMP SWITCH RIPPED OFF FROM DRIVE SHAFT. REPAIR OIL PLUG LEAK.
5. REMOVE AND REPLACE OF SEAT SENT IN FOR REPAIR.
6. R&R AIR FILTER FROM MONT TO INSTALL NEW DRY AIR FILTER AND REINSTALL.
7. R&R ALL FOUR DOOR TRIM LEDGES, REMOVE DOOR PANEL TO INSTALL THEM. REINSTALL.
8. R&R DOOR SEAL ALL DOORS, REMOVE DOOR STEP CUT RUBBER SEAL TO FIT, INSTALL, R EPLACE DOOR STEP COMPLETE.
9. REMOVE A/C VENT IN DASH GET NEW ONE AND INSTALL REPLACE REAR CAB A/C FILTER, REPLACE THE REAR A/C VENT.
10. TEST OUT FIRE PUMP FOUND LEAKS IN VALVE AND GEASE FITTING, FOUND CHECK VALVE LEAKING BACK INTO FOAM TANK, DRAIN TANKS START TO REPAIR VALVE AND CHECK VALVE.
11. REPLACE CHECK VALVE TO FOAM SYSTEM REPLACE BUTTERFLY VALVE ON PUMP MANAFOLD. CLEAN FACE FROM RUST, DUBBE GASKET RETEST UNIT FOUND SOME LEAK IN BUTTERFLY VALVE REPAIR REPLACE GREASE FITTING IN VALVE LEAK WATER UNDER PRESSURE, RECHECK VAC TEST PASS TEST OK.
12. FILL UP FOAM SYSTEM, FILL UP PUMP AND TANK WITH WATER, RUN SYSTEM FLOW FROM TEST ARE WORK OK.
13. ADDITIONAL REPAIR AFTER Q.A. OF TRUCK. PRIMER STICKING REMOVE AND CLEAN LUBE REINSTALLED.
14. FOAM SYSTEM NOT FLOWING RIGHT RECALIBRATION OF UNIT RECHECK OK.
15. DRAIN VALVE HANDLE MISSING LABLE, REMOVE FROM PARTS TRUCK INSTALLED ON PUMP PANEL HAD TO HEAT TO GET OFF OF BOTH TRUCK TO REMOVE.
16. Q. &A.
17. REMOVE DASH PANEL TO REPLACE WIPER WASHER SWITCH.

Parts

Quantity

038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
0381570000038-1570-06-0 VALVE CHECK 3 IN 9003-1	1
0460050000GASKET	2
064615900006-46159-001 SWITCH WIPER	1
0714021GASKET 2 1/2"	1
0769027STRAINER 2.5 IN	1
082-2007-00-0GREASE ZERK W/CHECK VLV	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CA8193AIR FILTER 46744 WIX	1
LB-D30BULB QUARTZ HAL. 12V 150W	1
R90PFILTER FUEL 33231	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50591

In Date: 07/04/2012 Meter Reading: 62,700.00

Close Date: 08/01/2012

Problem?

both air banks (brakes) bleeding down to zero again. E 18

Task performed:

WORK DONE ON 50647.

Parts	Quantity
NO PARTS USED	

Workorder: V50647

In Date: 07/06/2012 Meter Reading: 62,700.00

Close Date: 08/01/2012

Problem?

both air brake banks leak down to zero.

Task performed:

CHECKED TRUCK FOR AIR LEAKS REPAIRED SMALL AIR LEAK.

Parts	Quantity
NO PARTS USED	

Workorder: V51198

In Date: 07/30/2012 Meter Reading: 63,173.00

Close Date: 08/01/2012

Problem?

TIC screen comes up blanck, not working. R 18

Task performed:

DROPPED OFF NEW TIC AT STATION.

Parts	Quantity
NO PARTS USED	

Workorder: V50590

In Date: 07/04/2012 Meter Reading: 62,700.00

Close Date: 08/03/2012

Problem?

fuel gauge not working properly. just filled, can show as low as 3/4 or less. E 18

Task performed:

INSTALLED NEW SENSOR.

Parts	Quantity
22-27156-000GASKET FUEL SENDER	1
A2243065003FUEL SENDING UNIT	1



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50713

In Date: 07/10/2012 Meter Reading: 62,700.00
Close Date: 08/03/2012

Problem?

at pump panel, tank water level top light (full) is out. E18

Task performed:

INSTALLED NEW WATER LEVEL GAUGE AND CALIBRATED WITH NEW TRANSDUCER - FILES OPENING TO FIT NEW GAUGE.

Parts	Quantity
WL2000WLA200-A00 WATER TANKVISION OLD FERR # 35:	1

Workorder: V51355

In Date: 08/03/2012 Meter Reading: 63,173.00
Close Date: 08/06/2012

Problem?

e18 tailboard 2 1/2" hose connector 10-7

Task performed:

TRAVEL TO 18 REPLACED 2 1/2 SPRING LOCK FOR REAR HOSE.

Parts	Quantity
NO PARTS USED	

Workorder: V52528

In Date: 09/20/2012 Meter Reading:
Close Date: 09/24/2012

Problem?

loose fan belt and low starting battery. R 18

Task performed:

BELTS FINE.

Parts	Quantity
NO PARTS USED	

Workorder: V52674

In Date: 09/27/2012 Meter Reading:
Close Date: 10/01/2012

Problem?

turn signals 10-7. worked this morning now no signal. E18

Task performed:

TRVL TO 18 FOUND SIGNAL SWITCH COVER LOOSE ADJUSTED COVER OK.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52722

In Date: 09/30/2012 Meter Reading: 69,300.00
Close Date: 10/04/2012

Problem?
SIREN: hands-free controller on steering wheel not working properly. E 18

Task performed:	Parts	Quantity
CHECKED SIREN FOUND NO PROBLEM.	NO PARTS USED	

Workorder: V52745

In Date: 10/01/2012 Meter Reading: 69,300.00
Close Date: 10/04/2012

Problem?
engine 18 is slow to start, hesitates off key turn. once running it is fine.

Task performed:	Parts	Quantity
TRAVEL TO 18 R&R BATTERIES.	BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY	4
	HP-31D BATTERY 950CCA HP-31D	4

Workorder: V52869

In Date: 10/05/2012 Meter Reading:
Close Date: 10/12/2012

Problem?
DeWalt reciprocating saw battery pack (DW0242), charger shows "REPLACE PACK".

Task performed:	Parts	Quantity
TRVL TO 18 DELIVER PLUY BATTERY.	NO PARTS USED	

Workorder: V53039

In Date: 10/12/2012 Meter Reading:
Close Date: 10/16/2012

Problem?
spot light on top of cab 10-7. E18

Task performed:	Parts	Quantity
CHKD SPOT LIGHT.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53065

In Date: 10/14/2012 Meter Reading:
Close Date: 10/16/2012

Problem?

Spot light on top of the truck is out E 18

Task performed:	Parts	Quantity
REPLACED BROKEN SPOT LIGHT ON E18.	620122SPOT LIGHT REMOTE	1

Workorder: V53112

In Date: 10/16/2012 Meter Reading:
Close Date: 10/17/2012

Problem?

hurst tool power unit mounting bolts to carry cage not snapped off (not attached). E18

Task performed:	Parts	Quantity
REPLACED HURST POWER UNIT MOTO MOUNTS AND FEET.	377R054FEET - HURST TOOL	1
	HR149460107MOUNT VIBRATION (NEWER POWER UNITS	8

Workorder: V53330

In Date: 10/26/2012 Meter Reading: 64,977.00
Close Date: 11/01/2012

Problem?

tank to pump lever can't be moved, while on the hydrant

Task performed:	Parts	Quantity
TRAVEL TO 18 TRUCK HAS HOLE VALVE TO BE REPLACED AT NEXT SERVICE.	NO PARTS USED	

Workorder: V53821

In Date: 11/16/2012 Meter Reading: 65,231.00
Close Date: 11/20/2012

Problem?

cant open tank to pump when connected to hydrant pressure E18

Task performed:	Parts	Quantity
WENT TO 18 FOUND LINKAGE ARM VERY LOOSE - TIGHTENED ARM AND LINKAGE - CHECK OK.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53855

In Date: 11/18/2012 Meter Reading: 54,246.00
Close Date: 11/20/2012

Problem?
both air banks (brakes) leaking down. E18

Task performed:

CHECK FOR AIR LEAKS - SPRAYED FITTINGS, LINES ETC. FOUND PARK VALVE LEAKING REMOVED DASH PANELS, LINES, WIRES AND VALVE. SWAPTED FITTINGS - REPLACED VALVE - RAN AND CHECK OK.

Parts	Quantity
800034VALVE PARKING BRK.	1
HDY-H005700SOLENOID HORN AIR	1

Workorder: V54050

In Date: 11/28/2012 Meter Reading:
Close Date: 11/30/2012

Problem?
air leak e18

Task performed:

TRAVEL TO 18 REPLACED CAB AIR BAGS.

Parts	Quantity
LML-1102-0023CAB AIR BAG IS4007	2

Workorder: V54018

In Date: 11/27/2012 Meter Reading:
Close Date: 12/04/2012

Problem?
air banks (brakes) still leaking down. E18

Task performed:

CHECKED OK.

Parts	Quantity
NO PARTS USED	

Workorder: V54168

In Date: 12/03/2012 Meter Reading:
Close Date: 12/04/2012

Problem?
hurst tool power unit shuts off when throttle is put in "run" position. r18

Task performed:

- TRAVEL TO 18 WAITED ON TRUCK TO SHOW UP WAITED FOR 30 MINUTES LEFT.
- TRAVEL TO 18 AGAIN REPAIRED HURST UNIT FUEL SYSTEM. REPLACED FUEL SHUT OFF GASKE

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53908

In Date: 11/20/2012
Close Date: 12/06/2012

Meter Reading:

Problem?

Bad air leak from the pump change over switch. Had air leak issue yesterday. E18

Task performed:

WENT TO 18, FOUND PUMP SHIFT LEAKING. TIGHTENED SHAFT AND REPAIRED FITTING- CHK OK.

Parts

NO PARTS USED

Quantity

Workorder: V54422

In Date: 12/13/2012
Close Date: 12/18/2012

Meter Reading: 54,731.50

Problem?

door alarm going off e 18

Task performed:

TRAVEL TO 18 REPAIRED SHORTED WIRE FOR DOOR ALARM.

Parts

9947-0090REEEL BRAKE

Quantity

2

Workorder: V54582

In Date: 12/23/2012
Close Date: 12/28/2012

Meter Reading: 65,900.00

Problem?

in cab fuel gauge not working properly. E18

Task performed:

TRAVEL TO 18 AND CHECKED FUEL GAUGE.

Parts

NO PARTS USED

Quantity

Workorder: V54721

In Date: 01/01/2013
Close Date: 01/04/2013

Meter Reading:

Problem?

gas powered fan runs fine but needs to be in half choke position. shuts down in off position. Tried to enter this in equipment area but not able to enter asset number. E 18

Task performed:

TRAVEL TO 18 FOUND FUEL BAD AND FUEL LINE SHOT PICKED UP UNIT TO BRING TO SHOP.

Parts

16957-ZE1-812HONDA FUEL GROMET

Quantity

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V54973

In Date: 01/10/2013
Close Date: 01/14/2013

Meter Reading: 55,107.80

Problem?

need a case of oil

Task performed:

TRAVEL TO 18 DROPPED OFF CASE OF OIL.

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V55183

In Date: 01/21/2013
Close Date: 01/24/2013

Meter Reading: 55,329.00

Problem?

one (bottom gauge) air bank leaking down again.

Task performed:

TRAVEL TO 18 CHECKED FOR AIR LEAKS REPAIRED SEVERAL LOOSE FITTINGS.

Parts

NO PARTS USED

Quantity

Workorder: V55669

In Date: 02/09/2013
Close Date: 02/14/2013

Meter Reading:

Problem?

left side.(driver side) bulb burned out on spotlight E18

Task performed:

REPAIRED SPOT LIGHT W/U CONNECTION.

Parts

NO PARTS USED

Quantity

Workorder: V55728

In Date: 02/12/2013
Close Date: 02/14/2013

Meter Reading:

Problem?

driver side telescoping scene light has bulb out.

Task performed:

TRAVEL TO 18 REPLACED SCENE LIGHT BULBS.

Parts

CLR9185209186-1500-20 MARKER LT.AMBER LED
LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1
2



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55788

In Date: 02/15/2013

Meter Reading: 66,892.40

Close Date: 02/19/2013

Problem?

Back up alarm stuck on again. Might stop if it dries out, but for now its stuck on. E-18

Task performed:

TRAVEL TO 18 REPAIRED WATER IN CONNECTION
OK.

Parts

NO PARTS USED

Quantity

Workorder: V55789

In Date: 02/15/2013

Meter Reading: 66,892.40

Close Date: 02/20/2013

Problem?

Air leak under the cab. Constant leak can be heard. E-18

Task performed:

- CHECKED FOR AIR LEAK FOUND LEVELING VALVE LEAKING WILL ORDER PARTS.
- TRAVEL TO 18 REPLACED CAB LEVELING VALVE

Parts

LML-1350-0113AIR RIDE VALVE (CAB)

Quantity

1

Workorder: V56259

In Date: 03/08/2013

Meter Reading: 55,420.00

Close Date: 03/12/2013

Problem?

Officers door arm rest and handle. Forward bolt has pulled through. Not enough plastic remaining to secure with washer. E-18

Task performed:

TRAVEL TO 18 R&R DOOR HANDLE OFFICERS FOOI

Parts

6807200575HANDLE DOOR

Quantity

1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56359

In Date: 03/12/2013

Close Date: 03/22/2013

Meter Reading: 67,509.00

Problem?

C inseption E18

Task performed:

Parts

Quantity



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C-Inspection extra time greasing Hale valves and repairing tire valve core leaks.
2. Batteries tested bad. Replaced batteries.
3. Remove passenger seat and tag for repair.
4. Remove hose bed cover and tag for repair.
5. Replaced trans cooler. Replaced lower hoses and clamps connected to cooler.
6. Remove upper hoses and pump/engine cooler. Tighten loose clamps on hoses to water pump.
7. Cut upper hoses to size. Clean rust from Elbos install hoses and new clamps. Fill cooling system. Pressure check system. Wash motor of oil and coolant. Inspect for leaks.
8. Replaced wiper blades.
9. Remove drivers door panel and replaced broken trim piece.
10. Tail pipe bracket bolts worn through bracket. Install new bolts, washers, and lock nuts. Position bracket in place and tighten. Replace exhaust clamp at bell housing.
11. License plate falling off. Install new bolts, washers and lock nuts.
12. Repair threads in R-1 door trim piece and tighten all screws.
13. Tighten R-3 shock mount, L-1 tool bracket, and R-3 tray slide bolts. Add acorn nut missing.
14. Replaced belts and tensioner. R&R air cleaner.
15. T-Case service.
16. Rebuild dryer and replaced purge valve.
17. Relocate L-rear brake hose and protect with scrap water hose cover. Relocate and cover trans cooler lines
18. Bend bracket holding trans cooler lines at bell housing to ceep bracket from cutting hoses.
19. Torque u-bolts.
20. Back-up alarm in/op. Found connector unplugged at alarm. Connect alarm and tie strap harness. Test ok.
21. Power steering service.
22. Replace rear a/c filter. fabricate protective grill for filter.
23. Tighten rear compt. door hold open shock tighten L-3 compart. door shock.
24. Repair Hurst tool brackets. Replaced rings and broken pin cables. Missing one pin. Cannot get parts for these brackets any more.
25. Drain water tank. Air pump and check for leaking valves. Rebuild tank fill valve. Adjust stops on other valves. Perform dry vac test ok.
26. Drain foam tank. Removed foam hose inside pump panel and replaced foam tank float. Re-install hose.
27. Assist in foam tank float install.
28. Remove accredited decals and glue off doors.
29. Install officer's seat.
30. Install hose bed cover and change out hold down strap in rear.

038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
0381570000038-1570-06-0 VALVE CHECK 3 IN 9003-1	1
0401540000O-RING FOR HALE FOAM PUMP	1
0460050000GASKET	2
05-16423-000HOSE LOWER RADIATOR	2
107796DRYER KIT AD9 -NEW	1
14022-1-5COOLER 14032	1
15W40BSYN OIL BULK QTS	25
200-2491-00SENSOR HALE HPF FOAM FLOW	1
2510-0032FOAM PRO TANK FLOAT SENSOR	1
357884 IN CLAMP	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
5462270020VALVE KIT SS 546-2270-02-0	2
6806840018DOOR SILL L/H	1
71R755011-2624 TRINARY SWITCH A/C 1560	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9440BELT	1
9480BELT	1
A1834388002MOLD L/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2
WAT61403STRAINER 6 IN	1
PR338324070 WIX FILTER WATER	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
K080716BELT	1



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 31. Help Mac install seat.
- 32. Replace light box chargers.
- 33. Diagnose problem with foam in pump. Fill foam tank with water and check for leaking tank into water tank (ok) check valve for flush. ok.
- 34. Replaced L-rear threshold panel.
- 35. Rear a/c warm - found leaks at trinary switch and high side compressor fitting. Recover freon - replaced trinary switch. Removed high side compressor fitting and replaced O-ring. Vacuum system and charge.
- 36. Diagnose no condenser fans - found both fans bad. Replaced fan motors.
- 37. Foam pump in/op. Test pump in simulation mode. Pump runs slow and pauses then starts again. Check sensor for blinking ok.
- 38. Check trans codes - could not connect no program in computer. Check codes against code book - found inactive level sensor.
- 39. Repair air leaks at push on connectors and seal threads on pipe threads.
- 40. Further diagnose foam getting into pump and water tank. Checked level of foam tank ok. Opened valve for foam water going into pump. Removed injector valve (Bad) Replaced injector valve. Removed foam pipe flapper check valve (Bad). Replaced flapper check valve. Fill water tank and tried to calibrate water flow sensor. Would not read the same after calibrating several times. Replaced sensor and recalibrated. Checked several times (ok). Put foam pump in simulated mode pump runs slow. Removed pump and cleaned gears and sensor wheels. Checked sensor gap and condition (ok). Reassemble. Drain water and fill foam tank withfoam calibrate feed back sensor. Display said 37 gal after flowings.
- 41. Calibrate feed back and re-check ok. Refill foam tank. Test foam system from hose real (ok).

Workorder: V56561

In Date: 03/21/2013 **Meter Reading:** 67,509.00
Close Date: 03/22/2013

Problem?

continued repairs from C inspection wo# 56359

Task performed:

- 42. ACTIVE CODE 14-23 TRANS LEVEL. DISCONNECTED TRANS PLUG AND CHECKED PINS OK. RECONNECT PLUG CODE IS NOW INACTIVE. ERASE INACTIVE CODE.
- 43. ADJUST AIR HORNS FOR SOUND QUALITY.
- 44. TOP OFF WATER TANK
- 45. Q. & A.

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56783

In Date: 04/02/2013 Meter Reading: 67,509.00
Close Date: 04/09/2013

Problem?
TIC NOT CHARGING IN CHARGER. NEED SPARE TIC BATTERY.E18

Task performed:	Parts	Quantity
TRAVEL TO 18 REPLACED TIC CHARGER TIC STILL NOT CHARGING WILL TEST WITH ANOTHER T??	NO PARTS USED	

Workorder: V56831

In Date: 04/04/2013 Meter Reading: 56,987.00
Close Date: 04/11/2013

Problem?
pump discharge gauge reads 470 and 0. does not change. pumps water so not out of service. E-18

Task performed:	Parts	Quantity
1. TRAVEL TO 18 CHECKED GAUGES FOUND GAUGE BAD. ORDERED PARTS.	PSISDIDITAL VACUUM GAUGE KIT	1
2. TRAVEL TO 18 REPLACED SENSOR, GAUGE, AND HARNESS FOR PRESSURE GAUGE.		

Workorder: V55768

In Date: 02/14/2013 Meter Reading: 66,892.40
Close Date: 04/22/2013

Problem?
repair signs

Task performed:	Parts	Quantity
TRAVEL TO 18 REMOVED SIGNS PUT NEW ROD BACKING AND NUMBERS ON BACK OF OLD SIGN OK.	NO PARTS USED	

Workorder: V57331

In Date: 04/29/2013 Meter Reading:
Close Date: 05/02/2013

Problem?
right-side rear, upper, cone-shaped, red, running light very dim.E18

Task performed:	Parts	Quantity
TRAVEL TO 18 REPLACED MARKER LIGHT.	372000084MARKER LIGHT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58398

In Date: 06/13/2013 Meter Reading: 58,555.00
Close Date: 06/18/2013

Problem?
ASSIST CREW WITH 5 INCH HOSE E 18

Task performed:	Parts	Quantity
HELPED CREW LOAD 5" HOSE ON TRUCK ADJUSTED DIVIDERS, MOUNTED SPANNER WRENCHES. USED FORK LIFT TO BRING HOSE TO TRUCK.	NO PARTS USED	

Workorder: V58549

In Date: 06/19/2013 Meter Reading: 58,660.00
Close Date: 07/03/2013

Problem?
wheel chock cracked to unusable - need new chocks. And, E18 DOES NOT HAVE wheel chock brackets mounted. e18

Task performed:	Parts	Quantity
1. TRAVEL TO 18 HAD WRONG WHEEL CHOCKS WILL RETURN WITH PROPER CHOCKS. 2. DROP OFF WHEEL CHOCKS TO 18.	NO PARTS USED	

Workorder: V59121

In Date: 07/16/2013 Meter Reading: 70,255.00
Close Date: 07/19/2013

Problem?
left-side rear (red) flashing warning light out. located above tail-lights, below hosebed.

Task performed:	Parts	Quantity
TRAVEL TO 18 CHECKED ALL EMERGENCY LIGHTS ALL WORKING FINE.	NO PARTS USED	

Workorder: V57519

In Date: 05/06/2013 Meter Reading: 70,345.00
Close Date: 07/25/2013

Problem?
Needs rear tires, bald on l rear outside and r rear inside. Thanks #jp maxson

Task performed:	Parts	Quantity
NEEDS REAR TIRES, BALD ON 1 REAR OUTSIDE AND R REAR INSIDE. THANKS #JP MAXSON. Vendor?: BOULEVARD TIRE CENTE	292850BRIDGESTONE 12R22.5 TIRE	4



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59467

In Date: 07/31/2013 Meter Reading: 70,581.00
Close Date: 08/02/2013

Problem?
MOUNT 5" HOSE TO REAR OF ENGINE

Task performed:	Parts	Quantity
MOUNTED ADAPTER ON REAR DOOR FOR 5" HOSE	NO PARTS USED	

Workorder: V59678

In Date: 08/08/2013 Meter Reading: 70,581.00
Close Date: 08/14/2013

Problem?
#3 discharge gauge sticks..

Task performed:	Parts	Quantity
TRAVEL TO 18 REPLACED DISCHARGE GAUGE AND REPAIRED WIRE TO SCENE LIGHT.	91553940GAUGE 0-400 WHITE COMP	2

Workorder: V60045

In Date: 08/30/2013 Meter Reading: 59,955.00
Close Date: 09/10/2013

Problem?
ENGINE 18-DISCHARGE #3 GAUGE NOT WORKING..

Task performed:	Parts	Quantity
REPAIRED ON W.O. #V59678	NO PARTS USED	

Workorder: V60435

In Date: 09/11/2013 Meter Reading: 71,380.00
Close Date: 09/30/2013

Problem?
dash console fuel gauge not working properly.

Task performed:	Parts	Quantity
CHECK OUT FUEL GAUGE WORKING OK JUST DOESN'T GO TO FULL ALL THE TIME NEEDS REPLACED ON NEXT P.M NO ROOM TO GET UNIT OUT.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V60657

In Date: 09/21/2013 Meter Reading: 71,602.20
Close Date: 09/30/2013

Problem?
e18 hit post with bumper. need to ensure its stable

Task performed:	Parts	Quantity
TRAVEL TO ST 18 TO CHECK PUMPER SHEAR BOLTS OFF R&R BUMPER SHEAR BOLTS ON FRONT WING.	NO PARTS USED	

Workorder: V61104

In Date: 10/08/2013 Meter Reading: 71,906.00
Close Date: 10/11/2013

Problem?
for charging tablet: cigarette lighter not hot when truck battery switch is off.

Task performed:	Parts	Quantity
TRAVEL TO ST 18 PER WORK ORDER REWIRE TK POWER TO CHARGE PORT ON DASH TO BE POWER ALWAYS KEY OFF.	56415CIG. LIGHTER ACCES.	1

Workorder: V61605

In Date: 10/29/2013 Meter Reading:
Close Date: 10/31/2013

Problem?
Replaced driver's side headlight last night. Need a spare headlight for back up. E-18

Task performed:	Parts	Quantity
TRAVEL TO ST-18 DROP OFF HEADLIGHT OUT.	H6054USE CV TYPE SEALED BEAM	1

Workorder: V61888

In Date: 11/08/2013 Meter Reading: 72,486.00
Close Date: 11/14/2013

Problem?
L-1 compartment door wont open

Task performed:	Parts	Quantity
1. TRAVEL TO ST-18 GET DOOR OPEN STUCK LUBE LATCHES CHK OK. 2. CHECK K-12 SAW INOP R&R PLUG TRY TO ADJUST NEEDS TO GO TO SHOP FOR BILL.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62076

In Date: 11/16/2013 Meter Reading:
Close Date: 11/21/2013

Problem?

E18 deck gun gauge cracked sprays water out of face.deck gun rotation lock slips.crs #8242...

Task performed:

TRAVEL TO ST-18 DECK GUN LOCK INOP R&R LEVER AND REPLACE LOCK REMOVE GUAGE AND PLUG FOR NOW.

Parts	Quantity
X170DECK GUN ROTATION LOCK INSERT	1

Workorder: V61865

In Date: 11/07/2013 Meter Reading:
Close Date: 11/26/2013

Problem?

hurst tool hose 10-7. need replacement. have 3 working hoses.

Task performed:

TRAVEL TO ST-18 R&R HURST HOSES THAT WERE BAD ON UNIT.

Parts	Quantity
3530016HOSE HURST 16 ORANGE	2
353R091USE 353R403 HURST HOSE 16 GREEN	1

Workorder: V62341

In Date: 11/28/2013 Meter Reading: 61,715.40
Close Date: 12/05/2013

Problem?

E18 DRIVER SIDE HEADLIGHT OUT 2ND TIME HEADLIGHT HAS BEEN REPLACED, POSSIBLE SHORT

Task performed:

R&R HEAD LIGHT OUT.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

Workorder: V62681

In Date: 12/13/2013 Meter Reading:
Close Date: 12/18/2013

Problem?

MOTOR ON HOSE REEL IS NOT WORKING. BUT.IS MAKING A CLICKING SOUND WHEN BUTTON IS PUSHED. E18

Task performed:

1. TRAVEL TO ST-18 CHECK OUT HOSE REEL INOP CHECK POWER AND GROUND. CHECK RELAY MOTOR SHORTED WILL ORDER NEW MOTOR.
2. TRAVEL TO ST-18 R&R REEL MOTOR REWIRE ADJUST TEST OK.

Parts	Quantity
9910-1119GEAR CHAIN DRIVE HANNA	1
P56AN227MOTOR HOSE REEL	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62212

In Date: 11/22/2013
Close Date: 01/03/2014

Meter Reading: 72,850.00

Problem?

B inspection E18

Task performed:

1. A INSP.
2. R&R 2 TIRE SCHRADER VALVES AND INFLATE ALL 6 TIRES TO PRPOER INFLATION.
3. DISASSEMBLE AND REPAIR AIR CONTROL FORD FOR DRIVERS AIR SEAT.
4. DIAGNOSE QTZ TELE LTE "UP" WARNING SYSTEM. FOUND OUT WIRES TALKED TO FOREMAN TO RECONNECT OR NOT. WAITING FOR ANSWERS.
5. DIAGNOSE TRANS RECHARGE, CHECK FOR AIR PRESSURE CHECK VOLTING CAT SWITCH OPERATION CHECK CONNECTOR AND WIRING AT ACCUMULATOR.
6. R&R DASH R&R BROKEN HVAC CABLE REPAIR BINDING DIVERTER DOORS. ADJUST ALL 3 CABLES REPLACE BAD FOAM GASKET AT DASH AIR OUTLETS.
7. INSTALL SERVICE KIT IN R/S AIRHORN. TUNE BOTH AIR HORNS.
8. TRANS CODE 1423 OIL LEVEL SENSOR INACTIVE CODE CLEARED CODE ROAD TEST VEH CODE DID NOT RETURN.
9. CHECKED VEH CODES WITH LAPTOP, NONE ACTIVE AND NONE RELATED TO ENGINE MONITORS OR OPERATION.
10. Q.A.
11. R&R CAB AUX A/C FILTER.

Parts	Quantity
1094KIT-AIR HORN-GROVER	1
404-100 VALVE CORE	2
6808310398SEAL AIR DUCT	1
6808330631CABLE ASSY HEATER	1
78R536078R5360M 2PK FILTER AIR COND	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V63430

In Date: 01/15/2014
Close Date: 01/23/2014

Meter Reading: 73,683.60

Problem?

UNABLE TO RAISE HEIGHT ON DRIVER SEAT. E18

Task performed:

1. CHECK SEAT FOUND AIR VALVE IS NOT WORKING DID NOT HAVE PARTS ON TRUCK AND I HAD TO GO TO ST 52.
2. TRAVEL TO ST 18 R&R DRIVE SEAT AIR VALVE OLD ONE STUCK OUT.

Parts	Quantity
032110401150 VALVE AIR SEAT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V60938

In Date: 10/02/2013
Close Date: 02/21/2014

Meter Reading: 60,740.00

Problem?

Replaced left front tire.

Task performed:

REPLACED LEFT FRONT TIRE.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE

Workorder: V64238

In Date: 02/14/2014
Close Date: 03/05/2014

Meter Reading:

Problem?

air for driver seat not raising seat to R18

Task performed:

TRAVEL TO ST-18 CHECK OUT DR SEAT INOP RUBBER BOOT GETTING STUCK UNDER VALVE LEVER CUT BOOT TEST OK.

Parts

NO PARTS USED

Quantity

Workorder: V60929

In Date: 10/02/2013
Close Date: 03/19/2014

Meter Reading:

Problem?

front driverside tire tread is down to the wear bars

Task performed:

REPAIRED BY BOULEVARD TIRE ON W.O #60938.

Parts

NO PARTS USED

Quantity

Workorder: V64914

In Date: 03/13/2014
Close Date: 03/20/2014

Meter Reading:

Problem?

1 case of oil for engine and rescue

Task performed:

DROP OFF OIL AT ST-18.

Parts

15W40QSYN OIL QT

Quantity

12



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V64922

In Date: 03/13/2014 Meter Reading:

Close Date: 03/20/2014

Problem?

Driver side rear strobe lens cracked

Task performed:

1. TRAVEL TO ST-18 CHECK REAR LIGHT OUT TOPLT BAR DONT HAVE LENS WILL CUT AND REPLACE.
2. TRAVEL TO ST-18 R&R LT BAR LENS AND REMOUNT LT BAR.

Parts	Quantity
9ECAPCCLEAR END CAP 9000 BAR	1
9ULENSCCLEAR LENS FREEDOM BAR	1

Workorder: V65747

In Date: 04/16/2014 Meter Reading:

Close Date: 05/06/2014

Problem?

pass side clearence light needs to be replaced upper red light at top of engine also gasket on medical door leaking rain water into cabinet.

Task performed:

1. CHECK DOORS FOR WATER INTRUSION. FOUND NEEDS DOOR GASKETS ON R-1 AND R-2 DOORS HIGHT IS FIXED TOO.
2. DRIVE TO STATION, REMOVE AND REPLACE MEDICAL COMPARTMENTS. DOOR SEALS.

Parts	Quantity
NO PARTS USED	

Workorder: V66373

In Date: 05/09/2014 Meter Reading:

Close Date: 05/15/2014

Problem?

air horn not working R18

Task performed:

WORK COMPLETED ON V66416.

Parts	Quantity
NO PARTS USED	

Workorder: V66612

In Date: 05/20/2014 Meter Reading:

Close Date: 05/21/2014

Problem?

Could you send BAR CHAIN OIL for the new chainsaw please. Thanks, pinto

Task performed:

LD DELIVERED.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V66416

In Date: 05/12/2014 Meter Reading:
Close Date: 05/23/2014

Problem?
Air horn not working, unable to move traffic

Task performed:

TRAVEL TO ST-18 CHECK OUT HORN INOP CHECK AIR AND FILL VALVE BAD. R&R HORN VALVE REPLUMB AIR WIRING BAD REWIRE PLUG RETEST CHK OK.

Parts	Quantity
EL360081760611 SOLENOID AIR HORN	1

Workorder: V66660

In Date: 05/21/2014 Meter Reading:
Close Date: 06/10/2014

Problem?
lift suport for door on rear driver side broke from mount horizontal opening door

Task performed:

Travel to station 18 Check door Hold open R and R Broken Shock.

Parts	Quantity
101281021GSS1917UY 90# STRUT-LIFT	1
EAA-8350-60UGSS6557UP STRUT-LIFT	1

Workorder: V66875

In Date: 05/30/2014 Meter Reading:
Close Date: 06/17/2014

Problem?
found mirror on driverside broke at base vibrating. zip tied to keep from vib.and prevent from breaking off. E18

Task performed:

TRAVEL TO ST-87-18 CHECK OUT MIRROR LOWER BUT BROKEN WILL GET MIRROR OK.

Parts	Quantity
NO PARTS USED	

Workorder: V66929

In Date: 06/02/2014 Meter Reading:
Close Date: 06/17/2014

Problem?
The metal bracket for the Driver's side is cracked and needs to be replaced.

Task performed:

TRAVEL TO ST-18 R&R LOWER MIRROR BRAKET THAT WAS BROKEN.

Parts	Quantity
11133MIRROR MOUNT	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V67015

In Date: 06/06/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

Tank to pump will not open when there is pressure coming in from the hydrant.

Task performed:

TRAVEL TO ST-18 CHECK OUT TANK TO PUMP INOP
LUBE BALL VALVE AND LINKAGE TEST OK.

Parts

NO PARTS USED

Quantity

Workorder: V67068

In Date: 06/08/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

air leak on the primary and secondary air tanks

Task performed:

TRAVEL TO ST-18 CHECK FOR AIR LEAKS FOUND
HORN LEAKING R/R FITTING RETEST OK.

Parts

51-30219-1045 MASTER SWITCH 175 AMP

Quantity

1

Workorder: V65341

In Date: 03/31/2014
Close Date: 07/17/2014

Meter Reading:

Problem?

air horn very weak r18

Task performed:

air horn repaired on v66416

Parts

NO PARTS USED

Quantity



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V69037

In Date: 08/29/2014

Meter Reading: 78,818.00

Close Date: 09/19/2014

Problem?

C inspection, old E18 turn into spare, remove windshIELD number

Task performed:

Parts

Quantity



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. "C" inspection and road test.
(1. Remove station #decal 2. install new air cleaner 3. Height sticker installed)
2. Coolant low on sight glass. Pressure test found upper radiator hose clamp loose. Secure and top off coolant.
3. Cab rear/L box light support loose. Remove and install new nut and bolt-resecure. Install light.
4. Cab driver and L/rear window molding broken. Remove and install new window molding.
5. Cab rear A/C filter dirty. Remove filter and filter cage. Clean evaporator core, install filter and filter cage.
6. L-1 compartment ax holder off door. Drill tap new support holes and install ax holder. R1 door open support loose. Secure support.
7. Tailboard center light inop. Found LED faulty. Remove and install new light.
8. Windshield fluid reservoir dirty. Drain fluid wash out reservoir plug and fill with clean fluid and bug solvent.
9. Handheld spot light , handwirre spotlight in unit and fused with a 20 am fuse in center console to a 12v lighter plug.
10. Fuel leak. Operate engine, found fuel leaking from injector pump supply line. Shut down unit, remove faulty line. Replace fuel line washer and secure. Operate unit no further leak.
11. Transmission fluid and filter service.
12. Air dryer filter and purge valve assembly service.
13. Rear air tank to "O" PSI. Clean fitting, found 2 leaking lower tank and rotate tank in order to change defective fittings. Correct fault and retest.
14. Air pressure drops. Found pump shift control valve leaking in road position only, indicate vps bypassing. Check valve, found shift rod loose. Clean area and tighten leak stop.
15. #3 Discharge valve leaking, #1 crossing valve grease fitting, hose reel grease fitting at valve and deck gun valve. Remove and rebuild all listed valves. Remove grease fittings and install new ones. Relube fittings and retest vacuum, pass test.
16. Back up alarm inoperable. Test alarm extendedly malfunction , install new unit still inoperable. Trace wire to node #4. Found pinch wire in node compartment, repair fault unit working properly.
17. Attic ladder heat sticker expired. Remove and install new stickers.
18. Station decal (logo) removal.
19. QA

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
29526898 29548988 TRANS FILTER ALLISON	1
35200-RLIGHT MARKER LED RED	1
56415CIG. LIGHTER ACCES.	1
575BACKUP ALARM ECCO 107 DEC	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91398907 VALVE KIT 3 IN AKRON	1
94862PIGTAIL LED MARKER LIGHTS	1
A0924LADDER OUT OF SERVICE STICKER	4
A1834388002MOLD L/H	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V69634

In Date: 09/23/2014
Close Date: 09/24/2014

Meter Reading: 78,818.00

Problem?

Replace rear tires

Task performed:

Replace rear tires.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V70746

In Date: 11/06/2014
Close Date: 11/21/2014

Meter Reading:

Problem?

upon accelateration noise from engine compartment sounds like slipping belt. thanks barry, E51

Task performed:

Adjusted AC belts and road tested

Parts

Quantity

NO PARTS USED

Workorder: V71014

In Date: 11/18/2014
Close Date: 12/15/2014

Meter Reading:

Problem?

Telescoping lights (both) are not lighting up even though panel says they are on. E51

Task performed:

Repaired bad connection on lights

Parts

Quantity

NO PARTS USED

Workorder: V69090

In Date: 09/01/2014
Close Date: 12/22/2014

Meter Reading:

Problem?

#2 discharge bleeder does not completely close. There is a 15 psi difference between the test gauge and the truck master discharge gauge. The truck gauge reads 15psi higher

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V72022

In Date: 01/02/2015
Close Date: 01/05/2015

Meter Reading: 67,257.70

Problem?

make placards for E56

Task performed:

Make up number placards for engine 56

Parts	Quantity
L PLACARD INSERTLARGE PLACARD INSERT CARD	2

Workorder: V71126

In Date: 11/22/2014
Close Date: 01/06/2015

Meter Reading:

Problem?

E56 needs misc. tools and shelves moved around on the engine.

Task performed:

- Moved top shield and mounted tools in L-1
- Repaired rear door hinge

Parts	Quantity
NO PARTS USED	

Workorder: V71825

In Date: 12/22/2014
Close Date: 01/20/2015

Meter Reading:

Problem?

E56 will not charge off any shoreline. TK, 15748

Task performed:

Removed and replaced all batteries and repaired battery charger.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V71826

In Date: 12/22/2014
Close Date: 01/20/2015

Meter Reading:

Problem?

Requesting Tommy to mount / move various items on E56. If possible - Jan 2, 5, or 6 please, so myself and/or Captain Feierabend are on duty. TK, 15748

Task performed:

Mounted all items on truck that were needed.

Parts	Quantity
NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V71884

In Date: 12/27/2014 Meter Reading:
Close Date: 01/20/2015

Problem?

Tank to Pump valve is EXTREMELY difficult to open. Tommy will be down in the next week or so to do other work. We can add thi to the list. Thx. E56 TK, 15748

Task performed:	Parts	Quantity
Adjusted valve, and tested all operation of valve was good.	NO PARTS USED	

Workorder: V72157

In Date: 01/09/2015 Meter Reading:
Close Date: 01/28/2015

Problem?

TIC is not charging when placed on the charger that is on the truck.

Task performed:	Parts	Quantity
1. Repaired charger and adjusted 12 V tabs. 2. Traced air leaks.	NO PARTS USED	

Workorder: V72713

In Date: 01/29/2015 Meter Reading:
Close Date: 01/30/2015

Problem?

Sta 56 needs the following asap... -2 cycle oil -30W engine oil -hurst tool fluid -1 small funnel

Task performed:	Parts	Quantity
PARTS ONLY - DELIVERED.	NO PARTS USED	

Workorder: V72292

In Date: 01/13/2015 Meter Reading:
Close Date: 02/06/2015

Problem?

1. Emergency lights need to be inspected. Side mount water guage missing lights. Front Emerg. lights front of truck, 1 blinking, 1 solid not blinking. 2. Battery charger shows 50% charged after being plugged in all day.

Task performed:	Parts	Quantity
1. Repaired all emergency lights that were out. 2. Recalibrated water level gauges.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V72418

In Date: 01/18/2015
Close Date: 02/06/2015

Meter Reading:

Problem?

Blitz line staps which hold the nozzle down on the side of engine 56 need to be replace. Comes off with very little pressure applic

Task performed:

Parts

Quantity

1 Remounted all nozzles and hose brake.

NO PARTS USED

Workorder: V72327

In Date: 01/14/2015
Close Date: 02/20/2015

Meter Reading: 68,970.10

Problem?

Install GenCat E56

Task performed:

Parts

Quantity

Install muffler on ram fan.

NO PARTS USED

Workorder: V72715

In Date: 01/29/2015
Close Date: 02/20/2015

Meter Reading:

Problem?

Chain saw gas gasket has a leak.

Task performed:

Parts

Quantity

Swapped out saw.

NO PARTS USED

Workorder: V72743

In Date: 01/30/2015
Close Date: 02/20/2015

Meter Reading:

Problem?

Front suction driver panel air toggle switch will not work, not allowing the intake valve to open.

Task performed:

Parts

Quantity

Will need to come to shop.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V72756

In Date: 01/30/2015

Meter Reading:

Close Date: 02/20/2015

Problem?

While flowing water from crosslay #1 today. Discharge #4 was also opened and water flowed. While increasing pressure discharge #4 suddenly shut all on its own sending all pressure to crosslay #1. Needs to be checked. E56

Task performed:

Parts

Quantity

Found no problem with pump.

NO PARTS USED

Workorder: V72757

In Date: 01/30/2015

Meter Reading:

Close Date: 02/20/2015

Problem?

While connected to a hydrant and flowing water today. There was alot of water dripping into the rear compartment above the generator.E56

Task performed:

Parts

Quantity

Found no leaks at this time.

NO PARTS USED

Workorder: V72770

In Date: 01/31/2015

Meter Reading:

Close Date: 02/20/2015

Problem?

E56 front bumper intake valve not working. E56

Task performed:

Parts

Quantity

Worked on valve. Will need to come to shop.

NO PARTS USED

Workorder: V72771

In Date: 01/31/2015

Meter Reading:

Close Date: 02/20/2015

Problem?

E56 pump has small water leaking while it is turned off and parked.

Task performed:

Parts

Quantity

Checked for leaks. Found none.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V72772

In Date: 01/31/2015 Meter Reading:
Close Date: 02/20/2015

Problem?
E56 officer side scene light has one bulb out. E56

Task performed:	Parts	Quantity
Repaired bad connection.	NO PARTS USED	

Workorder: V73127

In Date: 02/13/2015 Meter Reading:
Close Date: 03/17/2015

Problem?
Engine 56 officer side scene light bulb is not working.

Task performed:	Parts	Quantity
1. Repaired bad connection on light.	NO PARTS USED	

Workorder: V74029

In Date: 03/19/2015 Meter Reading:
Close Date: 04/22/2015

Problem?
Discharge #3 is not working, under pressure its reading 0

Task performed:	Parts	Quantity
1. Ran pump and tested ok.	NO PARTS USED	

Workorder: V74360

In Date: 04/01/2015 Meter Reading:
Close Date: 04/22/2015

Problem?
Engine 56 Front LDH intake does NOT Work. e56

Task performed:	Parts	Quantity
1. Front suction valve will need to be repaired at shop on B-inspection.	NO PARTS USED	



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V73543

In Date: 03/01/2015
Close Date: 04/28/2015

Meter Reading:

Problem?

There was a small oil leak under the motor. The back up alarm was sounding constantly. Wires possibly got wet. There was water leaking on top of the generator in the rear compartment when hooked up to a hydrant. e56

Task performed:

Parts

Quantity

1. Checked oil leak and repaired.

NO PARTS USED

Workorder: V73620

In Date: 03/03/2015
Close Date: 04/30/2015

Meter Reading:

Problem?

ram fan exhaust muffler needs to be put in E56's fan

Task performed:

Parts

Quantity

1. Installed new muffler on fan.
2. Repaired water leak at pump.
3. Readjusted all cab door and tested.

NO PARTS USED

Workorder: V73777

In Date: 03/10/2015
Close Date: 04/30/2015

Meter Reading:

Problem?

Leak coming from intake relief drain

Task performed:

Parts

Quantity

1. Traced out air leaks and repaired.

NO PARTS USED

Workorder: V73855

In Date: 03/12/2015
Close Date: 05/01/2015

Meter Reading:

Problem?

No power to MDT or power supply for TripTix charger, possible fuse or other electrical problem. MDT not working.

Task performed:

Parts

Quantity

1. Repaired power to MDC and tested.

NO PARTS USED



10/27/2020

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155563

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V73299

In Date: 02/20/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

E56 air hose needs a different tip on the end of the hose to be able to connect to E56.

Task performed:

Parts

Quantity

1. Installed new fitting on hose and tested.

NO PARTS USED

Workorder: V70202

In Date: 10/16/2014
Close Date: 06/08/2015

Meter Reading:

Problem?

Hose fitting (cooler line) on top radiator hose leaking water.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V70314

In Date: 10/21/2014
Close Date: 06/30/2015

Meter Reading:

Problem?

scene lights do not work

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V72492

In Date: 01/21/2015
Close Date: 07/08/2015

Meter Reading:

Problem?

E56 - RED EMERGENCY WARNING LIGHT LOCATED ON FRONT GRILL DOES NOT FLASH WHEN ACTIVATED

Task performed:

Parts

Quantity

replace batteries repair light

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY

3

HP-31D BATTERY 950CCA HP-31D

3



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10155563) 2004 - FERRARA FL80 1250 Gpm Pumper

10155563

CSHOP-2015-1123

Comments: E56 WATER LEAKING FROM WHAT APPEARS TO BE PRESSURE RELIEF

Date Opened: 6-11-2015 Date Finished 6-16-2015 Meter 1 Reading: 70,423

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

CSHOP-2015-1171

Comments: E56 TOP SPOT LIGHT IS NOT WORKING

Date Opened: 6-15-2015 Date Finished 6-22-2015 Meter 1 Reading: 70,523

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

CSHOP-2015-1174

Comments: CALL OUT ON E56 COOLANT LEAK

Date Opened: 6-15-2015 Date Finished 6-22-2015 Meter 1 Reading: 70,623

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2015-1404

Comments: B INSPECTION E56

Date Opened: 6-26-2015 Date Finished 7-2-2015 Meter 1 Reading: 81,780

TASKS PERFORMED

Q PARTS

PM SERVICE B

2	FLUID; SYN OIL BULK QTS
1	LIGHT; 4 IN LIGHT
1	FILTER; OIL FILTER 51748
1	FILTER; FILTER FUEL 33231
1	LIGHT; 9186-1500-20 MARKER LT.AMBER LED
1	FILTER; FILTER FUEL WIX 33422 PS8689 FRAM

Asset Work Order History 10155563

CSHOP-2015-1414

Comments: **REPAIRS FROM INSPECTION ALSO NOTED BY CREWS: FRONT SUCTION INOP POSSIBLE TANK LEAK COOLANT LEAK**

Date Opened: 6-26-2015 Date Finished 7-2-2015 Meter 1 Reading: 81,780

TASKS PERFORMED

Q PARTS

FIRE PUMP CONTROLS	1	9IP; VALVE KIT SS VALVE 3 IN
TANK SUCTION VALVE FIRE PUMP	1	9IP; VALVE SENSING SV HALE
RELIEF VALVE FIRE PUMP	1	9IP; GASKET 2 1/2"
WATER PUMP	1	VALVE; VALVE AIR CONTROL
ANTIFREEZE	1	9IP; 4309418 PUMP-WATER ISC REBUILT
CAP	1	TENSIONER; GROOVED TENSIONER OLD#3936213
TRANSFER CASE	1	CAP; CAP RADIATOR 10 LB
POWER STEERING PUMP	1	FILTER; FG3939557S FILTER P/S NEW STYLE
AIR HORN	1	9IP; GASKET-P/S FILTER NEW STYLE
TRUNK LOCKS	1	FILTER; 78R5360M 2PK FILTER AIR COND
A/C FILTER SCREENS		
QUALITY CHECK-REPAIRS		

CSHOP-2015-1551

Comments: **AIR HORN GOES OFF SPONTANEOUSLY R56**

Date Opened: 7-6-2015 Date Finished 7-30-2015 Meter 1 Reading: 81,800

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	BAR; STRECHER BAR NEW
DIAGNOSE ELECTRICAL		
SAFTEY-EMERGENCY EQUIPMENT		

CSHOP-2015-1604

Comments: **CHECK SHORELINE CHARGER ONLY SHOWS ONE SIDE CHARGING E56**

Date Opened: 7-7-2015 Date Finished 7-17-2015 Meter 1 Reading: 81,800

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	CHARGER; CHARGER 2000
CHARGING SYSTEM		

CSHOP-2015-1842

Date Opened: 7-20-2015 Date Finished 7-24-2015 Meter 1 Reading: 81,800

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER		
RELIEF VALVE		

CSHOP-2015-2042

Comments: **E56 CAB SPOT LIGHT INOP**

Date Opened: 7-30-2015 Date Finished 8-6-2015 Meter 1 Reading: 81,800

TASKS PERFORMED

Q PARTS

ECU-ECM	1	LIGHT; SPOT LIGHT REMOTE
LIGHTING SYSTEM		
AIR CONDITIONING		

Asset Work Order History 10155563

CSHOP-2015-2112

Comments: **FRONT INTAKE NOT OPENING OR CLOSING E56**

Date Opened: 8-4-2015 Date Finished 8-7-2015 Meter 1 Reading: 81,800

TASKS PERFORMED

NO PARTS USED

FIRE PUMP
AIR CONDITIONING

CSHOP-2015-2509

Comments: **E56 CAB A/C**

Date Opened: 8-24-2015 Date Finished 9-9-2015 Meter 1 Reading: 81,900

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OIL
AIR CONDITIONING

CSHOP-2015-3503

Comments: **E56 HEADLIGHT OUT**

Date Opened: 10-20-2015 Date Finished 10-30-2015 Meter 1 Reading: 82,401

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

2 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

10/20/2015 LIGHTS / 19: LOOSE / REPAIR
E56 RIGHT HEADLIGHT IS NOT WORKING.

CSHOP-2015-351

Comments: **SHORELINE CHARGER INOP E56**

Date Opened: 4-29-2015 Date Finished 5-12-2015 Meter 1 Reading: 70,133

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
INVERTER
AIR SYSTEM
INSTRUMENTS-GAUGES-WARNING &
AIR CONDITIONING

1 CAP; RAD CAP 10231/R31
1 CHARGER; CHARGER 2000
1 CHARGER; CHARGER 2000
2 SWITCH; CIG. LIGHTER ACCES.

Asset Work Order History 10155563

CSHOP-2015-3587

Comments: **E56 DOOR LATCH WHERE TRASH LINE IS LOCATED FELL OFF**

Date Opened: 10-26-2015 Date Finished 11-16-2015 Meter 1 Reading: 72,517

TASKS PERFORMED

Q PARTS

BODY EXTERIOR

2 9IP; 434 LATCH TRIGGER S/O

Service Requests:

10/24/2015 BODY / 19: LOOSE / REPAIR
THE DOOR LATCH, WHERE THE TRASH LINE IS LOCATED FELL OFF. THE LATCH IS INSIDE THE COMPARTMENT IF NEEDED.

CSHOP-2015-3946

Comments: **ST56 POSSIBLE ISSUE WITH RELIEF VALVE**

Date Opened: 11-13-2015 Date Finished 12-3-2015 Meter 1 Reading: 72,758

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

2 GROMMET; HONDA FUEL GROMMET
1 GAUGE; GAUGE

Service Requests:

11/13/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
THE HONDA GASOLINE POWER GENERATOR IS LEAKING FUEL BY THE FUEL ON AND OFF SWITCH. THIS POWER GENERATOR HAS NO ASSET NUMBERS.

CSHOP-2015-4523

Comments: **E56 PUMP THROTTLE INOP**

Date Opened: 12-17-2015 Date Finished 12-18-2015 Meter 1 Reading: 72,916

TASKS PERFORMED

NO PARTS USED

FIRE PUMP
AIR CONDITIONING

Service Requests:

12/17/2015 ENGINE / 18: LEAKING / REPAIR
E56 GOES INTO PUMP BUT THE THROTTLE DOES NOT WORK. NO SECOND GREEN LIGHT TURNS ON.

CSHOP-2015-542

Date Opened: 5-8-2015 Date Finished 5-15-2015 Meter 1 Reading: 70,323

TASKS PERFORMED

Q PARTS

ALTERNATOR-GENERATOR

1 LIGHT; HEADLIGHT EXTRA BRIGHT
1 ALTERNATOR; 320 UPGRADE ALTERNATOR

Asset Work Order History 10155563

CSHOP-2016-2498

Date Opened: 5-24-2016 Date Finished 5-28-2016 Meter 1 Reading: 74,782

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
AIR CONDITIONING

CSHOP-2016-2531

Comments: BATT 5 SPARE ENGINE C INSPECTION COMPLETE REPAIR LIST DRIVER WINDOW MOLDING L REAR WINDOW
MOLDING DRIVER SIDE OVER HEAD POCKET OUT CAB A/C FILTER LEFT SIDE TAIL BOARD WARNING LIGHT HOSE
BED SNAP WARNING LIGHT R SIDE WHEEL WELL R SIDE LOWER AMBER WARNING LIGHT R 1 AND 3 HOLD OPEN

Date Opened: 5-26-2016 Date Finished 6-9-2016 Meter 1 Reading: 85,954

TASKS PERFORMED

Q PARTS

PM SERVICE C

25 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231
1 FILTER; OIL FILTER 51748
1 FILTER; 24070 WIX FILTER WATER
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM

Asset Work Order History 10155563

CSHOP-2016-2553

Comments: **REPAIRS FROM PM**

Date Opened: 5-26-2016

Date Finished

6-9-2016

Meter 1 Reading:

85,954

TASKS PERFORMED

	Q	PARTS
FIRE PUMP CONTROLS	1	9IP; SWITCH OLD # 200-0020-00
FIRE PUMP	1	LIGHT; HALE RED INDICATOR LED
DISCHARGE GAUGE	1	9IP; VALVE SENSING SV HALE
UL REPAIRS	1	CONTROL; PM CONTROL 562-0080-02
CANOPY	1	PUMP; TPM/QG HALE REPAIR KIT
WASHER RESERVOIR	1	9IP; 200-2262-50 SWITCH-PROXIMITY QG VALVE
WIPER BLADES	3	BULB; BULB
COOLING SYSTEM	1	SLIDE; SLIDE CONTROL 519-0071-10
LIGHTING SYSTEM	1	9IP; GASKET SEAL KIT P25/30
SEAL	1	GASKET; 14023 GASKET 6 IN
DIFFERENTIAL	1	SPRING; SPRING-VALVE QG RELIEF VALVE
STEERING	1	PUMP; TPM/QG HALE REPAIR KIT
AIR SYSTEM	1	9IP; QG VALVE
SAFTEY-EMERGENCY EQUIPMENT	1	9IP; WASHER CAP WPB-FREIGHTLINER
DOOR WEATHER MOLDING	2	WIPER; WIPER BLADES ANCO 24
DOOR	1	LIGHT; LIGHT LED RED TIR 6
BODY EXTERIOR	1	BULB; BULB
INTERIOR TRIM-MOLDINGS-UPHOLS	1	LIGHT; LIGHT MARKER LEDAMBER
CAB-INTERIOR ACCESSORIES	1	LIGHT; LIGHT MARKER LEDAMBER
A/C FILTER SCREENS	2	SEAL; SEAL SAME AS 29867 C/R
QUALITY CHECK-REPAIRS	4	GEAR; GEAR OIL SYN QT
	1	PUMP; VPS SHIFT KIT 546-0370-53-0
	2	GEAR; GASKET GEAR BOX COVER (HALE)
	-1	FILTER; 78R5360M 2PK FILTER AIR COND
	1	FILTER; 78R5360M 2PK FILTER AIR COND
	1	9IP; SEAL OLD STYLE PINON
	16	GEAR; GEAR OIL SYN QT
	1	LIGHT; LIGHT LED RED TIR 6
	1	SEAL; SEAL DOOR
	2	WINDOW; MOLD L/H
	1	9IP; MOLD R/H
	1	FILTER; 78R5360M 2PK FILTER AIR COND

CSHOP-2016-3420

Comments: **SPARE ENGINE AT ST51 WILL COME IN THURSDAY AM**

Date Opened: 7-17-2016

Date Finished

7-21-2016

Meter 1 Reading:

75,467

TASKS PERFORMED

	Q	PARTS
INTAKE VALVE		
BRAKES	2	BRAKE; DIAPHRAM BRAKE
AIR SYSTEM	1	PUMP; VPS SHIFT KIT 546-0370-53-0

Service Requests:

07/12/2016 BRAKES / 12: BROKEN / SERVICE BRAKE DIAPHRAGM LEAKING REMOVE DIAPHRAGM INSTALL N
AIR BRAKES BLEED DOWN WITHIN IN ONE HOUR AFTER TRUCKED IS TURNED OFF. THANKS BARRY

07/15/2016 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / OPERATE FRONT SUCTION FOUND N
FRONT INTAKE (AIR) DOES NOT OPEN. NOTICED DURING BACK FLUSHING

Asset Work Order History 10155563

CSHOP-2016-3530

Comments: **ON-CALL E51 GEN NOT RUNNING**

Date Opened: 7-23-2016 Date Finished 7-23-2016 Meter 1 Reading: 75,516

TASKS PERFORMED

NO PARTS USED

ALTERNATOR-GENERATOR

Service Requests:

07/23/2016 HAZARD / 12: BROKEN / INSPECT
THE GENERATOR NOT WORKING.

CSHOP-2016-3753

Date Opened: 8-2-2016 Date Finished 8-2-2016 Meter 1 Reading: 75,630

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

VENDOR? REGANS SMALL ENGINE SERVICE

CSHOP-2016-399

Comments: **E-56 PRESSURE RELIEF VALVE IS GETTING STUCK IN OPEN POSITION AND LEAKING WATER**

Date Opened: 1-27-2016 Date Finished 1-27-2016 Meter 1 Reading: 73,309

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

Service Requests:

01/26/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
PRESSURE RELIEF VALVE IS GETTING STUCK IN OPEN POSITION AND LEAKING WATER.

CSHOP-2016-4296

Comments: **SB5E AT ST51**

Date Opened: 9-1-2016 Date Finished 9-9-2016 Meter 1 Reading: 76,507

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM
BRAKES

1 CLAMP; CLAMP 4" 33969
1 SWITCH; NO SWITCH LOW AIR PRESSURE
1 SWITCH; NC SW PARK BK SPADE TYPE CONNECTOR

Service Requests:

09/01/2016 SERVICE REQUEST / 18: LEAKING / INSTALLED CLAMP FOR TEMPORARY REPAIR OF CURRENT F
EXHAUST PIPE SEPARATED UNDER VEHICLE

09/08/2016 BRAKES / 11: BINDS/STICKS / REPAIR
BRAKE ISSUES AUDIBLE HISSING AND LEAKING SOUND FROM BREAK PEDDLE WHEN PRESSURE IS APPLIED.

Asset Work Order History 10155563

CSHOP-2016-4334

Date Opened: 9-6-2016 Date Finished 9-6-2016 Meter 1 Reading: 76,407

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-4567

Date Opened: 9-20-2016 Date Finished 9-20-2016 Meter 1 Reading: 76,700

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

09/20/2016 BRAKES / 19: LOOSE / REPAIR
BRAKE ISSUES AUDIBLE AIR LEAK UNDER THE DASH

CSHOP-2016-4606

Comments: **SPARE ENGINE @ ST51**

Date Opened: 9-22-2016 Date Finished 10-4-2016 Meter 1 Reading: 76,922

TASKS PERFORMED

Q PARTS

AIR SYSTEM

2 SWITCH; NO SWITCH LOW AIR PRESSURE

Service Requests:

09/21/2016 BODY / 19: LOOSE / REPAIR
BODY ISSUE DOOR CONTROL BAR BROKE, OFFICER SIDE COMPARTMENT

09/21/2016 BRAKES / 19: LOOSE / REPAIR
BRAKE ISSUES AIR LEAK ENGINE IS AT ST51

CSHOP-2016-4968

Comments: **BATT SPARE**

Date Opened: 10-18-2016 Date Finished 11-7-2016 Meter 1 Reading: 77,508

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 LAMP; HEAD LAMP LOW BEAM CRYSTAL VISION

Service Requests:

10/17/2016 LIGHTS / 19: LOOSE / REPAIR
OFFICER SIDE HEADLIGHT NOT WORKING

Asset Work Order History 10155563

CSHOP-2016-5316

Date Opened: 11-14-2016 Date Finished 12-5-2016 Meter 1 Reading: 78,300

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
DIAGNOSE ELECTRICAL
AIR SYSTEM

1 SWIVEL; BD55015-1616-01 SWIVEL
1 ADAPTER; 53-16-16-SS SWIVEL ADPT

Service Requests:

11/10/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST-- WATER LEAKING FROM THE FITTING ON THE HOSE REEL WHEN THE PUMP IS IN GEAR ALSO
NEED A FITTING FOR THE AIR HOSE TO CONNECT TO THE SPARE TRUCK.

CSHOP-2016-5827

Date Opened: 12-13-2016 Date Finished 12-21-2016 Meter 1 Reading: 78,550

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT

1 9IP; IMMF11358A SEAT BELTS

Service Requests:

12/13/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST THE OFFICER'S SEAT SEATBELT THE MECHANISM THAT CATCHES THE BELT ON A SUDDEN STOP
ONLY WORKS OCCASIONALLY.

CSHOP-2016-6130

Comments: **E-58 K-12 WONT START**

Date Opened: 12-30-2016 Date Finished 1-10-2017 Meter 1 Reading: 78,921

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

12/30/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
K12 WILL NOT START

CSHOP-2017-1486

Date Opened: 3-10-2017 Date Finished 3-14-2017 Meter 1 Reading: 79,848

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

Service Requests:

03/09/2017 SERVICE REQUEST / 18: LEAKING / OVERHAUL
GAS GAUGE NOT TRUE.

Asset Work Order History 10155563

CSHOP-2017-1511

Date Opened: 3-11-2017 Date Finished 3-11-2017 Meter 1 Reading: 79,728

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

CSHOP-2017-17

Comments: **E-58 SPARE ENGINE AT 58 DOOR OPEN INDICATOR ON. CALLED CALLAGHAN FOR REAR TIRES ON 1-3-2017 10:45AM (SCOTT)**

Date Opened: 1-3-2017 Date Finished 2-3-2017 Meter 1 Reading: 79,912

TASKS PERFORMED

NO PARTS USED

REAR TIRES
SAFTEY-EMERGENCY EQUIPMENT

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

01/03/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST

01/03/2017 SERVICE REQUEST / 19: LOOSE / REPAIR

01/03/2017 SERVICE REQUEST / 19: LOOSE / REPAIR

CSHOP-2017-1741

Date Opened: 3-22-2017 Date Finished 7-5-2017 Meter 1 Reading: 81,117

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES 1 LIT; 8-1 2 ROUND MIRROR

Service Requests:

03/21/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
1 OF 2 LIGHT BULBS INSIDE OFFICERS SIDE QUARTS LIGHT IS OUT.

03/21/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
HURST TOOL POWER UNIT LEAKING/DRIPPING GAS WHEN GAS ON.

03/23/2017 BODY / 18: LEAKING / REPAIR
BODY ISSUE A FISHEYE MIRROR IS NEEDED ON THE RIGHT SIDE OF THE VEHICLE. BOTH THE SUPPORT BAR AND THE MIRROR IS NEEDED FOR SAFER DRIVING OF THE UNIT.

Asset Work Order History 10155563

CSHOP-2017-1887

Date Opened: 3-29-2017 Date Finished 4-21-2017 Meter 1 Reading: 80,698

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
AIR CONDITIONING

Service Requests:

03/29/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SIDE SCENE LIGHTS NOT WORKING

CSHOP-2017-20

Comments: **E-58 SPARE ENGINE AIR LEAK.**

Date Opened: 1-3-2017 Date Finished 1-3-2017 Meter 1 Reading: 78,810

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2017-252

Comments: **FRONT TIRE FLAT CALLED CALLAGHAN 1-12-17**

Date Opened: 1-12-2017 Date Finished 1-17-2017 Meter 1 Reading: 79,438

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-2827

Date Opened: 5-13-2017 Date Finished 5-16-2017 Meter 1 Reading: 81,099

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; FUEL WATER SEPARATOR
4 9OC; SYN 15W40
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2017-2890

Date Opened: 5-16-2017 Date Finished 5-16-2017 Meter 1 Reading: 81,099

TASKS PERFORMED

NO PARTS USED

FRAME

Asset Work Order History 10155563

CSHOP-2017-3029

Date Opened: 5-23-2017

Date Finished

6-9-2017

Meter 1 Reading:

81,084

TASKS PERFORMED

	Q	PARTS
FIRE PUMP PLUMBING	1	9IP; TPM/QG HALE REPAIR KIT
RELIEF VALVE	1	9IP; GASKET SEAL KIT P25/30
AIR FILTER	1	9IP; HALE RELIEF VALVE W/ VULCANIZED SEAT
EXHAUST PIPE	1	FIL; NAPAGOLD AIR FILTER
SPOT LIGHTS	-1	FIL; NAPAGOLD AIR FILTER
BATTERY	1	FIL; NAPAGOLD AIR FILTER
STEERING COLUMN-SHAFT-BOOT	1	2TP; EXHAUST ELBOW
MIRRORS	1	2TP; EXHAUST PIPE 4IN
INTERIOR TRIM-MOLDINGS-UPHOLS	1	BK; CLAMP
A/C CONDENSER FAN	1	EXH; STACK
	1	9IP; BULB QUARTZ HAL. 12V 150W
	2	9IP; MOLD L/H
	1	9IP; BULB QUARTZ HAL. 12V 150W
	4	1AD; BATTERY 31 SERIES
	-4	1AD; BATTERY 31 SERIES
	4	1AD; BATTERY 31 SERIES
	2	BK; BATTERY
	1	2FL; SHAFT
	1	GRO; CONVEX MIRROR
	1	GRO; UNIVERSAL MOUNT KIT
	-2	9IP; MOLD L/H
	2	9IP; MOLD L/H
	1	TEM; BLOW/MOT
	1	9IP; 18-2108 FIVE BLADE FAN 3382

CSHOP-2017-3538

Comments: **FUEL GAUGE INOP**

Date Opened: 6-15-2017

Date Finished

6-16-2017

Meter 1 Reading:

81,117

TASKS PERFORMED

	Q	PARTS
FUEL SYSTEM	1	2FL; SENDING UNIT
AIR SYSTEM	3	TWD; C-1COCK DRAIN
	2	WLD; BRASS WIRE BRUSH

CSHOP-2017-4791

Comments: **FUEL GAUGE WAS WOKING AT THIS TIME WILL HAVE CREW MONATOR**

Date Opened: 8-16-2017

Date Finished

9-24-2017

Meter 1 Reading:

81,677

TASKS PERFORMED

	Q	PARTS
FIRE APPARATUS	1	2DD; TRANSDUCER, DISCHARGE

Service Requests:

09/04/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST: ENGINES FUEL GAUGE NOT REGISTERING PROPER AMOUNT OF FUEL.

Asset Work Order History 10155563

CSHOP-2017-4817

Date Opened: 8-17-2017 Date Finished 8-21-2017 Meter 1 Reading: 81,284

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
COOLING SYSTEM

Service Requests:

08/17/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
PRIMER NOT WORKING.

CSHOP-2017-6332

Date Opened: 11-2-2017 Date Finished 11-17-2017 Meter 1 Reading: 82,029

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

11/02/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
PARKING BRAKE INDICATOR LIGHT NOT WORKING FUEL GAUGE IN CAB IS INACCURATE

CSHOP-2017-6476

Date Opened: 11-9-2017 Date Finished 11-17-2017 Meter 1 Reading: 82,029

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

1 9IP; STARTER SOLENOID EONE

Service Requests:

11/09/2017 ENGINE / 17: INSUFFICIENT LUBRICANT / REPAIR
PRIMER DOES NOT WORK

CSHOP-2017-7026

Comments: **E51**

Date Opened: 12-11-2017 Date Finished 12-12-2017 Meter 1 Reading: 82,470

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
AIR CONDITIONING

1 LMP; HALOGEN LAMP

Service Requests:

12/09/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
HEAD LIGHT OUT.

Asset Work Order History 10155563

CSHOP-2018-1045

Comments: **SPARE ENGINE AT 56**

Date Opened: 2-21-2018

Date Finished

2-22-2018

Meter 1 Reading:

83,312

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

02/17/2018

RADIATOR / 18: LEAKING / REPAIR

RADIATOR LEAKING. LEAK AT THE UPPER HOSE AT THE RADIATOR. LEAK WAS SLOWED BY TIGHTENINGB THE HOSE CLAMP BUT IS STILL LEAKING. RF LEVEL IS LOW.

CSHOP-2018-1518

Comments: **GENERATOR FOR ENGINE 56 COMPANY IN SPARE AT THIS TIME**

Date Opened: 3-14-2018

Date Finished

4-10-2018

Meter 1 Reading:

83,936

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

03/14/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

PORTABLE GENERATOR WILL ONLY RUN ON CHOKE THIS IS A SPARE ENGINE AT STATION 56

03/29/2018

LIGHTS / 18: LEAKING / REPAIR

VEHICLE LIGHTS NOT WORKING BULB NEEDS TO BE REPLACED, OFFICER'S SIDE TELESCOPIC LIGHT

CSHOP-2018-2135

Date Opened: 4-17-2018

Date Finished

4-24-2018

Meter 1 Reading:

84,541

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

04/17/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

THE VENT SAW AT STATION 56 IS MISSING SEVERAL TEETH. CAN WE PLEASE GET A NEW VENT SAW CHAIN AT STATION 56. THANK YOU

04/17/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

THE GENERATOR ON ENGINE 56 ONLY RUNS WHILE IN CHOKE.

Asset Work Order History 10155563

CSHOP-2018-2254

Date Opened: 4-24-2018 Date Finished 4-24-2018 Meter 1 Reading: 84,541

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
BODY EXTERIOR

Service Requests:

04/24/2018 AIR RIDE / 18: LEAKING / REPAIR
AIR RIDE ISSUE/AIR LEAK FROM THE PUMP POWER SHIFT AFTER PUMPING OPERATIONS

04/24/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
APPEARS THAT THE WATER TANK IS LEAKING INSIDE THE REAR COMPARTMENT WHERE THE LIGHT IS AND WHERE THE GROUND MONITOR BASE SITS UPSIDEDOWN. IT'S A STEADY TRCKEL INTO THE COMPARTMENT. PLACE PLUG AND DIKE AND APPEARED TO STOP FOR THE MEANTIME.

CSHOP-2018-2407

Date Opened: 5-2-2018 Date Finished 5-2-2018 Meter 1 Reading: 84,541

TASKS PERFORMED

NO PARTS USED

HOSES-LINES & FITTINGS

CSHOP-2018-279

Comments: **FILTERS ORDERED USE "A" INSPECTION FORM REPLACE OIL AND FILTERS**

Date Opened: 1-12-2018 Date Finished 1-24-2018 Meter 1 Reading: 83,152

TASKS PERFORMED

Q PARTS

PM SERVICE C

25 FLUID; SYN OIL BULK QTS
1 FIL; FUEL WATER SEPARATOR
-25 90C; SYN 15W40
25 90C; SYN 15W40
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

Asset Work Order History 10155563

CSHOP-2018-327

Date Opened: 1-16-2018

Date Finished

2-5-2018

Meter 1 Reading:

83,158

TASKS PERFORMED

Q PARTS

RELIEF VALVE FIRE PUMP	1	9HY; SEALS
EQUIPMENT MOUNTING BRACKETS	1	TWD; AD-9KIT
RADIO	32	FLUID; COOLANT ANTIFREEZE GAL
COOLING SYSTEM	1	FIL; NAPA HYDRAULIC FILTER
SPOT LIGHTS	1	5TN; TPM/QG HALE REPAIR KIT
FLASHER	1	FIL; NAPA COOLANT FILTER
PARK-CLEARANCE LIGHTS	1	2FL; MOLDING LH
LIGHTING SYSTEM	1	LIT; LED M C LAMP
STEERING	1	NBH; SIL SDI COOLANT HOSE
AIR DRIER	1	TWD; AD-9KIT MINOR
LIGHT BAR	1	NBH; RAD/HOSE
DOOR HINGE-PINS-BUSHINGS	-32	9OC; COOLANT
BODY EXTERIOR	32	9OC; COOLANT
INTERIOR TRIM-MOLDINGS-UPHOLS	1	9AP; BULB, 150W HALOGEN
DOOR HANDLES INSIDE-OUTSIDE	1	1WL; LIGHT LED RED TIR6
A/C FILTER SCREENS	2	9AP; QUARTZ BULB 12V 150W
	2	LMP; BULB
	2	9IP; ALLISON TRANS FLUID GAL
	-2	9OC; BULK TRANS SYN
	2	9OC; BULK TRANS SYN
	2	5AH; 10MM BALL STUD
	2	5AH; GAS SPRING, 12.087", 34LB
	1	2FL; HANDLE, DOOR
	1	2TK; FILTER

CSHOP-2018-3557

Date Opened: 6-25-2018

Date Finished

7-26-2018

Meter 1 Reading:

84,542

TASKS PERFORMED

Q PARTS

FIRE PUMP CONTROLS	1	5FR; KIT, THROTTLE EXCEL 200 CUM IS
--------------------	---	-------------------------------------

CSHOP-2018-4659

Comments: **E36**

Date Opened: 8-20-2018

Date Finished

8-23-2018

Meter 1 Reading:

85,135

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

08/18/2018	SERVICE REQUEST / 18: LEAKING / REPAIR TYPE PROBLEM INTO DESCRIPTION THE FIBERGLASS THAT BONDS THE HOOD TO THE HINGE ON THE DRIVER SIDE IS SNAPPED. THE HOOD WILL NEED TO BE REPLACED.
08/18/2018	SERVICE REQUEST / 18: LEAKING / REPAIR TYPE PROBLEM INTO DESCRIPTION- SPARE E36 FUEL GAUGE IS READING INCORRECTLY FUELED APPROX 30 GAL AND THE GAUGE WAS READING 1/4 TANK AFTER THE NEXT CALL 3/4 THEN A 1/2 TANK
08/19/2018	BRAKES / 18: LEAKING / REPAIR BRAKE ISSUES MAJOR AIR LEAK IN BRAKE SYSTEM TRUCK AT STATION 36

Asset Work Order History 10155563

CSHOP-2018-4719

Comments: SPARE ENGINE AT ST36 TYPE PROBLEM INTO DESCRIPTION DOESN`T APPEAR TO BE CHARGING FROM THE SHORE LINE. THE TWO CHARGING BAR ONLY SHOW 1 BLOCK ON THE CHARGE METER. TYPE PROBLEM INTO DESCRIPTION NOTICEABLE AIR LEAK UNDER THE TRUCK OFFICER SIDE

Date Opened: 8-21-2018 Date Finished 8-28-2018 Meter 1 Reading: 85,303

TASKS PERFORMED

Q PARTS

SHORELINE CHARGER
AIR SYSTEM

1 9IP; 29552377 VALVE ASSY.ACCUM

Service Requests:

08/21/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION DOESN`T APPEAR TO BE CHARGING FROM THE SHORE LINE. THE TWO CHARGING BAR ONLY SHOW 1 BLOCK ON THE CHARGE METER.

08/24/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION

08/24/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION NOTICEABLE AIR LEAK UNDER THE TRUCK OFFICER SIDE

CSHOP-2018-4820

Comments: SPARE ENGINE AT ST36

Date Opened: 8-24-2018 Date Finished 10-24-2018 Meter 1 Reading: 85,735

TASKS PERFORMED

Q PARTS

LEFT SIDE
HOOD HINGE

1 9IP; HANDLEWINDOW
1 NCB; QK EPOXY SYRINGE 25ML

Service Requests:

08/24/2018 WINDOW / 12: BROKEN / EXCHANGE - NEW LUBED WINDOW REGULATOR AND REPLACED STRII
WINDOW/GLASS DRIVER SIDE WINDOW CRANK IS SLIPPING WILL NOT ROLL UP THE WINDOW WITHOUT ASSISTANCE

08/31/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION HAD A SMALL BRUSH FIRE YESTERDAY USED A SMALL AMOUNT OF FOAM DUE TO BEES REPLACED THE FOAM. THIS MORNING WHILE FUELING THE ENGINE I NOTICED TANK LEVEL FLASHING EMPTY CLIMB UP AND CHECKED THE TANK AND IT WAS COMPLETELY EMPTY. CHECKED THE WATER TANK AND THERE IS FOAM IN IT

Asset Work Order History 10155563

CSHOP-2018-5044

Date Opened: 9-5-2018

Date Finished

10-2-2018

Meter 1 Reading:

85,707

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS
DIAGNOSE ELECTRICAL

Service Requests:

- 09/05/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION I BELIEVE THERE IS A CRACK IN THE TOP OF THE WATER TANK NEAR THE BASE OF THE LID TOWER THERE IS ABNORMAL AMOUNT OF WATER LEAKING FROM THE TRUCK WHEN SLOWING OR STOPPING
- 09/05/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
TYPE PROBLEM INTO DESCRIPTION ABNORMAL NOISE COMING FROM THE ENGINE COMP. WHEN ACCELERATING OR IN IDLE AT A LIGHT. THE SOUND IS INTERMITTENT. UNABLE TO OPEN THE HOOD DUE TO THE BROKEN HINGE THAT HOLDS THE HOOD OPEN
- 09/09/2018 FUEL / 18: LEAKING / REPAIR
FUEL GAUGE IS NO FUNCTIONING, WE ARE FUELING IT EVERY MORNING. PLACED TAPE OVER THE GAUGE ON THE DASH.

CSHOP-2018-5193

Date Opened: 9-12-2018

Date Finished

10-5-2018

Meter 1 Reading:

85,734

TASKS PERFORMED

Q PARTS

COMPARTMENT LIGHT BODY
FIRE APPARATUS

1 9IP; NODE HERCULES V-MUX

CSHOP-2018-6341

Comments: **NEED MIRROR AND BRACKET. SEND PIC**

Date Opened: 11-7-2018

Date Finished

11-16-2018

Meter 1 Reading:

85,825

TASKS PERFORMED

Q PARTS

PRIMING PUMP FIRE PUMP
THROTTLE CONTROLS
MIRRORS

1 9HD; STARTER RELAY
1 9IP; GRO716S MIRROR SS
1 GRO; STEEL L BRACKET

CSHOP-2018-6914

Date Opened: 12-5-2018

Date Finished

12-27-2018

Meter 1 Reading:

85,871

TASKS PERFORMED

Q PARTS

PUMP PANEL
FIRE PUMP
INTAKE GAUGE
DISCHARGE GAUGE
FIRE APPARATUS
ANTIFREEZE
BATTERY
REPAIR FROM PM - DECALS/CLEANLINESS
STROBE LIGHTS
FUEL GAUGE

-1 1WL; LIGHT LED RED TIR6
-1 1WL; LIGHT LED RED TIR6
2 1WL; LIGHT LED RED TIR6
1 2FL; GASKET
3 NBH; SIL SDI COOLANT HOSE
4 1AD; BATTERY 31 SERIES
2 5SC; DIGITAL PRESSURE GAUGEFLOW MINDER
1 2FL; SENDING UNIT

Asset Work Order History 10155563

CSHOP-2018-7368

Date Opened: 12-28-2018 Date Finished 12-28-2018 Meter 1 Reading: 85,882

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; FUEL WATER SEPARATOR
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2018-7369

Comments: **REPAIRS FROM PM**

Date Opened: 12-28-2018 Date Finished 1-24-2019 Meter 1 Reading: 85,882

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT
REPAIR FROM PM - PUMP PANEL CONTROLS
EXHAUST MANIFOLD
DIMMER SWITCH
LIGHTING SYSTEM
TRANSMISSION
LIGHT BAR

1 NBH; SILICONE HTR HOSE
6 2CU; EXHAUST MANI GASKET
1 FIL; NAPA COOLANT FILTER
1 2CU; TURBO GASKET
1 2CU; EXHAUST MANIFOLD
1 NONSTOCK; FREIGHT CHARGE
1 9IP; DO NOT USE CLEAR LENS FREEDOM BAR
1 1WL; LENS DIVIDER
2 LIT; LED M C LAMP
4 9IP; BULB QUARTZ HAL. 12V 150W
2 LIT; LED M C LAMP
3 LIT; LED M C LAMP
1 2CU; EXHAUST MANIFOLD
29 9OC; BULK TRANS SYN
1 FIL; NAPA TRANS FILTER
1 2CU; SCREW STUDDER
11 2CU; EXHUAST MANI BOLT

CSHOP-2018-932

Comments: **SPARE ENGINE NEEDS FUEL GAUGE IN DASH**

Date Opened: 2-12-2018 Date Finished 3-13-2018 Meter 1 Reading: 83,421

TASKS PERFORMED

Q PARTS

FIRE APPARATUS
CAB-INTERIOR ACCESSORIES
FUEL GAUGE

1 9IP; THROTTLE EXCEL CUMMINS IS SERIES
1 2FL; CLUSTER

Asset Work Order History 10155563

CSHOP-2019-1554

Date Opened: 3-25-2019

Date Finished

4-1-2019

Meter 1 Reading:

85,882

TASKS PERFORMED

QUALITY CHECK-REPAIRS
QUARTZ LIGHT
BATTERY
REPAIR FROM PM - BELTS
SAFTEY-EMERGENCY EQUIPMENT
AIR CONDITIONING

Q PARTS

2 9AP; BULB, 150W HALOGEN
1 9IP; AUTO CHARGER INDICATOR
4 1AD; BATTERY 31 SERIES
-1 NBH; SERPENTINE BELT
1 NBH; SERPENTINE BELT
1 NBH; SERPENTINE BELT
-1 NBH; SERPENTINE BELT
1 NBH; SERPENTINE BELT
-1 NBH; V-BELT
1 NBH; V-BELT
1 NBH; V-BELT
1 NBH; V-BELT
1 MMM; WTHRSTRP ADHBLK 5OZ
2 2FR; COVER, SAFETY BAR 26"
1 TEM; EXPANSION VALVE
1 TEM; FILTER DRIER
4 9XX; AC FREON 10174676
-1 TEM; FIL/DRY
1 TEM; FIL/DRY

CSHOP-2019-2283

Date Opened: 4-30-2019

Date Finished

5-10-2019

Meter 1 Reading:

84,373

TASKS PERFORMED

RELIEF VALVE FIRE PUMP
PRIMING PUMP FIRE PUMP
WINDOW CHANNEL

Q PARTS

1 5EF; STARTERSOLENOIDEONE
1 5HP; 5HP
1 NCB; DEGREASER MULTI PURP

CSHOP-2019-2794

Comments: **AIR LEAK**

Date Opened: 5-31-2019

Date Finished

6-19-2019

Meter 1 Reading:

86,145

TASKS PERFORMED

AIR SYSTEM

Q PARTS

1 2FL; TANK AIR

CSHOP-2019-4359

Date Opened: 8-17-2019

Date Finished

8-17-2019

Meter 1 Reading:

88,065

TASKS PERFORMED

AIR CONDITIONING

NO PARTS USED

Asset Work Order History 10155563

CSHOP-2019-5066

Comments: **QC AND TANK TO PUMP LEAKING**

Date Opened: 9-25-2019

Date Finished

10-22-2019

Meter 1 Reading:

88,937

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
CONTROL VALVE FIRE PUMP
PRIMING PUMP FIRE PUMP
HOSE BED BODY
LIGHTING SYSTEM
AIR SYSTEM
DOOR
INSTRUMENT CLUSTER
HEATING AND VENTILATION

1 9IP; VALVE KIT SS 546 2270 02 0
1 5HP; 3 SVS LEVEL 2 KIT
1 5HP; EPS PRIMER PUMP
1 5HP; EPS PRIMER PUMP
1 2PR; STARTER SOLENOID EONE PRESTOLITE
1 LMP; LAMP
1 2FL; CAB LEVEL VALVE
1 2FL; CLUSTER
1 2RD; FILTER 17 5X5 5 MASTER PK 2
1 9HD; LOWER UNIT SEAL KIT

CSHOP-2019-5577

Date Opened: 10-22-2019

Date Finished

10-22-2019

Meter 1 Reading:

89,200

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2019-5985

Comments: **SPARE AT 37**

Date Opened: 11-14-2019

Date Finished

1-6-2020

Meter 1 Reading:

91,067

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS
FIRE PUMP

1 5FR; KIT, THROTTLE EXCEL 200 CUM IS

Service Requests:

11/14/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
DISCHARGE 3 LEAKING, POSSIBLE BAD GASKET.

11/22/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
PTO WILL NOT ENGAGE. AND PUMP THROTTLE IS INOP. TRIED 4 TIMES AND TURNED ON/OFF THE TRUCK. STILL WON'T ENGAGE.

11/22/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
PTO WILL NOT ENGAGE AND PUMP THROTTLE IS INOP. TRIED 3 TIMES AND TURNED VEHICLE ON/OFF. STILL WON'T ENGAGE.

Asset Work Order History 10155563

CSHOP-2019-6137

Comments: **SPARE AT 37**

Date Opened: 11-25-2019 Date Finished 1-9-2020 Meter 1 Reading: 91,067

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM

1 **MBI; AIR PRESSURE VALVE**

Service Requests:

11/24/2019 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING. SPOT LIGHT BROKEN, THE LIGHT WILL NOT TURN ON BUT THE SPOT LIGHT DOES MOVE PROPERLY.

11/24/2019 SERVICE REQUEST / 12: BROKEN / OVERHAUL
THE AIR OUTLET (LOCATED ON THE DRIVERS SIDE OF THE TRUCK) DOES NOT WORK. WHEN AIR HOSE IS CONNECTED TO THE AIR OUTLET, THE AIR HOUSE WILL NOT WORK.

CSHOP-2019-6359

Comments: **SPARE AT 37**

Date Opened: 12-9-2019 Date Finished 12-13-2019 Meter 1 Reading: 90,666

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

12/06/2019 BRAKES / 18: LEAKING / OVERHAUL
DUE TO AUDIBLE AIR LEAK, ENGINE WILL NOT MOVE UPON STARTUP AND IS DELAYING RESPONSE TIMES AS THE PARKING BRAKE WILL NOT DISENGAGE. AIR LEAK IS AUDIBLE AND GETTING WORSE.

CSHOP-2020-1133

Date Opened: 2-26-2020 Date Finished 2-26-2020 Meter 1 Reading: 92,000

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-1670

Comments: **SPARE AT STATION 53**

Date Opened: 3-24-2020 Date Finished 3-30-2020 Meter 1 Reading: 92,000

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

Service Requests:

03/24/2020 SERVICE REQUEST / 18: LEAKING / REPAIR
DRIVER SIDE SCENE LIGHT ONE BULB IS OUT

Asset Work Order History 10155563

CSHOP-2020-257

Date Opened: 1-16-2020 Date Finished 1-21-2020 Meter 1 Reading: 91,067

TASKS PERFORMED

Q PARTS

BRAKES

2 TWD; COMBO
2 2TP; SLACK ADJUSTER

Service Requests:

01/16/2020 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES

CSHOP-2020-331

Comments: **DUP. WO.**

Date Opened: 1-21-2020 Date Finished 1-21-2020 Meter 1 Reading: 91,067

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

01/17/2020 ENGINE / 18: LEAKING / REPAIR
ENGINE PUMP THROTTLE UNIT.

CSHOP-2020-337

Date Opened: 1-21-2020 Date Finished 2-13-2020 Meter 1 Reading: 134,624

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS

1 5FR; SENSOR INTAKE 0 600 PSI

Service Requests:

01/21/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
PUMP ENGINE THROTTLE DISENGAGED AND BECAME INOPERABLE DURING MORNING PUMP CHECK. THIS IS THE FIRST TIME THIS HAS HAPPENED WHILE THROTTLE WAS ENGAGED. THE "THROTTLE READY" LIGHT ON THE PUMP PANEL WENT OFF AND THE THROTTLE CONTROL WAS INOPERABLE.

CSHOP-2020-4873

Comments: **WHILE PUMP TESTING TODAY, WE ENCOUNTERED A PROBLEM WITH ENGINE 10155563. WE WERE UNABLE TO REACH TEST PRESSURE OF 300 PSI. THE MOST WE COULD GET WAS 234 PSI WHILE ALSO HOOKED UP TO A HYDRANT. THE SECOND PROBLEM ENCOUNTERED WAS WITH THE FORWARD CROSS LAY(1.75" ATTACH LINE**

Date Opened: 9-16-2020 Date Finished 10-20-2020 Meter 1 Reading: 138,000

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

-1 SVP; COMPRESSOR
1 SVP; COMPRESSOR
1 SVP; SVP
1 9HY; A C HOSE CUSTOM

Asset Work Order History 10155563

CSHOP-2020-526

Comments: **PMC**

Date Opened: 1-31-2020

Date Finished

2-13-2020

Meter 1 Reading:

134,624

TASKS PERFORMED

PM SERVICE C

Q PARTS

28	4PC; 15W40 PREMIUM BLUE OIL
-1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD FUEL FILTER
2	MAC; MACS BATTERY CLEANER
2	LUC; LUCAS RED TACKY GRS
2	NCB; DEGREASER MULTI PURP
2	CRC; BAT TERM PROTECTOR
1	FIL; FIL
1	FIL; NAPAGOLD OIL FILTER
1	TWD; SEPARATR
2	NCB; PURPLE POWER 40 OZ

CSHOP-2020-576

Comments: **PMC REPAIR FOR PMC WO#526**

Date Opened: 2-3-2020

Date Finished

2-13-2020

Meter 1 Reading:

134,624

TASKS PERFORMED

GEAR BOX FIRE PUMP

DISCHARGE GAUGE

SWITCH

WIPERS-WASHER

EXHAUST SYSTEM

ENGINE AND ACCESSORIES

LIGHTING SYSTEM

REPAIR FROM PM - POWER STEERING

REPAIR FROM PM - COOLING SYSTEM

TRANSMISSION

REPAIR FROM PM - DIFFERENTIALS

REPAIR FROM PM - TRANSMISSION

AIR DRIER

AIR HORN

MIRRORS

SEAT BELTS

A/C SYSTEM

Q PARTS

5	4PC; GEAR OIL SYN BULK DELO
4	5CS; GAUGE 3 5 30 600 WH
1	5PF; SWITCH DOOR DPST NC MOM
2	1AN; 24 WIPER BLADE
1	FIL; NAPAGOLD AIR FILTER
2	GRO; REFLECTOR
1	FIL; NAPA HYDRAULIC FILTER
1	FIL; NAPA COOLANT FILTER
1	2DD; FILTER KIT TRANS SUMP 4
1	2DD; OIL LEVEL
1	2DD; 2DD
1	BK; INSERT
1	2DD; VALVE BODY HARNESS
19	4PC; GEAR OIL SYN BULK DELO
1	1CH; BRAKE CLEANER MOPAR
19	9OC; BULK TRANS SYN
1	2DD; FILTER KIT TRANS SUMP 4
3	CRC; CLEAN R CARB 20OZ
1	TWD; AD 9KIT MINOR
1	TWD; AD 9KIT
2	9AP; HORN KIT PAI 3390 1094
1	5TF; GAUGE
1	GRO; CONVEX MIRROR
1	2FL; BELT ASSY
1	SVP; COMPRESSOR
1	NBH; V BELT
1	HOSES

Asset Work Order History 10155563

CSHOP-2020-914

Date Opened: 2-18-2020 Date Finished 2-21-2020 Meter 1 Reading: 92,000

TASKS PERFORMED

Q PARTS

FIRE PUMP

2 5HP; HALE RELIEF VALVE STRAINER

RADIO-2017-572

Comments: **REPLACED UH-51 HEADSET**

Date Opened: 9-8-2017 Date Finished 9-15-2017 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

RADIO

1 9ES; HEADSET, WIRED, FIRECOM (CONTROL COMM)

Service Requests:

09/03/2017 RADIO / /
RADIO ISSUES- DRIVERS HEADSET NEEDS TO BE REPLACED, WIRES ARE COMING APART

RADIO-2018-321

Comments: **REMOVAL OF 10141692, INSTALL OF 10205593 INTO SE16 - 10155563**

Date Opened: 4-17-2018 Date Finished 4-17-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

04/17/2018 RADIO / /
REMOVAL & INSTALL OF NEW MOTOROLA MOBILE RADIO INTO SPARE ENGINE 16

SSHOP-2019-181

Date Opened: 6-11-2019 Date Finished 6-12-2019 Meter 1 Reading: 86,020

TASKS PERFORMED

NO PARTS USED

HANDLIGHT

SSHOP-2019-250

Date Opened: 8-9-2019 Date Finished 8-9-2019 Meter 1 Reading: 87,856

TASKS PERFORMED

NO PARTS USED

FOAM SYSTEM

SSHOP-2019-265

Date Opened: 8-21-2019 Date Finished 8-21-2019 Meter 1 Reading: 88,276

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
SEAT FRONT

Asset Work Order History 10155563

SSHOP-2020-80

Date Opened: 3-6-2020

Date Finished

3-20-2020

Meter 1 Reading:

92,000

TASKS PERFORMED

NO PARTS USED

TIRE
