



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V303

In Date: 10/04/2005  
Close Date: 10/05/2005

Meter Reading:

#### Problem?

WIG-WAG HEADLIGHTS WILL NOT SHUT OFF, T-14

Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V1301

In Date: 01/25/2006  
Close Date: 01/31/2006

Meter Reading: 40,430.00

#### Problem?

CHECK THROTTLE FOR OPERATION, T-14

Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V1469

In Date: 02/10/2006  
Close Date: 02/13/2006

Meter Reading:

#### Problem?

TACH IN CAB INOP, T-14

Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V1434

In Date: 02/06/2006  
Close Date: 02/14/2006

Meter Reading: 40,526.00

#### Problem?

ROAD TO PUMP SWITCH LEAKING AIR, T-14

Task performed:

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* **FREIGHLINER TANKER TRUCK**

**Workorder: V2226**

**In Date:** 04/14/2006

**Meter Reading:** 41,390.00

**Close Date:** 05/15/2006

**Problem?**

RELIEF VALVE INOP, T-14

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

See B Inspection pre-printed form

0100030000SCREEN 6 IN	2
038-0090-50VALVE RELIEF-HALE	1
038-0100-00BODY REIEF VALVE HALE	1
0465130010GASKET GEARBOX COVER	2
048009000SPEEDCOUNTER PUMP PANEL	1
05-17223-000CAP RADIATOR 10 LB	1
073-0010-00PISTON RELIEF VALVE HALE	1
0772750010SNAP RING	4
107623XAIR COMPRESSOR	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1157NABULB	1
1891BULB	1
211-2BULB	1
23505248COMPRESSOR FUEL PUMP GASKET	1
23505249FUEL PUMP DRIVE GEAR	1
250-0214-00250-0214-00 BEARING	1
250-0214-06250-0214-06 BEARING	2
250040900BEARING QFLO 250-0409-00	1
2508010000BEARING NEEDLE ROLLER	1
284358GOVERNOR D-2	1
2962540000SEAL SAME AS 29867 C/R	2
2PB51BELT	1
30-04330-043 AIR FILTER	1
473464473464 OIL SEAL	2
4870JBALTERNATOR 270 AMP NEEDS EXCITER WIRE	1
493988493988 GAS CAP	1
5-677XU JOINT	2
537-1700-00USE 037-1341-50-0 SHIFT KIT	1
54-140CIRCUIT BREAK 40 AMP	1
54-15 31-15 WIPER BLADE	2
546-0200-50QD REL.VALVE KIT	1
7-73-122BOLT FLANGE 7/16	18
800405PURGE VALVE KIT	1
80350DOME LIGHT	1
87499RY48 RELAY	1
9096-02SWITCH	1
91553943GUAGE	1
9510BELT	3
AS1141SLACK ADJUSTER AUTOMATIC	4
B2-LMB2-LM SPARK PLUG	1
CA3990AIR FILTER 46883	1
H4656USE CV TYPE HEAD LIGHT	1
MISC PARTMISC PART	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
TURBO64STROBE TUBE	2
UJ376U-JOINT USE 5-407X	2

Vendor?: VC-15214

#### Workorder: V2733

In Date: 05/25/2006

Meter Reading:

Close Date: 06/05/2006

#### Problem?

AIR LEAK, T-14

Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V3129

In Date: 06/24/2006

Meter Reading:

Close Date: 07/06/2006

#### Problem?

1. throttle surging with flasing of emergy lighs when pump is in gear.. 2. need 2 1/2" cap for intake (male threads). tanker 21

Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V3592

In Date: 07/21/2006

Meter Reading:

Close Date: 08/04/2006

#### Problem?

oil pressure gauge on pump panel not working. t14

Task performed:

Parts

Quantity

194BULB 10

78308930 AKRON 3 IN VALVE 1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V4014**

In Date: 08/18/2006

Meter Reading:

Close Date: 08/23/2006

**Problem?**

driver side tailboard handrail broken , need lower bracket T14

**Task performed:**

Parts

Quantity

291525END STANCHION

1

**Workorder: V4467**

In Date: 09/16/2006

Meter Reading: 2,481.00

Close Date: 09/27/2006

**Problem?**

LEFT REAR TURN SIGNAL LIGHT IS OUT. T-14

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 16 DROP OFF CHAIN SAW.
2. TRAVELED TO STN 19 DROP OFF VENT SAW AND CHAIN SAW.
3. TRAVELED TO STN 14 R/R R-REAR BULB.

NO PARTS USED

**Workorder: V4547**

In Date: 09/22/2006

Meter Reading: 2,481.00

Close Date: 10/02/2006

**Problem?**

Float-a-pump for T14 has a broken spark plug, also insulated rubber cap for plug has a hole worn through it.

**Task performed:**

Parts

Quantity

1. TRAVELED TO STN 14 FOUND SPARK PLUG BROKEN, REPLACED SPARK PLUG. PUMP RUNNING IN GOOD WORKING ORDER NOW.

B2-LMB2-LM SPARK PLUG  
BPMR4A6028 SPARK PLUG

2  
2

**Workorder: V4733**

In Date: 10/04/2006

Meter Reading: 2,481.00

Close Date: 10/12/2006

**Problem?**

red fluid leaking for bottom rt. side of radiator. possibly tranny fluid from tranny cooler. T-14

**Task performed:**

Parts

Quantity

1. TRAVELEDD TO STN 14 CHECKED FOR TRANI LEAK, ROAD TEST VEHICLE, NO LEAK DETECTED AT THIS TIME.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V4986

In Date: 10/20/2006  
Close Date: 11/02/2006

Meter Reading: 2,506.00

#### Problem?

relief valve not working T-14

#### Task performed:

1. TRAVELED TO STN 14. CLEANED SCREEN AND FOUND BAD GROUND ON SWITCH, REWORK GROUND, TEST/ OK.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V5414

In Date: 11/16/2006  
Close Date: 12/04/2006

Meter Reading: 43,131.00

#### Problem?

left rear tail light lens is melting from heat from tail light bulb T14

#### Task performed:

1. go to sta. and see what parts needed for repair  
2. r&r light

#### Parts

644-2601WARNING LIGHT 2010-0300-30  
K202200001K202200001 LENS

#### Quantity

2  
1

#### Workorder: V6517

In Date: 01/29/2007  
Close Date: 02/01/2007

Meter Reading: 2,553.00

#### Problem?

emergency warning lights (4) on hood not working.probley wireing or breaker. T14

#### Task performed:

1. R&R switch in dash tested ok

#### Parts

S30TLBULB

#### Quantity

2

#### Workorder: V6617

In Date: 02/05/2007  
Close Date: 03/14/2007

Meter Reading: 4,382.00

#### Problem?

AIR LEAK, T-14

#### Task performed:

1. Air brake leaking ordered parts  
2. R&R parking brake valve assy

#### Parts

800573MV3 DASH BRAKE VALVE

#### Quantity

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

**Workorder: V6821**

**In Date:** 02/19/2007

**Meter Reading:** 2,553.00

**Close Date:** 03/14/2007

**Problem?**

emergency lights on cab / hood out again. T14

**Task performed:**

Parts

Quantity

Removed strobe pack rewired terminals and reassemble

NO PARTS USED

---



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V8254**

**In Date:** 05/14/2007

**Meter Reading:** 43,820.00

**Close Date:** 06/05/2007

**Problem?**

B inspection and related repairs (back from 14)

**Task performed:**

1. Performed B-Service, replaced oil & filter, fuel & air, serviced transmission, serviced both rear ends, serviced transfer case, greased chassis
2. Removed and rebuilt air dryer assy
3. removed tie rod assy. Replaced both tie rod end boots. reinstalled rods
4. Replaced batteries & cables. Cleaned and tightened all connections, checked charging system
5. Replaced belts, tightened to specs
6. R/F wheel seal leaking, removed front hubs, replaced brake linings and drums, replaced seals, adjusted all brakes
7. Removed & replaced both rear clearance marker light assy with LED style
8. Serviced A/C system, replaced A/C dryer, vacumed and refilled Freon to spec
9. Warning light strobe pack burnt, replaced with upgraded unit, re-wired system to fit
10. Troubleshoot air leak, repaired various air leaks throughout system
11. Repair wiring at dome light
12. Vacumed test pump, repaired leak at valve, test again - OK
13. Replaced broken holddown clamps for hard suction hoses
14. Repaired wiring at backup alarm
15. Adjusted pump packing, ran pump checked OK
16. Service Float-A-Pump

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	1
1157BULB	1
22-43249-0001513 SW PRES.A/C	1
2953056429530564 TRANS. FILTER	1
330-3009COVER GASKET	2
3687DRUM 3687X	2
372000082CHROME MARKER LIGHT MOUNT	2
372000083GASKET MOUNTING	2
372000084MARKER LIGHT	2
372000085HARNES FOR MARKER LIGHT	2
380048A380048A SEAL	3
716907-0610A DRYER	1
800405PURGE VALVE KIT	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
CA3990AIR FILTER 46883	1
E-2769MKT4515QB BRAKE KIT	2
FREIGHTSHIPPING CHARGES	1
HP-31DBATTERY 950CCA HP-31D	3
JEIBC207M3BWJEIBC207M3BWS CABLE BATT	1
JEIBC207M3RWCABLE BATT	1
NI PLATEMARKER LIGHT MOUNTING PLATE	2
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
REX4514QFRONT BRAKE SHOES TANKER	4
TRW-L24VC0109DRAG LINK BOOT	1
UMVS-0811-11STRAP ZICO	2
UPS690NLA REPAIR ONLY POWER SUPPLY - WHELEN	1





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V8895**

In Date: 06/18/2007  
Close Date: 07/02/2007

Meter Reading: 4,382.00

**Problem?**

tow from central shop to Allison in Miami (outside agency-sister's towing)

**Task performed:**

Parts

Quantity

1. Tow from central shop to Allison in Miami

NO PARTS USED

Vendor?: SISTER'S TOWING

**Workorder: V9251**

In Date: 07/10/2007  
Close Date: 07/18/2007

Meter Reading: 4,382.00

**Problem?**

A inspection and related repairs T14 (back from transmission overhaul)

**Task performed:**

Parts

Quantity

A-Inspection & road test

1. Diagnosing rear lighting problem; fnd light bar falling apart & corrosive on contacts; replc/rewire rear lighting sys

2057LIGHT BULB

1

2. Fill tank & run pump; chk pressure & relief valve pump opns as per E. Ehrke, floor foreman; replc pump panel valve

3201132011 LENS

1

413-07413-07 PIGTAIL WIRE

1

52-247TERMINAL BLOCK 10 POST

1

644-2601WARNING LIGHT 2010-0300-30

1

67BULB 12 VOLT

1

H4651USE CV TYPE SEALED BEAM

1

S777COUPLING NIPPLE

1

**Workorder: V8625**

In Date: 06/06/2007  
Close Date: 07/26/2007

Meter Reading: 4,382.00

**Problem?**

transmission has skinner valve problem

**Task performed:**

Parts

Quantity

1.Replc both skinner valves & rep brkn T-fitting; test drove trans; internal problem exists.

NO PARTS USED

2. Larson assisted with setup of skinner valves & diagnostics



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V9440**

In Date: 07/19/2007      Meter Reading: 4,382.00  
Close Date: 07/30/2007

**Problem?**

overhaul transmission (outside agency-Fla Detroit Allison) T14

**Task performed:**

Overhaul transmission - Fla. Detroit Allison

**Parts**

NO PARTS USED

**Quantity**

Vendor?: FLA DETROIT

**Workorder: V9532**

In Date: 07/25/2007      Meter Reading: 4,382.00  
Close Date: 08/01/2007

**Problem?**

Air leak- check unit function for swap with T72

**Task performed:**

air leak in dash/ vent

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V9741**

In Date: 08/06/2007      Meter Reading: 4,382.00  
Close Date: 08/08/2007

**Problem?**

a inspection and repairs as needed spare tender

**Task performed:**

1. a inspection
2. turn signal inop on dash-repair circert board
3. repair strobes on bumper-rewire power supply
4. marker on bumper inop-repair wiring on ground

**Parts**

032-0116549297 BATTERY INDICATOR  
H4651USE CV TYPE SEALED BEAM  
H4656USE CV TYPE HEAD LIGHT

**Quantity**

1  
1  
1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V10509

In Date: 09/18/2007

Meter Reading: 44,631.00

Close Date: 09/27/2007

#### Problem?

A INSPECTION SPARE TENDER 1

#### Task performed:

A -Inspection

- 2.5 discharge 90 degree bad; rem/install part
- Brake light inop & backup buzzer; fnd grd cable loose; secure grd cable
- Parts pickup at Al Packard Ford east
- Shop setup
- Headliner light inop; drop headliner to find loose grd; sec grd & install headliner
- Handrail stan & bar missing; retap holesm, cut bar & install
- Tarp hold downs msng; retap holes, install new hold downs buttons & install tarp

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V11683

In Date: 11/19/2007

Meter Reading: 44,631.00

Close Date: 12/03/2007

#### Problem?

repair air leak spare tanker at 14

#### Task performed:

- Drive to Okee park, did not have valve, bring to shop repair, test OK.

#### Parts

#### Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

#### Workorder: V11717

In Date: 11/21/2007

Meter Reading: 2,611.00

Close Date: 12/03/2007

#### Problem?

R/T21 WIG WAGS NOT WORKING. NEED 3/24 and 3/12 inch bungy cords.

#### Task performed:

- Head light Inop. R/R wig wag, Test OK.

#### Parts

#### Quantity

360HLOBSOLETE FLASHER

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V11871

In Date: 12/03/2007

Meter Reading: 44,631.00

Close Date: 12/04/2007

#### Problem?

a inspection and repairs as needed back from 21

#### Task performed:

- |   | Parts         | Quantity |
|---|---------------|----------|
| 1. "A"inspection order hub cap front wheel. | NO PARTS USED |          |

#### Workorder: V11946

In Date: 12/06/2007

Meter Reading: 44,631.00

Close Date: 12/11/2007

#### Problem?

b inspection and repairs as needed spare tender back from 21

#### Task performed:

- |  | Parts                                   | Quantity |
|--|---|----------|
| 1. Perform "B" service.                          | 15W40BSYN OIL BULK QTS                  | 40       |
| 2. Replace corner piece of tail board (missing). | CA3990AIR FILTER 46883                  | 1        |
|  | P1147GFUEL FILTER 33120 WIX DELCO TP916 | 1        |
|  | P3613HYDRAUL FILTER 51623 WIX           | 1        |
|  | PH7405 51971 OIL FILTER WIX             | 2        |
|  | PR338324070 WIX FILTER WATER            | 1        |
|  | R90PFILTER FUEL 33231                   | 1        |

#### Workorder: V6600

In Date: 02/02/2007

Meter Reading: 4,382.00

Close Date: 01/08/2008

#### Problem?

park brake valve leaking t14

#### Task performed:

	Parts	Quantity
	NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V12283**

In Date: 12/31/2007  
Close Date: 01/16/2008

Meter Reading: 44,631.00

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED ST BACK FROM STA 14

**Task performed:**

Parts	Quantity
8550A250A8550A250A BULB	1
91583956GAUGE 0-600 PSI 5 IN BLACK COMP	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
HP-31DBATTERY 950CCA HP-31D	3

**Workorder: V4373**

In Date: 09/11/2006  
Close Date: 02/07/2008

Meter Reading: 2,481.00

**Problem?**

radio has to be manually turned on and off T14

**Task performed:**

Parts	Quantity
NO PARTS USED	

**Workorder: V13727**

In Date: 03/06/2008  
Close Date: 03/07/2008

Meter Reading: 45,382.00

**Problem?**

a inspection and repairs as needed st back from 21

**Task performed:**

- "A" inspection
- 1A "A" inspection
- Repair air leak on control panel switch
- Replace bulb on front post light
- Tighten hose fittings and hose

Parts	Quantity
NO PARTS USED	

**Workorder: V14552**

In Date: 04/18/2008  
Close Date: 04/24/2008

Meter Reading: 2,686.00

**Problem?**

FLOAT PUMP WONT START.... ALSO FYI... HOSE REEL HAS HEAVY RUST AND HOSE IS DRY ROTTED. T-14

**Task performed:**

- replace spark plug and adjust carb.

Parts	Quantity
J19LMUSE 1147 NGK SPARK PLUG	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V14791

In Date: 04/30/2008  
Close Date: 06/02/2008

Meter Reading: 45,679.00

#### Problem?

A inspection and repairs as needed st back from 14

#### Task performed:

- A-INSPECTION
- 2. RESECURE REAR CHUT PANEL
- 3. REP WIRE FOR DOME LIGHT. J

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V16509

In Date: 07/22/2008  
Close Date: 08/01/2008

Meter Reading: 45,679.00

#### Problem?

C INSPECTION AND REPAIRS AS NEEDED SPARE TENDER

#### Task performed:

- Perform C-Inspection
- 2. Svc T-Case
- 3. Replc RPM counter cable head (seized).
- 4. Rebuilt air dryer.
- 5. Replc all (3) btrys; cln all negative cables at frame rails; cldd all positive calbes at btry swtch; chkd btry swtch resistance.
- 6. R/R cab steps to replc mntng bolts; (broken/loose).
- 7. Replc left/right turn signal side marker lenses.
- 8. Replc left/right flag stickers.
- 9. Chkd voltage output at alt; FNP; (faulty btrys gave wrong output).
- 10. Replc all 200' of booster reel hose; greased gear drive; lubed chain. (cracked/dried).
- 11. Cln shop j

#### Parts

048009000SPEEDCOUNTER PUMP PANEL 1  
 107796DRYER KIT AD9 -NEW 1  
 107800VALVE CHECK AD9 1  
 15W40BSYN OIL BULK QTS 40  
 680-10LAMERICAN FLAG W UV CLEAR LEFT 1  
 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1  
 800405PURGE VALVE KIT 1  
 91513AMBER LENS 2  
 HP-31DBATTERY 950CCA HP-31D 3  
 P1147GFUEL FILTER 33120 WIX DELCO TP916 1  
 P3613HYDRAUL FILTER 51623 WIX 1  
 PH7405 51971 OIL FILTER WIX 2  
 PR338324070 WIX FILTER WATER 1  
 R90PFILTER FUEL 33231 1  
 BM6AUSE 5921 SPARK PLUG 1  
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY 3

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V16906

In Date: 08/07/2008

Meter Reading: 45,679.00

Close Date: 08/15/2008

#### Problem?

Shop's spare tender; preconnect #2 will charge without pulling valve. Discharge #4 difficult to open. Discharges #1&2 have leaky valves, won't hold pressure for hose testing. asset #K06239000

#### Task performed:

- 1 rebuild valves and vacuum test
- 2 john g assisted in rebuilding valves
- 3 install valves, vacuum test, run pump, fill tank and c/o for leaks

Parts	Quantity
0773149TRUNION BALL BRASS	1
23-12462-130SUPPLIES A/C SANDEN COMPRESSOR BOL	1
8201L17-3428 ESTER OIL E7	1
91378905 VALVE KIT 2 IN AKRON	2
91388906 VALVE KIT 2.5 IN AKRON	1
91398907 VALVE KIT 3 IN AKRON	2
9440BELT	1
9480BELT	1
K080716BELT	1

#### Workorder: V16907

In Date: 08/07/2008

Meter Reading: 45,679.00

Close Date: 09/02/2008

#### Problem?

Continuation of shop's spare tender, asset #k06239000; came to st 48 with only 1050ft of hose and not tested since 2006. Attempted to test the hose and 300ft failed at low pressure. It has 750ft of untested hose.

#### Task performed:

HOSE WAS CHARGED OUT FOR THIS UNIT, ALSO HOSE WAS SENT TO STATION 14 AND HOSE TESTED BY CREW AND PUT ON UNIT.

Parts	Quantity
NO PARTS USED	

#### Workorder: V17378

In Date: 08/28/2008

Meter Reading: 45,679.00

Close Date: 09/02/2008

#### Problem?

A inspection and repairs as needed s t back from 14

#### Task performed:

A-Inspection j

Parts	Quantity
NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHTLINER TANKER TRUCK

#### Workorder: V18150

In Date: 10/06/2008      Meter Reading: 2,729.00  
Close Date: 10/29/2008

#### Problem?

big gash on sidewall of tire on right side rear axle S T AT 72

#### Task performed:

Pressure test cooling sys; NPF; test cap (failed) replc cap; clear codes; test drive.      j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: CALLAGHAN

#### Workorder: V18478

In Date: 10/21/2008      Meter Reading: 46,440.40  
Close Date: 11/10/2008

#### Problem?

replace hose bed cover spare tanker

#### Task performed:

Replace hose bed cover spare tanker.      j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: CENTRAL AUTO TRIM

#### Workorder: V18829

In Date: 11/04/2008      Meter Reading: 2,742.30  
Close Date: 11/20/2008

#### Problem?

THERE IS A SMALL AIR LEAK.LEAK'SDOWN BELOW 60PSI IN ABOUT 5/6 HR'S T-21

#### Task performed:

1. Driv e to Stn; tighten fitting; still leaking at foot valve; order parts.
2. R/R foot valve.      j

#### Parts

286171BRAKE VALVE E-6 NEW

#### Quantity

1

#### Workorder: V19021

In Date: 11/12/2008      Meter Reading: 46,816.00  
Close Date: 11/20/2008

#### Problem?

A INSPECTION AND REPAIRS AS NEEDED BACK FROM 21

#### Task performed:

1. A-Inspection.
2. R/R L-frnt strobe light.
3. Tighten all pump panel gauges.      j

#### Parts

1136SOLENOID AIR HORN WAS  
1681AIR HORN KIT GROVER  
508RED58EC20RU STROBE-RED SURFACE MOUNT  
HRN6681HORN AIR 24" GROVER P/N-1510

#### Quantity

1  
2  
1  
1





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V21111

In Date: 02/14/2009  
Close Date: 02/24/2009

Meter Reading: 2,763.00

#### Problem?

pump leaks,driver side windshield wiper blade 10-7,air leaks,rt. side pumppanel lights not working. ST AT 14

#### Task performed:

Drive to Stn; tighten lines on pump; replc wipers; replc fitting for air leak & replc bulb; test ok. j

#### Parts

#### Quantity

52-24WIPER BLADES ANCO 24

2

54-15 31-15 WIPER BLADE

2

#### Workorder: V18349

In Date: 10/15/2008  
Close Date: 03/02/2009

Meter Reading: 2,738.90

#### Problem?

Water chute on spare tender wont close all the wayST AT 72

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V19716

In Date: 12/12/2008  
Close Date: 03/02/2009

Meter Reading: 46,875.00

#### Problem?

A INSPECTION AND REPAIRS AS NEEDED

#### Task performed:

A-Inspection j

#### Parts

#### Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V21480**

**In Date:** 03/02/2009

**Meter Reading:** 47,069.00

**Close Date:** 03/03/2009

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED S T BACK FROM 14

**Task performed:**

Parts

Quantity

- A-Inspection & road test.
- 2. Pass side spot mirror loose; rem/cln/reinstall; secure screws.
- 2. C-1 holdopen hinge screw loose; secure screws/nut.
- 4. R-side eng compt light inop; dia fault; fnd corroded butt connector ; splice & loose swtch conne ction; correct faults.
- 5. Chk A/C compressor for leak; signs of oil leak frm behind pulley; no leak fnd.
- 6. Pump packing leaking; diss side panel for access; adj packing & operate pump; reassemble.
- 7. Fill water tank.
- 8. Spotlight brkn; replce & install hanger for spotlight.
- 9. Stainless body molding loose; rem, retap holes & secure to body. j

NO PARTS USED

**Workorder: V21850**

**In Date:** 03/16/2009

**Meter Reading:** 2,777.20

**Close Date:** 03/26/2009

**Problem?**

can hear air leaking under truck after truck is shut off ( comes from ontop of transmission area), stops after about 5min. st at 14

**Task performed:**

Parts

Quantity

- 1. Drive to Stn; look at valve; order parts from Ed Woodland; need more info.
- 2. C/O air leak on valve; mounted on top of trans; ordered new valve.
- 3. Rep air leak in dash.
- 4. Drove to airport to renew airpot I.D. j

NO PARTS USED

**Workorder: V21832**

**In Date:** 03/16/2009

**Meter Reading:** 47,069.00

**Close Date:** 03/27/2009

**Problem?**

pump shift leaking air T14

**Task performed:**

Parts

Quantity

- Drive to Stn; re build pump shifter; test ok. j

5460370530VPS SHIFT KIT 546-0370-53-0

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V21974

In Date: 03/20/2009  
Close Date: 03/27/2009

Meter Reading: 47,069.00

#### Problem?

A inspection and related repairs (tender from 14)

#### Task performed:

1. Perform "A" service.
2. replcd marker light bulb in left T/S side light.

j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V22756

In Date: 04/23/2009  
Close Date: 05/04/2009

Meter Reading: 47,514.70

#### Problem?

B inspection and related repairs

#### Task performed:

B-Inspection j

#### Parts

15W40BSYN OIL BULK QTS  
 7001-25ESEAL  
 91553941GAUGE  
 A06-18266-000AIR SOLENOID  
 FREIGHTSHIPPING CHARGES  
 P1147GFUEL FILTER 33120 WIX DELCO TP916  
 PH7405 51971 OIL FILTER WIX  
 R90PFILTER FUEL 33231  
 VM43REGULATOR AIR

24  
1  
1  
1  
1  
1  
2  
1  
1

#### Workorder: V22059

In Date: 03/24/2009  
Close Date: 05/11/2009

Meter Reading: 47,069.00

#### Problem?

REPLACE 4 REAR TIRES, SPARE TENDER-1

#### Task performed:

Replace (4) rear tires, spare Tender-1 - Callaghan j

j

#### Parts

NO PARTS USED

#### Quantity

Vendor?: CALLAGHAN



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V22582**

In Date: 04/16/2009  
Close Date: 05/14/2009

Meter Reading: 2,798.00

**Problem?**

The air system bleeds down once the engine is shut down. There is a audible leak in a loom of hoses located underneath the drivers seat at the top of the frame rail. spare tanker at 72

**Task performed:**

1. Rem air swtch valve on top of tranny.
2. Adj pump packing; hard to rem cage; cln up; boar tight up packing.
3. Replc 6" press gauge on pump panel.
4. Replc piping for tank fill; vital - pipe on elbow rotten; clnup piping. j

Parts

Quantity

NO PARTS USED

**Workorder: V24014**

In Date: 06/12/2009  
Close Date: 06/19/2009

Meter Reading: 47,514.70

**Problem?**

A inspection and repairs

**Task performed:**

- Perform "A" Inspection j

Parts

Quantity

NO PARTS USED

**Workorder: V24439**

In Date: 06/29/2009  
Close Date: 07/02/2009

Meter Reading: 47,917.50

**Problem?**

A inspection and repairs (from 72)

**Task performed:**

1. Road test & A-Inspection
2. Dia/rep svc valve leaking; rem/install new R-14 relay valve.
3. Air leak behind dashboard; diss dash air cyl for A/C \_\_\_ line connection leaking; parts on order. j

Parts

Quantity

103010VALVE RELAY

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V24478**

In Date: 06/30/2009

Meter Reading: 47,917.50

Close Date: 08/05/2009

**Problem?**

air leak parts ordered spare tender

**Task performed:**

1. Take dash apart & rem air duct w/leaking blend door motor.
2. install new air duct w/blend door motor, put dash back tog.

**Parts**

**Quantity**

923182-2151 SWITCH MOMENTARY 24-372	1
A22-39461-000AIR DUCT	1
FREIGHTSHIPPING CHARGES	1

**Workorder: V24906**

In Date: 07/20/2009

Meter Reading: 48,124.30

Close Date: 08/05/2009

**Problem?**

A-inspection stender1

**Task performed:**

- A-Inspection
2. Finish insp.
3. T-shoot no dash lights & volt meters; fnd volt drop on grnd side; have new grnd wires frm btry to firewall & dash.
4. Rep swtch for L-1 compt light.
5. T-shoot shoe reel intermittent inop; R/R switch.
6. Start T-shoot pum panel oil press & trans temp gauge
7. Continue T-shoot pump panel oil press & trans temp gauge; R/R oil press sending unit; replcd bus bar for pump panel; order parts.
- 8.

**Parts**

**Quantity**

52-24682-2313 TERMINAL BLOCK 8 POST	1
54-13030055-30 CIRCUIT BREAKER	3
DDE/23532797OIL PRESSURE SWITCH DETROITS	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V25581**

**In Date:** 08/17/2009

**Meter Reading:** 48,124.30

**Close Date:** 09/11/2009

**Problem?**

A inspection and repairs (from 14)

**Task performed:**

- A-Inspection, fill washer bottle
- 2. Replc left spotlight bulb & wire term.
- 3. Press chk cooling sys-ok; press chk rad cap-NG; replcd rad cap.
- 4. Air all tires.
- 5. Replcd RF hub oil reservoir, gkst & fill plug; cln/fill to proper level.
- 6. Chk opn of rear brakes on 2nd axle-ok; adj brakes on 2nd rear axle.
- 7. Chk opn of relief valve/light; rem access cvr & fnd relief valve stock open; valve needs to be rebuilt.
- 8. Cut access hole in frt pump panel for removal of relief valve; drill/thread end of relief valve for use of slide hammer to facilitate removal of relief valve; rebuild relief valve & install; chkd opn of relief valve-ok.
- 9. Rebuild primer valve.
- 10. Replcd relief valve light fixture; splice wires; rem radio compt box for access; thread holes for box fasteners for installation w/o using nuts.
- 11. Dia water level gauge; fnd box/sensor bad; replcd sensor, gauge & electronic box; replc gauge bulb; splice wires, drain tank & test; ordered proper length sender.
- 12. Dia time for no pump panel oil press gauge.
- 13. Dia pump panel oil press gauge inop; fnd bad sender; ordered sender; replc sender/gauge; install wiring; secure wiring; R/R lower dash.
- 14. Fnd rear of truck badly rusted; had inspected by Scott Walthers; not to be addressed per Ed Ehrke & Scott.
- 15. Dia air leak; fnd fittings on drivers air actuated seat leaking & valve; replcd valve & reseal fittings w/thread sealer.
- 16. Make up label for wipers & other functions.
- 17. Dia air leaks; fnd fitting on firewall, hose under dash on air manifold & tank drain valve leaking; tighten fitting, hose & replcd drain valve.
- 18. Fill water tank. j

**Parts**

**Quantity**

032110401150 VALVE AIR SEAT	1
05-17223-000CAP RADIATOR 10 LB	1
12105QUICK DRAIN	1
1445BULB	1
2522GAUGE KIT	1
340-4009CAP OIL HUB	1
359-5990PLUG - HUB OIL CAP	1
4007BULB NIGHT FIGHTER	1
516TIRE INFLATOR	1
546-0200-50QD REL.VALVE KIT	1
AO638AO638 SENDER 4-WIRE	1
PVG-KITORING KIT	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V26266

In Date: 09/15/2009

Meter Reading: 48,124.30

Close Date: 09/17/2009

#### Problem?

repair water tank level guage

#### Task performed:

Install correct length water tank sender unit. j

#### Parts

4572400FOAM TANK GAUGE

#### Quantity

1

#### Workorder: V27525

In Date: 11/09/2009

Meter Reading: 48,124.30

Close Date: 11/30/2009

#### Problem?

LOWER BRACKET FOR HANDLE ON RT REAR OF TENDER 14 DROKE/ NEEDS REPLACE.... st at 14

#### Task performed:

Fnd rear handle brkn; must rem brkn end cap frm grab rail; needs end cap. j

#### Parts

291525END STANCHION

#### Quantity

1

#### Workorder: V27646

In Date: 11/13/2009

Meter Reading: 48,124.30

Close Date: 11/30/2009

#### Problem?

A inspection and repairs (from 14)

#### Task performed:

A-Inspection  
2. Redrill holes; install inserts & install new brag handle on R/side rear. j

#### Parts

101260001291686 GRAB RAIL FT

291525END STANCHION

#### Quantity

1

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V29577**

**In Date:** 02/01/2010

**Meter Reading:** 48,124.30

**Close Date:** 03/05/2010

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED SPARE TENDER

**Task performed:**

1. Drain coolant & rep fitting in water pump.
2. R/R btrys.
3. Fill radiator & press test coolant sys.
4. Fnd tank-to-pump leaking; adj linkage & vac; test ok.
5. Install straps on frnt hose body side hose bed & tailboard for cvrs.
6. Rinstall strut rod rear axle.
7. R/R axles seals on both rear end.
8. Perform quality chk.
9. Jack rear up; rem drums/brake shoe; cln up hub/backing plate; started back w/brake/wheel.
10. Svc air dryer.
11. Finish rear brakes.
12. Rem stud/rod to \_\_\_\_ put new bushing in it.
13. R/R backup alarm.
14. Rem air filter; looks good; blow out; put back in.
7. R/R belts.
16. Torque u-bolts to 450 \_\_\_\_.
17. C-Service
18. R/R headlight & rep wigwag lights; fill w/water & chkd codes - no codes. j

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1157BULB	1
15W40BSYN OIL BULK QTS	40
23-09114-010WASHER	1
2PB51BELT	1
3600AXBRAKE DRUM 16.5X7	4
380003ASEAL	4
401581GASKET AXLE FL80 R002435	4
575BACKUP ALARM ECCO 107 DEC	1
800405PURGE VALVE KIT	1
9510BELT	3
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
E-5743E-5743 WEDGE DRIVE FLANGE	1
FG-Q59278P/S GASKET	1
FG83213DP/S FILTER	1
H4656USE CV TYPE HEAD LIGHT	1
HP-31DBATTERY 950CCA HP-31D	3
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
S777COUPLING NIPPLE	2
SAHSVS2510STRAP	2
XK5234515QBRAKE SHOES 4515Q	4
CYBS27299011 STRAP 36IN	1
322-123TORQUE ARM BUSHING SPARE TENDER	2
FREIGHTSHIPPING CHARGES	18





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V30376

In Date: 03/02/2010      Meter Reading: 48,124.30  
Close Date: 04/22/2010

#### Problem?

hose bed cover (outside agency-central auto trim)

#### Task performed:

HOSE BED COVER - CENTRAL AUTO J

#### Parts

NO PARTS USED

#### Quantity

Vendor?: CENTRAL AUTO TRIM

#### Workorder: V31336

In Date: 12/29/2009      Meter Reading: 48,558.00  
Close Date: 05/05/2010

#### Problem?

A inspection and repairs (from 48)

#### Task performed:

1. Road test & A-Inspection.
2. Air leak; chk sys; fnd purge valve leaking; mk rep; air still leaking; fnd air leak loose fitting; secure fitting.
3. Help Mac look for air; chk out air valve on trans not leaking; tighten up some lines; fnd purge leaking.
4. Fill windshield washer fluid reservoir; rep crack fluid line. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V31687

In Date: 04/21/2010      Meter Reading: 48,891.00  
Close Date: 05/10/2010

#### Problem?

ODOMETER STICKS ST AT 72

#### Task performed:

1. Looks like needs a new speedometer in dash; sticks at 35 MPH, then jumps to 55 & up. j
2. Replace speedometer.
3. Calibrate speedometer. j

#### Parts

A22-38898-001SPEEDOMETER FLD120

#### Quantity

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V31982

In Date: 05/04/2010  
Close Date: 05/19/2010

Meter Reading: 48,935.90

#### Problem?

Perform "A" service.

#### Task performed:

A-Inspection j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V34337

In Date: 08/17/2010  
Close Date: 08/26/2010

Meter Reading: 49,139.00

#### Problem?

A INSPECTION ST BACK FROM 14

#### Task performed:

A-inspection  
2. Tighten fan belt.  
3. Rep air lines for leaks.  
Assist in air line repair.- Pat ja

#### Parts

365219PIPE FITTINGS  
91553941GAUGE

#### Quantity

1  
1

#### Workorder: V34044

In Date: 08/05/2010  
Close Date: 09/01/2010

Meter Reading: 48,935.90

#### Problem?

won't go in 4th gear lockup in pump mode

#### Task performed:

Wont go into 4th gear-locks up; Hobbs switch bad-replcd; rep wiring & air leak @ switch mnt. js

#### Parts

76575-4-NOSWITCH

#### Quantity

1

#### Workorder: V34321

In Date: 08/17/2010  
Close Date: 09/07/2010

Meter Reading: 49,000.00

#### Problem?

pipe on discharge side of pump leaking.(rusted thru ) " marked with yellow ribbon! ST AT 14

#### Task performed:

Diss, replc 2-1/2 nipple; test. js

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V35958**

**In Date:** 10/27/2010

**Meter Reading:** 49,150.00

**Close Date:** 11/17/2010

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED SPARE TENDER**

**Task performed:**

- B-Inspection
- 2. Emergency warning light 10-7; dia wiring problem; replc faulty sequencer; rewire under dash wiring for emergency lighting.
- 3. Assist mac on lights not working problem.
- 4. Compt light 10-7; dia fault; fnd bad grnd/cut wires; rep grnd & cut wires.
- 5. Cup holder brkn leaving jagged edges; rem cup holder.
- 6. Air leak behind dashboard; diss; fnd park brake air fitting loose; sec fitting & reassemble dash.
- 7. L-1 door lock loose; sec fasteners.
- 8. Rad hose chaffing on eng compt light suppot brkt; install protective rubber.
- 9. R/side light 10-7; replc bulbs.
- 10. Wtr tank door overflow loose; sec loose hinge.
- 11. R/side suction line leaking; fnd gskt defective; rem/install replacement gskt.
- 12. Wigwag 10-7; dia fault wigwag R/side failure; rem component & install new wigwag.
- 13. R/front t-signal 10-7; blown bulb; rem/install new bulb.
- 14. R/side pump panel light 10-7; replc blown bulb & bad bulb asy.
- 15. Quality check - Byrum
- 16. Quality check - McIntosh j

**Parts**

**Quantity**

15W40BSYN OIL BULK QTS	40
26331TAG LIGHT 60101	1
360HLOBSOLETE FLASHER	1
67BULB 12 VOLT	1
87499RY48 RELAY	4
EL30213091-32 LOAD MANAGER	1
EL35012EL35012 SWITCH ROCKER	1
H4651USE CV TYPE SEALED BEAM	1
H4656USE CV TYPE HEAD LIGHT	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH7405 51971 OIL FILTER WIX	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

**Workorder: V37005**

**In Date:** 12/08/2010

**Meter Reading:** 49,403.00

**Close Date:** 12/22/2010

**Problem?**

**air leak spare tender at 21**

**Task performed:**

- (1) TRAVELED TO ST21 FOR AIR LEAK IN SYSTEM OF SPARE TENDER THAT IS BEING USED AT ST21. FOUND LEAK AT THE PURGE VALVE. REPLACED WITH NEW.
- (2) SPARE TENDER NOT BUILDING AIR PRESSURE. BAD GOVENOR, REPLACED WITH NEW. SYSTEM WORKING OK NOW. J.W.

**Parts**

**Quantity**

103385NDRAIN COCK	2
284358GOVERNOR D-2	1
800405PURGE VALVE KIT	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V36822

In Date: 12/02/2010  
Close Date: 01/05/2011

Meter Reading: 266.70

#### Problem?

transmission wont downshift st at 21

#### Task performed:

1. Test drove w/driver; fnd trans not shifting properly sometimes; ck level; ck ok; no computer for trans opn; fnd external solenoids grnd ckt loose; rep grnds; test drove; problem better; ck ok.  
2. Fnd L-1 compt air pack brkt wont clamp; rem brkt; mov clamps; reinstalled; ck opn - ck ok. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V36841

In Date: 12/03/2010  
Close Date: 01/06/2011

Meter Reading: 49,324.00

#### Problem?

Lightbar not working

#### Task performed:

Travel to stn; Light bar inop; switch wire burnt; rep wiring. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V36915

In Date: 12/06/2010  
Close Date: 01/06/2011

Meter Reading: 49,324.00

#### Problem?

on call wont start t 21

#### Task performed:

Travel to Stn21; fnd gear shifter not located in neutral \_\_\_\_ position shfiter correctly; veh started ok; travel home. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V37565

In Date: 01/03/2011  
Close Date: 01/11/2011

Meter Reading: 49,613.00

#### Problem?

repair a/c

#### Task performed:

(1) R&R HEADLIGHT SWITCH.  
(2) R&R AIR CYLINDER FOR A/C & CONTROLLER.  
J.W.

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V37327

In Date: 12/21/2010

Meter Reading: 49,624.00

Close Date: 01/12/2011

#### Problem?

A inspection and repairs (from 21)

#### Task performed:

- A-Inspection
- 2. R/R (3) valve stem extension that were leaking; had to adj (1) valve stem ext & tightened (1) valve stem at wgeek tgat was keajubg & top off all ten tires to 120 psi.
- 3. R/R btry; cln term; add term protectors.
- 4. Rem brkn headlight switch; ordered new one & put old one back in til new comes in.
- 5. A/C heater defrost actuator cntrl valve leaking; R/R, reassem dash; parts on backorder.
- 6. Fill wtr tank. j

#### Parts

#### Quantity

440-44 1/8 IN VALVE EXT	2
440-5 VALVE EXT.	3
8956K895TOGGLE HEADLITE SWITCH 681-545-06-22	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	3
EC17592LUG NUT COVER WPB 1-1/2	1
HP-31DBATTERY 950CCA HP-31D	3

#### Workorder: V37795

In Date: 01/19/2011

Meter Reading: 49,796.00

Close Date: 01/20/2011

#### Problem?

A inspection Sta 42

#### Task performed:

- (1) "A" INSPECTION AND ROAD TEST. DONE AT ST 42. J.W.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V38082

In Date: 01/27/2011

Meter Reading: 49,892.80

Close Date: 02/02/2011

#### Problem?

Truck stalls whenin pump gear st at 72

#### Task performed:

- Rep pump shift valve leaking & line air both loose; shaft loose also; tighten up; all operate pump & drive; ok at this time. j

#### Parts

#### Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V38204

In Date: 02/01/2011

Meter Reading: 49,999.00

Close Date: 02/02/2011

#### Problem?

A inspection (from Sta 72)

#### Task performed:

Parts

Quantity

- A-Inspection
- 2. Rep pump panel light ckt grd.
- 3. dia loose cable; trace cable to term cble; has been disconnected & taped at other end.
- 4. Adj tire press. j

NO PARTS USED

#### Workorder: V39716

In Date: 04/06/2011

Meter Reading: 50,066.00

Close Date: 04/13/2011

#### Problem?

LIGHT BAR 10-7, BUT SIDE WHITE LIGHTS WORK... SIREN 10-7.... ALL OTHER WARNING LIGHTS WORK. st at 14

#### Task performed:

Parts

Quantity

- Travel to stn14; rep brkn wire to lite bar/siren shutoff switch for side lights. j

NO PARTS USED

#### Workorder: V40051

In Date: 04/21/2011

Meter Reading: 50,249.00

Close Date: 04/22/2011

#### Problem?

a inspection.

#### Task performed:

Parts

Quantity

- A-Inspection
- Unit btry dead, jump start. j

NO PARTS USED

#### Workorder: V40014

In Date: 04/19/2011

Meter Reading: 50,326.00

Close Date: 05/02/2011

#### Problem?

A inspection

#### Task performed:

Parts

Quantity

- A-Inspection

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V39917

In Date: 04/14/2011      Meter Reading: 50,066.00  
Close Date: 05/10/2011

#### Problem?

Exhaust leak in ehhaust system under cab.(rusted out ) st at 14

#### Task performed:

Rem old pipe & installed band clamp.      j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V41816

In Date: 07/05/2011      Meter Reading: 50,840.90  
Close Date: 07/12/2011

#### Problem?

A inspection.

#### Task performed:

A-Inspection      j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V42343

In Date: 07/27/2011      Meter Reading: 50,840.90  
Close Date: 08/05/2011

#### Problem?

Remove pre-connects. Spare tender

#### Task performed:

hose was removed by training division

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V42729

In Date: 08/10/2011      Meter Reading: 50,978.00  
Close Date: 09/01/2011

#### Problem?

C INSPECTION AND REPAIRS SPARE TENDER

#### Task performed:

perform c service

inspected servere rust on rear of frame rails

#### Parts

Parts	Quantity
15W40BSYN OIL BULK QTS	36
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHTLINER TANKER TRUCK

**Workorder:** V43462

**In Date:** 09/06/2011

**Meter Reading:** 49,055.00

**Close Date:** 12/05/2011

**Problem?**

REPAIR FRAME RAILS TOTAL TRUCK

**Task performed:**

Parts

Quantity

REPAIR FRAME RAILS TOTAL TRUCK.

NO PARTS USED

**Vendor?:** TOTAL TRUCK PARTS

---





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* **FREIGHTLINER TANKER TRUCK**

**Workorder: V45552**

**In Date:** 12/01/2011

**Close Date:** 12/15/2011

**Meter Reading:** 49,055.00

**Problem?**

C inspection.

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

PUMP LEAKING WATER - FOUND RECENT VALVE COPLER LEAKING # 1&2 DISCHARGE LEAKING, BOTH CROSSLAY LEAKING - REMOVE OLEAL TO REPAIR VALVES, REPORTION VITALIC COPLENS TO ASSEMBLE.

048009000SPEEDCOUNTER PUMP PANEL

1

108-12FBEADED CHAIN W/CONN 12

5

215057VALVE SAFETY 200PSI

1

2960030100PACKING PUMP

1

35103HANGAR EXHAUST

1

5004961NDRAIN VALVE M2

1

579235HANDLE GRAB RAIL

1

6811813495LENS-RED 68-1181349-5

1

91378905 VALVE KIT 2 IN AKRON

1

91398907 VALVE KIT 3 IN AKRON

1

PUMP TANK SHOUT HANDLE BROKEN - REMOVE PIECES, DRILL NEW HOLES AND INSTALL NEW HANDLE - FILL TANK.

FILL TANK ADJUST PACKING - PACKING STILL LEAKING, BLOWING OUT PACKING AND INSTALLING NEW PACKING. PASS VACCUM TEST.

WATER TANK SHORT SHUT OFF LEAKING - SEAL SHORT SHUT OFF PLATE MOUNTING ROD WITH #5200 SEALER AS PER MIKE LEHAN.

REPLACE BROKEN REAR STROBE LIGHT ASSEMBLY.

C-INSPECTION

TACHOMETOR INOP- FOUND LOOSE GAUGE CONNECTION. CORRECT FAULT.

RIGHT SIDE HEAD LIGHT INOP- FOUND LOOSE LIGHT BULB CONNECTION. CORRECT FAULT.

R-1 COMPARTMENT LIGHT 10-7 BULB GOOD, FOUND LOOSE POWER SUPPLY WIRE-CUT AND RECLAMP CONNECTION.

TANK TO PUMP VALVE LEAKING AT VALVE STEM - REMOVE, REBUILD AND REINSTALL. FILL TANK AND CHECK FOR LEAKES.

TIRE INSTALLED WITH VALVE STEMS INBOUND - REMOVE WHEEL COVER, REPOSITION STEMS AND EXTENSION ON ALL 4 OUT BOARD WHEELS AND CHECK PSI.

HOSE REEL LINE AT PUMP TWISTED - REMOVE INSTALL 90 DEGREE PIPE IN SYSTEM.

EXHAUST SUPPORT BROKEN - REMOVE PIECES AND INSTALL NEW SUPPORT BRACKET.

AIR LEAKS - FOUND BAD CONNECTIONS, TWISTED AIR LINES, TANK DUMP VALVE, AIR DRYER VALVE.

DISCHARGE (4) TO INTAKE CAP(2) MISSING - INSTALL NEW CHAINS.



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

POWER STEERING FLUID LOW - CHECK FOR LEAK  
NONE FOUND TOP OFF FLUID LEVEL.

TAILBOARD LIGHT 10-7 - FOUND POWER SUPPLY  
WIRE BROKEN AT BUTT CONNECTOR - REMOVE  
SECTION OF WIRE AND RECONNECT.

RPM PUMP CABLE BROKE - REMOVE, ASSEMBLE  
REPLACEMENT CABLE, REMOVE FROZEN DRIVER,  
INSTALL NEW DRIVER.

DRIVER SEAT MATERIAL LOOSE - SECURE SEAT  
RETAINER.

#### Workorder: V46709

In Date: 01/19/2012      Meter Reading: 2,194.00  
Close Date: 01/30/2012

**Problem?**  
A inspection.

Task performed:	Parts	Quantity
A-INSPECTION	NO PARTS USED	

#### Workorder: V46870

In Date: 01/26/2012      Meter Reading: 2,194.00  
Close Date: 02/27/2012

**Problem?**  
pump flapper recall

Task performed:	Parts	Quantity
PUMP FLAPPER VALVE RECALL - DRAIN ALL WATER FROM TANK PUMP AND COMPLETE SYSTEM - REMOVE AIR DRYER AIR LINES AND ARM COUNTER CABLE FOR ACCESS TO FLAPPER VALVE ASSEMBLY - REMOVE TANK TO PUMP VALVE FLEX HOSE AND REMOVE FLAPPER VALVE ASSEMBLY FROM PUMP - REMOVE EXISTING FLAPPER FROM PUMP HOUSING - GRIND OUT DEBRIE FROM PUMP OPENING SO NEW STYLE FLAPPER WILL SWING FREELY- CLEAN OFF ALL GASKET SURFACES, BOLT HOLES, ETC. - ASSEMBLE AND INSTALL NEW FLAPPER VALVE ASSEMBLY- ON BENCH REBUILD TANK TO PUMP VALVE AND REINSTALL TO TANK AND FLAPPER ASSEMBLY READJUST TANK TO PUMP PULL ROD - INSTALL NEW ANOIDE AND PLATE ASSEMBLY - REINSTALL ALL REMOVE COMPONENTS.	038-1862-50-0FLAPPER KIT	1
	0460060000GASKET	2
	115-1320-01-0FLANGE	1
	402169HOSE AND FITTING ASSY	1
	529008000529-0080-10-0 1 1/4 ANODE KIT	1
	91398907 VALVE KIT 3 IN AKRON	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V43370

In Date: 09/01/2011

Meter Reading: 49,055.00

Close Date: 03/09/2012

#### Problem?

MAKE REPAIRS FOUND ON P.M.

#### Task performed:

Parts

Quantity

NO PARTS USED

#### Workorder: V49957

In Date: 06/07/2012

Meter Reading: 3,104.00

Close Date: 06/08/2012

#### Problem?

left rear blinker not working. T21 SPARE

#### Task performed:

Parts

Quantity

CHECKED FOR POWER AT LIGHT NONE, TRACED WIRES FOUND OPEN IN HARNESS NEXT TO T/CASE REPAIRED OPEN AND TESTED OK.

NO PARTS USED

#### Workorder: V50020

In Date: 06/10/2012

Meter Reading: 3,197.70

Close Date: 07/03/2012

#### Problem?

hose reel will not feed out, and electrical switch detached...also drivers compartment inside latch broken . T21

#### Task performed:

Parts

Quantity

1. CHECKED HOSE REEL 90 DEGREE SWIVEL SIEZED. GO TO SHOP FOR PARTS.
2. REPAIRED LATCH TEMPORILARY UNTIL NEW LATCH CAN BE INSTALLED.
3. REPLACED HOSE REEL SWIVEL AND SOLENOID FOR MOTOR.

2407124071 SOLENOID

1

BD5501516160BD55015-1616-01 SWIVEL

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

**Workorder:** V50827

**In Date:** 07/13/2012

**Meter Reading:** 52,554.10

**Close Date:** 07/13/2012

**Problem?**

Power steering hose line broken T21

**Task performed:**

TRAVEL TO 1000 SR 7 IN PARKING LOT. COVERED OIL ON GROUND AND CONTACTED SUPERVISORS DUE TO STAINING ON PAVEMENT. REMOVED LEKING HOSES AND WENT TO MAKO HOSE TO HAVE REPLACEMENTS MADE INSTALLED HOSES AND FILLED WITH OIL. FOLLOWED TRUCK BACK TO STATION TO SECURE HOSES AND CHECK FLUID LEVELS OK.

**Parts**

**Quantity**

412867HOSE & FITTING ASSY

1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V51120**

**In Date:** 07/25/2012

**Meter Reading:** 52,627.20

**Close Date:** 08/06/2012

**Problem?**

B INSPECTION SPARE TENDER TRANSFER CAE 10-7

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

1. VEHICLE DOES NOT MOVE - TOW VEHICLE INTO SERVICE BAY FROM PARKING LOT.
2. DIAGNOSIS OF NO ROAD GEAR AT PUMP TRANS START DISASSEMBLY.
3. DISASSEMBLE OF PUMP TRANS INSPECTION ALL COMPONENTS MAKE PARTS LIST AND ORDER PARTS.
4. ASSIST KEN WITH DIAGNOSIS OF T-CASE PROBLEM, DISASSEMBLY OF T-CASE AND PARTS LIST TO ORDER ASSIST WITH REASSEMBLY OF SUB PARTS.
5. B-INSPECTION - WITHOUT BEING ABLE TO START OR DRIVE VEHICLE.
6. R&R L/R 2ND AXLE INNER VALVE STEM EXT AND INFLATE TIRE.
7. R&R HUB CAP R&R RETAINER LENS, CAP AND GASKET ON R/F STEMCO HUB RESERVOIR. R&R GASKETS AND UNS AND CAP. REFILL RESERVOIR WASH WHEEL AND HUB CAP.
8. R&R AIR FILTER.
9. COMPART. L-2 HARD TO OPEN AND CLOSE. FOUND LEVER S/S GUARD INTERFERING WITH HINGE. DRILL AND TAP GUARD TO SECURE LEVER
10. REMOVE COMPT. L-1 STRIKER PLATE - BROKEN - NO PART IN STOCK.
11. REDUCE LEVEL OF FLUID IN P/S RESERVOIR TO CORRECT LEVEL.
12. ADJ. FAN BELTS.
13. START REBUILD (PUMP TRANSMISSION).
14. REBUILD PUMP TRANSMISSION.
15. FINISH PUMP TRANS REBUILD REASSEMBLE DRIVELINE ROAD TEST VEHICLE AND TEST PUMP SHIFT OPERATION.
16. FILL 3000 GALL WATER TANK.
17. DIAGNOSE WHY RELIEF VALVE DOESN'T WORK R&R CONTROL SCREEN FITTING R&R RELIEF VALVE ASSY CLEAN CASE AND COVER AND REPLACE ALL GASKETS AND SEALS.
18. RELIEF VALVE REPAIRS AND TESTING CONTINUED.
19. RELIEF VALVE LIGHT ASSY NOT WORKING - DIAGNOSE AND REPAIR AND ADJ GAP BETWEEN SWITCH AND VALVE.
20. R&R HEAT CHECK R&R EXHAUST BAND CLAMP.
21. R/R AXLE 32 BRAKES FULL OF OIL. JACK VEH. REMOVE WHEELS DRUM HUB AND AXLE. DISASSEMBLE BRAKES START WASHING ALL PARTS OF OIL.
22. CONTINUE CLEANING ALL PARTS. REASSEMBLE ALL BRAKES, HUB, DRUM AND AXLE AND WHEELS, ADJ. BRAKES - ROAD TEST VEHICLE.
23. FABRICATE COMPT L-1 DOOR LATCH STRIKER PLATE - NO STOCK - PART ON ORDER.
24. REFILL 3000 GAL WATER TANK AFTER BRAKE

007-0080-03-0VPS CYLINDER	1
0100080010STRAINER	1
018-1816-02-0SCREW SHIFT FORK	1
028-0041-50-0SHIFT FORK REPLACEMENT KIT	1
037-1341-50-0VPS SHIFT KIT 2 PIECE	2
038-0090-50VALVE RELIEF-HALE	1
040-1149-00RING-COVER SEAL	2
044-0210-01-0VPS COVER HALE	1
046-5130-00GASKET GEAR BOX COVER (HALE)	1
073-0010-00PISTON RELIEF VALVE HALE	1
0772750010SNAP RING	1
1012910235619A STRIKER PLATE	1
142-0160-00SLINGER	1
1891BULB	1
20S-500EXHAUST CLAMP 33225 5 IN	1
250-0214-06250-0214-06 BEARING	3
2508010000BEARING NEEDLE ROLLER	1
380003ASEAL	1
401581GASKET AXLE FL80 R002435	1
537-1750-00DRIVE SHAFT GEAR BOX	1
0465060000GASKET	2
250-0214-00250-0214-00 BEARING	1
2962540000SEAL SAME AS 29867 C/R	2
340-4009CAP OIL HUB	1
440-5 VALVE EXT.	1
538-1400-00QG VALVE	1
546-0200-50QD REL.VALVE KIT	1
CA3990AIR FILTER 46883	1
R90PFILTER FUEL 33231	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
XK5234515QBRAKE SHOES 4515Q	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

JOB.  
25. ASSIST KEN WITH REPAIRS.

#### Workorder: V50824

In Date: 07/12/2012      Meter Reading: 52,554.10  
Close Date: 08/07/2012

#### Problem?

replace windshield washer blades. Light out over gated wye on officer side of truck. Sta 21

#### Task performed:

TRAVEL TO 21 REPLACED WIPER BLADES AND REPAIRED PUMP PANEL LIGHT.

Parts	Quantity
54-15 31-15 WIPER BLADE	2

#### Workorder: V51840

In Date: 08/23/2012      Meter Reading: 3,760.00  
Close Date: 09/20/2012

#### Problem?

A INSPECTION

#### Task performed:

1. A INSP
2. R&R L/F LOW BEAM HEADLIGHTS.

Parts	Quantity
2070-105-106ZICO PIVOT	1
H4656USE CV TYPE HEAD LIGHT	1

#### Workorder: V52483

In Date: 09/18/2012      Meter Reading:  
Close Date: 09/24/2012

#### Problem?

NAIL IN LEFT REAR OUTSIDE TIRE , VERY EDGE OF TREAD, INSIDE EDGE..... ALSO , NAIL IN RIGHT REAR INSIDE TIRE, OUTSIDE EDGE..... PSI GAUGE ON DASH ONLY GETS TO APPROX. 100 PSI ????? T14

#### Task performed:

TRVL TO 14 CHKD GAUGES CHK OK.

Parts	Quantity
NO PARTS USED	





10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V52159**

In Date: 09/05/2012

Meter Reading:

Close Date: 10/18/2012

**Problem?**

the strainer is missing a bolt. and the water dump tray hell apart. ST AT 72

**Task performed:**

1. TRVL TO ST 72 R&R STARINER BOLTS GUY AT TRAINING WELDING UP TRAY FOR DUMP.
2. REPLACE STRAPS ON HAND HOSE MOUNT AND REPLACE HOSE BED SWAP BED SNAP DRILL NEW HOLE.
3. CHK TANK FOR LEAKS TOP OF TANK FULL OF WATER RUNNING DOWN REAR.

Parts

Quantity

SAHSVS2510STRAP

3

**Workorder: V53649**

In Date: 11/09/2012

Meter Reading: 53,467.50

Close Date: 11/13/2012

**Problem?**

A INSPECTION

**Task performed:**

- A INSP. L-S LT BAR STROBE INOP/ CONNECTOR CORRODED/ REPAIRED CONNECTOR AND INSTALLED NEW BULB IN DASH.

Parts

Quantity

NO PARTS USED

**Workorder: V55464**

In Date: 01/31/2013

Meter Reading:

Close Date: 02/04/2013

**Problem?**

DRIVERS SEAT IS BOTTOMED OUT. WILL NOT MOVE UP. (AIR CONTROLLED) HAVE TO DRIVE WITH ROLL OF HOSE ON SEAT IF YOUR SHORT..... t14

**Task performed:**

1. TRAVEL TO 14 RPAIRED BROKEN AIR LINE TO DRIVERS SEAT REMOUNT DEBRIS UNDER SEAT TO KEEP FROM BREAKING HOSE AGAIN.
2. ADJUSTED PUMP PACKING TO STOP WATER LEAK.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

\* FREIGHLINER TANKER TRUCK

**Workorder: V55675**

In Date: 02/10/2013      Meter Reading:  
Close Date: 02/14/2013

**Problem?**  
right rear and front turn signals 10-7 T14

<b>Task performed:</b>	<u>Parts</u>	<u>Quantity</u>
CHECKED SIGNAL LIGHTS NO PROBLEM FOUND.	NO PARTS USED	

**Workorder: V55810**

In Date: 02/17/2013      Meter Reading: 54,141.00  
Close Date: 02/21/2013

**Problem?**  
air leak in the transfer case for the fire pump/ it does leaks the only on tank on the air system in about 30 minutes-90minutes Spar tender @ ST-14

<b>Task performed:</b>	<u>Parts</u>	<u>Quantity</u>
TRAVEL TO 14 REPLACED SEALS IN VPS SHIFTER ON T-CASE.	5460370530VPS SHIFT KIT 546-0370-53-0	1

**Workorder: V56219**

In Date: 03/07/2013      Meter Reading: 54,359.00  
Close Date: 03/11/2013

**Problem?**  
A inspection

<b>Task performed:</b>	<u>Parts</u>	<u>Quantity</u>
1. PERFORMED "A" SERVICE. 2. PULLED 8 TIRES OUT OF BUILDING #3 FOR TIRE GUY TO REPLACE ALL 8 TIRES. (REARS) (WORN)	NO PARTS USED	

**Workorder: V56226**

In Date: 03/07/2013      Meter Reading: 54,359.00  
Close Date: 03/11/2013

**Problem?**  
replace 8 rear tires, using our stock

<b>Task performed:</b>	<u>Parts</u>	<u>Quantity</u>
REPLACE 8 REAR TIRES, USING OUR STOCK.	292850BRIDGESTONE 12R22.5 TIRE	8

**Vendor?:** BOULEVARD TIRE CENTE



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

\* FREIGHLINER TANKER TRUCK

**Workorder: V57703**

In Date: 05/13/2013      Meter Reading: 5,865.50  
 Close Date: 05/20/2013

**Problem?**  
 not able to go over 45mph and tach intermittent

Task performed:	Parts	Quantity
1. OIL LEVEL CONNECT AND CLEAN NO BURNT SMELL.	0100080010STRAINER	1
2. RPM GUAGE INTERMITT OPERATION- DIAGNOSE AND TRACE SYSTEM.	042002000SPRING RELIEF VALVE HALE	1
3. PUMP PRESSURE SOLVE VALVE INOP - DRAIN PUMP- REMOVE VALVE, REBUILD VALVE INSTALL VALVE. OPERATE PUMP AND VALVE TO MANU SPECS.	546-0200-50QD REL.VALVE KIT	1
4. ASSIST MAC WITH DIAGNOSE AND ROAD TEST.		

**Workorder: V57842**

In Date: 05/20/2013      Meter Reading: 5,997.00  
 Close Date: 05/20/2013

**Problem?**  
 will not start, at sta-41, spare tender-42

Task performed:	Parts	Quantity
1. wash up, close up shop, travel to sta-41 check out spare tender for no start, test batterys, ok. check wiring, found cables loose on battery switch, tighten all cables on bat. switch, starts ok	NO PARTS USED	

**Workorder: V58151**

In Date: 06/03/2013      Meter Reading: 5,997.00  
 Close Date: 06/03/2013

**Problem?**  
 taillight out

Task performed:	Parts	Quantity
CHECKED LEFT BRAKE LIGHT INOP. FOUND NO VOLTAGE AT LIGHT ALSO LIGHT ASSEMBLED WAS RUSTED. REPAIRED CORRODED CONNECTIONS UNDER BODY. FINALLY TRACED PROBLEM TO FAULTY PLUG CONNECTION AT TURN SIGNAL SWITCH. CLOKED SWITCH ASSEMBLY. SECURED PLUG. CLEANED RUST FROM LIGHT ASSEMBLY AND REASSEMBLED.	NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V58595**

In Date: 06/21/2013      Meter Reading:  
Close Date: 06/21/2013

**Problem?**  
Need 2 2 2/1/2 cap for discharges on this unit !!!!! T14

Task performed:	<u>Parts</u>	<u>Quantity</u>
forwarded to Wayne	NO PARTS USED	

**Workorder: V58627**

In Date: 06/23/2013      Meter Reading: 55,333.00  
Close Date: 06/25/2013

**Problem?**  
alternator belt needs to be tighten..... acceleration the volt meter goes to 10 volts/amp meter goes to zero..... ilde speed 14 volts/5 amps T14

Task performed:	<u>Parts</u>	<u>Quantity</u>
ADJUSTED BELTS.	NO PARTS USED	

**Workorder: V58625**

In Date: 06/23/2013      Meter Reading: 55,333.00  
Close Date: 07/03/2013

**Problem?**  
Hose tarp needs to be secured to the hose bed since the snaps are broken!!! T 14

Task performed:	<u>Parts</u>	<u>Quantity</u>
REPAIRS WILL BE MADE AT SHOP.	NO PARTS USED	

**Workorder: V58691**

In Date: 06/26/2013      Meter Reading: 55,377.60  
Close Date: 07/03/2013

**Problem?**  
DRIVERS SEAT AIR LEAK. SEAT LEAKS DOWN WHILE DRIVING t14

Task performed:	<u>Parts</u>	<u>Quantity</u>
SECURED FITTING ON SEAT.	NO PARTS USED	



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHLINER TANKER TRUCK**

**Workorder: V57062**

**In Date:** 04/15/2013

**Meter Reading:** 54,865.50

**Close Date:** 07/08/2013

**Problem?**

B inspection Spare Tanker

**Task performed:**

1. B INSP
2. ELECTRICAL WIRE HARNESS HANGING ALONG UNDER CARRAGE- REMOUNT AND RESECURE.
3. FUEL LINE RUBBING ON EXHAUST PIPE SHEILD- INSTALL RUBBER SLEVE OVER FLUEL LINE AND SECURE AWAY FROM EXHAUST SYSTEM.
4. RIGHT AND LEFT TURN SIGNAL FRONT SIGNAL AND LEFT REAR, 4-WAY SIGNAL INOP- FOUND FRONT TURN BULBS BLOWN REPLACE BULBS, 4-WAY SIGNAL INOP FOUND TURN CONTROL DEFECTIVE, REMOVE AND MODIFY MOUNT FUR NEW TURN SIGNAL CONTROL INSTALL ALL FAULTS CORRECTED.
5. REPLACED GUAGES FOR BAT 3 TESTING.
6. INTERMITTING THROTTLE IMAGE HIGH TO LOW NPM- DIAGNOSE FAULT .
7. HOSE BED COVER SNAPS AND TWIST LOCK DAMAGE OR MISSING.
8. L-1 COMP COMP DOOR SEAL DAMAGE- REMOVE DAMAGE DOOR SEAL CLEAN SURFACE AND INSTALLED NEW DOOR SEAL.
9. Q & A.
10. R-2 COMP LIGHT- REMOVE BLOWN BULB- CLEAN SOCKET AND INSTALL 2 BULBS.

**Parts**

**Quantity**

1156BULB	2
436846HOSE & FITTINGS	1
6805450124SWITCH TURN SIGNAL	1
92541677TEST PRESSURE GAUGE	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
WIL-131973TPS SENSOR	1

**Workorder: V59141**

**In Date:** 07/16/2013

**Meter Reading:** 55,437.70

**Close Date:** 07/19/2013

**Problem?**

repair flat

**Task performed:**

REPAIR FLAT.

**Parts**

**Quantity**

NO PARTS USED

**Vendor?:** BOULEVARD TIRE CENTE



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

**Workorder: V59407**

In Date: 07/29/2013

Meter Reading:

Close Date: 10/10/2013

**Problem?**

Right grill strobe lens mount broken. Unit at station 21.

**Task performed:**

REPLACED ON WO 60758

**Parts**

NO PARTS USED

**Quantity**

**Workorder: V59615**

In Date: 08/06/2013

Meter Reading:

Close Date: 10/10/2013

**Problem?**

Discharges #1&2and front pumper line leak air. #4 Discharge will not open

**Task performed:**

1. REBUILD DISCHARGES #1, 2 AND 4 TIME SPENT TRYING TO FIND 6 GOOD LIFTS TO WORK.
2. REBUILD BUMPER VALVE. RE-INSTALL PUMP PANEL ACCESS. FILL WATER TANK RETURN BORROWED LIFTS CLEAN WATER ON FLOOR.

**Parts**

91388906 VALVE KIT 2.5 IN AKRON

91398907 VALVE KIT 3 IN AKRON

**Quantity**

3

1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V60758**

**In Date:** 09/24/2013

**Meter Reading:** 1,838.20

**Close Date:** 11/24/2013

**Problem?**

A INSPECTION LENS MISSING ON EME LT TACHOMETER 10- 7 PART IN PARTS ROOM

**Task performed:**

1. A INSP, FILL WASHER FLUID AIR TIRES.
2. REPAIR CONTEST FOR L FRT MARKER LIGHT.
3. R FRT STROBE LENS FIXTURE BROKEN REMOVE BROKEN PIECE AND INSTALL LONGER, THICKER SCREW TO SECURE LENS.
4. RIGHT PUMP PANEL LIGHT INOP-FOUND BAD GROUNDED. CLEAN GROUNDING SURFACES.
5. REMOVE ACCREDITED DECALS, CLEAN BODY OF GLUE.
6. UNCLOG A/C AND FRESH AIR PLENUMS REMOVE HOSES AND BLOW OUT DRAINS RE-INSTALL HOSES
7. DOOR OPEM WARNING INOP. REMOVED UPPER PANEL AND CHECKED FOR POWER (NONE). TRACED WIRES FOUND BAD SPLICE. REPAIRE SPLICE TEST OK.
8. LEFT HOSE REAL BOTTLES INOP. REPLACED BUTTON HOSE REAL FROZEN DIAGNOSE PROBLEM- FOUND RUSTED CHAIN AND HOSE ROLLED ON REEL INCORRECTLY. LUBRICATED AND REROLLED HOSE ON REEL TEST OK.
9. R CONVEX MIRROR CRACKED. REPLACED MIRROR ADJ AND CLEAN GLASS.
10. INSTALL PLASTIC PLACKARD FRAMES.
11. REPLACED TACH SET DIP SWITCHES. REPLACED PIGTAIL TEST OK.

**Parts**

**Quantity**

923182-2151 SWITCH MOMENTARY 24-372	1
980-412173 MIRROR 8 IN	1
A22-38915-000TACH	1
L PLACARDLARGE SIDE PLACARD	2
S PLACARDFRONT AND BACK PLACARD	2

**Workorder: V63586**

**In Date:** 01/21/2014

**Meter Reading:** 7,032.50

**Close Date:** 01/22/2014

**Problem?**

REPLACE FRONT TIRES T 21

**Task performed:**

REPLACE FRONT TIRES T-21.

**Parts**

**Quantity**

NO PARTS USED

**Vendor?:** BOULEVARD TIRE CENTE



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

**\* FREIGHTLINER TANKER TRUCK**

**Workorder: V63633**

In Date: 01/23/2014

Meter Reading: 7,078.50

Close Date: 01/23/2014

**Problem?**

air leak

**Task performed:**

DRIVER COMPLAINT AIR LEAK REPLACED SWITCH UNDER DASH ABOVE BRAKE PEDAL.

Parts

Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR 1

**Workorder: V63409**

In Date: 01/15/2014

Meter Reading:

Close Date: 02/11/2014

**Problem?**

Spare Tender at station 21. All emergency lights attached to the cab not working including the lightbar, only the rear beacons and rear side body strobes working. Major air leak behind the dash brake release area.

**Task performed:**

1. TRAVEL TO 21 DRIVER COMPLAINT ALL LEAK IN CAB REPAIRED LEAKING AIR FITTING.
2. DRIVER COMPLAINT NO STROBES ON CAB OR BODY REPAIRED LOOSE CONNECTION ON STROBE PACK FOR BODY STROBE OK.
3. DRIVER COMPLAINT LIGHT BAC INOP. CHECKED FOR POWER AT SWITCH AND RELAYBASED ALL GOOD OPENED UP LIGHT BAC FOUND POWER GOING TO ALL STROBE BOXES, NO STROBES REPLACED STROBE PACKS. STILL NO LIGHTS FOUND FAULTY CONNECTION AT MAIN BOARD IN LIGHT BAR TRIED TO REPAIR BOARD NO LUCK, ORDER PARTS.
4. INSTALLED AND REWIRED NEW BOARD IN LIGHT BAR TESTED OK.

Parts

Quantity

01-0269289-00AIO BOARD 1  
 9M4SPOWER SUPPLY 9M 2  
 SST308QUICK CONNECTOR 50AMP USED ON FLOOR SC 1

**Workorder: V64552**

In Date: 02/26/2014

Meter Reading:

Close Date: 03/10/2014

**Problem?**

Tender 72 spare's vent saw running rich and stalls when powered up to operating speed

**Task performed:**

VENT SAW NOT RUNNING PROPERLY STALE FUEL, REPAIRED FUEL TESTED OK.

Parts

Quantity

NO PARTS USED





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* **FREIGHLINER TANKER TRUCK**

### Workorder: V65115

In Date: 03/22/2014

Meter Reading:

Close Date: 04/01/2014

#### Problem?

Left rear turn signal out and strobe lights on hood not working T72

#### Task performed:

Parts

Quantity

TRAVEL TO 72 DRIVER COMPLAINT LIGHTS OUT  
CHECKED ALL LIGHTS OK.

NO PARTS USED

### Workorder: V66038

In Date: 04/28/2014

Meter Reading: 56,571.60

Close Date: 04/28/2014

#### Problem?

water leak, T-42

#### Task performed:

Parts

Quantity

1. truck was delivered to sta-42 to swap out, water tank was empty, crew filled tank, water started leaking by pump, check for leak found leak at tank to pump hose, empty tank, found clamp loose tighten clamp, refill water tank

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V64666**

**In Date:** 03/03/2014

**Meter Reading:** 56,571.60

**Close Date:** 04/29/2014

**Problem?**

B inspection Spare Tender

**Task performed:**

1. B INSP.
2. REPAIR BULB SOCKET ON RIGHT SIDE PUMP PANEL LIGHT.
3. BATTERIES FAILED BATT LOAD TEST- REPLACED BATT (NOTE BEHIND CAB STEP NO SLIDE TRAY REPAIR 4 ACCERSORY WIRE END THAT CONNECT TO BATT TERMINAL ENDS AND LATCH FOR BATT COVER.
4. SERV AIR DRYER.
5. OIL LEAK UNDER WATER PUMP AREA- FOUND OIL LINE ABOVE WATER PUMP SEEPING-TIGHTEN FITTING AND WASH OFF OIL RESIDUE.
6. OIL LEAK FROM P/S STEERING PUMP FILL HOSE-TIGHTEN CLAMPS- NG HOSE TO HARD AND BRITTLE- REMOVE HOSE AND SEND TO MAKO AND HAVE HOSE MADE UP- REPLACE.
7. SERV P/STEERING WHILE SYSTEM WAS DRAINED FOR HOSE REPLACEMENT REMOVE RESEVOIR COVER AND FILTER ASSEMBLE NOTE COVER WAS BENT SO SEAL WAS NOT SEALING STRAIGHTNED COVER TO SEAL FILL AND RECHECK FOR LEAKS.
8. WATER TANK HAS SLIDE FOWARD DAMAGING TANK FILL HOSES AND PIPING- FIGURE AWAY TO MOVE TANK BACK PRYING WITH BARS (NG) WITH TANK EMPTY TAY RUNNING IN REVERSE THAN HARD BRAKE- ALMOST LOST ALL HOSE OUT OF BED- PULL ALL HOSE BACK INTO BED AND MAKE UP A DAM TO GO ACROSS BACK SIDE OF BED TO HOLD HOSE IN-FILL TANK HALF WAY TO INCREASE ENERGY IN TANK- TAY THE REVERSE MOVE AGAIN- THIS TIME TANK MOVED BACK TO ORIGINAL POSITION. MAKE UP SOME KIND OF STOP BLOCKS TO HOLD TANK IN POSITION- GO TO MAKO HOSE AND FIGURE NRE PLUMBING FOR TANK FILL/REC ORDER PARTS.
9. AIR LEAKS CHRCK OUT AND SPRAY ALL CONNECTIONS- FOUND SEVERAL FITTINGS SEEPING AIR REPLACE ALL BAD FITTINGS.
10. DRIVRES SEAT DISMANTLE DRIVERS SEAT AND INSTALL NEW AIR BAG REPLACE AIR LINES NOTE NECESSARY TO TAKE A STANDARD AIR CONTROL VALVE AND MODIFY TO FIT MOUNTNG BRACKET (ORIGINAL IS MADE FOR THIS SET BY MANUFACTURE).

Parts	Quantity
032110401150 VALVE AIR SEAT	1
0772092772142 TRUNNION HAND	1
103385NDRAIN COCK	4
15W40BSYN OIL BULK QTS	10
466217HOSE & FITTING	1
91388906 VALVE KIT 2.5 IN AKRON	1
HP-31DBATTERY 950CCA HP-31D	3
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
PH7405 51971 OIL FILTER WIX	2
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	2
SA9671AIR BAG DURAFORM SEAT	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
FG-Q59278P/S GASKET	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
465554HOSE & FITTINGS	1
466116HOSE & FITTING ASSY	1



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

### Workorder: V66138

In Date: 05/01/2014

Meter Reading: 56,571.60

Close Date: 05/01/2014

#### Problem?

L-1 compt. door inop, T-42

#### Task performed:

1. repair door latch

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V66198

In Date: 05/03/2014

Meter Reading:

Close Date: 05/14/2014

#### Problem?

tail lights dont work, signals, emergency flashers work, just no running lights. T42

#### Task performed:

TRACED OUT PROBLEM FOUND WIRE SHORTED  
OUT IN TAIL LIGHT REPAIRED AND TESTED.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V66814

In Date: 05/28/2014

Meter Reading: 56,571.60

Close Date: 06/17/2014

#### Problem?

A inspection

#### Task performed:

A-INSP AND WIPERS AND ADJUST HORNS.

#### Parts

54-15 31-15 WIPER BLADE

#### Quantity

2

### Workorder: V67102

In Date: 06/10/2014

Meter Reading:

Close Date: 06/17/2014

#### Problem?

Drivers side first compartment door latch broken, door will stay closed but latch falls apart if opened @21

#### Task performed:

1. TOOK PIC-5 PART NOT ON TRUCK ORDER.  
2. REPLACED DOOR LATCH.

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

**Workorder: V67221**

**In Date:** 06/15/2014

**Meter Reading:**

**Close Date:** 06/18/2014

**Problem?**

both rear emergency beacon lights 10-7 on spare tender, T21

**Task performed:**

CHECKED LEAKS ON FENDER ALL OK.

Parts

NO PARTS USED

Quantity



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

**Workorder: V67288**

**In Date:** 06/17/2014

**Meter Reading:** 8,632.00

**Close Date:** 06/23/2014

**Problem?**

A inspection Spare Tanker

**Task performed:**

1. A INSP AIR TIRES TO PROPER PSI. ADD COOLANT.
2. LEFT LOW BEAM BAD. REPLACED LOW BEAM BULB. REMOVE RUSTED FROZEN SCREWS FROM BEZEL AND REPLACED WITH STAINLESS STEEL.
3. REAR TAIL BAORD STEP LIGHT OUT REPLACED BULB CLEAN AND LUBRICATE SOCET BEND SOCKET FOR TIGHT FIT. REPLACE MISSING SCREW.
4. DIAGNOSE NO EMERGENCY LIGHTS. REMOVE LEFT SIDE KICK PLATE. FOUND BURNT WIRE ON RELAY. REPLACED WIRE END TEST OK.
5. RELAY MOUNTING LOOSE AND HANGING DOWN REPOSITION RELAY AND SERVICE.
6. NO COMPT LIGHTS- FOUND WIRE CONNECTOR FOR TIGHTER FIT AND INSTALL ON RELAY TEST OK
7. DOME LIGHT INOP- FOUND BULB MISSING. DO NOT CARY CORRECT NO. FOR BULB. INSTALLED SIMILAR STYEL BULB.
8. #4 AND #1 DISCHARGE READ PUMP PRESSURE WHEN CLOSED. STRAIGHTEN BENT ACTUATING ROD ON #4. ADD #1 VALVE ROD. PERFORM DRY VAC TEST FAILED. ADJ TANK FILL VALVE. ADJ PUMP PACKING. REBUILD #1, TANK FILL #3 AND #2 PRECONNECT. REMOVE TANK FILL VALVE FLANGE AND RESEL THREADS. PERFORM DRY VAC TEST OK FILL WATER TANK.
9. AIR HORNS SOUND QUALITY BAD. ADJ AIR HORNS.
10. CROSSLAY COVER INSTALL FROM ROB. REPAIR BROKEN AND MISSING SNAPS AND INSTALL COVEF
11. CHECK CODES ON CHECK ENGINE LIGHT BEING ON FOUND J1708 DATA LINK ERROR. CODE DISAPPEARED WHEN CLICKING ON TROUBLE SHOOTING MENUUE.

**Parts**

**Quantity**

91378905 VALVE KIT 2 IN AKRON	1
91388906 VALVE KIT 2.5 IN AKRON	2
H4656USE CV TYPE HEAD LIGHT	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V60038

In Date: 01/01/1900  
Close Date: 07/16/2014

Meter Reading: 1,838.20

#### Problem?

SPARE TENDER-DISCHARGE #1 LEAKS AIR-DISCHARGE #2(BUMPER LINE) LEAKS AIR-DISCHARGE #2 WILL NOT CLOSE ALL THE WAY-DICHARGE #4 WILL NOT OPEN.

#### Task performed:

repairs done on ticket v59615.

Parts

Quantity

NO PARTS USED

#### Workorder: V67106

In Date: 06/10/2014  
Close Date: 07/16/2014

Meter Reading:

#### Problem?

latch broken on compartment D1, T21

#### Task performed:

repairs complete on ticket ser.v76288

Parts

Quantity

NO PARTS USED

#### Workorder: V67223

In Date: 06/15/2014  
Close Date: 07/16/2014

Meter Reading:

#### Problem?

(sorry if 2nd request for same thing) it didnt print out here at staion. both rear beacon emergency lights 10-7, T21

#### Task performed:

repairs done at time of ser, at shop v 67288

Parts

Quantity

NO PARTS USED

#### Workorder: V68282

In Date: 07/30/2014  
Close Date: 08/01/2014

Meter Reading: 8,632.00

#### Problem?

Brakes locked @ training

#### Task performed:

Went to H.Q. found all brakes locked on both rear axles. Manually broke 2 wheels free. Removed backing plates on other wheels. Pryed and beat loose. Readjusted rear axle brakes. Test drove, checked ok. Return to shop.

Parts

Quantity

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V69206

In Date: 09/06/2014

Meter Reading: 57,950.00

Close Date: 09/09/2014

#### Problem?

L-rear taillight is out T14

#### Task performed:

Travel to 14. Replaced tail light bulbs.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V69978

In Date: 10/07/2014

Meter Reading: 9,052.00

Close Date: 11/06/2014

#### Problem?

A inspection spare tender

#### Task performed:

- "A" inspection
- Pump relieve valve inop-Drain pump-Remove discharge PSI screen-Screen cloggeed-Install new screen-TPM still not working-Check relieve valve pressure-switch, switch working normal.
- A/C evaporator housing leaking water-Drain line-clean. Remove kick panel-seal joint with silicone.
- Left rear back up light inop.- assembly corroded. Remove new assemby mouting point modified to fit new light assembly-Install.
- Brake light inop-Assembly rusty and corroded-New assembly had to modified left and right side to fit new brake light assembly-install.

#### Parts

0100080010STRAINER 2  
 60R00XRRBRAKE/TAILLIGHT LED 2  
 644-2601WARNING LIGHT 2010-0300-30 1  
 6EFLANGE600 CHROME FLANGE 2

#### Quantity

#### Workorder: V70849

In Date: 11/12/2014

Meter Reading: 9,392.70

Close Date: 11/26/2014

#### Problem?

screws on door latch are stripped and latch has fallen off. the latch is inside the compartment on the right side. bungey cord holding door shut.

#### Task performed:

1 Driver's access hole in door skin thru bolted latch.

#### Parts

NO PARTS USED

#### Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHLINER TANKER TRUCK

#### Workorder: V70858

In Date: 11/12/2014

Meter Reading: 9,392.70

Close Date: 11/26/2014

#### Problem?

Rear tail lights not working, center rear marker light out. Will be sending tanker 21 back to station today 11/13/14

#### Task performed:

1. Removed access panels in rear compartments and rewired tail lights on both sides.

#### Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

#### Quantity

1

#### Workorder: V71708

In Date: 12/17/2014

Meter Reading:

Close Date: 12/18/2014

#### Problem?

yellow check engine light is on . checked the fluids ok

#### Task performed:

Travel to 14, checked codes found core 53 for non volatile memory 10-7, called detroit for ecm replacement.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V71661

In Date: 12/15/2014

Meter Reading: 9,739.00

Close Date: 12/29/2014

#### Problem?

Rear bumper clearance lamp inop. (Red 2-inch round) T14

#### Task performed:

Travel to 14-replaced light. Adjusted fan belts also per driver complaint

#### Parts

45822RED CLEARANCE TRK LITE 30200R

#### Quantity

1

#### Workorder: V71813

In Date: 12/22/2014

Meter Reading:

Close Date: 01/05/2015

#### Problem?

[r] rear spotlight fails to illuminated T14

#### Task performed:

Check rear light out-repair bad ground light.

#### Parts

NO PARTS USED

#### Quantity





10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* FREIGHLINER TANKER TRUCK

### Workorder: V72425

In Date: 01/18/2015

Meter Reading:

Close Date: 01/21/2015

#### Problem?

tender's tank is leaking near the pump and tank area greater than 20 gal's/day T14

#### Task performed:

Parts

Quantity

Travel to ST 14. Replaced rotted out plug in bottom of pump.

NO PARTS USED

### Workorder: V72896

In Date: 02/05/2015

Meter Reading:

Close Date: 02/11/2015

#### Problem?

[L] BUMPER CLEARANCE LIGHT FAILS TO ILLUMINATED.... FIXED BY MECHANIC TODAY/REPLACE LIGHT BULB T14

#### Task performed:

Parts

Quantity

Replaced light in bumper light.

NO PARTS USED



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

K06239

\* **FREIGHLINER TANKER TRUCK**

**Workorder: V73234**

**In Date:** 02/17/2015

**Meter Reading:** 59,273.50

**Close Date:** 05/19/2015

**Problem?**

C inspection spare tanker

**Task performed:**

Parts

Quantity



10/27/2020

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### K06239

### \* FREIGHTLINER TANKER TRUCK

1. C-Inspection.
2. Performed dryer service.
3. Serviced transfer case auto lube.
4. Performed air system leak tests. Found leak at priority valve. Replaced failed valve.
5. Performed pump vacuum and pressure leak tests. Found leak at #4 discharge valve. R&R valve and overhauled. Performed verification tests.
6. Found booster reel seized and not winding. Reel wind motor seized reel hoses swivel binding and reel drum bearings dry. Replaced wind motor, bracket, and lubed chain. Replaced hose swivel. Removed and lubed drum bearings.
7. All compartment door hold-open props failed. Replaced 8 hold-open props.
8. Found A/C belt cracked and splitting. Replaced and adjusted belt.
9. Pump relief valve intermittent inop, very slow to respond. Found valve screen clogged and pump valve seized. Replaced screen. R&I valve and overhauled. Performed verification tests.
10. A/C not blowing cold. Performed diagnostics and leak tests. Found compressor suction line leaking. Replaced suction line and dryer. Charged system to specs.
11. Found pump panel suction and bumper jumper gauges leaking glycerin and tach filled with water. Replaced suction and jump line gauges. Replaced tach, fabricated wiring and programmed.
12. Replaced missing pump cap chains. Replaced missing cap on #2 discharge.
13. Compartment lamps inop. Found fuse blown, short to ground. L1 compartment lamp and circuit fuse.
14. Found upper radiator hoses in poor condition. Fabricated correct hoses to use with pump cooler. Installed hoses and cooler. Removed hood spring assembly to clear hoses.
15. Replaced failed nozzle tri-lock on left rear.
16. Found cab doors out of adjustment and left weather strip torn. Bent door wings for proper door fit. Adjusted strikers. Replaced failed weather strip.
17. Found driver's seat cushion cover loose and falling off. Reinstalled cover and fabricated retention system to hold in place.
18. Found transfer case leak between rear bearing housing and case. Disassembled and removed rear drive shaft. R&I bearing housing and replaced gasket. Serviced transfer case.
19. Prep vehicle for transport to dealer.
20. Tank dump chute leaking and door close clevis rusting through. Removed dump fasteners. Used razor knife and port-a- power to remove 5200 adhesive securing valve to tank.
21. Disassembled dump valve and cleaned off sealer,

0100080010STRAINER	1
038-0090-50VALVE RELIEF-HALE	1
040-2420-00-OORING HALE	2
042002000SPRING RELIEF VALVE HALE	1
046-0080-00-OGASKET HALE	2
046-1570-00-OORING HALE	2
046-5130-00GASKET GEAR BOX COVER (HALE)	1
073-0010-00PISTON RELIEF VALVE HALE	1
077-0620-44RING SPRING RETAINER HALE	1
097-0990-00WASHER	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
108-12FBEADED CHAIN W/CONN 12	6
13745-1-5COOLER SPARE TANKER DETROIT	1
15W40BSYN OIL BULK QTS	40
2/9510PBBELT TANKER 60SERIES 2PB51	1
22-25294-005SEAL DOOR FLD120 A18-64044-000	1
223-485V91-8301 85 PSI CLOSED 67 OPEN PREESURE PF	1
2962540000SEAL SAME AS 29867 C/R	1
333-193GAGE TACHOMETER	1
496564HOSE & FITTINGS	1
496840HOSE & FITTINGS	1
497189HOSE & FITTINGS	1
54-15 31-15 WIPER BLADE	2
54-54054-540 CIRCUIT BREAKER	1
546126000TPM/QG HALE REPAIR KIT	1
716907-0610A DRYER	1
800405PURGE VALVE KIT	1
80350DOME LIGHT	1
91398907 VALVE KIT 3 IN AKRON	1
91553941GAUGE	1
91583953GAUGE COMPOUND LIQUID FILLED	1
9910-1119GEAR CHAIN DRIVE HANNA	1
9923-0008MOUNTING PLATE HANNAY	1
BD5501516160BD55015-1616-01 SWIVEL	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	8
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
P3613HYDRAUL FILTER 51623 WIX	1
P56AN227MOTOR HOSE REEL	1
PH7405 51971 OIL FILTER WIX	4
PR338324070 WIX FILTER WATER	1
QDV-HCHANDLE ASSY	1
R90PFILTER FUEL 33231	1



10/27/2020

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

**K06239**

**\* FREIGHLINER TANKER TRUCK**

adhesive and gaskets. Replaced door clevis and valve gaskets. Filled tank and checked for leaks. Water leaking through valve gaskets. Filled tank and checked for leaks. Water leaking through valve mounting bolts drained tank. Removed mounting bolts and applied sealer behind washers and on threads. Filled tank. Valve is sealed. Fabricated aluminum trim for around chute valve. Mounted chute extension.

22. Replaced transmission cooler due to age. Mounting system on new cooler different than original cooler. Fabricated new mounting system. Filled cooling system and purged air.

23. Fabricated and installed height sticker.

24. Painted fuel cap.

25. Corrected tire pressures. All tires low.

26. Performed Q&A Inspection, unit has transmission trouble.

**Workorder: V71720**

**In Date:** 12/17/2014

**Meter Reading:** 9,739.00

**Close Date:** 06/30/2015

**Problem?**

replace engine ecm

**Task performed:**

Parts

Quantity

NO PARTS USED



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (K06239) 1993 - FERRARA FLD120SD Freighliner Tanker Truck

**K06239**

**CSHOP-2015-1471**

Comments: **LEAKING WATER SPARE TANKER AT 14 PART HERE FOR TANK LID WAS WRITTEN UP FOR ANOTHER POSSIBLE SLIGHT LEAK**

Date Opened: 6-29-2015      Date Finished      7-20-2015      Meter 1 Reading:      10,350

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE APPARATUS  
TANK-RESERVOIR

1      NONSTOCK; FREIGHT CHARGE  
1      TANK; TANK LID 12X12

---

**CSHOP-2015-1878**

Comments: **WATER LEAK NEAT PTO THAT DRIVES PUMP SPARE TANKER @14**

Date Opened: 7-21-2015      Date Finished      7-23-2015      Meter 1 Reading:      10,350

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP

---

**CSHOP-2015-3229**

Comments: **TENDER AT 42 AIR LEAK AND RELIEF VALVE INOP**

Date Opened: 10-5-2015      Date Finished      10-15-2015      Meter 1 Reading:      12,109

**TASKS PERFORMED**

**NO PARTS USED**

FIRE APPARATUS  
AIR SYSTEM

---

**CSHOP-2015-4181**

Date Opened: 11-25-2015      Date Finished      12-8-2015      Meter 1 Reading:      12,618

**TASKS PERFORMED**

**Q      PARTS**

A INSPECTION  
RELIEF VALVE FIRE PUMP  
FIRE APPARATUS  
SPOT LIGHTS  
STROBE LIGHTS

1      BULB; BULB  
1      PUMP; PACKING PUMP  
2      SWITCH; 82-2116 TOGGLE SW ON/OFF  
2      SWITCH; 82-2106 TOGGLE GUARD  
2      NEWPART; REFLECTOR 97 SER  
1      9IP; POWER SUPPLY REPAIRED  
2      9IP; BULB  
2      NEWPART; LENS RED

---

**Asset Work Order History K06239**

**CSHOP-2015-4497**

Comments: **REAR TIRES REPAIR DONE BY BOULEVARD**

Date Opened: 12-15-2015      Date Finished      1-13-2016      Meter 1 Reading:      12,618

**TASKS PERFORMED**

**NO PARTS USED**

REAR TIRES

**VENDOR?**      ELPEX TIRE TIRESOLES

---

**CSHOP-2015-453**

Comments: **A INSPECTION SPARE TENDER**

Date Opened: 5-5-2015      Date Finished      5-29-2015      Meter 1 Reading:      10,349

**TASKS PERFORMED**

**Q      PARTS**

A INSPECTION	1	BULB; BULB
TURN SIGNAL LIGHTS	1	LIGHT; LIGHT ASSY. TURN SIGNAL
INSTRUMENTS-GAUGES-WARNING &	2	BULB; BULB

---

**CSHOP-2016-1027**

Date Opened: 3-3-2016      Date Finished      3-3-2016      Meter 1 Reading:      62,973

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SIREN

**Service Requests:**

03/03/2016      SERVICE REQUEST / 38: SHORTED / REPAIRED CONNECTION TO HEAD

---

**CSHOP-2016-1214**

Comments: **REPLACE LEFT FRONT TIRE**

Date Opened: 3-14-2016      Date Finished      3-14-2016      Meter 1 Reading:      62,973

**TASKS PERFORMED**

**NO PARTS USED**

FRONT TIRES

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2016-2008**

Comments: **CHECK GRILLE, WAS HIT AND BEING HELD ON BY TIE STRAPS**

Date Opened: 4-28-2016      Date Finished      5-3-2016      Meter 1 Reading:      64,543

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
BODY DAMAGE ACCIDENT

---

**Asset Work Order History K06239**

**CSHOP-2016-2019**

Comments: **SPARE TENDER AT ST72**

Date Opened: 4-28-2016

Date Finished

5-3-2016

Meter 1 Reading:

64,543

**TASKS PERFORMED**

**NO PARTS USED**

RELIEF VALVE

**Service Requests:**

04/28/2016

SERVICE REQUEST / 11: BINDS/STICKS / REPAIR  
RELIEF VALVE NOT WORKING

**CSHOP-2016-3129**

Date Opened: 6-29-2016

Date Finished

7-8-2016

Meter 1 Reading:

65,374

**TASKS PERFORMED**

**Q PARTS**

PM SERVICE C

-1 FILTER; FILTER FUEL 33231  
1 FILTER; FILTER FUEL 33231  
1 FILTER; FILTER FUEL 33231  
1 FILTER; HYDRAUL FILTER 51623 WIX  
-1 FILTER; OIL FILTER 51748  
1 FILTER; 24070 WIX FILTER WATER  
1 FILTER; OIL FILTER 51748  
-1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM  
2 FILTER; 51971 OIL FILTER WIX  
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM  
-1 FILTER; 33585XE FUEL FILTER WIX  
1 FILTER; 33585XE FUEL FILTER WIX  
40 FLUID; SYN OIL BULK QTS  
1 FILTER; FUEL FILTER 33120 WIX DELCO TP916

**CSHOP-2016-3311**

Comments: **PM FOLLOW UPS**

Date Opened: 7-8-2016

Date Finished

7-27-2016

Meter 1 Reading:

65,430

**TASKS PERFORMED**

**Q PARTS**

COMPARTMENT LIGHT BODY  
FIRE FIGHTING EQUIPMENT  
FIRE PUMP PLUMBING  
PUMP PANEL  
FIRE PUMP  
WIPER BLADES  
EXHAUST MANIFOLD  
SPOT LIGHTS  
PARK-CLEARANCE LIGHTS  
CHARGING SYSTEM  
DIAGNOSE ELECTRICAL  
KNUCKLE  
SUSPENSION  
RACK AND PINION ASSEMBLY  
GEAR BOX  
AIR SYSTEM

1 NEWPART; STEERING CYLINDER  
1 FLUID; P/S FLUID  
40 BEARING; 109041 BEARING 025 IN 50 PK  
1 9IP; GASKET 2 1/2"  
1 LIGHT; TAG LIGHT 60101  
1 BULB; BULB  
1 9IP; GASKET 2 1/2"  
1 CHAIN; BEADED CHAIN W/CONN 12  
2 WIPER; 31-15 WIPER BLADE  
1 NEWPART; MUFFLER TANKER  
4 CLAMP; EXHAUST CLAMP 33225 5 IN  
1 BULB; BULB  
4 REFLECTOR; B484R REFLECT-RED  
1 LIGHT; MARKER LIGHT  
10 BULB; BULB  
1 PLUG; B2-LM SPARK PLUG

**Asset Work Order History K06239**

**CSHOP-2016-4363**

Comments: **A INSPECTION**

Date Opened: 9-7-2016

Date Finished

10-28-2016

Meter 1 Reading:

16,889

**TASKS PERFORMED**

A INSPECTION  
WIPERS-WASHER  
OIL  
BATTERY  
AUTO-EJECT  
WHEEL STUD  
DOOR  
INSTRUMENTS-GAUGES-WARNING &

**Q PARTS**

---

1 NEWPART; CLAMP  
1 9IP; 370023A SEAL  
1 CHARGER; CHARGER 2000  
1 CHARGER; AUTO EJECT 20 AERO OTL3925  
1 NEWPART; FUSE HOLDER  
1 9IP; COVER, SQUARE, YELLOW  
1 9IP; NUT OUTER L/H R005977L  
1 MEDIC MASTER; HEADLESS STRIKER  
1 9IP; E7895L NUT INNER LEFT  
1 NEWPART; DOOR SEAL  
1 NEWPART; DOOR HINGE  
1 BRACKET; BRACKET WPB  
2 NEWPART; WIPER BLADE 15"  
1 GAUGE; GUAGE

**Service Requests:**

---

09/05/2016 DOOR / 12: BROKEN / REPAIR  
VEHICLE DOORS

---

**CSHOP-2016-4624**

Comments: **UNIT AT 42**

Date Opened: 9-23-2016

Date Finished

2-27-2017

Meter 1 Reading:

67,077

**TASKS PERFORMED**

FIRE PUMP PLUMBING  
FIRE APPARATUS  
SAFTEY-EMERGENCY EQUIPMENT

**Q PARTS**

---

1 5EO; 2.5 FLANGE

**Service Requests:**

---

11/09/2016 SERVICE REQUEST / 18: LEAKING / REPAIR  
T-42 'S FLOAT A PUMP NEEDS SERVICE. STALLS UNDER LOAD. STALLS WHILE FLOWING WATER. (NO PROBLEM STARTING EQUIPMENT)

09/23/2016 BODY / 17: INSUFFICIENT LUBRICANT / INSPECT  
2.5 INTAKE VALVE ON RIGHT SIDE OF PUMP, ALL THE BALL BEARINGS FELL OUT OF THE COUPLER. NOW THE COUPLER SLIDES RITE OFF, COUPLER LAYING IN THE WELL.

11/23/2016 SERVICE REQUEST / 12: BROKEN / REPAIR  
PUMP INTAKE ON PASSENGER SIDE HAS NO THREADS ON IT. NO WAY TO HOOK UP HOSE

---



**Asset Work Order History K06239**

**CSHOP-2016-6**

Comments: **T42 MIRROR MISSING**

Date Opened: 1-4-2016

Date Finished

1-27-2016

Meter 1 Reading:

62,973

**TASKS PERFORMED**

**Q PARTS**

MIRRORS

1 MIRROR; GRO716S MIRROR S/S  
1 MIRROR; 12173 MIRROR 8 IN

**Service Requests:**

01/01/2016 MIRROR / 18: LEAKING / REPAIR  
DRIVERS SIDE MIRROR MISSING

01/04/2016 TIRES / 19: LOOSE / REPAIR  
2 LOOSE LUG NUTS ON DRIVERS SIDE REAR

**CSHOP-2016-944**

Comments: **A INSPECTION ON SPARE TENDER**

Date Opened: 2-29-2016

Date Finished

3-4-2016

Meter 1 Reading:

62,973

**TASKS PERFORMED**

**Q PARTS**

A INSPECTION  
WIPER BLADES  
COOLING SYSTEM  
LIGHTING SYSTEM

2 9IP; NUT OUTER L/H R005977L  
2 WIPER; 31-15 WIPER BLADE  
1 BULB; BULB

**CSHOP-2017-1437**

Date Opened: 3-8-2017

Date Finished

3-8-2017

Meter 1 Reading:

67,178

**TASKS PERFORMED**

**NO PARTS USED**

EQUIPMENT MOUNTING BRACKETS

**CSHOP-2017-2425**

Comments: **USE A FORM**

Date Opened: 4-24-2017

Date Finished

5-19-2017

Meter 1 Reading:

67,652

**TASKS PERFORMED**

**NO PARTS USED**

PM SERVICE B

**Asset Work Order History K06239**

**CSHOP-2017-2426**

Comments: **REPAIRS FROM PM**

Date Opened: 4-24-2017

Date Finished

5-30-2017

Meter 1 Reading:

67,652

**TASKS PERFORMED**

**Q PARTS**

FIRE PUMP	3	9OC; SYN 15W40
OIL	1	9LL; BUMPER GUIDE LENS
PARK-CLEARANCE LIGHTS	2	9IP; BULB
BATTERY	3	1AD; BATTERY 31 SERIES
DIAGNOSE ELECTRICAL	4	2TP; 2TP
REAR HUB	4	NOS; NOS
ALIGNMENT	1	TWD; TIE ROD END
TIRES & WHEELS	1	TWD; TIE ROD END
U-BOLTS	1	NONSTOCK; FREIGHT CHARGE
SUSPENSION	1	5EF; INPUT SHAFT SEAL
TIE ROD ENDS OUTER	4	2TP; BRAKE
STEERING	2	TWD; AIR BRAKE CHAMBER
REAR BRAKE PADS-SHOES	2	2TP; SLACK ADJ
FRONT BRAKE PADS-SHOES	2	TWD; SLACK ADJUSTER KIT
BRAKE CHAMBER	-2	2TP; SLACKADJ
REPAIR FROM PM - DECALS/CLEANLINESS	4	TWD; BRAKE DRUM
AIR SYSTEM	2	2TP; SLACKADJ
	-4	2TP; GASKET
	-1	2TP; 2TP
	2	2TP; 2TP
	4	2TP; GASKET
	2	TWD; AIR BRAKE CHAMBER

**CSHOP-2017-2707**

Date Opened: 5-8-2017

Date Finished

5-8-2017

Meter 1 Reading:

67,178

**TASKS PERFORMED**

**NO PARTS USED**

COMMERCIAL WORK - OUTSIDE AGENCY

**VENDOR?** DAN CALLAGHAN ENTERPRISES

**CSHOP-2017-3239**

Date Opened: 6-2-2017

Date Finished

6-8-2017

Meter 1 Reading:

67,740

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER PUMP	3	9IP; 30WT MOTOR OIL
---	---	---------------------

**Service Requests:**

06/02/2017

SERVICE REQUEST / 15: FOREIGN MATERIAL / EXCHANGE - NEW

THE FLOAT A PUMP SPRAYS OIL FROM THE MUFFLER WHEN ATTEMPTING TO START IT. IT DOES NOT START.

**Asset Work Order History K06239**

**CSHOP-2017-3580**

Date Opened: 6-16-2017      Date Finished      6-22-2017      Meter 1 Reading:      67,879

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
TURN SIGNAL LIGHTS

1      9IP; LIGHT ASSY. TURN SIGNAL

**Service Requests:**

---

06/16/2017      LIGHTS / 12: BROKEN / EXCHANGE - NEW  
PASSENGER SIDE FRONT TURN SIGNAL LIGHT IS BROKEN. THIS IS THE SPARE TENDER FROM THE SHOP. TENDER  
14 SPARE.

---

**CSHOP-2017-4146**

Date Opened: 7-17-2017      Date Finished      8-22-2017      Meter 1 Reading:      69,005

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
BACK UP LIGHTS  
BATTERY  
INSTRUMENTS-GAUGES-WARNING &

**Service Requests:**

---

07/14/2017      SERVICE REQUEST / 11: BINDS/STICKS / REPAIR  
PUMP PRESSURE GAUGE IS STICKING AND FLUCTUATING, RELIEF VALVE LIGHT STAYS ON AND RIGHT REAR BACKUP  
LIGHT IS OUT.

07/31/2017      LIGHTS / 38: SHORTED / REPAIR  
RIGHT BACK UP TAILLIGHT NOT WORKING

---

**CSHOP-2017-4930**

Date Opened: 8-23-2017      Date Finished      10-13-2017      Meter 1 Reading:      69,005

**TASKS PERFORMED**

**NO PARTS USED**

WINDOW REGULATOR

**Service Requests:**

---

08/22/2017      WINDOW / 19: LOOSE /  
THE DRIVER SIDE WINDOW CRANK IS NOT CATCHING TO ROLL UP THE WINDOW. THE WINDOW IS IN THE DOWN  
POSITION.

---

**CSHOP-2017-5244**

Date Opened: 9-7-2017      Date Finished      9-7-2017      Meter 1 Reading:      69,005

**TASKS PERFORMED**

**Q      PARTS**

QUALITY CHECK-REPAIRS  
FIRE PUMP CONTROLS

1      9IP; SWITCH

---

**Asset Work Order History K06239**

**CSHOP-2017-5449**

Comments: **WATER LEAKING FROM DISCHARGES T21**

Date Opened: 9-19-2017 Date Finished 9-20-2017 Meter 1 Reading: 69,005

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP PLUMBING

**CSHOP-2017-5851**

Comments: **SPARE TENDER AT 72**

Date Opened: 10-11-2017 Date Finished 10-13-2017 Meter 1 Reading: 69,005

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
QUARTZ LIGHT

**Service Requests:**

10/10/2017 LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING -LARGE WARNING LIGHTS ON THE SIDES AND REAR ARE NOT WORKING.

**CSHOP-2017-5926**

Date Opened: 10-14-2017 Date Finished 10-17-2017 Meter 1 Reading: 69,005

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP

1 BK; SWITCH  
1 BK; SWITCH

**Service Requests:**

10/14/2017 SERVICE REQUEST / 12: BROKEN  
PUMP NOT WORKING PROPERLY HIGH RPM FOR LOW PRESSURES

**CSHOP-2017-6105**

Comments: **T72**

Date Opened: 10-23-2017 Date Finished 11-14-2017 Meter 1 Reading: 69,313

**TASKS PERFORMED**

**Q PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS  
HOOD LATCH

1 9IP; 434 LATCH TRIGGER S/O  
1 9IP; HOOD LATCH

**Service Requests:**

10/23/2017 SERVICE REQUEST / 12: BROKEN / REPAIR  
SERVICE REQUEST BODY WARNING LIGHTS NOT WORKING

10/29/2017 BODY / 12: BROKEN / EXCHANGE - NEW  
BODY ISSUE PASSENGER SIDE HOOD LATCH BROKEN DO NOT HAVE PART GET AT SHOP IN AM

11/07/2017 LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING BODY WARNING LIGHTS NOT WORKING

11/09/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW  
VEHICLE LIGHTS NOT WORKING. STROBES OVER WHEEL WELL AND ON REAR OF TRUCK NOT WORKING.

**Asset Work Order History K06239**

**CSHOP-2017-6567**

Date Opened: 11-14-2017      Date Finished      11-14-2017      Meter 1 Reading:      69,313

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2017-6619**

Date Opened: 11-15-2017      Date Finished      11-17-2017      Meter 1 Reading:      69,935

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
SHORELINE CHARGER  
STROBE LIGHTS

**2      BK; HI-AMP FLUSH MOUNT**

---

**CSHOP-2017-6680**

Date Opened: 11-20-2017      Date Finished      1-19-2018      Meter 1 Reading:      69,654

**TASKS PERFORMED**

**NO PARTS USED**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
PRE TRIP INSPECTION  
STROBE LIGHTS

**Service Requests:**

---

11/17/2017      LIGHTS / 12: BROKEN / INSPECT  
VEHICLE LIGHTS NOT WORKING/ STROBE LIGHT IN REAR PASSENGER NOT WORKING...T72 SPARE

11/19/2017      LIGHTS / 12: BROKEN / INSPECT  
VEHICLE LIGHTS NOT WORKING STROBES OVER REAR TIRES NOT WORKING AND RIGHT REAR TOP STROBE OUT

---

**CSHOP-2017-7192**

Date Opened: 12-18-2017      Date Finished      12-19-2017      Meter 1 Reading:      69,654

**TASKS PERFORMED**

**NO PARTS USED**

---

LIGHTING SYSTEM

**Service Requests:**

---

12/17/2017      LIGHTS / 12: BROKEN / REPAIRED TAIL LIGHT WIRING  
VEHICLE LIGHTS NOT WORKING. TAIL LIGHTS NOT WORKING

---

**CSHOP-2018-1224**

Date Opened: 2-28-2018      Date Finished      3-1-2018      Meter 1 Reading:      69,976

**TASKS PERFORMED**

**NO PARTS USED**

---

CONTROL VALVE

---

**Asset Work Order History K06239**

**CSHOP-2018-1591**

Date Opened: 3-19-2018      Date Finished      3-19-2018      Meter 1 Reading:      70,258

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRE

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2018-1655**

Date Opened: 3-22-2018      Date Finished      3-27-2018      Meter 1 Reading:      70,258

**TASKS PERFORMED**

**Q      PARTS**

---

TANK-RESERVOIR  
AIR SYSTEM

1      5AB; 2.5 BALL KIT COMPOSITE  
1      5TN; VPS GEARSHAFT KIT

---

**CSHOP-2018-1946**

Comments:      **CALL OUT T42**

Date Opened: 4-9-2018      Date Finished      5-25-2018      Meter 1 Reading:      22,090

AUX. DRIVE FELL OFF

**TASKS PERFORMED**

**Q      PARTS**

---

SERPENTINE BELT

1      2DD; BOLT  
1      2DD; AUX DRIVE ASM  
2      NBH; POWERBAND V-BELT  
1      NONSTOCK; FREIGHT CHARGE  
1      2DD; BOLT HEX FLG  
1      2DD; SEAL RING

---

**CSHOP-2018-2132**

Date Opened: 4-17-2018      Date Finished      4-25-2018      Meter 1 Reading:      70,851

**TASKS PERFORMED**

**Q      PARTS**

---

HEADLIGHTS LOW BEAM

1      LMP; HALOGEN LAMP

---

**Asset Work Order History K06239**

**CSHOP-2018-2270**

Date Opened: 4-25-2018

Date Finished

7-3-2018

Meter 1 Reading:

72,050

**TASKS PERFORMED**

HOSE BED BODY  
SIDE COMPARTMENT BODY  
WIPER BLADES  
GOVERNOR  
LIGHTING SYSTEM  
FILTER  
TRANSMISSION  
AIR SYSTEM

**Q PARTS**

10 1WL; TURTLETILEBLKEA1212BK1WL  
4 WIP; WIPER  
1 2FR; INFINITY PRO  
2 DC; AEROSOL PAINT  
6 1WL; 500 TIR6 CLEAR  
1 NONSTOCK; FREIGHT CHARGE  
3 1WL; 900 SERIES SUPER RED LED  
2 1WL; 900 SERIES SUPER RED LED  
10 9AP; LED67  
1 1WL; L31SERIESBEACONRED  
2 9AP; TAG LIGHT  
1 FIL; NAPAGOLD AIR FILTER  
1 FIL; NAPA TRANS FILTER  
1 TWD; AD-9KIT  
1 TWD; AD-9KIT MINOR

**CSHOP-2018-2577**

Date Opened: 5-10-2018

Date Finished

6-7-2018

Meter 1 Reading:

72,020

**TASKS PERFORMED**

PM SERVICE C

**Q PARTS**

1 FIL; NAPAGOLD FUEL FILTER  
1 FIL; NAPA COOLANT FILTER  
2 FIL; NAPAGOLD OIL FILTER  
1 FIL; NAPAGOLD FUEL FILTER

**CSHOP-2018-4836**

Date Opened: 8-27-2018

Date Finished

8-30-2018

Meter 1 Reading:

72,809

**TASKS PERFORMED**

TRANSFER CASE  
TRANSMISSION

**NO PARTS USED**

**Service Requests:**

08/26/2018

TRANSMISSION / 11: BINDS/STICKS / EXCHANGE - NEW

TRANSMISSION NOT SHIFTING PROPERLY. TAKES 10 TO 20 SECONDS TO SHIFT INTO EACH GEAR.

**CSHOP-2018-5099**

Date Opened: 9-9-2018

Date Finished

9-9-2018

Meter 1 Reading:

73,327

**TASKS PERFORMED**

TRANSMISSION

**NO PARTS USED**

**Asset Work Order History K06239**

**CSHOP-2018-5228**

Date Opened: 9-13-2018

Date Finished

9-20-2018

Meter 1 Reading:

73,618

**TASKS PERFORMED**

**Q PARTS**

---

TRANSMISSION

1 FIL; NAPA TRANS FILTER  
-5 1AD; TRANS FLUID  
24 1AD; TRANS FLUID  
5 1AD; TRANS FLUID

---

**CSHOP-2018-527**

Date Opened: 1-24-2018

Date Finished

2-14-2018

Meter 1 Reading:

69,654

**TASKS PERFORMED**

**Q PARTS**

---

QUALITY CHECK-REPAIRS  
FIRE PUMP  
TANK-RESERVOIR  
LIGHTING SYSTEM  
DIAGNOSE ELECTRICAL  
AIR SYSTEM  
LIGHT BAR

2 LMP; LAMP  
2 LMP; BULB  
1 5TN; VPS SHIFT CONTROL PUMP KIT  
1 9AP; BULB, 150W HALOGEN  
1 NONSTOCK; FREIGHT CHARGE

---

**CSHOP-2018-5299**

Date Opened: 9-17-2018

Date Finished

9-19-2018

Meter 1 Reading:

73,618

**TASKS PERFORMED**

**NO PARTS USED**

---

STROBE LIGHTS

**Service Requests:**

---

09/15/2018 LIGHTS / 19: LOOSE / INSPECT  
VEHICLE LIGHTS NOT WORKING EMERGENCY LIGHTS ON REAR OF TENDER NOT WORKING

---

**CSHOP-2018-5521**

Date Opened: 9-27-2018

Date Finished

10-11-2018

Meter 1 Reading:

74,215

**TASKS PERFORMED**

**Q PARTS**

---

FIRE PUMP  
TIRES & WHEELS

2 NCB; BLASTER PENETRANT  
2 NGK; SPARK PLUG  
25 9OC; BULK TRANS SYN  
1 FIL; NAPA TRANS FILTER  
1 5CS; GAUGE 600 PSI 4.5 IN WHITE  
1 5SC; QD RELIEF VALVE LESS PM CNTRL  
1 5CS; 4.5" -30 - 600 PSI WHITE

---



**Asset Work Order History K06239**

**CSHOP-2018-5980**

Date Opened: 10-20-2018      Date Finished      11-8-2018      Meter 1 Reading:      75,039

**TASKS PERFORMED**

**Q      PARTS**

---

ENGINE AND ACCESSORIES  
HEADLIGHTS LOW BEAM  
LIGHTING SYSTEM  
TIRE

2      PAF; ANTIFRZ  
1      9OC; COOLANT  
1      LMP; LAMP

**Service Requests:**

---

10/26/2018      SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW  
T42 DRIVER SIDE HEADLIGHT NOT WORKING

---

**CSHOP-2018-6330**

Date Opened: 11-6-2018      Date Finished      11-6-2018      Meter 1 Reading:      75,039

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRES ALL

**VENDOR?**      DAN CALLAGHAN ENTERPRISES

---

**CSHOP-2018-6354**

Date Opened: 11-7-2018      Date Finished      11-9-2018      Meter 1 Reading:      75,141

**TASKS PERFORMED**

**NO PARTS USED**

---

LIGHTING SYSTEM  
TIRES & WHEELS

**Service Requests:**

---

11/04/2018      BODY / 12: BROKEN / EXCHANGE - NEW  
BODY ISSUE T42 HAS A MILD SHAKING BETWEEN 45 AND 55 MPH. TRUCK IS OK FOR NOW BUT I THINK IT IS GETTING WORSE. ALSO THE DRIVERS SIDE FRONT BUMPER MARKER LIGHT IS OUT.

---

**CSHOP-2018-968**

Date Opened: 2-14-2018      Date Finished      2-22-2018      Meter 1 Reading:      69,887

**TASKS PERFORMED**

**NO PARTS USED**

---

TIRES & WHEELS  
SUSPENSION

---

**Asset Work Order History K06239**

**CSHOP-2019-1269**

Date Opened: 3-9-2019

Date Finished

5-13-2019

Meter 1 Reading:

26,286

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
FUEL SYSTEM	1	9AP; HAND SOAP PUM (TOTAL TRK)
COOLING SYSTEM	2	NCB; CLEAR DIESEL 32OZ
HEADLIGHTS HIGH BEAM	1	8GR; SIMPLEGREENCRYSTAL
HEADLIGHTS LOW BEAM	2	LMP; LAMP
INDICATOR LIGHT	1	LMP; LAMP
WINDOW REGULATOR	1	9IP; HANDLEWINDOW
GRILLE	1	9AP; GRILL

---

**CSHOP-2019-2567**

Date Opened: 5-15-2019

Date Finished

5-23-2019

Meter 1 Reading:

98,015

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
PM SERVICE B	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	-1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	2	FIL; NAPAGOLD OIL FILTER
	4	4PC; 15W40 PREMIUM BLUE OIL

---

**CSHOP-2019-2587**

Date Opened: 5-16-2019

Date Finished

5-28-2019

Meter 1 Reading:

98,015

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
DISCHARGE GAUGE	2	LIT; LED M C LAMP
LIGHTING SYSTEM	2	5CS; GAUGE 3.5, -30-600 WH
DIAGNOSE ELECTRICAL	2	9IP; SEAL
REAR HUB SEAL-GASKET	2	2TI; SET
REAR BEARING-RACE	30	4PC; GEAR OIL-SYN BULK (DELO)
REAR BRAKE PADS-SHOES	2	2TI; 2TI
AIR SYSTEM	2	1NS; AXLE FLANGE GASKET
FUEL GAUGE	1	2FL; SWITCH, NORMAL OPEN
AIR CONDITIONING	1	9HY; ACHOSE
	4	9XX; 134A 10194654

---

**CSHOP-2019-5046**

Date Opened: 9-25-2019

Date Finished

10-1-2019

Meter 1 Reading:

75,141

**TASKS PERFORMED**

	<b>Q</b>	<b>PARTS</b>
BATTERY	3	1AD; BATTERY GROUP 31

---

**Asset Work Order History K06239**

**CSHOP-2019-586**

Date Opened: 1-30-2019      Date Finished      2-14-2019      Meter 1 Reading:      75,141

**TASKS PERFORMED**

**Q      PARTS**

---

QUALITY CHECK-REPAIRS	1	5SC; PVG VALVE ONLYNO HARDWARE
FIRE PUMP PLUMBING	1	5AB; 2.5 BALL KIT COMPOSITE
FIRE APPARATUS	1	5AB; 2.5 BALL KIT COMPOSITE
ELECTRICAL	3	1AD; BATTERY 31 SERIES
TRANSFER CASE ASSEMBLY	1	NOS; NAPA OIL SEAL
REPAIR FROM PM - DECALS/CLEANLINESS	1	5HP; BEARING COVER GASKET
AIR SYSTEM	1	9AP; DETAIL
BODY EXTERIOR		

---

**CSHOP-2019-5980**

Date Opened: 11-14-2019      Date Finished      12-10-2019      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**Q      PARTS**

---

REPAIR FROM PM - POWER STEERING	1	2FL; CYLINDER STEERING
---------------------------------	---	------------------------

---

**CSHOP-2019-6044**

Comments:      **SPARE TANKER AT 21**

Date Opened: 11-18-2019      Date Finished      12-18-2019      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

**Service Requests:**

---

11/18/2019	LIGHTS / 38: SHORTED / REPAIR VEHICLE LIGHTS NOT WORKING STROBES ON LIGHT BAR NOT WORKING
11/18/2019	LIGHTS / 12: BROKEN / INSPECT VEHICLE LIGHTS NOT WORKING SIDE STROBE ON DRIVER SIDE FRONT BUMPER NOT WORKING

---

**CSHOP-2019-6365**

Comments:      **SPARE TANKER AT 21**

Date Opened: 12-9-2019      Date Finished      12-23-2019      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

**Service Requests:**

---

12/07/2019	LIGHTS / 38: SHORTED / REPAIR VEHICLE LIGHTS NOT WORKING- REAR SCENE LIGHTS NOT WORKING
------------	--

---

**Asset Work Order History K06239**

**CSHOP-2019-6728**

Date Opened: 12-31-2019      Date Finished      1-3-2020      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

**Service Requests:**

12/30/2019      LIGHTS / 38: SHORTED / REPAIR  
VEHICLE LIGHTS NOT WORKING - RIGHT REAR RUNNING LIGHT IS OUT.

**CSHOP-2020-102**

Date Opened: 1-8-2020      Date Finished      1-21-2020      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**Q      PARTS**

TRAVEL TO BE CHARGED TO WORK ORDER  
LIGHTING SYSTEM

1      9AM; LENS KIT BUMPER GUIDE  
2      LMP; LAMP LED 168 194

**Service Requests:**

01/07/2020      LIGHTS / 38: SHORTED / EXCHANGE - NEW  
VEHICLE LIGHTS NOT WORKING -

01/07/2020      SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW  
CLARIFICATION TO VEHICLE LIGHT SERVICE REQUEST ALREADY SUBMITTED. THE RIGHT FRONT MARKER LIGHT  
(AMBER POST LIGHT) IS OUT. AMBER LIGHT COVER IS ALSO MISSING.

**CSHOP-2020-1431**

Date Opened: 3-11-2020      Date Finished      5-1-2020      Meter 1 Reading:      76,704

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
FIRE PUMP  
LIGHT BAR  
STROBE LIGHTS

**Service Requests:**

03/11/2020      LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING END STROBES ON LIGHT BAR NOT WORKING

03/11/2020      LIGHTS / 12: BROKEN / REPAIR  
VEHICLE LIGHTS NOT WORKING LF BUMPER STROBE NOT WORKING

03/11/2020      SERVICE REQUEST / 18: LEAKING / OVERHAUL  
TYPE PROBLEM INTO DESCRIPTION PUMP LEAKING WHILE PUMP ENGAGED

**Asset Work Order History K06239**

**CSHOP-2020-1557**

Date Opened: 3-18-2020      Date Finished      4-13-2020      Meter 1 Reading:      76,704

**TASKS PERFORMED**

**Q      PARTS**

---

TRAVEL TO BE CHARGED TO WORK ORDER  
WIPERS-WASHER  
FAN CLUTCH  
AIR CONDITIONING

2      WIP; WIPER  
1      2FL; COMPRESSOR AC  
1      2FL; RECEIVER  
-1      2FL; RECEIVER  
1      NBH; V BELT  
1      TEM; FILTER DRIER  
1      2FL; 2FL  
1      2FL; CLUTCH FAN SINGLE SPEED

---

**CSHOP-2020-2515**

Comments:      **INSPECT ONLY NO OIL / FILTERS**

Date Opened: 5-12-2020      Date Finished      5-14-2020      Meter 1 Reading:      76,817

**TASKS PERFORMED**

**NO PARTS USED**

---

PM SERVICE C

---

**CSHOP-2020-2671**

Comments:      **LUBE OIL AND FILTERS PM FOLLOW UPS "SEE FILES"**

Date Opened: 5-19-2020      Date Finished      9-11-2020      Meter 1 Reading:      76,817

FRONT REAR RIGHT TIRES BAD

**TASKS PERFORMED**

**NO PARTS USED**

---

REAR TIRES

---

**CSHOP-2020-492**

Date Opened: 1-29-2020      Date Finished      2-6-2020      Meter 1 Reading:      75,930

**TASKS PERFORMED**

**Q      PARTS**

---

HOSE BED BODY  
PRE TRIP INSPECTION  
EXHAUST PIPE  
LIGHTING SYSTEM

1      2FL; PIPE TURBO  
2      1WL; LED FLOODLIGHT

---

**SSHOP-2019-356**

Date Opened: 10-18-2019      Date Finished      10-22-2019      Meter 1 Reading:      75,627

**TASKS PERFORMED**

**Q      PARTS**

---

THROTTLE CONTROLS

1      TWD; C HERSEE

---