

**Palm Beach County Fleet Management
Asset Maintenance History**

10196729 2014 TORO WORKMAN HDXD Sprayer, Self Propelled, 200 Gal. Tank

Workorder: 1411900 **Meter:** 2 **In Date:** 11/25/2014 **Closed:** 11/25/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
 :

Workorder: 1506002 **Meter:** 174 **In Date:** 06/16/2015 **Closed:** 06/19/2015
Problem: overheating

- Pressure test system for Leaks -none found- test run and
 ck for operation working normal- top off sys and road test -ok
 - changed oil and filter. Check over
 - Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
15-40 Oil	3.00
Shop Supplies	1.00

Hours 2.50 Labor: 150.00 Parts: 15.38 Total: 165.38
 :

Workorder: 1506152 **Meter:** 178 **In Date:** 06/18/2015 **Closed:** 07/07/2015
Problem: dealer pick up/ overheating

- To Hector turf for cooling sender and sensor warranty

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1511668 **Meter:** 287 **In Date:** 11/16/2015 **Closed:** 11/24/2015
Problem: pm service

- Pm
 - Hyd service
 - Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napa Gal 15w40	1.00
Napa Hydraulic Filtr	1.00
Brake Cleaner	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 300.00 Parts: 48.44 Total: 348.44
 :

Workorder: 1511782 **Meter:** 287 **In Date:** 11/18/2015 **Closed:** 11/24/2015
Problem: foamer solenoid problem

- to dealre for foamr liquid solenoid warranty

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605564 **Meter:** 388 **In Date:** 05/31/2016 **Closed:** 06/15/2016
Problem: defoamer marker not working, left rear hub making noise, platis pick up in tank broken,foame part

	Parts List	Qty
- Rebuild foamer pump repalce solenoid		
- Replace suction filter asm and foot tube	Rubber Hose	12.00
- Replace two hubs rear repalce driver side drive shaft asm	solenoid valve	4.00
- Shop Supplies	1cart Palladium 2 Grs	1.00
	tube suction	1.00
	Hub Wheel Bearing	2.00
	Diaphram Kit	1.00
	Tube Suction	1.00
	Suction Filter Assy	1.00
	Splined Shaft	1.00
	Spindle Nut	1.00
	Flange Nut	1.00
	Hose Clamp S/s	5.00
	driveshaft	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 330.00	Parts: 2,344.67
:		Total: 2,674.67

Workorder: 1611893 **Meter:** 604 **In Date:** 11/17/2016 **Closed:** 11/30/2016
Problem: pm/ defoamer/ front gauge/ see notes

	Parts List	Qty
- Pm		
- Hyd Service	solenoid valve	4.00
- Replaced all foamer solenoid and test run	Napagold Oil Filter	1.00
- Disconnect hose from front pressure gauge to rear "t"	Napagold Air Filter	1.00
Connection to clear out line and reinstall and test run	Napagold Fuel Filter	1.00
- Shop Supplies	15-40 Oil	4.00
	Napa Hydraulic Filtr	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 285.04
:		Total: 705.04

Workorder: 1700833 **Meter:** 672 **In Date:** 01/26/2017 **Closed:** 02/27/2017
Problem: rear water pump leaking, front press guage not reading

	Parts List	Qty
- R/r valve cover and diaphram, test run sys		
- Flush line and gauges with fresh water clear hardened chemical from hoses	Cover Pump	1.00
	Diaphragm	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 458.93
:		Total: 578.93

Workorder: 1707317 **Meter:** 841 **In Date:** 07/26/2017 **Closed:** 08/03/2017
Problem: defoamer solenids frozen

	Parts List	Qty
- Replaced foamer solenoids and test run		
- Ck Tire for leak-none found	solenoid valve	4.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 243.74
:		Total: 363.74

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1708038	Meter: 851	In Date: 08/16/2017	Closed: 08/25/2017
Problem: left side pump head leaking			
- r&r pump replace 5 heads, test ok at this time		Parts List	Qty
- Replace ign switch		Cover Pump	5.00
- Shop Supplies		Diaphragm	1.00
		Ignition Switch	1.00
		Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 2,084.74	Total: 2,384.74
:			

Workorder: 1710200	Meter: 891	In Date: 10/18/2017	Closed: 10/31/2017
Problem: leak/ replace hose/ see notes			
- R&r pump replace seal kit		Parts List	Qty
- Replace hoses and seals fittings		Silicone Spray 10oz	1.00
- Shop Supplies		Pump Kit	1.00
		O-ring	1.00
		O Ring	1.00
		Bypass Hose	1.00
		Hose Barb 90 Degree	1.00
		Suction Elbow	1.00
		Hose Clamp	2.00
		Shop Supplies	1.00
		Freight Charge	1.00
Hours 8.00	Labor: 480.00	Parts: 1,169.74	Total: 1,649.74
:			

Workorder: 1800022	Meter: 955	In Date: 01/02/2018	Closed: 01/22/2018
Problem: pm/ lr tire slow leak			
- Pm		Parts List	Qty
- Hyd Service		Prem Blue 15w40 1 Gal	1.00
- Load Test and Replace battery		Napagold Oil Filter	1.00
- Ck Poss Slow leak in L/r tire. No leak found		Napagold Air Filter	1.00
- Shop Supplies		Napagold Fuel Filter	1.00
		Non-chlor Brake Clnr	2.00
		Napa Hydraulic Filtr	3.00
		Group 26 Delco	1.00
		Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 170.56	Total: 560.56
:			

Workorder: 1800509	Meter: 955	In Date: 01/16/2018	Closed: 01/30/2018
Problem: defoamer cap and valve			
- Secure part for dept		Parts List	Qty
- Shop Supplies		Cap Assy	2.00
		Flow Reg Mount Cap	2.00
		Shop Supplies	1.00
Hours 0.50	Labor: 30.00	Parts: 429.41	Total: 459.41
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1805726 **Meter:** 1079 **In Date:** 06/05/2018 **Closed:**
Problem: radiator leak

-

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1805727 **Meter:** 1088 **In Date:** 06/05/2018 **Closed:** 06/15/2018
Problem: radiator leak

- pressure test cooling system, replace radiator and flush system **Parts List** **Qty**
- Shop Supplies

	Radiator	1.00
	Cap	1.00
	Napa Antifreeze Gal	2.00
	Shop Supplies	1.00

Hours 2.50 Labor: 150.00 Parts: 1,010.90 Total: 1,160.90
:

Workorder: 1809519 **Meter:** 1240 **In Date:** 09/14/2018 **Closed:** 10/18/2018
Problem: pm/ tires/ foamers/ hose reel/ 2 extra keys/ see notes

- pm service **Parts List** **Qty**
- hydraulic service Napagold Oil Filter 1.00
- replace foam tubing, foamer nozzle assy, mixer & filter assy Prem Blue 15w40 1 Gal 1.00
- secure keys Napagold Air Filter 1.00
- repair elect connect for reel & replace fuse Napagold Fuel Filter 1.00
- Shop Supplies Non-chlor Brake Clnr 2.00
Napa Hydraulic Filtr 1.00
Suction Filter 1.00
Filter Housing 1.00
Rod Mount Kit 1.00
Rod 2.00
Nozzle Foam Assy 2.00
Foam Mixer Asm 2.00
Ignition Key 2.00
Shop Supplies 1.00
Freight Charge 1.00
Freight Charge 1.00

Hours 11.50 Labor: 770.50 Parts: 837.70 Total: 1,608.20
:

Workorder: 1812533 **Meter:** 1330 **In Date:** 12/10/2018 **Closed:** 12/27/2018
Problem: spray nozzles pulsate when spraying/ see notes

- test for pulstion, replace pray pump. transfer all parts. test run **Parts List** **Qty**
- replace left rear tire 24x12.00-12 Toro 6 Ply 1.00
- Shop Supplies Pump 1.00
Shop Supplies 1.00
Tire Disposal Fee 1.00

Hours 5.00 Labor: 335.00 Parts: 4,165.86 Total: 4,500.86
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1905933 **Meter:** 1505 **In Date:** 06/05/2019 **Closed:** 06/11/2019
Problem: order parts for sprayer

- Parts Only	Parts List	Qty
- Shop Supplies	Nut Wing	6.00
	Nut Wing Plastic	6.00
	O-ring	3.00
	Suction Filter	3.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 0.00	Labor: 0.00	Parts: 415.36
:		Total: 415.36

Workorder: 1911038 **Meter:** 1719 **In Date:** 10/25/2019 **Closed:** 11/18/2019
Problem: pm, out rig foamer attachments, foam tank lid leak, fomer sol frozen, see note for rest

- Pm Service	Parts List	Qty
- Hydraulic service	Napa Qt 15w40	4.00
- Repl. L/s defoamer mount; repl. leaking defoamer tank cap;	Napagold Oil Filter	1.00
repl. flow control valve	Napagold Air Filter	1.00
- Repl. spray control switch; trace out & test hose reel circuit;	Napagold Fuel Filter	1.00
repl. faulty hose reel relay	Non-chlor Brake Clnr	2.00
- Adjust parking brake	Napa Hydraulic Filtr	1.00
- Repair battery terminals	Syn-atf Trans Fluid S	8.00
- Repl. cracked alternator belt	Cap Assy	1.00
- Shop Supplies	Rod Mount Kit	1.00
	Relay	1.00
	Rocker Switch	1.00
	V Belt	1.00
	Clamp	1.00
	Flow Regulator Kit	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00
Hours 11.00	Labor: 803.00	Parts: 485.19
:		Total: 1,288.19

Workorder: 2000413 **Meter:** 1748 **In Date:** 01/14/2020 **Closed:** 01/14/2020
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 146.00	Parts: 0.00
:		Total: 146.00