10162812 2006 GMC 1500 Pickup, 1/2 Ton, W/Toolbox, V8

Workorder: 642875 Meter: In Date: 07/24/2006 Closed: 07/24/2006 Problem: PRE-DELIVERY INSPECTION - Pre-delivery Inspection Labor: 100.00 Hours 2.00 Parts: 0.00 Total: 100.00 Closed: Workorder: 646354 Meter: 513 In Date: 09/29/2006 09/29/2006 Problem: FUEL CAP MISSING. - R & R Fuel Cap And Clear Computer System **Parts List** Qty - Shop Supplies **Shop Supplies** 1.00 15225005 Fuel Cap 1.00 Labor: 37.50 Parts: 18.10 Hours 0.75 Total: 55.60 Workorder: 735519 582 03/13/2007 Closed: 03/16/2007 Meter: In Date: Problem: P.M SERVICE, CHECK L/R TIRE & BATTERY - Pm Service Complete **Parts List** Qty - Nitro Fill All 4 Tires **Shop Supplies** 1.00 - Repair L/r Tire. 1522 Oil Filter Frm Ph3675/9837 Wix 51522 1.00 - Shop Supplies 10w30 Motor Oil 6.00 Hours 4.00 Labor: 220.00 Parts: 19.13 Total: 239.13 Workorder: 746762 Meter: 5361 In Date: 11/05/2007 Closed: 11/09/2007 Problem: P.M SERVICE - Pm Service **Parts List** Qty - Balance Tires For Vibration Concern **Shop Supplies** 1.00 Ph9837 Oil Filter Wix 51522 - Service Rear Brakes Clean And Adjust. 1.00 - Shop Supplies 10020 Injector Cleaner Don't Reorder 1.00 10w30 Motor Oil 6.00 Labor: 240.00 Hours 4.00 Parts: 22.96 Total: 262.96 Workorder: 05/22/2008 Closed: 05/27/2008 838894 Meter: 9662 In Date: Problem: P.M SERVICE, CRANKS SLOW - Pm Service **Parts List** Qty - Diagnose Slow Eng Crank.test Charging Sys & **Shop Supplies** 1.00 Battery.replace Defective Battery 6678 Air Filter Frm Ca8755a Wix 46678 1.00 - Service Rear Brakes.clean And Adjust Ph9837 Oil Filter Wix 51522 1.00 - Front End Alignment Complete.test Drive. 10w30 Motor Oil 6.00 - Shop Supplies Used Firex Refurbed Fire Extingshers 1.00 Group 78 Battery (acd 78ps) 1.00 Hours 6.50 Labor: 390.00 Parts: 148.66 Total: 538.66

Workorder: 847752 Meter: 13456 Problem: P.M SERVICE	In Date: 12/04/2008 Closed:	12/12/2008
- Pm Service	Parts List	Qty
- Replace Both Frt Tires.hi Speed Balance All 4	Shop Supplies	1.00
Tires.nitrofiltires.	Ph9837 Oil Filter Wix 51522	1.00
- Install 2 Small Spot Mirror.	10w30 Motor Oil	6.00
- Replace Pindle Hitch Safety Pin Missing.	V600 Spot Mirror 2" (velvac 723050)	2.00
- Resurface Frt Rotors To Correct Pulsation Fealt In Steering	31-22 Wiper Blades 22" Wiper Blade	2.00
Wheel, service Rear Brakes, inspect, clean And Adjust Rear Brakes.	Tire Disposal Fee	2.00
- Complete Front End Alignment. Test Drive.	758508188 245/70r17 Wrg Silent Armor 108	t 2.00
- Shop Supplies	18410 Pintle Pin	1.00
	630.00 Parts: 391.22 Total:	1,021.22
Workorder: 939261 Meter: 17133 Problem: PM SERVICE.	In Date: 06/19/2009 Closed:	06/30/2009
- Pm Service	Parts List	Qty
- Rotate And High Speed Balance All 4 Tires	Shop Supplies	1.00
- Rear Brake Service	Ph9837 Oil Filter Wix 51522	1.00
- Shop Supplies	10w30 Motor Oil	5.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 4.00 Labor:	240.00 Parts: 32.88 Total:	272.88
Workorder: 1000290 Meter: 21127 Problem: P.M service.	In Date: 01/07/2010 Closed:	01/20/2010
- P.m service.	Parts List	Qty
- Mount two new tires, rotate & balance all four tires.	Shop Supplies	1.00
- Replace worn R/s inner tie rod.	Ph9837 Oil Filter Wix 51522	1.00
- Alignment.	10w30 Motor Oil	6.00
- Service rear drum brakes.	31-22 Wiper Blades 22" Wiper Blade	2.00
- Shop Supplies	Ev370 Inner Tie Rod (moog)	1.00
	179469492 Lt245/70r17 Wrangler Sr-a E	2.00
	Tire Disposal Fee	2.00

Hours 8.70

Labor: 522.00 Parts: 424.10 Total: 946.10

Workorder: 100860 Problem: P.M. Se	7 Meter: 24834 ervice.A/C inop at times.		lr	n Date:	08/10/2010	Closed:	08/20/20	010
- Perform pm service.			Parts List					Qty
•	failed blower motor,resistor and	d pigtail	Shop Supp	olies				1.00
harness with new to co	rrect ac concern.		Ph9837 Oi	l Filter W	ix 51522			1.00
- Rotate and balance a			10w30 Mo	tor Oil				6.00
	service and adjust brake shoe	S.	Used Firex	Refurbe	d Fire Extings	hers		1.00
- Shop Supplies			31-20 Wipe	er Blades	20" Blade			2.00
			15-81683 E	Blower M	otor (acd)			1.00
			22807123	Resistor	Blower Motor	r (acd)		1.00
			Pt2195 Pig	tail Blow	er Motor (acd))		1.00
	Hours 6.50 :	Labor:	390.00	Parts:	279.12	Total:	669.12	
Workorder: 110164 Problem: Pm serv	8 Meter: 28584 vice also see notes on bed line	er cap.	lr	n Date:	02/11/2011	Closed:	02/17/20	011
- Perform pm service.			Parts List					Qty
	arging system.battery failed loa	d test	Shop Supp	olies				1.00
· ·	failed battery with new.		Ph9837 Oi	I Filter W	ix 51522			1.00
- Rotate and balance a			6678 Air F		1.00			
	rakes service and adjust brake	shoes.	10w30 Mo		6.00			
- Shop Supplies			31-20 Wipe		2.00			
			Group 78 E	Battery (a	icd 78ps)			1.00
	Hours 5.00 :	Labor:	300.00	Parts:	150.39	Total:	450.39	
Workorder: 110795 Problem: Pm serv	1 Meter: 32299 vice and airbag light on.		lr	n Date:	07/29/2011	Closed:	08/08/20	011
- P.m. Service.			Parts List					Qty
	stem.b0044.perform circuit test	and	Shop Supp	olies				1.00
replace defective clock	, •		Ph9837 Oi	I Filter W	ix 51522			1.00
- Service and adjust re			10w30 Mo	tor Oil				6.00
- Rotate and balance a	all tires.		Used Firex	Refurbe	d Fire Extings	shers		1.00
a. a			31-22 Wipe	er Blades	22" Wiper Bla	ade		2.00
- Shop Supplies								1.00
- Shop Supplies			Clock Sprii	ng				
- Shop Supplies	Hours 6.25	Labor:	Clock Sprii 375.00	•	245.64	Total:	620.64	
	: Meter: 33678	Labor:	375.00	•	245.64	Total:	10/24/20	011
Workorder: 111079 Problem: Airbag I	: Meter: 33678		375.00	Parts:				011 Qty
Workorder: 111079 Problem: Airbag I - Diagnose airbag ligh	: 3 Meter: 33678 ight on.		375.00 Ir	Parts:				
Workorder: 111079 Problem: Airbag I - Diagnose airbag ligh	: 3 Meter: 33678 ight on. tpin-point test and replace de		375.00 Ir	Parts: Date:	10/11/2011			Qty

Workorder: 1201518 Meter: 36388 Problem: P.M. service and check left rear tail light and	In Date: 02/15/2012 Closed: 02/28/2012 headliner falling down.
- P.m. Service.	Parts List Qty
- Replace left tail lamp assemble.	Shop Supplies 1.00
- Replace missing pintle pin.	Ph9837 Oil Filter Wix 51522 1.00
- Rotate and balance all tires.	10w30 Motor Oil 6.00
- Service and adjust rear brakes.	5068 Penetrant Lube Pentron (mantek) 1.00
- Shop Supplies	Air Freshener 1.00
	31-22 Wiper Blades 22" Wiper Blade 2.00
	Left Tail Lamp Assy 1.00
	18410 Pintle Pin 1.00
Hours 4.75 Labor:	: 285.00 Parts: 197.43 Total: 482.43
Workorder: 1206481 Meter: 39165 Problem: Power sterring leak and tailgate handle beze	In Date: 07/11/2012 Closed: 07/25/2012 came off.
- Replace leaking power steering oil cooler.flush and refill	Parts List Qty
system Replace missing tailgate bezel.	Shop Supplies 1.00
- Shop Supplies	61a P/steering Fluid 1.00
- Shop Supplies	Tailgate Bezel 1.00
	Power Steering Cooler 1.00
Hours 2.00 Labo	: 120.00 Parts: 155.64 Total: 275.64
Workorder: 1209994 Meter: 40890 Problem: Pm service.	In Date: 10/18/2012 Closed: 11/16/2012
- P.m. Service.	Parts List Qty
- Replace and balance four new tires.	10w30 Motor Oil 6.00
- Fabricate and replace rusted out brake line.	Ph9837 Oil Filter Wix 1.00
- Service and adjust rear brakes.	Used Firex Refurbed F 1.00
- Compklete wheel alignment.test drive.	05088 Brake Clean 1.00
- Shop Supplies	31-22 Wiper Blades 22 2.00
	179469492 Lt245-70r17 4.00
	2232 Brake Fluid Quar 1.00
	Tubing 18.00
	Fittings 4.00
	Tubing 2.00
	2232 Brake Fluid Quar 1.00
	Shop Supplies 1.00
Hours 13.50 Labor:	T: 810.00 Parts: 1,104.32 Total: 1,914.32
Workorder: 1301072 Meter: 42418 Problem: Check over starting and charging system.	In Date: 01/30/2013 Closed: 02/08/2013
- Test starting and charging system.battery failed loadtest	Parts List Qty
after recharge.replace failed battery with new warranty part	Group 78 Acd 1.00
- Shop Supplies	Shop Supplies 1.00
Hours 1.00 Labor:	:: 60.00 Parts: 119.45 Total: 179.45

Workorder:	1304757 P.M. service	Meter:		adlight and		In Date:	05/13/2013	Closed:	06/11/20	13
		and oneon	ngin side ne	adiigiit ailu	Parts Lis	J	(VIII.			O4-
- Perform pm			مما سمسماسامم							Qty
 Remove righ adjustment sci 				se	10w30 M					6.00
- Perform rear drum brake service and adjust brake shoes.						d Oil Filter				1.00
- Rotate and b			,		Wiper Bla	ade : Lithium G	roo			2.00 1.00
- Transport ve			auto trim sh	op for		r R&r	res			1.00
epairing dama				•	Shop Su	•				1.00
- Shop Suppli	es				Shop Su	opiies				1.00
	Hou :	urs 6.50		Labor:	390.00	Parts:	240.67	Total:	630.67	
Workorder:	1400249	Meter:	49397			In Date:	01/08/2014	Closed:	03/13/20	14
Problem:	Pm service.0	Check for fu	el gauge inte	ermittent op	peration.					
- Perform pm	service.				Parts Lis	st				Qty
- Install new f					10w30 M	otor Oil				6.00
	calipers and f and adjust b					d Oil Filter				1.00
nydraulic syste					Used Fire	e X Refurbi	shed			1.00
- Inspect and	replace failed	d hitch pinde	I pin with ne	w and	Wiper Bla					2.00
secure.					Brake Pa					1.00
- Computer diagnose fuel gauge inop.test and replace failed instrument cluster with new and reprogram with tech 2 pass					Pintle Pir					1.00
hru.	Ster With Hew	and reprogr	am with tech	1 2 pass	inst clust			1.00		
- Rotate and b	balance all for	ur tires.			Shop Su	oplies				1.00
- Shop Suppli	es									
	Hou	urs 10.25		Labor:	615.00	Parts:	512.27	Total:	1,127.27	
Workorder:	1404138	Meter:	49773			In Date:	04/30/2014	Closed:	04/30/20	14
Problem:	Transition Pr	rep Charge								
- Transition P	rep Charge									
	Hou	urs 2.00								
	:	G. C 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder:	1404194	Meter:	49773	Labor:		Parts:	0.00	Total:	120.00	14
	: 1404194 1 - Detail Ve	Meter:								14
Problem:	1 - Detail Ve	Meter: chicle Wash	Ticket(s) Iss							14
Workorder: Problem: - 1 - Detail Ve	1 - Detail Ve ehicle Wash T	Meter: chicle Wash	Ticket(s) Iss				04/30/2014		04/30/20	14
Problem: - 1 - Detail Ve Workorder:	1 - Detail Ve ehicle Wash T	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter:	Ticket(s) Iss	ued	0.00	In Date:	04/30/2014	Closed:	04/30/20	
Problem: - 1 - Detail Ve Workorder: Problem:	1 - Detail Ve ehicle Wash T Hou : 1409196	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter:	Ticket(s) Iss	ued	0.00	In Date: Parts: In Date:	04/30/2014	Closed:	04/30/20	
Problem: - 1 - Detail Ve Workorder: Problem: - Pm	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I	Meter: Phicle Wash Ticket(s) Issuurs 0.00 Meter: light on	Ticket(s) Iss	ued	0.00	In Date: Parts: In Date:	04/30/2014	Closed:	04/30/20	14
Problem: - 1 - Detail Ve Norkorder: Problem: - Pm - Clean And A	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter: light on	Ticket(s) Issued	ued Labor:	0.00 Parts Lis 10w30 B	In Date: Parts: In Date:	04/30/2014	Closed:	04/30/20	14 Qty
Problem: - 1 - Detail Ve Norkorder: Problem: - Pm - Clean And A - Ck Air Bag L Perform Pinpo	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I Adj Rear Brake Light Is On Sc bint Test And I	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter: light on es cana And Fo Foiund Bad	Ticket(s) Issued 51483 bund Code Bound Left Front Ai	ued Labor:	0.00 Parts Lis 10w30 B Napagolo	In Date: Parts: In Date: st	04/30/2014	Closed:	04/30/20	14 Qty 6.00
Problem: - 1 - Detail Ve Norkorder: Problem: - Pm - Clean And A - Ck Air Bag L Perform Pinpo	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I Adj Rear Brake Light Is On Sc bint Test And I	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter: light on es cana And Fo Foiund Bad	Ticket(s) Issued 51483 bund Code Bound Left Front Ai	ued Labor:	0.00 Parts Lis 10w30 B Napagolo Napagolo	Parts: In Date: In Date: It Oil Filter	04/30/2014 0.00 09/12/2014	Closed:	04/30/20	14 Qty 6.00 1.00
Problem: - 1 - Detail Ve Norkorder: Problem: - Pm - Clean And A - Ck Air Bag L Perform Pinpo	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I Adj Rear Brake Light Is On Sc bint Test And I	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter: light on es cana And Fo Foiund Bad	Ticket(s) Issued 51483 bund Code Bound Left Front Ai	ued Labor:	0.00 Parts Lis 10w30 B Napagolo Napagolo	Parts: In Date: In Date: In Date: It Ulk Sr It Oil Filter It Air Filter It X Refurbi	04/30/2014 0.00 09/12/2014	Closed:	04/30/20	14 Qty 6.00 1.00
Problem: - 1 - Detail Ve Workorder:	1 - Detail Ve chicle Wash T Hou : 1409196 pm, air bag I Adj Rear Brake Light Is On Sc bint Test And I	Meter: chicle Wash cicket(s) Issuurs 0.00 Meter: light on es cana And Fo Foiund Bad	Ticket(s) Issued 51483 bund Code Bound Left Front Ai	ued Labor:	0.00 Parts Lis 10w30 B Napagolo Napagolo Used Fire	Parts: In Date: In Date: In Date: In Date: In Coll Filter In Air Filter	04/30/2014 0.00 09/12/2014	Closed:	04/30/20	14 Qty 6.00 1.00 1.00

Workorder: Problem:	1505136	Meter:	55083			In Date:	05/20/2015	Closed:	05/26/20	015
- pm	piii				Parts Lis	t				Qty
- clean and ac	di rear brakes				10w30 Bu					6.00
- repair right re	•				Napagold					1.00
repair right is	car tag light				Wiper Bla					2.00
					Washer F					1.00
					Brake Cle					1.00
	Hour	s 3.50		Labor:	210.00		37.02	Total:	247.02	1.00
Workorder: Problem:	1511852 P.M.SERVICE	Meter: E,BROKEN	58343 N PASSENG	SER DOOR		In Date:	11/19/2015	Closed:	11/30/20)15
- pm					Parts Lis	t				Qty
- replace miro	r assy pass sic	le replace	rear bezeel		10w30 Bu	ılk Sr				6.00
- clean and re	adjust rear sho	es and dr	ums		Napagold	l Oil Filter				1.00
•	194 bulbs repla	ace driver	side tag ligh	nt housing	Wiper Bla	ade				2.00
assy					Bulb					2.00
- replace two	front tires due t	o dry crac	ks mount ar	nd balance	18311447	70 P245-7	'0r17			2.00
Third thir dir third	•				Mirror As	sembly				1.00
					Tag Lamp)				1.00
					Tail Gate	Handle Be	ezel			1.00
					Tire Dispo	osal Fee				2.00
	Hour :	s 6.00		Labor:	360.00	Parts:	623.64	Total:	983.64	
Workorder: Problem:	1604536 R/REAR SIGN	Meter:	60197 Г INOP.			In Date:	04/29/2016	Closed:	05/06/20	016
- Test and rep	lace two defec	tive 3157	bulbs.		Parts Lis	t				Qty
					Bulb					2.00
	Hour :	s 0.50		Labor:	30.00	Parts:	1.56	Total:	31.56	
Workorder: Problem:	1604748 Damage to fro	Meter: ont bumpe	60167 r			In Date:	04/11/2016	Closed:	05/05/20	016
- Damage to f	ront bumper									
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1604928 P.M.SERVICE	Meter:	60197			In Date:	05/11/2016	Closed:	05/24/20	016
- Pm service.					Parts Lis	t				Qty
- Service rear	drum brakes.				Napagold	l Oil Filter				1.00
- Verify nail rid	ght rear tire.rep	air right re	ear tire.rotate	e and	10w30 Bu	ılk Sr				6.00
balance all fou		Ü			22" Wiper	r Blade				2.00

Workorder: 1607579 Meter: 60870			In Date:	07/25/2016	Closed:	07/28/201	16
Problem: Battery leaking and rotten egg smell.							
- Test starting and charging system.test and replace		Parts Li	st				Qty
defective battery.		Group 7	8 Battery			•	1.00
Hours 0.75 L	_abor:	45.00	Parts:	103.74	Total:	148.74	
Workorder: 1612714 Meter: 63391			In Date:	12/12/2016	Closed:	12/27/201	 16
Problem: Pm Service.Check headlamp inop.							
- Pm service		Parts Li	st				Qty
- Clean and adjust rear brakes.		Napagol	d Oil Filter			•	1.00
- Repair right head light.		10w30 E	Bulk Sr			(6.00
- Replace both rear tires.balance all four.rotate new tire	s to	22" Wipe	er Blade			2	2.00
the front.		Washer	Fluid Conce	entr		•	1.00
		Napagol	d Air Filter			•	1.00
		Used Fir	e X Refurbi	ished		•	1.00
		Non-chlo	or Brake Clr	nr		•	1.00
		Halogen	Capsule			•	1.00
		1831144	170 P245-7	'0r17		2	2.00
		Tire Disp	oosal Fee			2	2.00
Hours 6.00 L	_abor:	360.00	Parts:	457.47	Total:	817.47	
Workorder: 1705238 Meter: 67083 Problem: Right front tire flat.Left head lamp inop.			In Date:	05/26/2017	Closed:	05/31/201	7
- Test and replace bad left side headlamp bulb.		Parts Li	st				Qty
- Repair and balance right front tire.		Halogen	Capsule			•	1.00
Hours 1.50 L	_abor:	90.00	Parts:	5.55	Total:	95.55	
Workorder: 1705727 Meter: 67137 Problem: P.M.SERVICE, A/C.			In Date:	06/08/2017	Closed:	06/19/201	7
- Pm Service.		Parts Li	st				Qty
- C/c ac wont go off with the key off.replace ac blower			d Oil Filter				1.00
motor,resistor and pigtail wire harness.		10w30 E				(6.00
- Service front calipers.rotors and replace brake pads.se	ervice	22" Wipe	er Blade				2.00
rear brakes.		•	Fluid Conce	entr			1.00
- Replace fuel cap.		Wire Tei	rm 16-14 BI	lt		10	0.00
- Repair left rear tire.		Non-chlo	or Brake Clr	nr			1.00
			Non-lockir				1.00
		Resistor		_			1.00
		Blower N					1.00
		Connect					1.00
		Brake Pa	ad Kit			•	1.00

Problem: Dead battery. Recharge battery.check charging system and found ignition switch causing draw on battery. Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service. Parts List Replace taglamp assembly in right side of bumper also replace left reverse lamp. Rotate and balance four tires. Clean and adjust rear brakes. Repaired tailgate to open and close properly.replace broken clip to extension rod.to latch(right side) Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48	Workorder: Problem:	1711626 PM Service.	Meter:	68526			In Date:	11/28/2017	Closed:	11/30/2017	7
- Vacume and clean air intake and crawl system.clogged with leaf and debris. - Rotate and balance four tires. - Rotate and balance four tires. - Rotate and balance four tires. - Hours 4.50 - Labor: 270.00 - Parts: 48.09 - Total: 318.09 - Workorder: 1802971 - Recharge battery. check charging system and found ignition switch causing draw on battery. - Remove steering colum covers and reset ignition switch timing. - Hours 2.75 - Labor: 165.00 - Parts: 0.00 - Parts: 0.00 - Total: 165.00 - Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly.replace broken clip to extension rod.to latch (right side) - Problem: Plours 6.00 - Labor: 360.00 - Parts: 74.48 - Total: 434.48 - Total: 434.48 - Workorder: 1808486 - Meter: 71440 - Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. - Test starting and charging system.test and replace bad battery. - Test starting and charging system.test and replace bad battery.	- Pm Service.					Parts Lis	st			(Qty
leaf and debris Rotate and balance four tires. Washer Fluid Concentr Used Fire X Refurbished Non-chlor Brake Clin Hours 4.50 Labor: 270.00 Parts: 48.09 Total: 318.09 Workorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery Recharge battery.check charging system and found ignition switch causing draw on battery Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service Parts List Used Fire X Refurbished Napagold Oil Filter 10w30 Bulk Sr - Clean and adjust rear brakes Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery.	- Clean and a	djust rear brak	es.			Napagolo	d Oil Filter			1	.00
Rotate and balance four tires. Rotate and balance four tires. Washer Fluid Concentr Used Fire X Refurbished Non-chlor Brake Clnr Hours 4.50 Labor: 270.00 Parts: 48.09 Total: 318.09 Workorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery. - Recharge battery.check charging system and found ignition switch causing draw on battery. - Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Parts List Battery			e and crav	wl system.clo	gged with	10w30 B	ulk Sr			6	.00
Workorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery. - Recharge battery.check charging system and found ignition switch causing draw on battery. - Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Parts List - Napagold Oil Filter - 10w30 Bulk Sr - 22" Wiper Blade Washer Fluid Concentr - Boxed Miniatures - Tag Lamp - Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery						22" Wipe	r Blade			2	2.00
Morkorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery. - Recharge battery.check charging system and found ignition switch causing draw on battery. - Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly.replace broken clip to extension rod.to latch(right side) Morkorder: 1808486 Meter: 71440 Labor: 1808486 Meter: 71440 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Non-cholor Brake Clor 270.00 Parts: 48.09 Total: 318.09 In Date: 03/20/2018 Closed: 05/21/20 Parts List Used Fire X Refurbished Napagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery.	- Rotate and b	palance four tir	es.			Washer I	Fluid Conc	entr		1	.00
Workorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery. - Recharge battery, check charging system and found ignition switch timing. - Remove steering colum covers and reset ignition switch timing. - Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) - Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Parts List - Test starting and charging system.test and replace bad battery. - Test starting and charging system.test and replace bad battery. - Test starting and charging system.test and replace bad battery. - Total: 318.09 - In Date: 03/20/2018 Closed: 05/30/20 - Parts List - Used Fire X Refurbished Napagold Oil Filter - 10w30 Bulk Sr - 22" Wiper Blade Washer Fluid Concentr - Boxed Miniatures - Tag Lamp - Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 - Total: 434.48						Used Fire	e X Refurb	ished		1	.00
Workorder: 1802971 Meter: 71120 In Date: 03/20/2018 Closed: 05/21/20 Problem: Dead battery. - Recharge battery.check charging system and found ignition switch causing draw on battery. - Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Problem: PM Service. - Pm Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Morkorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Parts List Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery						Non-chlo	r Brake Clı	nr		1	.00
Problem: Dead battery. Recharge battery.check charging system and found ignition switch causing draw on battery. Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service. Parts List Replace taglamp assembly in right side of bumper also replace left reverse lamp. Rotate and balance four tires. Clean and adjust rear brakes. Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Harts: 0.00 Harts: 0.00 Variation Date: 05/16/2018		Hour :	s 4.50		Labor:	270.00	Parts:	48.09	Total:	318.09	
switch causing draw on battery. Remove steering colum covers and reset ignition switch timing. Hours 2.75 Labor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 Problem: PM Service. Parts List Replace taglamp assembly in right side of bumper also Replace left reverse lamp. Rotate and balance four tires. Clean and adjust rear brakes. Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Labor: 360.00 Parts: 74.48 Workorder: 1808486 Meter: 71440 Problem: DEAD BATTERY Remove steering colum covers and reset ignition switch In Date: 08/17/2018 Parts List Used Fire X Refurbished Napagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Total: 434.48 Forblem: DEAD BATTERY Parts List Battery			Meter:	71120			In Date:	03/20/2018	Closed:	05/21/2018	8
timing. Hours 2.75 Eabor: 165.00 Parts: 0.00 Total: 165.00 Workorder: 1805063 Meter: 71120 Problem: PM Service. Pm Service. Replace taglamp assembly in right side of bumper also replace left reverse lamp. Rotate and balance four tires. Clean and adjust rear brakes. Repaired tailgate to open and close properly.replace broken clip to extension rod.to latch(right side) Hours 6.00 Hours 6.00 Labor: 165.00 Parts: 0.00 Parts: 0.00 Parts: 05/16/2018 Closed: 05/30/20 Parts List Used Fire X Refurbished Napagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 Problem: DEAD BATTERY Test starting and charging system.test and replace bad battery. Parts List Battery				tem and four	nd ignition						
Workorder: 1805063 Meter: 71120 In Date: 05/16/2018 Closed: 05/30/20 Problem: PM Service. - Pm Service Replace taglamp assembly in right side of bumper also replace left reverse lamp Rotate and balance four tires Clean and adjust rear brakes Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Bin Date: 05/16/2018 Closed: 05/30/20 In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery		ering colum co	vers and r	eset ignition s	switch						
Problem: PM Service. - Pm Service. - Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 - Hours 6.00 - Test starting and charging system.test and replace bad battery. Parts List Used Fire X Refurbished Napagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp 360.00 Parts: 74.48 Total: 434.48 Parts List Battery		Hour	s 2.75		Labor:	165.00	Parts:	0.00	Total:	165.00	
- Replace taglamp assembly in right side of bumper also replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) - Hours 6.00 - Test starting and charging system.test and replace bat battery. - Test starting and charging system.test and replace bad battery. - Repaired tailgate to open and close properly replace Washer Fluid Concentr - Boxed Miniatures - Tag Lamp - In Date: 08/17/2018 Closed: 09/18/20 - Parts List - Battery			Meter:	71120			In Date:	05/16/2018	Closed:	05/30/2018	8
replace left reverse lamp. - Rotate and balance four tires. - Clean and adjust rear brakes. - Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 - Test starting and charging system.test and replace bat battery. Napagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp 360.00 Parts: 74.48 Total: 434.48 In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery	- Pm Service.					Parts Lis	st			(Qty
- Rotate and balance four tires Clean and adjust rear brakes Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 - Hours 6.00 - Labor: Workorder: 1808486 - Meter: 71440 - Test starting and charging system.test and replace bat battery. Nayagold Oil Filter 10w30 Bulk Sr 22" Wiper Blade Washer Fluid Concentr Boxed Miniatures Tag Lamp 360.00 - Parts: 74.48 - Total: 434.48 In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery			in right si	de of bumper	also	Used Fire	e X Refurb	ished		1	.00
- Clean and adjust rear brakes Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Hours 6.00 Eabor: 360.00 Parts: 74.48 Workorder: 1808486 Problem: DEAD BATTERY In Date: 08/17/2018 Parts List Battery	•	•				Napagolo	d Oil Filter			1	.00
- Repaired tailgate to open and close properly replace broken clip to extension rod.to latch(right side) Hours 6.00 Hours 6.00 Boxed Miniatures Tag Lamp Hours 6.00 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Problem: DEAD BATTERY Parts List Battery						10w30 B	ulk Sr			6	00.6
broken clip to extension rod.to latch(right side) Boxed Miniatures Tag Lamp Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Parts List Battery		•				22" Wipe	r Blade			2	2.00
Boxed Miniatures Tag Lamp Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Boxed Miniatures Tag Lamp In Date: 08/17/2018 Closed: 09/18/20 Parts List Battery					ice	Washer I	Fluid Conc	entr		1	.00
Hours 6.00 Labor: 360.00 Parts: 74.48 Total: 434.48 Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Parts List Battery	broken clip to	extension rod.t	o laten(rigi	nt side)		Boxed M	iniatures			1	.00
: Workorder: 1808486 Meter: 71440 In Date: 08/17/2018 Closed: 09/18/20 Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Parts List Battery						Tag Lam	р			1	.00
Problem: DEAD BATTERY - Test starting and charging system.test and replace bad battery. Parts List Battery		Hour	s 6.00		Labor:	360.00	Parts:	74.48	Total:	434.48	
battery. Battery				71440			In Date:	08/17/2018	Closed:	09/18/2018	8
Battery		and charging	system.tes	st and replace	e bad	Parts Lis	st			(Qty
Hours 0.75 Labor: 45.00 Parts: 114.42 Total: 159.42	battery.					Battery				1	.00
		Hour	s 0.75		Labor:	45.00	Parts:	114.42	Total:	159.42	

Workorder: 181290 Problem: PM Se		72167 inop.		In Date:	12/19/2018	Closed:	12/27/2	018
- Pm Service.			Parts Li	st				Qty
- Installed 12 volt pow		g to fuse	Napago	ld Oil Filter				1.00
oox.installed 30 amp f			10w30 E	Bulk Sr				6.00
- Rotate and balance	·		Washer	Fluid Conc	entr			1.00
- Service rear drum b		22" Wipe	er Blade				2.00	
 Vacume debris from 	air cowl and engi	ne compartment.	Atc-30 F	use				5.00
			Fuse Ho	older				1.00
			12v Pow	ver Socket				1.00
	Hours 6.50	Lab	or: 435.50	Parts:	52.38	Total:	487.88	
Workorder: 190655 Problem: PM Se		74280 air.		In Date:	06/21/2019	Closed:	07/08/2	019
- Pm Service.			Parts Li	st				Qty
- Replace ac blend do	or actuator for dri	ver side mode.	10w30 N	Motor Oil				6.00
- Replaceboth side br	ake lamp bulbs ar	Napago	ld Oil Filter				1.00	
amp bracket assembl	у.	22" Wipe	er Blade			2.00		
 Replace burnt out 12 	2volt power outlet.		Washer	Fluid Conc			1.00	
- Rear brake service.			Napago	Napagold Air Filter				
 Lube both window tr 	•	down)	Actuator	r				1.00
 Vacume debris from 	air cowl.		Boxed N	/liniatures				2.00
			Pwr Out	·I				1.00
			Napa 10)w30 Qt				6.00
	Hours 9.25	Lab	or: 619.75	Parts:	212.01	Total:	831.76	
Workorder: 190857 Problem: R/REA		74879		In Date:	08/15/2019	Closed:	08/19/2	019
- Repair right rear tire								
	Hours 1.00	Lab	or: 67.00	Parts:	0.00	Total:	67.00	
Norkorder: 191153 Problem: R/SIDE		75605 INOP.		In Date:	11/06/2019	Closed:	11/13/2	019
- Repair lights.			Parts Li	st				Qty
- F 9				/liniatures				2.00
			Bulb					2.0

Workorder: 1912724 Problem: PM Service	Meter:	76200			In Date:	12/12/2019	Closed:	12/26/2019
- Pm Service.				Parts Li	st			Qty
- Service rear brakes.				10w30 E	Bulk Sr			6.00
- Repair left front marker light				Napago	ld Oil Filter			1.00
- Replace four tires.				Washer	Fluid Conc	entr		1.00
				22" Wip	er Blade			2.00
				Used Fi	re X Refurb	ished		1.00
				Non-chl	or Brake Cli	nr		1.00
				Boxed N	/liniatures			2.00
				245/70/	17 Tire Mich	1		4.00
				Tire Dis	posal Fee			4.00
Hours	5.50		Labor:	401.50	Parts:	989.36	Total:	1,390.86
Workorder: 2005479 Problem: PM Service.	Meter:	78640			In Date:	06/01/2020	Closed:	06/09/2020
- Pm Service.				Parts Li	st			Qty
- Rear brake service.				Napago	ld Oil Filter			1.00
- Repaired right rear tire.				10w30 E	Bulk Sr			6.00
- Rotate and balance 4 tires				22" Wip	er Blade			2.00
- Reattached tailgate bed line	r and ser	vice tool box.						
Hours :	5.75		Labor:	419.75	Parts:	28.05	Total:	447.80
Workorder: 2011362	Meter:	79965			In Date:	11/12/2020	Closed:	11/12/2020
Problem: Transition Prep	Charge							
Problem: Transition Prep - Transition Prep Charge	Charge							