		10178912	2009	FORD F150	пскир,	1/2 TON, W	/TOW PKg			
Workorder: Problem:	938923 PRE-DELIVE	Meter: RY INSPE	0 CTION			In Date:	06/11/2009	Closed:	06/11/20	009
- Pre-delivery	Inspection									
	Hou :	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	944782 pm service al	Meter: so tire pres	5016 sure warni	ng light on		In Date:	10/20/2009	Closed:	10/23/20	009
- P.m service.					Parts Li	st				Qty
- Shop Suppli	es				Shop Su	upplies				1.00
					1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
					5w20 Er	ngine Oil				7.00
	Hou	rs 2.00		Labor:	120.00	Parts:	17.85	Total:	137.85	
Workorder: Problem:	1004217 cut & progran	Meter: n key	11530			In Date:	04/23/2010	Closed:	04/29/20	010
- cut key blan	k and program	and test o	k		Parts Li	st				Qty
- Shop Suppli	es				164-r04	75 Ign Key 2	2010-earlier (d	don't Reorde	er)	1.00
					Shop Su	upplies				1.00
	Hour	rs 1.00		Labor:	60.00	Parts:	23.45	Total:	83.45	
Workorder: Problem:	1004219 P.M service.	Meter:	11530			In Date:	04/23/2010	Closed:	04/27/20	010
- P.m service.					Parts Li	st				Qty
- Rotate & bal	ance all four ti	res.			Shop Su	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
					Ca1026	2 Air Filter N	Mtc Fa1883 W	′ix 49883		1.00
					5w20 Er	ngine Oil				7.00
					31-22 W	/iper Blades	22" Wiper Bla	ade		2.00
	Hour	rs 3.00		Labor:	180.00	Parts:	31.91	Total:	211.91	
Workorder: Problem:	1007754 Right rear tire	Meter:	14615			In Date:	07/21/2010	Closed:	07/21/20	010
- Repair and b	balance right re	ear tire.			Parts Li	st				Qty
-	-									-
 Shop Suppli 	es				Shop Su	ipplies				1.00

 Perform pm service. Rotate and balance all four tires. Shop Supplies Shop Supplies Shop Supplies Shop Supplies 1372 OII Filter Frm Ph2 Wix 51372 5w20 Engine Oil Used Firex Refurbed Fire Extingshers Nb-19 Wiper Blades 19" Anco 31-19 Hours 3.00 Labor: 180.00 Parts: 42.16 Total: 222.16 i Workorder: 1012918 Meter: 17998 Problem: flash canceiver spot #220 Flash Canceiver install updated screws Shop Supplies Hours 1.00 Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 i Workorder: 1107317 Meter: 23882 Problem: Pm service Perform pm service. Install four new tires.nitrogen fill and balance all four. Computer diagnose for abs warning light on test and replace failed right rear wheel speed sensor with new.clear codes with 1.d.s. scan tool and road test. Perform wheel algnemt complete. Shop Supplies Shop Supplies Shop Supplies Stop Supplies Computer failes 22" Wiper Blades 22" Wiper Blade 183783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.5 i Workorder: 1108326 Meter: 23882 Problem: damage to rgt door - damage to rgt door - damage to rgt door - damage to rgt door 	Workorder: Problem:	1012710 P.M. ser		Meter:	17989 ver.			In Date:	11/15/2010	Closed:	11/19/20	010
 Rotate and balance all four tires. Shop Supplies Flash Canceiver spot #220 Flash Canceiver install updated screws Shop Supplies Hours 1.00 Labor: Shop Supplies Shop Supplies Shop Supplies Shop Supplies Perform m service. Perform wheel alignment complete. Shop Supplies Hours 9.25 Labor: Shop Supplies<!--</td--><td></td><td></td><td></td><td></td><td></td><td></td><td>Parte I i</td><td>st</td><td></td><td></td><td></td><td>Qty</td>							Parte I i	st				Qty
 Shop Supplies Shop Supplies Hours 3.00 Labor: 1900 Parts: List Shop Supplies Hours 1.00 Labor: Shop Supplies Hours 1.00 Labor: Shop Supplies Shop Supplies Hours 1.01 Labor: Morkorder: 11072/210 Closed: 11/227 Problem: Flash Canceiver install updated screws Shop Supplies Shop Supplies Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 2.00 2.00<td>-</td><td></td><td>ll four t</td><td>iros</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>1.00</td>	-		ll four t	iros								1.00
Sw20 Engine Oil Used Firex Refurbed Fire Extingshers Nb-19 Hours 3.00 Labor: 180.00 Parts: 42.16 Total: 222.16 Workorder: 1012918 Meter: 17998 Problem: ftah canceiver spot Hours 1.00 Labor: Or/12/2011 Closed: Offworder: 11/19/2010 Computer diagnose for abs warning light on test and replace failed right rear wheel speed sensor with new.clear odes with Lds. scan tool and road test. Perform wheel alignment complete. Shop Supplies Parts Refurbed Fire Extingshers 31-22 Yuipe Blades 22* Wiper Blades 22* Wiper Blade 183783418 Problem: Meter: 2382 In Date: Or/21/2011 Closed: Optione of amage to rgt door - Hours 9.25 Labor: 555.00 Hours 0.00 Labor:			ii ioui t	1103.			•	••	Dh2 Wiv 51	370		1.00
Used Firex Refurbed Fire Extingshers Nb-19 Wiper Blades 19" Anco 31-19 Fooler: 1012918 Meter: 17998 Parts: 42.16 Total: 222.16 im Date: 11/19/2010 Closed: 11/22/2 Problem: flash canceiver spot #220 - Flash Canceiver install updated screws Parts List Shop Supplies Foot Supplies Shop Supplies Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 im Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service Parts List Shop Supplies Shop Supplies Compared fill and balance all four. - Computer diagnose for abs warning 1ight on test and replace failed right rear wheel speed sensor with new.clear codes with Ld.s. scan tool and road test. - Perform theel alignment complete. - Perform wheel alignment complete. - Shop Supplies Shop Supplies State Value Firex Refurbed Fire Extingshers - Shop Supplies State Value Firex Refurbed Fire Extingshers - Shop Supplies State Value Value St	- Shop Suppli	65								572		7.00
Nb-19 Wiper Blades 19" Anco 31-19 222.16 Workorder: 1012918 Meter: 17998 In Date: 11/19/2010 Closed: 11/22/2 Problem: flash canceiver spot #220 - Flash Canceiver install updated screws Parts 11/19/2010 Closed: 11/22/2 - Flash Canceiver install updated screws - Shop Supplies Shop Supplies Shop Supplies - 60.00 Parts: 2.00 Total: 62.00 Workorder: 11/07317 Meter: 23882 In Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service. - Parts List Shop Supplies 1372 OII Filter Frm Ph2 Vix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Right Rear Wheel Speed Sensor Sw20 Engine Oi Used Firex Refurbed Fire Extingshers 31-22 Wiper Blades 22" Wiper Blade 13837/017 Wrangler Sr-a XI Trie Disposal Fee Portor Hours 9.25 Labor: 555.00 Parts: 0.00 Total: 0.00 Workorder: 11/08326 Meter: 2382 In Date: 07/21/2011 Closed: 0.00 - f								•	d Eiro Extingo	bore		1.00
Hours 3.00Labor:180.00Parts:42.16Total:222.16Workorder:1012918Meter:17998In Date:11/19/2010Closed:11/22/2Problem:flash canceiver spot #220-Flash Canceiver install updated screwsParts List-11/19/2010Closed:11/22/2- Flash Canceiver install updated screwsParts ListShop SuppliesShop Supplies-07/12/2011Closed:07/22/2- Flash Canceiver install updated screwsHours 1.00Labor:60.00Parts:2.00Total:62.00Workorder:1107317Meter:23882In Date:07/12/2011Closed:07/22/2Problem:Pm service-Canues of mass warming light on.test and replace failed right rear wheel speed sensor with new.clear codes with 1.d.s. scan tool and road testParts ListShop Supplies Perform wheel alignment complete Shop Supplies-Canues 22" Wiper Blade 13783418Flas783418Pa32/70/17Wita 49883 Shop Supplies <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0</td> <td></td> <td></td> <td>2.00</td>									0			2.00
i Workorder: 1012918 Meter: 17998 In Date: 11/19/2010 Closed: 11/22/2 Problem: flash canceiver spot #220 - Flash Canceiver install updated screws Parts List Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Control is 60.00 Parts: 2.00 Total: 62.00 Workorder: 1107317 Meter: 23882 In Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service Parts List Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Shop Supplies Control is 07/12/2011 Closed: 07/22/2 Problem: Pm service Parts List Shop Supplies Shop Supplies Shop Supplies Shop Supplies Carlos Advantage to replace failed right rear wheel speed Sensor with new.clear codes with Ld.s. scan tool and road test. - Perform wheel alignment complete. - Shop Supplies Carlos Carlo				2.00		Lohow					000.40	2.00
Problem: flash canceiver install updated screws Parts List - Flash Canceiver install updated screws Shop Supplies Shop Supplies - Shop Supplies Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Workorder: 1107317 Meter: 23882 In Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service Parts List Shop Supplies 07/12/2011 Closed: 07/22/2 - Perform pm service. - Install four new tires.nitrogen fill and balance all four. Shop Supplies Shop Supplies 1372 OI Filter Frm Ph2 Vix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 AWA 9883 - Perform wheel alignment complete. - Perform wheel alignment complete. Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 1373.01 Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 1373.01 Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 1373.01 Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 1373.01 Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 1373.01 Used Firex Refurbed Fire Extingshers 0.00<			Hours :	3.00		Labor:	180.00	Parts:	42.16	i otai:	222.16	
Shop Supplies Hours 1.00 Labor: Shop Supplies Total: 62.00 Workorder: 1107317 Meter: 23882 In Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service Perform pm service. Parts List Shop Supplies 07/12/2011 Closed: 07/22/2 - Derform pm service. - Install four new tires.nitrogen fill and balance all four. Shop Supplies 1372 Oil Filter Fm Ph2 Wix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Right Rear Wheel Speed Sensor Swop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Right Rear Wheel Speed Sensor Swop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Right Rear Wheel Speed Sensor Swop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Right Rear Wheel Speed Sensor Swop Supplies 31-22 Wiper Blades 22" Wiper Blade 133783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Notal: 1,303.5 Workorder: 1108326 Meter: 23882 In Date:								In Date:	11/19/2010	Closed:	11/22/20	010
Hours 1.00Labor:60.00Parts:2.00Total:62.00Workorder:1107317Meter:23882In Date:07/12/2011Closed:07/22/2Problem:Pm serviceParts ListShop Supplies1372Closed:07/22/2- Install four new tires.nitrogen fill and balance all four.Shop Supplies1372Closed:07/22/2- Computer diagnose for abs warning light on.test and replace failed right rear wheel speed sensor with new.clear codes with I.d.s. scan tool and road test.1372Oil Filter Frm Ph2Wix 51372- Perform wheel alignment complete Perform wheel alignment complete.Shop Supplies1372Oil Filter Mtc Fa1883Wix 49883- Shop Supplies- Meter:23882Near Wheel Speed Sensor5w20 Engine OilUsed Fire Refurbed Fire Extingshers- Shop Supplies- Meter:23882In Date:07/21/2011Closed:08/08/2Workorder:1108326Meter:23882In Date:07/21/2011Closed:08/08/2Problem:damage to rgt door- Meter:25515In Date:0.00Total:0.00- damage to rgt door- Meter:25515In Date:02/22/2012Closed:03/06/2- Porlorm m service Total:1.300Eabor:5 Nop Supplies137201/22/201/22/2- Perform pm service Total:0.00Eabor:0.00Total:0.000.00- Admage to rgt door- Meter:25515In Date:02/2	- Flash Cance	eiver insta	ll upda	ted screv	/S		Parts Li	st				Qty
Workorder: 1107317 Problem: Meter: 23882 In Date: 07/12/2011 Closed: 07/22/2 Problem: Pm service Parts List Shop Supplies Parts List Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 Ca10262 Air Filter Mtc Fa1883 Wix 49883 Cades with I.d.s. scan tool and road test. Perform wheel alignment complete. Shop Supplies Sw20 Engine Oil Used Firex Refurbed Fire Extingshers Shop Supplies Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.5 Workorder: 1108326 Meter: 23882 In Date: 07/21/2011 Closed: 08/08/2 Problem: damage to rgt door Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 1,303.5 Workorder: 1201714 Meter: 25515 In Date: 07/21/2011 Closed: 03/06/2 Problem: P. Service. Parts 0.00 Parts: 0.00 Total: 0.00 Problem: P. Service. Problem: Parts 0.00 Total: 0.00 Problem: P. Service. In	- Shop Suppli	es					Shop Su	pplies				1.00
Problem: Pm service - Perform pm service. - Install four new tires.nitrogen fill and balance all four. - Computer diagnose for abs warning light on.test and replace failed right rear wheel speed sensor with new.clear codes with I.d.s. scan tool and road test. - Perform wheel alignment complete. - Perform wheel alignment complete. - Shop Supplies Shop Supplies - Mours 9.25 - Hours 9.25 - Hours 9.25 - Hours 0.00 - Problem: damage to rgt door - damage to rgt door - Perform pm service. - Shop Supplies			Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
 Install four new tires.nitrogen fill and balance all four. Computer diagnose for abs warning light on.test and replace failed right rear wheel speed sensor with new.clear codes with 1.d.s. scan tool and road test. Perform wheel alignment complete. Shop Supplies Hours 9.25 Labor: Stop Supplies Morkorder: 108326 Meter: 23882 In Date: 0.7/21/2011 Closed: 0.00 Parts: 0.00 Total: 0.00 In Date: 0.2/22/2012 Closed: 0.3/06/2 Shop Supplies In Date: 0.2/22/2012 Closed: 0.3/06/2 Closed: 0				Meter:	23882			In Date:	07/12/2011	Closed:	07/22/20	011
 Install four new tires nitrogen fill and balance all four. Computer diagnose for abs warning light on test and replace failed right rear wheel speed sensor with new.clear codes with 1.d.s. scan tool and road test. Perform wheel alignment complete. Shop Supplies Shop Supplies Hours 9.25 Hours 9.25 Labor: Stange to rgt door Hours 0.00 Labor: One function of the pressure light on. Perform pm service. Perform pm service. Perform pm service. Perform pm service. Shop Supplies Shop Supplies Shop Supplies Morkorder: 1201714 Meter: 25515 Problem: P.M. service and tire pressure light on. Perform pm service. Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new, Rotate and balance all four tires. Shop Supplies 	- Perform pm	service.					Parts Li	st				Qty
replace failed right rear wheel speed sensor with new.clear codes with I.d.s. scan tool and road test. - Perform wheel alignment complete. - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Hours 9.25 - Hours 9.25 - Hours 0.00 - damage to rgt door - damage to rgt door - damage to rgt door - damage to rgt door - Perform pm service. - Rotate and balance all four tires. - Shop Supplies -	- Install four n	ew tires.n	itroger	n fill and b	alance all fou	r.	Shop Su		1.00			
codes with 1.d.s. scan tool and road test. - Perform wheel alignment complete. - Right Rear Wheel Speed Sensor - Shop Supplies Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 31-22 Wiper Blades 22" Wiper Blade 183783418 P235/7017 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: Hours 9.25 Labor: 555.00 Problem: damage to rgt door - damage to rgt door Hours 0.00 Labor: 0.00 Parts 0.00 Problem: Parts Perform pm service. Parts List - Perform pm service. Parts List - Rotate and balance all four tires. Shop Supplies	- Computer di	agnose fo	or abs v	warning li	ght on.test an	d	1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
 Perform wheel alignment complete. Shop Supplies Shop Supplies Shop Supplies Shop Supplies Right Rear Wheel Speed Sensor Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 31-22 Wiper Blade 183783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: S55.00 Parts: 748.53 Total: 1,303.5 Problem: damage to rgt door Morkorder: 1201714 Meter: 25515 In Date: 0.00 Total: 0.00 0.00 Parts List Shop Supplies In Date: Shop Supplies 	replace failed	right rear	wheel	speed se	nsor with new		Ca1026	2 Air Filter I	Mtc Fa1883 W	/ix 49883		1.00
 Perform wheel alignment complete. Shop Supplies Shop Supplies Sw20 Engine Oil Used Firex Refurbed Fire Extingshers 31-22 Wiper Blades 22" Wiper Blade 183783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.5 Workorder: 1108326 Meter: 23882 In Date: 07/21/2011 Closed: 08/08/2 Problem: damage to rgt door damage to rgt door Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Total: 0.00 In Date: 02/22/2012 Closed: 03/06/2 Problem: P.M. service and tire pressure light on. Perform pm service. Parts List Shop Supplies Shop Supplies Used Firex Refurbed Fire Extingshers 							Right Re	ear Wheel S	Speed Sensor			1.00
Used Firex Returbed Fire Extingshers 31-22 Wiper Blade 183783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.5 Workorder: 1108326 Meter: 23882 In Date: 07/21/2011 Closed: 08/08/2 Problem: damage to rgt door - damage to rgt d			ent coi	mplete.								7.00
31-22 Wiper Blades 22" Wiper Blade 31-22 Wiper Blades 22" Wiper Blade 183783418 P235/70r17 Wrangler Sr-a XI Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.5 Workorder: 1108326 Meter: 23882 In Date: 07/21/2011 Closed: 08/08/2 Problem: damage to rgt door - - - 0.00 Parts: 0.00 Total: 0.00 - damage to rgt door - - - 0.00 Parts: 0.00 Total: 0.00 - damage to rgt door - - - - 0.00 Total: 0.00 - damage to rgt door - - - - - 0.00 Total: 0.00 - damage to rgt door - - - - - 0.00 Total: 0.00 - damage to rgt door - - - - - - - - - - - - - <td< td=""><td>- Shop Suppli</td><td>es</td><td></td><td></td><td></td><td></td><td>Used Fi</td><td>ex Refurbe</td><td>ed Fire Extings</td><td>hers</td><td></td><td>1.00</td></td<>	- Shop Suppli	es					Used Fi	ex Refurbe	ed Fire Extings	hers		1.00
Tire Disposal Fee Hours 9.25 Labor: 555.00 Parts: 748.53 Total: 1,303.55 Workorder: 1108326 Meter: 23882 In Date: 07/21/2011 Closed: 08/08/2 Problem: damage to rgt door - In Date: 07/21/2011 Closed: 08/08/2 - damage to rgt door - Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 - damage to rgt door - Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 - damage to rgt door - Problem: 0.00 Total: 0.00 Closed: 0.00 0.00 - damage to rgt door - In Date: 0.2/22/2012 Closed: 0.3/06/2 Workorder: 1201714 Meter: 25515 In Date: 02/22/2012 Closed: 0.3/06/2 Problem: P.M. service and tire pressure light on. Parts List Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 Sw20 Engine Oil Sw20 Engine Oil Sw20 Engine Oil Used Fire Extingshers							31-22 W	iper Blades	s 22" Wiper Bla	ade		2.00
Hours 9.25Labor:555.00Parts:748.53Total:1,303.5Workorder:1108326Meter:23882In Date:07/21/2011Closed:08/08/2Problem:damage to rgt door-In Date:07/21/2011Closed:08/08/2- damage to rgt doorHours 0.00Labor:0.00Parts:0.00Total:0.00Workorder:1201714Meter:25515In Date:02/22/2012Closed:03/06/2Workorder:1201714Meter:25515In Date:02/22/2012Closed:03/06/2Perform pm service.Parts ListShop SuppliesShop Supplies1372Oil FilterFrm Ph2Wix 51372Sw20 Engine Oil- Rotate and balance all four tires.Shop SuppliesUsed Firex Refurbed Fire ExtingshersUsed Fire Refurbed Fire ExtingshersIn Date:In							183783418 P235/70r17 Wrangler Sr-a XI					4.00 4.00
Problem: damage to rgt door - damage to rgt door Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 : Workorder: 1201714 Meter: 25515 In Date: 02/22/2012 Closed: 03/06/2 Problem: P.M. service and tire pressure light on. Parts List Shop Supplies Shop Supplies - Perform pm service. Parts List Shop Supplies Shop Supplies - Rotate and balance all four tires. 5w20 Engine Oil Sw20 Engine Oil - Shop Supplies Used Firex Refurbed Fire Extingshers			Hours	9.25		Labor:			748.53	Total:	1,303.53	
Problem: damage to rgt door - damage to rgt door Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 : Workorder: 1201714 Meter: 25515 In Date: 02/22/2012 Closed: 03/06/2 Problem: P.M. service and tire pressure light on. Parts List Shop Supplies 3/22 Oil Filter Frm Ph2 Wix 51372 - Rotate and balance all four tires. Shop Supplies Sw20 Engine Oil Sw20 Engine Oil - Shop Supplies Used Firex Refurbed Fire Extingshers Store Extingshers			:									
Hours 0.00Labor:0.00Parts:0.00Total:0.00Workorder:1201714Meter:25515In Date:02/22/2012Closed:03/06/2Problem:P.M. service and tire pressure light on.Parts ListShop SuppliesShop SuppliesShop Supplies1372Oil Filter Frm Ph2 Wix 51372- Rotate and balance all four tires Shop SuppliesUsed Firex Refurbed Fire ExtingshersSupplies					23882			In Date:	07/21/2011	Closed:	08/08/20)11
Hours 0.00Labor:0.00Parts:0.00Total:0.00Workorder:1201714Meter:25515In Date:02/22/2012Closed:03/06/2Problem:P.M. service and tire pressure light on.Parts ListShop SuppliesShop SuppliesShop Supplies1372Oil Filter Frm Ph2 Wix 51372- Rotate and balance all four tires Shop SuppliesUsed Firex Refurbed Fire ExtingshersSupplies	- damage to r	at door										
Problem:P.M. service and tire pressure light on Perform pm service Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new, - Rotate and balance all four tires Rotate and balance all four tires Shop Supplies- Shop Supplies- Shop Supplies- Used Firex Refurbed Fire Extingshers	0	-	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
 Perform pm service. Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new, Rotate and balance all four tires. Shop Supplies Parts List Shop Supplies Used Firex Refurbed Fire Extingshers 	Workorder:	1201714		Meter:	25515			In Date:	02/22/2012	Closed:	03/06/20	012
 Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new, Rotate and balance all four tires. Shop Supplies Shop Supplies Shop Supplies 	Problem:	P.M. ser	vice an	nd tire pre	ssure light on							
after recharge.replace failed battery with new,1372 Oil Filter Frm Ph2 Wix 51372- Rotate and balance all four tires.5w20 Engine Oil- Shop SuppliesUsed Firex Refurbed Fire Extingshers	- Perform pm	service.					Parts Li	st				Qty
 Rotate and balance all four tires. Shop Supplies Shop Supplies<!--</td--><td></td><td></td><td></td><td></td><td></td><td>dtest</td><td>Shop Su</td><td>pplies</td><td></td><td></td><td></td><td>1.00</td>						dtest	Shop Su	pplies				1.00
- Shop Supplies Used Firex Refurbed Fire Extingshers	-			•	n new,		1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
Used The Artebubed The Extingations			II four t	ires.			5w20 Er	ngine Oil				7.00
7090blk Frt Floor Mats (rubber Queen)	- Shop Suppli	es					Used Fi	ex Refurbe	ed Fire Extings	hers		1.00
							7090blk	Frt Floor M	lats (rubber Q	ueen)		1.00
Group 59 Battery (mtc Bxt 59)							Group 5	9 Battery (r	ntc Bxt 59)			1.00
Hours 4.00 Labor: 240.00 Parts: 182.26 Total: 422.26			Hours	4.00		Labor:	240.00	Parts:	182.26	Total:	422.26	

Workorder: Problem:	1209112 P.M. service	Meter: and detail.	27075			In Date:	09/24/2012	Closed:	09/28/20	12
- P.m. Service	Э.				Parts L	ist				Qty
- Rotate and	balance all tire	es.			Shop Si	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	n Ph2 Wix 513	372		1.00
					5w20 E	ngine Oil				7.00
	Hou :	ırs 3.00		Labor:	180.00	Parts:	22.28	Total:	202.28	
Workorder: Problem:	1209303 1 - Detail Vel	Meter: hicle Wash	27075 Ticket(s) Issu	led		In Date:	09/28/2012	Closed:	09/28/20	12
- 1 - Detail Ve	hicle Wash Ti	cket(s) Issu	ied							
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1302933 P.M. service	Meter: and brakes	28339 feel spongy.			In Date:	03/26/2013	Closed:	04/03/20	13
- Perform pm	service.				Parts L	ist				Qty
- Computer d					5w20 E		7.00			
wheel brakes. scan tool and		nated bleed	hydraulic sy	stem with	1372 Oi	il Filter				1.00
- Rotate and I		ur tires.			31-20 V	Viper Blades	s 20			2.00
- Shop Suppli					Washer					1.00
						rex Refurbe	-			1.00
						enetrant Lub				1.00
						Viper Blades				2.00
					-	eel Cov - Fo	ord			1.00
					Shop Si	••				1.00
	Hou :	ırs 4.00		Labor:	240.00	Parts:	108.94	Total:	348.94	
Workorder: Problem:	1312249 Pm service a	Meter: and request	29983 for detail veh	nicle.		In Date:	12/09/2013	Closed:	12/13/20	13
- Perform pm	service.				Parts L	ist				Qty
- Rotate and I	balance all fou	ır tires.			5w20 E	ngine Oil				7.00
- Shop Suppli	es				Napago	ld Oil Filter				1.00
					Wiper B	Blade				2.00
					Shop Si	upplies				1.00
	Hou :	ırs 3.00		Labor:	180.00	Parts:	32.38	Total:	212.38	
Workorder: Problem:	1312381 1 - Detail Vel	Meter: hicle Wash	29829 Ticket(s) Issu	bed		In Date:	12/12/2013	Closed:	12/12/20	13
- 1 - Detail Ve	hicle Wash Ti	cket(s) Issu	ied							
		ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
	•									

Workorder: Problem:	1407377 P.M. Service	Meter: e.Detail.	32600			In Date:	07/28/2014	Closed:	08/07/20	014
- Perform pm	service.				Parts Li	st				Qty
- Inspect and		driver seat	trim with new		5w20 Er			7.00		
- Rotate and b	calance all for	ur tires.			Napago	ld Oil Filter				1.00
- Pinpoint test	t for left front :	strobe lamp	inop.fabricate	and	Wiper B	lade				2.00
repair broken wiring harness.						Used Fire X Refurbished				
- Shop Suppli	es				Washer	Fluid Conce	entr			1.00
					Housing					1.00
		Shop Su			1.00					
	Ηοι :	urs 4.25		Labor:	255.00	Parts:	147.67	Total:	402.67	
Workorder: Problem:	1407896 1 - Detail Ve	Meter: hicle Wash	32600 Ticket(s) Issu	ed		In Date:	08/11/2014	Closed:	08/11/20	014
- 1 - Detail Ve	hicle Wash T	icket(s) Issu	ed							
	Ηοι	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1409808 Tow in,dead	Meter: battery.	32816			In Date:	09/30/2014	Closed:	10/03/20	014
- Test battery	and charging	system.bat	tery failed loa	d	Parts Li	st				Qty
test.replace de	efective batter	у.			Battery					1.00
- Shop Suppli	es				Shop Su		1.00			
	Ηοι :	urs 1.00		Labor:	60.00	Parts:	121.61	Total:	181.61	
Workorder: Problem:	1409824 wont start	Meter:	32703			In Date:	09/30/2014	Closed:	09/30/20	014
- Tow From: V	Nud #8, Jog &	& Belvedere	To: vista							
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1501264 Pm service.	Meter:	33435			In Date:	02/03/2015	Closed:	02/19/20	015
- Pm service.					Parts Li	st				Qty
- FIII Service.	replace both	defective lea	aking rear sho	ock	5w20 Er	ngine Oil				7.00
- Inspect and	absorbers.									1.00
- Inspect and absorbers.			- Rotate and balance all four tires.							2.00
 Inspect and absorbers. Rotate and b 		ur tires.			Wiper B	lade	Mac Wite Lithium Gres			
- Inspect and absorbers.		ur tires.			-		res			1.00
 Inspect and absorbers. Rotate and b 		ur tires.			Mac Wit					
 Inspect and absorbers. Rotate and b 		ur tires.			Mac Wit Mac Bat	e Lithium G				1.00 1.00 2.00
 Inspect and absorbers. Rotate and b 		ur tires.			Mac Wit Mac Bat	e Lithium G tery Protect ruck Shock				1.00

Workorder: Problem:	1509079 Pm servio	Meter ce.Right kick	: 35160 panel.Repair ri	ight side b	ody dama	In Date: age and rea	09/10/2015 r bumper.Deta	Closed: ail.	09/30/20)15
- Pm service.					Parts Li	st				Qty
- Perform tran	smission f	lush service			Seat R /	And R				1.00
		er seat for rep	pairing torn viny	yl and	5w20 Er	7.00				
replace after re	•				Napago	d Oil Filter			1.00 1.00	
- Replace bro panel trim.	ken rear b	umper cover	and realign rig	jht kick	Napago	d Air Filter				
- Rotate and b	four tires		Wiper B	lade			2.00	2.00		
- Shop Suppli					Used Fi	e X Refurbi	shed			1.00
	00				Wd40 1	Soz				1.00
					Syn-atf	Trans Fluid	S			14.00
						mper Cover				1.00
					Shop Su	ipplies				1.00
	 :	Hours 6.50		Labor:	390.00	Parts:	645.29	Total:	1,035.29)
Workorder: Problem:	1511624 damage t	Meter o rgt side, ca				In Date:	09/29/2015	Closed:	11/13/20)15
- damage to r	gt side, ca	b & door								
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1605166 P.M. serv	Meter	: 36416 e on accel and	tire pressu	re light o	In Date: n.	05/18/2016	Closed:	05/27/20)16
- P.m. Service	Э.				Parts Li	st				Qty
- Pressure tes		ect cooling s	systemflush and	d refill		st ngine Oil				Qty 7.00
- Pressure tes system.	st and insp	-	-		5w20 Er Napago	ngine Oil Id Oil Filter				-
 Pressure tes system. Replace defe 	st and insp ective left	front tire pres	ssures sensor,r		5w20 Er Napago 22" Wip	ngine Oil Id Oil Filter er Blade				7.00 1.00 2.00
- Pressure tes system. - Replace def balance all fou	at and insp ective left ir tires.repi	front tire prea rogram sens	ssures sensor,r or.		5w20 Er Napago 22" Wip Peak Gl	ngine Oil Id Oil Filter er Blade obal				7.00 1.00
 Pressure test system. Replace definition Balance all four - Test and replace 	st and insp ective left f ir tires.rep place inop	front tire prea rogram sens	ssures sensor,r or.		5w20 Er Napago 22" Wip Peak Gl Tpms12	ngine Oil ld Oil Filter er Blade obal Sensor Tire	e Pr			7.00 1.00 2.00
- Pressure tes system. - Replace def balance all fou	st and insp ective left f ir tires.rep place inop	front tire prea rogram sens	ssures sensor,r or.		5w20 Er Napago 22" Wip Peak Gl	ngine Oil ld Oil Filter er Blade obal Sensor Tire	e Pr			7.00 1.00 2.00 2.00
 Pressure test system. Replace definition Balance all four - Test and replace 	ective left ective left ir tires.rep place inop es	front tire prea rogram sens	ssures sensor,r or.	rotate and	5w20 Er Napago 22" Wip Peak Gl Tpms12	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies	e Pr 145.60	Total:	565.60	7.00 1.00 2.00 2.00 1.00
 Pressure test system. Replace defubalance all four Test and replication of the system of the system. Shop Supplication Workorder: 	et and insp ective left ir tires.rep blace inop es I 1608472	front tire prea rogram sens left front stro	ssures sensor,r or. be light.	rotate and	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies		Total: Closed:	565.60 08/30/20	7.00 1.00 2.00 2.00 1.00 1.00
 Pressure tess system. Replace defibalance all four Test and rep Shop Suppli Workorder: Problem:	ective left f ir tires.repi blace inop es 1608472 Tow in,de	front tire prea rogram sens left front stro Hours 7.00 Meter ead battery.	ssures sensor,r or. be light.	rotate and Labor:	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date:	145.60			7.00 1.00 2.00 2.00 1.00 1.00
 Pressure tess system. Replace defibalance all four Test and rep Shop Suppli Workorder: Problem:	ective left ir tires.reproduce inop es 1608472 Tow in,de and charg	front tire prea rogram sens left front stro Hours 7.00 Meter ead battery.	ssures sensor,r or. be light. : 36704	rotate and Labor:	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su 420.00	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date:	145.60			7.00 1.00 2.00 2.00 1.00 1.00
 Pressure tess system. Replace defubalance all four Test and rep Shop Suppli Workorder: Problem: Test battery 	ective left ir tires.reproduce inop es 1608472 Tow in,de and charg	front tire prea rogram sens left front stro Hours 7.00 Meter ead battery.	ssures sensor,r or. be light. : 36704	rotate and Labor:	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su 420.00	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date: st	145.60			7.00 1.00 2.00 1.00 1.00 016 Qty
 Pressure tess system. Replace defubalance all four Test and rep Shop Suppli Workorder: Problem: Test battery 	ective left ir tires.reproduce inop es 1608472 Tow in,de and charg es	front tire prea rogram sens left front stro Hours 7.00 Meter ead battery.	ssures sensor,r or. be light. : 36704	rotate and Labor:	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su 420.00 Parts Li Battery Shop Su	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date: st	145.60	Closed:		7.00 1.00 2.00 1.00 1.00 1.00
 Pressure tess system. Replace defubalance all four Test and rep Shop Suppli Workorder: Problem: Test battery 	et and insp ective left ir tires.repro- blace inop es 1608472 Tow in,de and charg es	front tire pres rogram sens left front stro Hours 7.00 Meter ead battery. ing system,r	ssures sensor,r or. be light. : 36704 eplace bad bat	tery.	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su 420.00 Parts Li Battery Shop Su	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date: st	145.60 08/16/2016	Closed:	08/30/20	7.00 1.00 2.00 1.00 1.00 1.00 016 Qty 1.00
 Pressure tess system. Replace defubalance all four Test and rep Shop Suppli Workorder: Problem: Test battery Shop Suppli Workorder: Problem:	ective left ir tires.repro- blace inop es 1608472 Tow in,de and charg es 1608508 No start	front tire pres rogram sens left front stro Hours 7.00 Meter ad battery. ing system,r Hours 1.00	ssures sensor,r or. be light. : 36704 eplace bad bat	tery.	5w20 Er Napago 22" Wip Peak Gl Tpms12 Shop Su 420.00 Parts Li Battery Shop Su	ngine Oil Id Oil Filter er Blade obal Sensor Tire upplies Parts: In Date: st upplies Parts:	145.60 08/16/2016 120.41	Closed: Total:	08/30/20	7.00 1.00 2.00 1.00 1.00 1.00 016 Qty 1.00

	In Date:	01/09/2017	Closed:	01/23/2017		
- P.m. Service.	Parts List			Qty		
- Rotate and balance tires.	5w20 Engine Oil			7.00		
- Diagnose ans repair inop visor mounted strobe lamp wiring	. Napagold Oil Filter			1.00		
- Fabricate and replace worn out front asset #.	Washer Fluid Conc	entr		1.00		
- Shop Supplies	Used Fire X Refurb	ished		1.00		
	22" Wiper Blade			2.00		
	Shop Supplies			1.00		
Hours 4.50 Labor	270.00 Parts:	44.63	Total:	314.63		
Workorder:1800361Meter:38939Problem:P.M. service and tire pressure light on.	In Date:	01/10/2018	Closed:	01/19/2018		
- P.m. service.	Parts List			Qty		
- Inspect and replace two tires on front. Rotate and high	5w20 Engine Oil 7.0					
speed balance all four .nitro fill tires and replace right front and left rear tire sensor.relearn all sensors.	Napagold Oil Filter					
- Remove front visor strobe lights fabericate and rewire	22" Wiper Blade		2.00			
lamps .rewire rear strobe lights and test all.	Used Fire X Refurbished 1.					
- Perform complete front end alignment.road test.	183783418 P235-70r17 2.					
- Shop Supplies	Tpms12 Sensor Tir			2.00		
	Syn-atf Trans Fluid			2.00		
	Washer Fluid Conc	entr		1.00		
	Shop Supplies			1.00		
Hours 8.50 Labor	Tire Disposal Fee 510.00 Parts:	672.93	Tatali	2.00		
	510.00 Faits.					
:			Total:	1,182.93		
: Workorder: 1807875 Meter: 39685 Problem: P.M. service and tire light on .	In Date:	08/01/2018	Closed:	08/16/2018		
	In Date: Parts List					
Problem: P.M. service and tire light on .				08/16/2018		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . 	Parts List Kit O accumulator			08/16/2018 Qty 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. 	Parts List Kit O accumulator Evap /ac			08/16/2018 Qty 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1			08/16/2018 Qty 1.00 1.00 2.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil			08/16/2018 Qty 1.00 1.00 2.00 6.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter	08/01/2018		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb	08/01/2018		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade	08/01/2018		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 2.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc	08/01/2018 ished entr		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc 183783418 P235-7	08/01/2018 ished entr		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 2.00 1.00 2.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc 183783418 P235-7 Washer Nozzle	08/01/2018 ished entr		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc 183783418 P235-7 Washer Nozzle 22" Wiper Blade	08/01/2018 ished entr		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc 183783418 P235-7 Washer Nozzle 22" Wiper Blade Shop Supplies	08/01/2018 ished entr		08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00		
 Problem: P.M. service and tire light on . P.m. service. Test and replace left side washer nozzle . Retest. Replace two tires . Rotate and balance all four tires . Nitrofill and reset Tpms. Perform A/c performance test . Leak test . Recover feon . Replace leak evaporator core assembly ,seals and accumulator . Vacuum system and complete recharge to factory spec. Retest. Shop Supplies 	Parts List Kit O accumulator Evap /ac Freon Lv Shop 1 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurb 20" Wiper Blade Washer Fluid Conc 183783418 P235-7 Washer Nozzle 22" Wiper Blade Shop Supplies Tire Disposal Fee	08/01/2018 ished entr	Closed:	08/16/2018 Qty 1.00 1.00 2.00 6.00 1.00 2.00 1.00 2.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00		

Problem:	1809137 No power ste	Meter: eering.	39759			In Date:	09/05/2018	Closed:	09/10/20)18
	er steering . Fil	ll power ste	ering reservoir amp at reservo		Parts L Psf Qt	ist				Qty 1.00
	Hou :	ırs 0.50		Labor:	30.00	Parts:	6.83	Total:	36.83	
Workorder: Problem:	1809835 put spare on	Meter: , Pass rear	39759 tire flat			In Date:	07/27/2018	Closed:	09/24/20)18
- Tow From: v	water plant 8,		rd							
	Hou :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1901837 P.M. service	Meter: and towed	40162 in for no start.			In Date:	02/19/2019	Closed:	03/06/20)19
- P.m. service					Parts L					Qty
			st battery and or efective batter			old Oil Filter				1.00
•	•		d service calipe			ngine Oil or Blado				6.00
Replace front			rake system .		•	er Blade Id Air Filter				2.00
drive. Test and rer	alaca laft front	tiro proceu	re sensor .rota	ata and	Battery					1.00
	ur tires . Nitrofi			ale anu	Brake P	ad				1.00
- Shop Suppli	ies				Front Pa	ads				1.00
					Tpms12	2 Sensor Tire	e Pr			1.00
					Used Fi	re X Refurbi	shed			1.00
					Shop S	upplies				1.00
	Hou :	ırs 8.50		Labor:	569.50	Parts:	368.25	Total:	937.75	
	4004050	Meter:	39907			In Date:	02/19/2019	Closed:	02/19/20)19
	1901853 No Start/ PM	Service								10
Problem:	No Start/ PM		er Plant To: Lv	v shop						,10
	No Start/ PM 1500 Jog Rd.,		er Plant To: Lv	v shop Labor:	0.00	Parts:	0.00	Total:	0.00	,10
Problem: - Tow From: 1 Workorder:	No Start/ PM 1500 Jog Rd.,	Sys 8 Wate irs 0.00 Meter:	40162	Labor:	0.00	Parts: In Date:	0.00 09/05/2019	Total: Closed:	0.00	
Problem: - Tow From: 1 Workorder:	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service	Sys 8 Wate irs 0.00 Meter:	40162	Labor:	0.00 Parts L	In Date:)19
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep	40162 in for no start. place right rear	Labor:	Parts L	In Date:)19 Qty
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep	40162 in for no start. place right rear	Labor:	Parts L 20" Wip	In Date:				
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep	40162 in for no start. place right rear	Labor:	Parts L 20" Wip Napago 5w20 E	In Date: ist er Blade Id Oil Filter ngine Oil	09/05/2019			019 Qty 2.00 1.00 6.00
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep	40162 in for no start. place right rear	Labor:	Parts L 20" Wip Napago 5w20 E Tpms12	In Date: ist er Blade eld Oil Filter ngine Oil 2 Sensor Tire	09/05/2019			019 Qty 2.00 1.00 6.00 1.00
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all ies	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep and reset	40162 in for no start. place right rear	Labor:	Parts L 20" Wip Napago 5w20 E Tpms12 Shop Si	In Date: ist er Blade Id Oil Filter ngine Oil 2 Sensor Tire upplies	09/05/2019 e Pr	Closed:	09/16/20	019 Qty 2.00 1.00 6.00 1.00
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all ies	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep	40162 in for no start. place right rear	Labor:	Parts L 20" Wip Napago 5w20 E Tpms12	In Date: ist er Blade Id Oil Filter ngine Oil 2 Sensor Tire upplies	09/05/2019	Closed:		019 Qty 2.00 1.00 6.00
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens - Shop Suppli Workorder:	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all ies	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep and reset	40162 in for no start. place right rear	Labor:	Parts L 20" Wip Napago 5w20 E Tpms12 Shop Si	In Date: ist er Blade Id Oil Filter ngine Oil 2 Sensor Tire upplies	09/05/2019 e Pr	Closed:	09/16/20	019 Qty 2.00 1.00 6.00 1.00
Problem: - Tow From: 1 Workorder: Problem: - P.m. service - Balance and pressure sens - Shop Suppli Workorder: Problem:	No Start/ PM 1500 Jog Rd., Hou : 1909133 P.M. service e. d rotate all four for . Nitrofill all ies Hou : 1909164	Sys 8 Wate irs 0.00 Meter: and towed r tires . Rep and reset	40162 in for no start. place right rear Tpms . 40162	Labor:	Parts L 20" Wip Napago 5w20 E Tpms12 Shop Si	In Date: ist er Blade eld Oil Filter ngine Oil 2 Sensor Tire upplies Parts:	09/05/2019 e Pr 105.36	Closed: Total:	09/16/20 373.36	019 Qty 2.00 1.00 6.00 1.00

Workorder: Problem:	2002693 Transition Pre		40319			In Date:	03/17/2020	Closed:	03/17/2020
- Transition P	rep Charge								
	Hou :	ırs 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00