

**Palm Beach County Fleet Management
Asset Maintenance History**

10185049 2011 CHEVROLET SILVERADO Pickup, 1/2 Ton, Ext Cab, 4X4

Workorder: 1104877 **Meter:** 286 **In Date:** 05/09/2011 **Closed:** 05/09/2011
Problem: Pre Delivery Inspection

- Pre Delivery Inspection
- Wash Vehicle

Hours 3.00 Labor: 180.00 Parts: 0.00 Total: 180.00
:

Workorder: 1111745 **Meter:** 5597 **In Date:** 11/01/2011 **Closed:** 11/14/2011
Problem: Pm service.

- P.m. Service.

Parts List Qty

- Install new fire extinguisher with bracket..diagnose inop Shop Supplies 1.00
- horn.replace defective horn(filled with water).re-mount horn in Ph10060 Oil Filter Acd Pf48 Wix 57060 1.00
- new location and fabricate wiring. 10-9050 Oil Dexos1 5w30 6.00
- Service and adjust rear brakes. Custom5lb Bracket Firex Stock #340060300 1.00
- Inspect and service winch. Used Firex Refurbed Fire Extingshers 1.00
- Rotate and balance all tires. Horn 1.00
- Shop Supplies

Hours 7.75 Labor: 465.00 Parts: 134.11 Total: 599.11
:

Workorder: 1204318 **Meter:** 10634 **In Date:** 05/07/2012 **Closed:** 05/17/2012
Problem: P.M. Service

- P.m. Service.

Parts List Qty

- Battery leaking acid at positive terminal.clean terminal and Shop Supplies 1.00
- battery tray and replace battery. Ph10060 Oil Filter Acd Pf48 Wix 57060 1.00
- Resurface rear brake drums and replace worn out brake Brake Shoes 1.00
- shoes.clean sand and mud from hardware and backing 10-9050 Oil Dexos1 5w30 6.00
- plates. Wipers 2.00
- Inspect and service winch.r&r planetary gear and clean and Battery 1.00
- lubricate.
- Rotate and balance all four tires.
- Shop Supplies

Hours 11.75 Labor: 705.00 Parts: 448.88 Total: 1,153.88
:

Workorder: 1210288 **Meter:** 15517 **In Date:** 10/25/2012 **Closed:** 11/19/2012
Problem: P.M. service

- P.m. Service.

Parts List Qty

- Resurface rear brake drums,replace worn out brake Dexos 5w30 6.00
- shoes.clean sand and mud from backing plates.adjust brakes Ph10060 Oil Filter Ac 1.00
- and test drive. Used Firex Refurbed F 1.00
- Replace broken transmission filler tube. Ca8755a Air Filter Lb 1.00
- Rotate and balance all tires. Reman Brake Shoes 1.00
- Inspect and service winch. transmission tube 1.00
- Shop Supplies tube seal 1.00
- Shop Supplies 1.00

Hours 10.25 Labor: 615.00 Parts: 135.07 Total: 750.07
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1301472 **Meter:** 17490 **In Date:** 02/11/2013 **Closed:** 02/21/2013
Problem: Brake warning light on.

<ul style="list-style-type: none"> - Diagnose brake warning light.replace both leaking rear wheel cylinders.clean and adjust brakes and bleed system.clear Abs light and test drive. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Drum Brake Whl Cyлинд 1401 Brake Fluid Bra Brake Cleaner Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 2.00 1.00 2.00 1.00 	
Hours 2.20	Labor: 132.00	Parts: 43.18	Total: 175.18

Workorder: 1305751 **Meter:** 20046 **In Date:** 06/10/2013 **Closed:** 06/24/2013
Problem: Pm service.

<ul style="list-style-type: none"> - Perform pm service. - Rotate and balance all four tires. - Inspect and service power winch. - Perform rear drum brake service and adjust brake shoes. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Dexos 5w30 Filter Accufit Beam Shop Supplies 	<p>Qty</p> <ul style="list-style-type: none"> 6.00 1.00 2.00 1.00 	
Hours 5.75	Labor: 345.00	Parts: 65.44	Total: 410.44

Workorder: 1312807 **Meter:** 25043 **In Date:** 12/26/2013 **Closed:** 01/21/2014
Problem: Pm service.Check wiper blades and tires.

<ul style="list-style-type: none"> - Perform pm service. - Install four new tires.nitrogen fill and balance all four. - Install new rear brake shoes and two new rear brake drums.replace both rear wheel cylinders with new.flush brake fluid and automated bleed hydraulic system with scan tool. - Perform wheel alignment complete. - Shop Supplies 	<p>Parts List</p> <ul style="list-style-type: none"> Dexos 5w30 Oil Napagold Oil Filter Used Fire X Refurbished Accufit Beam 35x12.5r17 Nitto Grap 1401 Brake Fluid Bra Brake Cleaner Reman Brake Shoes Drum Brake Whl Cyлинд Drum Shop Supplies Tire Disposal Fee 	<p>Qty</p> <ul style="list-style-type: none"> 6.00 1.00 1.00 2.00 4.00 1.00 1.00 1.00 2.00 2.00 1.00 4.00 	
Hours 12.25	Labor: 735.00	Parts: 2,477.20	Total: 3,212.20

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407505 **Meter:** 30375 **In Date:** 07/30/2014 **Closed:** 08/12/2014
Problem: Pm service and wiper blade noisy.

- P.m. Service.	Parts List	Qty
- Resurface front brake rotors,replace front pads.service and lube calipers,inspect and service rear brakes.diagnose Abs light.repair left front Abs sensor wiring.	Dexos 5w30 Oil	6.00
	Napagold Oil Filter	1.00
	Napagold Air Filter	1.00
- Inspect and service winch.	Accufit Beam	2.00
- Rotate and balance all tires.	Washer Fluid Concentr	1.00
- Shop Supplies	Disc Pad	1.00
	Brake Cleaner	1.00
	Connector Abs Sensor	1.00
	Shop Supplies	1.00
Hours 11.25	Labor: 675.00	Parts: 183.74
:		Total: 858.74

Workorder: 1502028 **Meter:** 34580 **In Date:** 02/25/2015 **Closed:** 03/18/2015
Problem: P.M. Service.Check winch operation.

- Pm service.	Parts List	Qty
- Diagnose for winch inop.remove winch from inside bumper to acess and replace defective solenoid.also perform winch service.	Dexos 5w30 Oil	6.00
	Napagold Oil Filter	1.00
	Accufit Beam	2.00
- Inspect and service rear drum brakes.	Washer Fluid Concentr	1.00
- Rotate and balance all four tires.	Used Fire X Refurbished	1.00
- Shop Supplies	Repl Solenoid Term Up	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 125.08
:		Total: 545.08

Workorder: 1510210 **Meter:** 40404 **In Date:** 10/07/2015 **Closed:** 10/27/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Test electrical and starting system.battery failed loadtest after recharge.replace defective battery.	Dexos 5w30	6.00
	Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.	Accufit Beam	2.00
- Inspect and service winch.	Washer Fluid Concentr	1.00
- Inspect and service rear brakes.	Battery	1.00
- Perform complete front end alignment.	35x12.5r17 Nitto Grap	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.25	Labor: 615.00	Parts: 1,149.93
:		Total: 1,764.93

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604709 **Meter:** 44658 **In Date:** 05/04/2016 **Closed:** 05/17/2016
Problem: P.M. service and check A/C blows warm at times.

	Parts List	Qty
- P.m. Service.		
- A/c performance check,low freon.replace leaking accumulator and orifice tube.vacuum and rechargr system to specs.	Napagold Oil Filter	1.00
	Dexos 5w30	6.00
- Flush and refill transmission system.	Used Fire X Refurbished	1.00
- Inspect and service front differential.	Napagold Air Filter	1.00
- Fabricate and replace front asset #.	Accufit Beam	2.00
- Inspect and service winch.	Washer Fluid Concentr	1.00
- Service and adjust rear brakes.clean mud and debri from backing plates and brake hardware.	Accumulator	1.00
	Orifice Tube	1.00
- Rotate and balance all tires.	Pag Oil	1.00
- Shop Supplies	Syn-atf Trans Fluid S	16.00
	1qt Syngear Oil 75-90	2.00
	Shop Supplies	1.00
Hours 13.25	Labor: 795.00	Parts: 238.72
:		Total: 1,033.72

Workorder: 1610120 **Meter:** 48063 **In Date:** 09/27/2016 **Closed:** 09/30/2016
Problem: A/C blows warm at times.

	Parts List	Qty
- Diagnose a/c system blows warm intermittently.evaporator freezing up.replace bad evaporatot temperature sensor.	A/c Sensor	1.00
- Shop Supplies	Clr Rtv Silcn Sealant	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 47.96
:		Total: 347.96

Workorder: 1612978 **Meter:** 49176 **In Date:** 12/20/2016 **Closed:** 01/11/2017
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Replace two tires,rotate and balance all four.	Napa Syn 5w30 Qt	6.00
- Prssure test and inspect cooling system.flush and refill coolant.	Napagold Oil Filter	1.00
	Accufit Beam	2.00
- Replace rear braker shoes,wheel cylinders and drums.flush and bleed system.	Used Fire X Refurbished	1.00
	35x12.5r17 Nitto Grap	2.00
- Complete wheel alignment.test drive.	Dex Coolant Engine	2.00
- Inspect and service winch.	Hose Clamp	4.00
- Shop Supplies	Brake Drum	2.00
	Reman Brake Shoes	1.00
	Drum Brake Whl Cylind	2.00
	B Fluid Dot 3-32oz	1.00
	Spring Kit Brake Shoe	2.00
	Rear Adjuster Brake	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.25	Labor: 855.00	Parts: 1,381.50
:		Total: 2,236.50

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1707016 **Meter:** 52954 **In Date:** 07/18/2017 **Closed:** 08/03/2017
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Battery failed load test after recharge.check electrical system.replace bad battery. - Replace failed left front hub/bearing assembly. - Perform transfer case service. - Perform rear differential service. - Inspect and service winch.replace damaged cable and hook. - Perform rear brake service. - Rotate and balance four tires.nitrofill. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Napa Syn 5w30 Qt</td><td></td><td align="right">6.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>Accufit Beam</td><td></td><td align="right">2.00</td></tr> <tr><td>Mac Battery Protect</td><td></td><td align="right">1.00</td></tr> <tr><td>Battery</td><td></td><td align="right">1.00</td></tr> <tr><td>Hub Baring A/c Delco</td><td></td><td align="right">1.00</td></tr> <tr><td>Syn-atf Trans Fluid S</td><td></td><td align="right">2.00</td></tr> <tr><td>1qt Syngear Oil 75-90</td><td></td><td align="right">3.00</td></tr> <tr><td>Non-chlor Brake Clnr</td><td></td><td align="right">1.00</td></tr> <tr><td>Winch Cable W Hook</td><td></td><td align="right">1.00</td></tr> <tr><td>Winch Cable</td><td></td><td align="right">1.00</td></tr> <tr><td>Clevis Slip Hook-bulk</td><td></td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Napa Syn 5w30 Qt		6.00	Napagold Oil Filter		1.00	Accufit Beam		2.00	Mac Battery Protect		1.00	Battery		1.00	Hub Baring A/c Delco		1.00	Syn-atf Trans Fluid S		2.00	1qt Syngear Oil 75-90		3.00	Non-chlor Brake Clnr		1.00	Winch Cable W Hook		1.00	Winch Cable		1.00	Clevis Slip Hook-bulk		1.00	Shop Supplies		1.00	<table border="0"> <tr> <td>Hours 10.55</td> <td>Labor: 633.00</td> <td>Parts: 891.08</td> <td>Total: 1,524.08</td> </tr> <tr> <td>:</td> <td></td> <td></td> <td></td> </tr> </table>	Hours 10.55	Labor: 633.00	Parts: 891.08	Total: 1,524.08	:			
Parts List		Qty																																																		
Napa Syn 5w30 Qt		6.00																																																		
Napagold Oil Filter		1.00																																																		
Accufit Beam		2.00																																																		
Mac Battery Protect		1.00																																																		
Battery		1.00																																																		
Hub Baring A/c Delco		1.00																																																		
Syn-atf Trans Fluid S		2.00																																																		
1qt Syngear Oil 75-90		3.00																																																		
Non-chlor Brake Clnr		1.00																																																		
Winch Cable W Hook		1.00																																																		
Winch Cable		1.00																																																		
Clevis Slip Hook-bulk		1.00																																																		
Shop Supplies		1.00																																																		
Hours 10.55	Labor: 633.00	Parts: 891.08	Total: 1,524.08																																																	
:																																																				

Workorder: 1801453 **Meter:** 55999 **In Date:** 02/06/2018 **Closed:** 02/14/2018
Problem: P.M. service.

<ul style="list-style-type: none"> - P.m. service. - Inspect all brakes.replace front brake pads , rotors and calipers .inspect and service and adjust rear brakes .flush and bleed brake system. - Rotate and high speed balance all four tires .nitrofill all. - Inspect and service winch. - Shop Supplies 	<table border="0"> <thead> <tr> <th align="left" colspan="2">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>Brake Caliper</td><td></td><td align="right">1.00</td></tr> <tr><td>Brake Caliper</td><td></td><td align="right">1.00</td></tr> <tr><td>Napa Syn 5w30 Qt</td><td></td><td align="right">6.00</td></tr> <tr><td>Napagold Oil Filter</td><td></td><td align="right">1.00</td></tr> <tr><td>22in Exactfit-beam</td><td></td><td align="right">2.00</td></tr> <tr><td>Washer Fluid Concentr</td><td></td><td align="right">1.00</td></tr> <tr><td>Used Fire X Refurbished</td><td></td><td align="right">1.00</td></tr> <tr><td>Non-chlor Brake Clnr</td><td></td><td align="right">1.00</td></tr> <tr><td>Brake Rotor</td><td></td><td align="right">2.00</td></tr> <tr><td>Pintle Pin W/clip</td><td></td><td align="right">1.00</td></tr> <tr><td>Front Brake Pad A/c Delco</td><td></td><td align="right">1.00</td></tr> <tr><td>brake fluid</td><td></td><td align="right">1.00</td></tr> <tr><td>Caliper Washer</td><td></td><td align="right">4.00</td></tr> <tr><td>Shop Supplies</td><td></td><td align="right">1.00</td></tr> </tbody> </table>	Parts List		Qty	Brake Caliper		1.00	Brake Caliper		1.00	Napa Syn 5w30 Qt		6.00	Napagold Oil Filter		1.00	22in Exactfit-beam		2.00	Washer Fluid Concentr		1.00	Used Fire X Refurbished		1.00	Non-chlor Brake Clnr		1.00	Brake Rotor		2.00	Pintle Pin W/clip		1.00	Front Brake Pad A/c Delco		1.00	brake fluid		1.00	Caliper Washer		4.00	Shop Supplies		1.00	<table border="0"> <tr> <td>Hours 9.75</td> <td>Labor: 585.00</td> <td>Parts: 428.48</td> <td>Total: 1,013.48</td> </tr> <tr> <td>:</td> <td></td> <td></td> <td></td> </tr> </table>	Hours 9.75	Labor: 585.00	Parts: 428.48	Total: 1,013.48	:			
Parts List		Qty																																																					
Brake Caliper		1.00																																																					
Brake Caliper		1.00																																																					
Napa Syn 5w30 Qt		6.00																																																					
Napagold Oil Filter		1.00																																																					
22in Exactfit-beam		2.00																																																					
Washer Fluid Concentr		1.00																																																					
Used Fire X Refurbished		1.00																																																					
Non-chlor Brake Clnr		1.00																																																					
Brake Rotor		2.00																																																					
Pintle Pin W/clip		1.00																																																					
Front Brake Pad A/c Delco		1.00																																																					
brake fluid		1.00																																																					
Caliper Washer		4.00																																																					
Shop Supplies		1.00																																																					
Hours 9.75	Labor: 585.00	Parts: 428.48	Total: 1,013.48																																																				
:																																																							

Workorder: 1802563 **Meter:** 55999 **In Date:** 02/12/2018 **Closed:** 03/08/2018
Problem: Damage to left side of bed, rear bumper, tailgate & right side of bed

<ul style="list-style-type: none"> - Damage to left side of bed, rear bumper, tailgate & right side of bed 	<table border="0"> <tr> <td>Hours 0.00</td> <td>Labor: 0.00</td> <td>Parts: 0.00</td> <td>Total: 0.00</td> </tr> <tr> <td>:</td> <td></td> <td></td> <td></td> </tr> </table>	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00	:			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00						
:									

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808099 **Meter:** 59404 **In Date:** 08/07/2018 **Closed:** 08/16/2018
Problem: P.M. Service.

- P.m. service.	Parts List	Qty
- R&r right wheel bearing assembly due to noise.	Napagold Oil Filter	1.00
- Inspect and service winch .	Napa Syn 5w30 Qt	6.00
- Rotate and balance four tires. Nitrofill	22in Exactfit-beam	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Hub Assy	1.00
	Shop Supplies	1.00
Hours 6.05	Labor: 363.00	Parts: 478.10
:		Total: 841.10

Workorder: 1901668 **Meter:** 63925 **In Date:** 02/12/2019 **Closed:** 02/22/2019
Problem: P.M. service and left rear tire going flat .

- P.m. service.	Parts List	Qty
- Replace two worn tires and repair left rear tire . Rotate and balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Inspect and service winch .	Napa Syn 5w30 Qt	6.00
- Complete front end alignment and road test.	22in Exactfit-beam	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	35x12.5r17 Nitto Grap	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.25	Labor: 552.75	Parts: 1,038.42
:		Total: 1,591.17

Workorder: 1902368 **Meter:** 64526 **In Date:** 03/04/2019 **Closed:** 03/19/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Inspect and replace worn serpentine belt .	Napa Syn 5w30 Qt	6.00
- Replace rear brake drums ,wheel cylinders and brake shoes . Adjust rear brakes . Flush and bleed brake system . Road test .	Napagold Oil Filter	1.00
- Diagnose slow crank . Perform start circuit test . R&r defective starter assembly . Retest .	Used Fire X Refurbished	1.00
- Inspect and service winch .	Tram Fluid	1.00
- Rotate and balance all four tires . Nitrofill all and reset Tpms.	Serpentine Belt	1.00
- Shop Supplies	B Fluid Dot 3-32oz	2.00
	Drum Brake Whl Cylind	2.00
	Non-chlor Brake Clnr	2.00
	Reman Brake Shoes	1.00
	Drum	2.00
	Starter	1.00
	Shop Supplies	1.00
Hours 11.65	Labor: 780.55	Parts: 778.80
:		Total: 1,559.35

Workorder: 1904043 **Meter:** 65365 **In Date:** 04/12/2019 **Closed:** 04/22/2019
Problem: Vehicle seemed wobbly on turn pike.

- Test drive for concern . R&r defective left front wheel hub assembly. Retorque all lug nuts . Road test .	Parts List	Qty
- Shop Supplies	Hub Assy	1.00
	Shop Supplies	1.00
Hours 1.30	Labor: 87.10	Parts: 423.95
:		Total: 511.05

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1909291 **Meter:** 68827 **In Date:** 09/09/2019 **Closed:** 09/25/2019
Problem: P.M. service and right outside mirror damaged .

- P.m. service.	Parts List	Qty		
- Replace two tires . Balance and rotate all four tires . Nitrofill all.	Napagold Oil Filter	1.00		
	Napa Syn 5w30 Qt	6.00		
- Remove right front door panel to replace damaged mirror assembly .	22in Exactfit-beam	2.00		
	Png Head Gasket Sealr	1.00		
- Inspect and service winch .	Used Fire X Refurbished	1.00		
- Inspect and service rear brakes.	35x12.5r17 Nitto Grap	2.00		
- Shop Supplies	Mirror	1.00		
	Shop Supplies	1.00		
	Tire Disposal Fee	2.00		
Hours 8.00	Labor: 536.00	Parts: 1,193.83	Total: 1,729.83	
:				

Workorder: 2004214 **Meter:** 73152 **In Date:** 04/28/2020 **Closed:** 04/28/2020
Problem: Transition Prep Charge

- Transition Prep Charge				
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00	
:				