

**Palm Beach County Fleet Management
Asset Maintenance History**

10169523 2008 FORD F350 Utility Body, 1 Ton, 4X4, Winch

Workorder: 833584 **Meter:** 0 **In Date:** 02/04/2008 **Closed:** 02/04/2008
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
:

Workorder: 834462 **Meter:** 0 **In Date:** 02/21/2008 **Closed:** 02/22/2008
Problem: INSTALL AUX FUEL TANK (FROM 10124784)

- Install Aux Fuel Tank From 10124784
- Shop Supplies

Parts List
Shop Supplies 1.00
Ds-167 Toggle Switch (standard) 1.00

Hours 8.00 Labor: 480.00 Parts: 9.10 Total: 489.10
:

Workorder: 834504 **Meter:** 0 **In Date:** 02/22/2008 **Closed:** 03/10/2008
Problem: 001 KEY ISSUED OUT 02/22/08

- 001 Key Issued Out 02/22/08

Parts List
Duplicate Vehicle Keys 1.00

Hours 0.20 Labor: 0.00 Parts: 3.00 Total: 3.00
:

Workorder: 842585 **Meter:** 3740 **In Date:** 08/08/2008 **Closed:** 08/12/2008
Problem: P.M SERVICE

- Pm Service
- Nitro Service Six Tires.
- Service Vehicle Winch.
- Shop Supplies

Parts List
Shop Supplies 1.00
7312 Oil Filterfrm Ch9549 Wix 57312 1.00
Cs10263 Fuel Filter (use Cs10263a) 1.00
15/40 Oil 15.00

Hours 6.50 Labor: 390.00 Parts: 114.53 Total: 504.53
:

Workorder: 848537 **Meter:** 0 **In Date:** 12/23/2008 **Closed:** 12/23/2008
Problem: SISTERS TOWING & TRANSPORTATON TOW FROM FERNLY AND

- Sisters Towing & Transportaton Tow From Fernly And
Lanatana Rd - Tow To

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 848538 **Meter:** 5897 **In Date:** 12/23/2008 **Closed:** 12/30/2008
Problem: L/F TIRE FLAT

- Repair L/f Tire.
- Shop Supplies

Parts List
Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 932590 **Meter:** 0 **In Date:** 12/23/2008 **Closed:** 01/09/2009
Problem: TIRESOLES OF BROWARD INC

- Tiresoles Of Broward Inc

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 934286 **Meter:** 6715 **In Date:** 02/23/2009 **Closed:** 02/25/2009
Problem: P.M. SERVICE.RECALL.

- Pm Service	Parts List	Qty
- Right Rear Marker Lamp On Utility Box Not Working.test Circuits,ground Open In Lamp Base.drill Out Rivets To Rplace Base.	Shop Supplies	1.00
- Rotate And Hi Speed Balance 6 Tires.	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- Inspect And Service Winch.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Transport Vehicle To Dealer For Recalls #0807b 0806b	Cs10263 Fuel Filter (use Cs10263a)	1.00
- Shop Supplies	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	19721 Base Mount 19 Series 4" Marker Light	1.00
Hours 9.25	Labor: 555.00	Parts: 222.47
:		Total: 777.47

Workorder: 940844 **Meter:** 8734 **In Date:** 07/16/2009 **Closed:** 07/16/2009
Problem: 1 - Key(s) issued

- 1 - Key(s) issued	Parts List	Qty
	Duplicate Vehicle Keys	1.00
Hours 0.20	Labor: 12.00	Parts: 3.00
:		Total: 15.00

Workorder: 942671 **Meter:** 9727 **In Date:** 08/28/2009 **Closed:** 08/31/2009
Problem: P.M service.

- P.m service.	Parts List	Qty
- Rotate & balance all six tires.	Shop Supplies	1.00
- Inspect & service winch.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
	10w30 Motor Oil	15.00
	Vapor Control Vent Cap Pctv2	1.00
Hours 6.50	Labor: 390.00	Parts: 162.92
:		Total: 552.92

Workorder: 942758 **Meter:** 9730 **In Date:** 09/01/2009 **Closed:** 09/10/2009
Problem: Glove box won't close

- Glove box latch mechanisum binding, replace glove box latch assembly.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Glove Box Latch Assy 8c3z1506072aa	1.00
Hours 0.50	Labor: 30.00	Parts: 12.28
:		Total: 42.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1004547 **Meter:** 13197 **In Date:** 05/03/2010 **Closed:** 05/04/2010
Problem: P.M service.

- P.m service.	Parts List	Qty
- Inspect & service winch.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 5.00	Labor: 300.00	Parts: 110.99
:		Total: 410.99

Workorder: 1013656 **Meter:** 17345 **In Date:** 12/13/2010 **Closed:** 12/14/2010
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace and balance all six tires.	Shop Supplies	1.00
- Test batteries and charging system.recharge and retest both batteries.both failed load test.replace defective batteries.	Pm-22-a Additive Diesel Fuel (m/craft)	1.00
- Complete wheel alignment.	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- Inspect and service winch.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Group 65 Battery (mtc Bxt-65-850)	2.00
	Radiator Cxap	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	6.00
	Tire Disposal Fee	6.00
Hours 12.50	Labor: 750.00	Parts: 1,524.17
:		Total: 2,274.17

Workorder: 1108887 **Meter:** 21651 **In Date:** 08/23/2011 **Closed:** 08/25/2011
Problem: Pm service

- Perform pm service.	Parts List	Qty
- Pressure test and inspect cooling system.replace failed upper and lower radiator hoses with new.reverse flush and renew coolant.	Shop Supplies	1.00
- Test and repair ground circuit for tag lamp.fabricate and replace failed rear clearance light bar with new.	Lower Left Radiator Hose	1.00
- Rotate and balance all six tires.	Lower Right Radiator Hose	1.00
- Inspect and service power winch.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Shop Supplies	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	15050r Id Bar Red Model 15 Led	1.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 10.75	Labor: 645.00	Parts: 292.42
:		Total: 937.42

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1111780 **Meter:** 22569 **In Date:** 11/02/2011 **Closed:** 12/12/2011
Problem: replace aps fuel pump

- Replace Aps fuel pump	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Aps Fuel Pump/meter Combination	1.00
	Switch	1.00
	Ds-167 Toggle Switch (standard)	1.00
	Ds367 Yellow Pilot Light	1.00
Hours 5.00	Labor: 300.00	Parts: 767.02
:		Total: 1,067.02

Workorder: 1204251 **Meter:** 25268 **In Date:** 05/04/2012 **Closed:** 05/07/2012
Problem: Pm service

- P.m. Service.	Parts List	Qty
- Replace right rear light assemble.	Shop Supplies	1.00
- Fabricate piping and install filter on saddle tank.service system.	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
- Inspect and service winch.	24006 Fuel Filter Diesel And Gas	1.00
- Rotate and balance six tires.	1066 White Lithium (crc 05037)	1.00
- Shop Supplies	15/40 Oil	15.00
	3/4x5 Nipple Galv. (various)	1.00
	50003 Filter Head Single 3/4" (cim-tek)	1.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	44202r Tail Light 4" Red 42 Led	1.00
Hours 9.50	Labor: 570.00	Parts: 204.84
:		Total: 774.84

Workorder: 1208300 **Meter:** 27007 **In Date:** 09/04/2012 **Closed:** 09/20/2012
Problem: Fuel Pump Not Working

- replace switch fo aps fuel tank	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Ds-167 Toggle Switch (standard)	1.00
Hours 1.00	Labor: 60.00	Parts: 8.90
:		Total: 68.90

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1301448 **Meter:** 28620 **In Date:** 02/11/2013 **Closed:** 02/22/2013
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Replace left headlamp.replace left alley lamp bulb.	15-40 Oil	15.00
- Inspect and service aux. fuel system.	Oil Filter	1.00
- Rotate and balance all six tires.	Air Filter	1.00
- Inspect and service winch.	Napagold Fuel Filter	1.00
- Shop Supplies	Pm-22-a Additive Dies	1.00
	8c3z9a343a Seal Kit	1.00
	31-20 Wiper Blades 20	2.00
	Used Firex Refurbed F	1.00
	Halogen Lamp	1.00
	Fuel Filter	1.00
	17189e Bulb Mr11-12v	1.00
	Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 255.68
:		Total: 765.68

Workorder: 1311549 **Meter:** 31698 **In Date:** 11/15/2013 **Closed:** 11/25/2013
Problem: P.M. service.

	Parts List	Qty
- P.m. Service.		
- Inspect and service aux. fuel system.	15-40 Oil	15.00
- Test batteries and charging system.replace both bad batteries.	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
- Inspect and service winch.	Wiper Blade	2.00
- Rotate and balance all tires.	Napagold Fuel Filter	1.00
- Shop Supplies	Battery	2.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 387.50
:		Total: 927.50

Workorder: 1405772 **Meter:** 32467 **In Date:** 06/12/2014 **Closed:** 06/18/2014
Problem: P.M. service.

	Parts List	Qty
- Perform pm service.		
- Inspect and service auxiliary fuel tank and replace fuel filter.	15-40 Oil	15.00
- Install six new tires.nitrogen fill and balance all six.	Napagold Oil Filter	1.00
- Inspect and service power winch.fabricate and repair ground circuit.	Fuel Filter Ford Only	1.00
	Used Fire X Refurbished	1.00
- Perform wheel alignment complete	Napagold Fuel Filter	1.00
- Shop Supplies	Lt245 75r17 Hankook Dyn	6.00
	8c3z9a343a Seal Kit	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	6.00
Hours 11.50	Labor: 690.00	Parts: 1,874.03
:		Total: 2,564.03

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1406141 **Meter:** 32531 **In Date:** 06/23/2014 **Closed:** 07/03/2014
Problem: water in tank

- R&r Water fiilter ,and remove water from tank, reseal	Parts List	Qty
- Shop Supplies	Napagold Fuel Filter	1.00
	Ptex Ultra Grey 3oz	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 14.08
:		Total: 194.08

Workorder: 1408848 **Meter:** 33062 **In Date:** 09/03/2014 **Closed:** 09/08/2014
Problem: Left front tire flat.

- Repair flat and balance left front tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1411408 **Meter:** 34088 **In Date:** 11/17/2014 **Closed:** 11/25/2014
Problem: Pm service and ac not cold.

- Pm service.	Parts List	Qty
- Inspect and replace Both worn upper and lower radiator support to chasis insulators/body mounts.	15-40 Oil	15.00
- Inspect and replace defective right seal beam headlamp.	Napagold Oil Filter	1.00
- Ac performance and leak test for ac inop.replace leaking ac condenser,accumulator,orifice expansion valve and Hi side line with shredder valve.vacuum and recharge system to specs.	Fuel Filter Ford Only	1.00
- Inspect and service auxiliary fuel tank.replace leaking dispenser hose and nozzle.	Napagold Air Filter	1.00
- Pressure test and inspect cooling system.replace leaking radiator and both upper and lower hoses.flush and refill cooling system.	Wiper Blade	2.00
- Rotate and balance all six tires.	Floor Mat-2pc Rub Bk	1.00
- Shop Supplies	Mac Wite Lithium Gres	1.00
	Insulator	2.00
	Insulator	2.00
	Halogen Lamp	1.00
	A/c Condenser	1.00
	Line Asy	1.00
	Accumulator	1.00
	Orifice Tube	1.00
	R134a Lv Shop 2	2.00
	Napagold Fuel Filter	1.00
	Fuel Hose Asm	1.00
	11b0400 Black Nozzle	1.00
	Radiator	1.00
	Coolant Ford Gold	3.00
	Radiator Hose	1.00
	lower hose	1.00
	Top Radiator Hose	1.00
	Shop Supplies	1.00
Hours 21.50	Labor: 1,290.0	Parts: 2,561.35
:	0	Total: 3,851.35

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1501656 **Meter:** 34710 **In Date:** 02/12/2015 **Closed:** 02/13/2015
Problem: service call

- Tire Service airport hilton - service call

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1502346 **Meter:** 35203 **In Date:** 03/05/2015 **Closed:** 03/12/2015
Problem: Marker lamp on roof inop.

- Replace roof mounted marker lamp bulb .

Parts List
Bulb Qty
1.00

Hours 0.50 Labor: 30.00 Parts: 0.38 Total: 30.38
:

Workorder: 1507184 **Meter:** 36419 **In Date:** 07/17/2015 **Closed:** 07/30/2015
Problem: Pm service.Back windshield leaks.Hitch ball.

- Pm service.

- Replace one alley lamp bulb,two side marker lamp bulbs and base mounting.

- Inspect and service auxiliary fuel system.

- Inspect and service winch.

- Rotate and balance all six tires.

- Shop Supplies

Parts List
Qty
15-40 Oil 15.00
Napagold Oil Filter 1.00
Fuel Filter Ford Only 1.00
Wiper Blade 2.00
Used Fire X Refurbished 1.00
Clr Rtv Silcn Sealant 1.00
Bulb (Mr11-12v) 1.00
M C Lamp 1.00
M C Base Mount Kit 1.00
Napagold Fuel Filter 1.00
Pintle Pin W/chain 1.00
Pin W/clip 5/8 For Hitch 1.00
Shop Supplies 1.00

Hours 8.75 Labor: 525.00 Parts: 207.62 Total: 732.62
:

Workorder: 1507401 **Meter:** 36419 **In Date:** 07/24/2015 **Closed:** 07/27/2015
Problem: Repair Fuel Tank

- repair fuel leak at tank

- to mako

- Shop Supplies

Parts List
Qty
Cap 1.00
Shop Supplies 1.00

Hours 2.00 Labor: 120.00 Parts: 53.78 Total: 173.78
:

Workorder: 1512487 **Meter:** 37788 **In Date:** 12/10/2015 **Closed:** 12/16/2015
Problem: One of roof lights inop.

- Test and replace two roof clearance lamp bulbs.

Parts List
Bulb Qty
2.00

Hours 0.50 Labor: 30.00 Parts: 0.75 Total: 30.75
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1601401 **Meter:** 38425 **In Date:** 02/10/2016 **Closed:** 02/29/2016
Problem: Pm service.Switch for auxiliary fuel tank pump.

	Parts List	Qty
- Pm service.		
- Inspect and service auxiliary fuel tank.replace defective pump switch,wiring and pilot light.	15-40 Oil	15.00
	Napagold Oil Filter	1.00
- Inspect and replace both worn serpentine belt and ac belt.replace both belt tensioners and noisy idler pulleys.	Fuel Filter Ford Only	1.00
	Mac Wite Lithium Gres	1.00
- Dismantle light bar and replace defective right spot lamp.	Used Fire X Refurbished	1.00
- Inspect and replace left front upper and lower balljoints.also replace both front bump stops.	22" Wiper Blade	2.00
	Napagold Fuel Filter	1.00
- Rotate and balance all six tires.	Toggle Switch	1.00
- Complete front end alignment.	Tensioner-heavy Duty	1.00
- Shop Supplies	Serpentine Belt	1.00
	Tensioner-heavy Duty	1.00
	bumper	2.00
	Ball Joint - Lower - Front Sus	1.00
	Ball Joint - Upper - Front Sus	1.00
	Left Axle Out Seal	1.00
	9 16 Indicator Lite	1.00
	Serpentine Belt	1.00
	Drivealign Pulley	1.00
	B S Pulley	1.00
	Bulb (Mr11-12v)	1.00
	Shop Supplies	1.00
Hours 20.75	Labor: 1,245.0	Parts: 701.11
:	0	Total: 1,946.11

Workorder: 1606766 **Meter:** 39831 **In Date:** 07/05/2016 **Closed:** 07/12/2016
Problem: Check chirping noise in reverse.

	Parts List	Qty
- R&r drive shaft and replace both 'u' joints.		
- Inspect front brakes for squealing noise.resurface front rotors,replace calipers and pads.flush and bleed system.	Ujoint	2.00
	U Joint	2.00
- Shop Supplies	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	B Fluid Dot 3-32oz	1.00
	Brake Cleaner	1.00
	Brake Pads	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 392.29
:		Total: 812.29

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1609940 **Meter:** 40506 **In Date:** 09/23/2016 **Closed:** 09/28/2016
Problem: Battery blow up at roads parking lot P.M. service.

	Parts List	Qty
- Recharge and test batteries.replace both bad batteries.	Battery	2.00
- P.m. Service.	15-40 Oil	15.00
- Inspect and service aux fuel system.	Napagold Oil Filter	1.00
- Replace worn out rear bump stops.	Fuel Filter Ford Only	1.00
- Ffklush and refill transmission.	Washer Fluid Concentr	1.00
- Replace two tires,rotate and balance all six.	22" Wiper Blade	2.00
- Inspect and service winch.	Bulb	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Bumper	2.00
	Syn-atf Trans Fluid S	19.00
	179636492 Lt245-75r17	2.00
	Tr416 Valve Stem	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 12.50	Labor: 750.00	Parts: 1,061.28
:		Total: 1,811.28

Workorder: 1612574 **Meter:** 41070 **In Date:** 12/08/2016 **Closed:** 12/14/2016
Problem: Replace fire extinguisher.

	Parts List	Qty
- Replace extinguisher.	Used Fire X Refurbished	1.00
Hours 0.25	Labor: 15.00	Parts: 16.13
:		Total: 31.13

Workorder: 1703505 **Meter:** 42221 **In Date:** 04/07/2017 **Closed:** 04/18/2017
Problem: P.M. service and right middle bin door hard to close.

	Parts List	Qty
- P.m. Service.	15-40 Oil	15.00
- Inspect and service aux fuel system.	Napagold Oil Filter	1.00
- Replace windshield washer nozzles.adjust right center bin door striker.	20" Wiper Blade	2.00
- Replace brake lamps.	Fuel Filter Ford Only	1.00
- Resurface rear brake rotors.replace calipers and pads.flush and bleed system.	Washer Fluid Concentr	1.00
- Replace four tires,rotate and balance all six.	Napagold Fuel Filter	1.00
- Shop Supplies	Washer Nozzle	2.00
	Brake Pad	1.00
	Reman Brake Caliper	1.00
	Reman Brake Caliper	1.00
	B Fluid Dot 3-32oz	1.00
	179636492 Lt245-75r17	4.00
	4 Led S T T Lamp	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 14.50	Labor: 870.00	Parts: 1,481.28
:		Total: 2,351.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1709201 **Meter:** 44594 **In Date:** 09/22/2017 **Closed:** 10/25/2017
Problem: Broken fuel caps.

- Replace two fuel caps.	Parts List	Qty
- P.m. service	15-40 Oil	15.00
- Inspect and service auxiliary fuel system.	Napagold Oil Filter	2.00
- Diagnose auxilary fuel pump inop.internal short at fuel pump and switch.fabricate and rewire new fuel pump.replace shorted switch in storage compartment.	Fuel Filter Ford Only	1.00
	20" Wiper Blade	2.00
- Inspect and service winch.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Fuel Filter	1.00
	Toggle Switch	1.00
	Fuel Cap	2.00
	Fr Pump	1.00
	Shop Supplies	1.00
Hours 8.30	Labor: 498.00	Parts: 678.80
:		Total: 1,176.80

Workorder: 1800055 **Meter:** 45515 **In Date:** 01/03/2018 **Closed:** 01/04/2018
Problem: Right side wiper blade coming apart.

- Test and replace right side wiper blade.retest.	Parts List	Qty
	20" Wiper Blade	1.00
Hours 0.20	Labor: 12.00	Parts: 3.39
:		Total: 15.39

Workorder: 1801086 **Meter:** 45765 **In Date:** 01/30/2018 **Closed:** 01/31/2018
Problem: Had to jump start at roads lot.

- Charge batteries fully.test batteries and charging system.r&r both failed batteries.	Parts List	Qty
- Shop Supplies	Battery	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 259.28
:		Total: 379.28

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1805333 **Meter:** 47113 **In Date:** 05/24/2018 **Closed:** 06/05/2018
Problem: P.M. service and towed in stalled.

- P.m. service.	Parts List	Qty
- Check and replace all four rear body mounts . Replace both rear shock absorbers.	left door check asy	1.00
- Check and replace both defective reverse light bulbs.	Selector Valve	1.00
- Check and remove left front door panel to replace door check .	Sender Assembly	1.00
- Inspect and service auxiliary fuel tank .	Shock	2.00
- Check , pinpoint test fuel system .remove rear fuel tank to replace sender. Replace fuel switchinh valve . Add fuel to rear tank and bleed fuel system. Retest.	Napagold Oil Filter	1.00
- Inspect and service winch.	15-40 Oil	15.00
- Balance and rotate all six tires.	Used Fire X Refurbished	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Seal Kit	1.00
	Fuel Filter Ford Only	1.00
	Body Mount Kit	4.00
	Led Back-up Lamp Sys	2.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 19.00	Labor: 1,140.0	Parts: 1,958.78
:	0	Total: 3,098.78

Workorder: 1805393 **Meter:** 46798 **In Date:** 05/24/2018 **Closed:** 05/29/2018
Problem: Shut off and can not start u

- Tow From: North Bound 95 Under Pga Sign To: tow to Lv Shop

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1807032 **Meter:** 47727 **In Date:** 07/11/2018 **Closed:** 07/12/2018
Problem: Operator states that when he takes off from a stop, that the engine revs up and is loud.

- Diagnose engine noise . Engine overheating causing fan to stay on high cool. Pressure test cooling system .r&r defective radiator. flush cooling system . Test drive.	Parts List	Qty
- Shop Supplies	Peak Global Antifrz	2.00
	Radiator	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 922.88
:		Total: 1,282.88

Workorder: 1811076 **Meter:** 48720 **In Date:** 10/29/2018 **Closed:** 10/31/2018
Problem: clean fuel tank

- fuel tank clean and polish	Parts List	Qty
- Shop Supplies	Startron 8oz Fuel Trt	1.00
	Motor Treatment Gal	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 201.00	Parts: 68.84
:		Total: 269.84

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1900475 **Meter:** 49453 **In Date:** 01/11/2019 **Closed:** 01/16/2019
Problem: PM Service

- P.m. service.	Parts List	Qty
- Test and repair circuit to tag light and replace tag light .	Napagold Oil Filter	1.00
Replace right headlamp bulb .	15-40 Oil	15.00
- Inspect and service auxillary fuel tank .	Fuel Filter Ford Only	1.00
- Rotate and high speed balance all six wheels . Nitrofill all.	Washer Fluid Concentr	1.00
- Inspect and service winch .	20" Wiper Blade	2.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Napagold Air Filter	1.00
	Bat Term Protector	1.00
	License Bracket W/light	1.00
	Halogen Sealed Beams	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 536.00	Parts: 214.41
:		Total: 750.41

Workorder: 1907789 **Meter:** 51128 **In Date:** 07/26/2019 **Closed:** 07/31/2019
Problem: PM Service

- P.m. Service.	Parts List	Qty
- Inspect and service aux. fuel system.	Napagold Oil Filter	1.00
- Inspect and service winch.	15-40 Oil	15.00
- Rotate and balance all tires.	20" Wiper Blade	2.00
- Shop Supplies	Fuel Filter Ford Only	1.00
	Used Fire X Refurbished	1.00
	trailer plug	1.00
	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours 7.50	Labor: 502.50	Parts: 189.08
:		Total: 691.58

Workorder: 1909102 **Meter:** 51619 **In Date:** 08/30/2019 **Closed:**
Problem: Battery

-	Labor: 0.00	Parts: 0.00	Total: 0.00
Hours 0.00			
:			

Workorder: 1909103 **Meter:** 51620 **In Date:** 08/30/2019 **Closed:** 09/09/2019
Problem: Battery blew up, Parked at roads.

- Test batteries and charging system . R&r defective batteries .	Parts List	Qty
- Shop Supplies	Battery	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 134.00	Parts: 290.61
:		Total: 424.61

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1909344 **Meter:** 51830 **In Date:** 09/11/2019 **Closed:** 09/16/2019
Problem: Toggle switch for aux fuel tank inop.

- Test and replace defective toggle switch for aux fuel pump .

		Parts List	Qty
		Toggle Switch	1.00
Hours 0.50	Labor: 33.50	Parts: 9.30	Total: 42.80
:			

Workorder: 1910222 **Meter:** 51984 **In Date:** 10/02/2019 **Closed:** 10/07/2019
Problem: Fuse for parking lights keeps blowing .

- Diagnose parking light fuse blowing . Trace circuit to locate short to ground . Replace wire from right front utility box to main power . Replace fuse and retest .

		Parts List	Qty
		Fab Loom-split Poly	20.00
		Primary Wire	20.00
- Shop Supplies		Shop Supplies	1.00
Hours 2.00	Labor: 146.00	Parts: 14.20	Total: 160.20
:			

Workorder: 2001862 **Meter:** 52862 **In Date:** 02/25/2020 **Closed:** 02/25/2020
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			