		101	98895	2015 FORD	ESCAPI	E Suv, Mid	Size			
Workorder: Problem:	1507780 1061 - Pre De	Meter: elivery Insp	•			In Date:	08/04/2015	Closed:	08/04/20	015
- Pre Delivery	Inspection									
	Hou :	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1600033 Pm service.	Meter:	11396			In Date:	01/04/2016	Closed:	01/20/20	016
- Pm service.					Parts L	ist				Qty
- Rotate and b	balance all fou	r tires.			5w20 Ei	ngine Oil				6.00
- Shop Suppli	es				Napago	ld Oil Filter				1.00
					Washer	Fluid Conc	entr			1.00
					Shop Su	upplies				1.00
	Hou :	rs 3.00		Labor:	180.00	Parts:	19.84	Total:	199.84	
Workorder: Problem:	1601107 Replace fire of	Meter:	12585 er that wa	s used.		In Date:	02/01/2016	Closed:	02/04/20	016
		•			Parts L	ict				041
- Replace spe	int me extingu	ISHEL.				re X Refurb	ishod			Qty 1.00
	Hou	rs 0.30		Labor:			19.62	Total:	37.62	1.00
Workorder: Problem:	1604092 P.M. Service	Meter:	18540			In Date:	04/19/2016	Closed:	04/26/20	016
- P.m. Service	9.				Parts L	ist				Qty
- Replace blov	wn power outle	et fuse.			Napago	ld Oil Filter				1.00
- Rotate and b	balance all tire	s.			5w20 Ei	ngine Oil				6.00
- Shop Suppli	es				Washer	Fluid Conc	entr			1.00
					Accufit I	Beam				2.00
					Blade					1.00
					Fuse					1.00
					Shop Su	upplies				1.00
	Hou :	rs 3.50		Labor:	210.00	Parts:	77.56	Total:	287.56	
Workorder: Problem:	1606943 P.M. service.	Meter:	24936			In Date:	07/11/2016	Closed:	07/25/20	016
- P.m. Service	Э.				Parts L	ist				Qty
- Replace two	tires,rotate ar	nd balance	all four.		5w20 Ei	ngine Oil				6.00
- Complete wi	neel alignmen	t.test drive.			Napago	ld Oil Filter				1.00
- Repair and b	balance right f	ront tire.			Wd40 1	6oz				1.00
- Shop Suppli	-				235/55r	17 Assurance	се			2.00
					Shop Su	upplies				1.00
					-					
					Tire Dis	posal Fee				2.00

Workorder: Problem:	1609077 Battery goe	Meter: s dead.	28857			In Date:	08/31/2016	Closed:	09/20/20)16
- Recharge ba			ystem,good.	reprogram	Parts Lis	st				Qty
Ipc per Tsb Ss - Shop Suppli					Shop Su	pplies				1.00
		ours 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder:		Meter:	30488			In Date:	10/04/2016	Closed:	10/14/20)16
Problem:	P.M. service	e check batte	ery.							
- P.m. Service	e.				Parts Lis	st				Qty
- Recharge ba			test.replace	defective	5w20 En	-				6.00
battery and ter - Rrotate and						d Oil Filter				1.00
- Shop Suppli		1165.			Accufit B					2.00
	103				Wpr/blde					1.00
						Fluid Conce				1.00
						ft 96r Batte	ery			1.00
	Ца	ours 4.00		Lobor	Shop Su 240.00	• •	220.45	Total	460.45	1.00
	:	Juis 4.00		Labor.	240.00	Paris.	220.45	TOTAL	400.45	
Workorder: Problem:	1610681 Left rear tire	Meter: e going flat.	31795			In Date:	10/17/2016	Closed:	10/31/20)16
- Repair and I	balance left r	ear tire.			Parts Lis	st				Qty
Shop Suppl										
 Shop Suppli 	ies				Shop Su	pplies				1.00
- Shoh Sabbi		ours 1.00		Labor:		pplies Parts:	2.00	Total:	62.00	1.00
Workorder:		Meter:	37608 15c06.	Labor:	60.00	• •	2.00 01/09/2017	Total: Closed:	62.00 02/13/20	
Workorder:	Ho : 1700220 P.M. service	Meter:		Labor:	60.00	Parts:				1.00)17 Qty
Workorder: Problem:	Ho : 1700220 P.M. service e.	Meter: e and recall		Labor:	60.00	Parts:)17
Workorder: Problem: - P.m. Service - Re;place an - Transport ve	Ho 1700220 P.M. service e. nd balance for ehicle to deal	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En	Parts:)17 Qty
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho : 1700220 P.M. service e. d balance for ehicle to deal aking oil.	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En Napagolo	Parts: In Date: st gine Oil	01/09/2017			017 Qty 6.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve	Ho : 1700220 P.M. service e. d balance for ehicle to deal aking oil.	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B	Parts: In Date: st gine Oil d Oil Filter bin Air Filte eam	01/09/2017 er			017 Qty 6.00 1.00 1.00 2.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho : 1700220 P.M. service e. d balance for ehicle to deal aking oil.	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I	Parts: In Date: st gine Oil d Oil Filter bin Air Filte eam Fluid Conce	01/09/2017 er entr			017 Qty 6.00 1.00 2.00 1.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho : 1700220 P.M. service e. d balance for ehicle to deal aking oil.	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurance	01/09/2017 er entr			017 Qty 6.00 1.00 2.00 1.00 4.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho : 1700220 P.M. service e. d balance for ehicle to deal aking oil.	Meter: e and recall f ur new tires.	15c06.		60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su	Parts: In Date: st gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurance pplies	01/09/2017 er entr			017 Qty 6.00 1.00 2.00 1.00 4.00 1.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies	Meter: e and recall f ur new tires. ler for recall f	15c06.	engine	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurance pplies bosal Fee	01/09/2017 er entr ce	Closed:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 4.00 4.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies	Meter: e and recall f ur new tires.	15c06.	engine	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurance pplies bosal Fee	01/09/2017 er entr	Closed:		017 Qty 6.00 1.00 2.00 1.00 4.00 4.00 4.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies	Meter: e and recall of ur new tires. ler for recall of ours 6.00 Meter:	15c06. #15c06 and 39457	engine Labor:	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurance pplies bosal Fee	01/09/2017 er entr ce	Closed:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 4.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies Ho 1702343 Replace spe	Meter: e and recall of ur new tires. ler for recall of burs 6.00 Meter: ent fire exting	15c06. #15c06 and 39457	engine Labor:	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assuranc pplies bosal Fee Parts: In Date:	01/09/2017 er entr ce 642.79	Closed: Total:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 9 017
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies Ho 1702343 Replace spe e extinguisher	Meter: e and recall f ur new tires. ler for recall f ours 6.00 Meter: ent fire exting	15c06. #15c06 and 39457 guisher. Che	engine Labor: eck brake n	60.00 Parts Lis 5w20 En Napagole Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00 oise. Parts Lis	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assuranc pplies bosal Fee Parts: In Date:	01/09/2017 er entr ce 642.79 03/08/2017	Closed: Total:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 4.00 9 017 Qty
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli Shop Suppli	Ho 1700220 P.M. service e. Ind balance for ehicle to deal aking oil. ies Ho 1702343 Replace spe- e extinguisher or noisy brake	Meter: e and recall f ur new tires. ler for recall f ours 6.00 Meter: ent fire exting	15c06. #15c06 and 39457 guisher. Che	engine Labor: eck brake n	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00 oise. Parts Lis Used Fire	Parts: In Date: st gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurand pplies bosal Fee Parts: In Date:	01/09/2017 er entr ce 642.79 03/08/2017 shed	Closed: Total:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 4.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli Shop Suppli	Ho 1700220 P.M. service e. hd balance for ehicle to deal aking oil. ies Ho 1702343 Replace spe- e extinguisher or noisy brake per.	Meter: e and recall a ur new tires. ler for recall a burs 6.00 Meter: ent fire exting c. e complain.cl	15c06. #15c06 and 39457 guisher. Che	engine Labor: eck brake n	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00 oise. Parts Lis Used Fire	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurand pplies bosal Fee Parts: In Date: st e X Refurbi 7 Assurand	01/09/2017 er entr ce 642.79 03/08/2017 shed	Closed: Total:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 017 Qty 1.00
Workorder: Problem: - P.m. Service - Re;place an - Transport ve front cover lea - Shop Suppli Shop Suppli Workorder: Problem: - Replace fire - Road test fo and lube calip	Ho 1700220 P.M. service e. Ind balance for ehicle to deal aking oil. ies Ho 1702343 Replace spe e extinguisher or noisy brake ber. d balance left	Meter: e and recall a ur new tires. ler for recall a burs 6.00 Meter: ent fire exting c. e complain.cl	15c06. #15c06 and 39457 guisher. Che	engine Labor: eck brake n	60.00 Parts Lis 5w20 En Napagolo Napa Ca Accufit B Washer I 235/55r1 Shop Su Tire Disp 360.00 oise. Parts Lis Used Firo 235/55r1 Shop Su	Parts: In Date: gine Oil d Oil Filter bin Air Filte eam Fluid Conce 7 Assurand pplies bosal Fee Parts: In Date: st e X Refurbi 7 Assurand	01/09/2017 er entr ce 642.79 03/08/2017 shed	Closed: Total:	02/13/20	017 Qty 6.00 1.00 2.00 1.00 4.00 4.00 9 017 Qty 1.00 1.00

Workorder: Problem:	1703106 Rear Flat tire	Meter:	38822			In Date:	03/27/2017	Closed:	03/28/20)17
- Tire Service - Rear Flat tire	South County	Regional I	Park Maint C	Compound						
	Hour :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1705594 P.M. service.	Meter:	42346			In Date:	06/06/2017	Closed:	06/23/20)17
- P.m. Service	э.				Parts L	.ist				Qty
- Replace two	o tires,rotate an	d abalnce	all four.		Wire As	Sy				1.00
- R&r left fron	t seat for uphol	lstery repa	ir.		Seat R	And R				1.00
	op right rear do				Latch					2.00
•	efective actuato	or and mel	ted harness.		5w20 E	ngine Oil				6.00
- Shop Suppli	les					old Oil Filter				1.00
					Accufit					2.00
						r Fluid Conce	entr			1.00
					Wpr/blc					1.00
						17 Assuranc	ce			2.00
					Shop S					1.00
				Laban		sposal Fee	005 07	Tatal	4 005 05	2.00
	Hour :	rs 7.00		Labor:	420.00	Parts:	965.07	i otai:	1,385.07	/
Workorder:	1706585	Meter:	42971			In Date:	07/05/2017	Closed:	07/10/20)17
Problem:	Driver side mi	irror inop.								
	eft outside mirro	or inop.r&r	defective m	irror motor	Parts L	.ist				Qty
assembly rete					Motor A	Asy				1.00
- Shop Suppli	ies				Shop S	upplies				1.00
	Hour :	rs 0.80		Labor:	48.00	Parts:	42.05	Total:	90.05	
Workorder: Problem:	1709702 Front wipers b	Meter: binding.	45305			In Date:	10/04/2017	Closed:	10/05/20)17
- Test and rep	place both front	t wiper bla	des .retest.		Parts L	.ist				Qty
					Wiper E	Blade				1.00
					Wiper E	Blade				1.00
	Hour :	rs 0.20		Labor:	12.00	Parts:	37.50	Total:	49.50	
West and an	1710102	Meter:	45983			In Date:	10/16/2017	Closed:	10/19/20)17
Workorder: Problem:	Left brake ligh	nt inop.								
Problem:	Left brake ligh blace left brake		retest.		Parts L	.ist				-
Problem:	place left brake		retest.	Labor:	Bulb	. ist Parts:			18.78	Qty 1.00

Workorder: Problem:	1711565 P.M. service.	Meter:	47081			In Date:	11/27/2017	Closed:	11/29/20	017
- P.m. service					Parts L	ict				Qty
	, rakes.r&i new fr	ont brake	nade recurf	ace both		ngine Oil				6.00
front rotors.roa			paus.resuri			ld Oil Filter				1.00
- Rotate and	high speed bala	nce all for	ur wheels.nit	tro fill all.	Wiper B					1.00
- Shop Suppli	• •				Wiper B					1.00
					Blade	iaue				1.00
						Fluid Conc	entr			1.00
						or Brake Cl				1.00
					Brake P					1.00
					Shop S					1.00
	Hours	6.00		Labor:	360.00		164.38	Total	524.38	1.00
	:	5 0.00		Labor.	000.00	1 0113.	104.00	Total.	024.00	
Workorder: Problem:	1711899 Right brake lig	Meter: ht inop.	47224			In Date:	12/05/2017	Closed:	12/07/20	017
- Test and rep	place right brake	e light bulk	and retest.		Parts L	ist				Qty
					Bulb					2.00
	Hours	s 0.50		Labor:	30.00	Parts:	1.53	Total:	31.53	
Workorder: Problem:	1712109 Vehicle had to	Meter: jump star	47347 ted in A.M.			In Date:	12/11/2017	Closed:	12/19/20	017
good.scan cor spare .	mputer pulled co Hours	ode B10d7 s 0.50	/ .swaped ke	ey with Labor:	30.00	Parts:	0.00	Total:	30.00	
	:	••						<u> </u>	10/00/0	
Workorder:	1712578 Car would nor	Meter:	47347	vehicle was	off with	In Date:	12/20/2017	Closed:	12/28/20	J17
Fibblem.		Start, Mar	iyei stateu v		On with	overneau nç	gins on.			
for draw,none	ead battery.rech found at this tin work without ve	ne .drive s	aid lights w							
	Hours	s 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	
Workorder:		Meter:	48273			In Date:	01/31/2018	Closed:	02/01/20	018
Problem:	Has to jump st	art after u	sing overhe	ad lights.						
- Charge batt	ery fully .test ba	ttery .faile	d load test .	r&r	Parts L	ist				Qty
defective batte	ery.test charging	, system	ok.test load		Battery					1.00
	le off over ten a	mps with	lights on.		•	Terminal Pr	otectors			1.00
- Shop Suppli	les				Shop S					1.00
	Hours	s 1.00		Labor:			186.01	Total:	246.01	
Workorder:	1803236	Meter:	49441			In Date:	03/28/2018	Closed:	04/04/20	018
Problem:	Replace used	fire exting	uisher.							
- Replace use	ed fire extinguis	ner.			Parts L	ist				Qty
					Used Fi	re X Refurb	ished			1.00
	Hours	s 0.30		Labor:	18.00	Parts:	14.19	Total:	32.19	

:

Workorder: Problem:	1804977 P.M. service.	Meter:	50459		I	n Date:	05/14/2018	Closed:	05/17/2	018
- P.m. service	Э.				Parts List	t				Qty
	balance four ne	ew tires.nitr	ogen fill and	reset	Napagold	Oil Filter				1.00
Tpms.			5		5w20 Eng					6.00
- Perform four	r wheel alignm	ient.			Mac Wite		ires			1.00
- Shop Suppli	ies				Washer F	luid Conce	entr			1.00
					235/55r17	'Assurance	ce			4.00
					Shop Sup	plies				1.00
					Tire Dispo	osal Fee				4.00
	Hou :	rs 6.50		Labor:	390.00	Parts:	664.71	Total:	1,054.7	1
Workorder: Problem:	1809069 Low tire pres	Meter: sure light is	53893 s on.		I	n Date:	09/04/2018	Closed:	09/06/2	018
- Repair left re	ear tire and ba	lance . Nitr	ofill.		Parts List	t				Qty
- Shop Suppli			-		Shop Sup					1.00
		rs 1.00		Labor:		Parts:	2.00	Total:	62.00	
	•					n Date:	10/02/2018	Closed:	10/04/2	018
	1810211 Both rear tire	Meter: side wall c	54936 lamage .		I	n Date.	10,02,2010			
- Replace two	Both rear tire o rear tires and	side wall c	lamage .	all	Parts List		10,02,2010			Qty
Problem: - Replace two damage . Nitro	Both rear tire o rear tires and ofill.	side wall c	lamage .	all		t	10,02/2010			-
Problem:	Both rear tire o rear tires and ofill.	side wall c	lamage .	all	Parts List Tire Mic 2 Shop Sup	t 35/55/17 plies	10/02/2010			2.00 1.00
Problem: - Replace two damage . Nitro	Both rear tire o rear tires and ofill. ies	side wall c I balance .c	lamage .		Parts List Tire Mic 2 Shop Sup Tire Dispo	t 35/55/17 plies osal Fee				2.00 1.00
Problem: - Replace two damage . Nitro	Both rear tire o rear tires and ofill. ies	side wall c	lamage .	all Labor:	Parts List Tire Mic 2 Shop Sup Tire Dispo	t 35/55/17 plies osal Fee	410.32		477.32	2.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder:	Both rear tire o rear tires and ofill. ies	side wall c I balance .c rs 1.00 Meter:	lamage .		Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee			477.32 10/18/2	2.00 1.00 2.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder:	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service.	side wall c I balance .c rs 1.00 Meter:	lamage . lue to side w		Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: n Date:	410.32	Total:		
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service.	side wall o I balance .c Irs 1.00 Meter:	lamage . lue to side w	Labor:	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies bsal Fee Parts: n Date:	410.32	Total:		2.00 1.00 2.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove fror	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and bat	side wall of I balance .c Irs 1.00 Meter: Sembly for r tery tray to	lamage . lue to side w 55172 epair . Reins	Labor: tall seat .	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: In Date: t Oil Filter	410.32	Total:		2.00 1.00 2.00 018 Qty
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove fror strobe light an	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and bath od wire . Retes	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: n Date: t Oil Filter jine Oil	410.32	Total:		2.00 1.00 2.00 018 Qty 1.00 6.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and l	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies bsal Fee Parts: In Date: t Oil Filter jine Oil de	410.32	Total:		2.00 1.00 2.00 018 018 018 018 0.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove fror strobe light an	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies bsal Fee Parts: In Date: t Oil Filter jine Oil de	410.32	Total:		2.00 1.00 2.00 018 018 018 1.00 6.00 1.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and l	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: In Date: t Oil Filter jine Oil de de	410.32 10/10/2018	Total:		2.00 1.00 2.00 018 Qty 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and l	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: n Date: t Oil Filter jine Oil de de	410.32 10/10/2018 entr	Total:		2.00 1.00 2.00 018 018 018 018 0.00 1.00 1.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and l	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: n Date: t Oil Filter jine Oil de de	410.32 10/10/2018 entr	Total:		2.00 1.00 2.00 018 Qty 1.00 1.00 1.00 1.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and h	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: n Date: t Oil Filter jine Oil de de luid Conce Led Clea	410.32 10/10/2018 entr	Total:		2.00 1.00 2.00 018 Qty 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - Replace two damage . Nitro - Shop Suppli Workorder: Problem: - P.m. service - Remove left - Remove light an - Rotate and h	Both rear tire o rear tires and ofill. ies Hou : 1810435 P.M. service. e. t front seat ass nt grill and batt nd wire . Retes high speed bal	side wall c I balance .c rs 1.00 Meter: embly for r tery tray to t.	lamage . lue to side w 55172 epair . Reins replace left f	Labor: tall seat . ront	Parts List Tire Mic 2 Shop Sup Tire Dispo 67.00	t 35/55/17 plies osal Fee Parts: In Date: t Oil Filter jine Oil de de luid Conce Led Clea	410.32 10/10/2018 entr	Total:		2.00 1.00 2.00 018 Qty 1.00 1.00 1.00 1.00 1.00 8.00

Workorder: Problem:	1812673 Had to jump	Meter: start .	57082			In Date:	12/13/2018	Closed:	12/18/20	18
	ery fully . Test				Parts Lis	st				Qty
	load test . R&r			egative	Battery					1.00
-	. Reset battery	module lo	rius.		Bat Cable	е				1.00
- Shop Suppli	ies				Shop Su	pplies				1.0
	Hou :	rs 1.50		Labor:	100.50	Parts:	250.76	Total:	351.26	
Workorder: Problem:	1900033 Front passen	Meter: ger headlig	57477 ght out.			In Date:	01/02/2019	Closed:	01/07/20	19
- Test and rep	place right low	beam head	dlight bulb .		Parts Lis	st				Qty
					Blister Pa	ack Capsul	es			1.00
	Hou :	rs 0.50		Labor:	33.50	Parts:	12.59	Total:	46.09	
Workorder: Problem:	1901925 Check A/C m	Meter: node stuck	58826 on floor .			In Date:	02/20/2019	Closed:	02/27/20	19
	ance test . Sca			ids . R&r	Parts Lis	st				Qty
	le door actuato	or . Retest .			Motor A/d	c Blondor				1.00
 Shop Suppli 	ies				Shop Su	oplies				1.0
	Hou :	rs 2.00		Labor:	134.00		30.92	Total:	164.92	
	Hou : 1903557 P.M. service.	Meter:	59899	Labor:	134.00		30.92 04/02/2019	Total: Closed:	164.92 04/08/20	19
Problem:	: 1903557 P.M. service.	Meter:	59899	Labor:	134.00	Parts:				019 Qty
Problem: - P.m. service	: 1903557 P.M. service.	Meter:	59899	Labor:	134.00 Parts Lis	Parts:	04/02/2019			Qty
Problem: - P.m. service - Replace bot - Replace two	: 1903557 P.M. service. e. h rear leaking o worn tires . R	Meter:			134.00 Parts Lis Ford Trite	Parts: In Date:	04/02/2019			Qty 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr	: 1903557 P.M. service. e. th rear leaking o worn tires . R rofill all.	Meter: shocks . totate and h	nigh speed b	alance all	134.00 Parts Lis Ford Trite	Parts: In Date: St on Pvc Swo d Oil Filter	04/02/2019			Qty 1.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove fror	: 1903557 P.M. service. e. th rear leaking o worn tires . R rofill all. nt bumper cov	Meter: shocks . totate and h	nigh speed b	alance all	134.00 Parts Lis Ford Trito Napagolo	Parts: In Date: St on Pvc Swo d Oil Filter	04/02/2019			Qty 1.00 1.00 6.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove fror strobe bulb as	: 1903557 P.M. service. a. th rear leaking o worn tires . R rofill all. nt bumper cov ssembly .	Meter: shocks . totate and h er to test an	nigh speed b nd replace le	alance all ft front	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng	Parts: In Date: on Pvc Swo d Oil Filter gine Oil	04/02/2019			Qty 1.00 1.00 6.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove fror strobe bulb as - Replace bro	: 1903557 P.M. service. c. th rear leaking o worn tires . R for the service of the service cont bumper cov sembly . oken right front	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade	04/02/2019			Qty 1.00 1.00 6.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade ade a X Refurbi bin Air Filte	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock Ab	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade ade a X Refurbi bin Air Filte	04/02/2019			Qty 1.00 6.00 1.00 1.00 1.00 2.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock Ab	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade ade ade bin Air Filte psober	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00 1.00 2.00 2.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove from strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock At Tire235/5	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade ade ade bin Air Filte psober	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00 2.00 1.00
Problem: - P.m. service - Replace bot - Replace two our tires . Nitr - Remove fror strobe bulb as - Replace bro - Pressure tes	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock Ab Tire235/5 Lighting Handle	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade ade ade bin Air Filte psober	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00 2.00 2.00 1.00 1
Problem: - P.m. service - Replace bot - Replace two four tires . Nitr - Remove fror strobe bulb as - Replace bro	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock Ab Tire235/5 Lighting Handle	Parts: In Date: on Pvc Swo d Oil Filter gine Oil ade ade e X Refurbi bin Air Filte osober 55/17 Mic	04/02/2019			Qty 1.00 1.00 1.00 1.00 1.00 2.00 1.00 1.00
 P.m. service Replace bot Replace two four tires . Nitr Remove fror strobe bulb as Replace bro Pressure tes 	: 1903557 P.M. service. An rear leaking o worn tires . R rofill all. Int bumper cov ssembly . oken right front st and inspect	Meter: shocks . dotate and h er to test an asisst han	nigh speed b nd replace le dle assembly	alance all ft front /.	134.00 Parts Lis Ford Trito Napagolo 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Ca Shock Ab Tire235/5 Lighting Handle Anti Free	Parts: In Date: In Da	04/02/2019			

Workorder:1907572Meter:63361Problem:Shifting hard at times .	In Date: 07/22/2019 Closed:	08/06/2019
- Replace broken front motor mount.	Parts List	Qty
- Cv axles noisy when turning replace both axles.	Engine Mount	1.00
- Scan system for codes.relearn Kam and shift points.flush	Axle Nut	2.00
and refill transmission.test drive.	Left Front Axle	1.00
- Shop Supplies	Shaft Assy Motorcraft	1.00
	oil auto	10.00
	Shop Supplies	1.00
Hours 7.50 Labor	502.50 Parts: 650.94 Total:	1,153.44
Workorder:1908343Meter:63688Problem:Right brake light inop.	In Date: 08/12/2019 Closed:	08/15/2019
- Test and replace right brake light bulb .	Parts List	Qty
	Boxed Miniatures	1.00
Hours 0.50 Labor	33.50 Parts: 0.77 Total:	34.27
Workorder:1908591Meter:63827Problem:Left low beam headlight inop.	In Date: 08/16/2019 Closed:	08/19/2019
- Test and replace left low beam headlight bulb .	Parts List	Qty
	Blister Pack Capsules	1.00
Hours 0.50 Labor	33.50 Parts: 12.59 Total:	46.09
Workorder:1910040Meter:64763Problem:P.M. service.	In Date: 09/30/2019 Closed:	10/02/2019
- P.m. service.	Parts List	Qty
- Test and replace left lower marker light bulb.	Napagold Oil Filter	1.00
- Fabericate and replace front asset decal .	5w20 Engine Oil	6.00
- Rotate and balance all four tires . Repair left rear tire .	Blade	1.00
Nitrofill all .	Wiper Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Napa Air Filter	1.00
	Boxed Miniatures	1.00
	Shop Supplies	1.00
Hours 5.00 Labor	365.00 Parts: 92.62 Total:	457.62

:

Workorder: 2000365 Meter: 69577 Problem: P.M. service.	In Date:	01/13/2020	Closed:	01/16/2020
- P.m. service.	Parts List			Qty
- Replace two tires . Rotate and high speed balance all four	Napagold Oil Filter			1.00
tires . Nitrofill all.	5w20 Engine Oil			6.00
- Replace defective right lowwer control arm due to play in ball joint .	Blade			1.00
- Complete four wheel alignment and road test .	Wiper Blade			1.00
- Shop Supplies	Wiper Blade			1.00
- Shop Supplies	Tire235/55/17 Mic			2.00
	Arm Asy			1.00
	Used Fire X Refurb	ished		1.00
	Shop Supplies			1.00
	Tire Disposal Fee			2.00
Hours 8.20 Labo	598.60 Parts:	866.14	Total:	1,464.74
Workorder: 2006603 Meter: 73024 Problem: P.M. service.	In Date:	07/06/2020	Closed:	07/07/2020
- P.m. service.	Parts List			Qty
- Test and replace defective tag light bulbs .	Napagold Oil Filter			1.00
- Rotate and balance all four tires . Nitrofill all.	5w20 Engine Oil			6.00
- Shop Supplies	Washer Fluid Conc	entr		1.00
	Boxed Miniatures			2.00
	Shop Supplies			1.00
Hours 3.50 Labo	: 255.50 Parts:	26.23	Total:	281.73
Workorder: 2006671 Meter: 73024 Problem: Damage to passenger side front door, rear do	In Date:	05/26/2020	Closed:	07/07/2020
- Damage to passenger side front door, rear door, rear fender panels, and tail lamp assembly.	or, real lender parlets	s, and tail lamp	assembly.	
	: 0.00 Parts:	0.00	Total:	0.00
:	. 0.00 i uito.	0.00	rotai.	0.00
Workorder: 2007753 Meter: 73077	In Date:	08/05/2020	Closed:	08/05/2020
Problem: Transition Prep Charge				
- Transition Prep Charge				
Hours 2.00 Labo	: 146.00 Parts:	0.00	Total:	146.00