10198373 2015 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Problem:	1507868 1061 - Pre De	Meter: elivery Insp	130 ection			In Date:	08/06/2015	Closed:	08/06/201	5
- Pre Delivery	Inspection									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1509341 Install D.M.I u	Meter: nit.	1427			In Date:	09/16/2015	Closed:	10/13/201	5
- Fabricate ar	nd install Dmi u	nit.test ope	eration.		Parts Li	st				Qty
- Install windo	w vent visors.	•			D . M. I				1	1.00
- Shop Suppli	ies				Vent Vis	ors			1	1.00
					Shop Su	pplies			1	1.00
					Freight (	Charge			1	1.00
	Hour	s 4.50		Labor:	270.00	Parts:	1,533.44	Total:	1,803.44	
Workorder: Problem:	1601021 Pm service.	Meter:	7348			In Date:	01/29/2016	Closed:	02/04/201	6
- Pm service.					Parts Li	st				Qty
- Inspect and	service winch.				5w20 Er	igine Oil			7	7.00
- Rotate and I	balance all four	tires.			Napagol	d Oil Filter			1	1.00
- Shop Suppli	ies				Washer	Fluid Conce	entr		1	1.00
					Shop Su	pplies			1	1.00
	Hour :	s 4.75		Labor:	285.00	Parts:	21.23	Total:	306.23	
Workorder: Problem:	1605032 P.M. Service.	Meter:	12282			In Date:	05/13/2016	Closed:	05/24/201	6
- P.m. Service	е.				Parts Li	st				Qty
- Inspect and	service winch.				5w20 Er	igine Oil			7	7.00
- Rotate and I	balance all tires	S.			Napagol	d Oil Filter			1	1.00
reduce and r					Washer	Fluid Cana	entr		1	1.00
- Shop Suppli	ies				vvasiloi	Fluid Conce	J1101			
	ies					e X Refurbi			1	1.00
	ies					e X Refurbi				
		rs 4.75		Labor:	Used Fir	e X Refurbi	shed	Total:		1.00
- Shop Suppli Workorder:		Meter:	12820	Labor:	Used Fir Shop Su	e X Refurbi pplies	shed	Total:	1	1.00 1.00
- Shop Suppli Workorder:	Hour : 1605537 Replace hitch	Meter:	12820	Labor:	Used Fir Shop Su	e X Refurbi pplies Parts: In Date:	shed 40.49		325.49	1.00 1.00
- Shop Suppli Workorder: Problem:	Hour : 1605537 Replace hitch	Meter:	12820	Labor:	Used Fir Shop Su 285.00	e X Refurbi pplies Parts: In Date:	shed 40.49		325.49	1.00 1.00 6
- Shop Suppli Workorder: Problem:	Hour : 1605537 Replace hitch	Meter:	12820	Labor:	Used Fir Shop Su 285.00	e X Refurbi pplies Parts: In Date: st n W/chain	shed 40.49		325.49 06/09/201	1.00 1.00 6 <b>Qty</b>

Problem: P.M. se	89 <b>Meter:</b> ervice and shimm	18158 y in front tires	s ,winch,h		n Date:	09/29/2016	Closed:	09/30/20	16
- P.m. Service.				Parts List					Qty
- Rotate and balance	tires.			Napagold (					1.00
- Inspect and service		5w20 Engi					8.00		
- Shop Supplies	22" Wiper					2.00			
onep ouppines				Napagold A					1.00
				Macs Chai		_ube			1.00
				Shop Supp					1.00
	Hours 5.25		Labor:	315.00	Parts:	45.43	Total:	360.43	
Workorder: 170118 Problem: P.M. se		25627		Ir	n Date:	02/03/2017	Closed:	02/16/20	17
- P.m Service.				Parts List					Qty
- Rotate and balance	tires.			5w20 Engi	ne Oil				7.00
- Shop Supplies				Napagold (	Oil Filter				1.00
				22" Wiper	Blade				2.00
				Washer Flu	uid Conce	entr			1.00
				Mac Wite L	_ithium G	res			1.00
				Shop Supp	olies				1.00
	Hours 3.75		Labor:	225.00	Parts:	34.12	Total:	259.12	
Workorder: 170510 Problem: P.M. se		30107	eds.	lr	n Date:	05/23/2017	Closed:	05/25/20	17
- P.m. service.		, ,		Parts List					Qty
Daniaca all favor tira	e nitrogen fill tiree	.high speed	halanaa	5w20 Engi	ne Oil				
- Replace all four tires	s.muogen iii iires		Dalance	SWZU Eligi					7.00
four tires.	-		Dalalice	Napagold (					7.00
four tires. - Perform front end al	lignment.test drive	).	Dalance	ū	Oil Filter				
four tires Perform front end al - Inspect and service	lignment.test drive	١.	Dalalice	Napagold (	Oil Filter Blade	shed			1.00
four tires Perform front end al	lignment.test drive	).	Dalance	Napagold (22" Wiper	Oil Filter Blade	shed			1.00 2.00
four tires Perform front end al - Inspect and service	lignment.test drive	) <u>.</u>	Dalance	Napagold (22" Wiper Used Fire 2	Oil Filter Blade X Refurbi	shed			1.00 2.00 1.00
four tires Perform front end al - Inspect and service	lignment.test drive	ı.	Dalance	Napagold (22" Wiper Used Fire	Oil Filter Blade X Refurbi Air Filter	shed			1.00 2.00 1.00 4.00
four tires Perform front end al - Inspect and service	lignment.test drive	).	Dalance	Napagold (22" Wiper Used Fire 2 Tire Napagold (22" Napagold (22")	Oil Filter Blade X Refurbi Air Filter blies	shed			1.00 2.00 1.00 4.00 1.00
four tires Perform front end al - Inspect and service	lignment.test drive	).		Napagold (22" Wiper Used Fire 27 Tire Napagold 27 Shop Supp	Oil Filter Blade X Refurbi Air Filter blies sal Fee	shed 1,094.16	Total:	1,589.16	1.00 2.00 1.00 4.00 1.00 4.00
four tires.  - Perform front end al  - Inspect and service  - Shop Supplies	lignment.test drive winch  Hours 8.25 :  Meter:	30457		Napagold (22" Wiper Used Fire 22 Napagold (22 Napagold (23 Napagold (2	Oil Filter Blade X Refurbi Air Filter blies sal Fee		Total:	1,589.16	1.00 2.00 1.00 4.00 1.00 4.00
four tires Perform front end al - Inspect and service - Shop Supplies  Workorder: 170548 Problem: Had to	lignment.test drive winch  Hours 8.25 : 50 Meter: jump start .	30457	Labor:	Napagold (22" Wiper Used Fire 22 Napagold (22 Napagold (23 Napagold (2	Oil Filter Blade X Refurbi Air Filter blies sal Fee Parts:	1,094.16			1.00 2.00 1.00 4.00 1.00 4.00
four tires.  - Perform front end al  - Inspect and service  - Shop Supplies  Workorder: 170548	lignment.test drive winch  Hours 8.25 :  50 Meter: jump start .  t battery and char	30457 ging system.	Labor: battery	Napagold (22" Wiper Used Fire 2 Tire Napagold (22 Shop Supp Tire Dispose 495.00	Oil Filter Blade X Refurbi Air Filter blies sal Fee Parts:	1,094.16			1.00 2.00 1.00 4.00 1.00 4.00
four tires.  - Perform front end al  - Inspect and service  - Shop Supplies  Workorder: 170548  Problem: Had to  - Reharge battery.tes	lignment.test drive winch  Hours 8.25 :  50 Meter: jump start .  t battery and char	30457 ging system.	Labor: battery	Napagold (22" Wiper Used Fire 2 Tire Napagold (25) Shop Suppring Dispose 495.00	Oil Filter Blade X Refurbi Air Filter blies sal Fee Parts:	1,094.16			1.00 2.00 1.00 4.00 1.00 4.00 4.00

Workorder: Problem:	1707145 Check oil lev	Meter: rel.	32741			In Date:	07/21/2017	Closed:	07/31/2	017
- Check oil le	vel .add oil.ins	spect for lea	ks.		Parts Lis	st				Qty
					5w20 En	gine Oil				2.00
	Hou	ırs 0.20		Labor:	12.00	Parts:	4.35	Total:	16.35	
Workorder:	1709089	Meter:	35421			In Date:	09/20/2017	Closed:	09/28/2	017
Problem:	Right brake	amp inop.R	eplace pintle	pin.P.M.	service ,v	isor clip fell	down.			
- Replace righ	nt rear tail ligh	t bulb.			Parts Li	st				Qty
- Replace pin	tle hitch pin w	ith lanyard.			Bulb					1.00
- P.m. service	and replace	missing scr	ew in visor cl	ip.	Pintle Pi	n W/clip				1.00
- Replace wo	rn front brake	pads.resurf	ace rotors.lu	be	5w20 En	gine Oil				7.00
calipers and fl		•			Napagol	d Oil Filter				1.00
<ul> <li>Replace cor needed.</li> </ul>	roeded trailer	plug socket	repair wirin	g as	22" Wipe	er Blade				2.00
	service powe	r winch			Pedal Pa	ad				1.00
•	balance four t				Brake Pa	ad Motorcra	aft			1.00
- Shop Suppli					B Fluid D	Oot 3-32oz				1.00
- опор оцррп	163				Non-chlo	or Brake Clr	nr			1.00
					trailer plu	ıg				1.00
					Macs Ch	ain Cable I	_ube			1.00
					Shop Su	pplies				1.00
	Hou :	ırs 10.55		Labor:	633.00	Parts:	163.52	Total:	796.52	
Workorder: Problem:	1710887 Check oil lev	Meter:	38723			In Date:	11/02/2017	Closed:	11/08/2	017
- Check oil le	vel and inspec	ct for leaks.	add a quart o	of oil .	Parts Lis	st				Qty
	·		·		5w20 En	gine Oil				1.00
	Hou	urs 0.20		Labor:	12.00	Parts:	2.18	Total:	14.18	
Workorder: Problem:	1712064 PM Service	Meter:	40329			In Date:	12/08/2017	Closed:	12/18/2	017
- P.m. service	<b>3</b> .				Parts Lis	st				Qty
	service winch	l <b>.</b>			5w20 En					7.00
•	high speed ba		oad force all	four tires		d Oil Filter				1.00
and index two					22" Wipe	er Blade				2.00
- Shop Suppl	ies				Washer	Fluid Conce	entr			1.00
					Mac Wite	e Lithium G	res			1.00
					Shop Su	pplies				1.00
	Hou	ırs 4.75		Labor:	285.00	Parts:	34.31	Total:	319.31	
Workorder: Problem:	1800073 3 - Wash tick	Meter: (et(s) issued	40383			In Date:	01/03/2018	Closed:	01/03/2	018
- 3 - Wash tic	ket(s) issued									
	• •	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
						. 3.10.		. 5 (4)		

Workorder: Problem:	1804970 PM Service.	Meter:	45939		I	n Date:	05/11/2018	Closed:	05/17/2	018
- P.m. service	1.				Parts List	t				Qty
- Perform tran		ice . Flush a	nd refill.		Napagold					1.00
- Rotate and b				t Tpms.	5w20 Eng					7.00
- Service and					Used Fire		ished			1.00
- Shop Supplie	-				Napagold					1.00
					Syn-atf Tr					12.00
					Non-chlor					1.00
					Shop Sup	plies				1.00
	Hou	urs 6.25		Labor:	375.00	-	95.27	Total:	470.27	
Workorder: Problem:	1808370 Right front ti	Meter: re going flat	51496		I	n Date:	08/15/2018	Closed:	08/15/2	018
- Repair right	front tire and	balance . N	itrogen fill tire	es.	Parts List	t				Qty
- Shop Supplie	es				Shop Sup	plies				1.00
	Hou :	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1808490 Repair left re	Meter:	51885 out.		I	n Date:	08/17/2018	Closed:	08/22/2	018
	•	3								
- Test and rep				i.	Parts List	t				Qty
				i.	Parts List Boxed Mir					-
				i.		niatures	et			1.00
	olace left brak			Labor:	Boxed Mir Stp Trn Tl	niatures Lgt Sock	et 10.64	Total:	40.64	1.00
- Test and rep	olace left brak	e light and surs 0.50			Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock		Total:	40.64	1.00
- Test and rep  Workorder:  Problem:	Hou : 1809234 P.M. service	e light and surs 0.50	socket .retest		Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts:	10.64			1.00
- Test and rep	Hou : 1809234 P.M. service	e light and surs 0.50  Meter:	socket .retest	Labor:	Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts:	10.64			1.00 1.00 018
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci	Hou : 1809234 P.M. service	urs 0.50  Meter:  od . Replace	52911 south	Labor:	Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts: n Date: t	10.64			1.00 1.00 018 Qty 7.00
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all f	Hou : 1809234 P.M. service sise under hoo ing . Retest .	urs 0.50  Meter:  od . Replace	52911 south	Labor:	Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts: n Date: t pine Oil Oil Filter	10.64			1.00 1.00 018 Qty 7.00 1.00
Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms	House left brake House 1809234 P.M. service hoise under hooking . Retest . Four tires . Balls sensor . retri	wrs 0.50  Meter:  od . Replace lance and nain Tpms.	52911 e number one	Labor: e cylinder place	Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts: In Date: t pine Oil Oil Filter X Refurb	10.64			1.00 1.00 018 Qty 7.00 1.00
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface re	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retreat	we light and surs 0.50  Meter:  od . Replace lance and nain Tpms.  ors . Replaces	52911 e number one itrofill all . Re	Labor: e cylinder place and	Boxed Mir Stp Trn Tl 30.00	niatures Lgt Sock Parts: In Date: t pine Oil Oil Filter X Refurb	10.64			1.00 1.00 018 Qty 7.00 1.00 2.00
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface re	Hou :  1809234 P.M. service  ing . Retest .  four tires . Bat sensor . retrear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn Tl 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper	niatures Lgt Sock Parts: In Date: t pine Oil Oil Filter X Refurb Blade	10.64 09/07/2018 ished			1.00 1.00 1.00 018 Qty 7.00 1.00 1.00 2.00 4.00
Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface reservice caliper	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn Tl 30.00 Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire	niatures Lgt Sock Parts: In Date: t pine Oil Oil Filter X Refurb Blade	10.64 09/07/2018 ished			1.00 1.00 1.00 018 Qty 7.00 1.00 2.00 4.00 1.00
- Test and rep  Workorder: Problem:  - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface reservice caliper	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn TI 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy	Lgt Sock Parts:  In Date:  t ine Oil Oil Filter X Refurb Blade Brake Cli	10.64 09/07/2018 ished	Closed:		1.00 1.00 1.00 018 Qty 7.00 1.00 2.00 4.00 1.00
Workorder: Problem: P.m. service Diagnose no coil due to arci Replace all fright rear tpms Resurface reservice caliper Perform fron	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn TI 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy	hiatures Lgt Sock Parts: n Date: t pine Oil Oil Filter X Refurb Blade Brake Cli sure Monit	10.64 09/07/2018 ished	Closed:		1.00 1.00 1.00 7.00 1.00 2.00 4.00 1.00 2.00
Workorder: Problem: P.m. service Diagnose no coil due to arci Replace all fright rear tpms Resurface reservice caliper Perform fron	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn Tl 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy Tire Press	niatures Lgt Sock Parts: n Date: t nine Oil Oil Filter X Refurb Blade Brake Cli sure Monit	10.64 09/07/2018 ished	Closed:		1.00 1.00 1.00 018 Qty 7.00 1.00 2.00 4.00 1.00 2.00 1.00
Workorder: Problem: P.m. service Diagnose no coil due to arci Replace all fright rear tpms Resurface reservice caliper Perform fron	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and notain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn TI 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy Tire Press Real Brak	hiatures Lgt Sock Parts: In Date:  In Date: In D	10.64  09/07/2018  ished  or  coring System	Closed:		1.00 1.00 1.00 7.00 1.00 2.00 1.00 2.00 1.00 2.00 2.00
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface reservice caliper - Perform fron	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and nain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn TI 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy Tire Press Real Brak B Fluid Do	Lgt Sock Parts: In Date: In Da	10.64  09/07/2018  ished  or  coring System	Closed:		Qty 1.00 1.00 018 Qty 7.00 1.00 2.00 4.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00
- Test and rep  Workorder: Problem: - P.m. service - Diagnose no coil due to arci - Replace all fright rear tpms - Resurface reservice caliper - Perform fron	Hou : 1809234 P.M. service ding . Retest . four tires . Balls sensor . retries ear brake rotors . Flush and	me light and surs 0.50  Meter:  od . Replace lance and nain Tpms.  ors . Replace bleed brake	52911  e number one itrofill all . Re brake pads e system . Ro	Labor: e cylinder place and	Boxed Mir Stp Trn TI 30.00  Parts List 5w20 Eng Napagold Used Fire 22" Wiper Tire Non-chlor Coil Asy Tire Press Real Brak B Fluid Do Tpms12 S	Lgt Sock Parts: In Date:  In Date: In D	10.64  09/07/2018  ished  or  coring System	Closed:		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1809672 Tire senso	<b>Meter:</b> r fault on dash	53040		I	n Date:	09/19/2018	Closed:	09/20/20	018
- Test all Tpm	ns . Remove	and replace	left front tire	pressure	Parts List	:				Qty
sensor . Retra		•			Tpms12 S		1.00			
- Shop Suppli	ies				Shop Sup	plies				1.00
	H	ours 1.00		Labor:			80.17	Total:	140.17	
Workorder:	1812253	Meter:	55391		ı	n Date:	11/30/2018	Closed:	12/05/20	018
Problem:	A/C interm	ittant/issue wi	th belt? Froi	nt tires sha	ke at 55 mp	oh.				
- A/c performa	ance test . L	eak test . Red	cover and va	acuum	Parts List					Qty
system and co	omplete rech	narge and add	d dye . Retes	st.	Refrigerar	nt Oil				1.00
- High speed	balance and	d road force a	nd index all	four tires .	Freon Lv S	Shop 2				2.00
Retest drive.					Shop Sup	plies				1.00
- Shop Suppli		ouro 2.00		Lobori			20.46	Totalı	220.46	
	: :	ours 3.00		Labor:	201.00	Parts:	28.16	Total:	229.16	
Workorder: Problem:	1902043 P.M. servio	Meter: ce.	58547		I	n Date:	02/22/2019	Closed:	02/27/20	019
- P.m. service	<b>)</b> .				Parts List	:				Qty
- Charge batt	ery fully . Te	est battery and	d charging s	ystem .	Napagold	Oil Filter				1.00
battery failed l	oad test . R	&r defective b	attery.		5w20 Eng	ine Oil				7.00
- Rotate and I	balance all f	our tires . Nitr	ogen fill tire	S.	Washer Fl		entr			1.00
- Inspect and	service win	ch .			22" Wiper	Blade				2.00
- Test and rep	olace both fr	ont side mark	er light bulb	S.	Battery 65					1.00
- Shop Suppli	ies				Boxed Mir					2.00
					Shop Sup	plies				1.00
	Н	ours 6.55		Labor:	438.85		209.79	Total:	648.64	
Workorder: Problem:	: 1904213 Check oil ,	Meter:	61811		ı	n Date:	04/18/2019	Closed:	04/22/20	019
- Check oil le	vel and insp	ect for leakes	Top off oil		Parts List					Qty
0.1001.0.10	voi aira iriop	oot for loaned		•	5w20 Eng					1.00
	н	ours 0.20		Labor:	•	Parts:	2.39	Total:	15.79	1.00
Workorder: Problem:	1905777 P.M. servio	Meter:	64516		I	n Date:	05/31/2019	Closed:	06/10/20	019
- P.m. service	<del>j</del>				Parts List					Qty
- A/c performa		spect for leak	s Recover	and	Napagold					1.00
evacuate freo					5w20 Eng					8.00
complete rech					22" Wiper					2.00
- Inspect and	service win	ch .			Washer Fl		≏ntr			1.00
- Rotate and I	balance all f	our tires . Nitr	ofill all.		Batteries	uiu Conc	5i ili			1.00
- Shop Suppli	ies				Freon Lv S	Shop 1				2.00
					A/c Valve	onop i				
						nlion				1.00
		0.75		1 -1	Shop Sup		04.05	<del>-</del>	E40.00	1.00
	H .	ours 6.75		Labor:	452.25	Parts:	61.05	ı otal:	513.30	

	1907265 A/C blows w	Meter: arm .	65828			In Date:	07/16/2019	Closed:	07/18/2019
- A/c performa	nce test . Le	ak test .reco	ver and evu	ıcuate	Parts Li	st			Qt
system .r&r lea	king evapora	ator core, he	eater core a	nd	E8 A/c C	1.00			
accumulator Retest .	Vacuum syst	tem and con	nplete recha	irge .	Freon Lv	2.0			
- Test and rep	ace defective	e hrake light	switch		A/c Seal				1.00
- Shop Supplie		c brake light	SWILCH .		accumul	ator asy			1.00
опор оаррис	,3				Core A/c	•			1.00
					A/c Evap	orator			1.00
					Switch				1.00
					Shop Su	pplies			1.00
	Hou	urs 12.80		Labor:	857.60	Parts:	653.82	Total:	1,511.42
	1911357	Meter:	69731	wh.		In Date:	10/31/2019	Closed:	11/19/2019
- P.m. service.	P.M. service	and A/C no	t cold on nig	yn.	Parts Lis	-4			Qt
- Resurface bo		re Ponlaco	both front c	alipere		d Oil Filter			1.00
and brake pads					5w20 En				8.0
- Remove and	replace right	t side valve	cover and g	asket Per	22" Wipe	•			2.00
Tsb 15-0161 fo	r oil consum	ption .			•	Fluid Conc	entr		1.00
- Computer dia			all sixteen s	spark		e X Refurb			1.0
olugs and wire			مرامومان م	Fluck	Reman/o		ionod		1.00
<ul> <li>Perform com njectors .</li> </ul>	piete air inta	ke decarb ai	id cleaning	. FluSii	Reman/o				1.00
- Rotate and b	alance all for	ur tires . Nitr	ofill all.		Pedal Pa				1.0
- Inspect and s						Dot 4-320	Z		1.00
- Transport to			ce part repla	acement of					1.0
√c evaporator					Sealant		,		2.0
- Shop Supplie	es				Valve Co	over			1.0
					Espak P				4.0
					Espak P	_			4.0
					Spark Pl	_			16.0
					•	eaner Kit			1.0
					Motor Tu	ine-up 16o	Z		1.00
						on Pvc Sw			1.00
					Shop Su	pplies			1.00
	Hou	urs 18.95		Labor:	1,383.3 5		834.25	Total:	2,217.60
	1912462 Tire monitori	Meter: ing fault on o	69865 dash .			In Date:	12/05/2019	Closed:	12/10/2019
- Computer dia 31182 . Perfori g201 . Clear co sensors .	m pinpoint te ode and rete	st . Replace	defective g	round	Parts Lis Shop Su				<b>Qt</b> 1.0
- Shop Supplie		4 00		11	70.00	D1	4.00	<b>T</b> . ( . )	77.00
	Hot	urs 1.00		Labor:	73.00	Parts:	4.00	ı otal:	77.00

Workorder: Problem:	1913185 Brake light ou	Meter: ut.	71060			In Date:	12/31/2019	Closed:	01/03/2	020
- Replace righ	nt rear brake liç	ght bulb .			Parts Li	st				Qty
					Boxed N	1iniatures				1.00
	Hou :	rs 0.50		Labor:	36.50	Parts:	0.77	Total:	37.27	
Workorder: Problem:	2002623 PM Service	Meter:	75365			In Date:	03/13/2020	Closed:	03/19/20	020
- P.m. service	<b>)</b> .				Parts Li	st				Qty
- Replace two	tires . Rotate	and baland	ce all four tire	es.	Napago	d Oil Filter				1.00
Nitrofill all.					5w20 Er	ngine Oil				7.00
- Perform con	nplete front en	d alignmen	t and road to	est.	22" Wipe	er Blade				2.00
- Inspect and	service power	winch .			Washer	Fluid Conce	entr			1.00
- Shop Suppli	es				Napago	d Air Filter				1.00
					Lt245 75	5r17				2.00
					Shop Su	ıpplies				1.00
					Tire Disp	oosal Fee				2.00
	Цол	rs 8.25		Labor:	602.25	Parts:	602.24	Total:	1,204.49	9
	пои :	13 0.20			002.20					
Workorder: Problem:	2004314 Check oil leve	Meter:	76362			In Date:	04/30/2020	Closed:	05/05/20	020
Problem:	2004314	Meter:			Parts Li	In Date:			05/05/20	020 <b>Qty</b>
Problem:	: 2004314 Check oil leve	Meter:				In Date:			05/05/20	
Problem:	: 2004314 Check oil leve	Meter:			<b>Parts Li</b> 5w20 Er	In Date:	04/30/2020	Closed:	05/05/20	Qty
Problem: - Check oil lev Workorder:	: 2004314 Check oil leve	Meter: el . t for leaks . rs 0.20  Meter:		ıll mark .	<b>Parts Li</b> 5w20 Er	In Date: st	04/30/2020	Closed:		<b>Qty</b> 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump serry fully . Test	Meter: el . t for leaks . rs 0.20  Meter: start . battery and	Add oil to fu 76449 d charging sy	ıll mark . Labor:	<b>Parts Li</b> 5w20 Er	In Date: st ngine Oil Parts: In Date:	04/30/2020	Closed:	17.26	<b>Qty</b> 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump sery fully . Test	Meter: el . t for leaks . rs 0.20  Meter: start . battery and	Add oil to fu 76449 d charging sy	ıll mark . Labor:	<b>Parts Li</b> 5w20 Er 14.60	In Date: st ngine Oil Parts: In Date:	04/30/2020	Closed:	17.26	<b>Qty</b> 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump sery fully . Test	Meter: el . t for leaks . rs 0.20  Meter: start . battery and	Add oil to fu 76449 d charging sy	ıll mark . Labor:	Parts Li 5w20 Er 14.60	In Date:  st  ngine Oil Parts:  In Date:  st	04/30/2020	Closed:	17.26	Qty 1.00 020 Qty
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump sery fully . Test load test . R&r ies	Meter: el . t for leaks . rs 0.20  Meter: start . battery and	Add oil to fu 76449 d charging sy	ıll mark . Labor:	Parts Li 5w20 Er 14.60  Parts Li Battery G	In Date:  st ngine Oil Parts: In Date:  st 65 upplies	04/30/2020	Closed:  Total:	17.26	Qty 1.00 020 Qty 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I - Shop Suppli	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump sery fully . Test load test . R&r ies	Meter: el . t for leaks . rs 0.20  Meter: start . battery and defective to	Add oil to fundament of the fundament of	ull mark .  Labor:  ystem .  Labor:	Parts Li 5w20 Er 14.60  Parts Li Battery G	In Date:  st ngine Oil Parts: In Date:  st 65 upplies	2.66 05/06/2020	Closed:  Total:	17.26 05/07/20	Qty 1.00 020 Qty 1.00 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I - Shop Suppli  Workorder: Problem:	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump services load test . R&r ies Hou : 2005579	Meter: el . t for leaks . rs 0.20  Meter: start . battery and defective to rs 1.00  Meter: roof from f	Add oil to fu 76449 d charging sypattery .  77296 lood light mo	ull mark .  Labor:  ystem .  Labor:  ounting.	Parts Li 5w20 Er 14.60 Parts Li Battery 6 Shop Su 73.00	In Date:  st  ngine Oil Parts:  In Date:  st  65  upplies Parts:  In Date:	04/30/2020 2.66 05/06/2020 180.69	Closed:  Total:  Closed:	17.26 05/07/20 253.69	Qty 1.00 020 Qty 1.00 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I - Shop Suppli  Workorder: Problem:	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump serv fully . Test load test . R&r ies Hou : 2005579 Seal holes in	Meter: el . t for leaks . rs 0.20  Meter: start . battery and defective to rs 1.00  Meter: roof from f	Add oil to fu 76449 d charging sypattery .  77296 lood light mo	ull mark .  Labor:  ystem .  Labor:  ounting.	Parts Li 5w20 Er 14.60  Parts Li Battery ( Shop Su 73.00	In Date:  st  ngine Oil Parts:  In Date:  st  65  upplies Parts:  In Date:	2.66 05/06/2020 180.69 06/04/2020	Closed:  Total:  Closed:	17.26 05/07/20 253.69	Qty 1.00 020 Qty 1.00 1.00
Problem: - Check oil lev  Workorder: Problem: - Charge batte Battery failed I - Shop Suppli  Workorder: Problem:	: 2004314 Check oil level vel and inspect Hou : 2004543 Had to jump s ery fully . Test load test . R&r ies Hou : 2005579 Seal holes in	Meter: el . t for leaks . rs 0.20  Meter: start . battery and defective to rs 1.00  Meter: roof from f	Add oil to fu 76449 d charging sypattery .  77296 lood light mo	ull mark .  Labor:  ystem .  Labor:  ounting.	Parts Li 5w20 Er 14.60  Parts Li Battery ( Shop Su 73.00	In Date:  st ngine Oil Parts:  In Date:  st 65 upplies Parts:  In Date:  st Adh Seal Bll	2.66 05/06/2020 180.69 06/04/2020	Closed:  Total:  Closed:	17.26 05/07/20 253.69	Qty 1.00 020 Qty 1.00 1.00 020

Workorder: 2009909 Meter: 81605 Problem: P.M. Service.	In Date: 10/01/2020 Clo	sed: 10/05/2020
- P.m. service.	Parts List	Qty
- Replace two tires . Rotate and balance all four tires .	Drain Plug	1.00
Nitrofill all.	Napagold Oil Filter	1.00
- Replace both broken tag light lens .	5w20 Engine Oil	8.00
- Perform complete front end alignment and road test .	Washer Fluid Concentr	1.00
- Inspect and service winch .	22" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Yellow Markal Crayon	1.00
	Non-chlor Brake Clnr	1.00
	Tire	2.00
	Light Lens	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.75 Labor:	638.75 Parts: 560.12	Total: 1,198.87
Workorder: 2012132 Meter: 84580 Problem: Transition Prep Charge	In Date: 12/07/2020 Clo	sed: 12/07/2020
- Transition Prep Charge		
Hours 2.00 Labor:	146.00 Parts: 0.00	Total: 146.00