# 10201158 2017 FORD ESCAPE Suv, Mid Size

						,				
Workorder: Problem:	1611087 1061 - Pre De	Meter: livery Insp	923 pection			In Date:	10/26/2016	Closed:	10/26/2	016
- Pre Delivery - Travel time	Inspection									
	Hours :	s 3.50		Labor:	210.00	Parts:	0.00	Total:	210.00	
Workorder: Problem:	1611676 Light bar inop.	Meter:	4203			In Date:	11/14/2016	Closed:	02/14/2	017
controller.repla	op lightbar.fuse ace and rewire		orted		Parts Li					<b>Qty</b> 1.00
- Shop Suppli		s 2.50		Labor:	150.00	Parts:	2.00	Total:	152.00	
Workorder: Problem:	1702076 P.M. service a	<b>Meter:</b> nd rewire	5643 light bar to	work with c	ar off.	In Date:	02/28/2017	Closed:	03/14/2	017
- P.m. Service	э.				Parts L	ist				Qty
- Rewire light	bar to operate v	vhile vehi	cle bis off.		5w20 Eı	ngine Oil				6.00
- Rotate and I	balance tires.				Napago	ld Oil Filter				1.00
- Shop Suppli	es				Washer	Fluid Conce	entr			1.00
					Used Fi	re X Refurbi	ished			1.00
					Wd40 S	pr				1.00
					Shop St	upplies				1.00
	Hours :	s 4.00		Labor:	240.00	Parts:	43.81	Total:	283.81	
Workorder: Problem:	1702737 Right front par	Meter: king light	6717 inop.			In Date:	03/17/2017	Closed:	03/30/20	017
- Trace and re	epair right front	marker lig	ght wiring.		Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1705104 P.M. service.	Meter:	10294			In Date:	05/23/2017	Closed:	05/25/20	017
- P.m. service	<b>)</b> .				Parts L	ist				Qty
- Rotate and I	balance four tire	es.nitrofill.			5w20 Eı	ngine Oil				6.00
- Shop Suppli	es					ld Oil Filter				1.00
					Shop St					1.00
	Hours	s 3.00		Labor:	180.00	Parts:	18.16	Total:	198.16	

Workorder: Problem:	1707433 P.M. service.	Meter:	15210		ı	ln Date:	07/31/2017	Closed:	08/03/20	)17
- P.m. service	<del>)</del> .				Parts Lis	t				Qty
- High speed	balance all fou	ır tires.nitro	filled.		Napagold	Oil Filter				1.00
- Shop Suppli	ies				5w20 Eng	jine Oil				6.00
					Accufit Be	eam				2.00
					Wpr/blde					1.00
					Washer F	luid Conc	entr			1.00
					Shop Sup	plies				1.00
	Hou :	rs 3.00		Labor:	180.00	Parts:	63.40	Total:	243.40	
Workorder: Problem:	1708161 Left rear tire	Meter: going flat.	16541		1	In Date:	08/18/2017	Closed:	08/22/20	)17
- Repair left re	ear tire and ba	lance .nitro	gen fill tires.		Parts List	t				Qty
- Shop Suppli	ies				Shop Sup	plies				1.00
	Hou	rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1709891 P.M. service	Meter: and wipers	20056 binding.		I	In Date:	10/10/2017	Closed:	10/17/20	)17
- P.m. service	e.replace bindi	ng wiper bla	ades.		Parts Lis	t				Qty
- Balance and	d rotate all four	tires.			5w20 Eng	jine Oil				6.00
- Shop Suppli	ies				Napagold	Oil Filter				1.00
					Washer F	luid Conc	entr			1.00
					Blade					1.00
					Wiper Bla	de				1.00
					Wiper Bla	de				1.00
					Used Fire	X Refurb	ished			1.00
					Shop Sup	plies				1.00
	Hou :	rs 3.00		Labor:	180.00	Parts:	90.01	Total:	270.01	
Workorder: Problem:	1711163 Nail in rear tir	Meter:	22690		I	In Date:	11/13/2017	Closed:	11/16/20	)17
	tires .mount a	and balance	e on rear of v	ehicle	Parts Lis	t				Qty
and nitro serv					P235 55r	17 Fuel M	ax			2.00
- Shop Suppl	ies				Shop Sup	plies				1.00
					Tire Dispo	osal Fee				2.00
	Hou	rs 1.00		Labor:	60.00	Parts:	345.45	Total:	405.45	

Workorder: 17124 Problem: P.M. s		25233			In Date:	12/18/2017	Closed:	12/21/20	17
- P.m. service.				Parts Li	st				Qty
- Mount two tires and	l balance all fou	wheels.nitrofill	l.	Napagol	d Oil Filter				1.00
- Perform four wheel	alignment.			5w20 En	gine Oil				6.00
- Shop Supplies	_			P235 55	r17 Fuel Ma	эх			2.00
				Shop Su	pplies				1.00
				Tire Disp	osal Fee				2.00
	Hours 6.50 :		Labor:	390.00	Parts:	361.50	Total:	751.50	
Workorder: 18026 Problem: P.M. s		: 30350			In Date:	03/12/2018	Closed:	03/23/20	18
- P.m. Service.				Parts Li	st				Qty
- Rotate and balance	tires.			5w20 En	gine Oil				6.00
- Transport vehicle to	dealer for leak	ng rear shocks.		Napagol	d Oil Filter				1.00
- Shop Supplies				Washer	Fluid Conce	entr			1.00
				Blade					1.00
				Wiper BI	ade				1.00
				Wiper BI	ade				1.00
				Lug Nut					1.00
				Shop Su	pplies				1.00
	Hours 5.00 :		Labor:	300.00	Parts:	83.00	Total:	383.00	
Workorder: 18061 Problem: P.M. S		: 35679			In Date:	06/18/2018	Closed:	07/02/20	18
- P.m. Service.				Parts Lis	st				Qty
- Test battery and ch			test	Napagol	d Oil Filter				1.00
battery,fail load test.re	•	•		5w20 En	gine Oil				6.00
<ul> <li>Diagnose Tpms light sensor.rotate and ball</li> </ul>		or Replace defe	ective	Battery					1.00
- Shop Supplies	ance an mes.			Tpms12	Sensor Tire	e Pr			1.00
- Shop Supplies				Shop Su	pplies				1.00
	Hours 4.50 :		Labor:	270.00	Parts:	266.50	Total:	536.50	
Workorder: 18084 Problem: Nail in		39168			In Date:	08/15/2018	Closed:	08/16/20	18
- Repair left front tire	and balance . N	litrofill all tires.		Parts Lis					Qty
- Shop Supplies				Shop Su	pplies				1.00
	Hours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

<b>Norkorder:</b> 18090 <b>Problem:</b> P.M. s				ln l	Date:	09/04/2018	Closed:	09/06/20	018
- P.m. service.				Parts List					Qt
- Replace all four tire	s. Balance and	d nitrofill all .		Napagold O	il Filter				1.0
- Complete front end				5w20 Engine					6.0
- Shop Supplies				Washer Flui		entr			1.0
5ap				Used Fire X					1.0
				Napa Cabin					1.0
				235/55r17 A					4.0
				Shop Suppli					1.0
				Tire Disposa					4.0
	Hours 6.50		Labor:	390.00		684.58	Total:	1,074.58	
Workorder: 181020 Problem: Both re			sidewall.	In	Date:	10/03/2018	Closed:	10/04/20	018
- Replace two rear tir	es and balanc	e . Nitrogen fill	tires .	Parts List					Qt
- Shop Supplies				Tire235/55/1					2.0
				Shop Suppli					1.0
				Tire Disposa					2.0
	Hours 1.00		Labor:	67.00	Parts:	383.92	Total:	450.92	
Vorkorder: 18122	:	er: 44820		In	Date:	12/03/2018	Closed:	12/05/20	018
Problem: P.M. S	: 98 <b>Met</b> e	er: 44820			Date:	12/03/2018	Closed:	12/05/20	
<b>Problem:</b> P.M. S P.m. service.	: 98 <b>Met</b> e Service.		u tiroo	Parts List		12/03/2018	Closed:	12/05/20	Qt
Problem: P.M. S - P.m. service Repair right rear tire	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O	il Filter	12/03/2018	Closed:	12/05/20	<b>Qt</b> 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O Napa Quart	il Filter	12/03/2018	Closed:	12/05/20	<b>Qt</b> 1.0 6.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O Napa Quart Blade	il Filter 5w20	12/03/2018	Closed:	12/05/20	<b>Qt</b> 1.0 6.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O Napa Quart Blade Wiper Blade	il Filter 5w20	12/03/2018	Closed:	12/05/20	Qt 1.0 6.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade	il Filter 5w20		Closed:	12/05/20	Qt 1.0 6.0 1.0 1.0
	: 98 <b>Met</b> e Service.		r tires.	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit	il Filter 5w20 :hium G		Closed:	12/05/20	Qt 1.0 6.0 1.0 1.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Mete</b> Service. e . Rotate and			Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli	il Filter 5w20 :hium G	res			Qt 1.0 6.0 1.0 1.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires.	: 98 <b>Met</b> e Service.			Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit	il Filter 5w20 :hium G	res		12/05/20	Qt 1.0 6.0 1.0 1.0 1.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies	: 98 Meter Service.  e . Rotate and  Hours 4.00 :  47 Meter	balance all four		Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00	il Filter 5w20 :hium G	res			Qt 1.0 6.0 1.0 1.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires Shop Supplies  Vorkorder: 19026 - Problem: P.M. s	: 98 Meter Service.  e . Rotate and  Hours 4.00 :  47 Meter	balance all four		Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00	il Filter 5w20 :hium G es Parts:	res 94.01	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires Shop Supplies  Vorkorder: 19026 - Problem: P.M. s - P.m. service.	: 98 Meters Service.  Hours 4.00 : 47 Meters ervice.	balance all four	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00	il Filter 5w20 chium G es Parts:	res 94.01	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0
Problem: P.M. S - P.m. service Repair right rear tire litrogen fill tires Shop Supplies  Vorkorder: 19026 - Problem: P.M. s - P.m. service Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00 In I	il Filter 5w20 chium G es Parts: Date:	res 94.01	Total:	362.01	Qtt 1.0 6.0 1.0 1.0 1.0 1.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies  Vorkorder: 19026 Problem: P.M. s P.m. service. Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In I Parts List Napagold O	il Filter 5w20 chium G es Parts: Date:	res 94.01	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies  Vorkorder: 19026 Problem: P.M. s P.m. service. Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In I Parts List Napagold O 5w20 Engine	il Filter 5w20 chium G es Parts: Date: il Filter e Oil	res 94.01	Total:	362.01	Qtt 1.0 6.0 1.0 1.0 1.0 1.0 1.0 019 Qtt 1.0 6.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies  Vorkorder: 19026 Problem: P.M. s P.m. service. Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In Parts List Napagold O 5w20 Engine Blade	il Filter 5w20 chium G es Parts: Date:	res 94.01	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0 1.0 6.0 1.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies  Vorkorder: 19026 Problem: P.M. s P.m. service. Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In I  Parts List Napagold O 5w20 Engine Blade Wiper Blade	il Filter 5w20 chium G es Parts:  Date:  il Filter e Oil	res 94.01 03/11/2019	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0 1.0 6.0 1.0 1.0
Problem: P.M. S P.m. service. Repair right rear tire litrogen fill tires. Shop Supplies  Vorkorder: 19026 Problem: P.M. s P.m. service. Replace left front do	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In Parts List Napagold O 5w20 Engine Blade Wiper Blade Wiper Blade Wiper Blade	il Filter 5w20 chium G es Parts: Date:  il Filter e Oil	res 94.01 03/11/2019	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0 1.0 0.19
Problem: P.M. S - P.m. service Repair right rear tire Nitrogen fill tires Shop Supplies	: 98 Meter Service.  Hours 4.00 : 47 Meter ervice.	balance all four er: 49745 esing trim bezel	Labor:	Parts List Napagold O Napa Quart Blade Wiper Blade Wiper Blade Mac Wite Lit Shop Suppli 268.00  In I  Parts List Napagold O 5w20 Engine Blade Wiper Blade Wiper Blade Wiper Blade Washer Fluit	il Filter 5w20  chium G es Parts:  Date:  il Filter e Oil  d Concer	res 94.01 03/11/2019	Total:	362.01	Qt 1.0 6.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1

Problem:	1905817 Tag light inop	Meter: and left from	53694 ont low bear	m inop.		In Date:	06/03/2019	Closed:	06/05/201	19
- Test and repl	ace left low b	eam bulb a	and right tag	light bulb.	Parts Lis	st				Qty
- Shop Supplie	S				Boxed M	iniatures				1.00
					Blister P	ack Capsul	es			1.00
					Shop Su	pplies				1.00
	Hou	rs 0.80		Labor:	53.60	Parts:	16.19	Total:	69.79	
	1906347 P.M. service.	Meter:	54510			In Date:	06/17/2019	Closed:	06/24/201	19
- P.m. service.					Parts Lis	st				Qty
- Replace two			e all four tir	es.	5w20 En	gine Oil			(	6.00
Nitrofill all tires	•					d Oil Filter				1.00
- Replace rear		and brake	pads . Flush	and bleed	Washer	Fluid Conce	entr			1.00
orake system . - Test and repl		etrobo ewi	toh		Blade					1.00
- Test and repl - Diagnose noi				alva abaft	Wiper Bl	ade				1.00
ssembly . Ret		Rai delect	ive ieit iioiit	aixe Silait	Wiper Bl	ade				1.00
- Perform com		eel alignme	nt . Road te	est .	Tire235/	55/17 Mic			2	2.00
Shop Supplie -		Ü			Brake Ro	otor			2	2.00
					Brk Fluid	Dot 4-12o	z		2	2.00
					Brake Pa	ad				1.00
					Tape					1.00
					Switch -	Rocker				1.00
					Shaft Fro	ont Axle				1.00
					Shop Su	pplies				1.00
					Tire Disp	osal Fee			2	2.00
	Hou	rs 12.30		Labor:	824.10	Parts:	946.12	Total:	1,770.22	
	1909194 Right low bea	Meter: ım headligh	58320 nt inop.			In Date:	09/06/2019	Closed:	09/11/201	19
- Test and repl	ace defective	right low b	eam headli	ght bul;b .	Parts Lis	st				Qty
·		-			Blister P	ack Capsul	es			1.00
					33.50	Parts:		Total:		

Workorder: 1910057 Meter: 59368 Problem: P.M. service.	In Date: 09/30/2019 Closed:	10/02/2019
- P.m. service.	Parts List	Qty
- Replace both leaking rear shocks .	Napagold Oil Filter	1.00
- Diagnose noise on turns . R&r defective left front axle .	5w20 Engine Oil	6.00
Road test.	Washer Fluid Concentr	1.00
- Rotate and balance all four tires . Nitrofill all.	Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Wiper Blade	1.00
	Used Fire X Refurbished	1.00
	Ford Triton Pvc Swc	1.00
	Shockabsorberas	2.00
	Axle Nut	1.00
	Left Front Axle	1.00
	Shop Supplies	1.00
Hours 6.10 Labor:	445.30 Parts: 541.89 Total:	987.19
Workorder: 2000114 Meter: 65165 Problem: PM Service	In Date: 01/06/2020 Closed:	01/08/2020
- P.m. service.	Parts List	Qty
- Diagnose clicking noise on turns . R&r defective right front	Napagold Oil Filter	1.00
axle assembly . Retest .	5w20 Engine Oil	6.00
- Rotate and balance all four tires . Nitrofill all.	Blade	1.00
- Shop Supplies	Wiper Blade	1.00
	Wiper Blade	1.00
	Shaft Assy Motorcraft	1.00
	Shop Supplies	1.00
Hours 5.20 Labor:	379.60 Parts: 338.08 Total:	717.68
Workorder: 2000377 Meter: 65643 Problem: Left low beam headlight inop .	In Date: 01/13/2020 Closed:	01/16/2020
- Test and replace left side low beam headlight bulb .	Parts List	Qty
- Shop Supplies	Blister Pack Capsules	1.00
	Shop Supplies	1.00
Hours 0.50 Labor:	36.50 Parts: 17.86 Total:	

Workorder: Problem:	2003239 P.M. service		70130 p.		I	In Date:	03/31/2020	Closed:	04/09/2020
- P.m. service	е.				Parts List	t			G
- Replace two	o tires . Rotate	e and high spe	ed balance	all four	Napagold	Oil Filter			1.
tires . Nitrofill					5w20 Eng	jine Oil			6.
	ooth front brak				Wiper Bla	de			1.
Replace brake test.	e pads . Flush	and bleed bra	ake system .	. Road	Wiper Bla	de			1.
	liagnose radio	inop . Perforr	n pinpoint te	st A for	Blade				1.
no signal . Ac	cess headline				Washer F	luid Conc	entr		1.
mount and ma					Tire235/5	5/17 Mic			2.
- Shop Suppl	lies				Non-chlor	Brake Cli	nr		1.
					Brk Fluid	Dot 4-12o	Z		1.
					Brake Pag	d			1.
					Aerial Wit				1.
					Stanchion	1			1.
					Shop Sup	plies			1.
					Tire Dispo	sal Fee			2.
	Hoi	urs 9.00		Labor:	657.00	Parts:	626.27	Total:	1,283.27
	2004698 Had to jump		71483 battery .			In Date:	05/11/2020	Closed:	05/12/2020
Problem: - Charge batt Battery has ba	Had to jump tery fully . Tes ad cell . R&r d ery cable . Ho	start , check l t battery and d lefective batte	battery . charging sys ry .replace c		Parts List Macs Batt Battery Bat Cable Shop Sup	<b>t</b> tery Clean		Gloseu.	1. 1. 1.
Problem: - Charge batt Battery has ba negative batte	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hoo lies	start , check l t battery and d lefective batte	battery . charging sys ry .replace c	corroded	Parts List Macs Batt Battery Bat Cable	t tery Clean			1. 1. 1.
Problem: - Charge batt Battery has ba negative batte - Shop Suppl	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hoo lies	start , check of the battery and conference of the battery and conference of the batter of the batte	battery . charging sys ry .replace c	corroded	Parts List Macs Batt Battery Bat Cable Shop Sup 146.00	t tery Clean	er		1. 1. 1. 1.
Problem: - Charge batt Battery has ba negative batte - Shop Suppl	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service	start , check of the battery and conference of the battery and conference of the batter of the batte	charging sys ry .replace c set Bsm .	corroded	Parts List Macs Batt Battery Bat Cable Shop Sup 146.00	t tery Clean pplies Parts:	er 240.24	Total:	1. 1. 1. 1. 386.24
Problem: - Charge batt Battery has be negative batte - Shop Suppl  Workorder: Problem: - P.m. service	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service	start , check   t battery and clefective batte ok up lds to re urs 2.00  Meter: 7	charging sys ry .replace c eset Bsm .	corroded Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00	t tery Clean pplies Parts: In Date:	er 240.24	Total:	1. 1. 1. 1. 386.24
Problem: - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem: - P.m. service - Replace cal	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0	start , check of the battery and collefective batter batte	charging sys ry .replace c set Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00	t tery Clean pplies Parts: In Date: t	er 240.24	Total:	1. 1. 1. 386.24
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hoo lies  Hoo : 2007381 P.M. Service e. bin air filter . ( trobe light inop	start , check of the battery and collefective batter batte	charging sys ry .replace c set Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00	t tery Clean pplies Parts: In Date: t	er 240.24	Total:	07/30/2020 07/30/2020
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . ( trobe light inop e bulbs .	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng	tery Clean pplies Parts: In Date: t Oil Filter gine Oil	er 240.24	Total:	07/30/2020 07/30/2020 07/30/2020
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe - Rotate and	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Batt Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade	t tery Clean plies Parts: In Date: t Oil Filter gine Oil de	er 240.24	Total:	07/30/2020 07/30/2020 07/30/2020
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade Wiper Bla	t tery Clean plies Parts: In Date: t Oil Filter gine Oil de de	240.24 07/28/2020	Total:	07/30/2020 07/30/2020 07/30/2020 1. 6. 1.
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe - Rotate and	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Batt Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade Wiper Bla Wiper Bla	t tery Clean plies Parts: In Date: t Oil Filter gine Oil de de X Refurb	240.24 07/28/2020	Total:	07/30/2020 07/30/2020 07/30/2020 1.6.1.1.1.
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe - Rotate and	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire	tery Clean polies Parts: In Date:  t Oil Filter gine Oil de de X Refurb bin Air Filte	240.24 07/28/2020 ished	Total:	07/30/2020 07/30/2020 07/30/2020 1.66.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
- Charge batt Battery has be negative batte - Shop Suppl  Workorder: Problem: - P.m. service - Replace calc Diagnose st replace strobe - Rotate and	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Batt Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Cab	tery Clean plies Parts: In Date: t Oil Filter pine Oil de de X Refurb oin Air Filte Led Clea	240.24 07/28/2020 ished	Total:	07/30/2020 07/30/2020 07/30/2020 1.66.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
Problem:  - Charge batt Battery has ba negative batte - Shop Suppl  Workorder: Problem:  - P.m. service - Replace cal .  - Diagnose st replace strobe - Rotate and	Had to jump tery fully . Tes ad cell . R&r d ery cable . Hod lies  Hod : 2007381 P.M. Service e. bin air filter . 0 trobe light inoge bulbs . balance all for	start , check of the battery and collefective batter batte	charging sys ry .replace coset Bsm .	Labor:	Parts List Macs Battery Bat Cable Shop Sup 146.00  Parts List Napagold 5w20 Eng Blade Wiper Bla Wiper Bla Used Fire Napa Cab Mnt Conc	tery Clean polies Parts: In Date:  t Oil Filter gine Oil de de X Refurb bin Air Filte Led Clean iniatures	240.24 07/28/2020 ished	Total:	07/30/2020 07/30/2020 07/30/2020 1.6.1.1.1.1.1.2.

**Workorder:** 2007813 **Meter:** 75151 **In Date:** 08/07/2020 **Closed:** 08/07/2020

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00

: