

**Palm Beach County Fleet Management
Asset Maintenance History**

10187849 2013 GMC SAVANA Van, 3/4 Ton, Cargo

Workorder: 1209291 **Meter:** 116 **In Date:** 09/28/2012 **Closed:** 09/28/2012
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1302891 **Meter:** 6681 **In Date:** 03/25/2013 **Closed:** 04/03/2013
Problem: P.M. service.

- Perform pm service.

- Install new fire extinguisher and bracket.

- Rotate and balance all four tires.

- Shop Supplies

Parts List	Qty
Dexos 5w30	6.00
Filter	1.00
Used Firex Refurbed F	1.00
Custom Bracket Fire Ex	1.00
Washer FI	1.00
Shop Supplies	1.00

Hours 5.50 Labor: 330.00 Parts: 106.31 Total: 436.31
 :

Workorder: 1308126 **Meter:** 11586 **In Date:** 08/14/2013 **Closed:** 09/03/2013
Problem: Pm service.Turnsignal inop.and headlamp loose.Repair dent on passenger side.

- P.m. Service.

- Replace broken left head lamp retainer ring.replace right front signal light bulb.

- Rotate and balance all tires.

- Shop Supplies

Parts List	Qty
Dexos 5w30	6.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Hl/ring	1.00
Bulb	1.00
Shop Supplies	1.00

Hours 5.75 Labor: 345.00 Parts: 60.77 Total: 405.77
 :

Workorder: 1309157 **Meter:** 11586 **In Date:** 08/28/2013 **Closed:** 09/10/2013
Problem: damage to rgt rear fender

- damage to rgt rear fender

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1312069 **Meter:** 14757 **In Date:** 12/03/2013 **Closed:** 12/17/2013
Problem: Request easy load ladder rack and left head light inop and crack in windsheild.

- Diagnose inop headlamp.replace bulb and updated headlamp assemble.

- Remove old ladder rack.assemble and install new drop down ladder rack per request.re-install storage tube.

- Shop Supplies

Parts List	Qty
Headlamp Assy	1.00
Ez Load Ladder Rack	1.00
Shop Supplies	1.00

Hours 9.00 Labor: 540.00 Parts: 1,531.13 Total: 2,071.13
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1312165 **Meter:** 14656 **In Date:** 12/05/2013 **Closed:** 12/10/2013
Problem: repair chip in windsheid

- set up repairs and inspecgt **Parts List** **Qty**
- Shop Supplies Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1401746 **Meter:** 17414 **In Date:** 02/24/2014 **Closed:** 03/13/2014
Problem: Pm service

- P.m. Service. **Parts List** **Qty**
- Rotate and balance all tires. Dexos 5w30 Oil 6.00
- Traansport vehicle to dealer for leaking pinion seal. Napagold Oil Filter 1.00
- Shop Supplies Wiper Blade 2.00
Washer FI 1.00
Used Fire X Refurbished 1.00
Wd40 16oz 1.00
Shop Supplies 1.00

Hours 7.00 Labor: 420.00 Parts: 76.52 Total: 496.52
:

Workorder: 1407522 **Meter:** 23393 **In Date:** 07/31/2014 **Closed:** 08/22/2014
Problem: Pm service and safety trim inpact recall.

- Pm service. **Parts List** **Qty**
- Rotate and balance all four tires. Napagold Oil Filter 1.00
- Transport vehicle to and from dealer for safety recall 14082 Napa Quart 5w30 6.00
.repair passerger side dash panel tray. Napagold Air Filter 1.00
- Shop Supplies Wiper Blade 2.00
Shop Supplies 1.00

Hours 7.00 Labor: 420.00 Parts: 46.03 Total: 466.03
:

Workorder: 1501423 **Meter:** 29013 **In Date:** 02/06/2015 **Closed:** 02/19/2015
Problem: Pm service.Check brakes.

- Pm service. **Parts List** **Qty**
- Replace and balance all four tires. Dexos 5w30 Oil 6.00
- Perform complete front end alignment.roadtest. Napagold Oil Filter 1.00
- Shop Supplies Wiper Blade 2.00
Washer Fluid Concentr 1.00
744395900 245-75r16 4.00
Shop Supplies 1.00
Tire Disposal Fee 4.00

Hours 8.50 Labor: 510.00 Parts: 1,014.99 Total: 1,524.99
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1509395 **Meter:** 35328 **In Date:** 09/17/2015 **Closed:** 09/30/2015
Problem: Pm service.Grade braking warning light on dash intemittently

- P.m. Service.	Parts List	Qty
- Diagnose intermitten Abs light,right front hub bearing loose.replace defective right front hub assemble.	Dexos 5w30 Oil	6.00
- Rotate and balance all tires,	Napagold Oil Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Hub Bearing	1.00
	Shop Supplies	1.00
Hours 6.50	Labor: 390.00	Parts: 321.16
:		Total: 711.16

Workorder: 1602245 **Meter:** 40161 **In Date:** 03/03/2016 **Closed:** 03/14/2016
Problem: Pm service.

- Pm service.	Parts List	Qty
- Transmission flush and replace fluid.	Dexos 5w30	6.00
- Pressure test and Inspect cooling system.flush with new antifreeze..	Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.	22" Wiper Blade	2.00
- Replace broken hitch pintle pin.	Used Fire X Refurbished	1.00
- Shop Supplies	Syn-atf Trans Fluid S	14.00
	Dex Coolant Engine	2.00
	Lt245 75r16	2.00
	Pintle Pin W/chain	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.00	Labor: 600.00	Parts: 600.74
:		Total: 1,200.74

Workorder: 1610643 **Meter:** 45624 **In Date:** 10/14/2016 **Closed:** 10/27/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	Napagold Oil Filter	1.00
- Shop Supplies	Napa Syn 5w30 Qt	6.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Lt245 75r16	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 360.00	Parts: 518.06
:		Total: 878.06

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1701402 **Meter:** 47491 **In Date:** 02/09/2017 **Closed:** 02/28/2017
Problem: Towed in for no start and left turn signal inop.

- Test battery and charging system.replace bad battery. **Parts List** **Qty**
- Replace left signal light bulb. Battery 1.00
- Shop Supplies Bulb 1.00
Shop Supplies 1.00

Hours 1.50 Labor: 90.00 Parts: 113.36 Total: 203.36
:

Workorder: 1701473 **Meter:** 47173 **In Date:** 02/09/2017 **Closed:** 02/13/2017
Problem: no start

- Tow From: jpp To: lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1703653 **Meter:** 48095 **In Date:** 04/11/2017 **Closed:** 04/20/2017
Problem: P.M. Service.

- P.m. Service. **Parts List** **Qty**
- Rotate and balance tires. Napa Syn 5w30 Qt 6.00
- Shop Supplies Napagold Oil Filter 1.00
22" Wiper Blade 2.00
Washer Fluid Concentr 1.00
Shop Supplies 1.00

Hours 5.00 Labor: 300.00 Parts: 45.89 Total: 345.89
:

Workorder: 1711270 **Meter:** 52421 **In Date:** 11/15/2017 **Closed:** 11/29/2017
Problem: P.M. service and towed in for no start.

- P.m. service. **Parts List** **Qty**
- Perform battery load test and charging analyzing.battery failed .alt charging at 121 amps.no drain .r&i new battery. Napa Syn 5w30 Qt 6.00
- Install both front missing bump stops. Napagold Oil Filter 1.00
- Perform high speed balanceing and rotation. 22" Wiper Blade 2.00
- Shop Supplies Washer Fluid Concentr 1.00
Used Fire X Refurbished 1.00
Battery 1.00
Bumper 2.00
Battery Cable Bolt 1.00
Shop Supplies 1.00

Hours 6.30 Labor: 378.00 Parts: 229.07 Total: 607.07
:

Workorder: 1711365 **Meter:** 52331 **In Date:** 11/15/2017 **Closed:** 11/17/2017
Problem: No start/wont turn over

- Tow From: Jpp Maint Compound next to fuel pumps To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1806193 **Meter:** 56144 **In Date:** 06/18/2018 **Closed:** 06/27/2018
Problem: P.M. Service.Brakes squealing and A/C not cold when vehicle is stopped.

- P.m. service.	Parts List	Qty
- Check and resurface front and rear brake rotors . Service rear calipers and replace pads .flush and bleed brake system . Road test.	Napagold Oil Filter	1.00
- Diagnose and perform pinpoint test .replace defective blower resistor assembly.	Napa Syn 5w30 Qt	6.00
- Balance and rotate all four tires.	Wd40 Spr	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Brakepad	1.00
	lube	1.00
	B Fluid Dot 3-32oz	1.00
	Module Kit	1.00
	Shop Supplies	1.00
Hours 13.00	Labor: 780.00	Parts: 299.90
:		Total: 1,079.90

Workorder: 1808078 **Meter:** 56881 **In Date:** 08/07/2018 **Closed:** 08/15/2018
Problem: Ladder rack broken and hitting right rear door , A/c not cold ,check brakes.

- Remove all wheels ,peerform complete brake inspection . Perform Abs bleed procedure . Scan for codes ,no codes . Test drive.	Parts List	Qty
- A/c performance test . Scan controller for codes ,no codes .unable to duplicate syptoms at this time.	B Fluid Dot 3-32oz	2.00
- Repair ladder rack and return to orginal postion .retest.	Shop Supplies	1.00
- Shop Supplies		
Hours 5.00	Labor: 300.00	Parts: 14.51
:		Total: 314.51

Workorder: 1900177 **Meter:** 61132 **In Date:** 01/04/2019 **Closed:** 01/17/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace two tires . Rotate and balance all four tires . Nitrogen fill tires .	Napagold Oil Filter	1.00
- Shop Supplies	Napa Syn 5w30 Qt	6.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Lt245/75/16 Tire Mic	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 402.00	Parts: 537.99
:		Total: 939.99

Workorder: 1902107 **Meter:** 62349 **In Date:** 02/26/2019 **Closed:** 02/27/2019
Problem: Towed in right rear tir flat.

- Replace both rear tires and valve stems . Balance both tires . Nitrogen fill all.	Parts List	Qty
- Shop Supplies	Tire Pressure Monitoring System Sensor (2.00
	Lt245/75/16 Tire Mic	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.00	Labor: 67.00	Parts: 484.81
:		Total: 551.81

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1902108 **Meter:** 62246 **In Date:** 02/26/2019 **Closed:** 02/26/2019
Problem: Tire blew out, put spare on. confirmed with driver van has a spare.

- Tow From: Foresthill/jog North entrance riverbridge plaza

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1906711 **Meter:** 64496 **In Date:** 06/26/2019 **Closed:** 07/09/2019
Problem: P.M. service and headlight switch pushed in and radio.

- P.m. service.

- Inspect and replace broken dash bezel for headlight switch

- Balance and rotate all four tires . Nitrofill all.

- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	6.00
22" Wiper Blade	2.00
Whl/cvr	1.00
Cluster Bezel	1.00
Shop Supplies	1.00

Hours 5.80 Labor: 388.60 Parts: 295.98 Total: 684.58
:

Workorder: 1909332 **Meter:** 64842 **In Date:** 09/10/2019 **Closed:** 09/11/2019
Problem: Towed in for no start.

- Charge battery fully . Test battery and charging system .
Battery failed load test . R&r defective battery .

- Computer diagnose check engine light , code P0171
,p0174 . Perform pinpoint test . R&r failed vacuum hose from
intake to check valve and to vacuum resivor . Clear codes
and retest .

- Shop Supplies

Parts List	Qty
Battery	1.00
Battery Cable Bolt	1.00
W W Vacuum Tubing	3.00
Shop Supplies	1.00

Hours 3.00 Labor: 201.00 Parts: 135.60 Total: 336.60
:

Workorder: 1909369 **Meter:** 64842 **In Date:** 09/10/2019 **Closed:** 09/11/2019
Problem: NO Start

- Tow From: Jpp maint compound next to Electrical Shop
To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 2000757 **Meter:** 66265 **In Date:** 01/23/2020 **Closed:** 01/30/2020
Problem: P.M. service and two way radio stays on .

- P.m. service.

- Rotate and high speed balance all four tires . Tesdt and
replace right rear tire pressure sensor . Nitrofill all and retrain
all Tpms system .

- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
Napa Syn 5w30 Qt	6.00
Mac Wite Lithium Gres	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Tpms Ac Delco	1.00
Shop Supplies	1.00

Hours 6.00 Labor: 438.00 Parts: 142.33 Total: 580.33
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2006719 **Meter:** 70235 **In Date:** 07/08/2020 **Closed:** 07/08/2020
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			