

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10172305      2008 IMPERIAL EQ716 Trailer, 7 X 16, Dual Axle**

**Workorder:** 835758      **Meter:** 0      **In Date:** 03/19/2008      **Closed:** 03/19/2008  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 935332      **Meter:** 0      **In Date:** 03/18/2009      **Closed:** 03/26/2009  
**Problem:** PM SERVICE

- Replaced Traialer Pllug.test Connection.	<b>Parts List</b>	<b>Qty</b>
- Pm Service	Shop Supplies	1.00
- Reattached Several Boards And Tighten All Other Bolts.	T-235 Gray Primer	2.00
- Straighten Lower Lt.fender Damage.	1355 New Cat Yellow Plasti-kote	2.00
- Nitro Tires.	755-5046 Male Connector	1.00
- Cut Ood Fender Off W/torch.grind On Trailer/back Plate.cut Plate To Fit.weld Fender & Bracket In Place.prime Area & Paint Entire Area.	Fender	1.00
- Shop Supplies		

Hours 16.50      Labor: 990.00      Parts: 99.10      Total: 1,089.10  
:

**Workorder:** 1003312      **Meter:** 0      **In Date:** 04/01/2010      **Closed:** 04/02/2010  
**Problem:** P.M.

- P.m.	<b>Parts List</b>	<b>Qty</b>
- Repair bad wiring	Shop Supplies	1.00
- Shop Supplies	755-5046 Male Connector	1.00
	Ps1250f1 Battery (power Sonic Ps-1250-f1)	1.00

Hours 6.00      Labor: 360.00      Parts: 32.08      Total: 392.08  
:

**Workorder:** 1103399      **Meter:** 0      **In Date:** 03/30/2011      **Closed:** 03/31/2011  
**Problem:** pm service

- pm service	<b>Parts List</b>	<b>Qty</b>
- replace battery	Shop Supplies	1.00
- replace rear marker light and trailer plug	Ps1250f1 Battery (power Sonic Ps-1250-f1)	1.00
- add nitrogen to all tires	15250r Marker Light Red Led	1.00
- Shop Supplies	755-5046 Male Connector	1.00

Hours 7.50      Labor: 450.00      Parts: 39.14      Total: 489.14  
:

**Workorder:** 1203269      **Meter:** 0      **In Date:** 04/05/2012      **Closed:** 04/19/2012  
**Problem:** PM

- Pm Trailer axle and parts	<b>Parts List</b>	<b>Qty</b>
- repair open ground at frame for lights replace tag lights	Shop Supplies	1.00
- tighten all mounting bolts for deck boards	58856 Seal	4.00
- repair breake away cable cut in half	Tag Light Lens	1.00
- replaced damaged safety chain hook	1/4 Safety Hook	1.00
- Shop Supplies		

Hours 7.00      Labor: 420.00      Parts: 15.32      Total: 435.32  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1304162	<b>Meter:</b> 0	<b>In Date:</b> 04/26/2013	<b>Closed:</b> 05/09/2013
<b>Problem:</b> P.M.			
- pm service		<b>Parts List</b>	<b>Qty</b>
- replace pintal pin replace missing hardware for decking		18410 Pintle Pin	1.00
- tire		205/75r15 Freestar Tire	1.00
- Shop Supplies		Shop Supplies	1.00
		Tire Disposal Fee	1.00
Hours 5.50	Labor: 330.00	Parts: 113.89	Total: 443.89
:			
<b>Workorder:</b> 1304517	<b>Meter:</b> 0	<b>In Date:</b> 05/06/2013	<b>Closed:</b> 05/07/2013
<b>Problem:</b> replace tire			
- mount rr tire boulevard			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
<b>Workorder:</b> 1406492	<b>Meter:</b> 0	<b>In Date:</b> 07/01/2014	<b>Closed:</b> 07/15/2014
<b>Problem:</b> P.M.			
- pm		<b>Parts List</b>	<b>Qty</b>
- replace battery		1355 New Cat Yellow P	1.00
- replace tag light assembly		12v5amp/hour Battery	1.00
- replace break away pin		License Lamp	1.00
- repair jack and handle . paint area		Breakaway Switch	1.00
- Shop Supplies		Top Wind Knob	1.00
		Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 52.66	Total: 592.66
:			
<b>Workorder:</b> 1506745	<b>Meter:</b> 0	<b>In Date:</b> 07/07/2015	<b>Closed:</b> 07/13/2015
<b>Problem:</b> pm service			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Replace 3 tires		Seal 1.719 2.561 .500	4.00
- r/r trailer plug		762171406 205-75r15	3.00
- Replace brakeaway battery		Tr416 Valve Stem	3.00
- Adjust and clean all drum brakes. Repair l/r harness to drum plates		Trailer Conn Plug	1.00
		12v5amp/hour Battery	1.00
- Shop Supplies		Shop Supplies	1.00
		Tire Disposal Fee	3.00
Hours 9.50	Labor: 570.00	Parts: 438.02	Total: 1,008.02
:			
<b>Workorder:</b> 1611055	<b>Meter:</b> 0	<b>In Date:</b> 10/26/2016	<b>Closed:</b> 10/31/2016
<b>Problem:</b> pm service, check for loose deck boards			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Replace 3 deck boards		Planks 2x8x14	3.00
- Shop Supplies		Seal 1.719 2.561 .500	4.00
		Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 90.34	Total: 450.34
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1800179	<b>Meter:</b> 0	<b>In Date:</b> 01/04/2018	<b>Closed:</b> 01/30/2018
<b>Problem:</b> pm service			
- Pm		<b>Parts List</b>	<b>Qty</b>
- Replace trailer plug		Seal 1.719 2.561 .500	4.00
- Replace brake away battery		Non-chlor Brake Clnr	2.00
- Shop Supplies		Male Trailer Connector	1.00
		12v5amp/hour Battery	1.00
		Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 51.97	Total: 411.97
:			

---

<b>Workorder:</b> 1901747	<b>Meter:</b> 0	<b>In Date:</b> 02/14/2019	<b>Closed:</b> 03/11/2019
<b>Problem:</b> PM Service			
- Pm Service.		<b>Parts List</b>	<b>Qty</b>
- Replace breakaway battery box asm.mount,repair wiring and ground.		Break Away System	1.00
		Breakaway Switch	1.00
- Service electronic trailer brakes front and rear.clean and adjust.replace broken breakaway switch.		Seal 1.719 2.561 .500	4.00
		Grease Cap	4.00
- Remove hubs,clean out contaminated grease.reassemble.replace rear seals and grease caps with plug.		Grease Cap Plug	4.00
		Grease Cap Ss 1.98	4.00
- Shop Supplies		Shop Supplies	1.00
Hours 8.75	Labor: 586.25	Parts: 121.79	Total: 708.04
:			

---

<b>Workorder:</b> 2004170	<b>Meter:</b> 0	<b>In Date:</b> 04/27/2020	<b>Closed:</b> 05/11/2020
<b>Problem:</b> PM Service			
- Pm Service.		<b>Parts List</b>	<b>Qty</b>
- Replace 6 way trailer plug,		Male Trailer Connector	1.00
- Service front and rear brakes.		Non-chlor Brake Clnr	2.00
- Shop Supplies		Wd40 Spr	1.00
		Shop Supplies	1.00
Hours 8.00	Labor: 584.00	Parts: 27.13	Total: 611.13
:			

---

<b>Workorder:</b> 2009383	<b>Meter:</b> 0	<b>In Date:</b> 09/17/2020	<b>Closed:</b> 09/17/2020
<b>Problem:</b> Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 146.00	Parts: 0.00	Total: 146.00
:			

---

<b>Workorder:</b> 2009741	<b>Meter:</b> 0	<b>In Date:</b> 09/11/2020	<b>Closed:</b> 09/28/2020
<b>Problem:</b> "TURN IN" Being towed due to broken Ball Hitch on 9/14/2020 Contact John Soudard -561-252-2315			
- Tow From: 345 South Congress (fac South) To: Se shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			