

**Palm Beach County Fleet Management
Asset Maintenance History**

10165534 2006 JEEP LIBERTY Suv, Mid Size

| | | | |
|---|--------------------|-------------------------------------|---------------------------|
| Workorder: 639605 | Meter: 0 | In Date: 05/19/2006 | Closed: 05/19/2006 |
| Problem: TAG CHG | 05/19/06 | | |
| - Tag Chg | 05/19/06 | | |
| | | Parts List | Qty |
| | | Vehicle Tag Charge | 1.00 |
| Hours 0.00 | Labor: 0.00 | Parts: 51.85 | Total: 51.85 |
| : | | | |
| Workorder: 639611 | Meter: 0 | In Date: 05/22/2006 | Closed: 05/22/2006 |
| Problem: PRE-DELIVERY INSPECTION | | | |
| - Pre-delivery Inspection | | | |
| Hours 2.00 | Labor: 100.00 | Parts: 0.00 | Total: 100.00 |
| : | | | |
| Workorder: 640411 | Meter: 6 | In Date: 06/05/2006 | Closed: 06/19/2006 |
| Problem: INSTALL SPARE TIRE LOCK | | | |
| - Install Spare Tire Lock | | | |
| | | Parts List | Qty |
| | | 2508 Spare Tire Lock | 1.00 |
| Hours 0.50 | Labor: 25.00 | Parts: 20.12 | Total: 45.12 |
| : | | | |
| Workorder: 640703 | Meter: 0 | In Date: 06/12/2006 | Closed: 06/12/2006 |
| Problem: MINOR WELD REPAIR OR MACHINING. | | | |
| - Minor Weld Repair Or Machining. | | | |
| Hours 1.50 | Labor: 75.00 | Parts: 0.00 | Total: 75.00 |
| : | | | |
| Workorder: 641235 | Meter: 25 | In Date: 06/21/2006 | Closed: 06/26/2006 |
| Problem: CUT KEYS & PROGRAM | | | |
| - Cut Key & Program | | | |
| - Shop Supplies | | | |
| | | Parts List | Qty |
| | | 5139287aa Ign Key/fob | 2.00 |
| | | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 100.00 | Parts: 251.30 | Total: 351.30 |
| : | | | |
| Workorder: 733526 | Meter: 3044 | In Date: 01/30/2007 | Closed: 01/31/2007 |
| Problem: P.M SERVICE | | | |
| - Pm Service | | | |
| - Nitrogen Refill Tires. | | | |
| - Shop Supplies | | | |
| | | Parts List | Qty |
| | | Shop Supplies | 1.00 |
| | | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| | | 10w30 Motor Oil | 5.00 |
| Hours 3.00 | Labor: 165.00 | Parts: 16.70 | Total: 181.70 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 742994 **Meter:** 5102 **In Date:** 08/22/2007 **Closed:** 08/27/2007
Problem: P.M SERVICE,CHECK R/R PWR WINDOW

| | Parts List | Qty |
|---|--|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - Tire Balance All 4 Tires | Ca8817 Air Filter Lbf Af3588 Wix 42329 | 1.00 |
| - Transport To Dealer For Warrenty R/r Window Regulator And Recall # G03 Blower Motor. | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | 10020 Injector Cleaner Don't Reorder | 1.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | 2.00 |
| Hours 4.00 | Labor: 220.00 Parts: 49.37 | Total: 269.37 |
| : | | |

Workorder: 836327 **Meter:** 7663 **In Date:** 04/01/2008 **Closed:** 04/03/2008
Problem: P.M SERVICE

| | Parts List | Qty |
|--|-------------------------------------|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - Rotate And High Speed Balance Four Tires Refill W/nitrogen Air And Road Test. | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| - Shop Supplies | 10w30 Motor Oil | 6.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | 2.00 |
| | 5066964ad Wiper Blade Rear (jeep) | 1.00 |
| Hours 3.00 | Labor: 180.00 Parts: 41.59 | Total: 221.59 |
| : | | |

Workorder: 847252 **Meter:** 10026 **In Date:** 11/19/2008 **Closed:** 11/26/2008
Problem: P.M SERVICE,INSPECT A/C

| | Parts List | Qty |
|--|-------------------------------------|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - Ac Service And Inspection | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| - To/fr Dealer For Warranty Battey And Battery Cable | 10w30 Motor Oil | 5.00 |
| - Shop Supplies | Nb-19 Wiper Blades 19" Anco 31-19 | 2.00 |
| Hours 5.50 | Labor: 330.00 Parts: 27.69 | Total: 357.69 |
| : | | |

Workorder: 938952 **Meter:** 11436 **In Date:** 06/12/2009 **Closed:** 06/22/2009
Problem: PM SERVICE ALSO SEE NOTES ON AC AND DRIVER WINDOW.

| | Parts List | Qty |
|---|---|---------------|
| - Pm Service | Shop Supplies | 1.00 |
| - L/rear Window Not Working.remove Door Panel For Inspection. Repl Window Regulator/motor Assy.broken.replace Window Glass. | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| - Ac Blower Not Working On Speed 1&2.diag Circuits.replace Blower Resistor.burnt.test Ac Operation, Ok | 10w30 Motor Oil | 5.00 |
| - Rotate And Hi Speed Balance 4 Tires.fill W/nitrogen. | L/rear Window Regulator/less Glass | 1.00 |
| - Shop Supplies | L/rear Glass | 1.00 |
| | 5139719aa Resistor Blower Motor (dodge) | 1.00 |
| Hours 6.25 | Labor: 375.00 Parts: 297.55 | Total: 672.55 |
| : | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|--|-------------------------|----------------------------|---------------------------|
| Workorder: 941335 | Meter: 11659 | In Date: 07/28/2009 | Closed: 08/06/2009 |
| Problem: R/R window inop. A/C blows cold then warm . | | | |
| - Diagnose L/r window inop, R&r door panel & replace window regulator assembly. | Parts List | | Qty |
| | Shop Supplies | | 1.00 |
| - A/c inspection, replace leaking low pressure cycle switch, evacuate & recharge system. | R/rear Window Regulator | | 1.00 |
| | Window Glass | | 1.00 |
| - Shop Supplies | Window Tint | | 1.00 |
| | Low Pressure Switch | | 1.00 |
| Hours 3.50 | Labor: 210.00 | Parts: 264.25 | Total: 474.25 |
| : | | | |

| | | | |
|------------------------------------|-------------------------------------|----------------------------|---------------------------|
| Workorder: 1000875 | Meter: 13201 | In Date: 01/22/2010 | Closed: 02/02/2010 |
| Problem: P.M service. | | | |
| - P.m service. | Parts List | | Qty |
| - Replace worn drive belt. | Shop Supplies | | 1.00 |
| - Rotate & balance all four tires. | K060868 Serp Belt | | 1.00 |
| - Shop Supplies | 1516 Oil Filterfrm Ph3600 Wix 51516 | | 1.00 |
| | 10w30 Motor Oil | | 5.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | | 2.00 |
| Hours 3.50 | Labor: 210.00 | Parts: 69.87 | Total: 279.87 |
| : | | | |

| | | | |
|--|-------------------------------|----------------------------|---------------------------|
| Workorder: 1003006 | Meter: 13992 | In Date: 03/24/2010 | Closed: 03/29/2010 |
| Problem: D/S window fell down. | | | |
| - Diagnose & test driver side window motor failed, R&r motor/regulator & replace window glass. | Parts List | | Qty |
| | Shop Supplies | | 1.00 |
| - Shop Supplies | D/side Front Window Regulator | | 1.00 |
| | D/side Front Glass | | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 264.68 | Total: 384.68 |
| : | | | |

| | | | |
|---|--|----------------------------|---------------------------|
| Workorder: 1007953 | Meter: 15878 | In Date: 07/27/2010 | Closed: 08/04/2010 |
| Problem: P.M. Service.L/R window inop..See note. | | | |
| - Perform pm service. | Parts List | | Qty |
| - Diagnose and replace failed left rear window regulator and motor assembly with new. | Shop Supplies | | 1.00 |
| | 1516 Oil Filterfrm Ph3600 Wix 51516 | | 1.00 |
| - Inspect for noise and replace failed belt tensioner with new. | Ca8817 Air Filter Lbf Af3588 Wix 42329 | | 1.00 |
| - Rotate and balance all four tires. | 10w30 Motor Oil | | 5.00 |
| - Shop Supplies | L/rear Window Regulator/less Window | | 1.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | | 2.00 |
| | 5066964ad Wiper Blade Rear (jeep) | | 1.00 |
| | 49246 Belt Tensioner (goodyear) | | 1.00 |
| Hours 5.50 | Labor: 330.00 | Parts: 260.72 | Total: 590.72 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1012074 **Meter:** 16878 **In Date:** 10/28/2010 **Closed:** 10/29/2010
Problem: Right front window inop.

| | | |
|--|--------------------------|---------------|
| - Diagnose,inspect and replace failed right front window glass and regulator with new. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| | R/front Window Regulator | 1.00 |
| | Glass | 1.00 |
| | Label | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 252.43 |
| : | | Total: 372.43 |

Workorder: 1101495 **Meter:** 17644 **In Date:** 02/08/2011 **Closed:** 02/17/2011
Problem: Pm service.

| | | |
|--------------------------------------|-------------------------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Rotate and balance all four tires. | Shop Supplies | 1.00 |
| - Shop Supplies | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| | 10w30 Motor Oil | 5.00 |
| | 1066 White Lithium (crc 05037) | 1.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | 2.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 35.27 |
| : | | Total: 215.27 |

Workorder: 1109322 **Meter:** 19757 **In Date:** 08/31/2011 **Closed:** 09/09/2011
Problem: Pm service.

| | | |
|--------------------------------------|-------------------------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Rotate and balance all four tires. | Shop Supplies | 1.00 |
| - Shop Supplies | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| | 10w30 Motor Oil | 5.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 16.69 |
| : | | Total: 196.69 |

Workorder: 1202893 **Meter:** 22358 **In Date:** 03/26/2012 **Closed:** 04/09/2012
Problem: P.M. service and left rear window fell down.

| | | |
|---|-------------------------------------|---------------|
| - P.m. Service. | Parts List | Qty |
| - R&r left rear door panel and replace defective window regulator assemble. | Shop Supplies | 1.00 |
| - Rotate and balance all four tires. | 1516 Oil Filterfrm Ph3600 Wix 51516 | 1.00 |
| - Shop Supplies | Wd40 Spray Lube Stock# 405540002 | 1.00 |
| | 10w30 Motor Oil | 5.00 |
| | Lr Window Regulator | 1.00 |
| | Nb-19 Wiper Blades 19" Anco 31-19 | 2.00 |
| | 5066964ad Wiper Blade Rear (jeep) | 1.00 |
| Hours 4.50 | Labor: 270.00 | Parts: 276.93 |
| : | | Total: 546.93 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1206097 **Meter:** 23292 **In Date:** 06/28/2012 **Closed:** 07/06/2012
Problem: ABS and esp warning light on dash,see notes.

| | | | |
|--|---|--|---------------|
| <ul style="list-style-type: none"> - Computer diagnose for abs. and Esp.warning lights on.test and replace failed left rear wheel speed sensor with new.clear codes withscan tool and road test. - Diagnose for steering concern.inspect and replace serpentine belt with new counter measure belt asper tsb.to correct concern. - Inspect and replace both failed hood props/struts with new. - Repair right front tire flat.nitrogen fill and balance same. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies Fan Belt Gas Hood Support L/rear Wheel Speed Sensor | <p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 2.00 1.00 | |
| Hours 5.25 | Labor: 315.00 | Parts: 182.08 | Total: 497.08 |
| : | | | |

Workorder: 1207325 **Meter:** 23777 **In Date:** 08/03/2012 **Closed:** 08/09/2012
Problem: Right rear window inop.

| | | | |
|--|---|--|---------------|
| <ul style="list-style-type: none"> - Remove right rear door trim to acess,test and replace failed right rear window regulator/motor assembly with new. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Shop Supplies Right Rear Window Regulator | <p>Qty</p> <ul style="list-style-type: none"> 1.00 1.00 | |
| Hours 1.50 | Labor: 90.00 | Parts: 173.68 | Total: 263.68 |
| : | | | |

Workorder: 1300198 **Meter:** 25334 **In Date:** 01/04/2013 **Closed:** 01/17/2013
Problem: Pm service.

| | | | |
|---|--|--|-----------------|
| <ul style="list-style-type: none"> - P.m. Service. - Replace and balance four new tires. - Resurface rear brake rotors,replace rear brake pads.service and lube calipers,flush and bleed system and test drive. - Complete wheel alignment.test drive. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> 10w30 Motor Oil Ph3600 Oil Filter Lbf Wiper Blade Integral Blades Ca8817 Air Filter Lbf 183017418 P225-75r16 1401 Brake Fluid Bra 5066964ad Wiper Blade Front Brake Pads D981 Rear Pads Jeep L Shop Supplies Tire Disposal Fee | <p>Qty</p> <ul style="list-style-type: none"> 5.00 1.00 2.00 1.00 1.00 4.00 1.00 1.00 1.00 1.00 1.00 4.00 | |
| Hours 10.00 | Labor: 600.00 | Parts: 914.56 | Total: 1,514.56 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1311603 **Meter:** 29961 **In Date:** 11/18/2013 **Closed:** 11/27/2013
Problem: Pm service and turnsignals inop.

| | | |
|---|---------------------|---------------|
| - Perform pm service. | Parts List | Qty |
| - Test and replace failed right front and right rear turnsignal lamp bulbs with new.also replace failed third brake lamp bulb with new. | 10w30 Motor Oil | 5.00 |
| | Napagold Oil Filter | 1.00 |
| | Bulb | 1.00 |
| - Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new. | LI Miniature Bulb | 1.00 |
| | Bulb | 1.00 |
| - Inspect and replace both failed rear glass props with new. | Group 34 Battery | 1.00 |
| - Rotate and balance all four tires. | Glass Lift Support | 2.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 5.50 | Labor: 330.00 | Parts: 186.19 |
| : | | Total: 516.19 |

Workorder: 1400602 **Meter:** 30337 **In Date:** 01/17/2014 **Closed:** 01/28/2014
Problem: Check over all turnsignal lights operation.

| | | |
|--|-------------------|--------------|
| - Test and replace failed wiper blades and two turnsignal lamp bulbs with new. | Parts List | Qty |
| | Wiper Blade | 2.00 |
| - Shop Supplies | LI Miniature Bulb | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 0.75 | Labor: 45.00 | Parts: 24.32 |
| : | | Total: 69.32 |

Workorder: 1404128 **Meter:** 31916 **In Date:** 04/29/2014 **Closed:** 04/30/2014
Problem: Left rear tire flat.

| | | |
|--|-------------------|--------------|
| - Repair flat left rear tire.nitrogen fill and balance same. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1410441 **Meter:** 34690 **In Date:** 10/17/2014 **Closed:** 10/31/2014
Problem: Pm service and check for noise in steering and suspension.

| | | |
|--|---------------------------------|---------------|
| - P.m. Service. | Parts List | Qty |
| - Check front end for noise.replace both worn out lower ball joints. | 10w30 Motor Oil | 5.00 |
| | Napagold Oil Filter | 1.00 |
| - Complete wheel alignment.test drive. | Wiper Blade | 2.00 |
| - Rotate and balance all tires. | Wiper Blade | 1.00 |
| - Shop Supplies | Ball Joint - Lower - Front Susp | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 8.50 | Labor: 510.00 | Parts: 164.06 |
| : | | Total: 674.06 |

Workorder: 1503988 **Meter:** 36379 **In Date:** 04/17/2015 **Closed:** 04/17/2015
Problem: Brake issues/ PM service

| | | | |
|---|-------------|-------------|-------------|
| - Tow From: 525 Bacom Point, Pahokee Fl To: Lv Shop | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1504000 **Meter:** 36601 **In Date:** 04/17/2015 **Closed:** 04/30/2015
Problem: Pm service and towed in for brake concern.

| <ul style="list-style-type: none"> - Pm service. - Replace front brake pads and both front brake calipers.resurface both front brake rotors.flush and bleed brake system.roadtest. - Service transmission and replace filter.flush and replace transmission fluid. - Rotate and balance all four tires. - Shop Supplies | <table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>10w30 Motor Oil</td><td align="right">5.00</td></tr> <tr><td>Napagold Oil Filter</td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td align="right">2.00</td></tr> <tr><td>Wiper Blade</td><td align="right">1.00</td></tr> <tr><td>Reman Brake Caliper</td><td align="right">1.00</td></tr> <tr><td>1401 Brake Fluid Bra</td><td align="right">4.00</td></tr> <tr><td>Filter Kit</td><td align="right">1.00</td></tr> <tr><td>Syn-atf Trans Fluid S</td><td align="right">13.00</td></tr> <tr><td>Ptex Ultra Black 30z</td><td align="right">1.00</td></tr> <tr><td>Reman Brake Caliper</td><td align="right">1.00</td></tr> <tr><td>Filters</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table> | Parts List | Qty | 10w30 Motor Oil | 5.00 | Napagold Oil Filter | 1.00 | Wiper Blade | 2.00 | Wiper Blade | 1.00 | Reman Brake Caliper | 1.00 | 1401 Brake Fluid Bra | 4.00 | Filter Kit | 1.00 | Syn-atf Trans Fluid S | 13.00 | Ptex Ultra Black 30z | 1.00 | Reman Brake Caliper | 1.00 | Filters | 1.00 | Shop Supplies | 1.00 |
|--|--|-------------------|------------|-----------------|------|---------------------|------|-------------|------|-------------|------|---------------------|------|----------------------|------|------------|------|-----------------------|-------|----------------------|------|---------------------|------|---------|------|---------------|------|
| Parts List | Qty | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10w30 Motor Oil | 5.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Napagold Oil Filter | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Wiper Blade | 2.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Wiper Blade | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Reman Brake Caliper | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1401 Brake Fluid Bra | 4.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Filter Kit | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Syn-atf Trans Fluid S | 13.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Ptex Ultra Black 30z | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Reman Brake Caliper | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Filters | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Shop Supplies | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Hours 9.00 : | Labor: 540.00 Parts: 325.60 Total: 865.60 | | | | | | | | | | | | | | | | | | | | | | | | | | |

Workorder: 1509874 **Meter:** 37621 **In Date:** 09/29/2015 **Closed:** 10/20/2015
Problem: Pm service.Belt noise.Ac and blower speed inop.

| <ul style="list-style-type: none"> - Pm service. - Ac performance test.evacuate system.replace defective compressor,accumulator,orifice tube line and blower resistor.flush system.vacume and recharge system to specs. - Flush and refill cooling system. - Check starting and charging system.battery failed load test after recharge.replace defective battery. - Computer diagnose Abs warning light on.code C1032.test nd replace defective right rear wheel speed sensor.clear code and test drive. - Rotate and balance all four tires. - Shop Supplies | <table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>10w30 Motor Oil</td><td align="right">5.00</td></tr> <tr><td>Napagold Oil Filter</td><td align="right">1.00</td></tr> <tr><td>Wiper Blade</td><td align="right">2.00</td></tr> <tr><td>Serpentine Belt</td><td align="right">1.00</td></tr> <tr><td>Peak Global</td><td align="right">2.00</td></tr> <tr><td>Battery</td><td align="right">1.00</td></tr> <tr><td>E8 A/c Oil Univ W Dye</td><td align="right">1.00</td></tr> <tr><td>New Compressor</td><td align="right">1.00</td></tr> <tr><td>Alum Filter Drier Pm</td><td align="right">1.00</td></tr> <tr><td>Hose Assembly</td><td align="right">1.00</td></tr> <tr><td>R134a Lv Shop 1</td><td align="right">2.00</td></tr> <tr><td>Blower Motor Resistor</td><td align="right">1.00</td></tr> <tr><td>Rapid Seal Kit</td><td align="right">1.00</td></tr> <tr><td>Sensor</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table> | Parts List | Qty | 10w30 Motor Oil | 5.00 | Napagold Oil Filter | 1.00 | Wiper Blade | 2.00 | Serpentine Belt | 1.00 | Peak Global | 2.00 | Battery | 1.00 | E8 A/c Oil Univ W Dye | 1.00 | New Compressor | 1.00 | Alum Filter Drier Pm | 1.00 | Hose Assembly | 1.00 | R134a Lv Shop 1 | 2.00 | Blower Motor Resistor | 1.00 | Rapid Seal Kit | 1.00 | Sensor | 1.00 | Shop Supplies | 1.00 |
|---|---|-------------------|------------|-----------------|------|---------------------|------|-------------|------|-----------------|------|-------------|------|---------|------|-----------------------|------|----------------|------|----------------------|------|---------------|------|-----------------|------|-----------------------|------|----------------|------|--------|------|---------------|------|
| Parts List | Qty | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 10w30 Motor Oil | 5.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Napagold Oil Filter | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Wiper Blade | 2.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Serpentine Belt | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Peak Global | 2.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Battery | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| E8 A/c Oil Univ W Dye | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| New Compressor | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Alum Filter Drier Pm | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Hose Assembly | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| R134a Lv Shop 1 | 2.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Blower Motor Resistor | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Rapid Seal Kit | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Sensor | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Shop Supplies | 1.00 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Hours 14.50 : | Labor: 870.00 Parts: 746.29 Total: 1,616.29 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Workorder: 1701233 **Meter:** 41621 **In Date:** 02/06/2017 **Closed:** 02/28/2017
Problem: P.M. service and recall N46.

| <ul style="list-style-type: none"> - P.m. Service. - Rotate and balance tires. - Transport vehicle to dealer for recall @n46. - Shop Supplies | <table border="0"> <thead> <tr> <th align="left">Parts List</th> <th align="right">Qty</th> </tr> </thead> <tbody> <tr><td>10w30 Motor Oil</td><td align="right">5.00</td></tr> <tr><td>Napagold Oil Filter</td><td align="right">1.00</td></tr> <tr><td>Wiper Blade Anco</td><td align="right">2.00</td></tr> <tr><td>Accufit Rear</td><td align="right">1.00</td></tr> <tr><td>Shop Supplies</td><td align="right">1.00</td></tr> </tbody> </table> | Parts List | Qty | 10w30 Motor Oil | 5.00 | Napagold Oil Filter | 1.00 | Wiper Blade Anco | 2.00 | Accufit Rear | 1.00 | Shop Supplies | 1.00 |
|---|---|-------------------|------------|-----------------|------|---------------------|------|------------------|------|--------------|------|---------------|------|
| Parts List | Qty | | | | | | | | | | | | |
| 10w30 Motor Oil | 5.00 | | | | | | | | | | | | |
| Napagold Oil Filter | 1.00 | | | | | | | | | | | | |
| Wiper Blade Anco | 2.00 | | | | | | | | | | | | |
| Accufit Rear | 1.00 | | | | | | | | | | | | |
| Shop Supplies | 1.00 | | | | | | | | | | | | |
| Hours 5.00 : | Labor: 300.00 Parts: 32.17 Total: 332.17 | | | | | | | | | | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|---|---------------------|----------------------------|---------------------------|
| Workorder: 1702594 | Meter: 41827 | In Date: 03/14/2017 | Closed: 03/28/2017 |
| Problem: Left brake light inop and right rear inner door panel broken. | | | |
| - Replace left brake lamp bulb. | | Parts List | Qty |
| - Fabricate and repair right rear door inside panel. | | Bulb | 1.00 |
| - Shop Supplies | | Plastic Welding System | 1.00 |
| | | Shop Supplies | 1.00 |
| Hours 1.50 | Labor: 90.00 | Parts: 7.99 | Total: 97.99 |
| : | | | |
| Workorder: 1703833 | Meter: 42405 | In Date: 04/14/2017 | Closed: 04/27/2017 |
| Problem: Towed in right rear tire flat. | | | |
| - Replace and balance all four dry rotted tires. | | Parts List | Qty |
| - Complete wheel alignment.test drive. | | 183017418 P225-75r16 | 4.00 |
| - Shop Supplies | | Shop Supplies | 1.00 |
| | | Tire Disposal Fee | 4.00 |
| Hours 4.50 | Labor: 270.00 | Parts: 673.66 | Total: 943.66 |
| : | | | |
| Workorder: 1703853 | Meter: 42225 | In Date: 04/14/2017 | Closed: 04/17/2017 |
| Problem: Right Rear flat | | | |
| - Tow From: South of Southern on Jog Rd, southbound To: vista | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1705027 | Meter: 42614 | In Date: 05/19/2017 | Closed: 05/24/2017 |
| Problem: Towed in for no crank. | | | |
| - Charge battery fully .test battery and charging system.r&r defective battery. | | Parts List | Qty |
| - Shop Supplies | | Battery | 1.00 |
| | | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 114.17 | Total: 174.17 |
| : | | | |
| Workorder: 1705029 | Meter: 42575 | In Date: 05/19/2017 | Closed: 05/19/2017 |
| Problem: No start | | | |
| - Tow From: 4289 Cherry Rd, Wpb To: Lv shop | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1711428 | Meter: 44543 | In Date: 11/17/2017 | Closed: 12/04/2017 |
| Problem: P.M. service and check lights. | | | |
| - P.m. service. | | Parts List | Qty |
| - Check ,pinpoint test and replace defective right rear turn signal bulb. | | 10w30 Motor Oil | 5.00 |
| - Replace leaking spare rim and tire.balance and rotate all five tires. | | Napagold Oil Filter | 1.00 |
| - Shop Supplies | | Wiper Blade Anco | 2.00 |
| | | Wiper | 1.00 |
| | | Bulb | 1.00 |
| | | Wheel Rin | 1.00 |
| | | Shop Supplies | 1.00 |
| | | P225/75r16 Tire | 1.00 |
| Hours 4.50 | Labor: 270.00 | Parts: 289.73 | Total: 559.73 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1805364 **Meter:** 46784 **In Date:** 05/25/2018 **Closed:** 06/05/2018
Problem: P.M. service and check engine light on .

| | | |
|---|-----------------------|-----------------|
| - P.m. service. | Parts List | Qty |
| - Replace both front upper controls due to play. | 10w30 Motor Oil | 6.00 |
| - Replace both rear rotors and brake pads .service calipers and flush and bleed brake system . | Napagold Oil Filter | 1.00 |
| - Computer diagnose check engine light ,code P0456 .perform evap test .replace defective fuel cap and clear codes and retest. | Washer Fluid Concentr | 1.00 |
| - Test and replace right brake light bulb. Retest. | 10in Exactfitblade | 1.00 |
| - Perform complete alignment.test drive. | Wiper Blade Anco | 2.00 |
| - Shop Supplies | Non-chlor Brake Clnr | 1.00 |
| | Gas Cap Non-locking | 1.00 |
| | Control Arm | 2.00 |
| | Brake Rotor | 2.00 |
| | Brake Pad | 1.00 |
| | B Fluid Dot 3-32oz | 1.00 |
| | Boxed Miniatures | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 11.50 | Labor: 690.00 | Parts: 311.36 |
| : | | Total: 1,001.36 |

Workorder: 1810215 **Meter:** 48725 **In Date:** 10/02/2018 **Closed:** 10/22/2018
Problem: P.M. service and recall U38 18v-278 .

| | | |
|---|-----------------------|---------------|
| - P.m. service. | Parts List | Qty |
| - Remove and replace all four bump stops . | 10w30 Motor Oil | 6.00 |
| - Rotate and balance all four tires. Nitrofill all. | Napagold Oil Filter | 1.00 |
| - Transport to and from dealer for recall U38 .replace both rear lower control arms . | Washer Fluid Concentr | 1.00 |
| - Shop Supplies | Mac Wite Lithium Gres | 1.00 |
| | jounce bumper real | 2.00 |
| | Bump Stop | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 5.60 | Labor: 375.20 | Parts: 487.92 |
| : | | Total: 863.12 |

Workorder: 1900070 **Meter:** 49776 **In Date:** 01/02/2019 **Closed:** 01/07/2019
Problem: Towed in left front window broken and battery stolen .

| | | |
|--|-------------------|---------------|
| - Replace missing battery and test starting and charging systems . | Parts List | Qty |
| - Remove left front door panel to replace broken window . Clean up all broken glass. | Battery | 1.00 |
| - Shop Supplies | Glass Door | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 134.00 | Parts: 281.34 |
| : | | Total: 415.34 |

Workorder: 1900108 **Meter:** 49605 **In Date:** 01/02/2019 **Closed:** 01/03/2019
Problem: Broken back window/Stolen Battery (Vandalism)

| | | | |
|---|-------------|-------------|-------------|
| - Tow From: 4289 Chery Rd, (libray Annex) To: Lv shop | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1900509 **Meter:** 49800 **In Date:** 01/14/2019 **Closed:** 01/17/2019
Problem: Check engine light on .

| | | |
|---|-------------------|---------------|
| - Computer diagnose check engine light ,code P0455 .test evap system . Repair leaking vacuum hose at purge valve . Retest evap system . | Parts List | Qty |
| | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 1.50 | Labor: 100.50 | Parts: 3.00 |
| : | | Total: 103.50 |

Workorder: 1903780 **Meter:** 50550 **In Date:** 04/08/2019 **Closed:** 04/11/2019
Problem: P.M. Service.Check engine light.

| | | |
|---|----------------------|---------------|
| - P.m. service. | Parts List | Qty |
| - Computer diagnose check engine light , code P0456 . Perform evap test . Smoke test . R&r defective fuel cap and retest . Clear code . | Napagold Oil Filter | 1.00 |
| | 10w30 Motor Oil | 6.00 |
| - Balance and rotate all four tires . Nitrofill all. | Wiper Blade Anco | 2.00 |
| - Shop Supplies | Napagold Air Filter | 1.00 |
| | Gas Cap Non-locking | 1.00 |
| | Steering Wheel Cover | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 4.50 | Labor: 301.50 | Parts: 47.75 |
| : | | Total: 349.25 |

Workorder: 1905772 **Meter:** 51375 **In Date:** 05/31/2019 **Closed:** 06/25/2019
Problem: Check engine light on .

| | | |
|---|-------------------|-----------------|
| - Diagnose check engine light.p0456.perform smoke test on evap system.replace defective filler tube and pump.retest system. | Parts List | Qty |
| | Tube Fuel | 1.00 |
| - Recharge and test battery,fail load test.replace defective battery.(warranty). | Evap Valve | 1.00 |
| | Battery | 1.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 4.50 | Labor: 301.50 | Parts: 865.38 |
| : | | Total: 1,166.88 |

Workorder: 1907495 **Meter:** 51736 **In Date:** 07/19/2019 **Closed:** 08/26/2019
Problem: Check engine light on .

| | | |
|--|-------------------|---------------|
| - Computer diagnose , code P0456 . Perform pinpoint test . Replace defective Nvld valve and inspect all hoses . Retest evap system . Road test . | Parts List | Qty |
| | Evap Valve | 1.00 |
| - Shop Supplies | Evap Valve | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 2.50 | Labor: 167.50 | Parts: 409.31 |
| : | | Total: 576.81 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1909018 **Meter:** 51900 **In Date:** 08/28/2019 **Closed:** 09/11/2019
Problem: Back of vehicle smoking.

| | | | |
|---|--|-------------------|-----------------|
| <ul style="list-style-type: none"> - Test drive . Inspect brakes . Replace both rear calipers ,rotors and brake pads . Replace parking brake shoes and both parking brake cables . . Flush and bleed brake system . Road test . - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Brake Cable 1.00 Brake Cable 1.00 Brake Rotor-dih Parki 2.00 B Fluid Dot 3-32oz 1.00 Brakeshoes Park 1.00 Reman Brake Caliper 1.00 Reman Brake Caliper 1.00 Brake Pad 1.00 Shop Supplies 1.00 | <p>Qty</p> | |
| Hours 5.00 | Labor: 335.00 | Parts: 669.60 | Total: 1,004.60 |
| : | | | |

Workorder: 1909077 **Meter:** 51736 **In Date:** 08/28/2019 **Closed:** 08/29/2019
Problem: Smoking

- Tow From: 18685 Sr7,boca Raton FI (boca Library) To: Lv shop

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1913038 **Meter:** 52510 **In Date:** 12/20/2019 **Closed:** 01/03/2020
Problem: PM Service

| | | | |
|---|---|-------------------|---------------|
| <ul style="list-style-type: none"> - P.m. service. - Perform tune up . Replace all six spark plugs . - Perform complete fresh air intake decarb and throttle body cleaning . Flush injectors . - Inspect and service rear differential . - Rotate and balance all four tires . Nitrofill all. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Napagold Oil Filter 7.00 10w30 Motor Oil 6.00 Washer Fluid Concentr 1.00 12" wiper blade 1.00 Wiper Blade Anco 2.00 Throttle Body Cleaner 1.00 Cham Plt Pwr Spark Pl 6.00 Motor Tune-up 16oz 1.00 Intake Cleaner Kit 1.00 Px Grey Rtv Silicone 1.00 Napa Gear 80w-90 Qt 3.00 Shop Supplies 1.00 | <p>Qty</p> | |
| Hours 7.60 | Labor: 554.80 | Parts: 138.19 | Total: 692.99 |
| : | | | |

Workorder: 2002300 **Meter:** 53122 **In Date:** 03/05/2020 **Closed:** 03/11/2020
Problem: ABS light on.

| | | | |
|---|--|-------------------|---------------|
| <ul style="list-style-type: none"> - Computer diagnose Abs light , Code C1034. Perform pinpoint test . Replace defective left rear wheel speed sensor . Clear code and retest . - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Sensor 1.00 Shop Supplies 1.00 | <p>Qty</p> | |
| Hours 2.00 | Labor: 146.00 | Parts: 33.48 | Total: 179.48 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2002338 **Meter:** 53101 **In Date:** 03/03/2020 **Closed:** 03/05/2020
Problem: Brake Issues

- Tow From: 4289 Cherry Rd (library Annex) To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 2009940 **Meter:** 53259 **In Date:** 10/01/2020 **Closed:** 10/14/2020
Problem: P.M. service left turn signal inop .

- P.m. service.

- Test and replace defective blower motor resistor .

- Test and replace left rear turn signal bulb .

- Replace all four dry rotted tire and balance . Nitrofill all.

- Perform complete front end alignment and road test .

- Shop Supplies

Parts List

| | Qty |
|-----------------------|------------|
| Napagold Oil Filter | 1.00 |
| 10w30 Motor Oil | 5.00 |
| Washer Fluid Concentr | 1.00 |
| Wiper | 1.00 |
| Wiper Blade Anco | 2.00 |
| Mac Wite Lithium Gres | 1.00 |
| Blower Motor Resistor | 1.00 |
| Boxed Miniatures | 1.00 |
| 183017418 P225-75r16 | 4.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |

Hours 8.00 Labor: 584.00 Parts: 782.93 Total: 1,366.93
:

Workorder: 2011033 **Meter:** 53259 **In Date:** 11/02/2020 **Closed:** 11/02/2020
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00
: