

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10198089     2015 SCAG STT61V25KBD Mower, Zero Turn Radius (Ztr)**

**Workorder:** 1500489     **Meter:** 1     **In Date:** 01/14/2015     **Closed:** 01/14/2015  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00     Labor: 120.00     Parts: 0.00     Total: 120.00  
:

**Workorder:** 1502768     **Meter:** 23     **In Date:** 03/17/2015     **Closed:** 04/07/2015  
**Problem:** running hot over heating, missing lug nuts on back wheels , grease fittings cap

- replace spidle caps installnew wheel hub and lug nuts r  
side hub and rim provided by franks mower warranty  
- ck over heating ck coolant level test mow 1 hour unable to  
verify complaint at this time  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Spindle Cap	2.00
Shop Supplies	1.00

Hours 3.00     Labor: 180.00     Parts: 13.16     Total: 193.16  
:

**Workorder:** 1507333     **Meter:** 118     **In Date:** 07/22/2015     **Closed:** 08/06/2015  
**Problem:** SMOKE COMING FROM EXHAUST,WONT RUN FULL THROTTLE/P.M.SERVICE

- pm  
- wash eq  
- svc hyd sys inspect lines hoses etc correct fluid level  
- engine smoking wont idle up trouble shoot found pre air  
filter in backwards restricking air flow to motor replace air  
filter test drive  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Napagold Air Filter	1.00
Napagold Oil Filter	1.00
15w40 Bulk South Reg	4.00
Macs Battery Cleaner	1.00
Wd40 16oz	1.00
Fuel Filter	1.00
Fuel Filter	1.00
Shop Supplies	1.00

Hours 7.00     Labor: 420.00     Parts: 79.73     Total: 499.73  
:

**Workorder:** 1507910     **Meter:** 123     **In Date:** 08/07/2015     **Closed:** 08/11/2015  
**Problem:** ck battery

- ck battery test battery multiiple times test good unable to  
verify complaint at ths time ck charging sys  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Shop Supplies	1.00

Hours 1.00     Labor: 60.00     Parts: 2.00     Total: 62.00  
:

**Workorder:** 1508804     **Meter:** 156     **In Date:** 09/02/2015     **Closed:** 09/08/2015  
**Problem:** BELT POPPED/CKECK HYDRAULIC FLUID.

- ck belt belt adj deck pullys grease all fittings replace belt  
test mow  
- Shop Supplies

<b>Parts List</b>	<b>Qty</b>
Cutter Deck Belt	1.00
Shop Supplies	1.00

Hours 3.00     Labor: 180.00     Parts: 110.15     Total: 290.15  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1510288	<b>Meter:</b> 224	<b>In Date:</b> 10/09/2015	<b>Closed:</b> 10/20/2015
<b>Problem:</b> grease fittings/front deck wheel and bar.			
- ck deck wheels replace 4 deck wheels and 3 center wheels and shaft	<b>Parts List</b>	<b>Qty</b>	
	Anti-scalp Wheel	4.00	
- lube all grease fittings torque rear lug nuts	Carriage Bolt	4.00	
- Shop Supplies	Lug Nut	4.00	
	Anti Scalp Wheel	3.00	
	Roller Shaft	1.00	
	Shop Supplies	1.00	
Hours 3.00	Labor: 180.00	Parts: 188.27	Total: 368.27
:			
<b>Workorder:</b> 1512173	<b>Meter:</b> 278	<b>In Date:</b> 12/02/2015	<b>Closed:</b> 12/09/2015
<b>Problem:</b> nuestral safety switch, clutch broken and harness			
- verify clutch broken rr pto clutch provided by lawn mower head quarters repair damaged wiring test mow	<b>Parts List</b>	<b>Qty</b>	
	Shop Supplies	1.00	
- ck damaged switch replace nuestral safety switch			
- Shop Supplies			
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			
<b>Workorder:</b> 1603830	<b>Meter:</b> 278	<b>In Date:</b> 04/12/2016	<b>Closed:</b> 04/26/2016
<b>Problem:</b> New grass chute.New front deck pin with new roller wheels.Two new rear tires.			
- C/c rear tires.replace rear tires.add N2	<b>Parts List</b>	<b>Qty</b>	
- C/c rollers chute etc..replace chute and front rollers.	24-1200-12b Turf M Carl	2.00	
- Shop Supplies	deck chutes	1.00	
	Anti Scalp Wheel	3.00	
	Roller Shaft	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 4.00	Labor: 240.00	Parts: 451.97	Total: 691.97
:			
<b>Workorder:</b> 1604971	<b>Meter:</b> 410	<b>In Date:</b> 05/12/2016	<b>Closed:</b> 05/26/2016
<b>Problem:</b> Check pulleys bearing and chute.Replace front wheel and cover for spindle pulley on deck.			
- C/c making noise.lubricate all pulleys,drive shafts,etc..replace caps and front rollers.	<b>Parts List</b>	<b>Qty</b>	
	Roller Shaft	1.00	
- Change gear oil in Pto gear box	Anti Scalp Wheel	3.00	
- Shop Supplies	Spindle Cap	2.00	
	85 W 140 Drum South	2.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 79.10	Total: 319.10
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1610683	<b>Meter:</b> 590	<b>In Date:</b> 10/17/2016	<b>Closed:</b> 10/28/2016
<b>Problem:</b> PM service.Two rear tires.check all belts			
- P.m.service	<b>Parts List</b>	<b>Qty</b>	
- Service Hyd. System. R/r Filter,correct Fluid Level,inspect	Napagold Air Filter	1.00	
All-replace Hyd. Drive Belt.	Napagold Oil Filter	1.00	
- R/r Chute,rollers,anti Scalp Wheels.	15w40 Bulk South Reg	4.00	
- Verify Oil Sending Unit Leaking. R/r Oil Sending Unit.	Napa Trans Filter	1.00	
- C/c Two Rear Tires. R/r Rear Tires.	Oil Pressure Sender	1.00	
- Wash Equipment For Service And Repair.	Fuel Fil	1.00	
- Shop Supplies	Napagold Fuel Filter	1.00	
	Belt	1.00	
	deck chutes	1.00	
	Anti Scalp Wheel	3.00	
	Roller Shaft	1.00	
	Anti-scalp Wheel	2.00	
	Carriage Bolt	2.00	
	Lug Nut	2.00	
	24-1200-12b Turf M Carl	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 11.75	Labor: 705.00	Parts: 913.01	Total: 1,618.01
:			
<b>Workorder:</b> 1612011	<b>Meter:</b> 603	<b>In Date:</b> 11/21/2016	<b>Closed:</b> 11/30/2016
<b>Problem:</b> Wont stay running Hard to start,keeps cutting off.Needs two front tires.			
- C/c Wont Start. Verify Needs L/h Nuetral Safety Switch. R/r	<b>Parts List</b>	<b>Qty</b>	
Switch, Test Runs.	S9278 Tire-wheel Assy	2.00	
- Install Two New Solid Wheel Assy.	Seat Switch	1.00	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.50	Labor: 150.00	Parts: 350.60	Total: 500.60
:			
<b>Workorder:</b> 1706041	<b>Meter:</b> 779	<b>In Date:</b> 06/19/2017	<b>Closed:</b> 06/26/2017
<b>Problem:</b> Replace belt.Replace chute.			
- C/c belt and chute..replace chute,deck belt and lube	<b>Parts List</b>	<b>Qty</b>	
all.replace air filter clamp and dust cap.replace all rollers	Air Filter Cleaner Cap	1.00	
shafts and two brackets.	deck chutes	1.00	
- Shop Supplies	Cutter Deck Belt	1.00	
	Anti Scalp Wheel	3.00	
	Anti-scalp Wheel	4.00	
	Carriage Bolt	4.00	
	Anti-scalp Wheel Bracket	2.00	
	Roller Shaft	1.00	
	Lug Nut	4.00	
	Shop Supplies	1.00	
Hours 4.00	Labor: 240.00	Parts: 514.94	Total: 754.94
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1709929      **Meter:** 844      **In Date:** 10/11/2017      **Closed:** 11/20/2017  
**Problem:** pm/ see list

	<b>Parts List</b>	<b>Qty</b>
- Pm	Battery	1.00
- Hyd Service	Fuel Fil	1.00
- R/r broken clutch and repair wiring	Napagold Fuel Filter	1.00
- R/r hyd pump cover	Napagold Air Filter	1.00
- R/r weak battery	Napagold Oil Filter	1.00
- R/r deck belt	Napagold Air Filter	1.00
- R/r deck assembly transfer all parts	15-40 Oil	4.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Napa Trans Filter	1.00
	Napa 20w50 Qt	2.00
	Cutter Deck Belt	1.00
	Bearing	2.00
	Roller Shaft	1.00
	Anti Scalp Wheel	3.00
	Pulley	2.00
	Electric Clutch Assy	1.00
	Linkage Assy	1.00
	Shroud	1.00
	cutter deck	1.00
	Turbo Baffle	1.00
	Rod Weldment - Pusharm	2.00
	Deck Wear Pad	1.00
	Baffle	1.00
	Shop Supplies	1.00
Hours 16.00	Labor: 960.00	Parts: 3,793.70
:		Total: 4,753.70

**Workorder:** 1804883      **Meter:** 957      **In Date:** 05/10/2018      **Closed:** 05/31/2018  
**Problem:** Radiator loose and leaking.

	<b>Parts List</b>	<b>Qty</b>
- Verify top radiator mount went bad.radiator hit fan damaging beyond repairs.drain coolant Flush block.and hoses.replace radiator and resevoir.fill with coolant.and test run.	1gal Rtu Antifreeze	2.00
	Rub Cushion	1.00
- Shop Supplies	Radiator	1.00
	Coolant Res Tank	1.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 1,002.73
:		Total: 1,302.73

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1809180	<b>Meter:</b> 976	<b>In Date:</b> 09/06/2018	<b>Closed:</b> 09/27/2018
<b>Problem:</b> Keeps stalling./ P.M.SERVICE			
- Pm Service.	<b>Parts List</b>	<b>Qty</b>	
- Replace discharge chute.	Napagold Air Filter	1.00	
- Service hyd. system	Napagold Air Filter	1.00	
- C/c stalls.verify fuel tank contaminated with water and debris..clean screen pickup .drain tank.test run.	Napagold Fuel Filter	1.00	
	Fuel Fil	1.00	
- Wash equipment	15w40 Bulk South Reg	4.00	
- Shop Supplies	Napagold Oil Filter	1.00	
	deck chutes	1.00	
	Clean-r-carb 20oz	1.00	
	Shop Supplies	1.00	
Hours 8.00	Labor: 480.00	Parts: 127.94	Total: 607.94
:			
<b>Workorder:</b> 1810629	<b>Meter:</b> 1123	<b>In Date:</b> 10/16/2018	<b>Closed:</b> 10/31/2018
<b>Problem:</b> PTO Belt.Check rear tires			
- C/c belt fell off.replace Pto belt and anti rotation arm.	<b>Parts List</b>	<b>Qty</b>	
- Replace 2 rear tires.	Pto Spring	1.00	
- Shop Supplies	Linkage Assy	1.00	
	Lawn Blt	1.00	
	24-1200-12b Turf M Carl	2.00	
	481460 Clutch Belt Sc	1.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 4.75	Labor: 318.25	Parts: 447.91	Total: 766.16
:			
<b>Workorder:</b> 1812376	<b>Meter:</b> 1152	<b>In Date:</b> 12/05/2018	<b>Closed:</b> 12/12/2018
<b>Problem:</b> CHECK BATTERY/ NEED JUMP TO START			
- C/c wont start.remove and test battery,bad.replace battery and check charging system.	<b>Parts List</b>	<b>Qty</b>	
- Shop Supplies	Battery	1.00	
	Shop Supplies	1.00	
Hours 1.00	Labor: 67.00	Parts: 122.58	Total: 189.58
:			
<b>Workorder:</b> 1900125	<b>Meter:</b> 1157	<b>In Date:</b> 01/03/2019	<b>Closed:</b> 01/14/2019
<b>Problem:</b> Check starting,charging system and battery.			
- C/c test battery.loadtest battery and checked connections.passed test.	<b>Parts List</b>	<b>Qty</b>	
- C/c Check charging system.checked for draw.unable to duplicate any problem at this time.tighten alt.belt.	Shop Supplies	1.00	
- Shop Supplies			
Hours 2.00	Labor: 134.00	Parts: 3.00	Total: 137.00
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1904906	<b>Meter:</b> 1272	<b>In Date:</b> 05/06/2019	<b>Closed:</b> 05/30/2019
<b>Problem:</b> Broken deck belt			
- C/c broken deck belt.adjust pulley alignment.check fluid in gear boxreplace tensioner bearings and belt.grease all.test mow.		<b>Parts List</b>	<b>Qty</b>
		Bolt	1.00
		Idler Pivot	1.00
		Bearing	2.00
		Cutter Deck Belt	1.00
		Shop Supplies	1.00
Hours 2.75	Labor: 184.25	Parts: 173.54	Total: 357.79
:			
<b>Workorder:</b> 1907830	<b>Meter:</b> 1379	<b>In Date:</b> 07/29/2019	<b>Closed:</b> 08/19/2019
<b>Problem:</b> Broken belt.Hyd.oil leak.			
- C/c hyd. leak.found leaking hyd filter.install new suction Oem filter.correct fluid level.		<b>Parts List</b>	<b>Qty</b>
		Napa 20w50 Qt	3.00
- C/c Deck belt broken.replace deck belt and spring,wing nut,deck arm joints,l/h spindle bolt and nut.		Oil Filter	1.00
		Cutter Deck Spring	1.00
- Wash equipment.		Cutter Deck Belt	1.00
		U Nut	1.00
- Shop Supplies		Wing Nut	1.00
		Nut	1.00
		Hh Bolt	1.00
		rod end	2.00
		Shop Supplies	1.00
Hours 5.00	Labor: 335.00	Parts: 341.51	Total: 676.51
:			
<b>Workorder:</b> 1908905	<b>Meter:</b> 1411	<b>In Date:</b> 08/26/2019	<b>Closed:</b> 08/30/2019
<b>Problem:</b> Left deck support rod.			
- C/c left deck support lever for chain adjuster fell off.replace bolt and adjust linkage.		<b>Parts List</b>	<b>Qty</b>
		Shop Supplies	1.00
- Shop Supplies			
Hours 1.75	Labor: 117.25	Parts: 3.00	Total: 120.25
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1910267      **Meter:** 1495      **In Date:** 10/03/2019      **Closed:** 10/29/2019

**Problem:** PM Service.Adjust E-Brake.

- Pm Service.	<b>Parts List</b>	<b>Qty</b>
- Service hyd.system.inspect lines,hoses,etc...replace hyd.filter,correct fluid level.	Napagold Air Filter	1.00
- C/c adjust E-brake.replace both caliper assemblies.adjust linkages.	Fuel Fil	1.00
- Wash equipment.	Napagold Fuel Filter	1.00
- Replace all antiscalp wheels,rollers,and hardware,spindle cap etc..	15w40 Bulk South Reg	4.00
- Replace front right solid wheel assm.	Napagold Oil Filter	1.00
- Shop Supplies	Napa 20w50 Qt	1.00
	Oil Filter	1.00
	Carriage Bolt	4.00
	Caliper Assy	2.00
	Spindle Cap	1.00
	Lug Nut	4.00
	Anti-scalp Wheel	4.00
	Anti Scalp Wheel	3.00
	Roller Shaft	1.00
	S9278 Tire-wheel Assy	1.00
	Shop Supplies	1.00
Hours 11.50	Labor: 839.50	Parts: 727.51
:		Total: 1,567.01

**Workorder:** 1911353      **Meter:** 1513      **In Date:** 10/31/2019      **Closed:** 11/12/2019

**Problem:** Deck belt coming off.Check all belts.

- Replace deck belt.align spindle and pulleys.r/r idler pulley and bolt. Test mow. Lube all.	<b>Parts List</b>	<b>Qty</b>
- Shop Supplies	Washer	1.00
	Nut	1.00
	Bolt Hex	1.00
	Pulley	1.00
	Cutter Deck Belt	1.00
	Shop Supplies	1.00
Hours 2.25	Labor: 164.25	Parts: 188.76
:		Total: 353.01

**Workorder:** 2001538      **Meter:** 1603      **In Date:** 02/12/2020      **Closed:** 02/28/2020

**Problem:** Broken belt (PTO).

- C/c Pto belt.replace Pto Belt.reassemble and test run.	<b>Parts List</b>	<b>Qty</b>
- Replace air cleaner cap.	481460 Clutch Belt Sc	1.00
- Shop Supplies	Air Filter Cleaner Cap	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 146.00	Parts: 112.23
:		Total: 258.23

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 2005405      **Meter:** 1603      **In Date:** 05/29/2020      **Closed:** 06/30/2020

**Problem:** Front right wheel bearing.Left front deck wheel bolt.

- Verify battery tested bad.replace battery.check charging system	<b>Parts List</b>	<b>Qty</b>
	Battery	1.00
- Replace spindle cap,scalp wheels,bracket etc...	Lug Nut	4.00
- Replace front wheel bearings and seals.	Carriage Bolt	4.00
- Replace cap with latches on air filter housing.	Anti-scalp Wheel	4.00
- Shop Supplies	Anti-scalp Wheel Bracket	1.00
	Spindle Cap	2.00
	04001167 Wheel Bolt N	2.00
	43583 Sleeve Scag	2.00
	Wheel Spacer	4.00
	Nut	2.00
	Seal	4.00
	Bearing Scag	4.00
	Air Filter	1.00
	Shop Supplies	1.00
Hours 5.50	Labor: 401.50	Parts: 574.20
:		Total: 975.70

**Workorder:** 2008295      **Meter:** 1603      **In Date:** 08/19/2020      **Closed:** 08/25/2020

**Problem:** PTO Belt.

- C/c Pto belt.replace Pto belt and tdler pulley.deck dropping slow.remove drive shaft.clean lube and reinstall.lube all pivot points.test mow.	<b>Parts List</b>	<b>Qty</b>
	Idler Pulley	1.00
- Shop Supplies	481460 Clutch Belt Sc	1.00
	Shop Supplies	1.00
Hours 4.50	Labor: 328.50	Parts: 77.95
:		Total: 406.45

**Workorder:** 2010119      **Meter:** 0      **In Date:** 10/07/2020      **Closed:** 11/05/2020

**Problem:** pm service, broken weld on rgt frt wheel, 4 new tires, hour meter broken

- Pm Service	<b>Parts List</b>	<b>Qty</b>
- Replace Front & Rear Tires	Napagold Oil Filter	1.00
- Replace Discharge Chute	Prem Blue 15w40 1 Gal	1.00
- Replace 3 Blades	Fuel Fil	1.00
- Replace Hour Meter	Napagold Fuel Filter	1.00
- Repair/weld Broken Front Frame	Napagold Air Filter	1.00
- Clean & Adjust Parking Brake	24x12.00-12/4 Turf Master	2.00
- Wash Mower	S9278 Tire-wheel Assy	2.00
- Shop Supplies	Blade	3.00
	deck chutes	1.00
	Diesel Hour Meter	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.00	Labor: 1,022.0	Parts: 874.40
:	0	Total: 1,896.40



**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 2011527      **Meter:** 0      **In Date:** 11/18/2020      **Closed:** 11/23/2020  
**Problem:** weld cracked near front right tire

	<b>Parts List</b>	<b>Qty</b>
- Repair Cracked Front Frame, Straighten, Fabricate And Weld In Support Plates, Grind And Paint	Shop Supplies	1.00

- Shop Supplies

Hours 9.00

Labor: 657.00

Parts: 4.00

Total: 661.00

:

---

**Workorder:** 2100088      **Meter:** 0      **In Date:** 01/05/2021      **Closed:** 01/05/2021  
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours 2.00

Labor: 146.00

Parts: 0.00

Total: 146.00

: