

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

Workorder: 638068

Problem: PRE-DELIVERY INSPECTION

| Meter Reading: 0          | Labor                | Parts       |          |
|---------------------------|----------------------|-------------|----------|
| In Date: 04/26/2006       | Hours                | Description | Quantity |
| - Pre-Delivery Inspection | 2.00                 |             |          |
| Parts Charge: 0.00        | Labor Charge: 100.00 |             |          |

Workorder: 648929

Problem: P.M.

| Meter Reading: 1767 | Labor               | Parts                                |          |
|---------------------|---------------------|--------------------------------------|----------|
| In Date: 11/20/2006 | Hours               | Description                          | Quantity |
| - Pm Service        | 4.50                | SHOP SUPPLIES                        | 1.00     |
| - Nitro Tires       |                     | PH16 OIL FILTER LBF PH253 WIX 51307  | 1.00     |
| - Repair Bed Liner  |                     | 85/140 GEAR OIL GEAR LUBE            | 1.00     |
| - Road Test         |                     | USED FIREX REFURBED FIRE EXTINGSHERS | 1.00     |
| - Shop Supplies     |                     | 5W20 ENGINE OIL                      | 7.00     |
|                     |                     | 1066 WHITE LITHIUM (CRC 05037)       | 1.00     |
| Parts Charge: 48.63 | Labor Charge: 27.50 |                                      |          |

Workorder: 741550

Problem: P.M SERVICE

| Meter Reading: 8342                                   | Labor               | Parts                                  |          |
|---|---------------------|--|----------|
| In Date: 07/17/2007                                   | Hours               | Description                            | Quantity |
| - Pm Service  | 4.75                | USED FIREX REFURBED FIRE EXTINGSHERS   | 1.00     |
| - Test Strobe Light Circuits,Remove R/F Head Lamp And |                     | S30HACP STROBE BULB FOR KIT S660CCCC   | 1.00     |
| Replace Strobe Bulb                                   |                     | 10020 INJECTOR CLEANER DON'T REORDER   | 1.00     |
| - Balance All 4 Wheels And Nitro Tires                |                     | SHOP SUPPLIES                          | 1.00     |
| - Shop Supplies                                       |                     | CA9401 AIR FILTER LBF AF3590 WIX 42725 | 1.00     |
|   |                     | PH16 OIL FILTER LBF PH253 WIX 51307    | 1.00     |
|   |                     | 31-24 WIPER BLADES 24" BLADE           | 2.00     |
|   |                     | 5W20 ENGINE OIL                        | 7.00     |
| Parts Charge: 105.46                                  | Labor Charge: 55.00 |  |          |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 742134

**Problem:** A/C NOT WORKING PROPERLY.

| <b>Meter Reading:</b> 8717                        | <b>Labor</b> | <b>Parts</b>         |                 |
|---|--------------|----------------------|-----------------|
| <b>In Date:</b> 07/27/2007                        | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |
| - Transport To Dealer For Air Conditioning Repair | 1.00         | SHOP SUPPLIES        | 1.00            |
| - Shop Supplies                                   |              |                      |                 |
| <b>Parts Charge:</b>                              | 2.00         | <b>Labor Charge:</b> | 27.50           |

**Workorder:** 748856

**Problem:** P.M SERVICE

| <b>Meter Reading:</b> 14320                             | <b>Labor</b> | <b>Parts</b>                           |                 |
|---|--------------|--|-----------------|
| <b>In Date:</b> 12/19/2007                              | <b>Hours</b> | <b>Description</b>                     | <b>Quantity</b> |
| - Pm Service  | 4.75         | CA9401 AIR FILTER LBF AF3590 WIX 42725 | 1.00            |
| - High Speed Balance All 4 Tires And Clean Mud Off Rims |              | PH16 OIL FILTER LBF PH253 WIX 51307    | 1.00            |
| - Repair & Reinstall Frt Lower Bumper Valance.Reattach  |              | 5W20 ENGINE OIL                        | 7.00            |
| Bed Liner Rails   |              | 10020 INJECTOR CLEANER DON'T REORDER   | 1.00            |
| - Shop Supplies   |              | 31-24 WIPER BLADES 24" BLADE           | 2.00            |
|   |              | SHOP SUPPLIES                          | 1.00            |
| <b>Parts Charge:</b>                                    | 45.29        | <b>Labor Charge:</b>                   | 60.00           |

**Workorder:** 836127

**Problem:** TIRESOLES OF BROWARD INC

| <b>Meter Reading:</b> 0    | <b>Labor</b> | <b>Parts</b>              |                 |
|----------------------------|--------------|---------------------------|-----------------|
| <b>In Date:</b> 03/20/2008 | <b>Hours</b> | <b>Description</b>        | <b>Quantity</b> |
| - Tiresoles Of Broward Inc |              |                           |                 |
| <b>Parts Charge:</b>       | 0.00         | <b>Labor Charge:</b>      | 0.00            |
|                            |              | <b>Commercial Charge:</b> | 60.00           |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 837991

**Problem:** P.M SERVICE.A/C INSPECTION

| <b>Meter Reading:</b> 18500   |                               | <b>Labor</b>               |  | <b>Parts</b>    |      |
|---|-------------------------------|----------------------------|--|-----------------|------|
| <b>In Date:</b> 05/05/2008  | <b>Close Date:</b> 05/21/2008 | <b>Hours</b>               | <b>Description</b>                       | <b>Quantity</b> |      |
| - Pm Service  |                               | <b>6.55</b>                | CA9401 AIR FILTER LBF AF3590 WIX 42725   |                 | 1.00 |
| - Rotate Tires Highspeed Balance All 4                                    |                               |                            | PH16 OIL FILTER LBF PH253 WIX 51307      |                 | 1.00 |
| - Remove/Reinstall Computer Stand So Dealer Can Gain Access Toevaporater. |                               |                            | 31-24 WIPER BLADES 24" BLADE             |                 | 2.00 |
| - To/Fr Dealer For Warranty Evaporator Coil                               |                               |                            | 5W20 ENGINE OIL                          |                 | 7.00 |
| - Shop Supplies   |                               |                            | USED FIREX REFURBED FIRE EXTINGSHERS     |                 | 1.00 |
|   |                               |                            | SHOP SUPPLIES                            |                 | 1.00 |
|   |                               |                            | CUSTOM5LB BRACKET FIREX STOCK #340060300 |                 | 1.00 |
|   |                               |                            | WD40 SPRAY LUBE STOCK# 405540002         |                 | 1.00 |
| <b>Parts Charge:</b> 81.40  |                               | <b>Labor Charge:</b> 42.00 |  |                 |      |

**Workorder:** 846140

**Problem:** P.M SERVICE,SEE NOTE

| <b>Meter Reading:</b> 22239  |                               | <b>Labor</b>               |                                      | <b>Parts</b>    |       |
|--|-------------------------------|----------------------------|--------------------------------------|-----------------|-------|
| <b>In Date:</b> 10/24/2008   | <b>Close Date:</b> 11/06/2008 | <b>Hours</b>               | <b>Description</b>                   | <b>Quantity</b> |       |
| - Pm Service   |                               | <b>8.75</b>                | 5W20 ENGINE OIL                      |                 | 7.00  |
| - Remove L/F Headligh Assy To Perform Test On Strobe Light.R&Rdefective Bulb.                    |                               |                            | PH16 OIL FILTER LBF PH253 WIX 51307  |                 | 1.00  |
| - Scan For Codes P0457.Perform Pinpoint Test.Repl Defective Fuel Cap.Retest Evap Sys.Test Drive. |                               |                            | 31-24 WIPER BLADES 24" BLADE         |                 | 2.00  |
| - Service Trans.Flush And Refill   |                               |                            | 1066 WHITE LITHIUM (CRC 05037)       |                 | 1.00  |
| - To/Fr Dealer For Ac Condenser Fan & D/S Seat Cushion   |                               |                            | S30HACP STROBE BULB FOR KIT S660CCCC |                 | 1.00  |
| - Shop Supplies  |                               |                            | FUEL CAP                             |                 | 1.00  |
|  |                               |                            | SYN/ATF TRANS FLUID SYNTHETIC        |                 | 12.00 |
|  |                               |                            | SHOP SUPPLIES                        |                 | 1.00  |
| <b>Parts Charge:</b> 170.15  |                               | <b>Labor Charge:</b> 60.00 |                                      |                 |       |

**Workorder:** 935463

**Problem:** INSTALL COMPUTER STAND AND WIRING HARNESS.

| <b>Meter Reading:</b> 24043                              |                               | <b>Labor</b>                |                    | <b>Parts</b>    |      |
|--|-------------------------------|-----------------------------|--------------------|-----------------|------|
| <b>In Date:</b> 03/23/2009                               | <b>Close Date:</b> 03/25/2009 | <b>Hours</b>                | <b>Description</b> | <b>Quantity</b> |      |
| - Fabricate And Install Computer Stand And Wire Harness. |                               | <b>4.00</b>                 | SHOP SUPPLIES      |                 | 1.00 |
| - Shop Supplies  |                               |                             |                    |                 |      |
| <b>Parts Charge:</b> 2.00                                |                               | <b>Labor Charge:</b> 240.00 |                    |                 |      |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 939345                      **Problem:** P.M. SERVICE.REMOVE COMPUTER STAND.

| Meter Reading: 26121   | Labor    | Parts                     |
|------------------------|----------|---------------------------|
| In Date: 06/23/2009    | Hours    | Description               |
| Close Date: 06/30/2009 | Quantity | Quantity                  |
| -                      |          |                           |
| <b>Parts Charge:</b>   | 0.00     | <b>Labor Charge:</b> 0.00 |

**Workorder:** 940130                      **Problem:** P.M SERVICE

| Meter Reading: 26121                                    | Labor    | Parts                                       |
|---|----------|---|
| In Date: 07/02/2009                                     | Hours    | Description                                 |
| Close Date: 07/02/2009                                  | Quantity | Quantity                                    |
| - P.M Service   | 7.75     | 5W20 ENGINE OIL 7.00                        |
| - Mount, Balance & Nitro Fill 4 Tires                   |          | PH16 OIL FILTER LBF PH253 WIX 51307 1.00    |
| - Alignment   |          | USED FIREX REFURBED FIRE EXTINGSHERS 1.00   |
| - Diagnose & Repair Open Circuit In Strobe Light System |          | TIRE DISPOSAL FEE 4.00                      |
| - Shop Supplies   |          | CA9401 AIR FILTER LBF AF3590 WIX 42725 1.00 |
|   |          | SHOP SUPPLIES 1.00                          |
|   |          | TR416 VALVE STEM 4.00                       |
|   |          | 179469492 LT245/70R17 WRANGLER SR-A E 4.00  |
| <b>Parts Charge:</b>                                    | 700.62   | <b>Labor Charge:</b> 465.00                 |

**Workorder:** 1002664                      **Problem:** 2 - Wash ticket(s) issued

| Meter Reading: 26888        | Labor    | Parts   |
|-----------------------------|----------|---|
| In Date: 03/16/2010         | Hours    | Description   |
| Close Date: 03/16/2010      | Quantity | Quantity  |
| - 2 - Wash Ticket(S) Issued |          |   |
| <b>Parts Charge:</b>        | 0.00     | <b>Labor Charge:</b> 0.00 <b>Commercial Charge:</b> 14.40 |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1002701

**Problem:** P.M.SERVICE,L/REAR STROBE LIGHT INOP.BRAKES ARE SQUEALING

| <b>Meter Reading:</b> 27117                          | <b>Labor</b> | <b>Parts</b>                          |                 |
|--|--------------|---------------------------------------|-----------------|
| <b>In Date:</b> 03/16/2010                           | <b>Hours</b> | <b>Description</b>                    | <b>Quantity</b> |
| - P. M. Service.                                     | <b>4.50</b>  | 5W20 ENGINE OIL                       | 7.00            |
| - Replace Left Rear Strobe Light.                    |              | HA238C STROBE BULB USE WHELEN #S30HAC | 1.00            |
| - Install "How'S My Driving" Decal.                  |              | PH16 OIL FILTER LBF PH253 WIX 51307   | 1.00            |
| - C/S: Brake Squeaks. Verify. Inspect Brakes & Found |              | 5W20 ENGINE OIL                       | 1.00            |
| Brake Noise To Be Normal, Because Of The Type Of     |              | SHOP SUPPLIES                         | 1.00            |
| Brake Pads On Vehicle. Test Drive.                   |              |                                       |                 |
| - Shop Supplies                                      |              |                                       |                 |
| <b>Parts Charge:</b>                                 | 84.08        | <b>Labor Charge:</b>                  | 270.00          |

**Workorder:** 1002936

**Problem:** P.M service, install customers computer stand.

| <b>Meter Reading:</b> 27160                          | <b>Labor</b> | <b>Parts</b>                        |                 |
|--|--------------|-------------------------------------|-----------------|
| <b>In Date:</b> 03/23/2010                           | <b>Hours</b> | <b>Description</b>                  | <b>Quantity</b> |
| - P.M Service.                                       | <b>6.75</b>  | PH16 OIL FILTER LBF PH253 WIX 51307 | 1.00            |
| - Fabricate & Install Customer Computer Stand & Wire |              | 1066 WHITE LITHIUM (CRC 05037)      | 1.00            |
| Harness.   |              | 31-24 WIPER BLADES 24" BLADE        | 2.00            |
| - Shop Supplies                                      |              | 5W20 ENGINE OIL                     | 7.00            |
|  |              | SHOP SUPPLIES                       | 1.00            |
| <b>Parts Charge:</b>                                 | 30.10        | <b>Labor Charge:</b>                | 405.00          |

**Workorder:** 1004490

**Problem:** Right rear strobe light out

| <b>Meter Reading:</b> 28293             | <b>Labor</b> | <b>Parts</b>                          |                 |
|---|--------------|---------------------------------------|-----------------|
| <b>In Date:</b> 04/30/2010              | <b>Hours</b> | <b>Description</b>                    | <b>Quantity</b> |
| - Replace Right Rear Strobe Light Bulb. | <b>0.50</b>  | SHOP SUPPLIES                         | 1.00            |
| - Shop Supplies                         |              | HA238C STROBE BULB USE WHELEN #S30HAC | 1.00            |
| <b>Parts Charge:</b>                    | 42.47        | <b>Labor Charge:</b>                  | 30.00           |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1006176

**Problem:** MOUNT FUEL TANK/NEEDS AUX FUEL PUMP ASSY.

| Meter Reading: 29919                               | Labor  | Parts                           |          |
|--|--------|---------------------------------|----------|
| In Date: 06/10/2010                                | Hours  | Description                     | Quantity |
| - Clean, Assemble, & Install Aux Fuel Tank & Pump. | 17.25  | PRE-VENT FILL CAP               | 1.00     |
| - Fabricate Brackets & Install Tool Box.           |        | CAST IRON ADAPTER 3/4           | 1.00     |
| - R&R Wiper Blades.                                |        | SHOP SUPPLIES                   | 1.00     |
| - Repair Bed Liner                                 |        | 31-24 WIPER BLADES 24" BLADE    | 2.00     |
| - Shop Supplies                                    |        | DS-167 TOGGLE SWITCH (STANDARD) | 1.00     |
|  |        | 12V DC FUEL PUMP                | 1.00     |
|  |        | HYD. FILTERS                    | 2.00     |
|  |        | S-12-30 30 AMP BREAKER          | 1.00     |
| <b>Parts Charge:</b>                               | 650.83 | <b>Labor Charge:</b>            | 1,035.00 |

**Workorder:** 1008125

**Problem:** P. M. Service, & tighten screw for rear view mirror

| Meter Reading: 32008  | Labor | Parts                                     |          |
|---|-------|---|----------|
| In Date: 07/30/2010   | Hours | Description                               | Quantity |
| - P. M.   | 6.25  | SHOP SUPPLIES                             | 1.00     |
| - R&R Aux Tank Filter, & Lubed Nozzle, & Checked Operation. |       | CA9401 AIR FILTER LBF AF3590 WIX 42725    | 1.00     |
| - R&R Bulb.   |       | 1259 HYDR FILTER LBF FRM P1653A WIX 51259 | 1.00     |
| - Disassembled Lens, Repaired Connector, And R&R Bulb.      |       | PH16 OIL FILTER LBF PH253 WIX 51307       | 1.00     |
| - Lubed & Unsiezed Hook.                                    |       | 3157 TAIL LIGHT BULBS                     | 1.00     |
| - Tightened Mirror & Installed Driving Decal.               |       | 5W20 ENGINE OIL                           | 7.00     |
| - Shop Supplies   |       | HA238C STROBE BULB USE WHELEN #S30HAC     | 1.00     |
| <b>Parts Charge:</b>  | 91.53 | <b>Labor Charge:</b>                      | 375.00   |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1100621

**Problem:** P. M., strobe lights not working, new wipers, brake light out

| Meter Reading: 37127<br>In Date: 01/14/2011  | Close Date: 01/31/2011 | Labor<br>Hours | Description                               | Parts  | Quantity |
|--|------------------------|----------------|---|--------|----------|
| - P. M. Service.   |                        | <b>13.25</b>   | 1259 HYDR FILTER LBF FRM P1653A WIX 51259 |        | 1.00     |
| - Service Aux Fuel Tank.   |                        |                | F132005 BRAKE LUBE                        |        | 1.00     |
| - Replace Left Rear Brake Light Bulb. Replace Right Rear Park Light Bulb.  |                        |                | 3157 TAIL LIGHT BULBS                     |        | 2.00     |
| - Resurface Front Rotors, Service Calipers, Replace Pads & Test Drive.   |                        |                | 1401 BRAKE FLUID BRAKE FLUID              |        | 2.00     |
| - Check Charging System & Replace Battery.   |                        |                | 09997 BRAKE CLEAN                         |        | 1.00     |
| - C/S: Strobe Lights Not Working. Verify. Perform Pinpoint Test & Found Bad Switch. Relocate, Replace & Rewire Switch. |                        |                | FRONT BRAKE PAD                           |        | 1.00     |
| - Shop Supplies  |                        |                | SHOP SUPPLIES                             |        | 1.00     |
|  |                        |                | GROUP 65 BATTERY (MTC BXT-65-850)         |        | 1.00     |
|  |                        |                | DS-167 TOGGLE SWITCH (STANDARD)           |        | 1.00     |
|  |                        |                | 5W20 ENGINE OIL                           |        | 7.00     |
|  |                        |                | 31-24 WIPER BLADES 24" BLADE              |        | 2.00     |
|  |                        |                | PH16 OIL FILTER LBF PH253 WIX 51307       |        | 1.00     |
|  | <b>Parts Charge:</b>   | 252.42         | <b>Labor Charge:</b>                      | 795.00 |          |

**Workorder:** 1106740

**Problem:** Right rear strobe light inop.

| Meter Reading: 41394<br>In Date: 06/27/2011 | Close Date: 06/28/2011 | Labor<br>Hours | Description                          | Parts | Quantity |
|---|------------------------|----------------|--------------------------------------|-------|----------|
| - Replace Right Rear Strobe Bulb.           |                        | <b>0.50</b>    | S30HACP STROBE BULB FOR KIT S660CCCC |       | 1.00     |
| - Shop Supplies                             |                        |                | SHOP SUPPLIES                        |       | 1.00     |
|   | <b>Parts Charge:</b>   | 42.92          | <b>Labor Charge:</b>                 | 30.00 |          |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1107676

**Problem:** P. M. SERVICE

| Meter Reading: 41955                             | Labor  | Parts                                     |          |
|--|--------|---|----------|
| In Date: 07/21/2011                              | Hours  | Description                               | Quantity |
| - P. M. Service.                                 | 5.25   | 5W20 ENGINE OIL                           | 7.00     |
| - Service Aux Fuel Tank.                         |        | CA9401 AIR FILTER LBF AF3590 WIX 42725    | 1.00     |
| - Replace Both Rear Tires & Rotate To The Front. |        | 1259 HYDR FILTER LBF FRM P1653A WIX 51259 | 1.00     |
| - Shop Supplies                                  |        | SHOP SUPPLIES                             | 1.00     |
|  |        | LT245/70R17E,WANGLER SR-A                 | 2.00     |
|  |        | PH16 OIL FILTER LBF PH253 WIX 51307       | 1.00     |
|  |        | WASTE FEE                                 | 2.00     |
|  |        | USED FIREX REFURBED FIRE EXTINGSHERS      | 1.00     |
|  |        | 31-24 WIPER BLADES 24" BLADE              | 2.00     |
|  |        | TIRE DISPOSAL FEE                         | 2.00     |
| <b>Parts Charge:</b>                             | 411.95 | <b>Labor Charge:</b>                      | 315.00   |

**Workorder:** 1111353

**Problem:** Strobe light left rear works slowly

| Meter Reading: 44770  | Labor | Parts                                 |          |
|---|-------|---------------------------------------|----------|
| In Date: 10/26/2011   | Hours | Description                           | Quantity |
| - C/S: Strobe Light Working Slowly. Perform Pinpoint & Found Bad Left Rear Strobe Light Bulb. Replace Bulb. | 1.00  | SHOP SUPPLIES                         | 1.00     |
|   |       | HA238C STROBE BULB USE WHELEN #S30HAC | 1.00     |
| - Shop Supplies   |       |                                       |          |
| <b>Parts Charge:</b>  | 43.24 | <b>Labor Charge:</b>                  | 60.00    |



1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1201427

**Problem:** P.M. service and turn signal inop.

| <b>Meter Reading:</b> 47435 |  | <b>Labor</b> |                                       | <b>Parts</b>    |        |
|-----------------------------|--|--------------|---------------------------------------|-----------------|--------|
| <b>In Date:</b> 02/13/2012  | <b>Close Date:</b> 02/29/2012  | <b>Hours</b> | <b>Description</b>                    | <b>Quantity</b> |        |
| -                           | Perform Pm Service.  | <b>7.50</b>  | 5W20 ENGINE OIL                       |                 | 7.00   |
| -                           | Inspect And Service Auxiliary Fuel Tank Also Install New Fuel Filter.  |              | PH16 OIL FILTER LBF PH253 WIX 51307   |                 | 1.00   |
| -                           | Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.  |              | 31-24 WIPER BLADES 24" BLADE          |                 | 2.00   |
| -                           | Diagnose All Turnsignal Lights Inop.Remove Both Head Lamps And Tail Lamps.Test And Replace Both Failed Tail Lamp Sockets,Six 3157 Bulbs In Rear And Two 3157 Na Bulbs In Front With New. |              | 179469492 LT245/70R17 WRANGLER SR-A E |                 | 2.00   |
| -                           | Shop Supplies  |              | TR416 VALVE STEM                      |                 | 2.00   |
|                             |  |              | TIRE DISPOSAL FEE                     |                 | 2.00   |
|                             |  |              | 24006 FUEL FILTER DIESEL AND GAS      |                 | 1.00   |
|                             |  |              | 3157NA AMBER BULB                     |                 | 2.00   |
|                             |  |              | SHOP SUPPLIES                         |                 | 1.00   |
|                             |  |              | 3157 TAIL LIGHT BULBS                 |                 | 6.00   |
|                             |  |              | TAIL LAMP SOCKET ASSY                 |                 | 2.00   |
| <b>Parts Charge:</b>        |  | 420.34       | <b>Labor Charge:</b>                  |                 | 450.00 |

**Workorder:** 1205560

**Problem:** Power outlets inop.

| <b>Meter Reading:</b> 52283 |   | <b>Labor</b> |                      | <b>Parts</b>    |       |
|-----------------------------|---|--------------|----------------------|-----------------|-------|
| <b>In Date:</b> 06/13/2012  | <b>Close Date:</b> 06/21/2012   | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |       |
| -                           | Test For Short Circuit And Replace Failed 15 Amps Fuse For Power Outlet With New. | <b>0.50</b>  |                      |                 |       |
| <b>Parts Charge:</b>        |   | 0.00         | <b>Labor Charge:</b> |                 | 30.00 |

**Workorder:** 1205804

**Problem:** Accident

| <b>Meter Reading:</b> 52283 |  | <b>Labor</b> |                      | <b>Parts</b>              |        |
|-----------------------------|--|--------------|----------------------|---------------------------|--------|
| <b>In Date:</b> 06/18/2012  | <b>Close Date:</b> 06/19/2012  | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b>           |        |
| -                           | Tow From: Forest Hill Blvd (Btwn Haverhill And Military) To: Accident Line |              |                      |                           |        |
| <b>Parts Charge:</b>        |  | 0.00         | <b>Labor Charge:</b> |                           | 0.00   |
|                             |  |              |                      | <b>Commercial Charge:</b> | 104.15 |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1206422

**Problem:** damage to frt bumper, rgt head light, rgt fender & rgt tire

| <b>Meter Reading:</b> 52498                                   | <b>Labor</b> | <b>Parts</b>         |                 |                                    |
|---|--------------|----------------------|-----------------|------------------------------------|
| <b>In Date:</b> 06/19/2012                                    | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |                                    |
| - Damage To Frt Bumper, Rgt Head Light, Rgt Fender & Rgt Tire |              |                      |                 |                                    |
| <b>Parts Charge:</b>  | 0.00         | <b>Labor Charge:</b> | 0.00            | <b>Commercial Charge:</b> 1,992.60 |

**Workorder:** 1206511

**Problem:** P.M. service and right rear strobe light inop.

| <b>Meter Reading:</b> 52498  | <b>Labor</b> | <b>Parts</b>         |                 |  |
|--|--------------|----------------------|-----------------|--|
| <b>In Date:</b> 07/12/2012   | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |  |
| - P.M. Service. <b>6.25</b> SHOP SUPPLIES 1.00                                   |              |                      |                 |  |
| - Replace Right Rear Strobe Light Bulb. PH16 OIL FILTER LBF PH253 WIX 51307 1.00 |              |                      |                 |  |
| - Inspect And Service Aux. Fuel Tank. TRANSFER TANK FUEL FILTER 1.00             |              |                      |                 |  |
| - Repair Right Rear Tire. S30HACP STROBE BULB FOR KIT S660CCCC 1.00              |              |                      |                 |  |
| - Rotate And Balance All Tires. 31-24 WIPER BLADES 24" BLADE 2.00                |              |                      |                 |  |
| - Shop Supplies USED FIREX REFURBED FIRE EXTINGSHERS 1.00                        |              |                      |                 |  |
| 5W20 ENGINE OIL 7.00   |              |                      |                 |  |
| <b>Parts Charge:</b>   | 96.78        | <b>Labor Charge:</b> | 375.00          |  |

**Workorder:** 1209448

**Problem:** Engine overheated and right rear strobe light inop.

| <b>Meter Reading:</b> 53375   | <b>Labor</b> | <b>Parts</b>         |                 |  |
|---|--------------|----------------------|-----------------|--|
| <b>In Date:</b> 10/02/2012  | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |  |
| - Pressure Test And Inspect Cooling System.Replace Fan <b>4.00</b> S30HACP STROBE BULB F 1.00 |              |                      |                 |  |
| Clutch And Thermostat.Flush And Refill System. CLUTCH FAN 1.00                                |              |                      |                 |  |
| - Replace Right Rear Strobe Light Bulb. RADIATOR CAP 1.00                                     |              |                      |                 |  |
| - Shop Supplies ANTIFREEZE EXT-LIFE 2.00  |              |                      |                 |  |
| THERMOSTAT 1.00   |              |                      |                 |  |
| SHOP SUPPLIES 1.00  |              |                      |                 |  |
| <b>Parts Charge:</b>  | 289.99       | <b>Labor Charge:</b> | 240.00          |  |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1209705                      **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

| Meter Reading: 53233                       | Labor                     | Parts                           |
|--|---------------------------|---------------------------------|
| In Date: 10/10/2012                        | Hours                     | Description                     |
| Close Date: 10/10/2012                     |                           | Quantity                        |
| - 1 - Detail Vehicle Wash Ticket(S) Issued |                           |                                 |
| <b>Parts Charge:</b> 0.00                  | <b>Labor Charge:</b> 0.00 | <b>Commercial Charge:</b> 97.92 |

**Workorder:** 1212343                      **Problem:** Signal light and strobe lights inop.

| Meter Reading: 54450                                  | Labor                      | Parts                 |
|---|----------------------------|-----------------------|
| In Date: 12/27/2012                                   | Hours                      | Description           |
| Close Date: 12/28/2012                                |                            | Quantity              |
| - Test And Replace Failed Right Rear Strobe Lamp Bulb | 1.00                       | S30HACP STROBE BULB F |
| With New.Remove Left Head Lamp And Replace Failed     |                            | MINIATURE BULB        |
| Signal Lamp Bulb With New.                            |                            | SHOP SUPPLIES         |
| - Shop Supplies                                       |                            |                       |
| <b>Parts Charge:</b> 56.95                            | <b>Labor Charge:</b> 60.00 |                       |

**Workorder:** 1300775                      **Problem:** Pm service.Check over all lights.Back up alarm inop.

| Meter Reading: 54959                                   | Labor                       | Parts                 |
|--|-----------------------------|-----------------------|
| In Date: 01/23/2013                                    | Hours                       | Description           |
| Close Date: 01/31/2013                                 |                             | Quantity              |
| - P.M. Service.  | 9.00                        | CA9401 AIR FILTER LBF |
| - Inspect And Service Aux. Fuel System.                |                             | PH16 OIL FILTER LBF P |
| - Replace Both Brake Light Bulbs.Fabricate And Install |                             | USED FIREX REFURBED F |
| Back-Up Alarm.   |                             | 9-2951 BACKUP ALARM E |
| - Replace Belt Tensioner And Idler Pulley.             |                             | IDLER PULLEY          |
| - Repair Left Rear Tire,Rotate And Balance All Four.   |                             | 31-24 WIPER BLADES 2  |
| - Shop Supplies  |                             | MINIATURE BULB        |
|  |                             | DR BLT TENSIONER ASSY |
|  |                             | FUEL FILTER           |
|  |                             | 5W20 ENGINE OIL       |
|  |                             | SHOP SUPPLIES         |
| <b>Parts Charge:</b> 205.37                            | <b>Labor Charge:</b> 540.00 |                       |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1301733

**Problem:** ck brake lights

|   |                            |                    |                 |
|---|----------------------------|--------------------|-----------------|
| <b>Meter Reading:</b> 55487   | <b>Labor</b>               | <b>Parts</b>       |                 |
| <b>In Date:</b> 02/20/2013  | <b>Hours</b>               | <b>Description</b> | <b>Quantity</b> |
| <hr/>   |                            |                    |                 |
| - Ck Brake Light Verify Rr Brake Light Out Replace 3157 Tail Light Bulb | <b>0.50</b>                | MINIATURE BULB     | 1.00            |
| <b>Parts Charge:</b> 0.72   | <b>Labor Charge:</b> 30.00 |                    |                 |

**Workorder:** 1306318

**Problem:** rr strobe light not on

|   |                            |                       |                 |
|---|----------------------------|-----------------------|-----------------|
| <b>Meter Reading:</b> 58114                             | <b>Labor</b>               | <b>Parts</b>          |                 |
| <b>In Date:</b> 06/24/2013                              | <b>Hours</b>               | <b>Description</b>    | <b>Quantity</b> |
| <hr/>   |                            |                       |                 |
| - Repaired Connection At Strobe Pack Rr Bulb At Rs Rear | <b>1.00</b>                | S30HACP STROBE BULB F | 1.00            |
| - Shop Supplies   |                            | SHOP SUPPLIES         | 1.00            |
| <b>Parts Charge:</b> 57.36                              | <b>Labor Charge:</b> 60.00 |                       |                 |

**Workorder:** 1306801

**Problem:** l front turn signl indicator out

|                                       |                            |                    |                 |
|---------------------------------------|----------------------------|--------------------|-----------------|
| <b>Meter Reading:</b> 58729           | <b>Labor</b>               | <b>Parts</b>       |                 |
| <b>In Date:</b> 07/09/2013            | <b>Hours</b>               | <b>Description</b> | <b>Quantity</b> |
| <hr/>                                 |                            |                    |                 |
| - Replace Left Front Turn Signal Bulb | <b>0.50</b>                | 3157NA AMBER BULB  | 1.00            |
| <b>Parts Charge:</b> 1.79             | <b>Labor Charge:</b> 30.00 |                    |                 |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1308581

**Problem:** P.M. service.

| Meter Reading: 60010<br>In Date: 08/26/2013  | Close Date: 09/20/2013        | Labor<br>Hours              | Description             | Parts | Quantity |
|--|-------------------------------|-----------------------------|-------------------------|-------|----------|
| - P.M. Service.  |                               | <b>15.50</b>                | USED FIRE X REFURBISHED |       | 1.00     |
| - Replace Left Rear Strobe Bulb And Right Brake Lamp Bulb.   |                               |                             | NAPAGOLD FUEL FILTER    |       | 1.00     |
|  |                               |                             | BATTERY 65              |       | 1.00     |
| - Replace Leaking Battery And Test Charging System.Replace Noisy Alternator And Idler Pulley.        |                               |                             | RADIATOR                |       | 1.00     |
|  |                               |                             | FAN SHROUD              |       | 1.00     |
| - Pressure Test And Inspect Cooling System.Replace Leaking Radiator.Flush And Refill Cooling System. |                               |                             | SHOP SUPPLIES           |       | 1.00     |
|  |                               |                             | PH16 OIL FILTER LBF P   |       | 1.00     |
| - Inspect And Service Aux, Fuel System.  |                               |                             | S30HACP STROBE BULB F   |       | 1.00     |
| - Replace Condensor Fan Motor.Evacuate And Recharge A/C System.                                      |                               |                             | NAPAGOLD FUEL FILTER    |       | 1.00     |
|  |                               |                             | SHIELD                  |       | 1.00     |
|  |                               |                             | BULB                    |       | 1.00     |
| - Replace Right Front Tire,Rotate And Balance All Four.  |                               |                             | 5W20 ENGINE OIL         |       | 7.00     |
| - Reglue Bed Rail Caps.  |                               |                             | A/C FAN MOTOR           |       | 1.00     |
| - Shop Supplies  |                               |                             | FAN BLADE               |       | 1.00     |
|  |                               |                             | TIRE DISPOSAL FEE       |       | 2.00     |
|  |                               |                             | ENGINE SEAL 12OZ        |       | 1.00     |
|  |                               |                             | NEW ALTERNATOR          |       | 1.00     |
|  |                               |                             | 31-24 WIPER BLADES 2    |       | 2.00     |
|  |                               |                             | PEAK GLOBAL             |       | 1.00     |
|  |                               |                             | 179469492 LT245-70R17   |       | 2.00     |
|  | <b>Parts Charge:</b> 1,480.92 | <b>Labor Charge:</b> 930.00 |                         |       |          |

**Workorder:** 1311115

**Problem:** BRAKE LIGHT ON

| Meter Reading: 61543<br>In Date: 11/01/2013  | Close Date: 11/27/2013      | Labor<br>Hours              | Description           | Parts | Quantity |
|--|-----------------------------|-----------------------------|-----------------------|-------|----------|
| - C/S Brake Light On.Test Drive&Scan Found Code#C1009/C1008.Test&Found Bad Brake Fluid Level Sensor. R&R Master Cyl.W/Sensor. Clear Codes. |                             | <b>5.00</b>                 | SHOP SUPPLIES         |       | 1.00     |
|  |                             |                             | MASTER CYL            |       | 1.00     |
|  |                             |                             | 2232 BRAKE FLUID QUAR |       | 1.00     |
| - 40 Miles Test Drive After Repair.No Problem  |                             |                             |                       |       |          |
| - Shop Supplies  |                             |                             |                       |       |          |
|  | <b>Parts Charge:</b> 335.75 | <b>Labor Charge:</b> 300.00 |                       |       |          |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1404732

**Problem:** Pm service .Rear strobe light inop.

| Meter Reading: 64884<br>In Date: 05/14/2014  | Close Date: 05/30/2014        | Labor<br>Hours              | Description             | Parts | Quantity |
|--|-------------------------------|-----------------------------|-------------------------|-------|----------|
| - P.M. Service.  |                               | <b>13.25</b>                | TIRE DISPOSAL FEE       |       | 2.00     |
| - Replace Two Tires,Rotate And Balance All Four.   |                               |                             | 5W20 ENGINE OIL         |       | 7.00     |
| - R&R Left Front Seat For Upholstery Repairs.Replace Hood Struts.  |                               |                             | 30055-40 40AMP CIRC B   |       | 1.00     |
| - Replace Both Rear Strobe Light Bulbs.  |                               |                             | SHOP SUPPLIES           |       | 1.00     |
| - Inspect And Service Aux. Fuel Tank.Replace Defective Filler Nozzle.Repair Wiring And Install New Circuit Breaker And Switch. |                               |                             | 179469492 LT245-70R17   |       | 2.00     |
| - Replace Both Sway Bar Links.Complete Wheel Alignment.Test Drive.   |                               |                             | SEAT R AND R            |       | 1.00     |
| - Shop Supplies  |                               |                             | NAPAGOLD OIL FILTER     |       | 1.00     |
|  |                               |                             | NOZZLE FARM             |       | 1.00     |
|  |                               |                             | USED FIRE X REFURBISHED |       | 1.00     |
|  |                               |                             | HOOD LIFT SUPPORT       |       | 2.00     |
|  |                               |                             | 31-24 WIPER BLADES 2    |       | 2.00     |
|  |                               |                             | LINK                    |       | 2.00     |
|  |                               |                             | TOGGLE SWITCH           |       | 1.00     |
|  |                               |                             | NAPAGOLD FUEL FILTER    |       | 1.00     |
|  |                               |                             | HIDE AWAY STROB         |       | 2.00     |
|  | <b>Parts Charge:</b> 1,145.65 | <b>Labor Charge:</b> 795.00 |                         |       |          |

**Workorder:** 1411171

**Problem:** PM, RT REAR BRAKE LIGHTOUT, STROBE LIGHT OUT , REPLACE 2 POWER OUTLETS

| Meter Reading: 70398<br>In Date: 11/06/2014                               | Close Date: 12/15/2014     | Labor<br>Hours              | Description         | Parts | Quantity |
|---|----------------------------|-----------------------------|---------------------|-------|----------|
| - Pm  |                            | <b>6.50</b>                 | LIGHTER             |       | 1.00     |
| - Ck Tail Light Turn Signal Replace FI Turn Bulb Rr Tail Light Bulb       |                            |                             | NAPA TRANS FILTER   |       | 1.00     |
| - Ck Strobe Inop Remove Dash Replace Toggle Switch                        |                            |                             | NAPA QUART 5W20     |       | 7.00     |
| - Svc Auxilary Fuel Tank Replace Filter                                   |                            |                             | NAPAGOLD OIL FILTER |       | 1.00     |
| - Ck Cig Light Broken Replace One Fuse Replace One Socket Reassemble Dash |                            |                             | BULB                |       | 1.00     |
| - Shop Supplies   |                            |                             | BULB                |       | 1.00     |
|   |                            |                             | TOGGLE SWITCH       |       | 1.00     |
|   |                            |                             | SHOP SUPPLIES       |       | 1.00     |
|   | <b>Parts Charge:</b> 66.93 | <b>Labor Charge:</b> 390.00 |                     |       |          |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1412486                      **Problem:** Wiper blades seperated.

| Meter Reading: 70582                               | Labor | Parts                | Quantity |
|--|-------|----------------------|----------|
| In Date: 12/15/2014                                | Hours | Description          | Quantity |
| - Inspect And Replace Both Defective Wiper Blades. | 0.30  | 31-24 WIPER BLADES 2 | 2.00     |
| <b>Parts Charge:</b>                               | 10.95 | <b>Labor Charge:</b> | 18.00    |

**Workorder:** 1502476                      **Problem:** Right brake light inop.

| Meter Reading: 71618             | Labor | Parts                | Quantity |
|----------------------------------|-------|----------------------|----------|
| In Date: 03/10/2015              | Hours | Description          | Quantity |
| - Replace Right Brake Lamp Bulb. | 0.50  | BULB                 | 1.00     |
| <b>Parts Charge:</b>             | 0.75  | <b>Labor Charge:</b> | 30.00    |

**Workorder:** 1504314                      **Problem:** Right brake lamp inop.

| Meter Reading: 72452                                    | Labor | Parts                | Quantity |
|---|-------|----------------------|----------|
| In Date: 04/28/2015                                     | Hours | Description          | Quantity |
| - Test And Replace Defective Right Rear Tail Lamp Bulbs | 0.50  | TAIL LIGHT SOCKET    | 1.00     |
| - And Socket Assembly.                                  |       | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies   |       | BULB                 | 3.00     |
| <b>Parts Charge:</b>                                    | 42.62 | <b>Labor Charge:</b> | 30.00    |

**Workorder:** 1508336                      **Problem:** pm, wont start towed in, brake light on and off

| Meter Reading: 75228                                 | Labor  | Parts                   | Quantity |
|--|--------|-------------------------|----------|
| In Date: 08/19/2015                                  | Hours  | Description             | Quantity |
| - Pm   | 10.75  | SHOP SUPPLIES           | 1.00     |
| - Svc Aux Fuel Tank                                  |        | NAPAGOLD OIL FILTER     | 1.00     |
| - Ck Wont Start Perform Pinpoint Test Found Bad Fuel |        | NAPA QUART 5W20         | 7.00     |
| - Pump Remove Aux Tank And Replace Fuel Pump And     |        | USED FIRE X REFURBISHED | 1.00     |
| - Clear All Codes                                    |        | 31-24 WIPER BLADES 2    | 2.00     |
| - Repair Tag Lights                                  |        | NAPAGOLD AIR FILTER     | 1.00     |
| - Test Drive After Repair                            |        | NAPA TRANS FILTER       | 1.00     |
| - Repair Tool Box Lock                               |        | ELECTRIC FUEL PUMP      | 1.00     |
| - Shop Supplies                                      |        | BULB                    | 2.00     |
| <b>Parts Charge:</b>                                 | 269.79 | <b>Labor Charge:</b>    | 645.00   |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1508365                      **Problem:** wont start

**Meter Reading:** 75004                      **Labor**

**In Date:** 08/19/2015                      **Hours**                      **Parts**

---

|  | Close Date: |                      |      |                                  |
|--|-------------|----------------------|------|----------------------------------|
| - Tow From: 17715 Tiffany Trace Drive Boca To: Sr Shop | 08/20/2015  |                      |      |                                  |
| <b>Parts Charge:</b>                                   | 0.00        | <b>Labor Charge:</b> | 0.00 | <b>Commercial Charge:</b> 104.15 |

**Workorder:** 1509779                      **Problem:** needs 2 toolbox keys

**Meter Reading:** 76237                      **Labor**

**In Date:** 09/28/2015                      **Hours**                      **Parts**

---

|                        | Close Date: |                      |       |      |
|------------------------|-------------|----------------------|-------|------|
| - Secure Keys For Dept | 10/15/2015  |                      | 0.50  | 1.00 |
| - Shop Supplies        |             |                      | 30.00 | 2.00 |
| <b>Parts Charge:</b>   | 38.54       | <b>Labor Charge:</b> | 30.00 |      |

**Workorder:** 1509823                      **Problem:** flat tire

**Meter Reading:** 76457                      **Labor**

**In Date:** 09/29/2015                      **Hours**                      **Parts**

---

|                           | Close Date: |                      |       |      |
|---------------------------|-------------|----------------------|-------|------|
| - Repair Right Front Tire | 09/30/2015  |                      | 1.00  | 1.00 |
| - Shop Supplies           |             |                      |       |      |
| <b>Parts Charge:</b>      | 2.00        | <b>Labor Charge:</b> | 60.00 |      |

**Workorder:** 1509863                      **Problem:** flat itre rf

**Meter Reading:** 76237                      **Labor**

**In Date:** 09/28/2015                      **Hours**                      **Parts**

---

|  | Close Date: |                      |      |                                  |
|--|-------------|----------------------|------|----------------------------------|
| - Tow From: Sw 18 Ave Boca Raton To: Sr Shop | 09/29/2015  |                      |      |                                  |
| <b>Parts Charge:</b>                         | 0.00        | <b>Labor Charge:</b> | 0.00 | <b>Commercial Charge:</b> 104.15 |

**Workorder:** 1510731                      **Problem:** turn signal lamp l front out

**Meter Reading:** 77248                      **Labor**

**In Date:** 10/23/2015                      **Hours**                      **Parts**

---

|                                 | Close Date: |                      |       |      |
|---------------------------------|-------------|----------------------|-------|------|
| - Repair Left Front Turn Signal | 10/29/2015  |                      | 1.00  | 1.00 |
| - Shop Supplies                 |             |                      |       | 1.00 |
| <b>Parts Charge:</b>            | 3.69        | <b>Labor Charge:</b> | 60.00 | 1.00 |



1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1511636

**Problem:** Righr rear strobe light inop.

| Meter Reading: 77974   | Labor                       | Parts  |
|--|-----------------------------|--|
| In Date: 11/13/2015  | Hours                       | Description  |
| Close Date: 11/24/2015   |                             | Quantity   |
| - Test And Replace Right Rear Strobe Lamp Bulb.Retest.   | 10.00                       | SHOP SUPPLIES 1.00   |
| - Replace Both Front Brake Rotors And Loaded Calipers.Flush And Bleed Brake System.Test Drive.   |                             | HIDE AWAY STROB 1.00<br>REMAN BRAKE CALIPER 1.00   |
| - Test Drive For Noise And Abs Light On.Scan For Codes.C101C Replace Defective Right Front Wheel Bearing Assembly.Clear Code And Retest. |                             | REMAN BRAKE CALIPER 1.00<br>BRAKE ROTOR ONLY 2.00<br>BRAKE CLEANER 1.00                                |
| - Computer Diagnose For Air Bag Light On.Code B1206 Replace Defective Passenger Air Bag Deactivation Switch.Clear Codes And Retest.      |                             | B FLUID DOT 3-32OZ 1.00<br>R /F WHEEL BEARIN 1.00<br>AIR BAG SWITCH 1.00<br>CLR RTV SILCN SEALANT 1.00 |
| - Shop Supplies  |                             |  |
| <b>Parts Charge:</b> 846.53  | <b>Labor Charge:</b> 600.00 |  |

**Workorder:** 1601144

**Problem:** Nail in right rear tire.

| Meter Reading: 79062                  | Labor                      | Parts              |
|---------------------------------------|----------------------------|--------------------|
| In Date: 02/02/2016                   | Hours                      | Description        |
| Close Date: 02/04/2016                |                            | Quantity           |
| - Repair And Balance Right Rear Tire. | 1.00                       | SHOP SUPPLIES 1.00 |
| - Shop Supplies                       |                            |                    |
| <b>Parts Charge:</b> 2.00             | <b>Labor Charge:</b> 60.00 |                    |

**Workorder:** 1602309

**Problem:** FRONT STROBE LIGHT INOP.

| Meter Reading: 79554             | Labor                       | Parts                |
|----------------------------------|-----------------------------|----------------------|
| In Date: 03/04/2016              | Hours                       | Description          |
| Close Date: 03/08/2016           |                             | Quantity             |
| - Repair Both Front Strobe Light | 1.75                        | HIDE AWAY STROB 2.00 |
| - Shop Supplies                  |                             | SHOP SUPPLIES 1.00   |
| <b>Parts Charge:</b> 106.70      | <b>Labor Charge:</b> 105.00 |                      |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1603222                      **Problem:** pm, fix support on l side of tool bin so it will stay open more safely

| Meter Reading: 80141                        | Labor    | Parts                 |          |  |
|---|----------|-----------------------|----------|--|
| In Date: 03/28/2016                         | Hours    | Description           | Quantity |  |
| - Pm Service.                               | 7.25     | NAPAGOLD OIL FILTER   | 1.00     |  |
| - Repair Right Front Park Light.            |          | NAPA QUART 5W20       | 7.00     |  |
| - Replace Four Tires.                       |          | WASHER FLUID CONCENTR | 1.00     |  |
| - Replace Both Tool Box Lid Support Struts. |          | BULB                  | 1.00     |  |
| - Fill All Tires With Nitrogen.             |          | P245/70R17 MIC TIRE   | 4.00     |  |
| - Shop Supplies                             |          | SHOP SUPPLIES         | 1.00     |  |
|   |          | BULB                  | 1.00     |  |
|   |          | TIRE DISPOSAL FEE     | 4.00     |  |
|   |          | SUPPORT               | 2.00     |  |
|   |          | TIRE LT 245/70/17     | 4.00     |  |
| <b>Parts Charge:</b>                        | 1,103.48 | <b>Labor Charge:</b>  | 435.00   |  |

**Workorder:** 1604102                      **Problem:** ACCIDENT

| Meter Reading: 80141  | Labor | Parts                |          |                                 |
|---|-------|----------------------|----------|---------------------------------|
| In Date: 04/19/2016   | Hours | Description          | Quantity |                                 |
| - Tow From: 506 Ne 3Rd Street , Boynton Beach To: Accident Line |       |                      |          |                                 |
| <b>Parts Charge:</b>  | 0.00  | <b>Labor Charge:</b> | 0.00     | <b>Commercial Charge:</b> 96.00 |

**Workorder:** 1604104                      **Problem:** Payout charge to Sisters Towing

| Meter Reading: 80141                     | Labor | Parts                |          |                                  |
|--|-------|----------------------|----------|----------------------------------|
| In Date: 04/19/2016                      | Hours | Description          | Quantity |                                  |
| - Tow From: Big City Towing To: Accident |       |                      |          |                                  |
| <b>Parts Charge:</b>                     | 0.00  | <b>Labor Charge:</b> | 0.00     | <b>Commercial Charge:</b> 272.40 |

**Workorder:** 1605880                      **Problem:** Damage to right front fender, head lights, front bumper, hood, grille & possible steering

| Meter Reading: 80492  | Labor | Parts                |          |                                    |
|---|-------|----------------------|----------|------------------------------------|
| In Date: 04/20/2016   | Hours | Description          | Quantity |                                    |
| - Damage To Right Front Fender, Head Lights, Front Bumper, Hood, Grille & Possible Steering |       |                      |          |                                    |
| <b>Parts Charge:</b>  | 0.00  | <b>Labor Charge:</b> | 0.00     | <b>Commercial Charge:</b> 3,896.40 |

1/30/2017  
3:55:01PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164768 2006 DODGE 2500 Pickup, 3/4 Ton, W/Toolbox

**Workorder:** 1606779

**Problem:** Had to be jump started inA.M. and recall R25.

| <b>Meter Reading:</b> 81853 |   | <b>Labor</b> |                       | <b>Parts</b>    |       |
|-----------------------------|---|--------------|-----------------------|-----------------|-------|
| <b>In Date:</b> 07/05/2016  | <b>Close Date:</b> 07/19/2016                             | <b>Hours</b> | <b>Description</b>    | <b>Quantity</b> |       |
| -                           | Test Battery And Charging System.Replace Bad Battery.     | <b>9.00</b>  | SHOP SUPPLIES         |                 | 1.00  |
| -                           | Replace All Spark Plugs,Hard Start Runs Rough.            |              | INJECTOR CLEANER      |                 | 1.00  |
| -                           | Service And Clean Throttle And Induction.Flush Injectors. |              | CHAMP COPPER SPARK PL |                 | 16.00 |
| -                           | Transport Vehicle To Dealer For Recall #R25.              |              | INTAKE CLEANER KIT    |                 | 1.00  |
| -                           | Shop Supplies   |              | MAC BATTERY PROTECT   |                 | 1.00  |
|                             |   |              | BATTERY               |                 | 1.00  |
| <b>Parts Charge:</b>        |   | 213.15       | <b>Labor Charge:</b>  | 540.00          |       |

**Workorder:** 1610966

**Problem:** died on way to SE shop turns over wont start. gas leaking

| <b>Meter Reading:</b> 83626 |   | <b>Labor</b> |                      | <b>Parts</b>    |                                 |
|-----------------------------|---|--------------|----------------------|-----------------|---------------------------------|
| <b>In Date:</b> 10/21/2016  | <b>Close Date:</b> 10/24/2016                   | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |                                 |
| -                           | Tow From: Vista Fuel Island To: Se Shop Turn In |              |                      |                 |                                 |
| <b>Parts Charge:</b>        |   | 0.00         | <b>Labor Charge:</b> | 0.00            | <b>Commercial Charge:</b> 96.00 |

**Workorder:** 1611144

**Problem:** repair fuel leak

| <b>Meter Reading:</b> 83626 |                               | <b>Labor</b> |                      | <b>Parts</b>    |      |
|-----------------------------|-------------------------------|--------------|----------------------|-----------------|------|
| <b>In Date:</b> 10/27/2016  | <b>Close Date:</b> 10/28/2016 | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |      |
| -                           | Repair Fuel Line To Fuel Pump | <b>2.00</b>  | SHOP SUPPLIES        |                 | 1.00 |
| -                           | Shop Supplies                 |              |                      |                 |      |
| <b>Parts Charge:</b>        |                               | 2.00         | <b>Labor Charge:</b> | 120.00          |      |

**Workorder:** 1611145

**Problem:** Transition Prep Charge

| <b>Meter Reading:</b> 83626 |                               | <b>Labor</b> |                      | <b>Parts</b>    |  |
|-----------------------------|-------------------------------|--------------|----------------------|-----------------|--|
| <b>In Date:</b> 10/27/2016  | <b>Close Date:</b> 10/27/2016 | <b>Hours</b> | <b>Description</b>   | <b>Quantity</b> |  |
| -                           | Transition Prep Charge        | <b>2.00</b>  |                      |                 |  |
| <b>Parts Charge:</b>        |                               | 0.00         | <b>Labor Charge:</b> | 0.00            |  |

|                      |                 |                      |                  |                      |                 |
|----------------------|-----------------|----------------------|------------------|----------------------|-----------------|
| Total Parts Charges: | <b>9,605.84</b> | Total Labor Charges: | <b>11,355.00</b> | Total Comm. Charges: | <b>6,838.17</b> |
|----------------------|-----------------|----------------------|------------------|----------------------|-----------------|