

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10194191 2013 TORO 4000D Mower, 11 Ft., 58 Hp, Canopy**

**Workorder:** 1312444      **Meter:** 1      **In Date:** 12/13/2013      **Closed:** 12/13/2013  
**Problem:** 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00

:

**Workorder:** 1407572      **Meter:** 250      **In Date:** 08/01/2014      **Closed:** 08/19/2014  
**Problem:** pen on right deck come out throttle cable loose(REQUEST ASAP BY MR.DARYL 08/06/14)

- rr damaged linkage components on deck tighten throttle control grase test mow  
- Shop Supplies

**Parts List**

**Qty**

Bushing	2.00
Snap Ring	1.00
Washer	2.00
Damper	1.00
Rh Bell Crank Asm	1.00
Rod End	2.00
Tube-link	1.00
Rod End-spherical	2.00
Nut	2.00
Shop Supplies	1.00
Freight Charge	1.00

Hours 5.00      Labor: 300.00      Parts: 683.56      Total: 983.56

:

**Workorder:** 1412277      **Meter:** 423      **In Date:** 12/08/2014      **Closed:** 01/15/2015  
**Problem:** pm, right tire need brakes

- pm  
- inspect hyd sys and change filters  
- replace right rear tire  
- fab and repair damage screen on back of hood for radiator  
- clean debris froimt clogged rad remove deck belt covers clean debris from decks and battery casse  
- ck park brake not holding ck and replace missing pin for brake lever  
- Shop Supplies

**Parts List**

**Qty**

15w40 Bulk South Reg	10.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Napagold Fuel Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
Hydraulic Filter	1.00
Napa Hydraulic Filtr	1.00
Aw68 Bulk Sr	5.00
20x10.00x10 Multi-trac	1.00
Aluminum Rivet	1.00
Aluminum Rivet	1.00
1/4" Flat Washer	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 12.50      Labor: 750.00      Parts: 329.05      Total: 1,079.05

:

**Palm Beach County Fleet Management  
Asset Maintenance History**

<b>Workorder:</b> 1504576	<b>Meter:</b> 474	<b>In Date:</b> 05/05/2015	<b>Closed:</b> 05/07/2015
<b>Problem:</b> night rear tire slow leak			
- ck right rear tire verify side wall damage replace rr tire	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	20x10.00x10 Multi-trac		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 135.18	Total: 195.18
:			
<b>Workorder:</b> 1507639	<b>Meter:</b> 589	<b>In Date:</b> 07/31/2015	<b>Closed:</b> 08/06/2015
<b>Problem:</b> replace bracket			
- ck replace bracket verify bolt worn replace bolt to reverse bracket test mow	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
<b>Workorder:</b> 1509654	<b>Meter:</b> 656	<b>In Date:</b> 09/24/2015	<b>Closed:</b> 09/30/2015
<b>Problem:</b> left wing making noise, ck all belts			
- ck wing makes noise remove left deck replace tensioner and pulley inspect and lubricate all deck test mow	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	Idler Arm Assembly		1.00
	Extension Spring		1.00
	Capscrew		1.00
	Idler Pulley		1.00
	Shop Supplies		1.00
Hours 4.00	Labor: 240.00	Parts: 189.82	Total: 429.82
:			
<b>Workorder:</b> 1510820	<b>Meter:</b> 674	<b>In Date:</b> 10/26/2015	<b>Closed:</b> 11/10/2015
<b>Problem:</b> TIRE BACK REAR			
- ck back tire replace 1 rear tire mount add n2	<b>Parts List</b>		<b>Qty</b>
- Shop Supplies	20x10.00x10 Multi-trac		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 135.18	Total: 195.18
:			
<b>Workorder:</b> 1513026	<b>Meter:</b> 716	<b>In Date:</b> 12/29/2015	<b>Closed:</b> 01/22/2016
<b>Problem:</b> pm, leaking from water hose			
- pm	<b>Parts List</b>		<b>Qty</b>
- ck leaking hose replace lower rad hose flush coolant refill	Napagold Air Filter		1.00
- svc hyd sys	Napagold Air Filter		1.00
- wash eq	Napagold Fuel Filter		1.00
- Shop Supplies	Napagold Fuel Filter		1.00
	Napagold Oil Filter		1.00
	15w40 Bulk South Reg		10.00
	Rad Hose		1.00
	1gal Rtu Antifreeze		1.00
	Shop Supplies		1.00
Hours 8.00	Labor: 480.00	Parts: 140.53	Total: 620.53
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1601423      **Meter:** 726      **In Date:** 02/10/2016      **Closed:** 02/17/2016

**Problem:** FLAT TIRE

- ck flat tire verify tire damaged beypond repair replace tire add n2	<b>Parts List</b>	<b>Qty</b>
	20x10.00x10 Multi Trac	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 157.45
:		Total: 217.45

**Workorder:** 1604520      **Meter:** 773      **In Date:** 04/28/2016      **Closed:** 04/29/2016

**Problem:** One tire.

- C/c flat tire.verify unable to repair tire.replace tire and add N2	<b>Parts List</b>	<b>Qty</b>
	20x10.00x10 Multi Trac	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 167.35
:		Total: 227.35

**Workorder:** 1610799      **Meter:** 1015      **In Date:** 10/19/2016      **Closed:** 10/28/2016

**Problem:** NEEDS L/FRONT WING TIRE

- C/c Caster Wheels. Replace Two Tire/wheel Assy. On L/wing.	<b>Parts List</b>	<b>Qty</b>
	Castor Wheel 8"	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 1.50	Labor: 90.00	Parts: 260.16
:		Total: 350.16

**Workorder:** 1700207      **Meter:** 1029      **In Date:** 01/06/2017      **Closed:** 01/24/2017

**Problem:** pm/ wont start after sits for long period

- Pm	<b>Parts List</b>	<b>Qty</b>
- Hyd Service	Napagold Air Filter	1.00
- Ck for no start-battery-ng- Replace battery and ck charging sys	Napagold Air Filter	1.00
	Napagold Fuel Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Napagold Oil Filter	1.00
	15-40 Oil	10.00
	Hydraulic Filter	1.00
	Napa Hydraulic Filtr	1.00
	Aw68 Hydro Fluid Hydr	4.00
	Battery	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 253.37
:		Total: 613.37

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

<b>Workorder:</b> 1702084	<b>Meter:</b> 1046	<b>In Date:</b> 02/28/2017	<b>Closed:</b> 04/28/2017
<b>Problem:</b> CHECK FRONT TIRES,SIDE WINGS AND FRONT DECK WONT COME DOWN,WONT SHIFT TO HIGH GEAR.			
- C/c wing wont go up or down.no Pto.found faulty control module.tec-5001 dealer prograded module.	<b>Parts List</b>		<b>Qty</b>
	Switch		1.00
- C/c tires.replace 2 tires.mount.add N2	Tire 26x12-12		2.00
- Shop Supplies	Controller Tec5001		1.00
	Shop Supplies		1.00
	Freight Charge		1.00
Hours 8.00	Labor: 480.00	Parts: 1,622.76	Total: 2,102.76
:			

---

<b>Workorder:</b> 1706042	<b>Meter:</b> 1104	<b>In Date:</b> 06/19/2017	<b>Closed:</b> 07/12/2017
<b>Problem:</b> Replace front tires			
- C/c front tires.replace five tires and wheel assembly.lube all.correct N2	<b>Parts List</b>		<b>Qty</b>
	Castor Fork		1.00
- Replace front left caster fork and bolt.	Castor Wheel 8"		5.00
- Shop Supplies	Screw		1.00
	Locknut		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		5.00
Hours 4.00	Labor: 240.00	Parts: 831.20	Total: 1,071.20
:			

---

<b>Workorder:</b> 1800295	<b>Meter:</b> 1311	<b>In Date:</b> 01/09/2018	<b>Closed:</b> 02/06/2018
<b>Problem:</b> pm/ belts/ cover/ pins/ see notes			
- Pm	<b>Parts List</b>		<b>Qty</b>
- Hyd Service	Hydraulic Filter		1.00
- R/r Bearings in 2 caster wheels	Napa Hydraulic Filtr		1.00
- R/r all deck belts	Aw68 Hydro Fluid Hydr		20.00
- R/r deck idlerpulley, spidges 2 covers and all the swivel latches	Bearing		4.00
	Napa Qt 15w40		9.00
- Shop Supplies	Napagold Air Filter		1.00
	Napagold Air Filter		1.00
	Napagold Fuel Filter		1.00
	Napagold Fuel Filter		1.00
	Napagold Oil Filter		1.00
	15-40 Oil		10.00
	Bearing		4.00
	Deck Belt		4.00
	Pulley		4.00
	Spider Gear		3.00
	Swell Latch		24.00
	Lh Side Plate Cover		1.00
	Plate Cover R/h Side		1.00
	Shop Supplies		1.00
	Freight Charge		1.00
Hours 9.50	Labor: 570.00	Parts: 1,535.21	Total: 2,105.21
:			

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1802259      **Meter:** 1336      **In Date:** 02/28/2018      **Closed:** 03/19/2018

**Problem:** Hydraulic leak.Replace left side scalping wheel.

- C/c leaking hose.replace o-ring on hyd.block.correct fluid level.test run.	<b>Parts List</b>	<b>Qty</b>
	Aw68 Bulk Sr	5.00
- C/c scalp wheels.replace 6 anti-scalp wheels.	Tire 8,,	5.00
- Shop Supplies	Tube W/ Valve	5.00
	Castor Wheel 8"	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 5.00	Labor: 300.00	Parts: 551.34
:		Total: 851.34

**Workorder:** 1805272      **Meter:** 1350      **In Date:** 05/23/2018      **Closed:** 05/31/2018

**Problem:** Check seat inop,Check brakes,gas pedal all tires.See notes.

- Replace two tires.mount and add N2	<b>Parts List</b>	<b>Qty</b>
- C/c seat inop.found blown fuse for seat function.clean all connections.install new fuse test multiple times.	20x10.00x10 Multi Trac	2.00
	Ucb-10 Cir Brkr	1.00
- C/c traction pedal and brake pedal.test brakes on incline.. working properly.traction pedal working every start.unable to verify complaint at this time.	Atc-15 Fuse Pac	5.00
	Shop Supplies	1.00
- Shop Supplies	Tire Disposal Fee	2.00
Hours 4.25	Labor: 255.00	Parts: 285.02
:		Total: 540.02

**Workorder:** 1806801      **Meter:** 1417      **In Date:** 07/02/2018      **Closed:** 07/12/2018

**Problem:** Height adjusting pins broken.

- C/c height adjust pins.order pins for wheel adjustment on deck wheels.	<b>Parts List</b>	<b>Qty</b>
	Pin	4.00
- Shop Supplies	Clevis	4.00
	Shop Supplies	1.00
Hours 0.50	Labor: 30.00	Parts: 102.92
:		Total: 132.92

**Workorder:** 1808703      **Meter:** 1542      **In Date:** 08/23/2018      **Closed:** 09/28/2018

**Problem:** Accelerator cable broken.Flat tire.Check all tires.Adjust parking brake.

- C/c trottle cable.replace trottle cable.	<b>Parts List</b>	<b>Qty</b>
- C/c check deck wheels.replace two deck wheel assembly.break down multiple to replace tubes and tires.	Control Throttle	1.00
	Castor Wheel	1.00
- Verify wrong oil filter installed on equipment.replace oil filtre and change engine oil.	15w40 Bulk South Reg	6.00
	Napagold Oil Filter	1.00
- C/c Park brake.adjust parking brake.verify working properly and holding on incline.	Shop Supplies	1.00
- Wash equipment.		
- Shop Supplies		
Hours 7.75	Labor: 465.00	Parts: 230.95
:		Total: 695.95

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 1811432      **Meter:** 1594      **In Date:** 11/06/2018      **Closed:** 01/14/2019

**Problem:** lft frt deck whl, decks scapl shock when turn, check shocks loose, deck wheels,seat leaks, rad bot,

	<b>Parts List</b>	<b>Qty</b>
- replace bearings in lf deck wheel. check others		
- replace damper shocks on wings and broken bolt on mount	Bearing	2.00
- check and replace air control valve on seat	Spacer	1.00
- Shop Supplies	Rod End-spherical	4.00
	Damper	2.00
	Air Seat Switch Assy	1.00
	Shop Supplies	1.00
	Freight Charge	1.00

Hours 4.00

Labor: 268.00

Parts: 974.56

Total: 1,242.56

:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1904747      **Meter:** 1724      **In Date:** 05/01/2019      **Closed:** 05/30/2019  
**Problem:** pm/ see list

	<b>Parts List</b>	<b>Qty</b>
- pm service	Napagold Air Filter	1.00
- hydraulic service	Napagold Air Filter	1.00
- r/r 2 cater wheel assy.and r/r bearings in 2 cater wheels	Napagold Fuel Filter	1.00
- repair damage to left deck	Napagold Fuel Filter	1.00
- r/r radiator cap, lower hose and service cooling system	Napagold Oil Filter	1.00
- repair and reattach roof	15-40 Oil	10.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Napa Hydraulic Filtr	1.00
	Hydraulic Filter	1.00
	Aw68 Hydro Fluid Hydr	20.00
	Bearing	4.00
	Screw	2.00
	Spacer	2.00
	Caster Wheel	2.00
	Motor Cover L/h Deck	1.00
	Roller	1.00
	Comp Spring	1.00
	Plastic Bearing	2.00
	Flat Washer	1.00
	Rod End-spherical	1.00
	Damper	1.00
	1gal Rtu Antifreeze	7.00
	Cap	1.00
	Rad Hose	1.00
	Nut	2.00
	Swell Latch	2.00
	Bushing	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
	Freight Charge	1.00

Hours 17.50      Labor: 1,172.5      Parts: 1,488.91      Total: 2,661.41  
 :

**Workorder:** 1906760      **Meter:** 1779      **In Date:** 06/27/2019      **Closed:** 06/27/2019  
**Problem:** collant leak

	<b>Parts List</b>	<b>Qty</b>
- Check for leak - tightened hose clamp on lower hose	Shop Supplies	1.00
- Shop Supplies		

Hours 1.00      Labor: 67.00      Parts: 3.00      Total: 70.00  
 :

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1907708      **Meter:** 1853      **In Date:** 07/25/2019      **Closed:** 08/19/2019  
**Problem:** STRUT ON R/SIDE FALLS OFF,R/SIDE WING SCALPING

<ul style="list-style-type: none"> <li>- C/c strut and cover.replace missing shock absorber and outer pulley cover.re-route hyd.hoses.</li> <li>- Replace three caster wheels with solids.</li> <li>- Replace coolant tank reservoir.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Rod End-spherical</li> <li>Damper</li> <li>Motor Cover L/h Deck</li> <li>Caster Wheel</li> <li>Coolant Overflow Tank</li> <li>Shop Supplies</li> <li>Freight Charge</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 5.50 :	Labor: 368.50	Parts: 985.51	Total: 1,354.01

**Workorder:** 2006539      **Meter:** 2100      **In Date:** 07/01/2020      **Closed:** 08/17/2020  
**Problem:** PM Service.

<ul style="list-style-type: none"> <li>- Pm Service.</li> <li>- Service Hyd system .r/r filters.</li> <li>- Replace battery.</li> <li>- Replace two rear tires and five solid tires.</li> <li>- Replace L/h deck belt ,spindle assm.and idler arm w/pulley.</li> <li>- Wash equipment.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Air Filter</li> <li>Napagold Air Filter</li> <li>Napagold Fuel Filter</li> <li>Napagold Fuel Filter</li> <li>15w40 Bulk South Reg</li> <li>Napagold Oil Filter</li> <li>Aw68 Bulk Sr</li> <li>Hydraulic Filter</li> <li>Napa Hydraulic Filtr</li> <li>Battery</li> <li>20x10.00x10 Multi-trac</li> <li>Caster Wheel</li> <li>Deck Belt</li> <li>Pulley</li> <li>Idler Arm Assembly</li> <li>Low Driven Spindle Asm</li> <li>Shop Supplies</li> <li>Tire Disposal Fee</li> <li>Freight Charge</li> <li>Freight Charge</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>10.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>5.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> </ul>	
Hours 13.75 :	Labor: 1,003.7 5	Parts: 2,434.86	Total: 3,438.61

**Palm Beach County Fleet Management  
Asset Maintenance History**

---

**Workorder:** 2007885      **Meter:** 2111      **In Date:** 08/11/2020      **Closed:** 09/28/2020  
**Problem:** Fuel tank leaking.Hard to start.

<ul style="list-style-type: none"> <li>- C/c Leaking fuel.verify leaking exhaust at manifold melted hole in tank,unable to repair. Replace fuel tank.</li> <li>- Remove muffler,turbo,exhaust manifold etc..to replace blown manifold gaskets. Reassemble and test run.</li> <li>- Lh deck control arm fell apart.replace broken housing and multiple internal components.</li> <li>- Wash equipment of fuel,grass,soot and debris.</li> <li>- Verify leaking fuel tank contaminate engine oil.drain oil refill and relpace oil filter.</li> <li>- Shop Supplies</li> </ul>	<p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Nut</li> <li>Stud</li> <li>Gasket</li> <li>Gasket</li> <li>Mufler Gasket</li> <li>Screw</li> <li>Bushing</li> <li>Flat Washer</li> <li>Plastic Bearing</li> <li>Comp Spring</li> <li>Shaft Spring</li> <li>Lh Rear Arm Asm</li> <li>15w40 Bulk South Reg</li> <li>Napagold Oil Filter</li> <li>Tank-fuel</li> <li>Stud</li> <li>Shop Supplies</li> <li>Freight Charge</li> <li>Freight Charge</li> </ul>	<p><b>Qty</b></p> <ul style="list-style-type: none"> <li>8.00</li> <li>6.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>4.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>9.00</li> <li>1.00</li> <li>1.00</li> <li>2.00</li> <li>1.00</li> <li>1.00</li> </ul>
Hours 13.25 :	Labor: 967.25      Parts: 1,842.09	Total: 2,809.34

---

**Workorder:** 2100668      **Meter:** 2166      **In Date:** 01/20/2021      **Closed:** 01/20/2021  
**Problem:** Transition Prep Charge

<ul style="list-style-type: none"> <li>- Transition Prep Charge</li> </ul>	Hours 2.00 :	Labor: 146.00      Parts: 0.00	Total: 146.00
--	-----------------	--------------------------------	---------------