

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 641329 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 06/22/2006	Hours	Description
Close Date: 06/22/2006	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 100.00	

Workorder: 641538 **Problem:** MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0	Labor	Parts
In Date: 06/27/2006	Hours	Description
Close Date: 06/27/2006	Quantity	
- Minor Weld Repair Or Machining.	1.00	
Parts Charge: 0.00	Labor Charge: 50.00	

Workorder: 642157 **Problem:** NEEDS STROBE LIGHTS ON ROOF

Meter Reading: 82	Labor	Parts
In Date: 07/11/2006	Hours	Description
Close Date: 07/14/2006	Quantity	
- Fabricate & Install 2 Strobe Lights On Roof.	6.50	30055-30 30AMP CIRCUIT BREAKER 1.00
- Remove Lock Washers & Spaces From Winch To Have		DS367 YELLOW PILOT LIGHT 1.00
Bulb Blown		SHOP SUPPLIES 1.00
- Shop Supplies		250ADH12A STROBE STROBE LIGHT 12/24VT 2.00
		DS-167 TOGGLE SWITCH (STANDARD) 1.00
		06133 3M ELECTRIC TAPE STOCK #832260101 1.00
Parts Charge: 343.86	Labor Charge: 25.00	

Workorder: 642313 **Problem:** FAB EQUIPMENT BOX

Meter Reading: 82	Labor	Parts
In Date: 07/13/2006	Hours	Description
Close Date: 07/24/2006	Quantity	
- Fab Eqpt Box	36.00	207 ALUMINUM PAINT 2.00
- Shop Supplies		4"SQ ALUM TUBE 1/4 WALL 3.00
		SHOP SUPPLIES 1.00
		3/16X4X10 DIA PLATE ALUMINUM NON BRIGHT 96.00
		326-3 STACKED DRAWER UNIT 1.00
		1/4"1X20 ALUM FLAT BAR 6063 GAUGE 14.00
Parts Charge: 2,766.24	Labor Charge: 1,200.00	

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 643367

Problem: MODIFY BOX

Meter Reading: 82	Labor	Parts	
In Date: 08/03/2006	Hours	Description	Quantity
- Modify Box.	11.50	1/4"1X20 ALUM FLAT BAR 6063 GAUGE	10.00
- Shop Supplies		SHOP SUPPLIES	1.00
		3/16X4X10 DIA PLATE ALUMINUM NON BRIGHT	12.00
		1/4X8X12 ALUM. FLAT BAR	8.00
Parts Charge:	133.22	Labor Charge:	450.00

Workorder: 646813

Problem: REPAIR R/S MIRROR.

Meter Reading: 2054	Labor	Parts	
In Date: 10/06/2006	Hours	Description	Quantity
- R&R Door Panel And Replace Right Side Mirror Assemble.	1.00	5C3Z17682EAA RIGHT SIDE MIRRIR	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		5C3Z17D742BAA MIRROR FRONT COVER	1.00
Parts Charge:	354.62	Labor Charge:	55.00

Workorder: 733162

Problem: SCREW IN R/R TIRE

Meter Reading: 5769	Labor	Parts	
In Date: 01/24/2007	Hours	Description	Quantity
- Repair R/R Tire And Nitro Fill	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	55.00

Workorder: 733363

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 5940	Labor	Parts	
In Date: 01/26/2007	Hours	Description	Quantity
- Pm Service	3.75	SHOP SUPPLIES	1.00
- Nitrogen Fill Tires.		5W20 ENGINE OIL	7.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	34.19	Labor Charge:	55.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 739796

Problem: P.M SERVICE

Meter Reading: 11732	Labor	Parts	
In Date: 06/07/2007	Hours	Description	Quantity
- Pm	10.75	31-20 WIPER BLADES 20" BLADE	2.00
- Fab And Install Hook Under Topper Rail To Acc Roof Mounted Objects		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Bal All Tires		FG1083 FUEL FILTER	1.00
- Rr Ft Caliper Assem To Remove Debris Inside Rotor Housing		G8018 FUEL FILTER LBF G6593 WIX 33595	-1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
		G8018 FUEL FILTER LBF G6593 WIX 33595	1.00
Parts Charge:	61.69	Labor Charge:	110.00

Workorder: 742848

Problem: L/S MIRROR BROKE.

Meter Reading: 15350	Labor	Parts	
In Date: 08/20/2007	Hours	Description	Quantity
- Replace L/S Mirror And Light Assembly.	1.00	5C3Z17683EAA L/SIDE MIRROR	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		5C3Z17D743BAA L/SIDE MIRROR LIGHT	1.00
Parts Charge:	370.51	Labor Charge:	55.00

Workorder: 745192

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 16914	Labor	Parts	
In Date: 10/04/2007	Hours	Description	Quantity
- Pm Service	4.25	CA9687 AIR FILTER LBF AF1754 WIX 46804	1.00
- Replace Left Rear Turn Signal & Brake Light Bulbs.		31-20 WIPER BLADES 20" BLADE	2.00
- Service Vehicle Winch.		4114K BULB (ACD)	2.00
- Shop Supplies		10020 INJECTOR CLEANER DON'T REORDER	1.00
		5W20 ENGINE OIL	7.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	72.87	Labor Charge:	60.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 835154

Problem: P.M SERVICE,CHECK ELECTRICAL SYSTEM

Meter Reading: 22130		Labor		Parts	
In Date: 03/06/2008	Close Date: 03/12/2008	Hours	Description		Quantity
- Pm Service		6.35	1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Test Electrical Sys For Slow Cranking.Test Starter & Alternator.Charge And Test Battery.R&R Defective Battery.			10003 INJECTOR CLEANER DON'T REORDER		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC		1.00
- Check Lights,Replaced 2 Damaged Signal Light Lenses And Covers On Side Mirrors.			5W20 ENGINE OIL		7.00
			CA9687 AIR FILTER LBF AF1754 WIX 46804		1.00
- Service Winche			SHOP SUPPLIES		1.00
- Rotate & High Speed Balance All 4 Tires.Nitrofill Tires.			MIRROR HOUSING		1.00
			MIRROR HOUSING		1.00
- Shop Supplies			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			GROUP 65 BATTERY (MTC BXT-65-850)		1.00
	Parts Charge: 423.01	Labor Charge: 60.00			

Workorder: 844122

Problem: P.M. SERVICE.

Meter Reading: 27470		Labor		Parts	
In Date: 09/11/2008	Close Date: 09/16/2008	Hours	Description		Quantity
- Pm Service		6.25	CA9687 AIR FILTER LBF AF1754 WIX 46804		1.00
- Service Trans. Flush & Refill.			5W20 ENGINE OIL		7.00
- Service Winch.Test Operation,Respool,& Inspect Cable & Lube.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		16.00
- Rotate & High Speed Balance All 4 Tires.Nitro Fill Tires.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
	Parts Charge: 124.07	Labor Charge: 60.00			

Workorder: 845393

Problem: CHECK BATTERY

Meter Reading: 28442		Labor		Parts	
In Date: 10/08/2008	Close Date: 10/09/2008	Hours	Description		Quantity
- Test Starting & Charging Sys.Test And Replace Battery.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies			WARRANTY BATTERY		1.00
	Parts Charge: 2.00	Labor Charge: 60.00			

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 935032

Problem: P.M SERVICE

Meter Reading: 32638	Labor	Parts	
In Date: 03/12/2009	Hours	Description	Quantity
- Pm Service	11.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Mount And Hi Speed Balance 4 New Tires Nitro Fill To Specs		5W20 ENGINE OIL	7.00
		75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)	4.00
- Rearend Leaking At Pinion Seal.R&R Pinion Seal And Service Rear Differential.Drain And Refill Rear End W/New Fluid.		748535189 265/70R17 WRG SLT ARMOUR E	4.00
		C8AZ19B546A ADDITIVE DIFFERENTIAL (MC XL-3)	1.00
- Service Winch, Test,Inspect And Lubricate.		REAR PINION SEAL	1.00
- Complete Front End Alignment Test Drive.		TIRE DISPOSAL FEE	4.00
- Shop Supplies		TR416 VALVE STEM	4.00
		SHOP SUPPLIES	1.00
		CA9687 AIR FILTER LBF AF1754 WIX 46804	1.00
Parts Charge:	933.75	Labor Charge:	675.00

Workorder: 940730

Problem: check lights

Meter Reading: 33604	Labor	Parts	
In Date: 07/15/2009	Hours	Description	Quantity
- Check All Lights, Replace R/R Tail Lamp Bulb.	0.50	4114K BULB (ACD)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	4.85	Labor Charge:	30.00

Workorder: 942048

Problem: A/C inspection

Meter Reading: 34290	Labor	Parts	
In Date: 08/13/2009	Hours	Description	Quantity
- Test & Inspect A/C Vent Controls, Trace & Repair Vacuum Leak At Heater Control Valve.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 942852 **Problem:** 1 - Key(s) issued

Meter Reading: 34860	Labor	Parts	
In Date: 09/02/2009	Hours	Description	Quantity
- 1 - Key(S) Issued	0.20	DUPLICATE VEHICLE KEYS	1.00
Parts Charge: 3.00	Labor Charge: 12.00		

Workorder: 943404 **Problem:** P.M service.

Meter Reading: 35597	Labor	Parts	
In Date: 09/17/2009	Hours	Description	Quantity
- P.M Service.	4.75	31-20 WIPER BLADES 20" BLADE	2.00
- Rotate & Balance All Four Tires.		SHOP SUPPLIES	1.00
- Inspect & Service Winch.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
Parts Charge: 44.97	Labor Charge: 285.00		

Workorder: 944620 **Problem:** R/F tire flat.

Meter Reading: 36934	Labor	Parts	
In Date: 10/16/2009	Hours	Description	Quantity
- Replace Two Tires(Match Tires On Axle).Reinstall Spare On Rack.	1.50	179535492 LT265/70R17 WRANGLER SR-A E	2.00
		SHOP SUPPLIES	1.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
Parts Charge: 378.33	Labor Charge: 90.00		

Workorder: 945996 **Problem:** Dead battery

Meter Reading: 38618	Labor	Parts	
In Date: 11/16/2009	Hours	Description	Quantity
- Test Starting & Charging System, Test & Replace Battery.	1.00	GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 129.42	Labor Charge: 120.00		

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 946564

Problem: Dead battery

Meter Reading: 39007	Labor	Parts	
In Date: 12/02/2009	Hours	Description	Quantity
<hr/>			
- Test Starting & Charging System, Charge & Test Battery, Test & Trace System Draw To Light In Camper Left On.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1000888

Problem: P.M service.

Meter Reading: 40731	Labor	Parts	
In Date: 01/25/2010	Hours	Description	Quantity
<hr/>			
- P.M Service.	4.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Inspect & Service Winch.		5W20 ENGINE OIL	7.00
- Rotate & Balance All Four Tires.		CA9687 AIR FILTER LBF AF1754 WIX 46804	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	31.73	Labor Charge:	285.00

Workorder: 1005884

Problem: P.M service.

Meter Reading: 46065	Labor	Parts	
In Date: 06/04/2010	Hours	Description	Quantity
<hr/>			
- Perform Pm Service.	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Inspect And Service Power Winch.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
Parts Charge:	27.44	Labor Charge:	225.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1006288

Problem: Check ac blows warm air intermittently.

Meter Reading: 46391	Labor	Parts	
In Date: 06/14/2010	Hours	Description	Quantity
- Diagnose Ac Concern And Ac Performance Test.Remove Blower Motor And Resistor To Access And Clean Clogged Evaporator Fins And Housing.Replace Failed Fan Switch With New And Retest. - Fabricate And Replace Failed Rear Topper Door Struts And Brackets With New. Drill And Install New Ball Mount Bracket. - Shop Supplies	5.50	A/C BLOWER SWITCH	1.00
		A/C BLOWER RESISTOR	1.00
		6984 EVAPOR CLEANER EVAPORATOR CLEANER	1.00
		SHOP SUPPLIES	1.00
		DOOR BALL MOUNT	1.00
		DOOR STRUTS	2.00
Parts Charge: 133.36	Labor Charge: 270.00		

Workorder: 1011783

Problem: Pm service

Meter Reading: 51633	Labor	Parts	
In Date: 10/21/2010	Hours	Description	Quantity
- Perform Pm Service. - Replace Failed Cracked Right Tail Lamp Assembly With New.Drill And Install Strobe Lamp Bulb. - Replace Failed Ac Vents Center And Right With New.Had To Remove Bezel. - Inspect And Service Winch. - Rotate And Balance All Four Tires. - Shop Supplies	6.75	SHOP SUPPLIES	1.00
		5W20 ENGINE OIL	7.00
		RIGHT REAR LIGHT ASSY	1.00
		RIGHT CENTER A/C VENT	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		CA9687 AIR FILTER LBF AF1754 WIX 46804	1.00
Parts Charge: 113.92	Labor Charge: 405.00		

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1104543

Problem: P.M. Service.Check Engine light.Trans. shifts hard.

Meter Reading: 53011	Labor	Parts	
In Date: 04/28/2011	Hours	Description	Quantity
- Perform Pm Service.	11.75	SHOP SUPPLIES	1.00
- Computer Diagnose For Check Engine Light On.Replace Three Failed Ignition Coils With New.Extract Two Broken Spark Plugs And Replace All Eight Spark Plugs With New.Clear Codes And Road Test.		D3TZ2457B BRAKE PEDAL PAD 5068 PENETRANT LUBE PENTRON (MANTEK) SPARK PLUGS L17025 INDUCTION CLEANER SOFT (USE BG KA8A)	1.00 1.00 8.00 1.00
- Perform Induction Service And Clean Trottle Body.Clear Codes With Scan Tool.		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC 31-20 WIPER BLADES 20" BLADE	1.00 2.00
- Rotate And Balance All Four Tires.		5W20 ENGINE OIL	7.00
- Inspect And Service Power Winch.		COILS	3.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	389.11	Labor Charge:	705.00

Workorder: 1111644

Problem: P.M. service.

Meter Reading: 53759	Labor	Parts	
In Date: 11/01/2011	Hours	Description	Quantity
- P.M. Service.	4.75	SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		5W20 ENGINE OIL	7.00
- Inspect And Service Winch.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		31-20 WIPER BLADES 20" BLADE G10166 FUEL FILTER MTC FG1083 WIX 33243	2.00 1.00
Parts Charge:	37.73	Labor Charge:	285.00

Workorder: 1205085

Problem: P.M. Service.

Meter Reading: 55489	Labor	Parts	
In Date: 05/31/2012	Hours	Description	Quantity
- P.M. Service.	4.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Inspect And Service Winch.		31-20 WIPER BLADES 20" BLADE	2.00
- Rotate And Balance All Tires.		CA9687 AIR FILTER LBF AF1754 WIX 46804	1.00
- Shop Supplies		5W20 ENGINE OIL SHOP SUPPLIES	7.00 1.00
Parts Charge:	36.64	Labor Charge:	285.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1205786 **Problem:** damage to rgt side of bed & rear bumper

Meter Reading: 55489	Labor	Parts	
In Date: 06/01/2012	Hours	Description	Quantity
- Damage To Rgt Side Of Bed & Rear Bumper			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 1,199.40	

Workorder: 1207113 **Problem:** Turnsignal lights inop intermittent.

Meter Reading: 55600	Labor	Parts	
In Date: 07/31/2012	Hours	Description	Quantity
- Test And Replace Failed Left Front Signal Lamp Bulb And Main Flasher Unit With New.	0.75	SHOP SUPPLIES	1.00
- Shop Supplies		3157 TAIL LIGHT BULBS	1.00
		FLASHER	1.00
Parts Charge: 25.94	Labor Charge: 45.00		

Workorder: 1211430 **Problem:** Pm service.

Meter Reading: 57071	Labor	Parts	
In Date: 11/28/2012	Hours	Description	Quantity
- P.M. Service.	10.75	FORD FUEL FILTER	1.00
- Test Battery And Charging System.Replace Bad Battery.		PH2 OIL FILTER LBF PH	1.00
- Inspect And Service Winch.Replace Frozen Winch Motor And Solenoid.Heat Shaft To Free Rust.Clean And Lube Gear Sets.		SHOP SUPPLIES	1.00
		BATTERY 65	1.00
		5W20 ENGINE OIL	7.00
- Trace And Repair Short In Cargo Lamp Circuit.Replace Blown Fuse.		31-20 WIPER BLADES 20	2.00
- Repair Right Front Tire.Rotate And Balance All Four.			
- Shop Supplies			
Parts Charge: 195.10	Labor Charge: 645.00		

Workorder: 1303783 **Problem:** Winch Out

Meter Reading: 57940	Labor	Parts	
In Date: 04/15/2013	Hours	Description	Quantity
- Tow From: Boca Pit			
Parts Charge: 0.00	Labor Charge: 0.00		

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1305607

Problem: Pm service.

Meter Reading: 58842		Labor		Parts	
In Date: 06/06/2013	Close Date: 06/24/2013	Hours	Description		Quantity
- P.M. Service.		4.75	FLOOR MAT-2PC RUB BK		1.00
- Rotate And Balance All Tires.			MAXFILM PENETRANT		1.00
- Inspect And Service Winch.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			5W20 ENGINE OIL		7.00
			31-20 WIPER BLADES 20		2.00
			SHOP SUPPLIES		1.00
Parts Charge: 74.49		Labor Charge: 285.00			

Workorder: 1310023

Problem: Left rear tire flat.

Meter Reading: 59994		Labor		Parts	
In Date: 10/03/2013	Close Date: 10/08/2013	Hours	Description		Quantity
- Repair And Balance Left Rear Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1400738

Problem: P.M. service.

Meter Reading: 61374		Labor		Parts	
In Date: 01/23/2014	Close Date: 02/18/2014	Hours	Description		Quantity
- P.M. Service.		10.55	5W20 ENGINE OIL		7.00
- Install New Fire Extinguisher With Bracket.			NAPAGOLD OIL FILTER		1.00
- Replace Right Head Light.			NAPAGOLD FUEL FILTER		1.00
- Replace Two Tires, Rotate And Balance All Four.			NAPAGOLD AIR FILTER		1.00
- Test Battery And Charging System. Replace Bad Battery.			WIPER BLADE		2.00
- Complete Wheel Alignment. Test Drive.			USED FIRE X REFURBISHED		1.00
- Inspect And Service Winch.			SHOP SUPPLIES		1.00
- Shop Supplies			CUSTOM BRACKET FIRE EX		1.00
			TIRE DISPOSAL FEE		2.00
			HALOGEN LAMP		1.00
			179535492 LT265-70R17		2.00
			ALTERNATOR		1.00
Parts Charge: 902.94		Labor Charge: 633.00			

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1410896

Problem: Pm service.Check AC and strobe lights.Difficult to fill up fuel and shift lever binding.

Meter Reading: 68791 In Date: 10/30/2014	Close Date: 01/06/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		25.75	TIRE DISPOSAL FEE		2.00
- Replace Both Defective Front Top Becon Strobe Lamps.			SHOP SUPPLIES		1.00
- Ac Performance And Leak Test.Evacuate			REMAN BRAKE CALIPER		1.00
System.Replace Defective Ac Compressor Manifold Hose			BRAKE CLEANER		1.00
Assembly,Acumulator And Orifice Expansion			NAPAGOLD OIL FILTER		1.00
Valve.Vacume And Recharge System To Specs.			REMAN BRAKE CALIPER		1.00
- Computer Diagnose Canister Evapt System For Slow			REMOTE STROBE HEAD		1.00
Fill.Test And Replace Defective Vent Solenoid Valve And			RAPID SEAL KIT		1.00
Retest Evapt System.Pass.			BATTERY 65		1.00
- Remove Steering Colum And Cover.Replace Worn Shifter			WIPER BLADE		2.00
Shaft Bushings.			179535492 LT265-70R17		2.00
- Replace Front And Rear Brake Pads And			STROBE LP LED		2.00
Calipers.Resurface All Four Brake Rotors.Bleed And			E8 A/C OIL UNIV W DYE		1.00
Flush Hydraulic System.Road Test.			ORIFICE TUBE		1.00
- Replace Two Tires.Rotate And Balance All Four.			REMAN BRAKE CALIPER		1.00
- Load Test Battey.Test Starting And Charging			USED FIRE X REFURBISHED		1.00
System.Replace Defective Battery.			ACCUMULATOR		1.00
- Remove Spare Tire Mount Assembly And Replace Key			LOCK KIT		1.00
Kit.			REMAN BRAKE CALIPER		1.00
- Shop Supplies			TUBE		1.00
			R134A LV SHOP 1		3.00
			real pad		1.00
			SOLENOID		1.00
			BRAKE PADS		1.00
			B FLUID DOT 3-32OZ		1.00
			5W20 ENGINE OIL		7.00
			F3TZ7L278A BUSHING SH		2.00
	Parts Charge: 1,919.93	Labor Charge: 1,545.00			

Workorder: 1507697

Problem: Front Left flat

Meter Reading: 73846 In Date: 07/27/2015	Close Date: 08/03/2015	Labor Hours	Description	Parts	Quantity
- Tire Service Okeechobee/E Rd, S Side Of Road - Front					
Left Flat					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 66.34		

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1507996

Problem: P.M. service and spare flat and strobes in rear inop and right mirror broken.

Meter Reading: 74298	Labor	Parts	
In Date: 08/10/2015	Hours	Description	Quantity
- Pm Service.	8.25	PTEX SUP WTHRSTRP ADH	1.00
- Replace Defective Left Headlamp And Both Rear Strobe Lights Also Replace Broken Becon Lamp.		USED FIRE X REFURBISHED	1.00
- Replace Broken Right Side Mirror Assembly.		5W20 ENGINE OIL	7.00
- Replace One Tire.Rotate And Balance All Four.		HALOGEN LAMP	1.00
- Service Transfer Case.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		TIRE DISPOSAL FEE	1.00
		COVER MIRROR	1.00
		SYN-ATF TRANS FLUID S	2.00
		WIPER BLADE	2.00
		LAMP ASSY	1.00
		SOCKET ASSY	2.00
		SHOP SUPPLIES	1.00
		MIRROR ASSY	1.00
		179535492 LT265-70R17	1.00
		HIDE AWAY STROB	2.00
		TR416 VALVE STEM	1.00
		LED EXTERIOR DOUBLE BULB	1.00
			2.00
Parts Charge:	1,214.30	Labor Charge:	495.00

Workorder: 1508864

Problem: A/c blower inop.

Meter Reading: 74531	Labor	Parts	
In Date: 09/02/2015	Hours	Description	Quantity
- Test Blower Operation..Replace Defective Blower Motor And Blower Resistor.Re Test.	2.00	BLOWER MOTOR	1.00
- Shop Supplies		BLOWER RESISTOR	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	83.65	Labor Charge:	120.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1601150

Problem: Check engine light on.Pm service.

Meter Reading: 78930 In Date: 02/02/2016	Close Date: 02/08/2016	Labor Hours	Description	Parts	Quantity
- Pm Service.		14.00	NAPAGOLD OIL FILTER		1.00
- Computer Diagnose For Check Engine Light On.Code			5W20 ENGINE OIL		7.00
- P0420.Pinpoint Test And Replace Defective Catalytic Converter Assembly.Clear Codes And Retest.			NAPAGOLD AIR FILTER		1.00
- Pressure Test And Inspect Cooling Systemflush System And Refill To Specs.			NAPAGOLD FUEL FILTER		1.00
- Service Transmission.Replace Fliter.Flush And Refill To Specs.			MAC BATTERY PROTECT		1.00
- Replace Both Defective Front Bump Stops.			20" WIPER BLADE		2.00
- Service Winch And Test Operation.			BLASTER PENETRANT		1.00
- Rotate And Balance All Four Tires.			PEAK GLOBAL		2.00
- Shop Supplies			FT144 TRANS FILTER SC		1.00
			SYN-ATF TRANS FLUID S		20.00
			SHOP SUPPLIES		1.00
			bumper		2.00
			DF CONVERTER ULTRA		1.00
Parts Charge:		847.83	Labor Charge:		840.00

Workorder: 1606762

Problem: Had to jump start in roads parking lot.

Meter Reading: 85765 In Date: 07/05/2016	Close Date: 07/12/2016	Labor Hours	Description	Parts	Quantity
- Road Call At Roads Parking Lot.Test Battery And Charging System.Replace Bad Battery.		1.50	BATTERY		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		120.41	Labor Charge:		90.00

1/30/2017
3:56:12PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10164913 2006 FORD F250 Pickup, 3/4 Ton, 4X4, W/Crew Cab, Topper

Workorder: 1608581

Problem: P.M. service and check A/C and check lights and cruise control.

Meter Reading: 86921 In Date: 08/18/2016	Close Date: 08/30/2016	Labor Hours	Description	Parts	Quantity
- P.M. Service.		12.75	SHOP SUPPLIES		1.00
- Replace Boken Shift Indicator.			5W20 ENGINE OIL		7.00
- Replace Two Tires, Rotate And Balance All Four.			WD40 SPR		1.00
- Replace Left Front Signal Lamp Bulb.			20" WIPER BLADE		2.00
- Replace Both Worn Out Rear Bump Stops.			INDICATOR		1.00
- Diagnose Cruise Control System. Pin Point Test And			TIRE DISPOSAL FEE		2.00
Replace Defective Brake Pedal Pressurewitch. Bleed			BULB		1.00
System. Clear Codes.			BRAKE PRESSURE SWITCH		1.00
- Complete Wheel Alignment. Test Drive.			USED FIRE X REFURBISHED		1.00
- Shop Supplies			179535492 LT265-70R17		2.00
			BUMPER STOP		2.00
			NAPAGOLD OIL FILTER		1.00
Parts Charge:		764.84	Labor Charge:		765.00

Workorder: 1611101

Problem: Transition Prep Charge

Meter Reading: 89570 In Date: 10/27/2016	Close Date: 10/27/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
Parts Charge:		0.00	Labor Charge:		0.00

Total Parts Charges:	13,107.96	Total Labor Charges:	11,770.00	Total Comm. Charges:	1,265.74
----------------------	------------------	----------------------	------------------	----------------------	-----------------