

**Palm Beach County Fleet Management
Asset Maintenance History**

10194202 2014 FORD F150 Pickup, 1/2 Ton

Workorder: 1403283 **Meter:** 333 **In Date:** 04/03/2014 **Closed:** 04/03/2014
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
 :

Workorder: 1409669 **Meter:** 3649 **In Date:** 09/26/2014 **Closed:** 10/08/2014
Problem: Pm service.

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts List

	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Stg Wheel Cov - Ford	1.00
Floor Mat-2pc Rub Bk	1.00
Shop Supplies	1.00

Hours 3.00 Labor: 180.00 Parts: 69.35 Total: 249.35
 :

Workorder: 1502751 **Meter:** 7428 **In Date:** 03/17/2015 **Closed:** 03/26/2015
Problem: Pm service.Towed in for coolant leak.

- Pm service.

- Pressure test and inspect cooling system for coolant leak.replace leaking heater hose and cut off casting boss on intake asper Tsb # 14-0103.refill with coolant and retest..

- Rotate and balance all four tires.

- Shop Supplies

Parts List

	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Accufit Beam	2.00
Ford Red Antifreeze	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Heater Hose	1.00
Shop Supplies	1.00

Hours 4.50 Labor: 270.00 Parts: 130.16 Total: 400.16
 :

Workorder: 1502811 **Meter:** 7361 **In Date:** 03/17/2015 **Closed:** 03/18/2015
Problem: Coolant Leak

- Tow From: 825 Ave P To: Lv Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1512648 **Meter:** 12965 **In Date:** 12/15/2015 **Closed:** 12/31/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace two tires.rotate and balance all four.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	22" Wiper Blade	2.00
	Hankook P235 75r17 Dp At	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 4.00	Labor: 240.00	Parts: 456.83
:		Total: 696.83

Workorder: 1606850 **Meter:** 16850 **In Date:** 07/07/2016 **Closed:** 08/02/2016
Problem: P.M. service and A/C blows warm at times.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	6.00
- Transport vehicle to dealer for a/c repairs.(evaporator)	Napagold Oil Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	22" Wiper Blade	2.00
	Mac Wite Lithium Gres	1.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.00	Labor: 360.00	Parts: 482.24
:		Total: 842.24

Workorder: 1612771 **Meter:** 18273 **In Date:** 12/14/2016 **Closed:** 01/11/2017
Problem: Had to be jump started and radio inop.

- Recharge battery.test battery and charging system.battery fail load test.replace defective battery.	Parts List	Qty
- Replace broken left tail lamp.	Battery 65	1.00
- Transport vehicle to dealer for defective radio assemble.	Tail Ligth Ass	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 309.17
:		Total: 519.17

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706217 **Meter:** 21002 **In Date:** 06/23/2017 **Closed:** 07/31/2017
Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Airbag light stay on.diagnose airbag system.replacedoor ajar switch and repair broken wires in harness between door and door jam.	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
- Replace and rewire corrpded trailer connector.	Used Fire X Refurbished	1.00
- Rotate and balance tires.	22" Wiper Blade	2.00
- Shop Supplies	trailer plug	1.00
	Vinyl Electrical Tape	1.00
	Bulb	1.00
	Tag Lamp Socket	1.00
	Door Ajar Asy	1.00
	Shop Supplies	1.00
Hours 6.25	Labor: 375.00	Parts: 176.30
:		Total: 551.30

Workorder: 1800510 **Meter:** 23842 **In Date:** 01/16/2018 **Closed:** 01/30/2018
Problem: P.M. service , towed in for crank but no start.

- P.m. service.	Parts List	Qty
- Perform cooling system flush.pressure test and flush cooling system.	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
- Replace two front tires .balance all four wheels ,nitrofill.	31-22 Wiper Blades 22	1.00
- Computer diagnose no start, codesu300a, U3003 and P0230.perform fuel pressure test. Install fuse 27 relocation kit per Tsb 15-0137.clear codes and test drive.	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
- Perform four wheel alignment.	Anti Freeze Motorcraft	2.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Fuse Relocate Kit	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.00	Labor: 660.00	Parts: 505.41
:		Total: 1,165.41

Workorder: 1800618 **Meter:** 23725 **In Date:** 01/16/2018 **Closed:** 01/18/2018
Problem: Engine Issues/PM Service

- Tow From: 825 Ave "p", Riviera Beach, Fl To: Lv shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1804089 **Meter:** 25444 **In Date:** 04/19/2018 **Closed:** 04/25/2018
Problem: Driver door open message on.

- Diagnose door ajar light . Remove left front door panel to test and replace broken door harness . Retest.	Parts List	Qty
	Wire Asy	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 29.72
:		Total: 119.72

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1807554 **Meter:** 28053 **In Date:** 07/25/2018 **Closed:** 07/31/2018
Problem: PM Service

- P.m. service.	Parts List	Qty
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Test and replace high mount brake light bulb.	5w20 Engine Oil	6.00
- Shop Supplies	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Ford Triton Pvc Swc	1.00
	Boxed Miniatures	2.00
	Shop Supplies	1.00
Hours 3.30	Labor: 198.00	Parts: 58.87
:		Total: 256.87

Workorder: 1811097 **Meter:** 30756 **In Date:** 10/29/2018 **Closed:** 10/31/2018
Problem: Left rear tire going flat.

- Replace left rear tire and balance . Nitrogen fill tires.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	P235/75r17 Tire	1.00
	Tire Disposal Fee	1.00
Hours 0.50	Labor: 33.50	Parts: 109.99
:		Total: 143.49

Workorder: 1901849 **Meter:** 33342 **In Date:** 02/19/2019 **Closed:** 03/06/2019
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.	Napagold Oil Filter	1.00
- Diagnose low fan speed inop . R&r failed blower resistor . Retest .	5w20 Engine Oil	6.00
- Pressure test and inspect colling system . Replace leaking water pump , thermostat and gasket . Flush and refill cooling system .	Washer Fluid Concentr	1.00
- Replace broken left front side trim and cover .	22" Wiper Blade	2.00
- Complete front end alignment and road test.	Used Fire X Refurbished	1.00
- Shop Supplies	Hankook P235 75r17 Dp At	2.00
	Blower Resistor	1.00
	Gasket	1.00
	Anti Freeze Motorcraft	1.00
	Gasket	1.00
	Thermostat	1.00
	Thermostat Gasket	1.00
	Water Pump	1.00
	seatpanel shield asy	1.00
	Housing	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 12.00	Labor: 804.00	Parts: 884.89
:		Total: 1,688.89

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1906566 **Meter:** 36256 **In Date:** 06/21/2019 **Closed:** 07/02/2019
Problem: A/C inop

- A/c performance test . Leak test . Recover and vacuum system .replace leaking evaporator core , heater core and drier . Complete recharge to factory spec. Flush and refill cooling system . Retest .
- Shop Supplies

Parts List	Qty
Heter Core	1.00
A/c Seal Kit	1.00
A/c Evaporator	1.00
accumulator asy	1.00
E8 A/c Oil Univ W Dye	1.00
Freon Lv Shop 1	2.00
Anti Freeze Motorcraft	1.00
Shop Supplies	1.00

Hours 13.50 Labor: 904.50 Parts: 1,042.67 Total: 1,947.17
:

Workorder: 1907648 **Meter:** 36268 **In Date:** 07/23/2019 **Closed:** 07/25/2019
Problem: Tire pressure light on .

- Repair left front tire and balance . Nitrofill all.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 67.00 Parts: 3.00 Total: 70.00
:

Workorder: 1909038 **Meter:** 36424 **In Date:** 08/28/2019 **Closed:** 09/16/2019
Problem: P.M. Service.

- P.m. service.
- Test battery and charging system . Battery failed load test . R&r defective battery .
- Test and replace left rear cracked tail light lens . Test and replace dome light bulb .
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Battery	1.00
Lamp Assembly	1.00
Boxed Miniatures	2.00
Boxed Miniatures	1.00
Shop Supplies	1.00

Hours 5.00 Labor: 335.00 Parts: 340.11 Total: 675.11
:

Workorder: 1911842 **Meter:** 38898 **In Date:** 11/06/2019 **Closed:** 11/15/2019
Problem: SECURITY CALLED TIRE SERVICE FOR DEPT@6:25A 11/6/19 - FLAT TIRE ON FRONT

- Tire Service Phil Foster Park - Security Called Tire Service For Dept@6:25a 11/6/19 - Flat Tire On Front

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1911873 **Meter:** 38898 **In Date:** 11/15/2019 **Closed:** 11/18/2019
Problem: 1 new tire

- Parts only
- Shop Supplies

Parts List	Qty
P235/75r17 Fstone A/t Owl	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours 0.00 Labor: 0.00 Parts: 151.43 Total: 151.43
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1912495 **Meter:** 39894 **In Date:** 12/05/2019 **Closed:** 12/19/2019
Problem: Door ajar light in all the time .

- Computer diagnose left front door ajar . Remove left front door panel to replace defective door harness ,open on ground circuit .

	Parts List	Qty
	Wire Asy	1.00
	Shop Supplies	1.00

- Shop Supplies

Hours 1.50 Labor: 109.50 Parts: 53.50 Total: 163.00
:

Workorder: 1913175 **Meter:** 40845 **In Date:** 12/30/2019 **Closed:** 01/08/2020
Problem: P.M. service .

- P.m. service.

	Parts List	Qty
	Napagold Oil Filter	1.00
	5w20 Engine Oil	6.00
	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	Fire Ext Mount Strap Style	1.00
	Boxed Miniatures	2.00
	Hankook P235 75r17 Dp At	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

- Replace broken fire extiguisher bracket .

- Test and replace tail light bulbs.

- Replace two tires . Rotate and balance all four tires . Nitrofill all.

- Shop Supplies

Hours 5.00 Labor: 365.00 Parts: 525.73 Total: 890.73
:

Workorder: 2000337 **Meter:** 40855 **In Date:** 01/10/2020 **Closed:** 01/16/2020
Problem: A/C not cooling .

- A/c performance test . Diagnose high pressures and fans on high . R&r clogged condensor assmby and high side switch . Recover freon . Vacuum system and complete recharge to factory spec . Retest operation .

	Parts List	Qty
	Switch	1.00
	Seal Kits	2.00
	Freon Lv Shop 1	1.00
	Pag 46 W Uv Dye 8oz	1.00
	A/c Condenser	1.00
	Shop Supplies	1.00

- Shop Supplies

Hours 4.00 Labor: 292.00 Parts: 296.31 Total: 588.31
:

Workorder: 2001183 **Meter:** 41574 **In Date:** 02/03/2020 **Closed:** 02/18/2020
Problem: Cooling fan stays on high fan .

- Computer diagnose cooling fan on high blow . Hook up A/c machine monitot pressures . Recover feon and vacuum . R&r defective clogged expansion valve . Evacuate system and complete recharge to factory spec . Retest .

	Parts List	Qty
	Louvre	2.00
	Valve A/c Asy	1.00
	Shop Supplies	1.00

- Shop Supplies

Hours 3.50 Labor: 255.50 Parts: 108.22 Total: 363.72
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 2001856 **Meter:** 41883 **In Date:** 02/24/2020 **Closed:** 03/05/2020
Problem: A/C blows warm .

- A/c performance test . Recover freon . Replace locked compressor ,condenser, expansion valve and o rings . Flush system . Replace A/c belt and alternator belt . Evacuate and complete recharge to factory spec. Test drive .
- Shop Supplies

Parts List	Qty
Seal Kits	3.00
Kit O	1.00
V Belt	1.00
V Belt	1.00
Valve Assy	1.00
Frig Oil	1.00
Freon Lv Shop 2	2.00
Seal	1.00
Flush Solvent	1.00
A/c Condenser	1.00
A/c Compressor	1.00
Shop Supplies	1.00

Hours 7.40 Labor: 540.20 Parts: 875.98 Total: 1,416.18
:

Workorder: 2006628 **Meter:** 45825 **In Date:** 07/06/2020 **Closed:** 07/15/2020
Problem: P.M. service and A/c blows warm at times .

- P.m. service.
- A/c performance test . Leak test . Replace high and lower side port schrader valves . Recover and evacuate and complete charge system to factory spec . Retest .
- Test and replace defective left rear turn signal bulb . Replace broken right brake light lens .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts List	Qty
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
High Side Schrader Valve	1.00
A/c Valve Core Low Side	1.00
Boxed Miniatures	1.00
Tail Ligth Ass	1.00
Freon Lv Shop 2	2.00
Shop Supplies	1.00

Hours 6.00 Labor: 438.00 Parts: 249.58 Total: 687.58
:

Workorder: 2008477 **Meter:** 47250 **In Date:** 08/25/2020 **Closed:** 08/31/2020
Problem: A/c not working .

- A/c performance test . Computer diagnose , codes B10f1 and B1086 ,perform pinpoint test . Evap sensor out of range .service temp sensor connector and retest .
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 2.00 Labor: 146.00 Parts: 4.00 Total: 150.00
:

Workorder: 2100249 **Meter:** 50507 **In Date:** 01/08/2021 **Closed:** 01/08/2021
Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 146.00 Parts: 0.00 Total: 146.00
: