



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V283

In Date: 10/19/2005
Close Date: 10/20/2005

Meter Reading:

Problem?

RELIEF VALVE BULB INOP, RE-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V241

In Date: 10/17/2005
Close Date: 11/03/2005

Meter Reading: 21,832.00

Problem?

REPLACE WIPER BLADES RE-19

Task performed:

Parts

Quantity

52-24WIPER BLADES ANCO 24

2

Workorder: V370

In Date: 10/31/2005
Close Date: 11/07/2005

Meter Reading: 22,255.00

Problem?

CENTER RIGHT STROBE INOP, ON LIGHT BAR RE-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V433

In Date: 11/02/2005
Close Date: 11/07/2005

Meter Reading: 22,397.00

Problem?

relief valve light inoperative-valve functioning properly E19

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V491

In Date: 11/07/2005

Meter Reading:

Close Date: 11/10/2005

Problem?

SIREN NOT WORKING RE19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V902

In Date: 12/13/2005

Meter Reading:

Close Date: 12/14/2005

Problem?

TRASH LINE TRAY LOCKS INOP, RE-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V663

In Date: 11/22/2005

Meter Reading:

Close Date: 12/15/2005

Problem?

VISTA SCREEN DISPLAID A MESSAGE FROM NODE #3, ALL DOOR AJAR LIGHTS FLASHING, RE-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V769

In Date: 12/01/2005

Meter Reading:

Close Date: 12/15/2005

Problem?

QUARTZ LIGHTS INOP, E-19

Task performed:

Parts

Quantity

LB-D30BULB QUARTZ HAL. 12V 150W

2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V1295

In Date: 01/25/2006
Close Date: 02/01/2006

Meter Reading: 25,370.00

Problem?

RELIEF VALVE STICKING TAKES TO LONG TO RESET, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1385

In Date: 02/01/2006
Close Date: 02/13/2006

Meter Reading:

Problem?

LEFT REAR HUB CAP FALLING OFF, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1468

In Date: 02/10/2006
Close Date: 02/13/2006

Meter Reading:

Problem?

HURST POWER UNIT MOUNTING BRACKET BROKEN, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1493

In Date: 02/13/2006
Close Date: 02/28/2006

Meter Reading:

Problem?

PRIMER INOP, E-19

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V1573

In Date: 02/21/2006 Meter Reading:
Close Date: 03/10/2006

Problem?
R/SIDE TELELIGHT INOP, E-19

Task performed:	Parts	Quantity
	LB-D30BULB QUARTZ HAL. 12V 150W	1

Workorder: V1748

In Date: 03/06/2006 Meter Reading:
Close Date: 03/15/2006

Problem?
OFFICER SEAT BELT INOP, E-19

Task performed:	Parts	Quantity
	IMMF11358SEAT BELTS	1

Workorder: V1741

In Date: 03/06/2006 Meter Reading:
Close Date: 03/17/2006

Problem?
R/TURN SIGNALS INOP, E-19

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V2029

In Date: 03/29/2006 Meter Reading:
Close Date: 04/04/2006

Problem?
R/REAR DISCHARGE E-19

Task performed:	Parts	Quantity
	5462300020VALVE KIT SS VALVE 3 IN	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2193

In Date: 04/11/2006

Meter Reading:

Close Date: 04/17/2006

Problem?

GATED VALVE HOLDER ON TAIL BOARD INOP, E-19

Task performed:

Parts

Quantity

373-2.5E-Z LOK BRACKET

1

Workorder: V2204

In Date: 04/11/2006

Meter Reading:

Close Date: 04/18/2006

Problem?

COUPLING HOLDER ON REAR STEP BROKEN, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2219

In Date: 04/17/2006

Meter Reading:

Close Date: 04/19/2006

Problem?

PUMP TEST, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V282

In Date: 01/01/1900

Meter Reading:

Close Date: 05/11/2006

Problem?

relief valve light out, need oil for engine

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V326

In Date: 10/19/2005

Meter Reading:

Close Date: 05/11/2006

Problem?

RELIEF VALVE BULB INOP, RE-19

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V2554

In Date: 05/10/2006

Meter Reading: 29,812.00

Close Date: 05/25/2006

Problem?

B INSPECTION, CHANGE OUT S/S VALVE BALLS, E-19

Task performed:

<u>Parts</u>	<u>Quantity</u>
038-1550-00VALVE CHECK HALE 1/4"	1
040-1160-03-00 RING SEAL	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
17210ZE6505FILTER AIR HONDA	1
322502BULB PATIENT GH22	1
3530016HOSE HURST 16 ORANGE	1
3530033USE 353R222 HOSE HURST SWIVEL/ORING	2
52-24WIPER BLADES ANCO 24	2
5460990500GASKET SEAL KIT P25/30	1
5462300020VALVE KIT SS VALVE 3 IN	1
6806970098SEAL DOOR	1
6808300074VENT A/C LH	3
6808300174VENT A/C RH	2
7460967AIR FILTER 17210-ZE2-515 HONDA	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91553941GAUGE	1
A1834388003MOLD R/H	2
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Vendor?: VC-15214



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V3038

In Date: 06/16/2006

Meter Reading:

Close Date: 06/22/2006

Problem?

repair k-1200 saw E19 (outside agency-regan's small eng. service)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: REGANS

Workorder: V3053

In Date: 06/20/2006

Meter Reading:

Close Date: 06/23/2006

Problem?

ANTILOCK BRAKE LIGHT ON, E-19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3159

In Date: 06/27/2006

Meter Reading:

Close Date: 06/27/2006

Problem?

ON CALL SIREN 10-7

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3415

In Date: 07/11/2006

Meter Reading:

Close Date: 07/17/2006

Problem?

noise when turning left in the wheel area E19

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V3496

In Date: 07/17/2006

Meter Reading:

Close Date: 07/17/2006

Problem?

ON CALL TANK TO PUMP VALVE BROKEN E19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3468

In Date: 07/13/2006

Meter Reading:

Close Date: 07/20/2006

Problem?

new hose bed cover already torn at flap in rear

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3900

In Date: 08/14/2006

Meter Reading:

Close Date: 08/21/2006

Problem?

LIHT OUT ON REAR BUMPER E19

Task performed:

Parts

Quantity

35200-RLIGHT MARKER LED RED

2

35200-YLIGHT MARKER LEDAMBER

2

Workorder: V4089

In Date: 08/23/2006

Meter Reading:

Close Date: 08/25/2006

Problem?

A/C COMP. MOUNTING BROKEN

Task performed:

Parts

Quantity

5499FRE801910 REPAIR BRACKET A/C COMPRESSOR

1

72R311018-2640 VENT A/C NEW # 1719

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V4116

In Date: 08/25/2006
Close Date: 09/06/2006

Meter Reading:

Problem?

spot light 10-7 E19

Task performed:

Parts	Quantity
4537BULB 100W SPOT	1

Workorder: V4190

In Date: 08/31/2006
Close Date: 09/06/2006

Meter Reading:

Problem?

repair saw and generator (outside agency-regan's small engine service)

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: REGANS

Workorder: V4257

In Date: 09/05/2006
Close Date: 09/11/2006

Meter Reading: 32,787.00

Problem?

scene lt 10-7RE19

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V4616

In Date: 09/26/2006
Close Date: 10/03/2006

Meter Reading: 2,263.00

Problem?

pump leaking re19

Task performed:

1. WATER LEAKING FROM PRIMER PUMP. REPLACE PRIMER VALVE AND SWITCH, TEST PRIMER PUMP. PRIMER PUMP IN GOOD WORKING ORDER.

Parts	Quantity
538028052VALVE PRIMER PUMP W/HARDWARE	1
PVG-KITORING KIT	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V4942

In Date: 10/18/2006 Meter Reading: 34,179.00
Close Date: 10/23/2006

Problem?

QUARTZ LIGHT ALARM GOES OFF, E-19

Task performed:	Parts	Quantity
1. TRAVELED TO STN 19. ADJUSTED QUARTZ LIGHTS. TEST/ OK.	NO PARTS USED	

Workorder: V4931

In Date: 10/17/2006 Meter Reading: 34,179.00
Close Date: 10/25/2006

Problem?

HURST TOOL HOSE BURNT, E-19

Task performed:	Parts	Quantity
1.PARTS ONLY NO REPAIR	3530016HOSE HURST 16 ORANGE	1

Workorder: V4818

In Date: 10/10/2006 Meter Reading: 2,311.00
Close Date: 10/26/2006

Problem?

need engine oil and we need spare bottles at the station RE19 NEEDED TWO STROKE OIL

Task performed:	Parts	Quantity
1. DROP OFF OIL @ STN 19.	NO PARTS USED	

Workorder: V4856

In Date: 10/11/2006 Meter Reading: 33,994.00
Close Date: 10/26/2006

Problem?

E19 battery compartment door has only one of two locks holding it closed

Task performed:	Parts	Quantity
1. TRAVELED TO STN 19 LUBE AND ADJUST PINS IN BATT COMPARTMENT DOOR.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V4801

In Date: 10/09/2006 Meter Reading: 33,994.00
Close Date: 11/07/2006

Problem?

ON CALL PUMP OVERHEATED RE19

Task performed:

Parts

Quantity

1. TRAVELED TO STN 19. R/R DOOR SWITCH.

NO PARTS USED

Workorder: V5703

In Date: 12/06/2006 Meter Reading: 36,237.00
Close Date: 12/11/2006

Problem?

MAP LIGHT 10-7 E19

Task performed:

Parts

Quantity

1. TRAVELED TO STN 19. INSTALLED MAP LIGHT,
TEST/ OK.

NO PARTS USED

Workorder: V5662

In Date: 12/04/2006 Meter Reading: 36,237.00
Close Date: 12/12/2006

Problem?

REPLACE TIRES AT STA 19 E19

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V6177

In Date: 01/09/2007 Meter Reading: 37,078.00
Close Date: 01/31/2007

Problem?

Left rear hub cap reported missing E19

Task performed:

Parts

Quantity

1. B Inspection
2. Noise in front end found heat exchanger bracket rubbing r/f spring and spring bolt hitting exhaust pipe adjusted bracket and spring bolt
3. Serviced Hurst tool power unit. Replaced 2 hoses on ram replaced junction block
4. Serviced generator

ACX-84534LUG NUT COVER PK10

4



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V6191

In Date: 01/09/2007
Close Date: 01/31/2007

Meter Reading: 37,078.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED E19

Task performed:

1. Ok to pump light intermittent. Replaced pump shift switches
2. Add coolant and repaired leak from l/s of engine (coolant pipe to comp). Serviced cooling system
3. Noise when turning left inspected steering system flows and pressures as well as all components
4. A/C line rubbing reroute a/c line
5. Failed vacume test replaced check valve
6. Repaired marker and clearance lights as needed
7. Replaced all belts
8. Primer pump sticks on replaced primer valve

Parts	Quantity
0100080010STRAINER	2
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
038-1550-00VALVE CHECK HALE 1/4"	1
1280008CONNECTOR SET	1
180R002HURST HYD. FLUID QT	1
200-2450-00NC SWITCH OK TO PUMP	2
353R023HURST HOSE W/O SWIVEL	2
372000084MARKER LIGHT	1
50R03ZRRLIGHT 500 TIR LED	1
52-24WIPER BLADES ANCO 24	2
538028052VALVE PRIMER PUMP W/HARDWARE	1
6808300074VENT A/C LH	1
9440BELT	1
9480BELT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
UMVS111611STRAP	1

Workorder: V6456

In Date: 01/24/2007
Close Date: 01/31/2007

Meter Reading: 2,491.30

Problem?

E19 just return from (PM) . The grinding noise that was previously reported is worst now than before. It now makes noise sitting in neutral, braking, asselerating, left turns, some right turns, and at idle.

Task performed:

1. Located noise at radiator\cab braces. Isolated noise and road tested ok

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V6495

In Date: 01/26/2007 Meter Reading: 2,529.80
Close Date: 02/01/2007

Problem?

The primer is very, very hard to pull and was leaking around the bottom of the primer knob where the black hose connects to the brass fitting, under the panel where the levers are located. E-19

Task performed:

1. Installed new primer valve. Engauged pump leak water. Rework primer fitting and installed new tee for check valve

Parts	Quantity
012-0160-00T-HANDLE	1
538028052VALVE PRIMER PUMP W/HARDWARE	1

Workorder: V6704

In Date: 02/11/2007 Meter Reading: 2,568.00
Close Date: 02/21/2007

Problem?

One of the air tanks is leaking and is bent at the tip. The air tanks will not fill completely. Need a mechanic worm's eye view. E19

Task performed:

1. TRAVELED TO STN 19. NEED TO REPLACE AIR FLEETING DID NOT HAVE ONE ON TRUCK.
2. INSTALLED LIC PLATE AND REPALCE FITTING ON TANK.

Parts	Quantity
12105QUICK DRAIN	4

Workorder: V6948

In Date: 02/26/2007 Meter Reading: 2,615.90
Close Date: 03/06/2007

Problem?

Gas powered exhaust fan handle bent. e19

Task performed:

1. Drive to station. R&R handle and feet on ram fan

Parts	Quantity
006445COVERS	1
FB9609583SHOULDERED CAP SCREW GF165	1
FZ51368FEET RUBBER RAM-FAN	4
FZKNOB7028KNOB BLACK GF165	1
FZSPRGK114SPRING GF165	1
GA0203ZGF165 HANDLE	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V6927

In Date: 02/26/2007
Close Date: 03/08/2007

Meter Reading: 2,615.90

Problem?

The right small intake on the Lt. side is sticking and is hard to turn when connecting to the 3 inch line. The gasket may be the problem E19

Task performed:

1. Replaced balls in valve. Housing bad
2. Replaced coupling for intake

Parts	Quantity
338-25338-25 ADAPT.SUCTION	1
70002629109041 BEARING 025 IN 50 PK	50

Workorder: V7819

In Date: 04/19/2007
Close Date: 04/23/2007

Meter Reading: 41,212.00

Problem?

need 3 quarts of hurst oil E19

Task performed:

- Filled Hurst tool can; test-ok

Parts	Quantity
180R002HURST HYD. FLUID QT	3

Workorder: V7948

In Date: 04/26/2007
Close Date: 05/15/2007

Meter Reading: 2,792.00

Problem?

fuel gauge is not working properly. After filling the fuel tank, the gauge reads between 3/4 and full. E19

Task performed:

- Float stock in tank works; test ok

Parts	Quantity
NO PARTS USED	

Workorder: V8033

In Date: 05/01/2007
Close Date: 05/16/2007

Meter Reading: 41,666.00

Problem?

hurst power unit coming loose from frame E19

Task performed:

- Install new mounts

Parts	Quantity
HR149460107MOUNT VIBRATION (NEWER POWER UNITS	8



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V8375

In Date: 05/22/2007 Meter Reading: 2,978.00
Close Date: 06/05/2007

Problem?
deck gun- sensor, and air tank bleeder connection.E19

Task performed:	Parts	Quantity
1. Drive to Sta adjusted deck gun sender, test OK and remove tank bleeder line	NO PARTS USED	
2. Inspection at E-One on Bomb Truck		
3. Inspection on Heavy Truck at Medic Master		

Workorder: V8277

In Date: 05/16/2007 Meter Reading: 42,066.00
Close Date: 06/07/2007

Problem?
repair fuel gauge e19

Task performed:	Parts	Quantity
1. Drive to sta R/R fuel sender, go to Sta 16 fill truck with fuel	NO PARTS USED	

Workorder: V8482

In Date: 05/30/2007 Meter Reading: 2,978.00
Close Date: 06/13/2007

Problem?
Right side rear warning light needs to be reattached e19

Task performed:	Parts	Quantity
1. Drove to sta, installed rear lights, test OK	NO PARTS USED	

Workorder: V9000

In Date: 06/25/2007 Meter Reading: 43,480.00
Close Date: 06/25/2007

Problem?
ON CALL HURST UNIT 10-7 E19

Task performed:	Parts	Quantity
1. Hurst unit inop- ness to swap out at shop	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V8822

In Date: 06/12/2007 Meter Reading: 2,978.00
Close Date: 06/26/2007

Problem?

deck gun alarming / sensor issue e19

Task performed:

1. Drive to sta, installed new sender test ok

Parts	Quantity
X120WEAR RING	1
X125QUAD SEAL FOR CROSSFIRE	1
XG840-KITEXTENDA GUN SWITCH	1

Workorder: V8842

In Date: 06/14/2007 Meter Reading: 42,602.00
Close Date: 06/29/2007

Problem?

Install brackets E19

Task performed:

1. Drive to sta installed brackets

Parts	Quantity
NO PARTS USED	

Workorder: V8956

In Date: 06/21/2007 Meter Reading:
Close Date: 07/03/2007

Problem?

hurst cutters are weak under load and need to be pressure test.e19

Task performed:

Drive to station; test power unit; 6000a port; 5000b port;
give spare to stn; bring to shop for repair

Parts	Quantity
40R00FCR400 SER CLEARANCE LITE	1

Workorder: V9083

In Date: 07/01/2007 Meter Reading: 2,941.00
Close Date: 07/03/2007

Problem?

Passenger side upper right emergency light is out. Not working. E-19

Task performed:

1. DRIVE TO STATION. FOUND BAD CONNECTION
UNDER PLUG. REWORKED. TESTED E-LIGHTS-OK.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V9391

In Date: 07/17/2007
Close Date: 07/20/2007

Meter Reading: 2,986.00

Problem?

Deck Gun extention warning system keeps going off 4 times in one shift E19

Task performed:

1. SEE WORK ORDER #9063.

Parts

Quantity

600000003NODE HERCULES V-MUX

1

Workorder: V9496

In Date: 07/23/2007
Close Date: 07/27/2007

Meter Reading: 44,576.00

Problem?

hose reel will not rewind e19

Task performed:

Drive to station; fnd bad grnd; rework-test ok

Parts

Quantity

NO PARTS USED

Workorder: V9568

In Date: 07/27/2007
Close Date: 07/30/2007

Meter Reading: 2,998.70

Problem?

windshield wipers do not clear water from windshield E19

Task performed:

1. DRIVE TO STA. R/R WIPER BLADES. REPAIR LIGHT ON FENDER- TEST OK.

Parts

Quantity

52-24WIPER BLADES ANCO 24

2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: **V9628**

In Date: 07/30/2007

Meter Reading: 44,576.00

Close Date: 08/07/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED E19

Task performed:

- B-Inspection
- 1. Shop meeting
- 2. Rem (2) seats to be sent out/repared
- 3. Swapped into on-call truck
- 4. Svc batteries; replc all (4) batteries; clnd all term/cable ends
- 5. Svc aur dryer
- 6. Replc mntng bolts on exh clamp & tigthen
- 7. Painted fuel cap (yellow)
- 8. Replc broken tail board end cap on left side
- 9. Replc broken strobe on tail board (left side)
- 10. Replc rear A/C filter
- 11. Replc engine air filter
- 12. Replc right frt seat belt
- 13. Replc belts
- 14. Replc (4) door trims/molding(broken)
- 15. Replc (3) door weatherstrips (ripped)
- 16. Tighten door latch on R-1 compt & adj door
- 17. Svc generator
- 18. Svc Hurst tools
- 19. Rep vac test gauge (broken)
- 20. Reinstall seats that came back from upholstere
- 21. Replc heat stickers on ladders (expired)
- 22. Replc both backup lights

Parts

Quantity

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
121R019DIPSTICK	1
180R002HURST HYD. FLUID QT	2
353R023HURST HOSE W/O SWIVEL	2
50R03ZRRLIGHT 500 TIR LED	1
5TSMACMOUNT 500 TIR SER CHROME	1
60C00FCRCLEAR BACKUP 600 SERIES	2
6806970098SEAL DOOR	1
6808300174VENT A/C RH	1
7460967AIR FILTER 17210-ZE2-515 HONDA	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
92541676VAC TEST GAUGE 0-30	1
9440BELT	1
9480BELT	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR5ESSPARK PLUG 7734	2
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
IMMF11358SEAT BELTS	1
K080716BELT	1
R90PFILTER FUEL 33231	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V9661

In Date: 08/01/2007
Close Date: 08/10/2007

Meter Reading: 44,576.00

Problem?

repair seats at central auto trim e19

Task performed:

Parts	Quantity
A-1452ALT INT BR TK DELCO 19020309	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	2
HP-31DBATTERY 950CCA HP-31D	2

Vendor?: CENTRAL AUTOTRIM

Workorder: V9669

In Date: 08/01/2007
Close Date: 08/10/2007

Meter Reading: 44,576.00

Problem?

replace hose bed cover e19 central auto trim

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM

Workorder: V9838

In Date: 08/13/2007
Close Date: 08/30/2007

Meter Reading: 45,255.00

Problem?

A/C not blowing cold in the front. A/C not blowing cold in the back.R19

Task performed:

Drive to strn; replc both intake filters; chk pressure/wiring/nodes; front 38, rear 42; replc (2) dome lights

Parts	Quantity
322502BULB PATIENT GH22	2
78R536078R5360M 2PK FILTER AIR COND	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V9942

In Date: 08/15/2007
Close Date: 08/30/2007

Meter Reading: 45,056.00

Problem?

A/C blows warm E19

Task performed:

Low on freon-fill; fnd loose filling on dryer; tighten; test ok

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V9968

In Date: 08/17/2007 Meter Reading: 3,049.00
Close Date: 08/31/2007

Problem?

Tractor ABS warning light on E19

Task performed:

Drive to Stn; reset all wheel sender; chk loder; R/R wheel to fall out; test drive-ok

Parts

Quantity

NO PARTS USED

Workorder: V10072

In Date: 08/22/2007 Meter Reading: 3,049.00
Close Date: 09/12/2007

Problem?

REPAIR FLAT CALLAGHAN ENT E19

Task performed:

Repair flat - Callaghan

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V10325

In Date: 09/10/2007 Meter Reading: 3,089.00
Close Date: 09/20/2007

Problem?

Engine spotlight is out. Needs replacement. Thanks. e19

Task performed:

See W/O 10363

Parts

Quantity

NO PARTS USED

Workorder: V10363

In Date: 09/11/2007 Meter Reading: 3,089.00
Close Date: 09/20/2007

Problem?

Spotlight on roof is burnt out. Spotlight rotates but does not light up. E19

Task performed:

Drive to stn; R/R/ spotlight on roof; test ok

Parts

Quantity

620122SPOT LIGHT REMOTE

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V10364

In Date: 09/11/2007
Close Date: 09/21/2007

Meter Reading: 3,089.00

Problem?

Drivers side light on front grill is dim. The light on the passenger side is bright while the light on driver side is dim. e19

Task performed:

drive to Stn; fnd bad grnd; repaired; test ok

Parts

NO PARTS USED

Quantity

Workorder: V5971

In Date: 12/27/2006
Close Date: 10/15/2007

Meter Reading: 2,491.30

Problem?

small diesel leak from engine area E19

Task performed:

1. Checked for fuel leak scheduled cummins for repair

Parts

NO PARTS USED

Quantity

Workorder: V11091

In Date: 10/17/2007
Close Date: 10/23/2007

Meter Reading: 3,194.40

Problem?

foam pickup not working properly. It will not suck up foam out of a 5 gallon can. e19

Task performed:

1. foam fill pump inoperable. loss of ground. repaired wiring.

Parts

NO PARTS USED

Quantity

Workorder: V11187

In Date: 10/23/2007
Close Date: 10/25/2007

Meter Reading: 3,194.40

Problem?

rear door sensor is bad and alarms when truck is in gear. E19

Task performed:

1. travel to station 19. engine at training. travel to station 14 + back to station 19.
2. diagnose door alarm found bad door switch. install new switch.
3. check pump. recirculate ok. check relief valve. ok. operator error.

Parts

52-624SWITCH DOOR

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V11398

In Date: 11/02/2007

Meter Reading: 3,222.70

Close Date: 11/21/2007

Problem?

Belts squeeling in engine compartment when engine is at full throttle wet and dry E-19

Task performed:

drive to Stn; replc bearing on pulley & brkn bolt on other compressor; tighten both belts. j

Parts

203FFBEARING PULLEY

Quantity

1

Workorder: V11886

In Date: 12/03/2007

Meter Reading: 49,934.00

Close Date: 12/12/2007

Problem?

1 discharge wont open e19

Task performed:

1. Drive to Sta. installed bolt in valve, test OK.

Parts

NO PARTS USED

Quantity

Workorder: V11954

In Date: 12/07/2007

Meter Reading: 3,317.00

Close Date: 12/12/2007

Problem?

request for net type cover for passenger crosslay preconnect. the red rubberized cover tore and blew off. Engine 19 STATION 19

Task performed:

1. Travel to 19.
2. Found cover missing, Ness. to drill and mount new cover on right side.
3. Installed both cover for cross lay and cone in rear.

Parts

NO PARTS USED

Quantity

Workorder: V11971

In Date: 12/07/2007

Meter Reading: 50,195.00

Close Date: 12/20/2007

Problem?

replace tires at sta 19 callaghan ent

Task performed:

Replace tire Stn19 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V11955

In Date: 12/07/2007
Close Date: 01/02/2008

Meter Reading: 3,317.00

Problem?

REAR TAILBOARD , RIGHT SMALL LIGHT NEEDING TO BE REPLACED. E 19

Task performed:

1. Travel to 19.
2. Replace led light and pig tail on rear tailboard.

Parts	Quantity
35200-RLIGHT MARKER LED RED	1
94862PIGTAIL LED MARKER LIGHTS	1

Workorder: V12264

In Date: 12/28/2007
Close Date: 01/03/2008

Meter Reading: 3,369.00

Problem?

Rust on top of the cab E19

Task performed:

1. Travel to 19.
2. Needs to have rust stopped and then 5200 across rust.

Parts	Quantity
NO PARTS USED	

Workorder: V12729

In Date: 01/22/2008
Close Date: 01/22/2008

Meter Reading: 51,938.00

Problem?

ON CALL E19 CHECK BRAKES

Task performed:

1. On call, drive to station, C/O brakes.

Parts	Quantity
NO PARTS USED	

Workorder: V12730

In Date: 01/22/2008
Close Date: 02/01/2008

Meter Reading: 51,938.00

Problem?

ON CALL COOLANT LEAK R19

Task performed:

- On call for coolant leak; replc eng belt. j

Parts	Quantity
0127110042BELT MERCEDES MOTORS	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V12783

In Date: 01/23/2008
Close Date: 02/04/2008

Meter Reading: 51,938.00

Problem?

Need 1', 2' or 3' velcro straps for wrapping con space umbilical in figure eight fashion. E19

Task performed:

drive to stn; installed straps.

j

Parts

SAHSVS2510STRAP

Quantity

3

Workorder: V3467

In Date: 07/13/2006
Close Date: 02/07/2008

Meter Reading:

Problem?

marker light on rear step out

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V13100

In Date: 02/07/2008
Close Date: 02/11/2008

Meter Reading: 52,584.00

Problem?

light bar 10-7 horn 10-7 E19

Task performed:

Drive to stn; fnd truck volts & mulpex volt diff by (3) volts;
chk conn; cln & test ok.

j

Parts

0R80-0615-00INTERFACE MODULE

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V13180

In Date: 02/11/2008

Meter Reading: 52,584.00

Close Date: 02/14/2008

Problem?

B INSPECTION AND REPARS AS NEEDED E19

Task performed:

1. Perform "B" inspection
2. Assist "B" inspection
3. replaced both T/S side lenses (cracked)
4. Replaced cab light bar strobe
5. Replaced tail board LED marker light
6. Repaired wiring for left side grill strobe light
7. replaced 3 bad LED lights, 2 on right side, 1 on left rear tailboard
8. Programmed reverse lights not to flash
9. Replaced nozzle holder brackets
10. Checked condensor fans, OK

Parts

Quantity

02-0363769233D400 LED WHITE WHITE	1
020363596230NOT AVAIL REPAIR ONLY 400 SERIES (WHIT	1
15W40BSYN OIL BULK QTS	24
35200-RLIGHT MARKER LED RED	1
3972071THERMOSTAT ISB	1
50R03ZCRLIGHT LED RED TIR 6	3
91513AMBER LENS	2
94862PIGTAIL LED MARKER LIGHTS	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V13124

In Date: 02/08/2008

Meter Reading: 3,457.20

Close Date: 02/15/2008

Problem?

need to replace the drivers side light on the grill. e19

Task performed:

1. Drive to station, R & R lens, test OK

Parts

Quantity

020383470CROLENS RED/C USE 4 SCREW LENS NOW	1
---	---

Workorder: V13623

In Date: 03/01/2008

Meter Reading: 3,516.60

Close Date: 03/07/2008

Problem?

3 box lights on engine missing rings for strap. SO19

Task performed:

1. Drive to station, installed rings for straps on hand lights

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT	1
-----------------------------	---



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V13733

In Date: 03/07/2008
Close Date: 03/12/2008

Meter Reading: 53,699.00

Problem?

INSTALL PRO BARS AND NY HOOK BATT1

Task performed:

1. Drive to station 14, 11, 15, 16, 18, 19, installed pro bars and roof hooks.

Parts

Quantity

0100030000SCREEN 6 IN
5269LPVM-5 SM MOUNT
WAT61403STRAINER 6 IN

1
6
1

Workorder: V14320

In Date: 04/07/2008
Close Date: 04/08/2008

Meter Reading: 54,888.00

Problem?

repair a/c mounting e19

Task performed:

1. REWORK A/C BRACKET NEW BOLT.

Parts

Quantity

NO PARTS USED

Workorder: V14348

In Date: 04/08/2008
Close Date: 04/08/2008

Meter Reading: 5,499.00

Problem?

ON CALL E19 NOT CHARGING

Task performed:

1. CHECK OUT CHARGING SYSTEM PROBLEM-REPAIR WIRING TO WALDON VOLTAGE AND AMP MONITORING SYSTEM AND REPLACE BAD ALTERNATOR.

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR

1

Workorder: V14376

In Date: 04/09/2008
Close Date: 04/15/2008

Meter Reading: 3,595.00

Problem?

Right Rear Overhead emergency warning light loose. Spins freely. Unable to tighten. e19

Task performed:

1. r/r overhead emergency light assy/loose/tighten light assy.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V14414

In Date: 04/11/2008
Close Date: 04/23/2008

Meter Reading: 3,596.00

Problem?

FRONT GRILL DRIVER SIDE RED LED LIGHT VERY DULL AND HARD TO SEE WHEN TURNED ON IN CODE 3, OFFICER SI INTAKE DRAIN KNOB BROKE OFF/UNTHREADED. REAR HYDRANT WRENCH BROKEN. e19

Task performed:

1. BAD GROUND FOR LIGHT, REPLACE KNOB.

Parts

Quantity

012-0010-00KNOB DRAIN	2
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	1

Workorder: V14434

In Date: 04/13/2008
Close Date: 04/23/2008

Meter Reading: 3,603.00

Problem?

E19 is consuming oil ????

Task performed:

1. TOLD CAPT. AND LT. DRIVE IT,IF NEED OIL I WILL PUT IN.

Parts

Quantity

NO PARTS USED

Workorder: V14635

In Date: 04/23/2008
Close Date: 04/28/2008

Meter Reading: 3,624.90

Problem?

RELIEF VALVE IS NOT WORKING PROPERLY e19

Task performed:

1. drove to sta. and replaced relief valve and screen.tested pump-ok

Parts

Quantity

538-0201-02-OQG RELIEF VALVE COMPLETE	1
---------------------------------------	---

Workorder: V14729

In Date: 04/28/2008
Close Date: 05/05/2008

Meter Reading: 3,624.90

Problem?

LED warning light on vehicle's front left grill out. Very low to no visibility. e19

Task performed:

1. remove connetor and hard wire in-test ok

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V14825

In Date: 05/02/2008
Close Date: 05/23/2008

Meter Reading: 56,149.00

Problem?

deck gun valve wont open e19

Task performed:

1. Drive to Station 19, grease valve for deck gun, tested
- OK

Parts

Quantity

200226200200-2262-50 SWITCH-PROXIMITY QG VALVE
3530016HOSE HURST 16 ORANGE

1
1

Workorder: V15292

In Date: 05/23/2008
Close Date: 06/09/2008

Meter Reading: 3,689.00

Problem?

Bracket on the bottom of the driver mirror is broken E19

Task performed:

Make bracket; installed. j

Parts

Quantity

NO PARTS USED

Workorder: V15313

In Date: 05/24/2008
Close Date: 06/09/2008

Meter Reading: 3,689.00

Problem?

RELIEF VALVE ACTUATION LIGHT NOT WORKING. BULB CHECKED, GOOD. DECK GUN LEVER CANNOT BE OPENED FUI
UNLESS A DISCHARGE VALVE OPENED.E19

Task performed:

Adj sender; test ok. j

Parts

Quantity

NO PARTS USED

Workorder: V15454

In Date: 06/02/2008
Close Date: 06/09/2008

Meter Reading: 57,027.00

Problem?

ON CALL E19 # 3 DISCHARGE LINKAGE BROKE

Task performed:

Drive to Stn19; reinstall linkage on discharge #3.
j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V15347

In Date: 05/27/2008
Close Date: 06/13/2008

Meter Reading: 3,689.00

Problem?

The latch that holds the hurst spreader in place is broken and the spreader is moving around freely in the compartment. e19

Task performed:

Drive to Stn; rep strap; test ok. j

Parts

T69-15.5 STRAP FOR TOOL HOLDER

Quantity

3

Workorder: V14883

In Date: 05/06/2008
Close Date: 06/17/2008

Meter Reading: 56,298.00

Problem?

repair fitting on hurst ram e19

Task performed:

1. check ram fittings wont release, lossen fittings to release hydrolock
2. drive to sta. hook up ram tested ok. bring spare to shop.

Parts

R134AFREON LB

Quantity

3

Workorder: V15197

In Date: 05/19/2008
Close Date: 06/18/2008

Meter Reading: 3,944.60

Problem?

E19 pressure relief valve - needs replacing

Task performed:

1. Rrebuild releif valve to put on service truck. Walther
2. Drive to Stn; installed rebuilt control valve in pump panel test ok.
Lehan

Parts

0100080010STRAINER

519007110SLIDE CONTROL 519-0071-10

562008002PM CONTROL 562-0080-02

Quantity

1

1

1

Workorder: V16052

In Date: 06/30/2008
Close Date: 07/10/2008

Meter Reading: 3,740.00

Problem?

Having problems with siren. Siren does not work from the steering wheel. E19

Task performed:

1. drive to station r / r siren head test = ok

Parts

WS-295HFSM1USE 295SLSA1 SIREN

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V16219

In Date: 07/08/2008
Close Date: 07/18/2008

Meter Reading: 3,768.00

Problem?

Passenger side telescoping quartz lights is missing 1 of 4 screws e19

Task performed:

Drive to Stn; installed screws; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V16615

In Date: 07/27/2008
Close Date: 07/31/2008

Meter Reading: 3,813.40

Problem?

deck gun takes 3 men and a baby to open E-19

Task performed:

1. Look at valves & talk w/Ed O. about it.
 2. Chk out unit; needs Akron valve; installed on rear
- j

Parts

NO PARTS USED

Quantity

Workorder: V16564

In Date: 07/24/2008
Close Date: 08/01/2008

Meter Reading: 3,806.50

Problem?

led lights passenger side engine 19

Task performed:

1. drive to station. r/r lite tested all ok

Parts

50R03ZCRLIGHT LED RED TIR 6
HLD3999GSS1715UV 30LB STRUT GAS

Quantity

1
2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V16834

In Date: 08/05/2008

Meter Reading: 58,669.10

Close Date: 08/28/2008

Problem?

C inspection and related repairs E19 (replace deck gun and r/r discharge valves with Akron)

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

C-Inspection	038-1550-00VALVE CHECK HALE 1/4"	1
2. Rem oil pan & replc pan gasket; install pan; also fab a longer road draft tube.	05-17223-000CAP RADIATOR 10 LB	1
3. Svc trans.	082-2007-00-0GREASE ZERK W/CHECK VLV	1
4. Svc air dryer.	107796DRYER KIT AD9 -NEW	1
5. Replc front wheel bearing hub plugs.	107800VALVE CHECK AD9	1
6. Svc P.S sys.	17210ZE6505FILTER AIR HONDA	1
7. Replc wiper blades.	18-29935-001RH DOOR LATCH NEW	1
8. Rep washers.	203FFBEARING PULLEY	1
9. replc eng coolant filter hsng; assemble new hsng asy & reinstall on eng.	25-358SWITCH COVER	2
10. Drivers door hard to opn; realign door striker pin.	2952271729552377 VALVE ASSY.ACCUM	1
11. Replc all eng drive belts.	29526898 29548988 TRANS FILTER ALLISON	1
12. Replc (3) cab door weather strips(lower)	29535973ACCUM.KIT	1
13. Rem trans retarder accum from top of trans; rebuild on bench; install new control valve; assemble & reinstall in veh.	35200-RLIGHT MARKER LED RED	1
14. replc all (4) cab door window trim.	3818885O-RING WATER SHUT OFF	2
15. Free up slide draws for btrys & trash line; (binding up badly); rep latch assemb on trash line draw.	3934044 3938160 OIL PAN C GASKET	1
16. Replc L/R corner marker light.	39437384940575 HEAD CORROSION RESISTER	1
17. Rep broken wire inside L/R cab door for inside light; rem panel, etc.	39437394940547 SHAFT SHUT-OFF VALVE	1
18. Failed bat test; replc all btrys; cln out bat acid residue from containment box & hold down bracket.	3943740SHAFT SHUT-OFF VALVE	1
19. Replc leaking fitting from pum discharge port.	39438574989614 SEAL O-RING SHUT-OFF VALVE	1
20. Replc rear A/C intake filter.	3944718BRACKET - A/C COMP	1
21. Svc gen set.	450434450434 PLUG OIL HUB	2
22. Svc hurst tool equipment	52-24WIPER BLADES ANCO 24	2
23. Replc (8) door holdopen - gas pistons; rep (2) piston mount brkts.	532703-0602 COMPRESSOR U4735 4471	1
24. Retorque all front/rear u-bolts.	5499FRE801910 REPAIR BRACKET A/C COMPRESSOR	1
25. Replc front suction intake screen; mod slightly to fit hsng.	6805450124SWITCH TURN SIGNAL	1
26. Slide pull to right; rotate frnt tires from side to side.	6806970098SEAL DOOR	1
27. Assist Larson w/tire rotation.	6807200575HANDLE DOOR	2
28. Svc T- case.	6808300074VENT A/C LH	1
29. Rem trashline drain valve from pump panel; replc bad fitting in valve & reinstall in panel.	716907-0610A DRYER	1
30. Pull out all grnd ladders & replc all out dated heat sensors.	7460967AIR FILTER 17210-ZE2-515 HONDA	1
31. Replc damaged turn signal switch; doesn't cancel from right turns.	78R536078R5360M 2PK FILTER AIR COND	1
32. Replc burnt out bulb from rear lic plate light.	800405PURGE VALVE KIT	1
33. Replc r/center A/C dash vent.	8113-483IN SS NIPPLE	1
34. Replc fan grille in cab center console.	883088301201 3 IN SLO-CLOZ W/R1 HANDLE	2
35. Replc L/R door latch (bent).	A1834388002MOLD L/H	2
36. Replc (2) front seat belts; had to find missing spacers from R/F seat belt.	A1834388003MOLD R/H	2
37. Drain out entire foam sys; (foam mixed & jelled); diss foam components & flush entire sys; reassemble & refill foam sys.	A22-41331-048A/C HOSE	2
38. Set up veh on stand & rem L/R outer tire; find a good used tire from Bldg 3 & bring over to shop; have	A2241332074A22-41332-074 HOSE ASSY.	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	BPR5ESSPARK PLUG 7734	1
	BPR6ESSPARK PLUG 7131	1
	CA8193AIR FILTER 46744 WIX	1
	EAA-8350-30UGSS1783UQ STRUT-LIFT	8
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- Callaghan change out tires & rei nstll on veh.
- 39. Svc coolant sys.
- 40. Pump panel trans temp gauge inop; trace down problem in wiring & rep.
- 41. Assist Larson w/rep on gauge problem.
- 42. Replc torn pump panel; horn/tank level test push buttons covers.
- 43. Rem/rollup all hose from crosslays; rep bracket support for deck gun plumbing pipe support.
- 44. Assist Larson w/deck gun bracket rep.
- 45. Rem Hale S valves for deck gun & rear discharge; on deck gun a special flange has to be installed in order to install Akron valve; hadles have to be redrilled; SLO-CL02 assemb have to be installed; rods cut & rethreaded; install (2) new Akron valves.
- 46. Assist Larson w/Akron valve installation.
- 47. Vac test would not pull & hold; fnd chk valve to take stuck open; replc valve asy; retest; now hold vac.
- 48. Pull steering wheel & recenter. j

FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
IMMF11358SEAT BELTS	3
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
SPR-W58-1TEE PLASTIC	1
TRANSYNDALLISON TRANS FLUID GAL	6
WAT61403STRAINER 6 IN	1

Workorder: V17293

In Date: 08/25/2008 Meter Reading: 58,669.10
 Close Date: 09/16/2008

Problem?
 REPLACE TIRE E19

Task performed:	Parts	Quantity
replace tire at shop callaghan	NO PARTS USED	

Vendor?: CALLAGHAN ENT

Workorder: V17361

In Date: 08/27/2008 Meter Reading: 58,669.10
 Close Date: 09/16/2008

Problem?
 replace hose bed cover e 19

Task performed:	Parts	Quantity
REPLACED HOSE BED COVER CENTRAL AUTO TRIM	NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V17737

In Date: 09/16/2008 Meter Reading: 59,548.60
Close Date: 09/29/2008

Problem?

door ajar sensor needs repair- hose reel compartment door E19

Task performed:	Parts	Quantity
1 DRIVE TO STA REPLACE DOOR SWITCH	52-624SWITCH DOOR	1

Workorder: V17531

In Date: 09/06/2008 Meter Reading: 3,813.40
Close Date: 09/30/2008

Problem?

Quartz light bulb out on right telescoping flood light. 1 bulb still working, 1 out. E19

Task performed:	Parts	Quantity
Install quartz light at station 19.	LB-D30BULB QUARTZ HAL. 12V 150W	1

Workorder: V17650

In Date: 09/11/2008 Meter Reading: 3,813.40
Close Date: 09/30/2008

Problem?

The front warning lights are not working. I had another driver check to make sure it was not working properly. He confirmed front warning lights are out. e19

Task performed:	Parts	Quantity
install and program node #1, test OK.	600000003NODE HERCULES V-MUX	1

Workorder: V18047

In Date: 09/30/2008 Meter Reading: 59,985.00
Close Date: 10/17/2008

Problem?

repair seats r19 cetral auto trim

Task performed:	Parts	Quantity
Repair seats R19 - Central Auto Trim j	NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V15580

In Date: 06/06/2008
Close Date: 10/21/2008

Meter Reading: 3,707.00

Problem?

Problem drafting from front large diameter intake. Side steamers will pull draft with no problem. Spoke to Eddie Uhrke and explain problem. e19

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V18204

In Date: 10/08/2008
Close Date: 10/21/2008

Meter Reading: 60,084.40

Problem?

REPAIR A/C E19

Task performed:

Parts

Quantity

1-Drive to sta, High pressure switch has bad connection,
repair top off freon testok.

ABPN8332229011-3050 SWITCH BLOWER

1

RCB BOXBOX/COVER FOR RCB3000

1

RCB-3000CONTROL BOARD USE WITH CM3000

1

Workorder: V18319

In Date: 10/14/2008
Close Date: 10/24/2008

Meter Reading: 60,084.40

Problem?

on call e19 scene lts 10-7

Task performed:

Parts

Quantity

Night lighters inop; chkd opn-working ok; chkd wiring-night lighters working ok. j

NO PARTS USED

Workorder: V18680

In Date: 10/29/2008
Close Date: 11/05/2008

Meter Reading: 60,084.40

Problem?

PUMP WILL NOT GO INTO GEAR, E-19

Task performed:

Parts

Quantity

drive to Stn; replace both T-Case switches; test ok.

200-2450-00NC SWITCH OK TO PUMP

2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V18914

In Date: 11/07/2008
Close Date: 11/19/2008

Meter Reading: 3,948.00

Problem?

air tank resevoir line came undone. needs reattaching E-19

Task performed:

Drive to Training; rep line; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V19260

In Date: 11/21/2008
Close Date: 11/26/2008

Meter Reading: 61,916.60

Problem?

won't start E19

Task performed:

Drive to stn; replc btry; test charging sys-ok. j

Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY
HP-31DBATTERY 950CCA HP-31D

Quantity

4
4

Workorder: V19271

In Date: 11/22/2008
Close Date: 12/02/2008

Meter Reading: 3,970.40

Problem?

The step light on the driver side is out. This light is located under the driver door, under the step. Found during morning check. All other lights did come on when doors were open except, driver door. E19

Task performed:

Drive to Stn; fnd bad grnd; rework; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V20035

In Date: 12/30/2008
Close Date: 01/06/2009

Meter Reading: 4,024.00

Problem?

Quartz bulb out on telescopic light, driver's side. e19

Task performed:

Drive to stn; replcd bulb for quartz light; test ok. j

Parts

LB-D30BULB QUARTZ HAL. 12V 150W

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V20279

In Date: 01/11/2009

Meter Reading: 4,024.00

Close Date: 02/04/2009

Problem?

Far left roof light out. Small orange light on left side of engine roof. E-19

Task performed:

1- drive to station, clean connection for roof lite, test ok.
bad ground rework r=test ok.

Parts

NO PARTS USED

Quantity

Workorder: V20515

In Date: 01/22/2009

Meter Reading: 63,848.00

Close Date: 02/11/2009

Problem?

MOUNT EQUIPMENT, E-19

Task performed:

1-Drive to training, mount fire exhuster and scba bottle.

Parts

ABM-1BASE MOUNT ALUMINUM
SAHSVS2510STRAP
UMVS111611STRAP
UMVS162511STRAP

Quantity

2
2
2
2

Workorder: V20589

In Date: 01/26/2009

Meter Reading: 63,848.00

Close Date: 02/11/2009

Problem?

REPLACE BATTERY, E-19

Task performed:

1- Call out for battery (dead). Installed new battery, nned charger installed.
2- be stock service truck with battery equipment.

Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY
HP-31DBATTERY 950CCA HP-31D

Quantity

4
4

Workorder: V20536

In Date: 01/22/2009

Meter Reading: 63,848.00

Close Date: 02/12/2009

Problem?

INSTALL BATTERY CHARGER AND AUTO-EJECT, E-19

Task performed:

1- Drive to sta. mount auto injector and battery charger in truck.
2- Drive to sta. finished installing batterty charger.
3- mount charger, make and install wiring harness, wire all conectionsck ok.

Parts

0913912CHARGER 2000
0915520120AUTO EJECT 20 AERO OTL3925

Quantity

1
1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V20389

In Date: 01/15/2009
Close Date: 02/19/2009

Meter Reading: 63,076.10

Problem?

need 6 spare chains for chain saws in Battalion 1 (outside agency-Regan's small engine service)

Task performed:

Need (6) spare chains for chain saws in Batt1 - Regans
Small Eng j

Vendor?: REGANS SMALL ENG

Parts

Quantity

NO PARTS USED

Workorder: V20777

In Date: 02/02/2009
Close Date: 02/24/2009

Meter Reading: 4,064.50

Problem?

drivers side ff seat back is loose , missing fasteners. E-19

Task performed:

Tighten bolts; test ok. j

Parts

Quantity

NO PARTS USED

Workorder: V21138

In Date: 02/17/2009
Close Date: 02/24/2009

Meter Reading: 4,491.10

Problem?

Driver side LED not working. E-19

Task performed:

Drive to stn; replc (2) lights; test ok. j

Parts

Quantity

60R00FRR600 SERIES RED LED W/O FLANGE

3

Workorder: V21303

In Date: 02/24/2009
Close Date: 02/25/2009

Meter Reading: 64,604.20

Problem?

unit rolled out of bay on call r19

Task performed:

Chkd damage & brakes; left truck in svc; made minor
rep to body. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V19861

In Date: 12/19/2008
Close Date: 03/02/2009

Meter Reading: 3,987.00

Problem?

Need to have the E-19 sign mounted on back of truck.

Task performed:

Drive to Stn; mount sign on rear of truck & mount equipt in compt. j

Parts

Quantity

NO PARTS USED

Workorder: V21325

In Date: 02/24/2009
Close Date: 03/02/2009

Meter Reading: 4,491.10

Problem?

Install new your hook to side of truck. e19

Task performed:

drive to Stn; installed hook on end & mount equipmnt in compt. j

Parts

Quantity

NO PARTS USED

Workorder: V21959

In Date: 03/20/2009
Close Date: 03/25/2009

Meter Reading: 66,534.30

Problem?

medical compartment won't open E19

Task performed:

1. Corrected tickets to go on road repairs; also picked up parts.
2. Rod that opens door was disconnected; rep rod connections to door lock bar at Stn19. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V21914

In Date: 03/18/2009
Close Date: 04/03/2009

Meter Reading: 66,034.90

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 19

Task performed:

1. B-Inspection
2. U-bolts on rear axle loose; torqued bolts; still loose; rem all nuts/u-bolts; rem press from spring to rem spring separators that were sticking out; replcd all u-bolts; torque bolts.
3. Ck for coolant leak; press test sys; fnd air compressor coolant line fittings leaking; drained coolant; rem fuel filter , oil sender, tines & fittings; R/R seal grommets; reinstalled all parts; filled rad; ck ok.
4. Ck for slow pump opn; rem/replcd both screw strainers; ck opn; ck ok.
5. Complete paperwork/inventory from weekend on-call.
6. Replcd TIC charger
7. Replcd left/right flag stickers on rear of body. j

Parts	Quantity
0100080010STRAINER	2
108-12FBEADED CHAIN W/CONN 12	3
15W40BSYN OIL BULK QTS	24
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
8T7842U BOLT	4
A12-17442-000BRAKE LINE	1
DN78NUT	8
FREIGHTSHIPPING CHARGES	3
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	2
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
S1003-A3103015 SEAL	2
SUW78WASHER	8

Workorder: V22058

In Date: 03/24/2009
Close Date: 04/13/2009

Meter Reading: 66,534.30

Problem?

REPLACE 3 REAR TIRES, THERE WAS A NEW ONE ON R/REAR OUTSIDE E-19

Task performed:

- Replace (3) rear tires; there was a new one on R/rear outside e19 - Callaghan j
Vendor?: CALLAGHAN

Parts	Quantity
NO PARTS USED	

Workorder: V22081

In Date: 03/25/2009
Close Date: 04/13/2009

Meter Reading: 66,534.30

Problem?

replace front tires at s shop r46 callaghan

Task performed:

- Replace front tire at S. shop R46 - Callaghan j
Vendor?: CALLAGHAN

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V22145

In Date: 03/27/2009 Meter Reading: 66,534.30
Close Date: 04/13/2009

Problem?

replace hose bed cover e19 central auto trim

Task performed:	Parts	Quantity
Replace hose bed cover E19 - Central Auto j	NO PARTS USED	

Vendor?: CENTRAL AUTO

Workorder: V21494

In Date: 03/03/2009 Meter Reading: 65,364.30
Close Date: 04/14/2009

Problem?

repair flat tire e 19

Task performed:	Parts	Quantity
Repari flat tire E19 - Callaghan j	NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V22741

In Date: 04/22/2009 Meter Reading: 66,877.00
Close Date: 05/04/2009

Problem?

REPAIR STRETCHER LOCK R19

Task performed:	Parts	Quantity
Drive to Stn; installed lock; adj; test ok. j	090-0278STRECHER BAR NEW	1

Workorder: V22013

In Date: 03/23/2009 Meter Reading: 4,088.00
Close Date: 05/12/2009

Problem?

PINS FOR TIC RECHARGABLE BATTERY NEED REPAIR e19

Task performed:	Parts	Quantity
Replcd TIC charger on WO 21914 j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V22867

In Date: 04/28/2009 Meter Reading: 4,089.00
Close Date: 05/12/2009

Problem?

Need the map light replaced. E-19

Task performed:

Drive to Stn; replc maplight; test ok. j

Parts

Quantity

LF18TS-LEDMAP LIGHT LED 18 IN

1

Workorder: V23209

In Date: 05/11/2009 Meter Reading: 4,095.20
Close Date: 05/19/2009

Problem?

Right rear marker light and the rear A/C vent in the rear of the cab. e19

Task performed:

Replc vent. j

Parts

Quantity

35200-RLIGHT MARKER LED RED

1

372000084MARKER LIGHT

1

72R31001720 DIFFUSER A/C 3.5 IN

1

Workorder: V23433

In Date: 05/21/2009 Meter Reading: 68,242.00
Close Date: 06/15/2009

Problem?

REPLACE TIP ON EXHAUST R19

Task performed:

Drive to Stn; replcd parts; test oki. j

Parts

Quantity

29206CHROME STACK 24 IN 4 IN

1

33961C35976 MUFFLER CLAMP

1

Workorder: V23956

In Date: 06/09/2009 Meter Reading: 68,836.00
Close Date: 06/19/2009

Problem?

belt loose on e19

Task performed:

drive to Stn; tighten both belts; test frive ok. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V24171

In Date: 06/17/2009
Close Date: 06/23/2009

Meter Reading: 68,836.00

Problem?

repair patient lts r19

Task performed:

Chk pat area lights; fnd loose bul in light. j

Parts

NO PARTS USED

Quantity

Workorder: V24155

In Date: 06/17/2009
Close Date: 06/24/2009

Meter Reading: 4,128.20

Problem?

the rear 2.5 in nozzle holder, that hold the gate valve is broken. It only has two pins e19

Task performed:

Chk hodler opn; brkn; order parts. j

Parts

373-2.5E-Z LOK BRACKET

Quantity

1

Workorder: V24258

In Date: 06/22/2009
Close Date: 07/01/2009

Meter Reading: 4,140.60

Problem?

Engine 19 not passing vaccum test.

Task performed:

Drive to Stn; rebuild discharge valve #3; test ok. j

Parts

5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0

Quantity

1

Workorder: V24149

In Date: 06/17/2009
Close Date: 07/02/2009

Meter Reading: 4,128.20

Problem?

The front suction will not hold or pull a draft. The side suction will pull a draft and hold a good vacuum e19

Task performed:

Drive to Stn; replcd chk valve; test ok. j

Parts

038-1550-00VALVE CHECK HALE 1/4"

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V24344

In Date: 06/25/2009
Close Date: 07/08/2009

Meter Reading: 4,140.60

Problem?

Battery minder indicates a bad battery E19

Task performed:

Drive to Stn; installed new display; test btry sys; test ok.
j

Parts

Quantity

091-39-INDAUTO CHARGER INDICATOR

1

Workorder: V24718

In Date: 07/13/2009
Close Date: 07/15/2009

Meter Reading: 69,154.90

Problem?

UNIT OVERHEATING R19

Task performed:

Chkd unit; fnd quick connect for air live to fan clutch
brn; R/R connec tor ok. j

Parts

Quantity

NO PARTS USED

Workorder: V24510

In Date: 07/01/2009
Close Date: 07/17/2009

Meter Reading: 69,154.90

Problem?

replace gate valve e19

Task performed:

Swapout fitting connections on gate wye connections.
j

Parts

Quantity

NO PARTS USED

Workorder: V24756

In Date: 07/14/2009
Close Date: 07/22/2009

Meter Reading: 69,154.90

Problem?

COOLANT LEAK E 19

Task performed:

Drive to Stn; press chk; tighten hose clamp; filled; test
ok. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V25618

In Date: 08/18/2009
Close Date: 08/26/2009

Meter Reading: 4,175.00

Problem?

Tires need to be replaced. Getting down to the wear bars. E19 TIRE SOLES

Task performed:

tires need to be replace - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLES

Workorder: V25814

In Date: 08/27/2009
Close Date: 09/01/2009

Meter Reading: 71,181.50

Problem?

check vehicle-involved in accident E19

Task performed:

Drive to accident to see truck; out of svc; brkn axle bolt left rear wheel. j

Parts

NO PARTS USED

Quantity

Workorder: V25841

In Date: 08/28/2009
Close Date: 09/01/2009

Meter Reading: 71,181.50

Problem?

check and repair accident damage as needed E19

Task performed:

C/O accident damage; chkd underside of truck u-bolts, spring, shocks; C/O wheels/tires; rem axle & inspected; extracted brkn axle flange stud & replc w/new; ckd hub asy; topped off fluid; filled truck w/water & road tested.

Parts

23-09114-010WASHER
401581GASKET AXLE FL80 R002435
ACX-84534LUG NUT COVER PK10
R005960AXLE WEDGE SOLID

Quantity

1
1
4
1

Workorder: V25847

In Date: 08/28/2009
Close Date: 09/03/2009

Meter Reading: 71,181.50

Problem?

will not draft with front suction E19

Task performed:

Drive to Stn; go to where they draft using front suction & work w/driver; test ok. j

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25982

In Date: 09/02/2009

Meter Reading: 4,175.70

Close Date: 09/16/2009

Problem?

Need oil for E-19 in station supply.

Task performed:

drive to Stn; chk eng; fill (2) qt oil. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V26196

In Date: 09/11/2009

Meter Reading: 4,175.70

Close Date: 09/30/2009

Problem?

draind for #2, 3, and 4 discharges leak e19

Task performed:

drive to Stn; rebuild valves; test ok. j

Parts

040214003O-RING SEAL

040218000O-RING

Quantity

6

3

Workorder: V26251

In Date: 09/14/2009

Meter Reading: 4,175.70

Close Date: 09/30/2009

Problem?

Front left strobe on grill not working. LED flasher in between the cab doors on Officers side not flashing. The foam system is actin; up. Will not stay on. Turns on and off. e19

Task performed:

1. drive to Stn; replc lights on hood; test ok.
2. Chk foam sys; tightene both pos/neg wires; test ok.

j

Parts

60R00FRR600 SERIES RED LED W/O FLANGE

Quantity

1

Workorder: V26441

In Date: 09/24/2009

Meter Reading: 4,175.70

Close Date: 10/06/2009

Problem?

Emergency light on grill not working. E19

Task performed:

Drive to Stn; fnd bad grnd; rework; test ok. j

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V26338

In Date: 09/20/2009
Close Date: 10/07/2009

Meter Reading: 4,175.70

Problem?

Hose Reel will not retract hose automatically. The button won't work. so19

Task performed:

drive to Stn; chk relay power button wires; back trace wiring-fnd brkn where motorcycles rolled under truck; rep; test ok. j

Parts

M-608SWITCH

Quantity

1

Workorder: V24730

In Date: 07/13/2009
Close Date: 10/16/2009

Meter Reading: 69,154.90

Problem?

replace tires at shop r19 callaghan never billed, no record at Callaghan...per NB 10.16.09 closed

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V27026

In Date: 10/20/2009
Close Date: 10/28/2009

Meter Reading: 73,456.90

Problem?

Engine low on oil. e19

Task performed:

drive to Stn; chk oil in eng & chk for leaks; talk w/driver about no leaks; test ok. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V26776

In Date: 10/08/2009
Close Date: 11/12/2009

Meter Reading: 4,175.20

Problem?

Strobe light on officer side of cab between doors is on while emergency lights are on but does not flash. e19

Task performed:

Replcd LED light on R/side of truck. j

Parts

50R03ZCRLIGHT LED RED TIR 6

Quantity

2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27459

In Date: 11/05/2009

Meter Reading: 73,456.90

Close Date: 11/16/2009

Problem?

replace hose bed cover e19

Task performed:

Parts

Quantity

Replc hose bed cover E19 -Central Auto j

NO PARTS USED

Vendor?: CENTRAL AUTO

Workorder: V26777

In Date: 10/08/2009

Meter Reading: 4,175.20

Close Date: 11/23/2009

Problem?

Engine hour meter does not work. e19

Task performed:

Parts

Quantity

1. Rebuild Hale drain valve mstker.
2. Rebuild dryer, chk, purge, filter.
3. Rem/rebuild primer pump handle; side pump panel; R/R upper primer handle & rebuild.
4. R/R hour meter per Mike Lehan; didn/t work; chk out sys; fnd bad oil press switch; replc/test; old hour meter gone in trash. j

8534203HRS METER 85342-03

1

Workorder: V27061

In Date: 10/21/2009

Meter Reading: 4,175.20

Close Date: 11/23/2009

Problem?

During a fire last nite, foam was not being produced 50% of the time. e19

Task performed:

Parts

Quantity

1. C/O foam sys; chk wiring, connections, etc.; replc injection valve; retest, flush water tank etc.; cal foam sys
2. R/R 3" chk valve per Ed Ehrke; retest. j

NO PARTS USED

Workorder: V27595

In Date: 11/12/2009

Meter Reading: 73,798.10

Close Date: 11/23/2009

Problem?

REPLACE HOLD DOWN STRAP R19

Task performed:

Parts

Quantity

R/R hold downs. j

UMVS-0811-11STRAP ZICO

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V27030

In Date: 10/20/2009

Meter Reading: 73,456.90

Close Date: 11/24/2009

Problem?

c inspection and repairs as needed E19

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- C-Inspection
2. Low voltage - E11 test.
3. R/R heat sensors; rem old ones; cln laddeer off; reapply sensors.
4. Svc small eqmpt, gen, Hurst; R/R Hurst hoses; swap out ram; cldnt free up handles; swapout power unit not pump to spec.
5. Tightened up SCBA doors.
6. C/O ____ sys; rear hose reel door; fnd brkn connection swth; R/R swtch; install new sckt & wire; tightene latch for door; adj door swtch.
7. Remnt hose clamp on back door; tighten & lock tite bolts on clamp/brkt.
8. R/R T-case frnt seal & gskt.
9. Make up new tank cable for pump panels.
10. Svc T-case.
11. Charge out gear lube tank; try to get pump working, wont pump; stuck; tell Scott to have fixed.
12. R/R reflectors.
13. Reroute wiring; strap up out of tac way was cutting on rear frame.
14. Install wrap on hose getting cut by fuel tank brkt.
15. Extend A/C drain lines on rear A/C unit.
16. R/R brkn handle unit for tank to pump valve.
17. R/R alt.
18. R/R belts & ten.
19. R/R A/C vent pass side.
20. R/R discharge gauge; rep hosees.
21. R/R door moldings & reinstalled door panels.
22. Remnt door shock in L2 compt.
23. Remnt/drill shelf in L2 compt; remnt new brkts.
24. R/R steering wheel.
25. Defrosters inop; pull dash; adj blend doors; lube linkage; replc gskts.
26. Change out chk valve on sensing valve; retest; still failed dry vac; pull intake relief valve; rebuild; R/R sensing valve; retest; replc leaking fittings.
27. Pull off #1 dis valve, #4 cln up lube etc.; grease valves; instake & dis.
28. Press relief valve lts not working; ck wiring; ckt open to grnd; chase down wiring; call Hale for wiring sch; fnd intake relief valve swtch was wrng; replc ____.
29. C/O water leak; Hale valve leaking; tighten up flange; fnd grease fitting leaking water; replc fitting.
30. R/R foam fill swtch boot; remnt swtch-not tight.
31. Cln/paint fuel cap.
32. Replc axe brkt in L1 compt.
33. R/R heater cable on A/C unit; reinstall dash/adj cable.
34. C/O noise in dash when in pump; fnd alarm when fuel reading goes to pump panel; computer picks up no fuel sign.
35. R/R night light hook.
36. C/O relief valve; says works slow; work unit cldnt find

038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
0381570000038-1570-06-0 VALVE CHECK 3 IN 9003-1	1
042-0091-00SPRING PRIMER	2
042002000SPRING RELIEF VALVE HALE	1
0460050000GASKET	2
0465130010GASKET GEARBOX COVER	1
073004100PISTON	2
082-2007-00-0GREASE ZERK W/CHECK VLV	1
104967DIAPHRAM FOR 6 PORT DUMP VALVE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1280008CONNECTOR SET	1
15W40BSYN OIL BULK QTS	28
1893BULB	1
22-49905-000CABLE HEATER	1
2962540000SEAL SAME AS 29867 C/R	1
3530033USE 353R222 HOSE HURST SWIVEL/ORING	2
4867JB320 UPGRADE ALTERNATOR	1
52-624SWITCH DOOR	1
538-1410-00VALVE SENSING SV HALE	1
546085303NC SWITCH/BRACKT	1
546126000TPM/QG HALE REPAIR KIT	1
6804640001NEW# 3184640001 STEERING WHEEL	1
6806890001LOCK DASH	2
6808300174VENT A/C RH	1
6808310398SEAL AIR DUCT	1
76052-15-NO76052-15-NO SWITCH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
8126482-2106 TOGGLE GUARD	1
91553943GUAGE	1
9440BELT	1
9480BELT	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
B480AREFLECT-AMBER	1
CA8193AIR FILTER 46744 WIX	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HA24063HOOK WHEELED COACH	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PGL/22019CPIN TURN SIGNAL STEERING WHEEL	1
PR338324070 WIX FILTER WATER	1
PVG-KITORING KIT	2



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

a problem. j

R90PFILTER FUEL 33231

1

RC-4101 AKRON SHORT HANDLED VALVE REMOTE

1

Workorder: V28264

In Date: 12/11/2009

Meter Reading: 73,895.20

Close Date: 12/21/2009

Problem?

nite fighter light out E19

Task performed:

Replcd night fighter spotlight bulb. j

Parts

Quantity

4007BULB NIGHT FIGHTER

1

Workorder: V28513

In Date: 12/21/2009

Meter Reading: 4,262.20

Close Date: 01/05/2010

Problem?

NEED BOTTLE OF COLLANT FOR STATION sta19

Task performed:

Chkd coolant level; brought extra gallon for stn; no leaks
fnd. j

Parts

Quantity

ALA00350-50 EXTENDED LIFE COOLANT GAL

1

Workorder: V28663

In Date: 12/29/2009

Meter Reading: 75,269.00

Close Date: 01/06/2010

Problem?

Diver complaint brakes not working properley

Task performed:

Went 19; fnd press swtch behind dash leaking air; replc
swtch & test drove; no air leaking in cab now. j

Parts

Quantity

NO PARTS USED

Workorder: V28677

In Date: 12/29/2009

Meter Reading: 5,157.80

Close Date: 01/26/2010

Problem?

Front Left turning light is not working properly e19

Task performed:

Chk/installed 1156 light; working at this time. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V28738

In Date: 01/01/2010
Close Date: 01/28/2010

Meter Reading: 75,725.20

Problem?

E19 left front turn signal wire loose and causes turn signal to not work E19

Task performed:

- Needs new harness & lite asy; it works now for the time being.
- Replc defective L/F t-signal asy. j

Parts	Quantity
6808200020LIGHT ASSY. TURN SIGNAL	1

Workorder: V29838

In Date: 02/09/2010
Close Date: 03/02/2010

Meter Reading: 76,955.90

Problem?

check engine light on -unknown cause-reported to shop E19

Task performed:

- Went to Stn19; ck eng light on; plugged in laptop; fnd eng speed/pos sensor bad; R/R sensors; only (1) on svc trk; w/for another sensor; ran; cleared codes; ck ok.
j

Parts	Quantity
4921597OUTBOARD SPEED SENSOR	2

Workorder: V29840

In Date: 02/09/2010
Close Date: 03/02/2010

Meter Reading: 76,955.90

Problem?

One of the passenger tower flood lights are out. needs replacing E19

Task performed:

- Fnd R/tower light out; diss light; R/R bulb; ck ok.
j

Parts	Quantity
LB-D30BULB QUARTZ HAL. 12V 150W	1

Workorder: V30347

In Date: 03/01/2010
Close Date: 04/20/2010

Meter Reading: 77,246.70

Problem?

ROOF SPOT LIGHT NEEDS ATTENTION. NOT POSITIONING CORRECTLY. E19

Task performed:

- Chk roof spotlight lens cvr incorrect; not hitting movable lite asy; lite moves left/right up/down; NPF. j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V30699

In Date: 03/12/2010
Close Date: 04/20/2010

Meter Reading: 77,246.70

Problem?

DOOR AJAR SENSOR AND BUZZER MALFUNCTIONING - SHOWS DRIVER ENGINEER COMPARTMENT.E ?R ?SO ? 19

Task performed:

Parts

Quantity

1. Fnd lite/buzzer operate even when parking brake is applied; rem dash & parking brake valve frm frame; rem wires frm switch & chkd press switch-ok; reinstall dash.
2. Mnt rear line nozzle & (1) easy lock on tailboard. j

NO PARTS USED

Workorder: V30748

In Date: 03/15/2010
Close Date: 04/22/2010

Meter Reading: 4,175.00

Problem?

repair engine(check engine lt. on) E19 (outside agency-fla. detroit diesel)

Task performed:

Parts

Quantity

Repair engine - Florida Detroit Diesel j

NO PARTS USED

Vendor?: FLORIDA DETROIT

Workorder: V31584

In Date: 04/16/2010
Close Date: 04/29/2010

Meter Reading: 77,246.70

Problem?

on call se at 14 siren soaker fell out

Task performed:

Parts

Quantity

RF siren skr fell out; replc msng hardware & secured. j

NO PARTS USED

Workorder: V31856

In Date: 04/28/2010
Close Date: 05/10/2010

Meter Reading: 77,246.70

Problem?

driver's side rear outer rim has a slight dent. not sure if it will affect the performance of the tire or not. R14

Task performed:

Parts

Quantity

Went to Stn14; fnd R/rear outside rim had small ent; ok to run. j

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V32187

In Date: 05/13/2010
Close Date: 05/28/2010

Meter Reading: 78,768.00

Problem?

REPAIR LATCH ON BATTERY COMP E14

Task performed:

1. Fnd btry latch sticking; cldn/lubed latches; ck opn; ck ok.
 2. Ck for air leak; aired up truck sprayed hoses/fittings; R/R fitting out air tank; aired truck; ck for leaks; ck ok.
- j

Parts

NO PARTS USED

Quantity

Workorder: V33690

In Date: 07/21/2010
Close Date: 08/02/2010

Meter Reading: 78,768.00

Problem?

mount hurst equip. sb1 e

Task performed:

- Rem Hurst mnts frm E19; went to 19; mntd Hurst tool mnts; mntd cone strap, rear hose coupling strap, fire ext; replc hose crimp & one strap. ja

Parts

SAHSVS2510STRAP
 UMVS111611STRAP
 UMVS162511STRAP
 UMVS254411STRAP 46 IN

Quantity

1
2
1
1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V33883

In Date: 07/29/2010
Close Date: 08/27/2010

Meter Reading: 79,703.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED SPARE BATT 1 ENG

Task performed:

- 1. B-Inspection & road test.
- 2. T-case svc.
- 3. Diff svc.
- 4. Air dryer svc.
- 5. Blow out clogged A/C filter & reinstall.
- 6. Officers wind molding & R/rear window molding damaged; rem/install new molding.
- 7. L/side frnt body marker light & tailboard marker ight 10-7; rem blown LED lights & install new.
- 8. Taglight bulb 10-7; rem blown bulb & install new bulb.
- 9. Right t-signal frnt lens brkn; rem lens & install new lens.
- 10. Msng lugnut cvrs - replc.
- 11. City horn inop; fnd horn button corroded & grndng cable pinched; rem parts & install new button & grndng cable.
- 12. Windshield fluid reservoir low; add fluid & add bug solvent.
- 13. Quality check. ja

Parts

Quantity

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
35200-RLIGHT MARKER LED RED	2
35200-YLIGHT MARKER LEDAMBER	1
67BULB 12 VOLT	1
6804640043HORN CONTACT	1
6814600340A14-15472-000 HORN BUTTON	1
800405PURGE VALVE KIT	1
91513AMBER LENS	1
A1834388003MOLD R/H	2
ACX-84534LUG NUT COVER PK10	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V31507

In Date: 04/13/2010
Close Date: 08/31/2010

Meter Reading: 77,246.70

Problem?

pump panel pressure guage third digit not lighting up. single numerical E14

Task performed:

work completed on WO 31511 ja

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V31511

In Date: 04/14/2010
Close Date: 08/31/2010

Meter Reading: 77,246.70

Problem?

pump panel gauge's third digit not reading. (number burnt out) E14

Task performed:

1. No new gauge; will be in in (4) weeks.
 2. Rem defective gauge; install new gauge; operate pump to ensure proper opn of gauge; unit working normal.
- ja

Parts	Quantity
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1

Workorder: V33747

In Date: 07/23/2010
Close Date: 09/07/2010

Meter Reading: 79,133.20

Problem?

Light box charger on the driver side rear seat needs to be replaced. light box not sitting in charger correct and charging.E19 spare

Task performed:

- R/R light box charger; fnd fuse bad; R/R fuse & holder; ck ok. js

Parts	Quantity
NO PARTS USED	

Workorder: V35858

In Date: 10/22/2010
Close Date: 11/05/2010

Meter Reading: 79,133.20

Problem?

REPAIR FUEL SYSTEM CUMMINS

Task performed:

- Rep fuel sys - Cummins j

Parts	Quantity
NO PARTS USED	

Vendor?: CUMMINS

Workorder: V33585

In Date: 07/16/2010
Close Date: 11/08/2010

Meter Reading: 78,768.00

Problem?

The generator in question is off the regular engine that's in pm now. It appears to be leaking oil. The oil that leaked appears to have been there for a while but it did leak a moderate amount nonetheless. E68

Task performed:

1. Fnd gen leaking gas; brought to shop.
 2. PU spare btry (1) gen @ 68 for repairs.
- j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V36340

In Date: 11/09/2010
Close Date: 11/18/2010

Meter Reading: 79,775.00

Problem?

E17 Left quartz scene light buzzer won't shut off.

Task performed:

1. Rep both pole lights on eng; alarm going off; C/O light on one of the pole light; rep pins.
2. Adj doors on rescue at some of the pins out of adjustment & tip of door out of adjustment; ok.
3. Replc light on spotlight on R/side pole; John said that he was going to do but did not. j

Parts

Quantity

LB-D30BULB QUARTZ HAL. 12V 150W

2

Workorder: V35739

In Date: 10/18/2010
Close Date: 11/19/2010

Meter Reading: 79,133.20

Problem?

STATION BLOWER WON;T START. Sta 15

Task performed:

1. blower inop, cleaned carberator, will not stay running. jab

Parts

Quantity

NO PARTS USED

Workorder: V36331

In Date: 11/09/2010
Close Date: 12/06/2010

Meter Reading: 79,775.00

Problem?

right side scene light one bulb out se at 17

Task performed:

- (1) TRAVELED TO ST 17 TO REPAIR RIGHT SCENE LIGHT ON SE17. CHECKED OUT BOTH SCENE LIGHT AND FOUND THEM WORKING OK. J.W.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V37569

In Date: 01/03/2011

Meter Reading: 80,186.60

Close Date: 01/06/2011

Problem?

ON CALL TURBO 10-7 SB1E AT 18

Task performed:

(1) OT. SBE1 ENGINE SMOKING VERY BAD AND MAKING ALOT OF NOISE. TRAVELED TO BAT-1 TO REPAIR SBE1. CHECKED IUT THE PROBLEM. FOUND THAT THE TURBO HAD BLOWN. GOT E18 BACK TO STATION AND DID A SWAP OUT OF ENGINES. TRUCK# 10132085. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V37509

In Date: 12/30/2010

Meter Reading: 80,186.60

Close Date: 01/10/2011

Problem?

Suction control lever bent so much on pump panel that we cant lock it down. Needs to be straightened or replaced. Cpt JP Maxso se at 18

Task performed:

(1) TRAVELED TO ST-18 TO REPAIR BENT TANK TO PUMP LEVER ON SE1. INSTALLED A NEW LEVER AND TESTED OK. J.W.

Parts

RC-4101 AKRON SHORT HANDLED VALVE REMOTE

1

Workorder: V37618

In Date: 01/04/2011

Meter Reading: 80,186.60

Close Date: 01/18/2011

Problem?

TURBO 10-7 SB1 E

Task performed:

1. Replcd turbo (blown),.
2. R/R after cooler to be clnd - oil/turb o debris.
3. Changed eng oil/oil filter - contaminated.
4. Cln out all piping to/frm after cooler/turbo; also clnd air filter hsnng & replcd air filter - (debris frm turbo failure).

Parts

3800401RXUSE 4955658RX TURBO

1

BHT-8983SCOOLER AIR CHARGE

1

CA8193AIR FILTER 46744 WIX

1

DDE-5411870080GASKET OIL RETURN TUBE TURBO

1

HPH6349AOIL FILTER 51748

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V37822

In Date: 01/15/2011
Close Date: 01/24/2011

Meter Reading: 80,186.60

Problem?

Tank to pump stuck in closed position, also when transmission is put into D mode for the PTO to engage the pump, gear selection shows 4 , not 5. Pump does engage, and can be used. E15

Task performed:

1. Tank to pump stuck - linkage out of adj; adj linkage.
2. Boost hose off; realigned turbo & reinstalled hose & tightened all hoses.
3. L/headlight inop - bulb; replc d bulb.
4. Shoreline inop; stn cord end wrng; replcd shoreline female end. j

Parts	Quantity
5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	1
H6054USE CV TYPE SEALED BEAM	2

Workorder: V38146

In Date: 01/29/2011
Close Date: 02/04/2011

Meter Reading: 80,186.60

Problem?

Spare @ E14. OIC side rear outside tire is wearing unevenly.

Task performed:

- Travel to stn; inspect rear tires; tires will need replacement soon; will notify Scotty. j

Parts	Quantity
NO PARTS USED	

Workorder: V38022

In Date: 01/24/2011
Close Date: 02/25/2011

Meter Reading: 77,246.70

Problem?

won't go into pump gear E14 (on-call)

Task performed:

- Not going in pump gear; fnd bad pump switch; replc switch & tested. j

Parts	Quantity
200-2450-00NC SWITCH OK TO PUMP	1

Workorder: V39370

In Date: 03/22/2011
Close Date: 05/02/2011

Meter Reading: 80,186.60

Problem?

primer motor innop

Task performed:

1. Travel to 19; got primer working to mk pump test; will replc tomorrow.
2. Replcd primer pump as per above dia; rewired solenoid on new pump to match wiring on truck. j

Parts	Quantity
501-3090-00PRIMER PUMP MOTOR	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V40137

In Date: 04/25/2011

Meter Reading: 81,045.70

Close Date: 05/06/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED SB1 E

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- Perform "C" service.
- 2. Replcd all (4) btrys.
- 3. Reroute/rewire neg btry cable to proper side of btry pack - wired wrong.
- 4. R/R pass frnt seat to be rep at upholstery shop.
- 5. painted fuel cap.
- 6. Svc T-case.
- 7. Replcd pull cord style air drains w/petock style drains - leaking.
- 8. Rebuilt air brake dryer.
- 9. Svc trans.
- 10. Svc P/S sys.
- 11. Perform a second vac test to determine reason for vac lost; fnd intake relief valve leaking; replcd chk valve & rechkd sys; still leaking at intake relief.
- 12. Rebuilt recirculater valve - leaking.
- 13. Rebuilt tank to pump valve.
- 14. Rebuilt intake relief valve.
- 15. Replcd intake relief valve indicator light switch, brkt & relay - bent/brkn.
- 16. R/R intake relief valve a second time to double gskt mntng flange.
- 17. Rebuilt intake relief sensing valve - leaking; cln debris frm chk valves; connected truck to hydrant to exercise intake relief.
- 18. Performed numerous vac test; finally passed test after afore-mentioned repairs; test start: 22 min; test finish: 19 in.
- 19. Driver's door outer handle/latch brkn; replcd; also adj latch linkage & lube window regulator - binding.
- 20. C/O foam sys inop; fnd foam sys inop; fnd foam sys unable to see wtr flow; replcd flow sensor in pump manifold; calibrated foam sys; foam sys now operates normally.
- 21. Assisted w/foam calibration.
- 22. Replcd grnd ladder heat stickers.
- 23. Replc L/side t-signal marker light lens - cracked.
- 24. Replc wiper blades; also clnd debris frm windshield squirters.
- 25. Replcd rear A/C filter.
- 26. Replcd left A/C vent on center section of dash - brkn
- 27. Replce all (4) cab door weatherstrips.
- 28. Compt light/door alarm inop for hose reel compt; adj door switch & replc door latch mechanism - bent.
- 29. Lube, tighten & adj all compt & cab door latches, hinges & hold opens; also tightened numerous compt eqmpt mnts & straps.
- 30. Performed quality inspection.
- 31. Replcd holdopens for doors on compt L-1 & L-3 - leaking. j

038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
0460050000GASKET	2
101280018LATCH ASSY. FOR D-PADDLE HANDLE	1
103385NDRAIN COCK	3
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1250E473PLUG DRAIN REAR END FREIGHTLINER	2
15W40BSYN OIL BULK QTS	24
200-2491-00SENSOR HALE HPF FOAM FLOW	1
29526898 29548988 TRANS FILTER ALLISON	1
52-24WIPER BLADES ANCO 24	2
546085303NC SWITCH/BRACKT	1
546126000TPM/QG HALE REPAIR KIT	1
5462270020VALVE KIT SS 546-2270-02-0	1
5462300020VALVE KIT SS VALVE 3 IN	1
6806970098SEAL DOOR	1
6807600070HANDLE DOOR EXT L/H	1
6808300174VENT A/C RH	1
75W90GEAR OIL SYN QT	4
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	1
ANTICOOLANT ANTIFREEZE GAL	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
BPR5ESSPARK PLUG 7734	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	2
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	5



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V40403

In Date: 05/04/2011
Close Date: 05/18/2011

Meter Reading: 81,045.70

Problem?

Replace 4 rear tires.

Task performed:

Replc (4) rear tires - Elpex j

Parts

Quantity

NO PARTS USED

Vendor?: EXPEX

Workorder: V41794

In Date: 07/05/2011
Close Date: 07/13/2011

Meter Reading: 82,049.50

Problem?

Fuel leak.

Task performed:

went to 19
ran engine
found injection line leaking at pump
tightened line cleared ckeck
returned home ak

Parts

Quantity

NO PARTS USED

Workorder: V41858

In Date: 07/07/2011
Close Date: 07/14/2011

Meter Reading: 82,049.50

Problem?

Primer 10-7. Sta 19.

Task performed:

Primer stuck on; solenoid stuck; R/R solenoid; hooked
btry back up; no primer coming on w/btry; fnd switch on
hand valve stuck; took hand valve apart & relubed; replc
switch; tested opn - all ok. j

Parts

Quantity

NO PARTS USED

Workorder: V41936

In Date: 07/12/2011
Close Date: 07/14/2011

Meter Reading: 82,625.20

Problem?

ON CALL FUEL LEAK SE AT 19

Task performed:

Fnd fuel seeping out of back of injection pump; tried to
tighten looseline at pump to try & tighten fitting on pump;
cld not stop; not affecting eng performance. j

Parts

Quantity

9096-02SWITCH

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V41943

In Date: 07/12/2011

Meter Reading: 82,625.20

Close Date: 07/28/2011

Problem?

Diesel fuel is leaking from engine, Telescoping Light will not work. Sta 15.

Task performed:

- A-Service
- 2. Rep pole light - C/O; fnd solenoid wires loose & bad grnd on solenoid; rep & working.
- 3. Fnd bad light on left frnt fender; replc w/new & replc other lens cvr.
- 4. Top off all fluids.
- 5. Replc handle on R/side intake drain (used). j

Parts

Quantity

15W40BSYN OIL BULK QTS	1
50R03ZCRLIGHT LED RED TIR 6	1
6819634283068-1963428-30 LENS CLR	1

Workorder: V41947

In Date: 07/12/2011

Meter Reading: 82,625.20

Close Date: 09/20/2011

Problem?

repair fuel system cummins

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CUMMINS

Workorder: V45283

In Date: 11/18/2011

Meter Reading:

Close Date: 12/12/2011

Problem?

left(driver's) headlight is out

Task performed:

Parts

Quantity

replaced headlight and checked pwoer to modem

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V46924

In Date: 01/30/2012

Meter Reading: 85,612.90

Close Date: 01/30/2012

Problem?

Tank to pump valve stuck.

Task performed:

TRAVEL TO STA 19 - FOUND HANDLE AND ROD BENT. FOUND VALVE STOP BENT. LEVER LOCKED FROM TO FAR PAST FULCUM SHORTEN ROD TO ALLOW VALVE HANDLE TO SWING. VEHICLE NEEDS NEW HANDLE AND TO BE SET UP PROPERLY. ALSO NEW VALVE STOP.

Parts

NO PARTS USED

Quantity

Workorder: V46858

In Date: 01/26/2012

Meter Reading: 85,534.30

Close Date: 02/07/2012

Problem?

Tank to pump locking mechanism not working right and lever is very stiff. Sta 19

Task performed:

TRAVEL TO STATION FOUND LINKAGE LOOSE AND BINDING CORRECTED OK.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V47116

In Date: 02/06/2012

Close Date: 02/15/2012

Meter Reading: 85,679.00

Problem?

B inspection

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. AFTER STARTING A "C" INSPECTION (VERBAL BY MIKE LEHAN) STEVE REINES CAM E AND TOLD ME IT IS A B INSPECTION - REWRITE PAPER WORK.
2. B INSPECTION.
3. B INSPECTION.
4. R&R HOSE REEL COMPT DOOR SW ALSO HAD TO SPLICE A NEW SWITCH CONNECTOR ON TO VEHICLE WIRING HARNESS - DAMAGES.
5. CLEAN LUBE AND REPAIR TRASHLINE COMPT. DOOR LATCHES AND BATTERY TRAY COMPARTMENT DOOR LATCHES.
6. TIGHTEN 8 R&L SIDE REAR AXLE TRAILING ARM BOLTS.
7. TIGHTEN R/F SHOCK ABSORBER MOUNTING BOLTS.
8. ADJUST ALL TIRE PRESSURES - LOW.
9. R&R LENS R&R BULB R/F FENDER MARKER LIGHT.
10. FABRICATE GUSSETT - MOUNT DRILL AND INSTALL ON 4 R CAB STEP TO REPAIR BROKEN WELDS.
11. DIAGNOSE WHY TURN SIGNALS DON'T SELF CONCEL R&R TURN SIG SWITCH R&R STEERING WHEEL FABRICATE SPACER FOR CAM PIN ON STERRING WHEEL 12. CONTINUED ABOVE REPAIR.
13. R&R DASH PANELS REPAIR AND ADJUST ALL HEAT A/C CONTROL CABLES FOR CORRECT OPERATION. R&R 3 DEFROSTER LOWERS REMOVE THPE AND CARDBOARD SOME INSTALLED TO BLOCK AIRFLOW ALSO REINSTALL DUCTS TO LOWERS THAT FELLOUT. INSTALL MISSING DASHBOARD SCREWS R&R LIGHT BULB FOR HEAT AND A/C CONTROL.
14. DRAIN COOLING SYSTEM R&R 2 COOLANT HOSES REPLACE HOSE SEPERATORS INSTALL HOSE CHAFF GUARDS.
15. Q&A.
16. R&R COMPT DOOR HOLD OPEN.
17. R&R COMPT DOOR LATCH STRIKER - BENT - PARTS ROOM NEW STRIKER MADE DIFFERENT - WON'T WORK - PUT ORIGINAL IN PRESS TO STRAIGHTEN REINSTALL AND ADJ.
18. R&R PRIMER VALVE ASSY. REBUILD PRIMER VALVE INSTALL AND TEST.
19. FINISH ABOVE REPAIR.
20. R&R HEATER VALVE ASSY AND ADJ. CABLE.

23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LONG	2
52-624SWITCH DOOR	1
657843STRIKER EGS-FM-E500-106-ZN MT EONE	1
ABPN83324191WATER VALVE OLD # KYS417266	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PVG-KITORING KIT	1
R90PFILTER FUEL 33231	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47287

In Date: 02/13/2012 Meter Reading: 85,721.00
Close Date: 02/29/2012

Problem?

Hurst tool tray difficult to close. At station 16.

Task performed:

CLEANED AND LUBED TRACKS.

Parts

NO PARTS USED

Quantity

Workorder: V47423

In Date: 02/20/2012 Meter Reading: 85,992.00
Close Date: 03/06/2012

Problem?

need to check air system for leaks/loss air about 10hrs. SE AT 16

Task performed:

CHECKED AIR SYSTEM FOR LEAKS FOUND ONE AIR
LINE NOT SEATED.

Parts

NO PARTS USED

Quantity

Workorder: V47830

In Date: 03/08/2012 Meter Reading: 86,196.80
Close Date: 03/19/2012

Problem?

at station 17, mechanic here. Horn/siren does not work in any setting on steering wheel. Sta 17

Task performed:

TRAVEL TO STATION CHECKED SWITCH FOUND
HORN BUTTON NOT WORKING REMOVED FROM
STEERING WHEEL RECONNECTED WIRE.
CHECKED OK.

Parts

NO PARTS USED

Quantity

Workorder: V48001

In Date: 03/15/2012 Meter Reading: 86,297.40
Close Date: 03/20/2012

Problem?

air leaks down both tanks overnight down to 30-20psi Batt1 spare Sta 17 Engine

Task performed:

WENT TO 17 - AIRED UP TRUCK - SPRAYED
FITTINGS AND LINES AND DRIER - FOUND FITTINGS
LEAKING AT ??????? - CUT OFF HOSES RESEALED
CHECK OK.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V47796

In Date: 03/06/2012
Close Date: 05/07/2012

Meter Reading: 86,196.80

Problem?

officers side scene light one bulb intermitant,multiple discharge and intake cap chains broken or missing bracket for hurst cutters missing horn button/siren/ air horn 10-7 officers side nozzle holder rusted ready tobrek, Sta 17

Task performed:

Parts

Quantity

1. HORN SELECTOR SWITCH REPAIRED.
2. REPAIRED HURST CUTTER BRACKET.

NO PARTS USED

Workorder: V49401

In Date: 05/16/2012
Close Date: 05/25/2012

Meter Reading: 86,941.00

Problem?

both telescoping scene lights and pump panel lights not working.

Task performed:

Parts

Quantity

TRAVEL TO 18 BOTH LIGHTS AND PUMP PANEL LIGHTS OPERATE - NO PROBLEM FOUND.

NO PARTS USED

Workorder: V49836

In Date: 06/02/2012
Close Date: 06/06/2012

Meter Reading: 87,172.00

Problem?

FOAM TANK LEAKING E14

Task performed:

Parts

Quantity

TRAVEL TO 14 FOUND FOAM PUMP LEAKING BETWEEN PUMP AND MOTOR WILL GO TO SHOP FOR REPAIR.

NO PARTS USED

Workorder: V49842

In Date: 06/03/2012
Close Date: 06/06/2012

Meter Reading: 87,172.00

Problem?

Leaking foam E15

Task performed:

Parts

Quantity

SEE R/O#V49836

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V49212

In Date: 05/09/2012 Meter Reading: 86,603.00
Close Date: 06/14/2012

Problem?

circle D light 10-7. male plug broke off. E18

Task performed:

1. TRAVEL TO 18 PICKED UP CIRCLE D LIGHT TO EXCHANGE AT SHOP.
2. DROP OFF CIRCLE D LIGHT AT STA 18.

Parts	Quantity
065624AD-IP DRIER	1
K022105PURGE VALVE AD-IP-IS	1

Workorder: V50107

In Date: 06/13/2012 Meter Reading: 87,172.00
Close Date: 06/18/2012

Problem?

REPAIR FOAM SYSTEM FOR LEAK ON SBE1.

Task performed:

1. CHECK OUT FOAM LEAK - FOUND PUMP HEAD SHAFT LEAKING - REMOVE COMPLETE FOAM SYSTEM PUMP AND MOTOR W/CONTROL FROM VEHICLE AND DISASSEMBLE ON BENCH - CHECK ON PARTS AVAILABLE TO MAKE REPAIRS NONE IN STOCK DID HAVE NEW COMPLETE PUMP ASSEMBLY AND REMAN MOTOR AVAILABLE - NOTE: CHECKED WITH SUPER TO EITHER ORDER PARTS OR TO USE NEW COMPONENTS - DECISION WAS MADE TO USE NEW - ASSEMBLE NEW PUMP TO REMAN MOTOR AND MOUNT ONTO MOTOR PLATE - INSTALL CONTROLL MODULE ALSO TO MOTOR PLATE - INSTALL COMPLETE ASSEMBLY INTO VEHICLE - MAKE ALL NECESSARY CONNECTIONS.
2. FOAM SYSTEM - INOP - CHECK ALL CONTROL SYSTEMS - FOUND PUMP PANEL CONTROL MONITOR - NG - INSTALL NEW MONITOR - NOTE: NEW UPDATED MONITOR MOUNTING DIFFERANT AND PUMP PANEL NEEDED TO BE MODIFYED - MAKE NECESSARY MODIFICATIONS - ALSO WIRING NEEDED TO INSTALLED AND ONE OF THREE DATA CABLES NEEDED TO BE REPLACED - AFTER THESE REPAIRS AND SYSTEM UP AND RUNNING - NOTICED THERE WAS NO DETECTION OF WATER FLOW RATE - ISOLATE PROBLEM - AND FOUND FLOW SENSOR (PADDLE WHEEL) TYPE - NG - REMOVE FROM WATER PIPE AND INSTALL NEW SET UP VEHICLE AT HYDRANT AND CALIBRATE FLOW AND FOAM.

Parts	Quantity
045-0770-00108494-00 MOTOR ELECT HALE FOAM PUMP	1
200-2491-00SENSOR HALE HPF FOAM FLOW	1
501-3130-00PUMP HALE FOR FOAMMASTER	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V51508

In Date: 08/10/2012 Meter Reading: 87,403.00
Close Date: 08/13/2012

Problem?

Bad air leak. Both tanks leak down to 25psi within two hours of sitting. E 16

Task performed:	Parts	Quantity
TRAVEL TO 16 REPLACED LEAKING AIR FITTING AT GOVERNOR OK.	NO PARTS USED	

Workorder: V51658

In Date: 08/16/2012 Meter Reading:
Close Date: 09/06/2012

Problem?

Cab air ride air bags not inflating and Has an air leak too . K.C. #6318 Thanks

Task performed:	Parts	Quantity
1.CHECKED AIR BAGS FOUND NO PROBLEM	NO PARTS USED	

Workorder: V52037

In Date: 08/30/2012 Meter Reading:
Close Date: 09/11/2012

Problem?

2in play in brake pedal, air leak in air brake system.

Task performed:	Parts	Quantity
1. TRAVEL TO 19 ADJUSTED BROKEN PEDAL.	NO PARTS USED	

Workorder: V52044

In Date: 08/30/2012 Meter Reading: 87,542.00
Close Date: 09/12/2012

Problem?

TANK TO PUMP HANDLE BROKE E19

Task performed:	Parts	Quantity
1. TRAVEL TO JUPITER PD GO TO ST 19 R&R BROKEN PUMP PANEL HANDEL FOR TANK TO PUMP AND ADJUST AND TO GO TO SHOP FOR PARTS.	102AKRON LONG ARM RC-4	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V52110

In Date: 09/03/2012

Meter Reading:

Close Date: 09/12/2012

Problem?

Needs a new nozzle basket on passenger side pre connect. E19

Task performed:

Parts

Quantity

1. TRAVEL TO 19 REPLACE NOZZLE BASKET AND MOUNT.

NO PARTS USED

Workorder: V52104

In Date: 09/03/2012

Meter Reading:

Close Date: 09/19/2012

Problem?

Engine 19 (Batt 1 spare) Asset # 10155566 has a significant air leak.

Task performed:

Parts

Quantity

TRVL TO 19. REPLACE ABS VALVE AND CHK FOR LEAKS OK.

472-500-121-0ABS ASSBLY

1

Workorder: V51526

In Date: 08/10/2012

Meter Reading:

Close Date: 10/09/2012

Problem?

needs new windshield wipers Thanks K.C. #6318 E16

Task performed:

Parts

Quantity

TRVL TO 16 REPLACED WIPER BLADES.

52-24WIPER BLADES ANCO 24

2

Workorder: V52036

In Date: 08/30/2012

Meter Reading: 87,542.00

Close Date: 11/01/2012

Problem?

driver side rear extrication tray will not pull out. SBE1

Task performed:

Parts

Quantity

R&R HURST TOOL TRAY REPAIR ROLLER SLIDES AND REPLACE MISSING HARDWARE.

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V52295

In Date: 09/10/2012

Meter Reading: 88,123.00

Close Date: 11/01/2012

Problem?

Air Leak was fixed, but still leaks out with in the hour. e 19

Task performed:

1. DIAGNOSE AIR LEAKS R&R PARKING BRAKE VALVE IN DASH - CONTINUE DIAGNOSIS. REPAIR LEAKS YELLOW HOSE REPAIR LEAK AT AIR HORN SOLENOID.
2. ONE SYSTEM HELD L00 PSI OVER NIGHT OTHER DROPPED CONTINUE LEAK FIND. R&R FITTING ON AIR TANK.

Parts

Quantity

800034VALVE PARKING BRK.

1

Workorder: V53265

In Date: 10/23/2012

Meter Reading: 88,563.20

Close Date: 11/15/2012

Problem?

C Inspection BSE1

Task performed:

1. C INSP
2. C INSP
3. FINISH C AND SERV ON BOARD GENERATOR.
4. R/R R/S DOOR HOLD OPEN PISTON.
5. TIGHTEN BOTH BALL STUDS FOR DOOR HOLD OPEN ON R/S COMPT #1.
6. R/R RAN CAP.
7. TIGHTEN BOLTS ON R/F SHOCK ABS ORDER.
8. CLEAN ADJ AND LUBE BATTERY TRAY LATCHES.
9. R/R CAB AUX A/C FILTER.
10. R/R AND OVERHAUL AIR DRYER.
11. SECURE WASHER HOSE TO WIPER ARM.
12. DRAIN COOLANT R/R COOLANT FILTER AND FILTER HENDER. CLEAN GASKET SERVICES. REBUILT SHUT OFF VALVE IN HENDER. REINSTALL WITH NEW GASKET.
13. REFILL COOLING SYSTEM AND LEAK TEST.
14. VEH FAILED DRY VAC. REPAIR LEAKS. ADJ LENGTH OF TANK TO PUMP VALVE ROD AND INDEX ROD TO VALVE. DO DRY VAC TEST AGAIN- CHK OK.
15. RE TORQUE U-BOLTS.

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB

1

082-2007-00-0GREASE ZERK W/CHECK VLV

1

107796DRYER KIT AD9 -NEW

1

107800VALVE CHECK AD9

1

3818885O-RING WATER SHUT OFF

2

3937367GASKET 4942874

1

39437394940547 SHAFT SHUT-OFF VALVE

1

3943740SHAFT SHUT-OFF VALVE

1

39438574989614 SEAL O-RING SHUT-OFF VALVE

1

39444543977737 SCREW SHUTOFF VALVE

1

4989614O-RING SHUT-OFF VALVE

1

78R536078R5360M 2PK FILTER AIR COND

1

800405PURGE VALVE KIT

1

BPR6ESSPARK PLUG 7131

1

CA8193AIR FILTER 46744 WIX

1

EAA-8350-30UGSS1783UQ STRUT-LIFT

1

EXO3AH00015SPLUG RAD. DRAIN

1

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

1

HPH6349AOIL FILTER 51748

1

PR338324070 WIX FILTER WATER

1

R90PFILTER FUEL 33231

1

SS-25SC5025 SUCTION SCREEN

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V54137

In Date: 12/03/2012
Close Date: 12/05/2012

Meter Reading:

Problem?

spare engine, left (driver's side) pump panel scene light not attached securely to telescoping pole. E 14

Task performed:

CHECKED SCENE LIGHTS FOUND NO PROBLEM.

Parts

NO PARTS USED

Quantity

Workorder: V54184

In Date: 12/04/2012
Close Date: 12/05/2012

Meter Reading:

Problem?

water in fuel light in dash activated. no water visual in filter sight glass. E14

Task performed:

TRAVEL TO 14 DRAINED FILTER AND FOUND ALGEC
ADDED ALGICIDE TO TANK OK.

Parts

NO PARTS USED

Quantity

Workorder: V54390

In Date: 12/12/2012
Close Date: 01/29/2013

Meter Reading:

Problem?

back up alarm is going off when the battery is turned on and never turns off. Alarm going off while driving down the road.

Task performed:

CHECKED FOR ALARM ISSUE NO PROBLEM.

Parts

NO PARTS USED

Quantity

Workorder: V54391

In Date: 12/12/2012
Close Date: 01/29/2013

Meter Reading:

Problem?

Quartz light alarm continuing to go off even when quartz lights are stowed.

Task performed:

ADJUSTED SWITCH FOR QUARTZ LIGHT.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V56595

In Date: 03/23/2013
Close Date: 03/27/2013

Meter Reading: 89,347.50

Problem?

BOTH TELESCOPIC SCENE LIGHTS 10-7. SWITCH PANEL SHOWS THERE ON BUT NO LIGHT.E-14

Task performed:

BOTH LIGHTS WORK FINE.

Parts

NO PARTS USED

Quantity

Workorder: V56770

In Date: 04/02/2013
Close Date: 04/05/2013

Meter Reading: 89,855.00

Problem?

Quartz light up warning on SE @ ST-14

Task performed:

WENT TO 14 - ADJUSTED QUARTZ LIGHT POSITION -
CHECK OK - RETURN HOME.

Parts

NO PARTS USED

Quantity

Workorder: V56369

In Date: 03/13/2013
Close Date: 04/24/2013

Meter Reading: 89,347.50

Problem?

Not running good

Task performed:

DIAGNOSED ENGINE PROBLEM WITH COMPUTER -
CODE 359 CHANGED FUEL FILTER AND TEST DROVE
ENGINE. COULD NOT DUPLICATE RETURNED TO
SERVICE.

Parts

FS1022FILTER FUEL WIX 33422 PS8689 FRAM

1

Quantity

Workorder: V57500

In Date: 05/06/2013
Close Date: 05/07/2013

Meter Reading:

Problem?

Spare engine will not start. Completely dead, might be the battery switch SE @15

Task performed:

CHARGED BATTERIES AND PLUGGED TRUCK IN OK

Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

1

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V59104

In Date: 07/15/2013
Close Date: 07/22/2013

Meter Reading: 89,932.00

Problem?

B inspection OCS SBE1

Task performed:

B inspection by OCS
filters changed

Vendor?: OCS

Parts

Quantity

NO PARTS USED

Workorder: V59349

In Date: 07/25/2013
Close Date: 07/31/2013

Meter Reading: 89,932.00

Problem?

one bulb on drivers side spot light is out. E17

Task performed:

1. TRAVEL TO 17 REPLACED SCENE LIGHT BULB.
2. TRAVEL TO 15 REPAIRED SPOT LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V60914

In Date: 10/01/2013
Close Date: 10/16/2013

Meter Reading: 89,932.00

Problem?

ran the spare Engine this morning and noticed that there was a "Water in Fuel" warning light on the dash. at 15

Task performed:

1. CHECK OUT W.I.F. LIGHT ON DRAIN WATER FROM BOWL TK OK.
2. CHECK OUT BATTS ON UNIT WILL GET NEW CHARGER ORDERED FOR UNIT SAID LIGHTS WERE NOT WORKING 110V CHARGER INOP.
3. TRAVEL TO ST 15 CHECK BATTS AGAIN BEFORE CHARGER REPLACEMENT R&R BATTS ON TRUCK RETEST CHARGE IS UP NOW USAGE STILL LOW.

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

4

HP-31DBATTERY 950CCA HP-31D

4



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V61254

In Date: 10/14/2013
Close Date: 10/18/2013

Meter Reading: 89,932.00

Problem?

tank to pump handle broke off and pump not going past 130 psi

Task performed:

1. TANK TO PUMP HANDLE BROKEN - REMOVE HANDLE AND ASSEMBLY - INSTALL NEW TANK TO PUMP HANDLE AND ASSEMBLY.
2. OPERATOR COMPLAIN PUM WILL NOT GO PASS 130 PSI - OPERATE PUMP AT 90, 120, 130, 160 AND 200 PSI NO FAULT FOUND - PUMP WORKING TO MANUFACTORY SPECS -PRESSURE RELIVE VALVE AND GOVERNOR OPERATING TO SPECS NO FAULT FOUND AT THIS TIME.
3. REMOVE OLD METAL PLAK HOLDERS - CLEAN SURFACE AND ISTALL NEW HOLDER.

Parts	Quantity
102AKRON LONG ARM RC-4	1
S PLACARDFRONT AND BACK PLACARD	1

Workorder: V61381

In Date: 10/19/2013
Close Date: 10/30/2013

Meter Reading:

Problem?

Tank to pump handle broken and primer sticking in on position. SB1 E AT 15

Task performed:

1. TRAVEL TO ST 15 CHECK BROKEN HANDLE REMOVE OLD HANDLE KNOCK OUT PIN DRILL OUT BROKEN HANDLE TIP REINSTALL NEW HANDLE ASSY REINSTALL ON THE TEST OK.
2. TEST PRIMER ON TRUCK STICKING LUBE HANDLE TEST OK.

Parts	Quantity
538028052VALVE PRIMER PUMP W/HARDWARE	1

Workorder: V63126

In Date: 01/03/2014
Close Date: 01/07/2014

Meter Reading:

Problem?

Pumper needs (2) 2.5" caps and(1) 2.5" plug for discharges and intakes. E19

Task performed:

PARTS ONLY NO LABOR.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V63124

In Date: 01/03/2014

Meter Reading:

Close Date: 01/08/2014

Problem?

Tank to pump handle very difficult to open. E19

Task performed:

Parts

Quantity

CHECKED VALVE LINKAGE ON BET NEEDS REBUILT AT SHOP.

NO PARTS USED

Workorder: V63125

In Date: 01/03/2014

Meter Reading:

Close Date: 01/08/2014

Problem?

Vehicle needs power source for trip tix charger. Also needs antenna and modem for trip tix. E19

Task performed:

Parts

Quantity

INSTALLED OUTLET FOR CHARGER.

56415CIG. LIGHTER ACCES.

1

Workorder: V63538

In Date: 01/20/2014

Meter Reading:

Close Date: 01/21/2014

Problem?

E19 radiator hose leak, OOS.

Task performed:

Parts

Quantity

TRAVEL TO 19 DRIVER COMPLAINT COOLANT LEAK FOUND UPPER HOSE CLAMPS 10-7 REPLACED CLAMPS AND TESTED OK.

NO PARTS USED

Workorder: V63577

In Date: 01/21/2014

Meter Reading: 91,303.00

Close Date: 01/23/2014

Problem?

Rear Air Breaks Do not hold air. When truck stops you can hear a hissind noise. Have to wait for them to build pressure every time you start the truck

Task performed:

Parts

Quantity

1. TRAVEL TO ST 15 TO CHECK OUT BRAKES. TRUCK AT ST 19 CALL ROB TO GO BY AND REPAIR.
2. CHECKED FOR COOLANT LEAK FOUND EITHER HEAD GASKET OR WATER PUMP LEAK ALSO AIR LEAKING SENT TO SHOP FOR REPAIR.

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V63600

In Date: 01/22/2014

Meter Reading:

Close Date: 02/24/2014

Problem?

THE RADIATOR / COOLING SYSTEM LEAKS UNDER PRESSURE. ATER CALLS WATER LEAKS FROM THE SYSTEM. se at :

Task performed:

1. DIAGNOSE COOLANT LEAK. R&R WATER PUMP. R&R ALL 3 BELTS. ALSO R&R BELT. TENSIONER. ALSO COOLING SYSTEM.
2. FABRICATE A BRACKET TO CLAMP UPPER RAD HOSE TO STAY CLEAR OD A/C PULLEY.\
3. PRESSURE TEST COOLING SYSTEM COLD AND CHECK FOR LEAKS ROAD TEST VEH AND RECHECK FOR LEAKS. CHECK AND ERASE ENGINE COOLANT CODES.

Parts

Quantity

39768315259022 GROOVED TENSIONER OLD#3936213

2

40896474309418 PUMP-WATER ISC REBUILT

2

9440BELT

1

9480BELT

1

EXO3AH00015PLUG RAD. DRAIN

1

Workorder: V58963

In Date: 07/09/2013

Meter Reading: 89,932.00

Close Date: 03/03/2014

Problem?

B inspection SBE1 OCS

Task performed:

duplicate ticket, work completed on 59104

Parts

Quantity

NO PARTS USED

Workorder: V63515

In Date: 01/18/2014

Meter Reading:

Close Date: 03/11/2014

Problem?

Air system leaks. You can hear the leak when truck is shut off. Have to wait every time truck is started to build pressure. Q15

Task performed:

R&R LEAKING AIR VALVE IN LADDER COMPARTMENT.

Parts

Quantity

NO PARTS USED

Workorder: V65334

In Date: 03/31/2014

Meter Reading:

Close Date: 04/02/2014

Problem?

tank to pump valve is very hard to use, needs attention. SB1 E AT 15

Task performed:

CHECK TANK TO PUMP LUBE LINKAGE AND ADJUST HANDLE RODS.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V60073

In Date: 10/15/2013
Close Date: 04/18/2014

Meter Reading: 89,932.00

Problem?

SPARE BATT 1-FAILED CAPACITY TEST- RIGHT INTAKE 2 1/2 LEAKS AIR-FAILED GLOVE TEST. HAD TO CAP RELIEF VALV TO PASS DRY VACUUM TEST. MAX GPM 1224.

Task performed:

SPARE BATT 1-FAILED CAPACITY TEST- RIGHT INTAKE 2 1/2 LEAKS AIR-FAILED GLOVE TEST. HAD TO CAP RELIEF VALVE TO PASS DRY VACUUM TEST. MAX GPM 1224.

Parts

NO PARTS USED

Quantity

Workorder: V66554

In Date: 05/17/2014
Close Date: 06/10/2014

Meter Reading:

Problem?

Battery switch is very hard to turn on and off Q15

Task performed:

Truck back at shop

Parts

NO PARTS USED

Quantity

Workorder: V66493

In Date: 05/15/2014
Close Date: 08/08/2014

Meter Reading:

Problem?

Battery switch is very hard to turn on and off. Needs new switch

Task performed:

travel to sta, 15 R&R bad batt, sw, and rewire system
R&R primer value leaking on floor and replum.
R&R bad rocker sw,on dash.

Parts

538028052VALVE PRIMER PUMP W/HARDWARE
SWT5492744435 ACTUATOR-BLACK

Quantity

1
3

Workorder: V68463

In Date: 08/06/2014
Close Date: 08/15/2014

Meter Reading:

Problem?

Rear A/C in cab blowing hot air

Task performed:

ck, out a/c on w/o v68630 needs additional work a/c compressor no good need to go to shop.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V68629

In Date: 08/12/2014

Meter Reading:

Close Date: 08/15/2014

Problem?

Rear suspension is very bad. Rear suspension bottoms out even while driving slow and gently.

Task performed:

Parts

Quantity

ck,out rear suspension inop spring and et look ok test drive unit cant repeat problem must only be over speed bumps unfound problem.
ck, water leak replaced primer vaule seal leak stop ok.

NO PARTS USED

Workorder: V68630

In Date: 08/12/2014

Meter Reading:

Close Date: 08/15/2014

Problem?

Air leak is pretty bad. One air tank will not fill as high as other. Air can be hear leaking after shut down. Low air symbol on dash frequent. Park brakes stick until air fills.

Task performed:

Parts

Quantity

travel to sta,15 ck, air leak found line leaking repaired line retested ok.
ck, out rear a/c not cold compressor not on found high side at 250 low side in vac, need to go to shop for repair,

NO PARTS USED

Workorder: V68685

In Date: 08/14/2014

Meter Reading: 92,080.70

Close Date: 08/21/2014

Problem?

Pressur governor inop @15

Task performed:

Parts

Quantity

WENT TO STA15 R&R GOV,PUMP CONTROLER CK, PUMP OPERATION NOT WORKING PROPERLY REMOVED LINES TROBLESHOOT SYSTEM REMOVED AND REBIULDED SENSING VALUE CK, OK RETURN HOME.

562008002PM CONTROL 562-0080-02

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

* FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V68699

In Date: 08/15/2014
Close Date: 08/26/2014

Meter Reading:

Problem?

Pressure relief valve is not working. Back flushed the pump this am, then exercised the pump and could not get the Pressure relief valve to work. I was told this morning it was just fixed???

Task performed:

ck, and tested on w/o v68759 work completed

Parts

Quantity

NO PARTS USED

Workorder: V68759

In Date: 08/18/2014
Close Date: 08/26/2014

Meter Reading:

Problem?

light on Pressure relief not working. Pressure relief valve works though. E15

Task performed:

travel to sta,15 ck, out pressure relief valve inop ck, system ran pump test system working ok now light ok also will monitor.

Parts

Quantity

NO PARTS USED

Workorder: V69028

In Date: 08/28/2014
Close Date: 08/29/2014

Meter Reading: 92,080.70

Problem?

AC COMPRESSORS SEIZED BELT BROKEN

Task performed:

Phone call A/C compressor locked up busted belt still operatable.

Parts

Quantity

NO PARTS USED

Workorder: V68993

In Date: 08/27/2014
Close Date: 09/08/2014

Meter Reading:

Problem?

Generator not starting

Task performed:

CK, OUT GEN NO START PULL OFF CARB CLEANED OUT GUMED UP REPLACED FUEL SHUT OFF IN CARB STILL WONT RUN GOOD WILL GET NEW GEN OUT HERE.

Parts

Quantity

16957-ZE1-812HONDA FUEL GROMET

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V69075

In Date: 08/31/2014

Meter Reading:

Close Date: 09/09/2014

Problem?

The "AUTO CHARGE" on E15 shows LOW even though it stays plugged in to shoreline. E15

Task performed:

1. TRAVEL TO STA,15 CK, OUT CHARGER ON TRUCK INOP, CHECK BATTS, AND CHARING SYSTEM OF TRUCK OK, CK, OUT 110V SYSTEM NO OUT PUT OF SYSTEM NEED CHARGER REPLACED NEED TO RETURN WITH ONE .
2. TRAVEL TO STA,15 R&R AUTO CHARGER ON UNIT AND REWIRED SYSTEM TESTED OK.

Parts	Quantity
0913912CHARGER 2000	1

Workorder: V69550

In Date: 09/20/2014

Meter Reading: 92,743.00

Close Date: 10/30/2014

Problem?

broken reflector on rear right bumper E15

Task performed:

Remove and replace broken reflector on rear bumper.

Parts	Quantity
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	1

Workorder: V69658

In Date: 09/24/2014

Meter Reading: 92,743.00

Close Date: 10/30/2014

Problem?

ONBOARD CHARGER FOR THE TRIPTIX CHARGER NOT WORKING R15

Task performed:

Travel to station 15 install charger port and wire up hot all the time for trip tix charger

Parts	Quantity
56415CIG. LIGHTER ACCES.	1

Workorder: V70643

In Date: 11/02/2014

Meter Reading: 93,918.20

Close Date: 11/07/2014

Problem?

Tank to pump lever snapped off in hand this am. Driver able to remain in service and handle for shift Sunday until fixed. E15

Task performed:

Travel to station 15. Check out pump to tank. Handle inoperable. R & R broken valve handle on p.p. and adjust valve.

Parts	Quantity
102AKRON LONG ARM RC-4	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V70779

In Date: 11/07/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Foam system not working. Mechanic fixed it.

Task performed:

Travel to station 15, check foam system inop. Clean out pump veins in pump test ok.

Parts

NO PARTS USED

Quantity

Workorder: V70780

In Date: 11/07/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

Emergency lights on OIC side mid body lower.

Task performed:

1. Check out light on pass side body-found light bad power and ground ok. R/R light and rewire
2. Check for air leaks per DR.-found cab air bags and valve leaking also shocks bad for cab will order.

Parts

50R03ZRRLLIGHT 500 TIR LED

Quantity

1

Workorder: V70781

In Date: 11/07/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

air leak at the front intake PTO switch.

Task performed:

Check air leak on clippard valve-R/R valve, R/R fittings and replumb.

Parts

MJTV5 VALVE AIR CONTROL

Quantity

1

Workorder: V70782

In Date: 11/07/2014

Meter Reading:

Close Date: 11/20/2014

Problem?

OIC side rear compartment hydraulic door spring broken and repaired.

Task performed:

Repair door hold open inop-R/R shock on door and repair bolts missing and replace.

Parts

EAA-8350-30UGSS1783UQ STRUT-LIFT

Quantity

1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V69038

In Date: 08/29/2014
Close Date: 12/08/2014

Meter Reading: 92,080.70

Problem?

A/C inop

Task performed:

1. Performed a/c performance and leak tests. Replaced seized compressor, dryer and section hose end at compressor. Charged system. Found clogged expansion valve on rear cab a/c. Recovered system. R & R rear x-valve. Charged system to specifications.

2. Diagnose cab auxiliary a/c. R & R compressor. R & R fitting at compressor blow thru lines. Evacuate and recharge system. Low side in vacuum. Exp valve blocked. Discharge system. Start removal of exp valve.

Parts	Quantity
11-262571R7500 TRI SWITCH MALE	1
160012-2012A EXPANSION VALVE 71R8301	1
4512S08-6933BS A/C FITTING STEEL	1
576403-3470 COMPRESSOR A/C 5720	1
74R258607-2613A RED DOT DRIER 7127	1
9440BELT	1

Workorder: V72057

In Date: 01/05/2015
Close Date: 01/05/2015

Meter Reading: 94,617.00

Problem?

repair seat and hose bed cover

Task performed:

repair seat and hosbed cover

Parts	Quantity
NO PARTS USED	

Vendor?: CENTRAL



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

Workorder: V71615

In Date: 12/12/2014

Close Date: 01/20/2015

Meter Reading: 94,719.00

Problem?

C inspection SBE1

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

1. C inspection- air tires, remove air cleaner and clean filter
2. Replaced wipe blades
3. Replaced washer reservoir cap, add washer concentrate and fill reservoir. Test squirts ok
4. Replaced rear AC filter clean protective screen
5. Remove accreted: decals. Remove glue and buff out body
6. Check generator fueled tank and check output
7. Remove and R frt seat for repair
8. Remove hosebed cover for repair
9. Remove L rear seat for repair
10. Left door trim broken, removed door panel replaced trim. Install new screws with larger washers.
11. L rear door trim broken-removed door panel, replaced trim. Install new screws with larger washers.
12. R frt door trim loose-found missing screws removed door panel and install screws and washers.
13. Clean and paint fuel cap
14. Replaced FRT suction strainer
15. Remove L frt rocker cover-cut and splice in new weatherstrip
16. Replaced L rear rocker cover and splice in piece of weatherstrip
17. R rear seatbelt twisted
18. Knob missing from rear AC unit, install universal knob. Mark knob position in correct spot with paint pen. Covered wrong marking with black to cover wrong location.
19. Rear AC register missing, removed evaporator cover and replaced register.
20. Diagnose miv. closed light indicator inop. Clean and lube socket, replaced bulb. Bulb loose in socket, replaced light assembly, splice and heat shrink connections.
21. Tighten R-1 door nades pins
22. Diagnose failed dry vacuum test. Found leaking R intake drain valve. Rebuild valve and retest.
23. Rebuild dryer and purge valve
24. Trans service
25. T case service
26. Retorque u bolts
27. Tighten R-3 door striker screws and adjusted
28. Replaced rear tail board marker lights.
29. Remove rear campaign sign frames, remove mastic and buff out body
30. Tighten L-1 & L-3 striker pin bolts-adjusted
31. Remove toot brackets from doors and tighten allen screws on back side for axe holder. Re-thread door screws on inside door
32. Extend a gun wiring disconnected, reconnect wiring. Add length of wire, heat shrink connections, test operation of warning system, ok.
33. Hurst tool bracket pins and cables missing or

01-0269477-00BALLAST 4 CHANNEL LED LIGHTBAR 01-02	1
040114003SEAL SVS DRAIN VALVE	4
107796DRYER KIT AD9 -NEW	1
15W40BSYN OIL BULK QTS	23
22-40868-000WASHER CAP WPB-FREIGHTLINER	1
29526898 29548988 TRANS FILTER ALLISON	1
35200-RLIGHT MARKER LED RED	2
52-24WIPER BLADES ANCO 24	2
546-00011-001HALE RED INDICATOR LED	1
68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
6806840018DOOR SILL L/H	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
A1834388002MOLD L/H	2
ACX-84534LUG NUT COVER PK10	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1
S PLACARD INSERTFRONT AND BACK INSERT CARD	2
TRANSYNDALLISON TRANS FLUID GAL	4
WAT61403STRAINER 6 IN	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155566

*** FIRE DEPARTMENT PUMPER NFPA COMPLIANT**

- damaged-replaced pins, canles and rings.
- 34. Repair missing discharge caps and chains. Remove cap and chain from surplus engine.
- 35. Protect cooling bleed hose-reroute and install loom with tie straps to secure
- 36. Adjusted air horns for sound quality
- 37. Lubricate rpm counter
- 38. Intake relief leaking-drain pump connect air line to service port and force water and air to clean relief valve seat.
- 39. Tighten AC belts
- 40. Test drive vehicle and check trans fluid hot after serice. Add 2 qts to bring fluid to full hot.
- 41. Install left rear and right frt seats back from repair
- 42. Replaced hose bed fasteners on truck. Relocate, drill and tap and move fasteners for correct fit of cover. Repair grometsi n hose bed cover and install.
- 43. Make up buckles to snap to hose bed male ends. Cut to size, drill holes through web-pop rivet strap together with back up washers.
- 44. Calibrate foam and water flow meters.
- 45. Trans dipstick won't tighten swap out dipstick with surplus vehicle
- 46. Swap left frt and right frt-replaced missing lug nut cover. Road test and check for pulling ok per Jim.
- 47. QA veh
- 48. Replaced broken pump panel light lens
- 49. FRT light bar piercing light left side-inop diagnose problem-found bud ballast. Disassemble light bar and replaced ballast. Reinstall parts and test ok

Workorder: V73125

In Date: 02/12/2015

Meter Reading:

Close Date: 05/12/2015

Problem?

Engine has an air leak under the cab to the point were there is no air in system after 1 hour. Vehicle is now at Station 19.

Task performed:

Parts

Quantity

1. Travel to ST-15. Check out air leak under cab. Found bad fitting. R&R fitting test ok.

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10155566) 2004 - FERRARA FL80 1250 Gpm Pumper

10155566

CSHOP-2015-1973

Comments: SCENE LIGHTS INOP INCLUDING TELELIGHTS AND PANEL LIGHTS SE@15

Date Opened: 7-27-2015 Date Finished: 8-5-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

CSHOP-2015-2178

Comments: WIF LIGHT ON DASH SPARE ENGINE AT 19 CAB SPOTLIGHT INOP

Date Opened: 8-6-2015 Date Finished: 8-20-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL SYSTEM
SPOT LIGHTS

1 9IP; N122WSKL4000 SENSOR WATER IN FUEL

CSHOP-2015-2290

Comments: REPLACE TIRES

Date Opened: 8-12-2015 Date Finished: 8-12-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-3410

Comments: DROP COOLANT OFF TO STA 17

Date Opened: 10-13-2015 Date Finished: 10-13-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

Asset Work Order History 10155566

CSHOP-2015-3448

Comments: SE@17

Date Opened: 10-15-2015 Date Finished 10-21-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

Service Requests:

10/15/2015 AIR RIDE / 44: WORN / EXCHANGE - NEW
AIR LEAK SPARE ENGINE AT STATION 17

CSHOP-2015-3449

Comments: SE@17

Date Opened: 10-15-2015 Date Finished 10-22-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

Q PARTS

COOLING SYSTEM	1	9IP; TURBO REPLACES 3800401RX
ENGINE AND ACCESSORIES	1	LIGHT; LIGHT LED RED TIR 6
DIAGNOSE ELECTRICAL	1	9IP; AIR RIDE VALVE (CAB)
AIR SYSTEM	2	FREIGHTLINER; CAB AIR BAG IS4007

Service Requests:

10/15/2015 LIGHTS / 10: BENT / OVERHAUL
SCENE LIGHTS ARE NOT WORKING SPARE ENGINE AT STATION 17

10/16/2015 LIGHTS / 10: BENT / REPAIR
SIDE OF HOOD PASSENGER SIDE EMERGENCY LIGHT NOT WORKING TRUCK IS IN SERVICE AT STATION 17 NOW

10/16/2015 STEERING / 18: LEAKING / REPAIR
BOTH FRONT TIRES WERE REPLACED 10/13, THEY HAD EXTREME WEAR TO THE OUTSIDE OF BOTH FRONT TIRES. ALIGNMENT SEEMS TO BE OFF, THE OUTSIDES WERE BELOW 4/32" AND THE INSIDES APPEARED TO BE AT ABOUT HALF OF TOTAL WEAR, LIFE CYCLE WAS SIGNIFICANTLY AFFECTED

10/16/2015 BRAKES / 18: LEAKING / REPAIR
AIR LEAK ON THE EMERGENCY SIDE, LEAKS APPROX 30PSI OR MORE PER MINUTE. CAN HEAR AIR RELEASE UNDER CAB, UNABLE TO LOCATE EXACT LOCATION.

10/17/2015 SERVICE REQUEST / 18: LEAKING / REPAIR
FLASHLIGHT CHARGERS AND SAFETY PAD PLUG NOT WORKING ON CENTER CONSOLE. ENGINE IS INSERVICE AT STATION 17

CSHOP-2015-3921

Comments: E17 EMER LIGHT OUT

Date Opened: 11-12-2015 Date Finished 12-8-2015 Meter 1 Reading: 95,165

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHT BAR

Service Requests:

11/12/2015 LIGHTS / 19: LOOSE / INSPECT
FRONT DRIVERS SIDE FORWARD FACING EMERGENCY LIGHT IN LIGHTBAR NOT WORKING

Asset Work Order History 10155566

CSHOP-2015-4138

Comments: **SBE1 B INSPECTION**

Date Opened: 11-24-2015 Date Finished 12-1-2015 Meter 1 Reading: 99,481

TASKS PERFORMED

Q PARTS

PM SERVICE B

4 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
1 FILTER; OIL FILTER 51748

CSHOP-2015-4234

Comments: **REPAIRS FROM INSPECTION**

Date Opened: 12-1-2015 Date Finished 12-8-2015 Meter 1 Reading: 99,489

TASKS PERFORMED

Q PARTS

HOSE BED BODY
WIPER BLADES
PARK-CLEARANCE LIGHTS
BATTERY
TIRE
REAR BRAKE PADS-SHOES
AIR DRIER
AIR HORN
A/C HOSES/FITTINGS

2 WIPER; WIPER BLADES ANCO 24
1 LIGHT; TOP CLEARANCE LIGHT M2
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D
1 VALVE; PURGE VALVE KIT
1 DRYER; 07-2613A RED DOT DRIER 7127
1 GOVERNOR; GOVERNOR D-2
1 DRYER; DRYER KIT AD9 -NEW
1 DRAIN; DRAIN COCK
1 VALVE; VALVE CHECK AD9
1 FILTER; 78R5360M 2PK FILTER AIR COND
1 9IP; 12-2012A EXPANSION VALVE 71R8301

CSHOP-2016-2327

Comments: **ST16**

Date Opened: 5-16-2016 Date Finished 5-18-2016 Meter 1 Reading: 100,993

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

05/14/2016 LIGHTS / 12: BROKEN / REPAIR
THE DRIVER SIDE HEADLIGHT WENT OUT. THE HIGH BEAM WORKS.

CSHOP-2016-3571

Comments: **DEAD BATTERY**

Date Opened: 7-26-2016 Date Finished 7-29-2016 Meter 1 Reading: 101,190

TASKS PERFORMED

Q PARTS

BATTERY

4 BATTERY; BATTERY 950CCA HP-31D
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

Asset Work Order History 10155566

CSHOP-2016-4417

Comments: **DOOR OPEN WARN GOING OFF NEEDS TO GO TO SHOP**

Date Opened: 9-10-2016 Date Finished 11-7-2016 Meter 1 Reading: 101,722

TASKS PERFORMED

NO PARTS USED

DISCHARGE GAUGE
LIGHTING SYSTEM

Service Requests:

09/10/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
DISCHARGE GAUGES ON THE DRIVER PANEL ARE NOT WORKING.

CSHOP-2016-4863

Date Opened: 10-11-2016 Date Finished 10-11-2016 Meter 1 Reading: 101,408

TASKS PERFORMED

Q PARTS

STARTER

1 STARTER; 6808 38MT 12T STARTER

CSHOP-2016-5066

Comments: **AT STATION 15**

Date Opened: 10-24-2016 Date Finished 12-15-2016 Meter 1 Reading: 102,642

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
AIR SYSTEM

Service Requests:

10/21/2016 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING, EMERGENCY LIGHT BAR ON ROOF WORKS INTERMITTENTLY. WHILE RESPONDING TO A CALL I NOTICED THAT VEHICLES WERE NOT MOVING TO THE SIDE AND AT THE CALL THE LIGHTS WERE NOT WORKING. I RESTARTED THE TRUCK AND THEY WORKED, HOWEVER I NOTICED SEVERAL LIGHTS STILL APPEARED TO BE OUT. THIS NEEDS FIXED.

12/15/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST- AIR LEAK ON SPARE ENGINE 15 HAS SUDDENLY GOTTEN SO BAD THAT AIR TANKS ARE COMPLETELY EMPTY BETWEEN START UPS. THIS IS CAUSEING THE ENGINE TO RUN IN THE BAY EXCESSIVELY AT EVERY START UP AND CAUSING DELAY IN RESPONSE. THIS NEEDS REPAIRED ASAP. THANK YOU

CSHOP-2016-5572

Comments: **ON-CALL E15 PUMP SHIFT**

Date Opened: 11-29-2016 Date Finished 12-1-2016 Meter 1 Reading: 102,455

TASKS PERFORMED

Q PARTS

FIRE PUMP

1 PUMP; VPS SHIFT KIT 546-0370-53-0

Asset Work Order History 10155566

CSHOP-2016-6039

Comments: **BATT 1 SPARE AT 15 COOLANT LEAK**

Date Opened: 12-27-2016

Date Finished

1-19-2017

Meter 1 Reading:

102,857

TASKS PERFORMED

LADDER INSPECTION
PONY PUMP MOTOR
COMPARTMENT LIGHT BODY
FIRE PUMP
EQUIPMENT MOUNTING BRACKETS
SIDE COMPARTMENT BODY
DOOR LATCH
WIPER BLADES
REPAIR FROM PM - FOAM SYS
REPAIR FROM PM - FIRE PUMP SYS
REPAIR FROM PM - GENERATOR
COOLING SYSTEM
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
INDICATOR LIGHT
BELT
FUSE BLOCK
ELECTRICAL
TRANSFER CASE
RESERVOIR
BRAKES
AIR DRIER
AIR SYSTEM
AIR HORN
SEAT BELTS
HVAC SYSTEM

Q

PARTS

6	9IP; 9IP
1	9IP; 9IP
1	9IP; VALVE KIT SS VALVE 3 IN
1	ANODE; ANODE ONLY
1	9IP; 9IP
2	9IP; 9IP
1	GAUGE; VAC TEST GAUGE 0-30
2	CHAIN; BEADED CHAIN W/CONN 12
1	9IP; ORING KIT
1	9IP; VALVE KIT SS 546-2270-02-0
2	LIGHT; MARKER LIGHT
1	LMP; HALOGEN LAMP
1	SWITCH; 82-2151 SWITCH MOMENTARY 24-372
1	BELT; BELT
1	BELT; BELT
1	BELT; BELT
2	9IP; STUD DZ
1	FUSE; COVER FUSE PANEL
8	9OC; GEAR OIL BULK
5	9OC; BULK TRANS SYN
-1	9IP; 9IP
1	9IP; 9IP
-2	TWD; BRAKE DRUM
2	TWD; TWD
2	2TP; 2TP
1	MBI; GRIP/KIT
1	9IP; 9IP
1	9IP; 9IP
1	HORN; KIT-AIR HORN-GROVER
1	9IP; VALVE CORE
3	9XX; 134A 10194654

Service Requests:

12/22/2016

ENGINE / 18: LEAKING / REPAIR

SPARE ENGINE AT ST15 HAS LARGE PUDDLE OF ENGINE COOLANT UNDERNEATH ENGINE ON GROUND.

Asset Work Order History 10155566

CSHOP-2017-1575

Comments: **BATT 1 SPARE AT 18**

Date Opened: 3-14-2017 Date Finished 3-17-2017 Meter 1 Reading: 103,094

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

Service Requests:

03/13/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
WE HAVE THIS SPARE ENGINE AT STATION 18. IT WAS DELIVERED TO US TODAY WITH NO HANDLIGHTS. THE LIGHTS WE HAVE ON OUR ENGINE ARE NOT TRANSFERABLE OVER TO THE SPARE THAT WAS DELIVERED TODAY. WE ALSO HAVE NO PORTABLE DOCKING STATION MOUNTED ON THE SPARE TRUCK, AND NO CHARGER AT THE STATION. ALSO, THE MSA/TIC DEVICE STRAP IS BROKEN WHERE THE SPARE BATTERY SITS, AND WE ARE UNABLE TO ATTACH THE SPARE BATTERY TO THE TIC HOLDER. WE NEED A NEW STRAP TO HOLD THE SPARE BATTERY IN THE DOCKING STATION.

CSHOP-2017-1919

Date Opened: 3-31-2017 Date Finished 5-31-2017 Meter 1 Reading: 105,073

TASKS PERFORMED

NO PARTS USED

AIR HORN

Service Requests:

03/31/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SERVICE REQUEST AIR HORN INOP

CSHOP-2017-2965

Comments: **E14**

Date Opened: 5-18-2017 Date Finished 6-1-2017 Meter 1 Reading: 105,073

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT

Service Requests:

05/18/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT

CSHOP-2017-3088

Comments: **SPARE AT 16**

Date Opened: 5-25-2017 Date Finished 6-1-2017 Meter 1 Reading: 105,073

TASKS PERFORMED

NO PARTS USED

SIREN

Service Requests:

05/25/2017 SERVICE REQUEST / 19: LOOSE / ADJUST
SIREN KNOB TO CHANGE TONES JUST SPINS, WILL NOT CHANGE. POSSIBLY NEEDS NEW KNOB. TRUCK AT STATION
16

Asset Work Order History 10155566

CSHOP-2017-3186

Date Opened: 5-31-2017 Date Finished 6-23-2017 Meter 1 Reading: 105,458

TASKS PERFORMED

NO PARTS USED

STROBE LIGHTS

Service Requests:

05/31/2017 LIGHTS / 22: MISALIGNED / ADJUST
REAR TOP DRIVERS SIDE WARNING LIGHT HALF OUT, PORTION THAT FACES OUT TOWARDS TRAFFIC WHEN ANGLED FOR BLOCKING.

CSHOP-2017-3874

Date Opened: 6-30-2017 Date Finished 8-2-2017 Meter 1 Reading: 106,048

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
FOAM SYSTEM
AUTO-EJECT

1 5SC; AUTO EJECT KIT W/YELLOW CVR

Service Requests:

07/02/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST - THE FOAM TANK LEAKS AFTER SHUTTING DOWN THE "TANK TO PUMP" AND "RECIRCULATION" VALVES.

CSHOP-2017-4644

Date Opened: 8-10-2017 Date Finished 9-5-2017 Meter 1 Reading: 106,400

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
DOOR PROP CYLINDER
COOLING SYSTEM
HUB CAP
A/C FILTER

6 5AH; GAS SPRING, 12.087", 34LB
1 9IP; CAP RADIATOR 10 LB
1 NOS; SCOTSEAL HUB CAP
-2 NTL; OIL SEAL
2 NTL; OIL SEAL
2 BRG; WHEEL BEARING CONE
1 9IP; 340-4024 HUB COVER - FRONT AXLE 2004 RES
4 MAC; NON-CHLOR BRAKE CLNR
2 9IP; SEAL 35066
2 BRG; WHEEL BEARING CUP
2 BRG; HD TAPER BEARING SET
1 9IP; 78R5360M 2PK FILTER AIR COND

CSHOP-2017-6042

Comments: **DEAD BATTERY BATTALION SPARE AT ST18**

Date Opened: 10-19-2017 Date Finished 10-25-2017 Meter 1 Reading: 106,533

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

Asset Work Order History 10155566

CSHOP-2017-6604

Date Opened: 11-15-2017 Date Finished 11-21-2017 Meter 1 Reading: 106,552

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

4 1AD; BATTERY 31 SERIES

Service Requests:

11/15/2017 ENGINE / 12: BROKEN / REPAIR
ENGINE BATTERIES ARE DEAD, IT WILL NOT TURN ON

CSHOP-2017-6961

Comments: **SE AT 15**

Date Opened: 12-6-2017 Date Finished 1-29-2018 Meter 1 Reading: 106,552

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EQUIPMENT MOUNTING BRACKETS

2 9ME; STRAP

Service Requests:

12/05/2017 BODY / 44: WORN / EXCHANGE - NEW
BODY ISSUE, VELCRO STRAP ON REAR BUMPER OF ENGINE THAT HOLDS THE HOSE CLAMP SECURELY NEEDS TO
BE REPLACED. THIS IS THE SPARE ENGINE AT STATION 15.

CSHOP-2017-86

Date Opened: 1-4-2017 Date Finished 1-11-2017 Meter 1 Reading: 102,857

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 9IP; 9IP
23 9OC; SYN 15W40
1 9IP; 9IP
1 9IP; 9IP
1 9IP; 9IP
1 9IP; 9IP

CSHOP-2018-1112

Date Opened: 2-23-2018 Date Finished 3-2-2018 Meter 1 Reading: 106,570

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
21 9IP; 15W40 MOTOR OIL NON SYN
21 9IP; 15W40 MOTOR OIL NON SYN
-21 9IP; 15W40 MOTOR OIL NON SYN
1 FIL; FUEL WATER SEPARATOR
1 FIL; NAPAGOLD OIL FILTER

Asset Work Order History 10155566

CSHOP-2018-1410

Date Opened: 3-9-2018

Date Finished

3-13-2018

Meter 1 Reading:

106,570

TASKS PERFORMED

Q PARTS

RESTRAINT

1 9AP; TIE STRAP

CSHOP-2018-1828

Comments: **REPAIRS FROM PM**

Date Opened: 4-2-2018

Date Finished

6-19-2018

Meter 1 Reading:

107,107

TASKS PERFORMED

Q PARTS

FOAM SYSTEM

1 1DB; PUMP

PRIMING PUMP FIRE PUMP

1 9IP; THROTTLE EXCEL CUMMINS IS SERIES

FIRE PUMP

-1 9IP; THROTTLEEXCELCUMMINISSERIES

HOSE REEL

1 5TN; SWITCH DOOR DPST NC MOM

DISCHARGE GAUGE

1 1WL; LENS, CLEAR, 4" FLAT RND

HOSE BED BODY

1 5TN; DOOR SWITCH CONNECTOR

WIPERS-WASHER

2 5SC; GAUGE 4.5" -30 TO 600PSI

SPOT LIGHTS

1 9HY; HOSE

PARK-CLEARANCE LIGHTS

1 2FL; PUMP, WASHER W/HARNES

TRANSFER CASE

2 9AP; BULB, 150W HALOGEN

ALIGNMENT

10 LMP; LAMP

U-BOLTS

1 BK; PTEX ULTRA BLACK 30Z

AIR DRIER

1 TWD; AD-9KIT

AIR SYSTEM

1 9IP; VALVE CHECK AD9

MIRRORS

1 TWD; AD-9KIT MINOR

A/C CONDENSER FAN

1 MBI; AIR PRESSURE VALVE

A/C FILTER

1 GRO; CONVEX MIRROR

2 TEM; BLOW/MOT

CSHOP-2018-3676

Comments: **PRE TRIP**

Date Opened: 6-29-2018

Date Finished

6-29-2018

Meter 1 Reading:

107,242

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2018-4587

Date Opened: 8-15-2018

Date Finished

9-25-2018

Meter 1 Reading:

107,778

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE PUMP

LIGHTING SYSTEM

Service Requests:

08/15/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
AIR HORN BUTTON ON PUMP PANEL DOES NOT WORK

08/15/2018 RADIATOR / 12: BROKEN / REPAIR
PUMP OVEHEAT WARNING LIGHT NOT WORKING ON PUMP PANEL

Asset Work Order History 10155566

CSHOP-2018-4588

Comments: **SPARE ENGINE AT 16**

Date Opened: 8-15-2018

Date Finished

8-23-2018

Meter 1 Reading:

107,549

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
SPOT LIGHTS
AIR SYSTEM
AIR HORN

1 LMP; LAMP, RO BLISTER PK
2 9AP; BULB, 150W HALOGEN
1 9IP; VALVE AIR CONTROL
1 9AP; HORNBLASTER SOLENOID

Service Requests:

08/15/2018 LIGHTS / 18: LEAKING / REPAIR LEAK
SPOTLIGHT ON PASSENGER SIDE HAS ONE BULB BURNT OUT

08/15/2018 BRAKES / 12: BROKEN / REPAIR
AIR LEAKS OUT WITHIN 2 HOURS TO 0 ON SECONDARY TANK. HAS TO AIR UP BEFORE MOVING TRUCK

08/16/2018 SERVICE REQUEST / 12: BROKEN / REPLACE SOLENOID AND REPAIR AIR LEAKS
AIR HORN IN CAB NOT WORKING

CSHOP-2018-5574

Date Opened: 10-1-2018

Date Finished

11-6-2018

Meter 1 Reading:

109,133

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

09/29/2018 A/C / 49: CAN NOT DUPLICATE CONCERN / INSPECT
REAR A/C UNIT TURNS ON FOR ABOUT 2 MINUTES AND THEN SHUTS OFF FOR ABOUT 5 MINUTES AND CYCLES IN THIS FORMAT.

CSHOP-2018-5930

Date Opened: 10-18-2018

Date Finished

11-7-2018

Meter 1 Reading:

109,133

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DISCHARGE GAUGE
FIRE APPARATUS

3 5CS; GAUGE
1 5TF; REED SWITCH

Service Requests:

10/18/2018 ALARMS / 21: MISADJUSTED / ADJUST
ALARM GOING OFF FOR DECK GUN EXTENDED

10/24/2018 ALARMS / 21: MISADJUSTED / ADJUST
DECK GUN ALARM IS GOING OFF AGAIN AFTER ALREADY BEING FIXED THIS WEEK . THE ALARM IS INTERMITTENT AND WILL SOME TIMES GO OFF IF I RESTART THE TRUCK.

10/24/2018 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
DISCHARGE GAUGES 1,3, AND 4 DO NOT READ CORRECT PRESSURES. THEY WILL GET STUCK THEN SHOOT UP. THEY ARE ALSO ALL LOW OR HAVE NO OIL IN THE GLASS.

Asset Work Order History 10155566

CSHOP-2018-5978

Date Opened: 10-20-2018 Date Finished 10-20-2018 Meter 1 Reading: 108,659

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2018-6478

Date Opened: 11-14-2018 Date Finished 11-26-2018 Meter 1 Reading: 109,421

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INTAKE VALVE
LIGHTING SYSTEM

Service Requests:

11/14/2018 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE LIGHTS NOT WORKING NO EXTENDED SPOT LIGHTS FROM DRIVER AREA AND HORN FROM DRIVER AREA
ALSO NOT WORKING

CSHOP-2018-6920

Comments: **PUMP TEST REPAIRS**

Date Opened: 12-5-2018 Date Finished 1-10-2019 Meter 1 Reading: 109,955

TASKS PERFORMED

Q PARTS

FIRE PUMP

-1 5EO; PS GASKET
1 9IP; SLIDE CONTROL 519007110
-1 5EO; PS PUMP
1 5EO; PS PUMP
1 5EO; PS GASKET

CSHOP-2018-7334

Comments: **BOBBY DETAILED THIS VEHICLE ON 12-26-18 WAITING ON INVOICE**

Date Opened: 12-26-2018 Date Finished 5-23-2019 Meter 1 Reading: 109,421

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - DECALS/CLEANLINESS

1 9AP; DETAIL 10155566

CSHOP-2019-1019

Date Opened: 2-25-2019 Date Finished 3-12-2019 Meter 1 Reading: 110,715

TASKS PERFORMED

Q PARTS

SMALL ENGINE REPAIR
AUTO-EJECT

6 NOL; NAPA HEAVY DUTY 30QT

Service Requests:

02/24/2019 SERVICE REQUEST / 11: BINDS/STICKS / LUBRICATE
SHORELINE SOMETIMES DOES NOT POP OUT

Asset Work Order History 10155566

CSHOP-2019-170

Date Opened: 1-10-2019 Date Finished 1-22-2019 Meter 1 Reading: 109,958

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FIL; NAPA COOLANT FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; FUEL WATER SEPARATOR
1 FIL; NAPAGOLD AIR FILTER
24 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2019-2177

Comments: **AT-19**

Date Opened: 4-25-2019 Date Finished 5-23-2019 Meter 1 Reading: 111,315

TASKS PERFORMED

NO PARTS USED

FIRE PUMP

Service Requests:

04/25/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
THE PUMP ENGAGED AND PUMP READY INDICATOR LIGHTS ARE NOT WORKING. THE PRESSURE RELIEF VALVE LIGHT IS NOT WORKING AS WELL.

CSHOP-2019-2244

Comments: **SPARE ENGINE AT 19**

Date Opened: 4-29-2019 Date Finished 4-30-2019 Meter 1 Reading: 110,977

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
AIR SYSTEM
DOOR ALARM OR OTHER WARNING

3 2TP; DIAHPRAM
1 TWD; AIR BRAKE CHAMBER

Service Requests:

04/27/2019 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE LIGHTS NOT WORKING DRIVER SIDE TELESCOPIC WORK LIGHTS NEEDS A BULB REPLACED

04/27/2019 AIR RIDE / 18: LEAKING / EXCHANGE - NEW
REAR AIR LEAK WHILE DRIVING

04/29/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
EXTENDED GUN LIGHT AND BUZZER GOING OFF WHEN IN DRIVE

Asset Work Order History 10155566

CSHOP-2019-3078

Comments: **SPARE ENGINE AT ST16**

Date Opened: 6-14-2019 Date Finished 6-18-2019 Meter 1 Reading: 111,517

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT

Service Requests:

06/13/2019 SERVICE REQUEST / 12: BROKEN / INSPECT
TYPE PROBLEM INTO DESCRIPTION, SMOOTH BORE 2 1/2 STACK TIP NOZZLE HANDLE ON RIGHT SIDE BROKE. STILL OPERABLE.

CSHOP-2019-3112

Comments: **SPARE ENGINE AT 16**

Date Opened: 6-17-2019 Date Finished 6-28-2019 Meter 1 Reading: 111,948

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 9IP; SPOTLIGHTREMOTE
1 LIT; LED M C LAMP

Service Requests:

06/15/2019 LIGHTS / 12: BROKEN / REPAIR
EMERGENCY LIGHT BAR ON ROOF, THE LIGHT ABOVE DRIVER IS NOT WORKING. SPOT LIGHT NOT WORKING. REAR UPPER LIGHT NEXT TO EMERGENCY LIGHT NOT WORKING; DRIVER SIDE.

CSHOP-2019-316

Comments: **PM REPAIRS**

Date Opened: 1-17-2019 Date Finished 2-14-2019 Meter 1 Reading: 109,958

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
FIRE APPARATUS
WIPER BLADES
WIPERS-WASHER
BODY EXTERIOR

1 9IP; CHECK VALVE INJECTOR HALE FOAM SYS
20 9AP; HEAT SENSOR LADDER LABELS
2 1AN; WIPER BLADES
1 9IP; LH W LOCK SLIDE 500 LBS
1 8HD; WIREWHEELS
2 5SC; 12 CHAIN
2 MMM; MARINE ADH SEAL WHITE
1 5AH; GAS SPRING, 12.087", 34LB

Asset Work Order History 10155566

CSHOP-2019-3501

Comments: **SPARE BATTALION ENGINE AT ST16**

Date Opened: 7-5-2019

Date Finished

7-30-2019

Meter 1 Reading:

112,655

TASKS PERFORMED

QUALITY CHECK-REPAIRS
EXHAUST MANIFOLD
LIGHT BAR
CABIN AIR FILTER

Q PARTS

1	2CU; TURBOCLAMPVBAND
4	2CU; EXHAUSTMANIGASKET
1	2FL; CLAMP
4	2CU; SCREWSTUDD
1	FIL; NAPA COOLANT FILTER
2	2CU; EXHAUSTMANIGASKET
1	9IP; 3286499 HOSE OIL RETURN
4	2CU; EXHUAST BOLT SPACER
8	2CU; EXHUAST BOLT SPACER
8	2CU; EXHUAST MANI BOLT
1	9IP; BALLAST4CHANNELLEDLIGHTBAR01026974
1	2RD; FILTER, 17.5X5.5, MASTER PK (2)

Service Requests:

07/05/2019 LIGHTS / 12: BROKEN / REPLACED BALLAST
DRIVERS SIDE LED EMERGENCY LIGHT IN LIGHTBAR NOT WORKING

CSHOP-2019-3536

Comments: **BATT 1 SPARE AT STATION 16**

Date Opened: 7-8-2019

Date Finished

7-30-2019

Meter 1 Reading:

112,587

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
SAFTEY-EMERGENCY EQUIPMENT

Q PARTS

3	9AP; BULB, 150W HALOGEN
---	-------------------------

Service Requests:

07/08/2019 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
EMERGENCY LIGHTS, FRONT LIGHTBAR RED LED OUT OVER DRIVERS SIDE.

CSHOP-2019-4213

Date Opened: 8-11-2019

Date Finished

8-27-2019

Meter 1 Reading:

112,685

TASKS PERFORMED

TURBOCHARGER

Q PARTS

1	9HC; CHARGE AIR COOLER SVC
1	2FL; GASKET
1	2FL; GASKET
1	2FL; CONNECTOR
1	8HD; BRAIDED NYLON
1	2CU; TURBOREPLACES3800401RX
1	9AP; HAND SOAP PUM TOTAL TRK

Asset Work Order History 10155566

CSHOP-2019-4220

Date Opened: 8-12-2019 Date Finished 8-12-2019 Meter 1 Reading: 112,685

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

08/11/2019 ENGINE / 12: BROKEN / REPAIR
POSSIBLE PROBLEM WITH TURBO. WHINE AND RATTLE COMING FROM AREA OF TURBO.

CSHOP-2019-4847

Date Opened: 9-13-2019 Date Finished 9-17-2019 Meter 1 Reading: 113,085

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS

Service Requests:

09/13/2019 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
ENGINE: ELECTRIC THROTTLE ON PUMP PANEL HAS TO BE TURNED QUICKLY TO GET A RESPONSE AND HAVE THE ENGINE RPM'S INCREASE. THIS CAN CAUSE AN UNSAFE SPIKE IN NOZZLE REACTION.

CSHOP-2019-4848

Date Opened: 9-13-2019 Date Finished 9-17-2019 Meter 1 Reading: 113,085

TASKS PERFORMED

NO PARTS USED

HOSE BED BODY

Service Requests:

09/13/2019 SERVICE REQUEST / 12: BROKEN / INSPECT
BACK TARP OVER HOSE BED HAS LOST ATTACHMENT POINTS WHICH CAUSE IT TO FLAP DURING DRIVING.

CSHOP-2019-4849

Date Opened: 9-13-2019 Date Finished 9-17-2019 Meter 1 Reading: 113,085

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 9IP; 11 3050 SWITCH BLOWER

Service Requests:

09/13/2019 A/C / 38: SHORTED / EXCHANGE - NEW
A/C ISSUE, A/C SWITCH HAS TO BE SWITCHED FROM OFF TO MAX POWER MULTIPLE TIMES TO ENGAGE A/C

Asset Work Order History 10155566

CSHOP-2019-5071

Comments: **BATT 1 SPARE ENGINE AT 19**

Date Opened: 9-26-2019 Date Finished 10-1-2019 Meter 1 Reading: 113,644

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SHORELINE CHARGER
AIR SYSTEM
AIR HORN

2 2DD; SWITCH ALLISON AIR ELEC
1 6KU; 6KU
1 2DD; 2DD
2 9AP; HORN KIT PAI 3390 1094

Service Requests:

09/25/2019 BRAKES / 18: LEAKING / EXCHANGE - NEW
BRAKE ISSUES. PARKING BRAKE BUTTON LEAKING AIR WHEN PRESSED IN TO RELEASE PARKING BRAKE.

09/25/2019 SERVICE REQUEST / 38: SHORTED / INSPECT
CHARGING PLUG SHOWS ONE BAR ONLY NOT CHARGING ALL THE WAY.

CSHOP-2019-5120

Date Opened: 9-30-2019 Date Finished 10-1-2019 Meter 1 Reading: 113,644

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

09/27/2019 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES; AIR LEAK NOTICED BEHIND DASH CLUSTER. GAUGE LEAKED DOWN FROM 110-60PSI IN APX. 1 HOURS TIME.

CSHOP-2019-5121

Date Opened: 9-30-2019 Date Finished 10-1-2019 Meter 1 Reading: 113,644

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

09/28/2019 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES ENGINE HAS A SLOW LEAK IN THE AIR SYSTEM THAT TAKES THE PSI DOWN IT DOWN TO NEAR EMPTY AFTER ABOUT 3 HOURS OF NON USE. CAN NOT HEAR LEAK.

Asset Work Order History 10155566

CSHOP-2019-5122

Date Opened: 9-30-2019 Date Finished 11-14-2019 Meter 1 Reading: 146,943

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM
AIR HORN

1 TWD; AIR VALV
1 TWD; PP DCVALVE DASH
1 TWD; VELVAC

Service Requests:

09/28/2019 ALARMS / 12: BROKEN / EXCHANGE - NEW
ALARM SIGNALS AIR HORN ON DRIVERS SIDE HAS A BROKEN BRACKET. HORN IS STILL ATTACHED TO RIG BUT NEEDS A NEW ONE.

CSHOP-2019-5189

Comments: **SPARE ENGINE AT 19**

Date Opened: 10-3-2019 Date Finished 10-8-2019 Meter 1 Reading: 113,952

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM

1 6AM; HEADLIGHT H6054CVC1

Service Requests:

10/03/2019 LIGHTS / 12: BROKEN / REPAIR
VEHICLE LIGHTS NOT WORKING, DRIVER SIDE HEADLIGHT OUT

CSHOP-2019-5350

Date Opened: 10-10-2019 Date Finished 10-15-2019 Meter 1 Reading: 114,271

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
QUARTZ LIGHT

Service Requests:

10/10/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
SPOT LIGHT INTERMITTENT

CSHOP-2019-5376

Date Opened: 10-11-2019 Date Finished 10-11-2019 Meter 1 Reading: 114,086

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10155566

CSHOP-2019-5837

Date Opened: 11-6-2019

Date Finished

2-14-2020

Meter 1 Reading:

115,050

TASKS PERFORMED

Q PARTS

PM SERVICE B

1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER
1	FIL; FUEL WATER SEPARATOR
30	4PC; 15W40 PREMIUM BLUE OIL

Asset Work Order History 10155566

CSHOP-2019-5842

Comments: **REPAIR FORM PM B**

Date Opened: 11-6-2019

Date Finished

2-12-2020

Meter 1 Reading:

147,860

TASKS PERFORMED

Q PARTS

Asset Work Order History 10155566

FIRE PUMP CONTROLS	1	9IP; REMOTE HANDLE
RELIEF VALVE FIRE PUMP	1	5HP; TPM REBUILD KIT
HOSE BED BODY	1	5AB; 1 5 VALVE SUB ASS SS BALL
REPAIR FROM PM - TRANSFER CASE	1	5HP; VPS KPS PWR SHIFT AMP CNTRL KIT
WIPERS-WASHER	1	5HP; 5HP
REPAIR FROM PM - FIRE PUMP SYS	1	5HP; HALE QG RELIEF VALVE KIT
AIR FILTER	1	5HP; HALERELIEFVALVEWVULCANIZEDSEAT
GOVERNOR	1	5HP; TPM REBUILD KIT
LIGHTING SYSTEM	1	9IP; PISTON TPM RELIEF VALVE
REPAIR FROM PM - POWER STEERING	1	5HP; RELIEF VALVE W VULCANIZED SEAT
BATTERY	4	5SC; BUCKLE ASSY W STRAPS
SHORELINE CHARGER	1	9IP; U JOINT
REPAIR FROM PM - COOLING SYSTEM	1	5HP; BEARINGCOVERGASKET
UNIVERSAL JOINT	2	1AN; WIPER BLADES
U-BOLTS	1	5HP; 3 SVS LEVEL 2 KIT
POWER STEERING PUMP	2	2FR; COVER SAFETY BAR 18
REPAIR FROM PM - CAB	1	5AB; HANDWHEEL 6"
REPAIR FROM PM - TRANSMISSION	1	5AB; 5AB
AIR DRIER	3	5HP; HALE 2.5 VALVE REPAIR KIT
AIR SYSTEM	-1	5AB; 1 5 BALL KIT
DOOR	1	5AB; 1 5 BALL KIT
SEAT REAR	1	5AB; KIT 3 AMP 3 5 BALL VALVE
DOOR ALARM OR OTHER WARNING	1	5EB; 5EB
INSTRUMENTS-GAUGES-METERS	1	5EB; 5EB
CABIN AIR FILTER	1	5EB; 5EB
HVAC SYSTEM	1	9IP; VALVE KIT SS 546 2270 02 0
	1	5AB; 5AB
	-1	5AB; 5AB
	-1	5AB; 2 5 BALL KIT COMPOSITE
	1	5AB; 2 5 BALL KIT COMPOSITE
	2	2FR; COVER, SAFETY BAR 26"
	1	5EB; 5EB
	1	5EB; 5EB
	1	5EB; LOCKING SLEEVE
	1	5HO; 5HO
	1	5HP; BALL VALVE 3
	5	5CS; GAUGE 3 5 30 600 WH
	-5	5CS; 5CS
	2	5HP; SWITCH GEAR SHIFT
	1	5AB; 3IN SLOW CLOSE VALVE R1 HANDLE
	4	9IP; 600 802 BULB TAG LIGHT
	5	5CS; 5CS
	1	FIL; NAPAGOLD AIR FILTER
	30	9OC; BULK TRANS SYN
	2	5HP; HALE RELIEF VALVE STRAINER
	2	GRO; REFLECTOR
	1	9ES; BULB 150W HALOGEN
	20	6VD; LAMP INSTRUMENT
	1	1WL; TRAFFIC CONTROL HEAD
	5	NOL; TRAN FLU QT DEXRON3I
	1	9HY; CUSTOM PS HOSE
	1	9HY; FITTINGS
	1	9HY; HOSE ASSY
	4	1AD; BATTERY GROUP 31
	1	6KU; AC2000 12V PLC TEN 8
	2	BK; HI AMP FLUSH MOUNT
	1	6KU; AUTO CHARGE INDICATOR
	2	CRC; CRC DUSTER

Asset Work Order History 10155566

1 FIL; NAPA COOLANT FILTER
1 FIL; NAPA COOLANT FILTER
1 FIL; NAPA HYDRAULIC FILTER
1 2FL; PUMP POWER STEERING
1 9HY; HOSE
1 5AB; 2 5 BALL KIT COMPOSITE
1 5AB; 2 5 BALL KIT COMPOSITE
-1 5AB; 2 5 BALL KIT COMPOSITE
-1 5AB; 2 5 BALL KIT COMPOSITE
3 NOL; TRAN FLU QT DEXRON3I
1 2TK; BLOWER
2 2FL; WEATHERSTRIP
4 NCB; CHKTHRTLBDYCLNRBERRYMAN
1 2FL; DIPSTICK TRANSMISSION
1 2DD; FILTER KIT TRANS SUMP 4
1 2FL; 2FL
1 5HP; SEAL INPUT OUTPUT
1 TWD; AD 9KIT MINOR
1 MMM; ELECTRICAL TAPE
1 9IP; TRANS TEMP GAUGE
1 5TF; GAUGE CROSSFIRE
1 BK; CBC 50B CIR BRKR
1 6CB; 6CB

CSHOP-2019-784

Date Opened: 2-8-2019 Date Finished 2-11-2019 Meter 1 Reading: 110,129

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR ALARM OR OTHER WARNING

CSHOP-2020-1394

Date Opened: 3-9-2020 Date Finished 3-9-2020 Meter 1 Reading: 115,553

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-2002

Date Opened: 4-14-2020 Date Finished 4-14-2020 Meter 1 Reading: 115,881

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
HVAC SYSTEM

2 9IP; 1720 DIFFUSER A C 3 5 IN

Asset Work Order History 10155566

CSHOP-2020-5151

Date Opened: 10-1-2020 Date Finished 10-15-2020 Meter 1 Reading: 115,881

TASKS PERFORMED

Q PARTS

BATTERY
CRANKING SYSTEM

1 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2020-6298

Date Opened: 12-3-2020 Date Finished 12-7-2020 Meter 1 Reading: 115,943

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT
CRANKING SYSTEM

1 5TF; REED SWITCH KIT EXTENDA GUN
1 1AD; STARTER NEW 12 TOOTH 38MT 12V
4 1AD; 1000 CCA 31 SERIES BATTERY

RADIO-2018-77

Comments: **REMOVED 10141539, INSTALLED 10205850 INTO SPARE BAT1 ENG 10155566**

Date Opened: 2-5-2018 Date Finished 2-5-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

02/05/2018 RADIO / /
REMOVE & INSTALL NEW MOTOROLA MOBILE RADIO

SSHOP-2020-63

Date Opened: 2-14-2020 Date Finished 2-14-2020 Meter 1 Reading: 115,050

TASKS PERFORMED

Q PARTS

RADIO

2 5SC; HELMET HEADSET HOOK
