



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V204

In Date: 10/13/2005
Close Date: 10/21/2005

Meter Reading: 13,590.00

Problem?
B INSPECTION E43

Task performed:

See B Inspection pre-printed form

Parts	Quantity
0100030000SCREEN 6 IN	1
038-1550-00VALVE CHECK HALE 1/4"	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
29526898 29548988 TRANS FILTER ALLISON	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
52-624SWITCH DOOR	1
5462300020VALVE KIT SS VALVE 3 IN	1
5499FRE801910 REPAIR BRACKET A/C COMPRESSOR	1
5546-10M10 HELICOIL KIT S/O	1
5546-16HELICOIL KIT	1
5546-46M16 HELICOIL KIT S/O	1
60C00FCRCLEAR BACKUP 600 SERIES	1
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
8714287142 LIGHT MAP 12"	1
9440BELT	2
9480BELT	1
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
WL2600WLA260-A00 FOAM TANK VISION OLD FERR # 352	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V419

In Date: 11/02/2005 Meter Reading:
Close Date: 11/03/2005

Problem?
LIGHT IN LIGHT BAR INOP, E-43

Task performed:	Parts	Quantity
	01-0269477-00BALLAST 4 CHANNEL LED LIGHTBAR 01-02	2
	020363596230NOT AVAIL REPAIR ONLY 400 SERIES (WHIT	1
	9UCAPCC9UCAPCC END CAP CLEAR	1

Workorder: V707

In Date: 11/28/2005 Meter Reading:
Close Date: 11/30/2005

Problem?
HEADLIGHT BURNED, OUT RE-43

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V1190

In Date: 01/17/2006 Meter Reading:
Close Date: 01/23/2006

Problem?
L/SIDE HEADLIGHT INOP, RE-43

Task performed:	Parts	Quantity
	52-624SWITCH DOOR	1
	H6054USE CV TYPE SEALED BEAM	6

Workorder: V1283

In Date: 01/25/2006 Meter Reading:
Close Date: 02/14/2006

Problem?
SPOT LIGHT ON CAB INOP, R-43

Task performed:	Parts	Quantity
	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1343

In Date: 01/30/2006 Meter Reading:
Close Date: 03/02/2006

Problem?
NEED HYDRAULIC OIL, RE-43

Task performed:	Parts	Quantity
	180R002HURST HYD. FLUID QT	6

Workorder: V1414

In Date: 02/06/2006 Meter Reading:
Close Date: 03/02/2006

Problem?
DECK GUN VALVE HARD TO OPEN, RE-43

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V843

In Date: 12/08/2005 Meter Reading:
Close Date: 03/02/2006

Problem?
L/SIDE LIGHTBAR LENS BROKEN, R/LEFT LED LIGHTS IN LIGHT BAR INOP, RE-43

Task performed:	Parts	Quantity
	9ULENSCCLEAR LENS FREEDOM BAR	1
	SAHSVS2510STRAP	5
	UMVS111611STRAP	5

Workorder: V1605

In Date: 02/23/2006 Meter Reading:
Close Date: 03/20/2006

Problem?
TURN SIGNALS INOP, RE-43

Task performed:	Parts	Quantity
	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V1969

In Date: 03/27/2006

Meter Reading:

Close Date: 03/29/2006

Problem?

NEED HOLES DRILLED IN BATTERY COMPT, RE-43

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1953

In Date: 03/24/2006

Meter Reading:

Close Date: 04/13/2006

Problem?

DOOR AJAR LIGHT INOP, RE-43

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2133

In Date: 04/07/2006

Meter Reading:

Close Date: 04/19/2006

Problem?

BUNGEE HOOK STRAP THAT HOLDS JAWS IS BROKEN. RE-43

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2342

In Date: 04/24/2006

Meter Reading:

Close Date: 04/28/2006

Problem?

SLOW CLOSE 3" R/REAR VALVE INOP, RE-43

Task performed:

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V2463

In Date: 05/03/2006 Meter Reading:
Close Date: 05/08/2006

Problem?
DOOR AJAR LITE ON, RE-43

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V3078

In Date: 06/21/2006 Meter Reading:
Close Date: 06/23/2006

Problem?
We need 12 2 1/2" replacement gaskets for E43 & T43. We used all of our reserves when we did hose testing on the tender.

Task performed:	Parts	Quantity
	0714023GASKET 3.5 IN	6
	0714025GASKET 4.5 IN	6
	REDG25TGASKET 2.5 IN RED HEAD	25
	REDG6S14023 GASKET 6 IN	3

Workorder: V3192

In Date: 06/28/2006 Meter Reading:
Close Date: 06/30/2006

Problem?
PLEASE CHECK REAR A/C DRAIN PLUG, SMALL PUDDLE NOTED ON FLOOR BOARD E43

Task performed:	Parts	Quantity
	78R536078R5360M 2PK FILTER AIR COND	4

Workorder: V3172

In Date: 06/27/2006 Meter Reading:
Close Date: 07/10/2006

Problem?
2 1/2 gallon water extinguisher for E43.

Task performed:	Parts	Quantity
	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V3161

In Date: 06/27/2006
Close Date: 07/20/2006

Meter Reading:

Problem?

24' extension ladder missing protective cap from tip of 2nd extension section e43/ ground ladder.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3866

In Date: 08/10/2006
Close Date: 08/17/2006

Meter Reading: 14,300.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED RE43

Task performed:

Parts	Quantity
35200-YLIGHT MARKER LEDAMBER	1
5TSMACMOUNT 500 TIR SER CHROME	1
6809880678STUD DZ	2
6809940145CLIP	2
78R536078R5360M 2PK FILTER AIR COND	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V4170

In Date: 08/29/2006
Close Date: 08/31/2006

Meter Reading: 13,288.00

Problem?

hood latch broken, air horn innop E43

Task performed:

Parts	Quantity
17-12438-000HOOD LATCH	1
680-880-01-60LATCH	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V4205

In Date: 09/01/2006
Close Date: 09/06/2006

Meter Reading: 13,288.00

Problem?

repair hurst power unit e43

Task performed:

Parts	Quantity
BPR5ESSPARK PLUG 7734	1

Workorder: V3908

In Date: 08/14/2006
Close Date: 09/08/2006

Meter Reading:

Problem?

2 FRONT TIRES AT CALLAGHAN TIRES E43

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: VC-15214

Workorder: V4910

In Date: 10/16/2006
Close Date: 10/25/2006

Meter Reading: 1,080.00

Problem?

CHAINSAW ON E43 STARTS UP OK, BUT AFTER IDLE WILL NOT RUN BACK UP.

Task performed:

1. WORKED ON SAW CLEANED CARB RUN AND TEST NPF

Parts	Quantity
NO PARTS USED	

Workorder: V4967

In Date: 10/19/2006
Close Date: 11/02/2006

Meter Reading: 21,516.00

Problem?

both chain saws out of service. stop running on full throttle. added new mixed gas (50:1), spark plug looks good, but still not running. E-43

Task performed:

1. TRAVELED TO STN 43. RAN BOTH CHAIN SAWS' AND FOUND NOTHING WRONG WITH THEM.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V5146

In Date: 10/30/2006 Meter Reading: 1,097.00
 Close Date: 11/06/2006

Problem?
 fuel gauge not reading correctly on dashboard. RE43

Task performed:	Parts	Quantity
1. CHECK FUEL GAGE	NO PARTS USED	

Workorder: V5150

In Date: 10/30/2006 Meter Reading: 1,097.00
 Close Date: 11/06/2006

Problem?
 E43 frony suction switch inop/10-7

Task performed:	Parts	Quantity
1. CHECK FRONT SUCTION VALVE	MJTV5 VALVE AIR CONTROL	1

Workorder: V5177

In Date: 10/31/2006 Meter Reading: 21,954.00
 Close Date: 11/06/2006

Problem?
 REPAIR CHAIN SAW REGAN SMALL EQUIP REPAIR RE43

Task performed:	Parts	Quantity
REPAIR CHAIN SAW E43	NO PARTS USED	

Vendor?: REGANS MOBILE ENGIN

Workorder: V6135

In Date: 01/08/2007 Meter Reading: 23,436.00
 Close Date: 01/16/2007

Problem?
 Foam leaking from pump area E43

Task performed:	Parts	Quantity
1. Replaced foam supply hose	100R4FOAM HOSE AS PER SAMPLE	1
2. Adjusted tank to pump linkage		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V6348

In Date: 01/18/2007 Meter Reading: 23,670.00
Close Date: 01/23/2007

Problem?
REPAIR SAW RE43 REGANS

Task performed:	Parts	Quantity
1. SAW SENT OFF TO REGAN'S FOR REPAIR.	NO PARTS USED	

Vendor?: REGAN'S MOBILE SMALL

Workorder: V6380

In Date: 01/20/2007 Meter Reading: 2,287.00
Close Date: 01/23/2007

Problem?
Polaroid PR camera dose not appear to be working correctly. It will not close up. Also it is out of film. E-43

Task performed:	Parts	Quantity
1. TRAVELED TO STN 42. INSPECTED & TESTED POLAROID CAMERA, NO FILM ADVISE LT TO CONTACT WAREHOUSE.	NO PARTS USED	

Workorder: V6522

In Date: 01/29/2007 Meter Reading: 2,287.00
Close Date: 02/27/2007

Problem?
REPLACE BACK SMALL NUMBER PLATE AND NUMBER ON E43. INSTALL SMALL NUMBER PLATE WITH NUMBER ON FRC OF T43

Task performed:	Parts	Quantity
1. TRAVELED TO STN 43. INSTALLED NUMBER PLATES.	NO PARTS USED	

Workorder: V7220

In Date: 03/15/2007 Meter Reading: 2,400.00
Close Date: 03/23/2007

Problem?
REPAIR SLEDGE HAMMER HOLDER IN DE COMPARTMENT. ALSO AIR HORN BUTTON ON PUMP PANEL DOES NOT WOR E43

Task performed:	Parts	Quantity
Remounted bracket	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V7221

In Date: 03/15/2007 Meter Reading: 2,400.00
 Close Date: 03/23/2007

Problem?

A HANDLIGHT FROM E43 WILL NOT HOLD A CHARGE. ALSO PLEASE CHECK BOTH BACKSEAT LIGHT BOXES. THE CHARGING LIGHTS ARE NOT COMING ON. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
Found wire disconnected	NO PARTS USED	

Workorder: V8476

In Date: 05/30/2007 Meter Reading: 2,619.50
 Close Date: 06/14/2007

Problem?

E43 FOAM SYSTEM NEEDS TO BE CHECKED OUT. SHUTS OFF BY ITSELF AND IS USING EXCESSIVE AMOUNTS OF FOAM

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. Disassembled foam pump head and cleaned, reassembled and tested	NO PARTS USED	
2. Checked problem with hurst motor, cleaned and adjusted carb		

Workorder: V8577

In Date: 06/04/2007 Meter Reading: 2,637.00
 Close Date: 06/26/2007

Problem?

RIGHT SIDE (OFFICERS SIDE) INTAKE FEMALE SWIVEL LOCKED TIGHT. WILL NOT TURN/SWIVEL. e43

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. Removed swivel and cleaned and lubed	NO PARTS USED	

Workorder: V9239

In Date: 07/09/2007 Meter Reading: 1,288.00
 Close Date: 07/18/2007

Problem?

chain saw pull cord is not turning engine. E-43

Task performed:	<u>Parts</u>	<u>Quantity</u>
Chkd all saw on trucks & fnd all working; fnd no problem with pull cord	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8921

In Date: 06/19/2007

Meter Reading: 27,291.00

Close Date: 07/19/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED E43

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. B INSP & ROAD TEST	013-2010-054 PIN CABLE FLOW SENSOR HALE FOAM SYS	1
2. T-CASE SERVICE	038-1550-00VALVE CHECK HALE 1/4"	1
3. DIFFERENTIAL INPUT SEAL LEAKING. REMOVE OIL. REMOVE DRIVE LINE. REMOVE YOKE, FLANGE, & SEAL. INSTALL NEW SEAL. CLEAN PARTS. FILL DIFFERENTIAL, CHANGE OUT EMPTY GEAR OIL DRUM.	038-1790-00CHECK VALVE INJECTOR HALE FOAM SYS.	1
4. CHECK U-BOLTS TO TORQUE SPECS, FRONT AND REAR.	040154000O-RING FOR HALE FOAM PUMP	2
5. SERVICE AIR DRYER.	042-0091-00SPRING PRIMER	1
6. COOLANT SYSTEM SERV.	042-0550-00SPRING-VALVE QG RELIEF VALVE	1
7. BATT.SERV REPLACEMENT SCHED.	100557SEAL OLD STYLE PINON	1
8. BELT SERV. REPLACE PULLEY, BEARING, IDLER & TENSIONER.	107796DRYER KIT AD9 -NEW	1
9. PUMP VAC TEST-VALVES NEED UPDATING. REBUILD 4 DISCHARGE VALVES.	108-12FBEADED CHAIN W/CONN 12	2
10. RAD LEAK. REMOVE AND DISSASSEMBLE RAD & INSTALL.	200-2450-00NC SWITCH OK TO PUMP	1
11. WIPER BLADES & FLUID. ADD BUG SOLVENT TO RESEVOIR.	200-2481-00-0546-3240-00-0 FOAM PUMP SENSOR KIT	1
12. DRIVERS DOOR AND WINDOW MOLDING AND SEAL. L-1 DOOR LOCK REPAIR & REPLACE AS NEEDED.	203FFBEARING PULLEY	1
13. LIGHT FAILURE-R&R DEFECTIVE OR BROKEN LIGHTS.	2332920005SMASK LENS W/RST BUTTON VDO	1
14. SHOP MEETING.	39768315259022 GROOVED TENSIONER OLD#3936213	1
15. REBUILD VALVES. R&R DISCHARGE, HOSE REEL, INTAKE RELIEF, TANK TO PUMP. REPLACED SENSING VALVE, CHECK VALVE. REPAIR PIPE NIPPLE LEAK. DRAIN TANK. REMOVED TANK TO PUMP VALVE, NIPPLE, AND RESEAL. FILL WATER TANK. PERFORM DRY VAC TEST.	50R00FRRFLASHER RED LED FLANGED	1
16. VACATION	52-24WIPER BLADES ANCO 24	2
17. B INSP. GREASE FITTINGS. DRAIN OIL TO CORRECT LEVEL. CLEAN REAR AC FILTER.	546126000TPM/QG HALE REPAIR KIT	1
18. SWAP OUT INTO SERVICE TRUCK FOR ON CALL. FUEL TRUCK. ADD 2 QTS OIL, COOLANT, WASHER FLUID, CHECK TRANS FLUID & LIGHTS.	5462270020VALVE KIT SS 546-2270-02-0	1
19. WEIGH VEHICLE AND TALK TO LIFT MANUFACTURER.	5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	3
20. REBUILD BOTH PRIMER VALVES.	5462300020VALVE KIT SS VALVE 3 IN	2
21. INSTALL CROSSLAY NETS	68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
22. SERVICE SMALL ENG. EQUIP.	6806970098SEAL DOOR	1
23. ON CALL PARTS.	75908SWITCH BATTERY MASTER 300A	1
24. REMOVE AND INSTALL LADDER DECALS.	84871GROUND STRAP 12 IN	1
25. REMOVE R FRONT FENDER BRACE AND RE-WORK SO BRACE DOESN'T CUT FRONT SUCTION HOSE.	89BULB	1
26. REPLACE PUMP COMPOUND PRESSURE GAUGE. SET UP FOR NEW3 GOV GAUGE AND THROTTLE (NO MONEY IN ACCT)	9440BELT	1
27. DIAGNOSE FOAM MASTER GAUGE- TROUBLE CODE "HOT". REPLACED DISTRIBUTION BOX INJ, SWAPPED CABLE A7 CONTROL HEAD, CHECKED	9480BELT	1
	A1834388002MOLD L/H	1
	A2243065003FUEL SENDING UNIT	1
	BHT-B2110CORE AND TANKS	1
	CA8193AIR FILTER 46744 WIX	1
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	HPH6349AOIL FILTER 51748	1
	I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT	1
	IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
	K080716BELT	1
	PR338324070 WIX FILTER WATER	1
	PVG-KITORING KIT	1
	R90PFILTER FUEL 33231	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- VOLTAGE DROPS, FLOW SENSOR.
- 28. REPLACED R PRECONNECT NOZZLE BUCKET BRACKET. REDESIGNED FASTENER SYSTEM.
- 29. INSTALL LR HUBCAP AND LUG NUT COVERS. INSTALL LUG NUT COVERS ON R SIDE.
- 30. WORK ON HOIST. CHECK BATTERIES.
- 31. VACATION- JUNE 28-29, JULY 2-3, JULY 5-6.
- 32. FOAM SYSTEM DIAGNOSIS- ELEC. FAULT. CONTACT HALE TECH SUPPORT AND ENGINEER REGARDING PROBLEM.
- 33. FOAM SYSTEM. R&R FOAM INJ PER ED. R&R FLOW SENSOR TWICE PER ED. REPLACED FOAM SENSOR AND SCREWED ALL THE WAY IN PER ED. REMOVE PUMP AND CLEAN PUMP AND GEARS PER ED.
- 34. SCREW SENSOR FOR FOAM OUT PER MIKE. (OK NOW) REPLACE DISCHARGE SENSOR. FILL FOAM TANK. MEETING.
- 35. FUEL GAUGE PROBLEM. REPLACED SENDING UNIT PER ED.
- 36. REPLACED DASH BEZEL.

Workorder: V9460

In Date: 07/22/2007 **Meter Reading:** 27,553.00
Close Date: 07/24/2007

Problem?

E43 air horn spontaneously ingages when battery first turned

Task performed:

Air horn sounds constantly; chkd unit & replc foot swtch horn; still sounding; chkd for relay in ckt-none; signal goes to node; tried to reprogram node-no good; frnd input to node grounded; will bring to shop for repair

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Workorder: V8945

In Date: 06/21/2007 **Meter Reading:** 27,291.00
Close Date: 07/25/2007

Problem?

repace two tires at shop callaghan ent e43

Task performed:

Replace two tires at shop - Callaghan

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Vendor?: CALLAGHAN



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V9596

In Date: 07/28/2007 Meter Reading: 2,696.00
Close Date: 07/28/2007

Problem?

no reply from node 2. deck gun cab light illuminates when (P) break released. Pump panle lights and quartz scene lights unable to be turned on. "O.K. To Pump" light in cab not illuminating when engine placed into pumping e43

Task performed:	Parts	Quantity
No power to pump panel; replc node #2	600000003NODE HERCULES V-MUX	1

Workorder: V9506

In Date: 07/24/2007 Meter Reading: 27,553.00
Close Date: 08/07/2007

Problem?

repair air horns e43

Task performed:	Parts	Quantity
1. rewired air horns	372000082CHROME MARKER LIGHT MOUNT	2
2. replaced marker light right top rear		

Workorder: V10031

In Date: 08/21/2007 Meter Reading: 28,245.00
Close Date: 09/11/2007

Problem?

VIBRATION IN DRIVELINE E43

Task performed:	Parts	Quantity
1. Chkd drive line vibration; fnd pinion out loose; rem driveline, pinion yoke, drained fluid; fnd large amount of metal; reassemble & fille with new fluid	NO PARTS USED	
2. Delivered truck to Brake & Wheel		

Workorder: V10146

In Date: 08/27/2007 Meter Reading: 2,754.00
Close Date: 09/13/2007

Problem?

Repair/Replace hub caps on rearwheels of E43. One hubcap at Station. Also airhorn is still inoperative.

Task performed:	Parts	Quantity
1. Rewire air horn & tested	NO PARTS USED	
2. Rem rear center chrome cap from rear wheel		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V10095

In Date: 08/23/2007 Meter Reading: 28,245.00
Close Date: 09/18/2007

Problem?
rebuild rear end total truck e43

Task performed:	Parts	Quantity
Rebuild rear end - Total Truck	NO PARTS USED	

Vendor?: TOTAL TRUCK

Workorder: V10489

In Date: 09/17/2007 Meter Reading: 2,790.00
Close Date: 09/25/2007

Problem?
E43 PRIMER RELIEF LIGHT INOPERATIVE, DECK GUN WARNING LIGHT STILL BLINKING, FUEL GAUGE ON PUMP PANEL INOPERATIVE e43

Task performed:	Parts	Quantity
1. Traced problem w/relief valve light & fuel gauge; fnd broken wire relay; reran new wires & tested	NO PARTS USED	
2. Adj all cab door latches		

Workorder: V10160

In Date: 08/28/2007 Meter Reading: 2,754.00
Close Date: 09/27/2007

Problem?
Air hose unaccounted for. Need vehicle air hose and air'chuck' to fill tires, pressurized water cans. e43

Task performed:	Parts	Quantity
DC will E-mail wayne	NO PARTS USED	

Workorder: V10361

In Date: 09/10/2007 Meter Reading: 2,768.00
Close Date: 09/27/2007

Problem?
PUMP PANEL LIGHTS, AND SCENE LIGHTS NOT WORKING. EXTEND-A-GUN WARNING LIGHT FLASHING INSIDE CAB. E43

Task performed:	Parts	Quantity
1.Fnd bad connection in Y connector; cln; fnd bd node; R/R & downloaded node; fixed pump panel light & scene light but not extend-abar warning light; wire to switch but light didnt go off	6000000003NODE HERCULES V-MUX	1
2. Traced problem w/deck gun light going off; fnd bad grnd, ran new grnd wire	NISENSORNI-SENSOR SENSOR DECK GUN USE XG840-K	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V8399

In Date: 05/23/2007 Meter Reading: 2,582.70
Close Date: 10/15/2007

Problem?
REPLACE CLEAR COVER FOR SIDE COLOR WATER LEVEL INDICATOR. (DRIVERS SIDE) e43

Task performed:	Parts	Quantity
1. replaced lens for water level	68-3963453-30LENS CLEAR FOR STRIP LIGHT	1
2. Recalabrated water level guages		

Workorder: V11652

In Date: 11/17/2007 Meter Reading: 2,926.00
Close Date: 11/21/2007

Problem?
master pressure guage (digital) fluctuating by 50-100 psi, possibly affecting pressure relief valve. E43 NO CALL

Task performed:	Parts	Quantity
REM PRESSURE RELIEF SCREEN & CLEAN. J	NO PARTS USED	

Workorder: V11684

In Date: 11/19/2007 Meter Reading: 2,934.00
Close Date: 11/28/2007

Problem?
EMERGENCY SIDE LIGHTS ON OFFICERS SIDE WORKING INTERMITTENTLY. SOMETIMES THEY DON'T COME ON, THE COME ON AND DON'T BLINK, AND MIDDLE ONE HAS SOME LEDS BURNT OUT. e43

Task performed:	Parts	Quantity
Fnd (3) LED lights out; rem lights & install new j	50R03ZCRLIGHT LED RED TIR 6	3

Workorder: V10835

In Date: 10/04/2007 Meter Reading: 28,875.00
Close Date: 11/29/2007

Problem?
mount fuel can e43

Task performed:	Parts	Quantity
1. Remounted fuel can.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11852

In Date: 12/01/2007 Meter Reading: 30,135.00
Close Date: 12/06/2007

Problem?

digital master discharge gauge appears to need calibration it appears to be off by about 40psi high. For example in tank to pump a idle discharge reads 90psi were other Engines read 50psi. In pump it also is 40too high E43

Task performed:

1. Traced out problem with gauge found discharge sencer N/G removed and repaired.

Parts	Quantity
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1

Workorder: V11957

In Date: 12/07/2007 Meter Reading: 30,135.00
Close Date: 12/12/2007

Problem?

front left blinker not working on engine 43 and no replacement bulbs in station

Task performed:

1. Travel to 43.
2. Check truck NPF has already been fixed.

Parts	Quantity
NO PARTS USED	

Workorder: V11938

In Date: 12/11/2007 Meter Reading: 30,371.50
Close Date: 12/19/2007

Problem?

TURN SIGNAL 10-7 E43

Task performed:

1. Repaired bad connection in light.

Parts	Quantity
NO PARTS USED	

Workorder: V11180

In Date: 10/22/2007 Meter Reading: 29,302.00
Close Date: 01/15/2008

Problem?

engine 43 air horn not functioning

Task performed:

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V11853

In Date: 12/01/2007 Meter Reading: 30,135.00
Close Date: 01/15/2008

Problem?

Pressure relief valve light dose not appear to be working properly. When relief valve is disengaged it flickers instead of stays off. When it is engaged it comes on properly. Thanks guys hope you had a good weekend. E43

Task performed:

1. Relief valve light on, Ran pump and found light working at this time.

Parts	Quantity
538-1400-00QG VALVE	1
546-0200-50QD REL.VALVE KIT	1

Workorder: V12405

In Date: 01/07/2008 Meter Reading: 1,455.00
Close Date: 02/04/2008

Problem?

air horn on pump panel not functioning E-43

Task performed:

At shop for B-Inspection. j

Parts	Quantity
NO PARTS USED	

Workorder: V12705

In Date: 01/20/2008 Meter Reading: 3,080.00
Close Date: 02/04/2008

Problem?

air horn on pump panel oos, light on relief valve does not go out when setting relief valve ,and ems compartment door sticks. E43

Task performed:

At shop for B-Inspection. j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V12810

In Date: 01/24/2008
Close Date: 02/04/2008

Meter Reading: 31,358.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED E43

Task performed:

- B-Inspection
- 2. Rebuilt bypass valve; (magnet was shattered)
- 3. Replc wiper blades
- 4. Replc T/S side lenses; (both cracked)
- 5. Sealed condensor hsng on rear cab A/C; (lkg condensation into cabl flr)
- 6. Rem siren/horn; rocker swtch in dash; fab new bezel & reinstalled swtch
- 7. Chkd air horns going off when btry swtch is turned on; cld not reproduce concern; wired air horns back into original harness & reinstalled kick panel; test air horns repeatedly

Parts

Quantity

15-18150-04OIL DRAIN CUMMINS ISB ISC	1
15W40BSYN OIL BULK QTS	21
52-24WIPER BLADES ANCO 24	2
538-1400-00QG VALVE	1
546126000TPM/QG HALE REPAIR KIT	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V13892

In Date: 03/14/2008
Close Date: 03/14/2008

Meter Reading: 32,462.00

Problem?

k12 saw belt 10-7 while cutting garage door on house fire 08-22797. dc3 notified. tagged and sitting in St43 bay

Task performed:

- 1. Unit repaired on EMS 3 ticket

Parts

Quantity

NO PARTS USED

Workorder: V13899

In Date: 03/14/2008
Close Date: 03/14/2008

Meter Reading: 32,462.00

Problem?

repair a/c e43

Task performed:

- 1. Replaced blown low pressure A/C line from compressor to expansion block, vaccum, charge, leak check system

Parts

Quantity

716907-0610A DRYER	1
A2241332074A22-41332-074 HOSE ASSY.	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History 1015554 FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V13380

In Date: 02/20/2008 Meter Reading: 31,883.00
Close Date: 03/20/2008

Problem?
repair flat at sta 43 callaghan e43

Task performed:	Parts	Quantity
Repair flat at Stn43 - Callaghan j	NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V13868

In Date: 03/13/2008 Meter Reading: 3,201.00
Close Date: 03/20/2008

Problem?
Front right turn single not working. Still have on going problems with fuel gauge in cab of E43.

Task performed:	Parts	Quantity
1. Traced out problem with turn signal, found bad connection	NO PARTS USED	

Workorder: V13869

In Date: 03/13/2008 Meter Reading: 3,201.00
Close Date: 03/20/2008

Problem?
A/C unit leaking water into back floor board of E43. Tommy looked at it and informed us that the unit was "rusted out" and needs to be replaced. e43

Task performed:	Parts	Quantity
1. Checked rear A/C unit leaking water, resealed unit and will monitor	NO PARTS USED	

Workorder: V13952

In Date: 03/18/2008 Meter Reading: 3,208.00
Close Date: 04/02/2008

Problem?
Please repair/replace the cigarette lighter plug in the cab of E43. We use it for our portable spotlight.

Task performed:	Parts	Quantity
1. Repaired bad connection for power plug	56415CIG. LIGHTER ACCES.	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14060

In Date: 03/24/2008 Meter Reading: 3,232.00
 Close Date: 04/02/2008

Problem?

E43, B43, R43 ALL HAVE ONE OR TWO EMERGENCY LIGHTS THAT ARINOPERTATIVE.

Task performed:

1. Replaced LED light on front of Engine that was out.

Parts	Quantity
NO PARTS USED	

Workorder: V14322

In Date: 04/07/2008 Meter Reading: 33,034.00
 Close Date: 04/07/2008

Problem?

AIR HORN INOP, E-43

Task performed:

1. air horn stays on/rewired air horn.

Parts	Quantity
NO PARTS USED	

Workorder: V14114

In Date: 03/26/2008 Meter Reading: 3,237.00
 Close Date: 04/11/2008

Problem?

right front side led red warning light does not work.

Task performed:

1.replaced LED lite that wasnt working.

Parts	Quantity
50R03ZCRLIGHT LED RED TIR 6	1

Workorder: V14349

In Date: 04/08/2008 Meter Reading: 33,034.00
 Close Date: 04/11/2008

Problem?

REPAIR CHARGING SYSTEM E43

Task performed:

charging sys. on e 43 no charge

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V14408

In Date: 04/11/2008 Meter Reading: 33,143.00
Close Date: 04/14/2008

Problem?
REPLACE ALTERNATOR E43

Task performed:	Parts	Quantity
1. REPLACE ALTERNATOR.	4867JB320 UPGRADE ALTERNATOR	1

Workorder: V15209

In Date: 05/20/2008 Meter Reading: 34,563.00
Close Date: 05/20/2008

Problem?
PIN MISSING FROM SPREADER TIPS, E-43

Task performed:	Parts	Quantity
Pin missing gfrom spreader tips E43 - Team Equipment j	NO PARTS USED	
Vendor?: TEAM EQUIPMENT		

Workorder: V15215

In Date: 05/20/2008 Meter Reading: 3,364.00
Close Date: 06/05/2008

Problem?
E43 has returned from the deployment up north and needs to be check out. Front A/C was not cooling. complete a inspection

Task performed:	Parts	Quantity
1. Cab A/C; A/C filter; chkd cab, A/C & replcd filter.	78R536078R5360M 2PK FILTER AIR COND	1
2. Coolant leak; fnd coolant leak & rep hose clamp.	98279CONNECTOR	3
3. A-Inspection		
4. Cab door hard to open; adj cab door latches. j		

Workorder: V15156

In Date: 05/19/2008 Meter Reading: 34,563.00
Close Date: 06/18/2008

Problem?
ON CALL ALARM GOING OFF

Task performed:	Parts	Quantity
1. alarm going off, found no alarm	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15540

In Date: 06/05/2008 Meter Reading: 34,867.00
Close Date: 07/01/2008

Problem?
REPAIR ACCESSORY PLUG E43

Task performed:	Parts	Quantity
1. installed 2nd new 12volt plug in dash.	50R03ZCRLIGHT LED RED TIR 6	2
2. air leak traced out. air leak found at seat . repaired test = ok.	56415CIG. LIGHTER ACCES.	1
3. rear LED out repaired bad connection	RSR03ZCRLIGHT LED RED TIR3 SERIES	2

Workorder: V15552

In Date: 06/05/2008 Meter Reading: 34,867.00
Close Date: 07/01/2008

Problem?
fuel gauge dose not read write. e43

Task performed:	Parts	Quantity
1. FUEL GAUGE IN-OP. REPLACED DASH CLUSTER AND FUEL SENDER AND TESTED.	22-27156-000GASKET FUEL SENDER	1
	A2243065003FUEL SENDING UNIT	1
	A2249250001 A22-49250-003 CLUSTER ASSY	1

Workorder: V15562

In Date: 06/05/2008 Meter Reading: 3,399.00
Close Date: 07/01/2008

Problem?
The air adjustment on the drivers' seat does not work. "Feels like you are driving a lowrider". E43

Task performed:	Parts	Quantity
1. travel to 43	NO PARTS USED	
2. repair airline to drivers seat.		
3. check air hose.		

Workorder: V15616

In Date: 06/09/2008 Meter Reading: 34,986.00
Close Date: 07/01/2008

Problem?
ON CALL COMP DOOR WONT OPEN E43

Task performed:	Parts	Quantity
1. medical door wont open handle broken inside. drilled out opened, went to shop for parts= repaired	14996-02D PADDLE HANDLE	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V15621

In Date: 06/09/2008 Meter Reading: 3,410.00
Close Date: 07/09/2008

Problem?
air horn on pump panel oos. r43

Task performed:	Parts	Quantity
1. traced out problem with air horn, found bad ground and repaired	NO PARTS USED	

Workorder: V15743

In Date: 06/14/2008 Meter Reading: 3,417.00
Close Date: 07/09/2008

Problem?
siren does not come on when you press the horn button E43

Task performed:	Parts	Quantity
1. checked horn button and tested ok	NO PARTS USED	

Workorder: V15879

In Date: 06/20/2008 Meter Reading: 3,437.00
Close Date: 07/11/2008

Problem?
pressure relief valve takes a long time to control pressure E43

Task performed:	Parts	Quantity
ran pump & chkd relief valve; tested ok. j	NO PARTS USED	

Workorder: V16397

In Date: 07/17/2008 Meter Reading: 35,655.00
Close Date: 07/30/2008

Problem?
warning light for the doors being open does not work. e43 the air ajustment on the drivers side seat needs a air switch. it does not ajust.

Task performed:	Parts	Quantity
1. found light diconnected, reconnected light and tested = ok	NO PARTS USED	
2. repaired drivers side air seat that was not working.		



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V16662

In Date: 07/28/2008
Close Date: 07/31/2008

Meter Reading: 3,500.00

Problem?

The door ajar light in the cab of E43 is blinking again. Tommy was out today (Mon.) to check it and now it's blinking again.

Task performed:

1. Door open warning switch shows water corrosion buildup & (1) brkn switch; replc all defective switches. sys working normal at this time.
2. Opr states siren come on/off; I could not duplicate this fault; all sys working normal; chk alt output; all are operating normal. j
3. Repaired short in L-1 door switch. j

Parts	Quantity
52-624SWITCH DOOR	5

Workorder: V16737

In Date: 07/31/2008
Close Date: 08/05/2008

Meter Reading: 3,509.00

Problem?

Drivers side haedlight out E43

Task performed:

1. Replc headlight on right side. j

Parts	Quantity
NO PARTS USED	

Workorder: V17149

In Date: 08/19/2008
Close Date: 09/02/2008

Meter Reading: 3,541.00

Problem?

open door light is malfunctioning e43

Task performed:

1. Light works ok at this time; buzzer not coming on with light. j

Parts	Quantity
NO PARTS USED	

Workorder: V17275

In Date: 08/24/2008
Close Date: 09/22/2008

Meter Reading: 3,555.00

Problem?

Right side (officers side) above rear wheel, the strobe light is stuck on, does not flash/blink. E-43

Task performed:

1. Replaced LED light on right side that was not flashing. j

Parts	Quantity
01-0663672-54A200 SERIES TRI RED	1
50R03ZCRLIGHT LED RED TIR 6	2



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V17578

In Date: 09/08/2008 Meter Reading: 3,586.00
Close Date: 09/29/2008

Problem?

Door ajar light blinking and will not go off. E43

Task performed:

Traced out problem with light found bad ground.

Parts	Quantity
NO PARTS USED	

Workorder: V16738

In Date: 07/31/2008 Meter Reading: 3,509.00
Close Date: 09/30/2008

Problem?

Thermal imager camera not charging properly E43

Task performed:

Repaired bad connection on TIC charger.

Parts	Quantity
6010000000NODE MINI V-MUX 6010-0000-00	2

Workorder: V17121

In Date: 08/18/2008 Meter Reading: 3,541.00
Close Date: 09/30/2008

Problem?

Please check TIC holder/charger on E43. The power light is coming on, but neither charging light is coming on the unit or spare battery. E43

Task performed:

1. Radio speakere mount on dash; Need base for charger; replc w/another
 2. Need to chk on buzzer to door open;
 3. Need to rep LED side marker light, rear tail board & left rear corner.
- j

Parts	Quantity
35200-RLIGHT MARKER LED RED	3
35200-YLIGHT MARKER LEDAMBER	3

Workorder: V17437

In Date: 09/01/2008 Meter Reading: 3,581.00
Close Date: 10/01/2008

Problem?

radio speaker bracket broken on dash. E-43

Task performed:

1. Repaired radio brack on dash.

Parts	Quantity
NO PARTS USED	

(R.T.)



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18213

In Date: 10/08/2008 Meter Reading: 51,445.00
 Close Date: 10/17/2008

Problem?
 REPAIR SEATS AT CENTRAL

Task performed:	Parts	Quantity
Repair seats - Central Auto Trim j	NO PARTS USED	

Vendor?: CENTRAL AUTO TRIM

Workorder: V15601

In Date: 06/08/2008 Meter Reading: 3,405.00
 Close Date: 10/21/2008

Problem?
 upper left red turn signal needs to be changed R43

Task performed:	Parts	Quantity
1. REPAIRED MARKER LIGHT THAT WAS NOT WORKING.	NO PARTS USED	

Workorder: V18604

In Date: 10/26/2008 Meter Reading: 88.50
 Close Date: 11/06/2008

Problem?
 E43 has just return from a scheduled "B" maintenance. Both air systems are leaking down, front and rear. Dosen't appear to be a rapid leak, and after a few minutes it builds up and we can respond.

Task performed:	Parts	Quantity
Checked for air leaks & fnd none at this time. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18160

In Date: 10/06/2008

Meter Reading: 37,489.00

Close Date: 11/07/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED E43

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. Road call to Stn43 to troubleshoot horn/siren sticking on; fnd faulty horn button; changed horn button out with spare unit.
2. Perform "C" service.
3. Performed low voltage electrical sys performance test
4. Drove Julio to upholstery shop.
5. Svc "T" case.
6. Svc air brake dryer.
7. Sec loose exh clamp & hanger.
8. Cln vac motor positive connection (corroded).
9. Replcd pinion seal (leaking).
10. Svc trans.
11. Replaced belts.
12. Chkd out Hurst tool no start cond; cld not reproduce customer concern; unit started and ran normally.
13. Replcd horn button in steering wheel (broken)
14. R/R air gov & fittings.
15. Rem oil line (supply) from air compressor & replc; go to Macko hose & have made up.
16. Insurance meeting w/rep.
17. Go to Red Wing store & get boots.
18. Replc all (4) dash defusers.
19. Lube all door & compt latches & chk opn.
20. Replace wiper blades.
21. Replc L/R; complete weatherstrip; replc L/F door lower weather strip & R/F door lower weatherstrip.
22. Replc (2) amber midship marker lights; replc both frnt turn signal lamp reflector lenses; replc (2) amber reflectors midship on each side.
23. Replc bulb in left side telescopic light.
24. Cln rear rear A/C drain; cln clogged evap core to rear unit & replc filter.
25. Rep hose reel compt light; replc node #3; reprogram new node & install; had to rem Hurst tool shelves to rem/repl nodes.
26. Rep rem, cln, repair & reinstall fuel cap.
27. Replc bulb in maplight & chk opn.
28. Replc both flag stickers on rear of unit.
29. Rem RPM cable frm T-case; make new cable & reinstall.
30. Reinstall driver/pass seats back in unit.
31. road call to Stn47; rem hubcaps for tire co. & reinstall.
32. Rem slow close valves for R/R discharge & deck gun; install new Akron valves.
33. Rem hose crosslay #1 & #2 deck plate & reattach deck gun stand pipe; reinstall deck plate for crosslay.
34. Assist w/deck gun valve & right rear discharge valve replacement.
35. Perform vac test. rem/rebuild 33 discharge & rem/rebuild intake discharge valve.
36. Replc tank to pump valve; replace #1 & #4 discharge valves; replc tank recirculate valve.
37. Assisted vac leak dia & repair.

0106837849C8COMP LIGHT WHITE LED 200	1
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
048009000SPEEDCOUNTER PUMP PANEL	3
100557SEAL OLD STYLE PINON	1
1050093 IN P1S FLANGE	1
105018FLANGE ADAPTER 3 X HALE	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1160033 IN FLANGE ADPT W/ HOLES P2S	2
1202364111-0 MAP LIGHT BULB	1
15W40BSYN OIL BULK QTS	24
22-40868-000WASHER CAP WPB-FREIGHTLINER	1
29526898 29548988 TRANS FILTER ALLISON	1
323864HOSE/FITTING	1
35200-YLIGHT MARKER LEDAMBER	2
52-24WIPER BLADES ANCO 24	2
546126000TPM/QG HALE REPAIR KIT	1
5462270020VALVE KIT SS 546-2270-02-0	1
6.5-70-18XSTRAP U-JOINT	1
600000003NODE HERCULES V-MUX	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	2
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
6814600340A14-15472-000 HORN BUTTON	1
715000000501 1/2 IN VALVE SS 715-0000-00-50	1
72500000050VALVE SS 2 1/2	3
73000000050VALVE SS 3IN NEW # 830-0000-00-50	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
8113-483IN SS NIPPLE	1
883088301201 3 IN SLO-CLOZ W/R1 HANDLE	2
91513AMBER LENS	2
9440BELT	1
9480BELT	1
A0631087000CABLE BATT. POS.	1
B480AREFLECT-AMBER	2
BPR5ESSPARK PLUG 7734	1
CA8193AIR FILTER 46744 WIX	1
CD2004DRAIN HOSE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
LB-D30BULB QUARTZ HAL. 12V 150W	2



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

38.Fill task w/water & chk valves/pipes for leaks.

PR338324070 WIX FILTER WATER

1

39. Turn in warranty valves & clnup work area. j

R90PFILTER FUEL 33231

1

Workorder: V18486

In Date: 10/21/2008

Meter Reading: 51,445.00

Close Date: 11/10/2008

Problem?

replace hose bed cover e43

Task performed:

Parts

Quantity

Replace hose bed cover E43 - Central Auto j

NO PARTS USED

Vendor?: CENTRAL AUT TRIM

Workorder: V19072

In Date: 11/14/2008

Meter Reading: 3,715.00

Close Date: 11/20/2008

Problem?

newly replaced valve on e43 is leaking, seems like its leaking from threads

Task performed:

Parts

Quantity

1. Rep coated leak at R/R discharg valve; replcd lower flange & close nipped.

1050093 IN P1S FLANGE

1

2. Rep deck gun position sensor.

800034VALVE PARKING BRK.

1

3. Replc Y-connector at node #2.

8113-483IN SS NIPPLE

1

4. Chkd valve need to come into shop for repair.

DT043PP007DEUTSCH RECEPTACLE

1

5. Replcd park valve asy; rem dash panels, instrument panel, ___ & air lines; R/R valve asy; reinstall fittings/switches; ran/ck for leaks; ck ok; go to Training fac.

XG840-KITEXTENDA GUN SWITCH

1

Workorder: V19181

In Date: 11/19/2008

Meter Reading: 3,726.00

Close Date: 11/26/2008

Problem?

air pressure leak. Air pressure have to be build up after engine shut down and sat. e43

Task performed:

Parts

Quantity

Repaired on W/O 19072 (11/15/08). j

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V19205

In Date: 11/20/2008 Meter Reading: 38,328.00
Close Date: 11/26/2008

Problem?
DRIVERS SEAT BELT 10-7 E43

Task performed:	Parts	Quantity
Drive to Stn; drivers seat belt lock broken; R/R seat belt. j	IMMF11358SEAT BELTS	1

Workorder: V18937

In Date: 11/08/2008 Meter Reading: 3,698.00
Close Date: 12/01/2008

Problem?
air horn is not sounding at pedal or controls E-43

Task performed:	Parts	Quantity
1. Rep bad connection in rear pump panel for air horn. 2. Rear door cab not latching; readjust door latch. j	NO PARTS USED	

Workorder: V19046

In Date: 11/13/2008 Meter Reading: 3,715.00
Close Date: 12/01/2008

Problem?
The air horn on E43 is not working. Please send motor oil for E43, R43 to Station 43.

Task performed:	Parts	Quantity
Readjust air horns that were out of adjustment. j	NO PARTS USED	

Workorder: V19182

In Date: 11/19/2008 Meter Reading: 3,726.00
Close Date: 12/02/2008

Problem?
pressure relief light not working e43

Task performed:	Parts	Quantity
Ran pump & chkd relief valve & tested ok. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V18485

In Date: 10/21/2008 Meter Reading: 51,445.00
 Close Date: 12/05/2008

Problem?
 replace tires at shop callaghan

Task performed:	Parts	Quantity
replace tires at shop	NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V19339

In Date: 11/25/2008 Meter Reading: 3,741.70
 Close Date: 12/08/2008

Problem?
 REPLACE FRONT TIRES AT STA CALLAGHAN E43

Task performed:	Parts	Quantity
	NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V19414

In Date: 12/01/2008 Meter Reading: 38,460.00
 Close Date: 12/15/2008

Problem?
 PUMP LEAK AT DECK GUN E-43

Task performed:	Parts	Quantity
Deck gun leaking at pump fitting; tighten valve; will monitor valve. j	NO PARTS USED	

Workorder: V19783

In Date: 12/16/2008 Meter Reading: 3,783.00
 Close Date: 01/05/2009

Problem?
 The yellow pre connect (crosslay) open/close valve is leaking on E43. With it closed, you can see the pressure slowly build up on the pump panel.

Task performed:	Parts	Quantity
Preconnect #2 - leaking; installed new valve. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V20571

In Date: 01/24/2009 Meter Reading: 29.50
Close Date: 02/13/2009

Problem?

1. Slow fuel leak, appears to be leaking from the bottom of the water separator... Everything appears to be tight. 2. The pressure relief valve is sticking consistently and not improving with continued cycling. e43

Task performed:

	Parts	Quantity
1. Fuel leak; rep bottom part of fuel filter.	R90PFILTER FUEL 33231	1
2. Rel valve inop; tested rel valve & tested ok. j	RK211131311FUEL BOWL KIT NON-HEATED	1

Workorder: V18042

In Date: 09/30/2008 Meter Reading: 3,641.00
Close Date: 03/02/2009

Problem?

speaker bracket inside cab needs replacement e43

Task performed:

	Parts	Quantity
	NO PARTS USED	

Workorder: V21624

In Date: 03/08/2009 Meter Reading: 137.50
Close Date: 03/12/2009

Problem?

The hurst power unit located on E43 has three broken mounts. Three of the four rubber mounts which locate the power unit within the frame have completely failed... the power unit is no longer secure within its frame. E43

Task performed:

	Parts	Quantity
Replcd (4) broken Hurst tool lebg to tool cage & clean unit. j	HR149460107MOUNT VIBRATION (NEWER POWER UNITS	4
Installed new motor mounts for Hurst unit. j		

Workorder: V21936

In Date: 03/19/2009 Meter Reading: 169.00
Close Date: 03/27/2009

Problem?

E43's Warning compartment open light and deck gun extended light in cab flashing without cause, possible electrical issue from excessive rain E43

Task performed:

	Parts	Quantity
Travel to Stn43; chkd eng; fnd loose connection at extend gun switch & rep door ajar not going off; chkd swtchs; ok. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22062

In Date: 03/25/2009
Close Date: 04/03/2009

Meter Reading: 6,059.00

Problem?

generator leaks fuel e 43

Task performed:

1. Drop off oil.
2. Fuel leak; rep fuel leak on gen.
3. Door open light on; readj rear door swtchs.
4. Ram fan inop; clnd out carb & fuel; ran/tested ok. j

Parts	Quantity
15W40BSYN OIL BULK QTS	12

Workorder: V21735

In Date: 03/12/2009
Close Date: 04/13/2009

Meter Reading: 5,994.50

Problem?

REPLACE R/REAR INSIDE TIRE, E-43

Task performed:

Replace R/rear inside tire E43 - Callaghan j

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V15550

In Date: 06/05/2008
Close Date: 04/17/2009

Meter Reading: 34,867.00

Problem?

HURST POWER UNIT SPUTTERS UNDER LOAD e43

Task performed:

replaced spark plug & tested. j

Parts	Quantity
BPR6ESSPARK PLUG 7131	1

Workorder: V22383

In Date: 04/07/2009
Close Date: 05/05/2009

Meter Reading: 2,011.00

Problem?

netting clip broken for preconnect on driver side. needs replacement E43

Task performed:

1. Preconnect netting brkn; replcd netting.
2. Air horn inop; replcd air horn foot swtch.
3. Door open light obn; fnd no lights on.
4. Hurst unit no start; installed new plug. j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V22698

In Date: 04/20/2009 **Meter Reading:** 2,050.00
Close Date: 05/08/2009

Problem?

red battery cable is frayed, located by the left front wheel e43

Task performed:

	Parts	Quantity
--	-------	----------

1. Chkd btry cables/tested ok.
2. water leak; rep fitting on pump.
3. A/C belts making noise; adj belts.
4. Coolant leak; rep leak at tank. j

NO PARTS USED

Workorder: V23475

In Date: 05/22/2009 **Meter Reading:** 7,690.00
Close Date: 06/01/2009

Problem?

DOOR AJAR LIGHT ON, E-43

Task performed:

	Parts	Quantity
--	-------	----------

Door open light on; fnd water in connection. j

NO PARTS USED

Workorder: V24119

In Date: 06/15/2009 **Meter Reading:** 8,116.00
Close Date: 06/19/2009

Problem?

ON CALL VISTA SCREEN 10-7 E 43

Task performed:

	Parts	Quantity
--	-------	----------

Rep screw in HUR node in console; loose & moving arnd. j

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V23869

In Date: 06/06/2009
Close Date: 06/20/2009

Meter Reading: 8,116.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED E43

Task performed:

- B-Inspection
- 2. Replcd btrys - bad.
- 3. Brakes squeel; brake dust; rem backing plates & clnd w/soap/water.
- 4. Pulls to the right - tires; swapped frnt tires; road tested ok.
- 5. Frnt hubs leak; over full; adj oil level/cln.
- 6. Cant chk rear tire press; valve exts msng; installed new extensions
- 7. Install air horn foot swtch for officer; Stn request.
- 8. Several body markers dim; door grnds; rep grnds & install new lights.

NOTE: Air horn foot swtch charged out on another W/O.

- 9. Eng oil leak; return elbow split for turbo & breather; replcd elbow.
- 10. Fuel leak/lift pump; replcd lift pump. j

Parts

Quantity

15W40BSYN OIL BULK QTS	40
20A-400CLAMP 4" 33969	2
35200-RLIGHT MARKER LED RED	2
35200-YLIGHT MARKER LEDAMBER	2
3935172USE 3963988 WASHER-SEAL	2
3949085PUMP ISC FUEL TRANSFER NEW #4935005	1
3963983WASHER SEAL ISB	2
3968496HOSE DRAIN OIL 3948068	1
435 VALVE CAP	10
440-44 1/8 IN VALVE EXT	2
50R03ZCRLIGHT LED RED TIR 6	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V24345

In Date: 06/25/2009
Close Date: 07/06/2009

Meter Reading: 2,182.00

Problem?

left telelight stays on.

Task performed:

- 1. Replcd switch for spotlight.
- 2. Water leak in cab; resealed roof. j

Parts

Quantity

NO PARTS USED

Workorder: V24364

In Date: 06/26/2009
Close Date: 07/08/2009

Meter Reading: 8,394.70

Problem?

SPOT LIGHTS NOT SHUTTING OFF, E-43

Task performed:

- Spot lights inop; replcd light switch. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24582

In Date: 07/06/2009
Close Date: 07/15/2009

Meter Reading: 2,196.00

Problem?

door ajar light and buzzer stays on. e43

Task performed:

1. Traced door ajar problem to junction box under truck full of water; replcd junction box; rewired & replcd door adjar switch in ladder compt. j

Parts	Quantity
52-624SWITCH DOOR	1
CB-104BOX-CIRCUT BREAK BE22040	1

Workorder: V24980

In Date: 07/22/2009
Close Date: 07/27/2009

Meter Reading: 8,768.50

Problem?

RE43 K-12 SAW REPAIRED BY REGAN

Task performed:

RE43 K-12 saw repaired by Regan j

Parts	Quantity
NO PARTS USED	

Vendor?: REGANS SMALL ENG

Workorder: V24852

In Date: 07/17/2009
Close Date: 07/28/2009

Meter Reading: 2,216.00

Problem?

Driver side, rear passenger seatbelt top anchor fell out. Unable to use. e43

Task performed:

Rep rear seat that was coming loose. j

Parts	Quantity
NO PARTS USED	

Workorder: V24864

In Date: 07/18/2009
Close Date: 07/28/2009

Meter Reading: 8,768.50

Problem?

the k-12 shuts off when the throttle is pulled E43

Task performed:

1. worked on K-12 saw & tested.
2. Preconnect leaking; readj valve.
3. Rear marker lights out; ran new wire for marker lights, j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V24893

In Date: 07/20/2009 Meter Reading: 2,216.00
Close Date: 07/28/2009

Problem?

driver side rear passenger seat belt bolt fell out again. No seat belt on that side.r43

Task performed:	Parts	Quantity
rep left rear seat belt; tested & tested ok. j	NO PARTS USED	

Workorder: V23514

In Date: 05/25/2009 Meter Reading: 2,129.00
Close Date: 07/29/2009

Problem?

At your convenience, would you bring by some valve stem extensions for the rear inner tires. I'm unable to measure the air pressure for the rear inner tires... there are no extensions currently in place. E43

Task performed:	Parts	Quantity
Installed new valve stem on rear tires. j	NO PARTS USED	

A/C inop; recharged sys.
Marker lights out; fnd bad grnd. j

Workorder: V24527

In Date: 07/02/2009 Meter Reading: 2,188.00
Close Date: 07/29/2009

Problem?

Windshield wipers take several attempts to turn off. e43

Task performed:	Parts	Quantity
1. Replcd wiper switch.	NO PARTS USED	
2. Door open light on; fnd switch bad; readj switch. j		

Workorder: V25237

In Date: 08/03/2009 Meter Reading: 8,934.00
Close Date: 08/17/2009

Problem?

E-43 oil leak

Task performed:	Parts	Quantity
1. Oil leak rep leak at filter.	NO PARTS USED	
2. Air leak; chkd for air leaks; fnd none at this time.		
j		



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25332

In Date: 08/05/2009
Close Date: 08/24/2009

Meter Reading: 9,107.40

Problem?

will not idle and does not reach full rpm. k12 just back from shop. needs repair. E-43

Task performed:

Parts

Quantity

- 1.Saw inop; worked on saw; will send back to shop (K12 saw).
2. Chain saw inop; rem bad fuel & clnd carb. j

NO PARTS USED

Workorder: V25291

In Date: 08/04/2009
Close Date: 08/27/2009

Meter Reading: 9,107.40

Problem?

Need 2 cycle oil for Station 43.

Task performed:

Parts

Quantity

1. Belt making noise; adj A/C belt & rep A/C brkt. j

39768315259022 GROOVED TENSIONER OLD#3936213
K080716BELT

1

1

Workorder: V25532

In Date: 08/14/2009
Close Date: 08/27/2009

Meter Reading: 476.00

Problem?

fan belts still making screeching noise when truck accelerates, work request made last week and mechanic came out and stated that a part was needed and would return the following day to correct, however no one returned E-43

Task performed:

Parts

Quantity

1. Belts making noise; readj belts.
2. Door open light on; readj all door switches. j

NO PARTS USED

Workorder: V25533

In Date: 08/14/2009
Close Date: 08/27/2009

Meter Reading: 476.00

Problem?

K-12 saw won't start, work request made previously, saw still not serviced

Task performed:

Parts

Quantity

1. Worked on K12 saw; will send back to shop.
2. Ram fan inop; rem gas & put new gas in tank. j

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V25541

In Date: 08/15/2009
Close Date: 08/27/2009

Meter Reading: 476.00

Problem?

valve for #2 preconnect leaks, charging the hose. E43

Task performed:

1. readj #2 discharge valve that was leaking.
2. Chain saw inop; cind carb & tested.
3. Air horns inop; rep connection on solenoid. j

Parts

NO PARTS USED

Quantity

Workorder: V25565

In Date: 08/16/2009
Close Date: 08/27/2009

Meter Reading: 9,328.00

Problem?

E43's K-12 needs to be checked out. If you run it at high revs the engine starts breaking up almost to a stall. Also, could you ask Tommy about the tension bar for E43. The engine is still squealing

Task performed:

1. Air leak; no air leaks at this time.
2. Spotlight inop; rep bad connection. j

Parts

NO PARTS USED

Quantity

Workorder: V25969

In Date: 09/02/2009
Close Date: 09/30/2009

Meter Reading: 9,629.60

Problem?

Valve on No.2 crosslay leaking, guage builds pressure while fully closed. e43

Task performed:

1. ran pump for second time & fnd no leaks.
2. Installed velcro strps in rear compt. j

Parts

91368904 VALVE KIT 1 1/2 IN
91398907 VALVE KIT 3 IN AKRON

Quantity

1

1

Workorder: V26037

In Date: 09/04/2009
Close Date: 09/30/2009

Meter Reading: 2,271.00

Problem?

E43's deck gun is leaking all the time from the drain, please check.

Task performed:

1. Ran pump at 150PSI & fnd no leaks at deck gun.
2. Readj all valve linkages. j

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V26163

In Date: 09/10/2009
Close Date: 09/30/2009

Meter Reading: 9,688.30

Problem?

REPAIR DOME LTS E43

Task performed:

Mount tools in rear compt. j

Parts

Quantity

NO PARTS USED

Workorder: V26530

In Date: 09/29/2009
Close Date: 11/06/2009

Meter Reading: 232.00

Problem?

left siren speaker not working. e43

Task performed:

1. R/R siren speaker.
2. Relief valve inop; tested valve & tested ok. j

Parts

Quantity

SD-210RSIREN DRIVER

1

Workorder: V26632

In Date: 10/02/2009
Close Date: 11/06/2009

Meter Reading: 10,158.60

Problem?

ENGINE BELTS MAKING NOISE, E-43

Task performed:

1 Installed belts & belt tensioner. j

Parts

Quantity

K080716BELT

1

Workorder: V26760

In Date: 10/08/2009
Close Date: 11/12/2009

Meter Reading: 22.40

Problem?

right telelight not working. E43

Task performed:

1. Rep right side spotlight.
2. Primer inop; cln/lubed. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V27597

In Date: 11/12/2009
Close Date: 12/08/2009

Meter Reading: 97.00

Problem?

The officer's side telescoping scene light quit working (all three bulbs)...repositioning and telescoping did not fix it... ***We need a 14" composite (concrete/steel) blade for our loaner K12 saw, please*** e43

Task performed:

Rep bad connection in spotlight. j

Parts

NO PARTS USED

Quantity

Workorder: V27687

In Date: 11/16/2009
Close Date: 12/10/2009

Meter Reading: 10,976.40

Problem?

repair vent saw (outside agency-regan's small engine service)

Task performed:

Repair vent saw - Regans j

Parts

503155902HALF HANDLE
503401302HANDLE HALF

Quantity

1
1

Vendor?: REGANS SMALL ENG

Workorder: V28543

In Date: 12/22/2009
Close Date: 12/29/2009

Meter Reading: 11,509.00

Problem?

REPAIR SAW E 43REGAN

Task performed:

Parts

NO PARTS USED

Quantity

Vendor?: REAGANS

Workorder: V28614

In Date: 12/28/2009
Close Date: 01/08/2010

Meter Reading: 11,709.00

Problem?

ON CALL COOLANT LEAK E43

Task performed:

Coolant leak; rep leak & tested. j

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V28353

In Date: 12/15/2009 Meter Reading: 162.00
Close Date: 01/14/2010

Problem?
Chainsaw, O-ring seal on bar/chain oil reservoir cap missing. will not hold oil. e43

Task performed:	Parts	Quantity
Rep oil cap & cln carb & tested. j	NO PARTS USED	

Workorder: V28530

In Date: 12/22/2009 Meter Reading: 162.00
Close Date: 01/14/2010

Problem?
right telelight not working. E43

Task performed:	Parts	Quantity
1. Rep right side spotlight.	NO PARTS USED	
2. Water leak; rep/replc brass fitting on pump cooler. j		

Workorder: V28579

In Date: 12/25/2009 Meter Reading: 11,709.00
Close Date: 01/14/2010

Problem?
Hale foam system turns itself off and reads "NoPr" on screen after approx 15 sec of being turned on. must repeatedly turn system back on in order to get foam at nozzle. E43

Task performed:	Parts	Quantity
1. Ran foam sys & tested ok.	NO PARTS USED	
2. No t-signals; rep switch. j		

Workorder: V28585

In Date: 12/26/2009 Meter Reading: 183.00
Close Date: 01/14/2010

Problem?
1. Right side (officer's side) telelight is inoperative.E43 2. #2 crosslay continues to fill with water with the gate valve in the closed position (slow leak) 3. Master intake valve red lamp no longer illuminates. E43

Task performed:	Parts	Quantity
1. Readj crosslay valve that was leaking.	24117SOLENOID INS CONT DUTY	1
2. Recalibrated foam & water gauges.		
3. Rep master intake light that was not working.		
4. Rep air leaks. j		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V28204

In Date: 12/08/2009 Meter Reading: 142.00
Close Date: 01/15/2010

Problem?
right side telescoping scene (spot) light inoperative

Task performed:	Parts	Quantity
1. Rep bad conetion in light.	NO PARTS USED	
2. Water leak; rep fitting on pump. j		

Workorder: V28885

In Date: 01/07/2010 Meter Reading: 11,936.00
Close Date: 02/22/2010

Problem?
air leaks e43

Task performed:	Parts	Quantity
Traced out air leaks. j	NO PARTS USED	

Workorder: V28985

In Date: 01/11/2010 Meter Reading: 215.30
Close Date: 02/22/2010

Problem?
relief valve is activating very slow. passenger side cross lay is leaking. E 43

Task performed:	Parts	Quantity
tested relief valve & tested ok. j	NO PARTS USED	

Workorder: V29834

In Date: 02/09/2010 Meter Reading: 12,534.00
Close Date: 03/03/2010

Problem?
Charging contacts on vehicle mounted TIC charger are bent and not allowing TIC to charge correctly or not at all. e43

Task performed:	Parts	Quantity
Rep contacts on TIC charger & tested. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V29989

In Date: 02/16/2010 Meter Reading: 12,873.00
Close Date: 03/04/2010

Problem?
on call crosslay valve leaking e43

Task performed:	Parts	Quantity
Went to Stn43; ck valve opn; valve inop; rem linkage pipe & valve; rebuilt valve; reinstalled all parts; ck opn; ck ok; return home. j	5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	1

Workorder: V29922

In Date: 02/12/2010 Meter Reading: 12,807.00
Close Date: 03/10/2010

Problem?
during a fire call yesterday, the sawsall was being used when it broke in half. a replacement is needed for engine 43.

Task performed:	Parts	Quantity
Call Stn43; direct them to have Chief Beelsey approve & notify W. Chambers. j	NO PARTS USED	

Workorder: V29406

In Date: 01/25/2010 Meter Reading: 236.00
Close Date: 03/19/2010

Problem?
One section (right side)of strobe lights out on E43's light bar.

Task performed:	Parts	Quantity
Rep LED light that was out in light bar. j	NO PARTS USED	

Workorder: V30389

In Date: 03/02/2010 Meter Reading: 13,182.00
Close Date: 03/25/2010

Problem?
Please repair light bar on E43. The right half has lights out.

Task performed:	Parts	Quantity
LED out on light bar - replcd. j	02-0363596250400 LED / RED	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V30801

In Date: 03/17/2010
Close Date: 04/21/2010

Meter Reading: 13,574.30

Problem?

Relief valve not working properly. VERY slow to close and reset when performing morning check out. e43

Task performed:

tested valve & tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V31811

In Date: 04/26/2010
Close Date: 04/30/2010

Meter Reading: 11,709.00

Problem?

door ajar light on (on-call) E43

Task performed:

Door open lite on; rep ladder compt door. j

Parts

Quantity

NO PARTS USED

Workorder: V31025

In Date: 03/25/2010
Close Date: 05/01/2010

Meter Reading: 13,648.00

Problem?

k-12 pull cord about to break, and wont start

Task performed:

installed 100 inverter for tic & ___ sys. j

Parts

Quantity

3WA16POWER INVERTER 375 AMP

1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V31047

In Date: 03/26/2010

Meter Reading: 13,648.00

Close Date: 05/25/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED E43

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

C-Inspection	01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	1
2. Svc rear axle.	0100080010STRAINER	1
3. Svc T-case.	038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
4. Svc air dryer.	042002000SPRING RELIEF VALVE HALE	1
5. Replc frnt shocks; bottom bolts on both shocks rusted on; had to use oil/heat to remove.	05-17223-000CAP RADIATOR 10 LB	1
6. Replc all (4) btrys; cln terms.	073-0010-00PISTON RELIEF VALVE HALE	1
7. Svc P/S.	107796DRYER KIT AD9 -NEW	1
8. Torque u-bolts front/rear.	107800VALVE CHECK AD9	1
9. Rep brkn wires at connector for R/side pump panel walic waylite; replc both LED lites; replc LED lite i L-1 compt.	108-12FBEADED CHAIN W/CONN 12	4
10. Rem eng fan; replc alt belt/tensioner; replc both A/C belts; reinstall fan; run eng; readj belts.	14022-1-5COOLER 14032	1
11. Drain cooling sys; rem trans cooler; travel to C/S to rem fittings; install new cooler; refill coolant.	15W40BSYN OIL BULK QTS	24
12. Replc L/side rear marker lite; LED's were half out on lite.	1891BULB	3
13. Replc A/C vents on rear red deot sys; cab vents were msng.	29526898 29548988 TRANS FILTER ALLISON	1
14. LED display bad on throttle cntrl on pump panel; replce display.	3040815PLUG THREAD	1
15. Replc switch for quartz lites;hard to turn on/off.	3046202THREAD PLUG	1
16. Trilock on R/side ump panel brin;	372000030BATTERY ON DISPLAY	1
17. All (4) A/C dah vents brkn; replc all (4).	372000031IGNITION ON DISPLAY	1
18. Replc all brkn discharge chains for caps; rplace all brkn intake chains for caps.	372000084MARKER LIGHT	1
19. Rem leaking eng trans pump; rem L/side frnt fender & rem pump; install new trans pump; reinstall fendeer; run/chk; ok.	3920773WASHER DRAIN PLUG	1
20. Rem intake relief valve & rep, install intake relief valve.	3924147OIL DRAIN PLUG CUMMINS	1
21.Replc LED lite on pump panel.	3949085PUMP ISC FUEL TRANSFER NEW #4935005	1
22. Install master btry on/off switch switch was hard to turn.	3963983WASHER SEAL ISB	4
23; Remove discharge side relief valve & rebuild, install new chkc valve; isntall (2) new hose fittings; reinstall relief valve.	3963988WASHER SEAL	3
24. Rem R/side rolleer for preconect & install bottom clip for net.	39768315259022 GROOVED TENSIONER OLD#3936213	1
25. Rebuild master drain valve.	524740830-805 A/F HONDA 17210-ZE1-505	1
26. Replc "Batton " & Ing on" switchs on dash board; green lites wld not come on.	546126000TPM/QG HALE REPAIR KIT	1
27. Rem master intake valve on L/side 6" Instake valve & replce lite switches	5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	1
for open/closed lites; lites were not coming on. j	607141-05USE 61H01 COPMPARTMENT LIGHT	3
	6803230300 65482 SHOCK FRONT ENGINE	2
	6808300074VENT A/C LH	2
	6808300174VENT A/C RH	2
	72R31001720 DIFFUSER A/C 3.5 IN	3
	7460967AIR FILTER 17210-ZE2-515 HONDA	1
	75908SWITCH BATTERY MASTER 300A	1
	78R536078R5360M 2PK FILTER AIR COND	1
	800405PURGE VALVE KIT	1
	8126482-2106 TOGGLE GUARD	1
	9440BELT	1
	9480BELT	1
	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
	BPR5ESSPARK PLUG 7734	2
	CA8193AIR FILTER 46744 WIX	1
	ELA101-ATHROTTLE EXCEL CUMMINS IS SERIES	1
	FG87904MFG3937557S FILTER P/S NEW STYLE	1
	FGQ79699GASKET-P/S FILTER NEW STYLE	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HP-31DBATTERY 950CCA HP-31D	4
HPH6349AOIL FILTER 51748	1
K080716BELT	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1

Workorder: V31907

In Date: 05/01/2010 **Meter Reading:** 14,255.00
Close Date: 06/04/2010

Problem?

during pump testing on 4/30-B shift noticed 1/10 engine speed connection not working. Also digital pump discharge guage hard to read in sunlight due to LED lights broken on display. This might already be on order. E43

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Chkd opn of pump & tested ok. j	NO PARTS USED	

Workorder: V32046

In Date: 05/06/2010 **Meter Reading:** 14,322.80
Close Date: 06/04/2010

Problem?

1/10 engine speed port not working, this was discovered during the pump test. E43

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Rep cable for pump RPMS. j	NO PARTS USED	

Workorder: V32266

In Date: 05/18/2010 **Meter Reading:** 14,577.00
Close Date: 06/09/2010

Problem?

the stihl chain saw on engine 43 will not start up.

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Clnd carb & tested. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V32450

In Date: 05/26/2010
Close Date: 06/28/2010

Meter Reading: 14,646.00

Problem?

K12 saw starter cord handle is broken. needs to be replaced to start safely. True assest number is F00758 E43

Task performed:

sent to shop for repair. j

Parts

Quantity

NO PARTS USED

Workorder: V32723

In Date: 06/07/2010
Close Date: 06/28/2010

Meter Reading: 14,940.00

Problem?

T.I.C. screen is not clear and the readings seem to be incorrect.

Task performed:

1. Chkd opn of gauge & tested ok.
 2. T-signals inop; rep connection in left rear frame rail.
- j

Parts

Quantity

NO PARTS USED

Workorder: V32724

In Date: 06/07/2010
Close Date: 07/21/2010

Meter Reading: 14,940.00

Problem?

siren cannot be operated by utilizing the horn located on the steering wheel. E43

Task performed:

Replc siren head.

Parts

Quantity

NO PARTS USED

Workorder: V33333

In Date: 07/05/2010
Close Date: 07/23/2010

Meter Reading: 15,231.50

Problem?

pressure relief valve has a long delay while setting and doesnt seem to work correctly E43

Task performed:

Went to 43; FF on shift said relief valve working good; we ran pump & is reacting well within 30PSI; just a little slow releasing. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V34645

In Date: 08/31/2010 Meter Reading: 9,688.30
Close Date: 09/29/2010

Problem?
Replace 4 rear tires (outside agency-boulevard tire) E43

Task performed:	Parts	Quantity
Replc (4) rear tires E43 - Boulevard j	NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V34875

In Date: 09/11/2010 Meter Reading: 16,730.00
Close Date: 10/05/2010

Problem?
need 2 lugnuts caps for front wheel. E43

Task performed:	Parts	Quantity
1. Replc msng/brkn lugnut cvrs.	101305001BRACKET LEFT DH0008-5	1
2. Rep brkn strut brkt on L-1 compt door. j	ACX-84534LUG NUT COVER PK10	3
	EAA-8350-30UGSS1783UQ STRUT-LIFT	1

Workorder: V35043

In Date: 09/19/2010 Meter Reading: 16,930.00
Close Date: 10/18/2010

Problem?
It appears that the front 2 bolts to the engine intake manifold are missing and intake gasket it slipping out. E43

Task performed:	Parts	Quantity
Will need to come to shop for repair. j	NO PARTS USED	

Workorder: V34532

In Date: 08/26/2010 Meter Reading: 16,215.00
Close Date: 10/20/2010

Problem?
Left side / telescoping quartz spot/scene light has one (1) of two (2) bulbs 10-7. E43

Task performed:	Parts	Quantity
1. Rep bad connection in light & tested.	NO PARTS USED	
2. Air ride seat inop; rep air line; installed new one. j		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V34979

In Date: 09/16/2010 **Meter Reading:** 16,930.00
Close Date: 10/20/2010

Problem?

for your information: while responding to a call, engine 43 shut completely down while making a right turn. after letting it sit for a few seconds with everything shut off, it started back up and was ok after that. e43

Task performed:

Task performed:	Parts	Quantity
Chkd truck road tested; NFP w/truck. j	020383481RALENS SPLIT RED/AMBER	2
	50R03ZCRLIGHT LED RED TIR 6	4
	602000RULIGHT	2

Workorder: V35083

In Date: 09/21/2010 **Meter Reading:** 16,930.00
Close Date: 10/20/2010

Problem?

Drivers air seat not working.. will not inflate.

Task performed:

Task performed:	Parts	Quantity
Rep air line on air seat. j	NO PARTS USED	

Workorder: V36057

In Date: 11/01/2010 **Meter Reading:** 17,852.00
Close Date: 12/10/2010

Problem?

Valve/plumbing on right side 1 3/4" preconnect (yellow) leaking allowing bottom sections of hose to partially charge with water. Almost could not get out of hosebed on fire call last night. PLEASE FIX E43

Task performed:

Task performed:	Parts	Quantity
(1) TRAVELED TO STATION 43 TO REPAIR RIGHT SIDE PRECONNECT VALVE THAT ISN'T CLOSING OFF ALL THE WAY ON E43. REMOVED VALVE, ADJUSTED LINKAGE AND REINSTALLED VALVE AND TESTED. OK.	NO PARTS USED	

J.W.



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V36203

In Date: 11/04/2010 **Meter Reading:** 17,934.00
Close Date: 12/13/2010

Problem?
screw/nail in front left tire E43

Task performed:

	Parts	Quantity
--	-------	----------

(1) TRAVELED TO STATION 43 TO REPAIR A TIRE ON E43. REMOVED A NAIL FROM THE TIRE. WAS NOT LEAKING AIR AFTER REMOVAL OF THE NAIL. OK.
 (2) COMPARTMENT LIGHT WAS STAYING ON. CHECKED AND FOUND THE DOOR SWITCH UNPLUGGED. REPAIRED AND TESTED OK.
 (3) REPAIRED SLIDE OUT TRAY THAT WAS HARD TO OPEN. OK.

NO PARTS USED

Workorder: V36553

In Date: 11/18/2010 **Meter Reading:** 17,983.00
Close Date: 12/14/2010

Problem?
Pump panel lights and telescoping scene lights 10-7. Also, right side 1 3/4 " preconnect still leaking and charging hose in hosebec E43

Task performed:

	Parts	Quantity
--	-------	----------

(1) TRAVELED TO STATION 43 TO REPAIR PUMP PANEL LIGHTS AND TELESCOPING SCENE LIGHTS ON E43 THAT WASN'T WORKING. TESTED ALL LIGHTS AND FOUND THAT THE DRIVER OPERATOR DID NOT SEEM TO KNOW HOW TO TURN THEM ON. OK. J.W.

NO PARTS USED

Workorder: V36448

In Date: 11/15/2010 **Meter Reading:** 17,983.00
Close Date: 12/15/2010

Problem?
Left A/C compressor on engine appears to have a bolt missing on mounting bracket. Top/left rear compartment door latch is loose..needs adjusting. e43

Task performed:

	Parts	Quantity
--	-------	----------

(1) TRAVELED TO STATION 43 TO REPLACE A BOLT ON THE A/C COMPRESSOR OF E43 THAT WAS NOTED. INSTALLED NEW BOLT INTO THE A/C COMPRESSOR AND MOUNT. OK. J.W.

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V36239

In Date: 11/06/2010 **Meter Reading:** 17,983.00
Close Date: 12/16/2010

Problem?
 found air leaking from valve on front tank. Also front suction air valve is not working properly. The valve did not open during fire training this morning. Not sure if these are related.E43

Task performed:	Parts	Quantity
(1) TRAVELED TO ST43 TO REPAIR AIR LEAK ON E43 FRONT AIR TANK AND CHECK OUT FRONT SUCTION VALVE. TESTED FRONT SUCTION VALVE AND DID NOT FIND ANYTHING NOT WORKING. J.W.	NO PARTS USED	

Workorder: V35239

In Date: 09/28/2010 **Meter Reading:** 16,930.00
Close Date: 12/22/2010

Problem?
 WONT START E43

Task performed:	Parts	Quantity
(1) E43 WON'T START. FOUND STARTER BAD. REPLACED WITH NEW ONE. E43 THEN STARTED. J.W.	190260286808 8200005 STARTER	1
	6811802643S68-1180264-3S LENS	2
	6811813493LENS CLEAR 68-1181349-3	2

Workorder: V35420

In Date: 10/05/2010 **Meter Reading:** 17,257.90
Close Date: 12/22/2010

Problem?
 chain saw 10-07 e43

Task performed:	Parts	Quantity
(1) CHAIN SAW WON'T RUN ON E43 UNIT WAS TAKEN TO THE COUNTY FR SHOP. J.W.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V36676

In Date: 11/26/2010

Meter Reading: 18,396.00

Close Date: 01/03/2011

Problem?

Engine 43 foam inductor malfunctioning. When foam is activated, the engine rpm drops. contact Dave Allen at 43B for more info.
969-0656 E43

Task performed:

(1) TRAVELED TO ST-43 TO REPAIR FOAM RPM PROBLEM ON E43. TRACED OUT PROBLEM WITH FOAM SYSTEM. FOUND BAD WIRE GROUND. REPAIRED.

(2) CHECKED OUT TANK FILL VALVE FOR LEAKING H2O. READJUSTED VALVE AND LEAK STOPPED.

Parts

Quantity

NO PARTS USED

J.W.



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37303

In Date: 12/20/2010

Meter Reading: 19,119.00

Close Date: 01/05/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED E 43

Task performed:

1. remove exhaust manifold's, remove broken bolts in head. install new manifolds, bolts, gaskets, and spacers.
2. B inspection
3. replace a/c compressor for cab rear a/c, replace dryer, flush out system, replace a/c compressor lines, remove engine fan replace a/c belt. evacuate and charge system.
4. driver stated rear a/c water leaking on cab floor, reseal a/c unit
5. replace water pump, replace coolant tank sight glass, tighten coolant hoses
6. check for air leak, found air ride bags leaking for cab, replace both bags, recheck for air leak, tighten numerours fittings that were leaking, and repalce 3 fittings on foot valve.
7. install battery charger, and auto-eject

Parts	Quantity
0913912CHARGER 2000	1
0915520120AUTO EJECT 20 AERO OTL3925	1
15W40BSYN OIL BULK QTS	24
3348757O RING	1
3922794SEAL O RING	1
3937477MANIFOLD EXHAUST	1
39374795269779 EXHAUST GASKET C	6
3937706USE 5264569 GASKET OIL	1
3943841EXHAUST MANIFOLD	1
3944593EXH. MAN. BOLT	12
3945252SPACER EXH. MAN.	12
40896474309418 PUMP-WATER ISC REBUILT	1
4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT	1
4512S08-6933BS A/C FITTING STEEL	1
576403-3470 COMPRESSOR A/C 5720	1
74R258607-2613A RED DOT DRIER 7127	1
78R536078R5360M 2PK FILTER AIR COND	1
8201L17-3428 ESTER OIL E7	1
9440BELT	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
LML-1102-0023CAB AIR BAG IS4007	1
PR338324070 WIX FILTER WATER	1
R90PFILTER FUEL 33231	1
VML-T1413T3248 SIGHT GLASS	1

Workorder: V37009

In Date: 12/08/2010

Meter Reading: 18,646.00

Close Date: 01/11/2011

Problem?

Foam inductor malfunctioning. When foam inductor is engaged, engine rpm drops. e43

Task performed:

Rep bad power & grnd wire; problem rep. j

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37037

In Date: 12/09/2010 Meter Reading: 18,646.00
 Close Date: 01/11/2011

Problem?

The K12 on E-43 had the pull rope pulled out of it while trying to start it during morning check out

Task performed:	Parts	Quantity
Rep pull cord on K12. j	NO PARTS USED	

Workorder: V37170

In Date: 12/15/2010 Meter Reading: 18,926.40
 Close Date: 01/11/2011

Problem?

E43 LEAKING RADIATOR FLUID FROM TOP HOSE.

Task performed:	Parts	Quantity
1. Rep hose clamps on top hose.	NO PARTS USED	
2. Wtr gauge inop; recalibrated wtr level gauge. j		

Workorder: V38843

In Date: 02/28/2011 Meter Reading: 20,210.00
 Close Date: 03/03/2011

Problem?

CHECK ENG STOP ENG LT ON E 43

Task performed:	Parts	Quantity
Change out fuel filter/sensor on eng; pull off ECM plus off side of motor; chk wiring to pump throttle & rep; fnd pump throttle on pump panel bad; replc w/new; C/O code - all inactive; clear & test drive; all codes gone. j	ELA101-ATHROTTLER EXCEL CUMMINS IS SERIES FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1 1

Workorder: V37844

In Date: 01/17/2011 Meter Reading: 19,306.50
 Close Date: 03/08/2011

Problem?

While pumping a dumpster fire, I engaged the Hale Foam system and the pump lost pressure and then fluctuated pressures. I the disengaged the Foam system and my pressure returned to normal. E43

Task performed:	Parts	Quantity
Chkd foam sys & tested ok; ran new grnd wire to computer. j	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38422

In Date: 02/10/2011 Meter Reading: 19,813.00
Close Date: 03/08/2011

Problem?

deck gun swivel lock broke. not able to lock so it rotates. looks like its just the metal spring. E43

Task performed:	Parts	Quantity
Replcd lock on swivel & tested. j	X170DECK GUN ROTATION LOCK INSERT	1

Workorder: V38543

In Date: 02/15/2011 Meter Reading: 19,867.00
Close Date: 03/09/2011

Problem?

the backup alarm on engine 43 is not sounding.

Task performed:	Parts	Quantity
Replcd backup alarm & tested. j	NO PARTS USED	

Workorder: V38774

In Date: 02/25/2011 Meter Reading: 20,154.00
Close Date: 03/09/2011

Problem?

Front driver's side warning light on side of hood - 2 led bulbs out. e43

Task performed:	Parts	Quantity
1. Rep LED light out on hood. 2. Adj rear door latch that was hard to open. j	NO PARTS USED	

Workorder: V38569

In Date: 02/16/2011 Meter Reading: 19,867.00
Close Date: 03/15/2011

Problem?

digital pump discharge guage on pump panel-last digit unable to read. mechanic stated already replaced but is now not working again. E43

Task performed:	Parts	Quantity
Replcd unit on 1-1-11; tested guage & tested ok. j	IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38632

In Date: 02/18/2011 **Meter Reading:** 20,008.00
Close Date: 03/15/2011

Problem?

the number 2 crosslay (yellow) valve leaks, which caused the crosslay to charge in its bed while the engine was pumping at a brush fire. when the drain valve is opened, a small steady stream of water keeps flowing out. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
Chkd preconnect for valve leaking; fnd no valve leaking. j	NO PARTS USED	

REFER TO WO 38993 AND 37779

Workorder: V38633

In Date: 02/18/2011 **Meter Reading:** 20,008.00
Close Date: 03/15/2011

Problem?

when the foam pump is turned on, the engine rpm's oscillates up and down. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
Ran pump; FNP w/pump. j	NO PARTS USED	

Workorder: V39254

In Date: 03/16/2011 **Meter Reading:** 20,546.80
Close Date: 03/18/2011

Problem?

PUMP SURGES UP TO 100 PSI WHEN FOAM SYSTEM IS ACTIVATED E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. travel to sta-43	15W40QSYN OIL QT	12
2. check out surge in pump	IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
3. travel to central shop for parts, travel back to sta-43		
4. replace master pump gauge		
5. check foam system, called hale products spoke with sal was told it might be a bad ground. check all grounds and clean. recheck system still surges, spoke with hale and was told it might be in the FRC throttle system.		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V38976

In Date: 03/05/2011 Meter Reading: 20,389.10
Close Date: 04/06/2011

Problem?
lightbar mounted spotlight is not working. E43

Task performed:	Parts	Quantity
rep spotlight that was out. j	2208880ALL STEER SWITCH	1
	FREIGHTSHIPPING CHARGES	15

Workorder: V38993

In Date: 03/06/2011 Meter Reading: 20,489.00
Close Date: 04/06/2011

Problem?
Intake pressure relief valve activates while in tank to pump, resulting in dumping tank water on the ground. E 43

Task performed:	Parts	Quantity
1. Ran pump & chkd opn of pump & tested ok. j	NO PARTS USED	
REFER TO WO37779 AND 38632		

Workorder: V38994

In Date: 03/06/2011 Meter Reading: 20,489.00
Close Date: 04/06/2011

Problem?
remote roof spot light is out E43

Task performed:	Parts	Quantity
Rep handheld spotlight. j	NO PARTS USED	

Workorder: V39031

In Date: 03/07/2011 Meter Reading: 20,546.80
Close Date: 04/06/2011

Problem?
spot light on top of the engine is out. E43

Task performed:	Parts	Quantity
rep rear spotlight. j	168-0380-56-0FM CONTROL UNIT RETROFIT KIT	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39109

In Date: 03/10/2011 **Meter Reading:** 20,546.80
Close Date: 04/06/2011

Problem?

Thermal imaging camera is not charging tic properly and indicator light is not functioning E43

Task performed:

replcd TIC charger. j

Parts	Quantity
NO PARTS USED	

Workorder: V39110

In Date: 03/10/2011 **Meter Reading:** 20,546.80
Close Date: 04/06/2011

Problem?

pinhole is located in the soft sleeve supply line on engine E 43

Task performed:

DC will order new hose. j

Parts	Quantity
NO PARTS USED	

Workorder: V39282

In Date: 03/18/2011 **Meter Reading:** 20,546.80
Close Date: 04/22/2011

Problem?

Intake Pressure Relief Valve opens and dumps tank water on the ground when excessive pressure is put on the pressure relief valve while exercising it. This should not happen. E 43

Task performed:

1. travel to sta-43 check relief valve, travel to s/shop for parts, travel back to sta-43
2. replace check valve in TPM system, still dumps water, per ED.E will bring to shop for repairs
3. Assist in t-shooting eng mgmt pump panel cntrol & foam sys.
4. install new foam sys controller in pump panel; cut to fit pump panel; wire into sys; works ok at this time.
5. Replc switch on L/side telecope light wire in new one; brkn on pump panel.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V39830

In Date: 04/11/2011
Close Date: 04/22/2011

Meter Reading: 21,298.00

Problem?

E 43 unable to pass primer test until 2.5inch intake relief valve as capped. Same Intake valve now leaking after test. Pump panel trans temp guage OOS.

Task performed:

1. C/O truck; fnd slow relief valve cntrl; replc controller on pump panel bad; works ok at this time.
2. Fnd flow meter not _____; C/O - fnd wire off - rep; reading ok at this time; C/O foam system.
3. Rebuild transfer valve under truck for water; dumping out - ok.(See W.O. 39282)
4. R/R foam head on motor; C/O gear, etc.
5. C/O temp on trans gauge; looks to be ok at this time.

Parts	Quantity
0100080010STRAINER	2
038-0191-00CONTROL VALVE	1
168-0380-56-0FM CONTROL UNIT RETROFIT KIT	1
519007110SLIDE CONTROL 519-0071-10	1
5582-10 82-2111 GROTE ON-OFF WEATHERPROOF	1
562008002PM CONTROL 562-0080-02	1
8126482-2106 TOGGLE GUARD	1
ELA101-ATHROTTLER EXCEL CUMMINS IS SERIES	1

Workorder: V39303

In Date: 03/20/2011
Close Date: 05/13/2011

Meter Reading: 20,546.80

Problem?

left telelight is not working. E43

Task performed:

1. Rep bad connection on light. j

Parts	Quantity
NO PARTS USED	

Workorder: V40579

In Date: 05/12/2011
Close Date: 06/03/2011

Meter Reading: 22,306.00

Problem?

driver side head light is out. Sta 43.

Task performed:

1. Replc headlight & adjusted.
2. Rep air ride seat that was not working. j

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	4



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41133

In Date: 06/06/2011

Meter Reading: 22,841.00

Close Date: 06/07/2011

Problem?

Call-out. E43 rough idle, check engine light.

Task performed:

E43 rough idle; chk eng light; code 277 & code for heating; R/R transient heatsink; still running rough; injection cntrl valve fault; swapped into spare from shop.
j

Parts

Quantity

3944110DIODE SUPPRESSOR

1

Workorder: V41130

In Date: 06/06/2011

Meter Reading: 22,841.00

Close Date: 06/08/2011

Problem?

Won't run. Towed to shop

Task performed:

Wont run, towed to shop - Westway j

Parts

Quantity

NO PARTS USED

Vendor?: WESTWAY

Workorder: V40655

In Date: 05/17/2011

Meter Reading: 22,306.00

Close Date: 06/09/2011

Problem?

Pressure relief valve is still dumping tank water on the ground from the intake pressure relief valve being ingauged just on tank water. Sta 43.

Task performed:

Ran pump & chkd op n of pump & tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V40810

In Date: 05/23/2011

Meter Reading: 22,644.00

Close Date: 06/09/2011

Problem?

#2 preconnect line (crosslay/yellow nozzle) possibly has slow leak,filling hose line.line was drained earlier and hose has filled up again.Confirmed valve was closed. Sta 43.

Task performed:

Readj valve & tested. j

Parts

Quantity

7200000050VALVE SS 2IN 720-0000-00-50

1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V41153

In Date: 06/06/2011 **Meter Reading:** 22,841.00

Close Date: 06/13/2011

Problem?
injection pump.

Task performed:	<u>Parts</u>	<u>Quantity</u>
Test drove - has code 111; needs ECM & poss injection cntrl valve. j	NO PARTS USED	

Workorder: V41308

In Date: 06/15/2011 **Meter Reading:** 23,049.00

Close Date: 06/23/2011

Problem?
A inspection, ear on a/c broken.

Task performed:	<u>Parts</u>	<u>Quantity</u>
A-Svc - fill wtr tank to test pump.	194BULB	3
2. Fnd A/C omp bolt brkn; loosen belt & R/R bolt; ran & ck ok.	50R03ZCRLIGHT LED RED TIR 6	1
3. Fnd L/hood strobes out; R/R light asy; R/R L/marker lens/bulb; ck ok.	52-24WIPER BLADES ANCO 24	2
4. Quality check - Hines.	5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0	1
5. Fnd mirror brkt; mnt bolts loose - tightened bolts; ck ok.	78R536078R5360M 2PK FILTER AIR COND	1
6. R/R compt door shocks; R/R rear A/C filters.	91513AMBER LENS	1
7. Fnd #2 x-lay valve leaking; drained tank, rem valve; rebuilt valve; installed/greased; R/R drain hose fitting; filled tank; ck ok.	EAA-8350-30UGSS1783UQ STRUT-LIFT	3
8. Ck for coolant leaks; press test, tightened clamps; toppd off tank; ck ok.		
9. Cln btry/trash line compt slides; cln, blew off & lubed slides/locks; ck opn - ck ok.		
10. Ck for eng codes; test drove; ck codes; ck ok.		
j		

Workorder: V42126

In Date: 07/19/2011 **Meter Reading:** 23,382.00

Close Date: 07/19/2011

Problem?
Deliver hurst hoses to sta 43.

Task performed:	<u>Parts</u>	<u>Quantity</u>
parts only no labor	3530016HOSE HURST 16 ORANGE	1
	353R091USE 353R403 HURST HOSE 16 GREEN	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V37779

In Date: 01/12/2011
Close Date: 07/28/2011

Meter Reading: 18,926.40

Problem?

Intake relief valve will not reseal. Leaking. Temporarily shut with a 2.5" cap from brush 43. E43

Task performed:

REFER TO WO 38993 AND 38632 AK

Parts

Quantity

NO PARTS USED

Workorder: V39163

In Date: 03/14/2011
Close Date: 08/05/2011

Meter Reading: 20,546.80

Problem?

Low oil...none at station

Task performed:

work completed

Parts

Quantity

NO PARTS USED

Workorder: V41891

In Date: 07/08/2011
Close Date: 08/08/2011

Meter Reading: 23,382.00

Problem?

foam started flowing after 10 minutes of engagement.

Task performed:

tested system and tested ok

Parts

Quantity

NO PARTS USED

Workorder: V42217

In Date: 07/21/2011
Close Date: 08/25/2011

Meter Reading: 24,033.00

Problem?

fyi: added two quarts of motor oil to engine 43 this morning. Sta 43.

Task performed:

Dropped off oil. j

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V42702

In Date: 08/10/2011 **Meter Reading:** 24,359.00
Close Date: 09/12/2011

Problem?

Inside door handle on drivers door, connected in 3 places, 1 section has separated, stripped around bolt holding it in E 43

Task performed:

replaced door handle and tested

Parts	Quantity
6807200575HANDLE DOOR	1

repaired rear air pack that was falling out

Workorder: V43022

In Date: 08/24/2011 **Meter Reading:** 24,869.00
Close Date: 09/19/2011

Problem?

Fuel Gauge oos. Registering Empty although tank is Full. Sta 43.

Task performed:

checked gauges and tested ok

Parts	Quantity
NO PARTS USED	

Workorder: V43072

In Date: 08/26/2011 **Meter Reading:** 24,899.00
Close Date: 09/19/2011

Problem?

fyi: added two quarts of motor oil to engine 43 this morning. Sta 43.

Task performed:

2 quarts of oil added by crew.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V43474

In Date: 09/06/2011

Meter Reading: 25,264.00

Close Date: 09/27/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED E 43

Task performed:

1. C insp.
2. repalce 3 a/c dash vents on dash board
3. driver stated engine uses oil, check for leak none found the hole time vehicle was in the shop.
4. replace rear cab a/c filter
5. L-3 compt.door hold open broken r&r strut
6. replace ground ladder heat sensors
7. L/S upeer and lower red LED lites 1/2 out, replace both lites
8. R/S upper and lower red LED lites 1/2 out, replace both lites
9. middle tail board marker lite inop, repair ground wire
10. L/S lower red LED lite inop, replace lite
11. R-1 compt. door hold open broken, r&r strut
12. r/side and l/s pump panel lites 1/2 out, replace both pump panel lites
13. RPM counter on pump panel inop, found cable broken replace cable and ends
14. no power to foam fill pump trace wiring found wire connected to node pos. in pump panel and fuse blown, run wire to solenoid for quatrz lite, then found pump frozen replace foam fill pump.
15. found FRC throttle excel on pump panel LED's 1/2 out, replace throttle excel
16. failed vacumn test, adjust all discharge valve stops, recheck and passed test
17. service air drier
18. service trans.
19. battery tray hard to open, clean tracks and lube
20. r/rear service brake chamber hose had hole in it and leaking, replace hoses on both sides.
21. found tail pipe separated from exhaust pipe, replace clamp and tighten bracket that hold tail pipe in place
22. l/side intake drain leaking, remove and replace O rings.
23. fill water tank and road test

Parts

Quantity

01-06635060-C90PSC0CDCR STRIP LIGHT STEADY WHITE	2
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	25
29526898 29548988 TRANS FILTER ALLISON	1
391898HOSE & FITTING ASSY	1
4300-505PUMP FLOJET 12V	1
50R03ZCRLIGHT LED RED TIR 6	1
60R00FRR600 SERIES RED LED W/O FLANGE	4
6808300074VENT A/C LH	3
78R536078R5360M 2PK FILTER AIR COND	3
800405PURGE VALVE KIT	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	2
ELA101-ATHROTTLE EXCEL CUMMINS IS SERIES	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
MSA150-A20MANSAYER COVER	2
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	19



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44073

In Date: 10/01/2011 Meter Reading: 3,808.00

Close Date: 10/07/2011

Problem?

Hydraulic arm broken inside medical compartment door E43

Task performed:

Parts

Quantity

replaced arm on med compartment

NO PARTS USED

water leak repaired flange on deck gun

Workorder: V44181

In Date: 10/05/2011 Meter Reading: 3,808.00

Close Date: 10/21/2011

Problem?

Air leak. low air alarm every time the truck is started. No audible leak detected. E43

Task performed:

Parts

Quantity

checked for air leaks found none at this time

NO PARTS USED

Workorder: V44245

In Date: 10/09/2011 Meter Reading: 25,542.00

Close Date: 10/21/2011

Problem?

The engine throttles up and down on it's own when it is in pump gear and flowing foam. E 43

Task performed:

Parts

Quantity

ran pump and found no poble with pump

NO PARTS USED

repaired rear slide out tray

Workorder: V41173

In Date: 06/07/2011 Meter Reading: 22,841.00

Close Date: 11/02/2011

Problem?

Outside repair at Cummins, ECM bent.

Task performed:

Parts

Quantity

Repair Cummins j(11/2/11)

NO PARTS USED

Vendor?: CUMMINS



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V44401

In Date: 10/14/2011 Meter Reading:
Close Date: 11/07/2011

Problem?

TIC does not charge in holder and I would like the TIC and one box light switched (location) R 2

Task performed:	<u>Parts</u>	<u>Quantity</u>
REPAIRED TIC CHARGER AND TESTED	NO PARTS USED	

Workorder: V44464

In Date: 10/18/2011 Meter Reading:
Close Date: 11/07/2011

Problem?

"ok to pump" light bulb is out. Sta 43.

Task performed:	<u>Parts</u>	<u>Quantity</u>
REPAIRED PUMP SWITCH AND TESTED	NO PARTS USED	

Workorder: V44818

In Date: 10/31/2011 Meter Reading:
Close Date: 11/14/2011

Problem?

The K12 stalls when in idle. Sta 43.

Task performed:	<u>Parts</u>	<u>Quantity</u>
1. Clnl carb & tested.		
2. Rep power 110 cord for charger. j	3578105C2FRONT SHOCKS	2

Workorder: V44902

In Date: 11/02/2011 Meter Reading:
Close Date: 11/21/2011

Problem?

front flasher emergency light officer's side is out, sta 43.

Task performed:	<u>Parts</u>	<u>Quantity</u>
installed new light and tested	NO PARTS USED	
repaired ram fan and tested		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45362

In Date: 11/22/2011
Close Date: 11/29/2011

Meter Reading:

Problem?

Replace front tires.

Task performed:

Replace front tires.bp

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V44982

In Date: 11/04/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

Bleeder valves in discharges 1, 3, 4 leaking while under pressure. Tried multiple attempts to lubricate/stop leak, still leaks E43

Task performed:

cleaned sand out of valves

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

NO PARTS USED

Workorder: V45096

In Date: 11/11/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

Tension Rods in the medical and extrication compartment doors are broken, doors swing freely open E43

Task performed:

replaced piston on door

replaced spot light bulbs

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

EAA-8350-30UGSS1783UQ STRUT-LIFT 4

LB-D30BULB QUARTZ HAL. 12V 150W 2

Workorder: V45361

In Date: 11/22/2011
Close Date: 12/12/2011

Meter Reading:

Problem?

Discharges #1,2,3, & 4 bleeder valves are all leaking. Sta 43

Task performed:

repaired all valves that were leaking water

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

040114003SEAL SVS DRAIN VALVE 10



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45511

In Date: 11/30/2011
Close Date: 12/12/2011

Meter Reading:

Problem?

for your information: added one quart of engine oil to engine 43 this morning. jrm. Check for oil leak. Sta 43

Task performed:

checked for oil leak

Parts

Quantity

NO PARTS USED

Workorder: V45612

In Date: 12/04/2011
Close Date: 12/12/2011

Meter Reading:

Problem?

pressure relief valve stuck, not resetting. tried multiple times with no success E 43

Task performed:

hooked up to hydrant and cleaned out valve all tested ok

Parts

Quantity

NO PARTS USED

Workorder: V45354

In Date: 11/22/2011
Close Date: 12/16/2011

Meter Reading:

Problem?

driver side front tire tread is down to wear bars, measures at a 4 on gauge. All other tires appear to have good tread left. Sta 43

Task performed:

CHECK TIRES WILL MONITOR

Parts

Quantity

NO PARTS USED

Workorder: V45796

In Date: 12/12/2011
Close Date: 01/03/2012

Meter Reading:

Problem?

Captain side light box not working, Sta 43

Task performed:

repaired light and tested

Parts

Quantity

NO PARTS USED

coolant leak, repaired leak and tested



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V45783

In Date: 12/11/2011 Meter Reading: 27,011.00
Close Date: 01/13/2012

Problem?

1 circle D light bulb is out and new one is needed, also two door brackets are broken allowing compartment doors to swing out uncontrolled when opened E 43

Task performed:	Parts	Quantity
REPLACED DOOR PISTIONS.	EAA-8350-30UGSS1783UQ STRUT-LIFT	4

Workorder: V45838

In Date: 12/13/2011 Meter Reading: 27,011.00
Close Date: 01/13/2012

Problem?

alarm sensor in truck will not shut off while in drive.tried multiple times raising- lowering and checking wires/ground.still not working alarm will not shut off, Sta 43

Task performed:	Parts	Quantity
REPLACE MUD FLAP.	B2420LP-SMUD FLAP 24 X 24	1

Workorder: V46392

In Date: 01/07/2012 Meter Reading: 27,961.00
Close Date: 01/23/2012

Problem?

docking station for light boxes between the driver and captian are not holding a charge. E 43

Task performed:	Parts	Quantity
REPAIRED LIGHTS IN CAB THAT HAD BLOWN FUSE.	NO PARTS USED	

Workorder: V46608

In Date: 01/17/2012 Meter Reading: 28,240.00
Close Date: 01/27/2012

Problem?

3 box lights 10-7, Sta 43

Task performed:	Parts	Quantity
REPAIRED LIGHT BOX THAT HAD BAD CONNECTION	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V46609

In Date: 01/17/2012 Meter Reading: 28,240.00
Close Date: 01/27/2012

Problem?
system bleeds down 60psi in approx 20min not running. Sta 43

Task performed:	Parts	Quantity
TRACED OUT AIR LEAKS AND REPAIRED TWO FITTINGS IN REAR.	NO PARTS USED	

Workorder: V46801

In Date: 01/24/2012 Meter Reading: 28,389.00
Close Date: 02/03/2012

Problem?
need light bulb for portable light on engine E 43

Task performed:	Parts	Quantity
DROPPED OFF BULB.	NO PARTS USED	

Workorder: V46971

In Date: 01/30/2012 Meter Reading: 28,501.00
Close Date: 02/03/2012

Problem?
Need four replacement straps for flash lights and velcro straps for Irons with shoulder strap. Sta 43

Task performed:	Parts	Quantity
REPAIRED STRAPS AND DROPPED OFF VELCRO STRAPS.	NO PARTS USED	

Workorder: V47666

In Date: 03/01/2012 Meter Reading: 29,252.70
Close Date: 03/13/2012

Problem?
foam system shuts down while foam is running. E 43

Task performed:	Parts	Quantity
RAN PUMP AND CHECKED OPERATION OF PUMP, FOUND NO PROBLEM.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V47735

In Date: 03/04/2012 Meter Reading: 29,421.00
Close Date: 03/13/2012

Problem?
alot of fuel is dripping from the hurst power unit. E 43

Task performed:	Parts	Quantity
SWAPPED OUT UNIT AND SENT UNIT FOR REPAIR.	NO PARTS USED	

Workorder: V47725

In Date: 03/03/2012 Meter Reading: 29,421.00
Close Date: 03/16/2012

Problem?
E 43's yellow 1 3/4 hose line buckle of security netting broken E 43

Task performed:	Parts	Quantity
REPAIRED NETTING AND REMOUNTED NOZZLE HOLDER.	NO PARTS USED	

Workorder: V47862

In Date: 03/11/2012 Meter Reading: 29,672.00
Close Date: 03/16/2012

Problem?
watercooler on the engine is leaking. Sta 43

Task performed:	Parts	Quantity
REPAIRED WATER LEAK ON PUMP PANEL	NO PARTS USED	

Workorder: V48070

In Date: 03/20/2012 Meter Reading: 29,908.00
Close Date: 03/27/2012

Problem?
REPLACE REAR TIRES E43

Task performed:	Parts	Quantity
REPLACE REAR TIRES E43.	NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48029

In Date: 03/17/2012 Meter Reading: 29,845.00
Close Date: 04/02/2012

Problem?
Relief valve/drain discharge 1 leaking E43

Task performed:	Parts	Quantity
CHECKED FOR LEAKS RAN PUMP FOUND NO LEAKS.	NO PARTS USED	

Workorder: V48176

In Date: 03/26/2012 Meter Reading: 29,908.00
Close Date: 04/02/2012

Problem?
air leak/hard starting

Task performed:	Parts	Quantity
FOUND AIR LEAK AND REPAIRED REBUILT PUMP SHIFTER. HARD STARTING WAS DUE TO NOT PLUGGING IN TRUCK, RECHARGED BATTERIES AND LOAD TESTED.	NO PARTS USED	

Workorder: V48192

In Date: 03/26/2012 Meter Reading: 29,908.00
Close Date: 04/16/2012

Problem?
Discharge #1 pressuse relief will not seal properly. Discharge # OOS 10-7, Sta 43

Task performed:	Parts	Quantity
REBUILT ALL DRAIN VALVES AND TESTED.	NO PARTS USED	

Workorder: V48881

In Date: 04/25/2012 Meter Reading: 30,948.00
Close Date: 05/07/2012

Problem?
driver side head light is not working. (FYI-- there is a new headlight in there now and it is still now functioning)

Task performed:	Parts	Quantity
CHECKED FOUND BAD CONNECTION REPAIRED CHECKED OK.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48884

In Date: 04/25/2012 Meter Reading: 30,948.00
Close Date: 05/07/2012

Problem?
left headlight out on engine 43. the headlight had been replaced yesterday (04/24) per the offgoing shift, and the light still did not work. e43

Task performed:	Parts	Quantity
WORK DONE ON 48881.	H6054USE CV TYPE SEALED BEAM	3

Workorder: V48945

In Date: 04/27/2012 Meter Reading: 31,007.00
Close Date: 05/07/2012

Problem?
driver side spot light out B43

Task performed:	Parts	Quantity
OPERATED LIGHT FOUND BAD CONNECTION AT SWITCH REPAIRED CHECKED OK.	NO PARTS USED	

Workorder: V48919

In Date: 04/26/2012 Meter Reading: 31,007.00
Close Date: 05/08/2012

Problem?
shelve in extracation department missing hardware to hold shelve in place. Shelve has dropped on right side. Needs the bolt and small back plate replaced.E43

Task performed:	Parts	Quantity
REMOVED EQUIPMENT FROM SHELF STRAIGHTENED AND INSTALLED NEW HARDWARE.	NO PARTS USED	

Workorder: V48975

In Date: 04/30/2012 Meter Reading: 31,074.00
Close Date: 05/08/2012

Problem?
install velcro straps e 43

Task performed:	Parts	Quantity
CHECKED OK.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48584

In Date: 04/11/2012 Meter Reading: 30,590.00
 Close Date: 05/11/2012

Problem?
 PRESSURE RELIEF VALVE DOES NOT WORK PROPERLY LONG DELAY TO COME ON AND WON'T HOLD PRESSURE STEADY ALSO HAS STEADY LEAK. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
FLUSHED OUT VALVE AND RETESTED.	NO PARTS USED	

Workorder: V48585

In Date: 04/11/2012 Meter Reading: 30,590.00
 Close Date: 05/11/2012

Problem?
 DISCHARGES 1 AND 4 DRAINS WILL NOT SEAL ALSO DISCHARGE 2 INTERMITTENTLY FAILS ALSO. PUMP WILL NOT HO A VACUUM UNABLE TO PASS 1ST PART OF PUMP TEST. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
ALL DRAIN VALVE ARE REPAIRED.	NO PARTS USED	

Workorder: V48587

In Date: 04/11/2012 Meter Reading: 30,590.00
 Close Date: 05/11/2012

Problem?
 FOAM SYSTEM OVER RIDES PUMP THOTTLE CONTROL AND SHUTS PUMP ON AND OFF REPEATEDLY REDERING IT INOPERABLE. E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
RAN PUMP AND FOAM SYSTEM, COULD NOT GET SYSTEM TO FAIL.	NO PARTS USED	

Workorder: V48588

In Date: 04/11/2012 Meter Reading: 30,590.00
 Close Date: 05/11/2012

Problem?
 SAFETY NET ON PASSENGER SIDE CROSS LAY NEEDS TO BE REPLACED E43

Task performed:	<u>Parts</u>	<u>Quantity</u>
REPLACED NET ON RIGHT SIDE	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V48589

In Date: 04/11/2012
Close Date: 05/11/2012

Meter Reading: 30,590.00

Problem?

HOSE BED COVER NEEDS TO BE REPLACED WORN AND TORN E43

Task performed:

WILL HAVE MADE UP AT B

Parts

Quantity

NO PARTS USED

Workorder: V48190

In Date: 03/26/2012
Close Date: 05/14/2012

Meter Reading: 29,908.00

Problem?

net covering preconnect on passenger side needs placement. need two spark plugs nkg BM6A, Two Circle D replacement light bulbs, wood blades and metal cutting blades for sawsall, T handle for chain saw with flat head.Sta 43

Task performed:

1. DROPPED OFF ALL SUPPLIES TO STATION.
2. INSTALLED NEW PRECONNECT NETS.

Parts

Quantity

NO PARTS USED

Workorder: V48387

In Date: 04/02/2012
Close Date: 05/14/2012

Meter Reading: 30,343.00

Problem?

Annual Vacuum test failed. Discharges 1 & 3 leak at bleeder valve with caps on. Discharge 4 leak indicated by guage. Vacuum tes had 15 inches of drop in 45 seconds. Test discontinued until repairs are made. e43

Task performed:

REPAIRED ALL BLEEDER VALVES AND REPAIRED VACUUM LEAKS.

Parts

Quantity

NO PARTS USED

Workorder: V49151

In Date: 05/07/2012
Close Date: 05/18/2012

Meter Reading: 31,197.40

Problem?

quartz warning light and buzzer coming on. e 43

Task performed:

READJUSTED POLE LIGHT SWITCH.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49096

In Date: 05/04/2012 Meter Reading: 31,197.40
 Close Date: 05/30/2012

Problem?
 the left rear top red warning light is not working.

Task performed:	Parts	Quantity
1. REPAIRED GROUND WIRE ON REAR LIGHT.	NO PARTS USED	
2. REAR A/C INOP - REPAIRED REAR A/C RELAY.		

Workorder: V49429

In Date: 05/17/2012 Meter Reading: 31,520.10
 Close Date: 05/30/2012

Problem?
 primer pump does not even turn on - tried multiple times shutting the truck on/off. Does not even turn over.

Task performed:	Parts	Quantity
1. REPAIRED BAD CONNECTION ON PRIMER MOTOR.	NO PARTS USED	
2. REAR SPOTLIGHT OUT REPAIRED BAD GROUND ON LIGHT.		

Workorder: V49691

In Date: 05/29/2012 Meter Reading: 31,744.00
 Close Date: 06/08/2012

Problem?
 Replaced the right head light this morning and the rear upper left strobe is out.

Task performed:	Parts	Quantity
DROPPED OFF SPARE LIGHT.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49733

In Date: 05/30/2012
Close Date: 06/18/2012

Meter Reading: 31,744.00

Problem?

While truck in pump the transmission sometime wont engage even after take pump out and repeating steps. truck is come up for PM 43

Task performed:

1. OPERATE PUMP COMPLAIN OF NOT ENGAUGE FAULT - PUMP ENGAUGE WITH NO FAULT OR UESITATION NOTICABLE. PUMP OPERATING NORMAL AT THIS TIME.
2. DIAGNOSE PUMP CONTROLE VALVE FAULT PUMP DERATED UNDER INSTALL POWER. REMOVE AND REBUILD TYUM CONTROLE VALVE, REMOVE AND REBUILD SV SENDING VALVE.
3. FOAM DISCHARGE EXCESIVE - FOAM DISCHARGE DISPLAY MAX FLOW A 5% REMOVE FOAM PUMP ASSEMBLEY FOAM DISTRIBUTION BOX WIRES EXPOSE - REMOVE BOX AND INSTALL NEW DISTRUBITION BOX RECALIBRATE WATER FLOW AND FOAM FLOT TO MANUFACTORY SPEC. FILL FOAM TANK. OPERATE UNIT. REPAD APART REPLACE LED SENSOR.
4. CALIBRATE WATER FLOW SENSOR FOR FOAM SYSTEM.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V49710

In Date: 05/29/2012

Meter Reading: 31,744.00

Close Date: 06/21/2012

Problem?

B INSPECTION E 43

Task performed:

1. B-Inspection; windshield wiper blade and fluid; rear a/c filter; right front turn signal and macke lense; replace blown tray bulb.
2. Remove hose bed cover and l/rear seat for repair. Install new hose bed cover and reupholstered seat.
3. Battery and trash line tray slider and lock seized up - clean latching mechanism and sliders, lubricate and operate.
4. Rear indicator light inop - remove blown bulb install new bulb - system still inop - trace wire harness to chassie support strap found power cable short to ground - repair fault.
5. Cab door seals torn remove seals and install new door seals.
6. Window moldings damage or broken - remove moldings and install new moldings.
7. Diagnosing L/rear light bar failure - found led assembly bad - replace LED, found micro ballast one side malfunction. no parts - parts on order - reassemble.
8. Power steering service.
9. Engine and a/c belt service, replace tensioner and idler tensioner pully bearing.
10. Hologen light l/side inop - found bulbs in good condition, no power to assembly - found pinched line. correct fault. Repair pinched line.
11. L-1 comp tool holders loose - remove retap hold down holes and reinstall tool holders.
12. Rear a/c cool - diagnose fault - found unit low on freon - vacuum system check for leak none found - charge system operate unit cooling to 35 degree.
13. Hose bed cover hold down snaps broken - remove old damage snap and install new snaps.
14. Cab dimond plate cover loose - screws holes worn - retap several holes and secure plate to cab.
15. Air leak - replace leaking fittings and secure loose air lines.
16. Q.A.

Parts	Quantity
01-0269606-D0LIGHT BALLEST MINI BAR	1
038-0191-00CONTROL VALVE	1
097-0220-00WASHER DIAPRAGM SUPPORT (PMD VALVE)	1
097-0990-00WASHER	1
2002501500DISTRIBUTION BOX	1
203FFBEARING PULLEY	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
538-1410-00VALVE SENSING SV HALE	1
546-2210-02-0LIGHT KIT HALE	1
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
9150391503 LENS AMBER	1
91513AMBER LENS	1
9440BELT	1
9480BELT	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
AMH-1AMH-1 VALVE EXTENSION	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
K080716BELT	1
R90PFILTER FUEL 33231	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50389

In Date: 06/26/2012 Meter Reading: 32,064.90
Close Date: 07/09/2012

Problem?

Transmission retarder leaks air when brake is applied lightly and stops when applied fully. E43

Task performed:

TRAVEL TO STATION REMOVE AIR CONTROL VALVE
ON TRANSMISSION INSTALL NEW VALVE.

Parts	Quantity
2952271729552377 VALVE ASSY.ACCUM	1

Workorder: V50597

In Date: 07/04/2012 Meter Reading: 23,246.00
Close Date: 07/10/2012

Problem?

air pressure will not build up

Task performed:

AIR PRESSURE COONT BUILD UP/TRANS RETARDER
VALVE SOLENOID LEAKING AT EXHAUST/REPLACED
VALVE.

Parts	Quantity
2952271729552377 VALVE ASSY.ACCUM	1
800405PURGE VALVE KIT	1

Workorder: V50664

In Date: 07/07/2012 Meter Reading: 32,419.30
Close Date: 07/13/2012

Problem?

T.I.C. Charger does not charge T.I.C. only charges the spare and needs to be moved to top of center compartment. E43

Task performed:

REPAIRED TIC CHARGER.

Parts	Quantity
NO PARTS USED	

Workorder: V50665

In Date: 07/07/2012 Meter Reading: 32,419.30
Close Date: 07/13/2012

Problem?

E43 needs PVC styrofoam cup holder

Task performed:

- AIR LEAK, REPAIRED LEAK AT DRIVER'S SEAT.
- STATION WILL MAKE CUP HOLDER.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50668

In Date: 07/07/2012 Meter Reading: 32,419.30
Close Date: 07/13/2012

Problem?
E43 missing Dynablade for K12

Task performed:	Parts	Quantity
DC WILL ORDER BLADE.	NO PARTS USED	

Workorder: V50695

In Date: 07/09/2012 Meter Reading: 32,419.30
Close Date: 07/25/2012

Problem?
K12 will start. Will not stay running. Does not accelerate to high RPM. e 43

Task performed:	Parts	Quantity
CLEANED CARB AND RAN UNIT.	NO PARTS USED	

Workorder: V50736

In Date: 07/10/2012 Meter Reading: 32,419.30
Close Date: 07/25/2012

Problem?
need case of oil

Task performed:	Parts	Quantity
DROPPED OFF OIL AT STATION.	NO PARTS USED	

Workorder: V51367

In Date: 08/05/2012 Meter Reading:
Close Date: 09/13/2012

Problem?
QUARTZ ALARM IN CAB HAS ASHORT IN IT COMES ON AND GOES OFF WITH THE LIGHTS DOWN. E43

Task performed:	Parts	Quantity
1. RGT SIDE QUARTZ LIGHT OUT REPAIRED LIGHT.	NO PARTS USED	
2. QUARTZ LIGHT ALARM GOING OFF READING SWITCH.		
3. DROPPED OFF OIL AT STATION.		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51741

In Date: 08/20/2012 Meter Reading:
Close Date: 09/13/2012

Problem?
the air horn blast when I hit a small bump in the road. E43

Task performed:	Parts	Quantity
1. REPLACED AIR HORN BOTTON THAT WAS LOADED W/ WATER AND TESTED.	7605-666764-0023 SWITCH FOOT SIREN	1
2. REPAIRED 110 CORD THAT WAS SHORTOUT.		

Workorder: V51390

In Date: 08/06/2012 Meter Reading:
Close Date: 09/14/2012

Problem?
tower light on passenger side light bulb burned out

Task performed:	Parts	Quantity
QUARTZ LIGHT BULB OUT REPLACED BULB AND TESTED. QUARTZ LIGHT ALARM GOING OFF ADJUSTED SWITCH.	LB-D30BULB QUARTZ HAL. 12V 150W	2

Workorder: V51569

In Date: 08/13/2012 Meter Reading:
Close Date: 09/17/2012

Problem?
PUMP THROTTLE FINIKY. WOULD NOT THROTTLE UP AT A CALL. SHUT DOWN, PULLED ENGINE FORWARD 6' AND RETRIED. THROTTLE WORKED. REALLY????? E43

Task performed:	Parts	Quantity
1. RAN PUMP CHKD ALL CONNECTIONS ALL TESTED OK.	NO PARTS USED	

Workorder: V51662

In Date: 08/17/2012 Meter Reading:
Close Date: 09/17/2012

Problem?
SIDE WATER LIGHT GADGES ARE NOT WORKER ON EITHER SIDE. PASSWAY LEVEL GADGE IS WORKING

Task performed:	Parts	Quantity
1. RECHARGED WATER LEVEL LIGHTS AND TESTEL	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V51673

In Date: 08/17/2012
Close Date: 09/17/2012

Meter Reading: 33,458.40

Problem?
primer pump sticking

Task performed:

FINE ON PRIME PUMP REPAIR WIRES AND
REPLACE WIRES REPLACE PRIME PUMP AND
SOLID PRIME VALVE SWITCH.

Parts	Quantity
200-2450-00NC SWITCH OK TO PUMP	1
501-3090-00PRIMER PUMP MOTOR	1

Workorder: V52577

In Date: 09/23/2012
Close Date: 10/01/2012

Meter Reading:

Problem?
We need some 2 cycle oil for equipment. Sta43

Task performed:

DROPPED OFF OIL AT STATION.

Parts	Quantity
NO PARTS USED	

Workorder: V52753

In Date: 10/01/2012
Close Date: 10/16/2012

Meter Reading:

Problem?
E 43 left rear emergency light bracket broken off. Mechanic already by station. E43

Task performed:

REINSTALLED NEW BRACKET AND REWIRED.

Parts	Quantity
NO PARTS USED	

Workorder: V52777

In Date: 10/02/2012
Close Date: 10/16/2012

Meter Reading: 34,557.40

Problem?
repair rear light e 43

Task performed:

REPAIRED SHORTED WIRES IN REAR LIGHT.

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V52902

In Date: 10/07/2012 Meter Reading:
Close Date: 11/09/2012

Problem?
Bi-lat (Right) side of each telelight bulb is burned out. E 43

Task performed:	Parts	Quantity
REPLACED LIGHT.	NO PARTS USED	

Workorder: V53264

In Date: 10/23/2012 Meter Reading:
Close Date: 11/09/2012

Problem?
box light charger left rear passenger seat broken and needs to be replaced. We also need a case of motor oil for E43 and B43

Task performed:	Parts	Quantity
INSTALLED NEW CHARGED FOR HANDLIGHTS AND NEW FUSE HOLDER. AIR LEAK-REPAIRED AIR LEAKS.	15W40BSYN OIL BULK QTS	12

Workorder: V49057

In Date: 05/02/2012 Meter Reading: 31,129.00
Close Date: 11/20/2012

Problem?
while drafting, the master pressure relief drain had to be capped, as it was sucking in a large amount of air, preventing a vacuum. E43

Task performed:	Parts	Quantity
CORRECTED RELIEF VALVE.	546126000TPM/QG HALE REPAIR KIT	1

Workorder: V53362

In Date: 10/29/2012 Meter Reading:
Close Date: 11/28/2012

Problem?
E 43 losing air pressure. Mechanic contacted

Task performed:	Parts	Quantity
AIR LEAK, REPLACED PARKING BRAKE VALVE.	800034VALVE PARKING BRK.	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53566

In Date: 11/06/2012 Meter Reading:

Close Date: 11/28/2012

Problem?

for your information: two quarts of motor oil was added to engine 43 this morning. jrm/9573.

Task performed:

REPAIRED OIL LEAK AT DRAIN PLUG.

Parts

NO PARTS USED

Quantity

Workorder: V53559

In Date: 11/06/2012 Meter Reading:

Close Date: 11/30/2012

Problem?

Air leak. goes down to 50 psi. after about 1-2hours. E43

Task performed:

CHECKED FOR AIR LEAKS AND REPAIRED.

Parts

NO PARTS USED

Quantity

Workorder: V53597

In Date: 11/07/2012 Meter Reading:

Close Date: 11/30/2012

Problem?

both tower lights need bulbs replaced E43

Task performed:

REPLACED BULBS.

Parts

NO PARTS USED

Quantity

Workorder: V53633

In Date: 11/08/2012 Meter Reading:

Close Date: 11/30/2012

Problem?

LEFT TELE LIGHT(1) OF THE (2) BULBS IN THE HOUSING IS BLOWN E43

Task performed:

REPAIRED ALL SPOT LIGHTS THAT WERE OUT.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53595

In Date: 11/07/2012
Close Date: 12/07/2012

Meter Reading:

Problem?

Need 2 cycle oil e43

Task performed:

DROPPED OFF OIL.

Parts

Quantity

NO PARTS USED

Workorder: V53646

In Date: 11/09/2012
Close Date: 12/07/2012

Meter Reading:

Problem?

The remote controlled top mounted spotlight does not light up.

Task performed:

REPAIRED SPOT LIGHT GROUND THAT WAS OUT.

Parts

Quantity

NO PARTS USED

Workorder: V53726

In Date: 11/13/2012
Close Date: 12/07/2012

Meter Reading:

Problem?

tower lights not working properly one bulb one each work intermittently

Task performed:

REPAIRED SHORTED WIRE IN POLE.

Parts

Quantity

NO PARTS USED

Workorder: V53727

In Date: 11/13/2012
Close Date: 12/07/2012

Meter Reading:

Problem?

top mounted spot light is out E43

Task performed:

REPAIRED SPOTLIGHT.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V53728

In Date: 11/13/2012 Meter Reading:
Close Date: 12/07/2012

Problem?
all step work lights are out E43

Task performed:	Parts	Quantity
REPAIRED STEP LIGHTS FOR REAR AND SIDE OF TRUCK.	NO PARTS USED	

Workorder: V53981

In Date: 11/26/2012 Meter Reading: 35,800.10
Close Date: 12/26/2012

Problem?
S.C.B.A. Bracket right rear is missing mounting bolt and has come lose E43

Task performed:	Parts	Quantity
1. AIR LEAK - REPAIRED AIR LEAK. 2. REPAIRED BRACKET IN REAR OF SEAT.	NO PARTS USED	

Workorder: V54435

In Date: 12/14/2012 Meter Reading:
Close Date: 01/14/2013

Problem?
air bags under passenger cab not working cab bottoms out while driving

Task performed:	Parts	Quantity
CHECKED FOR LEAKS FOUND NO LEAKS ROAD TESTED.	02036317300STROBE LINEAR REFLECTOR 6ELTUBE	1

Workorder: V54480

In Date: 12/18/2012 Meter Reading:
Close Date: 01/14/2013

Problem?
The left front turn signal, and the top mounted remote controlled spotlight are both not working.

Task performed:	Parts	Quantity
REPAIRED SPOT LIGHT AND TURN LIGHT.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V54550

In Date: 12/21/2012 Meter Reading:
Close Date: 01/14/2013

Problem?

both the left front turn signal and the top mounted remote controlled spotlight are not working.

Task performed:

INSTALLED NEW HEADLIGHT AND WIRED. AIR LEAKS CHECKED FOR AIR LEAKS FOUND NONE AT THIS TIME.

Parts	Quantity
NO PARTS USED	

Workorder: V54779

In Date: 01/03/2013 Meter Reading:
Close Date: 01/14/2013

Problem?

Strobe light out on rear driver side light by hose bed r43

Task performed:

REPAIRED LIGHT AND REPAIRED STROBE IN BACK.

Parts	Quantity
NO PARTS USED	

Workorder: V54872

In Date: 01/06/2013 Meter Reading:
Close Date: 01/14/2013

Problem?

primer (switch) sticks in the on position from the pump panel. primer on the officer side next to steamer valve functions properly. Problem is evidently with teh panel switch. E43

Task performed:

TESTED PRIMER VALVE AND TESTED OK. CHECKED FOR AIR LEAKS FOUND NONE AT THIS TIME.

Parts	Quantity
NO PARTS USED	

Workorder: V54913

In Date: 01/07/2013 Meter Reading: 36,888.80
Close Date: 01/25/2013

Problem?

Pressure gauge for preconnect # 2 non- operational. E43

Task performed:

1. REMOVED AND REPLACED PRESSURE GAUGE.
2. AIR LEAK - TRACED OUT AIR LEAKS.

Parts	Quantity
91553943GUAGE	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V54996

In Date: 01/11/2013 Meter Reading: 36,888.80
 Close Date: 01/25/2013

Problem?

#2 preconnect pressure gauge not working.

Task performed:

1. REMOVED AND REPLACED NO #2 GAUGE.
2. AIR LEAK, CHECKED FOR AIR LEAKS.

	Parts	Quantity
	NO PARTS USED	

Workorder: V55688

In Date: 02/11/2013 Meter Reading: 38,963.00
 Close Date: 02/12/2013

Problem?

no power, running rough

Task performed:

ENGINE LOW ON POWER - FOUND BLACK FUEL - CONTAMINATED WITH OIL. SWAPPED INTO BATTALION 3 SPARE.

	Parts	Quantity
	NO PARTS USED	

Workorder: V55351

In Date: 01/28/2013 Meter Reading: 37,405.00
 Close Date: 02/22/2013

Problem?

air pressure low when starting the engine. air leak..

Task performed:

TRACED OUT AIR LEAKS AND REPAIRED.

	Parts	Quantity
	NO PARTS USED	

Workorder: V55466

In Date: 02/01/2013 Meter Reading: 37,501.00
 Close Date: 02/22/2013

Problem?

leak in the air system of the engine delaying response. E-43

Task performed:

TRACED OUT AIR LEAKS AND REPAIRED.

	Parts	Quantity
	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55508

In Date: 02/04/2013 Meter Reading: 37,688.00
Close Date: 02/22/2013

Problem?
air leak causing delay in response.

Task performed:	Parts	Quantity
1. CAB AIR BAGS, CHECKED NO LEAKS.	FZ-K190-1MOTOR MOUNT RAM FAN GF165	4
2. REPAIRED RAM FAN, INSTALLED RUBBER FEET.	LML-1102-0023CAB AIR BAG IS4007	4

Workorder: V55594

In Date: 02/07/2013 Meter Reading: 38,963.00
Close Date: 02/22/2013

Problem?
drivers side headlight not working. e43

Task performed:	Parts	Quantity
REPLACED HEADLIGHTS.	H6054USE CV TYPE SEALED BEAM	4

Workorder: V56255

In Date: 03/08/2013 Meter Reading: 38,148.00
Close Date: 03/11/2013

Problem?
constantly has a vibration/shutter while driving

Task performed:	Parts	Quantity
WENT TO 43 CHECK ORIVELINE - CHECK OK - STARTED AND RAN ENGINE - CHECK FOR CODES - NO CODES - RAN CYLINDER - CUT - OUT TEST - CHECK OK - RAN CONTROL VALVE TEST - CHECK OK - TEST DROVE WITH DRIVER FOUND SMALL ENG MISS FROM 1200 - 1600 RPM UNDER LOAD.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V55716

In Date: 02/11/2013

Meter Reading: 38,963.00

Close Date: 03/18/2013

Problem?

C inspection - injectors and tubes need to be replaced, oil in fuel. Fuel tank needs to be drained and refilled with fresh fuel.

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

1. C-INSPECTION.	029-0511-00-0ANODE ONLY	2
2. C-INSPECTION CONTINUE.	038-1550-00VALVE CHECK HALE 1/4"	1
3. SERVICE PUMP TRANSMISSION.	048009000SPEEDCOUNTER PUMP PANEL	1
4. SERVICE REAR AXLE.	3899283MOUNTING ORING	2
5. R&R WIPER BLADES.	3936953INJ TUBE	6
6. INFLATE FRONT RIRES TO 105 INFLATE REAR TIRES TO 115.	3939284VALVE GASKET COVER	1
7. R&R CAB AUX A/C FILTER.	3948529RXINJECTOR	6
8. R&R 2 FRONT HUB OIL FIL CAPS.	3963988WASHER SEAL	8
9. R&R RAD CAP AND TOP OFF COOLANT.	3992090RACK GASKET	1
10. MAKE AND INSTALL ASSETT STICKER FOR WINDSHIELD.	4025130FUEL PRESS SENSOR	1
11. TIGHTEN ALL HOLD OPEN HARDWARE ON BOTH COMPT L-3 DOORS.	440-5 VALVE EXT.	2
12. R&R LOWER PIVOT BOLT ON CAB A/C COMPRESOR AND ADJ FANBELT. ALSO ADJ FANBELT ON CAB AUX A/C COMPRESSOR.	52-24WIPER BLADES ANCO 24	2
13. ROMOVE OLD PAINT. CLEAN AND PRIME CAP. LET DRY PAINT FUEL CAP YELLOW.	5462270020VALVE KIT SS 546-2270-02-0	1
14. R&R AIR FILTER.	5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0	3
15. FORCE OPEN BATTERY TRAY DRAWER. CLEAN AND LUBE SLIDES AND LATCHES AND LATCH HANDLE ASSY.	6808310398SEAL AIR DUCT	1
16. R&R TAIL PIPE SUPPORT BRACKET. INSTALL NEW HARDWARE AND TIGHTEN.	6808330631CABLE ASSY HEATER	1
17. R&R DRYER FROM VEHICLE (AD-9) OVERHAUL DRYER AND R&R CHECK VALVE ASSY.	72R311018-2640 VENT A/C NEW # 1719	1
18. R&R 4 BATTERIES. ALSO REPLACED POSITIVE MULTI. CABLE ASSY AND REPAIRED 3 POS, WIRES THAT TERMINALS TORE OFF WHEN REMOVING ATTACHMENT NUT.	78308930 AKRON 3 IN VALVE	1
19. R&R TOP HALF OF CAB AUX A/C UNIT IN ORDER TO R&R AIR DIFFUSER.	78R539018-2699 A/C FILTER	1
20. DIAGNOSE WHY RPM COUNTER ON PUM PANEL DOESN'T WORK. PUMP PANEL COUNTER ON PUMP PANEL BAD INNER AND OUTER CABLE BAD. FABRICATE NEW INNER OUTER CABLE ASSY AND REPLACE PANEL COUNTER ASSY.	91398907 VALVE KIT 3 IN AKRON	1
21. R&R AND REBUILD PRIMER VALVE.	A0631087000CABLE BATT. POS.	1
22. START VEHICLE WON'T PASS DRY VAC TEST DIAGNOSIS.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
23. DRY VACUUM TEST DIAGNOSIS AND REPAIRS.	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
24. DRY VACUUM TEST DIAGNOSIS AND REPAIRS CONTINUED.	HP-31DBATTERY 950CCA HP-31D	4
25. REMOVE BUCKLE AND STRAP FOR REAR OF HOSE BED COVER TO USE FOR SAMPLE AT CENTRAL AUTO TRIM. THEN REINSTALL 2 BUCKLES ONTO REAR CROSSBAR.	HPH6349AOIL FILTER 51748	1
26. R&R 3 DASH PANELS IN ORDER TO DIAGNOSE AND REPAIR WHY DEFROSTER DUCTS HAVE TAPE ON THEM. R&R ONE CABLE. R&R ONE BULB ADJ ANOTHER CABLE UNTIL CORRECT. REMOVE DUCT TAPE FROM TOP OF DASH.	PR338324070 WIX FILTER WATER	1
27. START R&R INJECTORS AND TUBES.	PVG-KITORING KIT	1
	R90PFILTER FUEL 33231	1
	SPR-W58-1TEE PLASTIC	1



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

- 28. REMOVE LINES, TUBES, VALVE COVER. A/C LINES, AND INJECTORS.
- 29. CONTINUE TROUBLESHOOT, REPLACE FUEL PRESSURE SENSOR AND FUEL TEMP SENDER, TEST DRIVE, STILL SAME ?????
- 30. REPLACE BAJO SEALING WASHERS ON LIFT PUMP RE-TEST DRIVE-STILL SAME.
- 31. START REMOVE INJECTORS, CHECK WHERE TUBES MOUNTS, FOR POSSIBLE CRUSHING OR CRACKS.
- 32. REINSTALL INJECTORS OK. RETEST DRIVE STILL NOT RIGHT.
- 33. FINISH INSTALL TUBES AND INJECTORS.
- 34. TAKE TRUCK FOR LONG TEST DRIVE, RUNNING BATTER BUT STILL NOT RIGHT, ENGINE VIBRATION AND LONG CRANKS, START TROUBLESHOOT.
- 35. CONTINUE TROUBLESHOOT, RE-TORQUE ALL TUBES.
- 36. TRY TO BLEED FUEL SYSTEM, CHECK TUBES.
- 37. REMOVE INJECTOR PUMP FROM PART'S ENGINE.
- 38. REMOVE INJECTOR PUMP FROM E-43 TO SWAP PUMPS WITH PARTS ENGINE.
- 39. FINISH REMOVE PUMP FROM E-43, START TO INSTALL PUMP FRAME PARTS ENGINE IN 43.
- 40. FINISH PUMP INSTALL IN E-43 TAKE ON TEST DRIVE OK. LET SIT OVERNIGHT CHEC IN A.M.
- 41. TEST START UP AFTER SITTING OVER NIGHT TEST DRIVE.
- 42. START INSTALL INJECTOR PUMP OFF OF E-43 ON PARTS TRUCK..
- 43. FINISH INSTALL INJECTOR PUMP ON PART'S TRUCK.
- 44. BLEED FUEL SYSTEM, REPAIR LEAKING LINES ON PART'S TRUCK.

Workorder: V56497

In Date: 03/19/2013

Meter Reading: 38,285.00

Close Date: 03/19/2013

Problem?

Hurst unit wont start E-43

Task performed:

HURST PUMP INOP. SPARK PLUG BROKE/REPLACED SPARK PLUG AND EXTRACTED BROKEN TIP FROM PLUG WIRE CONNECTOR.

Parts

Quantity

FSC17491907NO SWITCH LOW AIR PRESSURE

1

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V56428

In Date: 03/15/2013 Meter Reading: 38,285.00
Close Date: 03/22/2013

Problem?
E 43 roof top spot light damaged and had to be removed. A bay door damaged the light

Task performed:	Parts	Quantity
1. CHECKED SPOT LIGHT NEEDS NEW ONE ORDERED.	620122SPOT LIGHT REMOTE	1
2. INSTALLED NEW SPOT LIGHT.	77102LIGHT	1

Workorder: V56408

In Date: 03/14/2013 Meter Reading: 38,216.00
Close Date: 04/05/2013

Problem?
engine slow to start.

Task performed:	Parts	Quantity
REPAIRED CONNECTION ON STARTER.	NO PARTS USED	

Workorder: V50138

In Date: 06/14/2012 Meter Reading:
Close Date: 04/08/2013

Problem?
Power pug broken and falling out and wont charge the Thermo Cam.

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V50371

In Date: 06/25/2012 Meter Reading: 32,064.90
Close Date: 04/22/2013

Problem?
air brakes leaking while applied

Task performed:	Parts	Quantity
	11830GDIAPHRAM BRAKE	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V50393

In Date: 06/26/2012
Close Date: 04/22/2013

Meter Reading: 32,064.90

Problem?
air leak

Task performed:	Parts	Quantity
	NO PARTS USED	

Workorder: V56870

In Date: 04/07/2013
Close Date: 04/26/2013

Meter Reading: 38,960.00

Problem?
Door sensors in D/O compartment not showing door closed, setting off alarms in cab.

Task performed:	Parts	Quantity
REPAIRED DOOR ALARM GOING OFF.	NO PARTS USED	

Workorder: V57363

In Date: 04/30/2013
Close Date: 05/01/2013

Meter Reading: 39,375.00

Problem?
HARD START COLD SIREN WORKS INTERMITTENT COMES ON BY ITSELF e 43

Task performed:	Parts	Quantity
REMOVE AND INSTALL NEW LIFT PUMP ON ENGINE FUEL SYSTEM.	39181923918192 WASHER SEAL	2
	3949085PUMP ISC FUEL TRANSFER NEW #4935005	1
	3963983WASHER SEAL ISB	2
	FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
	R90PFILTER FUEL 33231	1

Workorder: V57644

In Date: 05/10/2013
Close Date: 05/17/2013

Meter Reading:

Problem?
primer motor not working...

Task performed:	Parts	Quantity
REPALCED PRIMER MOTOR.	501-3090-00PRIMER PUMP MOTOR	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V57688

In Date: 05/13/2013 Meter Reading:
Close Date: 05/17/2013

Problem?
Prime motor not working. E43

Task performed:	Parts	Quantity
1. REPLACED PRIMER HANDLE THAT WAS HARD TO PULL.	NO PARTS USED	
2. SPOT LIGHT REPAIRED BAD CONNECTION.		

Workorder: V57690

In Date: 05/13/2013 Meter Reading:
Close Date: 05/17/2013

Problem?
Spot light on roof of the engine not working.E43

Task performed:	Parts	Quantity
1. REPAIRED BAD CONNECTION.	NO PARTS USED	
2. READJUSTED TANK TO PUMP VALVE LINKAGE.		

Workorder: V57691

In Date: 05/13/2013 Meter Reading:
Close Date: 05/17/2013

Problem?
Water level lights on side of the engine not working.E43

Task performed:	Parts	Quantity
1. REPAIRED BAD CONNECTION ON WATER LEVEL LIGHTS.	NO PARTS USED	
2. REPAIRED REAR GRAB RAIL FOR REAR OF TRUCK.		

Workorder: V57692

In Date: 05/13/2013 Meter Reading:
Close Date: 05/17/2013

Problem?
E43 is getting a bubbling rust line on the top of the engine.

Task performed:	Parts	Quantity
1. RESEALED TOP OF ROOF.	NO PARTS USED	
2. REPAIRED DECK GUN VALVE THAT WAS LEAKING.		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58512

In Date: 06/18/2013 Meter Reading: 40,652.00
Close Date: 06/24/2013

Problem?
extenda gun light on again, which hinders the ability to drive at night. E43

Task performed:	Parts	Quantity
CHECKED CONNECTION ON TRUCK FOR EXTENDA GUN LIGHT AND ALL CHECKED OK - ROAD TESTED AND LIGHT IS NOT ON AT THIS TIME.	NO PARTS USED	

Workorder: V58581

In Date: 06/20/2013 Meter Reading: 40,652.00
Close Date: 06/24/2013

Problem?
Roof rotating white spot light is not working. In addition, the rear driver side compartment rollout drawer appears to be difficult to roll back into the compartment.

Task performed:	Parts	Quantity
SPOT LIGHT IS NOT WORKING DUE TO NEED TO REPLACE CABLE, WILL DO AT LATER TIME.	NO PARTS USED	

Workorder: V57349

In Date: 04/29/2013 Meter Reading:
Close Date: 07/19/2013

Problem?
E 43 hesitates when starting. May be the starter. E43

Task performed:	Parts	Quantity
repaired on 57363	NO PARTS USED	

Workorder: V59352

In Date: 07/25/2013 Meter Reading: 41,552.40
Close Date: 07/29/2013

Problem?
FYI: Added two quarts of engine oil to Engine 43 this morning.

Task performed:	Parts	Quantity
NO ACTION AT THIS TIME.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58842

In Date: 07/03/2013 Meter Reading: 41,000.60
Close Date: 08/02/2013

Problem?
top emergency light bar above the cab driver side, One light not working. Pressure relief valve not working properly. door ajar audible sound is not working E43

Task performed:	Parts	Quantity
REMOVED AND REBUILT RELIEF VALVE.	042-0550-00SPRING-VALVE QG RELIEF VALVE	1
	546126000TPM/QG HALE REPAIR KIT	1

Workorder: V58880

In Date: 07/05/2013 Meter Reading: 41,060.00
Close Date: 08/02/2013

Problem?
Spot light is not working. In addition, red flashing light on front roof light bar on the driver side is not working.

Task performed:	Parts	Quantity
REPAIRED LEFT REAR SPOTLIGHT THAT HAD BAD GOUND.	NO PARTS USED	

Workorder: V58890

In Date: 07/06/2013 Meter Reading: 41,140.20
Close Date: 08/02/2013

Problem?
Rubber Hook that holds the Spreaders/ Hurst tool down is very loose. It looks like it needs a replacement to help hold the spreade down. In addition, the chainsaw needs a chainsaw wrench.E 43

Task performed:	Parts	Quantity
READJUSTED TOOL BRACKETS AND REPAIRED HOLDER.	NO PARTS USED	

Workorder: V59316

In Date: 07/24/2013 Meter Reading: 41,552.40
Close Date: 08/02/2013

Problem?
top left emergency strobe, right bulb is out. also, relief valve continues to not function properly, as it will activate but is slow deactivate. i excercised it for 10 min. with no improvement

Task performed:	Parts	Quantity
RAN PUMP TESTED RELIEF VALVE AND TESTED OK	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V58641

In Date: 06/24/2013 Meter Reading: 40,652.00
Close Date: 08/07/2013

Problem?
One of our two circleD lights is not working. 11240 RA

Task performed:	Parts	Quantity
1. REPAIRED CIRCLE D-LIGHT.	NO PARTS USED	
2. REPAIRED REAR STEP LIGHTS THAT WERE OUT.		

Workorder: V59078

In Date: 07/15/2013 Meter Reading: 41,295.00
Close Date: 08/07/2013

Problem?
Pressure relief valve stuck in open position. E43

Task performed:	Parts	Quantity
1. RAN PUMP AND TESTED RELIEF VALVE AND REBUILT VALVE.	NO PARTS USED	
2. REPAIRED AIR LEAK AT REAR OF TRUCK AT AIR TANK.		

Workorder: V59410

In Date: 07/29/2013 Meter Reading:
Close Date: 08/22/2013

Problem?
emergency lights on front bar and driver side rear top corner continue to be only partially operative. Each needs at least one bulb replaced. Air leak is also becoming increasingly more severe.

Task performed:	Parts	Quantity
repaired on w/o59419	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59419

In Date: 07/29/2013

Meter Reading:

Close Date: 08/22/2013

Problem?

near catastrophic brake failure while responding to call. D/O was not driving hard on brakes and had not applied brakes in over a mile, approx. 90 seconds before failure. E43

Task performed:

- travel to sta-43, check brakes, driver and officer did not feel the truck was safe to drive, drove to c/shop pick up spare and bring to sta-43
- check brakes, found front brake chambers inop, remove front wheels and rear wheels, repalce front brakes, brake chambers, slack adjusters, hardware, brake drums, front rotors, wheel bearings, oil seals. set up slack adjusters and adjust brakes, replace brake foot valve
- replace rear brakes, brake hardware, drums, brake chambers, slack adjusters, set up slack adjusters, adjust brakes. install wheels
- rust on roof of cab, also cracked, remove all rust and seal roof seam with marine grade sealer
- check for spotlight inop, found wires under lite bar broken, remove headliner and spotlight assy. install new comunion cable, reinstall headliner
- front and rear lites out in lite bars, replace lites and control boards
- found air leak will not hold over night, check with soap and water found multiple air leaks fixed all. air system now hold over night
- relief valve inop, remove and rebuild intake and discharge valves, replace TPM control valve, replace sensor valve, adjust lite switch,
- door ajar lite inop, found complete door ajar system disconnected, wires cut for lites and alarm, trace out wiring for complete system found deck gun switch inop, replace switch, found quartz lites sensor out of adjustment, also found L-1 compt. door switch bad, rewire ajar lites and alarm
- water leaks inside cab from rear red dot a/c, remove filter and clean out drains
- vehicle hard starting, hook up laptop, found code for fuel pressure sensor, replace sensor, still hard starting, and still had codes for sensor, trace out wiring, check fuel system, could not find problem, sent to cummins
- pump intake and discharge pressure gauges inop, replace FRC led gauge display and transducers

***** these were problems reported to me by the officer and never repaired*****

Parts	Quantity
01-026B807-50LINAER CORNER	1
038-1010-01HALE RELIEF VALVE W/ VULCANIZED SEAT	1
042-0550-00SPRING-VALVE QG RELIEF VALVE	1
042002000SPRING RELIEF VALVE HALE	1
10003890HUB FRONT WHEEL CON MET	2
10400BRAKE CHAMBER 24	2
200226200200-2262-50 SWITCH-PROXIMITY QG VALVE	1
286171BRAKE VALVE E-6 NEW	1
330-3024HUB COVER GASKET	2
3576REAR BRAKE DRUMS	2
370001ASEAL 35066	2
3758FRONT DRUM M2 ENGINE 3598 107453	2
40010070SLACK ADJ WAB 406 10759	2
40010140SLACK ADJUSTER WAB-409-10615	2
4025130FUEL PRESS SENSOR	1
4921497SENSOR PRESSURE	1
516TIRE INFLATOR	1
538-1400-00QG VALVE	1
538-1410-00VALVE SENSING SV HALE	1
546-0200-50QD REL.VALVE KIT	1
546126000TPM/QG HALE REPAIR KIT	1
ACX-84534LUG NUT COVER PK10	20
CM103596BEARING INNER	2
EAA-8350-30UGSS1783UQ STRUT-LIFT	1
FP4000PT-1TRANSDUCER DISCHARGE DIG. MASTER PU	1
FREIGHTSHIPPING CHARGES	1
I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT	2
IOA200A00DISPLAY MODULE REBUILD ONLY SEND IN	1
KSR3014720QPBRAKE SHOES FRONT M2	2
MF39063NUT WHEELBRG TORQUE TITE	2
S690AIR CHUCK	1
SBN NP026773TRBBEARING CUP	2
SBN NP435398TRBBEARING CUP	2
SBN NP874005TRBBEARING CONE	2
XG840-KITEXTENDA GUN SWITCH	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V59756

In Date: 08/13/2013
Close Date: 09/10/2013

Meter Reading: 41,642.00

Problem?

B inspection E43

Task performed:

1. B inspection, repairs made on w/o#59419
2. repalce broken # 4 discharge gauge
3. replace discharge transducer for FRC pump panel gauge, that was inop,

Parts	Quantity
91553943GUAGE	1
FS1022FILTER FUEL WIX 33422 PS8689 FRAM	1
HPH6349AOIL FILTER 51748	1
R90PFILTER FUEL 33231	1

Workorder: V60453

In Date: 09/12/2013
Close Date: 10/09/2013

Meter Reading: 41,642.00

Problem?

need either a new chain saw chain or sharpen the spare chain on E43

Task performed:

DROPPED OFF NEW CHAIN AND INSTALLED ON SAW.

Parts	Quantity
NO PARTS USED	

Workorder: V61630

In Date: 10/29/2013
Close Date: 11/06/2013

Meter Reading: 41,642.00

Problem?

QA and replace rear tailboard

Task performed:

1. START REMOVING REAR TAIL BOARD FROM TRUCK.
2. REMOVED TAIL BOARD FROM PARTS TRUCK CLEANED UP INSTALLED HARNESS FROM TAILBOARD ON E-43 INSTALLED TAILBOARD ON TRUCK.

Parts	Quantity
35200-RLIGHT MARKER LED RED	1
3542606C12611234C1 VENT ACTUATOR	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	3



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62176

In Date: 11/21/2013
Close Date: 11/26/2013

Meter Reading: 41,642.00

Problem?

E43 air stuck on

Task performed:

AIR HORN STOCK OK. CHECK FOUND LOOSE CONNECTION NEAR LINE REPAIR CONNECTION AND SECURE WIRES TEST FOR OPERATION IS GOOD NOW.

Parts

Quantity

NO PARTS USED

Workorder: V62426

In Date: 12/02/2013
Close Date: 12/03/2013

Meter Reading: 41,642.00

Problem?

replace injectors E43

Task performed:

REPLACE INJECTORS E43.

Parts

Quantity

NO PARTS USED

Vendor?: CUMMINS POWER SOUTH

Workorder: V62283

In Date: 11/26/2013
Close Date: 12/04/2013

Meter Reading: 41,642.00

Problem?

air horn staying on when battery switch turned, air line disconnected at solenoid also do a quality check

Task performed:

1. CHECK AIR HORN - REMOVED DASH PANEL AND CHECK SWITCH - CHECK OK. CHECK V-MOR NODES ON AIR HORN CIRCUIT - CHECK OK - AIR HORN CHECK OK.
2. FOUND VARIOUS NODES LOAD SHEADING - REPROGRAMMED ALL NODES CHECK OK.
3. Q.C. - TEST DROVE PUMPED CHECK OK.

Parts

Quantity

NO PARTS USED



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62506

In Date: 12/05/2013 Meter Reading:
Close Date: 12/31/2013

Problem?
Needs constant power point put in, shuts off with Engine

Task performed:	Parts	Quantity
REWIRED 12 VOLT TO CONSTRUCT POWER.	NO PARTS USED	

Workorder: V62514

In Date: 12/05/2013 Meter Reading:
Close Date: 12/31/2013

Problem?
need placards for E43 rear doors, they have been removed and need to be replaced(black mounting brackets)

Task performed:	Parts	Quantity
INSTALLED NEW NUMBER PLATES AND REMOVED OLD ONES.	S PLACARDFRONT AND BACK PLACARD	1

Workorder: V62605

In Date: 12/09/2013 Meter Reading:
Close Date: 12/31/2013

Problem?
Emergency light on officer side grille not working. E43

Task performed:	Parts	Quantity
1. REMOVED LIGHT AND INSTALLED NEW LIGHT AND REWIRED UNIT. 2. TRACED OUT AIR LEAKS FOUND NONE AT THIS TIME.	60R00FRR600 SERIES RED LED W/O FLANGE	1

Workorder: V62606

In Date: 12/09/2013 Meter Reading:
Close Date: 12/31/2013

Problem?
Door shock on medical compartment broken. E43

Task performed:	Parts	Quantity
INSTALLED NEW BRACKET AND PISTON IN MED COMPARTMENT.	575BACKUP ALARM ECCO 107 DEC	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62607

In Date: 12/09/2013 Meter Reading:
Close Date: 12/31/2013

Problem?
Relocate the microphone holder on the officers side... e43

Task performed:	Parts	Quantity
MOVED MIKE HOLDER TO OFFICERS SIDE AND REWIRED 12 VOLT CHARGER.	NO PARTS USED	

Workorder: V62685

In Date: 12/13/2013 Meter Reading: 41,987.30
Close Date: 01/27/2014

Problem?
Right front turn signal is not working. E43

Task performed:	Parts	Quantity
REPAIRED BAD CONNECTION IN LIGHT.	NO PARTS USED	

Workorder: V62714

In Date: 12/14/2013 Meter Reading: 42,088.00
Close Date: 01/27/2014

Problem?
Right front turn signal not working. E43

Task performed:	Parts	Quantity
REPAIRED ALL AIR LEAKS THAT WERE FOUND.	NO PARTS USED	

Workorder: V62715

In Date: 12/14/2013 Meter Reading: 42,088.00
Close Date: 01/27/2014

Problem?
Door strut on generator compartment broken. E43

Task performed:	Parts	Quantity
REPAIRED COMPARTMENT DOOR THAT WOULD NOT CLOSE - REPAIRED HINGE.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V62750

In Date: 12/16/2013 Meter Reading: 142,162.50
Close Date: 01/27/2014

Problem?
Right front turn signal out. E43

Task performed:	Parts	Quantity
REPAIRED RIGHT TURN SIGNAL THAT WAS OUT DUE TO BROKEN WIRES.	NO PARTS USED	

Workorder: V62867

In Date: 12/21/2013 Meter Reading:
Close Date: 02/06/2014

Problem?
Door strut on generator compartment broken... 11240 RA E43

Task performed:	Parts	Quantity
REMOVED AND REPLAECED DOOR PISTON.	NO PARTS USED	

Workorder: V63393

In Date: 01/14/2014 Meter Reading:
Close Date: 02/06/2014

Problem?
Drivers compartment door warning light going off intermittently while driving with door closed... 11240 RA

Task performed:	Parts	Quantity
REPAIRED REAR DOOR SWITCH THAT WAS SHORTING OUT.	NO PARTS USED	

Workorder: V64024

In Date: 02/06/2014 Meter Reading: 43,490.00
Close Date: 02/06/2014

Problem?
replace hurst hoses and need a case oil

Task performed:	Parts	Quantity
DELIVERED OIL.	15W40QSYN OIL QT	12
	3530016HOSE HURST 16 ORANGE	1
	353R091USE 353R403 HURST HOSE 16 GREEN	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V64107

In Date: 02/10/2014 Meter Reading:
Close Date: 02/10/2014

Problem?
Need hurst hydraulic fluid 1-2 qts

Task performed:	Parts	Quantity
PARTS DELIVERED.	180R002HURST HYD. FLUID QT	2

Workorder: V64101

In Date: 02/10/2014 Meter Reading: 43,490.00
Close Date: 02/12/2014

Problem?
No air presure.

Task performed:	Parts	Quantity
TRACED OUT LEAK AND REPAIRED.	NO PARTS USED	

Workorder: V64236

In Date: 02/14/2014 Meter Reading: 43,557.90
Close Date: 02/24/2014

Problem?
Mount brackets for new hose installation

Task performed:	Parts	Quantity
MOVE HOSE BED DIVIDER. MOUNT 5" TOOL HOLDER BRACKETS AT VARIOUS PLACES ON TRUCK. ATTACH 5 TO RT2 CAP RETAINER.	NO PARTS USED	

Workorder: V64587

In Date: 02/27/2014 Meter Reading: 44,035.40
Close Date: 02/28/2014

Problem?
no crank

Task performed:	Parts	Quantity
NO CARNK. FOUND FAULTY STARTER REPLACE ALSO SOLENOID ON FIREWALL ORIGINAL SOLENOID.	82000056808 38MT 12T STARTER	1
	ESX120105112STARTER RELAY ESX-120-105112	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V64453

In Date: 02/22/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

The ignition doen not turn the motor intrmittently before turning over... Possibly low cranking amps... E43

Task performed:

CHECKED ALL CONNECTION STARTED TRUCK SEVERAL TIMES AND STARTED OK,

Parts

NO PARTS USED

Quantity

Workorder: V64454

In Date: 02/22/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

Front bumper suction valve not opening... E43

Task performed:

REPAIRED TANK FILL LINE THAT WAS INOP-LINKAGE WAS OFF VALVE.

Parts

NO PARTS USED

Quantity

Workorder: V64455

In Date: 02/22/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

Is it possible to have a third set of large diameter spanners mounted on the right side panel... E43

Task performed:

DC WILL NEED TO ORDER.

Parts

NO PARTS USED

Quantity

Workorder: V61623

In Date: 10/29/2013
Close Date: 03/28/2014

Meter Reading: 41,642.00

Problem?

engine hard starting

Task performed:

REPAIRES COMPLETED.

Parts

NO PARTS USED

Quantity



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V64609

In Date: 03/01/2014 Meter Reading:
Close Date: 03/28/2014

Problem?
Still having the intermittent delay in cranking. E 43

Task performed:	Parts	Quantity
TRACED OUT PROBLEM, TESTED WIRES AND CHECKED ALL CONNECTION WILL MONITOR.	NO PARTS USED	

Workorder: V64613

In Date: 03/01/2014 Meter Reading:
Close Date: 03/28/2014

Problem?
When attempting to start Engine 43 this morning, there was a click when the ignition was turned on, then nothing. The engine started on the second attempt. E43

Task performed:	Parts	Quantity
REMOVED AND INSTALLED NEW KEY SWITCH.	NO PARTS USED	

Workorder: V64728

In Date: 03/05/2014 Meter Reading:
Close Date: 03/28/2014

Problem?
E43 WILL NOT START WHEN IGNITION SWITCH IS TURN AT TIMES. HAVE TO TURN IGNITION SWITCH MORE THEN ONCE DOES NOT ALWAYS WORK CORRECTLY. FRONT INTAKE DOES NOT WORK AND AIR SWITCH LEAKS AIR WHEN USED.

Task performed:	Parts	Quantity
1. TRACED OUT WITH INTERMITTENT STARTING.	101AKRON SHORT ARM RC-4	1
2. VALVE HANDLE BROKEN, REMOVED AND REPAIRED.	102AKRON LONG ARM RC-4	1

Workorder: V65757

In Date: 04/16/2014 Meter Reading:
Close Date: 04/21/2014

Problem?
right rear outside tire worn to wear bars on outside of tire

Task performed:	Parts	Quantity
right rear outside tire worn to wear bars on outside of tire	NO PARTS USED	
Vendor?: ELPEX		



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V65441

In Date: 04/04/2014 Meter Reading:
Close Date: 04/25/2014

Problem?
Throttle fluctuated wildly while pumping a fire.

Task performed:	Parts	Quantity
1. CHECKED ALL CONNECTION AND RAN PUMP AND FOUND NO PROBLEM.	180R002HURST HYD. FLUID QT	3
2. DROPPED OFF HURST OIL.		

Workorder: V64492

In Date: 02/24/2014 Meter Reading:
Close Date: 05/22/2014

Problem?
front intake valve needs to be replaced and E43 needs 5" spanners with mount to be mounted on passenger side of engine. Than you

Task performed:	Parts	Quantity
1. REMOUNTED TOOLS IN L-1 COMPARTMENT.	ALA00350-50 EXTENDED LIFE COOLANT GAL	6
2. CHECK ENGINE LIGHT ON-FOUND LOW ON COOLANT, PRESSURE TEST MOTOR.		

Workorder: V65752

In Date: 04/16/2014 Meter Reading:
Close Date: 05/23/2014

Problem?
The strap that holds the spreader in place is broken and the spreaders fall out of holder when door is opened and is unable to be closed, also hose bag for the extracation hose needs to be replaced it has two large hole E43

Task performed:	Parts	Quantity
1. REMOVED AND REPLACED STRAP FOR HURST CUTTERS.	NO PARTS USED	
2. CLEANED CARB ON HURST UNIT AND TESTED.		

Workorder: V66243

In Date: 05/05/2014 Meter Reading:
Close Date: 05/23/2014

Problem?
Foam tank level light flucuating from full to 1/2 tank when tank is full.

Task performed:	Parts	Quantity
CLEANED GROUND WIRE ON SENDING UNIT AND TESTED GUAGE.	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V66680

In Date: 05/23/2014 Meter Reading:
Close Date: 06/09/2014

Problem?
quartz tower light alarm will not go off

Task performed:	Parts	Quantity
read justed switch for quartz lights.	NO PARTS USED	

Workorder: V67203

In Date: 06/13/2014 Meter Reading:
Close Date: 07/03/2014

Problem?
Lock on 5in hose broken on 1 stortz coupling E43

Task performed:	Parts	Quantity
1. AIR LEAK REPAIRED AND RECHECKED FOR LEAKS.	NO PARTS USED	
2. DOOR ALARM TRACED OUT ALARM FOUND BAD GROUND ON REAR DOORS.		

Workorder: V67116

In Date: 06/10/2014 Meter Reading:
Close Date: 07/09/2014

Problem?
CHAIN SAW WILL NOT START..

Task performed:	Parts	Quantity
shop pick up saw.	NO PARTS USED	

Workorder: V67214

In Date: 06/14/2014 Meter Reading:
Close Date: 07/16/2014

Problem?
Section of 5 inch hose in need of repair. Red coupling lock broken. E43

Task performed:	Parts	Quantity
repairs complete on ticket v67203	NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V69059

In Date: 08/29/2014

Close Date: 11/03/2014

Meter Reading: 47,061.00

Problem?

C inspection SE7

Task performed:

Parts

Quantity



7/1/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

<ol style="list-style-type: none"> 1. a & b - C Inspection. 2. C Inspection. 3. C Inspection. 4. Performed pump tests after dry vacuum tests to determine location of leaks. Large leaks at tank to pump and tank fill/recirculation valves. 5. Batteries failed load tests after recharge. Replaced 4 batteries. 6. Replaced intake air filter and rear cab A/C filter. 7. Serviced air dryer. 8. Found foam system, pump to valve hose severely degraded and cracked. Replaced hose and tested system. 9. Replaced failed compartment door hold open props on R1/rear R3/both, rear lower/both. R & I rear grab rail to replace failed hose bed cover straps. 10. R & I tank to pump valve and overhauled. Recalculated valve arm geometry. Cut and welded arm to correct. Installed correct length shift rod and adjusted. 11. Removed tank fill/recirc. valve and replaced with revised Arkon valve. Removed Arkon valve flanges and piping from parts truck and installed. Adjusted shift rod geometry and adjusted. 12. Retested for pump leaks by performing dry vacuum test and pressure tests. Secondary leaks found at #1 discharge and trash line Hale valves. 13. Removed and overhauled #1 discharge and trashline Hale pump valves. Performed dry vacuum and pressure tests to verify repairs. 14. Found pump panel transmission temperature gauge holding water. Replaced failed gauge and fabricated wiring. 15. Performed cooling system flush and replaced filter. Pressure tested and replaced failed radiator cap. 16. Remove campaign sign brackets. Cleaned adhesive 17. a & b - Replaced front and rear compressor belts and adjusted. Replaced worn and noisy engine serp. belt and failed tensioner. Replaced sheared compressor mounting bolt. 18. Removed rusting, corroded crosslay nozzle holders. Assembled new holders and fabricated mounts. 19. Removed damaged glove holder in rear of cab and remove adhesive. Installed 2 new glove holders. Removed decals from windshield. 20. Rear upper grab bar loose. Drilled and tapped new mounting holes. Secured with new fasteners. 21. Walk thru pump panel. Upper inspection panel, cam lock missing and all fasteners loose. Removed cam locks from parts truck. Installed cam lock. Drilled out and installed new rivets on all panel locks. 22. a & b - R & I middle and rear headliner sections. R & I L/R seat for upper cushion and cover repairs. Sent headliners and seat to trim shop. 23. Removed duct tape from defrost vents and cleaned 	<p>0100030000SCREEN 6 IN 2</p> <p>05-17223-000CAP RADIATOR 10 LB 1</p> <p>107796DRYER KIT AD9 -NEW 1</p> <p>107800VALVE CHECK AD9 1</p> <p>108-12FBEADED CHAIN W/CONN 12 2</p> <p>15W40BSYN OIL BULK QTS 25</p> <p>194BULB 1</p> <p>310-303TRANS TEMP GAUGE 1</p> <p>39768315259022 GROOVED TENSIONER OLD#3936213 1</p> <p>404-100 VALVE CORE 10</p> <p>480714HOSE & FITTINGS 1</p> <p>52-24WIPER BLADES ANCO 24 2</p> <p>5462280020VALVE KIT 2 IN SS VALVE 546-2280-02-0 1</p> <p>5462290020VALVE KIT SS VALVE 2 1/2 546-2290-02-0 1</p> <p>56415CIG. LIGHTER ACCES. 1</p> <p>600-802600-802 BULB TAG LIGHT 1</p> <p>6805450124SWITCH TURN SIGNAL 1</p> <p>6814600340A14-15472-000 HORN BUTTON 1</p> <p>7001-15EG150T SEAL 1</p> <p>78R536078R5360M 2PK FILTER AIR COND 1</p> <p>800405PURGE VALVE KIT 1</p> <p>91398907 VALVE KIT 3 IN AKRON 1</p> <p>9440BELT 2</p> <p>9480BELT 1</p> <p>9914-0393PINION GEAR 1</p> <p>ANTICOOLANT ANTIFREEZE GAL 8</p> <p>BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY 4</p> <p>CA8193AIR FILTER 46744 WIX 1</p> <p>EAA-8350-30UGSS1783UQ STRUT-LIFT 5</p> <p>FS1022FILTER FUEL WIX 33422 PS8689 FRAM 1</p> <p>HP-31DBATTERY 950CCA HP-31D 4</p> <p>HPH6349AOIL FILTER 51748 1</p> <p>K080716BELT 1</p> <p>LF18TS-LEDMAP LIGHT LED 18 IN 1</p> <p>PR338324070 WIX FILTER WATER 1</p> <p>PSTANKWATER LEVEL LED LIGHT 1</p> <p>R90PFILTER FUEL 33231 1</p> <p>RGTTAS65052ASTEERING GEAR BOX FRTLNR. ENG. 1</p> <p>S337INNER POLE SWITCH MAGNET 1</p> <p>TRANSYNDALLISON TRANS FLUID GAL 2</p> <p>WAT61403STRAINER 6 IN 1</p>
--	---



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

adhesive from dash panel. Adjusted defrost/vent cable.

24. Found horn pad broken and turn signal switch bent and sticking. Replaced horn pad and turn signal switch assembly.

25. a & b - Found all warning buzzers and lamps inoperable. Repaired cut wiring and disconnected buzzers and lamps. Removed left quartz pole lamp and disassembled. Replaced warning sensor magnet. Adjusted sensor.

26. a & b -75% of green LEDs on right side tank level indicator inoperable. No access to wiring behind indicator. Drilled hole in body to access wiring. Fabricated wiring and installed new indicator.

27. Found front intake valve not opening. air switch working properly. Removed valve motor assembly and disassembled valve seized due to debris. Cleaned and lubricated valve. Reinstalled.

28. Found L/12 handlight charger inoperable and map lamp missing. Removed corroded connector and repaired wiring on charger. Installed map lamp.

CONTINUED ON WORK ORDER # 70617



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V70617

In Date: 08/29/2014 **Meter Reading:** 47,061.00
Close Date: 11/03/2014

Problem?
 additional work order for C inspection SE7

Task performed:	<u>Parts</u>	<u>Quantity</u>
CONTINUED FROM W/O # 69059	NO PARTS USED	

29. a & b - Removed booster reel and disassembled. Found failed brake/manual pinion gear. Replaced gear. Reinstalled.

30. Installed wiper blades. Cleaned garbage and debris from cab and body. Installed right pump panel #2 discharge cap and 2 cap chains.

31. Power steering noise diagnostics and complete system flush.

32. Polish, attempt, replacement wheels.

33. R & I front wheels for tire replacement.

34. a & b - Performed power steering diagnostics using pressure/flow gauge. Installed new gear and bled system. Test drove. Removed steering wheel to position straight. Test drove again. Verified repair.

35. Replaced failed bulb in left front clearance lamp.

36. Quality & Assessment.

Workorder: V70710

In Date: 11/04/2014 **Meter Reading:** 47,061.00
Close Date: 11/07/2014

Problem?
 replace fronts

Task performed:	<u>Parts</u>	<u>Quantity</u>
WORK REPAIRS REQUESTED.	NO PARTS USED	

Vendor?: BLVD TIRE CENTER



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V71222

In Date: 11/26/2014
Close Date: 12/04/2014

Meter Reading: 47,061.00

Problem?

A inspection SE7

Task performed:

1. "A" Inspection air tires to proepr PSI
2. L seat belt cover torn, trim loose cover away
3. Diangose driver step light inop-found wires pulled from connector. Repair connection and pulled slack from harness and tie strap to secure.
4. Left and right fender markers inop-found both bulbs burnt out, replaced bulbs.
5. Cab light box charger broken and loose. Replaced charger, splice wires. Install lock nuts on bottom slide test charger (ok) protect wiring
6. Center rear right tail board marker dim-found bad light assembly and cut pinched wire, repaired wire and replaced light assy
7. L-1 shock missing-install new shock on L-1 door
8. Loosen and adjusted R air horn sound

Parts	Quantity
35200-RLIGHT MARKER LED RED	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	1

Workorder: V71622

In Date: 12/13/2014
Close Date: 12/18/2014

Meter Reading:

Problem?

pressure alarm sounding, no rpm, no temp reading, no oil pressure on panel, pressure relief light lit when in drive, discharge gaug giving reading when in drive E14

Task performed:

1. Travel to 14, driver complaint no oil pressure or temp or tach. Throttle working traced wiring back as far as possible could not locate EDM connection-replaced throttle head.
2. Driver complaint of check engine light, checked system found new throttle 10-7, repaired system-ok.

Parts	Quantity
ELA101-ATHROTTLE EXCEL CUMMINS IS SERIES	1

Workorder: V71809

In Date: 12/22/2014
Close Date: 12/30/2014

Meter Reading: 47,799.60

Problem?

Pump trottle on panel not working. Panel show's no RPM, but display code E01.

Task performed:

Checked truck found no problem with throttle

Parts	Quantity
NO PARTS USED	



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

1015554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V69959

In Date: 10/06/2014 Meter Reading: 47,656.00
Close Date: 01/02/2015

Problem?
pump panel display shows error e01, no rpm, oil pressure, or temperature readouts

Task performed:	Parts	Quantity
Pump panel display shows error eol no rpm oil pressure or temp. Checked system ok	NO PARTS USED	

Workorder: V71889

In Date: 12/28/2014 Meter Reading:
Close Date: 01/05/2015

Problem?
TIC (asset # 10173219) is not getting any charge when place or attach it on base charger E14

Task performed:	Parts	Quantity
Check out tire on truck not charging tic R/R and rewire new base	NO PARTS USED	

Workorder: V73009

In Date: 02/09/2015 Meter Reading: 48,395.60
Close Date: 02/23/2015

Problem?
A INSPECTION

Task performed:	Parts	Quantity
1. A Inspection. 2. R & R compartment L-3 hold open. 3. R & R lens and bulb on cab roof marker light. 4. A/C compressor bolt broken. Loosen all adjacent bolts. R & R pivot bolt, washers and nut. Adjust belt tension.	EAA-8350-30UGSS1783UQ STRUT-LIFT	1

Workorder: V73750

In Date: 03/09/2015 Meter Reading:
Close Date: 03/09/2015

Problem?
K12 fuel cap is partially chipped so it does not have a complete seal, therefor leaking fuel. Asset # for saw is 10167121.

Task performed:	Parts	Quantity
Light duty delivered	505312226FUEL CAP PARDNERS	1



7/1/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10155554

FL80 FIRE DEPARTMENT PUMPER NFPA COMPLIANT

Workorder: V73698

In Date: 03/06/2015
Close Date: 03/19/2015

Meter Reading:

Problem?

(Spare Ferrara), toggle switch for front intake not working. Not opening valve for front intake. -Tom Parker (561)324-2447

Task performed:

1. Travel to station 37. Check out front intake valve inop. Try to free up valve cylinder bad. Needs to go to shop for replacement on next P.M.

Parts	Quantity
NO PARTS USED	

Workorder: V74240

In Date: 03/27/2015
Close Date: 05/06/2015

Meter Reading: 49,490.00

Problem?

A-inspection

Task performed:

1. A-Inspection.
2. L/rear and R/rear window molding broken- remove and install new molding.

Parts	Quantity
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1

Workorder: V69127

In Date: 09/03/2014
Close Date: 06/08/2015

Meter Reading:

Problem?

Will not hold vacuum Tank to pump valve or tank fill valve not closing completely. Tank level gauges on the side of the truck not working when in pump gear

Task performed:

Parts	Quantity
NO PARTS USED	



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10155554) 2004 - FERRARA FL80 1250 Gpm Pumper

10155554

CSHOP-2015-1041

Comments: E27 THROTTLE PROBLEM

Date Opened: 6-8-2015

Date Finished

6-8-2015

Meter 1 Reading:

49,590

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

1 THROTTLE; THROTTLE EXCEL CUMMINS IS SERIES

CSHOP-2015-1064

Comments: E27 RELIEF VALVE INOP

Date Opened: 6-8-2015

Date Finished

6-16-2015

Meter 1 Reading:

49,690

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE APPARATUS

CSHOP-2015-1215

Comments: THROTTLE NOT FUNCTIONING PROPERLY ON PUMP PANEL SPARE ENGINE AT 27

Date Opened: 6-16-2015

Date Finished

6-17-2015

Meter 1 Reading:

50,000

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

FIRE PUMP

CSHOP-2015-1220

Comments: SAFETY ALARM FOR DECK GUN STUCK ON

Date Opened: 6-16-2015

Date Finished

7-7-2015

Meter 1 Reading:

50,000

TASKS PERFORMED

Q PARTS

A INSPECTION

AIR SYSTEM

STROBE LIGHTS

AIR HORN

SAFTEY-EMERGENCY EQUIPMENT

HVAC SYSTEM

1 LIGHT; 600 SERIES RED LED W/O FLANGE
3 SWITCH; EXTENDA GUN SWITCH

CSHOP-2015-1705

Comments: NEED 12V POWER FROM BATTERY WHEN IGN OFF FOR SAFETY PAD SE@54

Date Opened: 7-13-2015

Date Finished

7-23-2015

Meter 1 Reading:

50,000

TASKS PERFORMED

NO PARTS USED

BATTERY

Asset Work Order History 10155554

CSHOP-2015-2062

Comments: **FRONT INTAKE DOES NOT WORK E 54**

Date Opened: 8-3-2015 Date Finished 8-7-2015 Meter 1 Reading: 50,000

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS

CSHOP-2015-2334

Comments: **A INSPECTION SE7**

Date Opened: 8-14-2015 Date Finished 8-18-2015 Meter 1 Reading: 51,290

STROBES OUT LEFT SIDE

TASKS PERFORMED

Q PARTS

A INSPECTION

1 FLUID; SYN OIL BULK QTS

ANTIFREEZE

1 9IP; IGNITION ON DISPLAY

OIL

2 LIGHT; LIGHT LED RED TIR 6

LIGHTING SYSTEM

BATTERY TRAY

REPAIR FROM PM - TIRES

REPAIR FROM PM - HOSES

AIR SYSTEM

STROBE LIGHTS

CSHOP-2015-2854

Comments: **E23 FRONT SUCTION INOP**

Date Opened: 9-11-2015 Date Finished 9-17-2015 Meter 1 Reading: 52,163

DIAGNOSE FRONT SUCTION NOT WORKING

TASKS PERFORMED

NO PARTS USED

FIRE PUMP PLUMBING

CSHOP-2015-3008

Comments: **SPARE ENGINE, SHELF WITH RAMS NEEDS TWO SCREWS BEFORE IT FALLS OUT ON SOMEONE**

Date Opened: 9-21-2015 Date Finished 9-25-2015 Meter 1 Reading: 154,208

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

BODY EXTERIOR

Asset Work Order History 10155554

CSHOP-2015-3169

Comments: **A-INSPECTION**

Date Opened: 9-30-2015

Date Finished

10-7-2015

Meter 1 Reading:

52,662

TASKS PERFORMED

A INSPECTION
FIRE FIGHTING EQUIPMENT
FIRE PUMP CONTROLS
TANK SUCTION VALVE FIRE PUMP
HOSE BED BODY
AIR SYSTEM
STROBE LIGHTS
DOOR

Q PARTS

1 CHAIN; BEADED CHAIN W/CONN 12
1 KNOB; KNOB DRAIN
1 VALVE; VALVE AIR CONTROL
1 LIGHT; LIGHT LED RED TIR 6
1 STRUT; GSS1783UQ STRUT-LIFT

CSHOP-2015-3443

Comments: **C-INSPECTION**

Date Opened: 10-15-2015

Date Finished

10-15-2015

Meter 1 Reading:

52,669

TASKS PERFORMED

PM SERVICE C

Q PARTS

1 FILTER; OIL FILTER 51748
25 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM

CSHOP-2015-3570

Comments: **NEED A TIC CHARGER PM FOLLOW UPS**

Date Opened: 10-23-2015

Date Finished

2-24-2016

Meter 1 Reading:

52,669

TASKS PERFORMED

FOAM SYSTEM
SIDE COMPARTMENT BODY
REPAIR FROM PM - FIRE PUMP SYS
BATTERY
TRANSMISSION
AIR DRIER
AIR SYSTEM
AIR HORN
SEAT BELTS
A/C FILTER

Q PARTS

1 9IP; SENSOR HALE HPF FOAM FLOW
1 CABLE; 4 PIN CABLE FLOW SENSOR HALE FOAM SYS.
1 9IP; 529-0080-10-0 1 1/4 ANODE KIT
4 BATTERY; BATTERY 950CCA HP-31D
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
1 HOSE; HOSE LOWER RADIATOR
1 COOLER; COOLER 14032
1 FILTER; 29548988 TRANS FILTER ALLISON
1 DRYER; DRYER KIT AD9 -NEW
1 DRYER; DRYER KIT AD9 -NEW
1 VALVE; PURGE VALVE KIT
1 VALVE; PURGE VALVE KIT
1 VALVE; VALVE CHECK AD9
1 VALVE; VALVE CHECK AD9
1 FILTER; 78R5360M 2PK FILTER AIR COND

Asset Work Order History 10155554

CSHOP-2015-921

Comments: AIR PRESSURE LOW WHEN NOT RUN FOR A FEW HOURS TEMP AND OIL PRESS LIGHTS ON PUMP PANEL NOT WORKING SPARE ENGINE @ 27

Date Opened: 6-1-2015 Date Finished 6-12-2015 Meter 1 Reading: 49,590

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

CSHOP-2016-1400

Comments: SE @ 48

Date Opened: 3-23-2016 Date Finished 4-4-2016 Meter 1 Reading: 53,262

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

03/23/2016 LIGHTS / 19: LOOSE / REPAIR
TELESCOPING LIGHT ON DRIVER SIDE IS OUT.

03/23/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
BUZZER AND LIGHT FOR THE DECK GUN COMES ON WHILE DRIVING. THE DECK GUN IS SEATED PROPERLY.

CSHOP-2016-1692

Comments: E48

Date Opened: 4-11-2016 Date Finished 4-27-2016 Meter 1 Reading: 53,576

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT
SAFTEY-EMERGENCY EQUIPMENT
HVAC SYSTEM

Service Requests:

04/13/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
FOAM TANK INDICATOR LIGHT - ON PUMP PANEL- NOT WORKING PROPERLY. FLASH EMPTY THEN FULL- FOAM TANK IS FULL NOTE THIS WAS REPAIRED ON ANOTHER WORK ORDER, GAUGE JUST NEEDED TO BE RECALABRATED

04/13/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
HANDLE BENT ON ATTIC LADDER- E48 SPARE/REPAIRED LADDER HANDLE ,,,,,,

04/14/2016 SERVICE REQUEST / 18: LEAKING / A
K12 UNOPERATIONAL DUE TO PULL CORD BROKEN DURING START UP.

Asset Work Order History 10155554

CSHOP-2016-2011

Comments: SE@48

Date Opened: 4-28-2016

Date Finished

6-8-2016

Meter 1 Reading:

54,586

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
DIAGNOSE ELECTRICAL
BODY EXTERIOR

Service Requests:

04/28/2016 LIGHTS / 19: LOOSE / P
DRIVER SIDE SCENE LIGHT NOT WORKING

05/04/2016 DOOR / 19: LOOSE / REPAIR
PISTON HINGE ON THE COMPARTMENT DOOR IS BROKEN. FOUND AT CHECK OUT. OFFICER SIDE REAR DOOR-
GENERATOR COMPARTMENT

CSHOP-2016-2226

Comments: E48

Date Opened: 5-9-2016

Date Finished

5-21-2016

Meter 1 Reading:

53,576

TASKS PERFORMED

Q PARTS

FIRE APPARATUS

1 KNOB; KNOB DRAIN

Service Requests:

05/07/2016 SERVICE REQUEST / 18: LEAKING / Q
NEED ONE KNOB FOR RELIEF VALVE ON OFFICER SIDE 3 INCH INTAKE

CSHOP-2016-2937

Comments: REPLACE RRI TIRE

Date Opened: 6-20-2016

Date Finished

6-20-2016

Meter 1 Reading:

55,175

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-3042

Comments: ON-CALL E33 DECK GUN ALARM

Date Opened: 6-24-2016

Date Finished

6-26-2016

Meter 1 Reading:

55,433

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE PUMP CONTROLS

Asset Work Order History 10155554

CSHOP-2016-3068

Comments: **ON-CALL SPARE ENGINE AT 33 SCENE LIGHTS OUT**

Date Opened: 6-27-2016 Date Finished 6-28-2016 Meter 1 Reading: 55,433

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUARTZ LIGHT

6 9IP; BULB QUARTZ HAL. 12V 150W

CSHOP-2016-3277

Comments: **A INSPECTION**

Date Opened: 7-7-2016 Date Finished 7-8-2016 Meter 1 Reading: 55,599

TASKS PERFORMED

Q PARTS

A INSPECTION
INTAKE VALVE
EQUIPMENT MOUNTING BRACKETS
LIGHTING SYSTEM
LIGHT BAR
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

2 LIGHT; LIGHT MARKER LED RED
1 LIGHT; BALLAST 4 CHANNEL LED LIGHTBAR 01-0269742-00
2 STRUT; GSS1783UQ STRUT-LIFT
1 9IP; 3943793 LINK ADJ A/C COMP
1 9IP; BOLT ADJ A/C COMP
3 A/C; FREON LB

CSHOP-2016-3400

Comments: **A-INSPECTION**

Date Opened: 7-14-2016 Date Finished 7-18-2016 Meter 1 Reading: 55,433

TASKS PERFORMED

Q PARTS

A INSPECTION

2 WIPER; WIPER BLADES ANCO 24

CSHOP-2016-4241

Comments: **2 BULBS FOR 14**

Date Opened: 8-29-2016 Date Finished 10-14-2016 Meter 1 Reading: 57,489

TASKS PERFORMED

Q PARTS

CONTROL VALVE FIRE PUMP
ENGINE AND ACCESSORIES
QUARTZ LIGHT
HEADLIGHTS LOW BEAM
LIGHTING SYSTEM
AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT
DOOR LOCKS
GLOVE BOX
CABIN AIR FILTER
HEATER CONTROL VALVE
QUALITY CHECK-REPAIRS
HVAC SYSTEM

2 BULB; BULB
1 KNOB; KNOB DRAIN
2 CHAIN; BEADED CHAIN W/CONN 12
2 LIGHT; HEADLIGHT EXTRA BRIGHT
2 9IP; BULB QUARTZ HAL. 12V 150W
1 BULB; BULB 12 VOLT
6 DECAL; LADDER OUT OF SERVICE STICKER
1 9IP; VENT A/C LH
1 FILTER; 78R5360M 2PK FILTER AIR COND
1 9IP; CABLE HEATER
1 VALVE; 12-0615A VALVE EXPANSION FTRLNR 1606
4 A/C; FREON LB
1 DRYER; 07-0610A DRYER

Service Requests:

08/28/2016 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / LIGHTS WORKING
VEHICLE LIGHTS NOT WORKING. FRONT OFFICER LIGHT NOT WORKING IN LOW BEAM. WILL WORK IN HIGH BEAM.
THIS VEHICLE IS AT STATION 14 AS A SPARE

Asset Work Order History 10155554

CSHOP-2016-4605

Comments: **SENT CALLAGHAN TO INSTALL 4 REAR 9-22-16**

Date Opened: 9-22-2016 Date Finished 9-26-2016 Meter 1 Reading: 57,310

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

09/22/2016 TIRES / 44: WORN / EXCHANGE - NEW
BAD TIRES

CSHOP-2016-4801

Date Opened: 10-4-2016 Date Finished 10-14-2016 Meter 1 Reading: 57,489

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 FILTER; OIL FILTER 51748
1 FILTER; FILTER FUEL WIX 33422 PS8689 FRAM
25 FLUID; SYN OIL BULK QTS
1 FILTER; FILTER FUEL 33231

CSHOP-2016-5329

Comments: **SPARE AT 30**

Date Opened: 11-14-2016 Date Finished 12-6-2016 Meter 1 Reading: 58,343

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

1 9IP; BLOWER MTR RD# 73R3002
1 SWITCH; 11-3050 SWITCH BLOWER

Service Requests:

11/12/2016 A/C / 38: SHORTED / EXCHANGE - NEW
A/C ISSUE

CSHOP-2016-5806

Date Opened: 12-12-2016 Date Finished 12-20-2016 Meter 1 Reading: 58,515

TASKS PERFORMED

Q PARTS

HEADLIGHTS LOW BEAM
DOOR ALARM OR OTHER WARNING

1 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

12/12/2016 ALARMS / 15: FOREIGN MATERIAL / INSPECT
ALARM SIGNALS. PRESSURE ALARM SIGNAL GOES OFF EVERY 10 SEC.

12/12/2016 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING. LEFT FRONT HEADLIGHT OUT.

Asset Work Order History 1015554

CSHOP-2017-1003

Comments: **ENGINE AT 47**

Date Opened: 2-16-2017

Date Finished

3-2-2017

Meter 1 Reading:

59,586

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM
HVAC SYSTEM

Service Requests:

02/16/2017

ENGINE / 18: LEAKING / REPAIR

EXCESSIVE CRANKING TIME WHILE STARTING

CSHOP-2017-1127

Comments: **THIS IS THE SPARE ENGINE AT ST47 I THINK SCOTTY FORGOT TO PUT WHERE IT IS ALSO WO#944**

Date Opened: 2-23-2017

Date Finished

3-23-2017

Meter 1 Reading:

60,408

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
COOLING SYSTEM

Service Requests:

02/23/2017

SERVICE REQUEST / 18: LEAKING / REPAIR

SERVICE REQUEST DISCHARGE PRESSURE RELIEF VALVE WILL NOT ENGAGE MULTIPLE ATTEMPTS WERE MADE

03/15/2017

RADIATOR / 18: LEAKING / REPAIR

COOLANT LEAK, 1 GALLON OF COOLANT ADDED THIS AM. SMALL AMOUNT OF COOLANT NOTED ON BAY FLOOR THIS AM AND THEN THROUGHOUT THE SHIFT

CSHOP-2017-1948

Date Opened: 4-3-2017

Date Finished

4-5-2017

Meter 1 Reading:

60,898

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY DAMAGE ACCIDENT

Service Requests:

04/03/2017

SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT

SERVICE REQUEST PER CHIEF BATTALLION 2 E21 NEEDS TO HAVE A MECHANIC COME OUT AND INSPECT THE VEHICLE AFTER POSSIBLE DAMAGE.

Asset Work Order History 10155554

CSHOP-2017-2051

Date Opened: 4-7-2017

Date Finished

7-27-2017

Meter 1 Reading:

62,868

TASKS PERFORMED

A INSPECTION
COOLING SYSTEM

<u>Q</u>	<u>PARTS</u>
4	9ME; STRAP 25"-44"
4	9ME; STRAP
1	TFW; HD WATER PUMP
-1	2DD; FAN
1	2DD; 2DD
1	BRG; ALTERNATOR BEARING
1	5FF; FAN BLADE
1	BELT; BELT
1	BELT; BELT
1	BELT; BELT
1	5EF; IDLER PULLEY
1	NONSTOCK; FREIGHT CHARGE
1	NONSTOCK; FREIGHT CHARGE

CSHOP-2017-247

Comments: **SPARE ENGINE 7 AT STATION 29 EXTENDED START TIME AND RELIEF VALVE**

Date Opened: 1-11-2017

Date Finished

1-23-2017

Meter 1 Reading:

58,678

TASKS PERFORMED

FIRE PUMP
ENGINE AND ACCESSORIES

<u>Q</u>	<u>PARTS</u>
1	5HP; RELIEF VALVE KIT HALE

Service Requests:

01/11/2017 ENGINE / 19: LOOSE / REPAIR
DELAYED START EXTENDED TURN OVER.

01/11/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
PRESSURE RELIEF VALVE ISNT WORKING PROPERLY AND LEAKS WHEN SET AND TRUCK IS OFF.

CSHOP-2017-3929

Date Opened: 7-3-2017

Date Finished

7-5-2017

Meter 1 Reading:

62,868

TASKS PERFORMED

PM SERVICE B

<u>Q</u>	<u>PARTS</u>
1	FIL; NAPAGOLD OIL FILTER
2	1AN; WIPER BLADE 24 IN
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; FUEL WATER SEPARATOR
-30	9OC; SYN 15W40
30	9OC; SYN 15W40
30	FLUID; SYN OIL BULK QTS

Asset Work Order History 10155554

CSHOP-2017-3937

Date Opened: 7-3-2017

Date Finished

8-15-2017

Meter 1 Reading:

62,891

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	-2	9IP; GSS1783UQ STRUT-LIFT
FIRE FIGHTING EQUIPMENT	2	9IP; GSS1783UQ STRUT-LIFT
SIDE COMPARTMENT BODY	1	5SC; GAUGE, CROSSFIRE
WIPER BLADES	2	9AP; MAN SAVER 20"
FUEL SYSTEM	1	9IP; EXTENDA GUN SWITCH
OIL FILTER	1	NONSTOCK; FREIGHT CHARGE
LIGHTING SYSTEM	1	5FF; SWITCH
REPAIR FROM PM - COOLING SYSTEM	14	9AP; HEAT SENSOR LADDER LABELS
REPAIR FROM PM - ENGINE	2	9IP; GSS1783UQ STRUT-LIFT
DOOR ALARM OR OTHER WARNING	2	9IP; BULB QUARTZ HAL. 12V 150W
	1	BK; SWITCH
	-2	1WL; LIGHT LED RED TIR6
	2	1WL; LIGHT LED RED TIR6
	2	1WL; LIGHT
	12	9AP; HEAT SENSOR LADDER LABELS

CSHOP-2017-484

Comments: **SPARE RESCUE AT 29 HEAD LIGHT OUT AND LIGHTS NOT WORKING**

Date Opened: 1-23-2017

Date Finished

1-26-2017

Meter 1 Reading:

58,868

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER HEADLIGHTS LOW BEAM	1	LMP; HALOGEN LAMP
---	---	-------------------

Service Requests:

01/21/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW
VEHICLE LIGHTS NOT WORKING, RIGHT FRONT HEADLIGHT WENT OUT LAST NIGHT ON A CALL.

CSHOP-2017-5044

Comments: **SPARE RESCUE AT 21 USED AS A TRUCK FOR LOOSE TIRE MOUNTING BILLING PURPOSE ONLY**

Date Opened: 8-28-2017

Date Finished

10-12-2017

Meter 1 Reading:

63,146

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES
TIRE

Service Requests:

08/26/2017 STARTER / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE TAKES MULTIPLE ATTEMPTS TO START. ST21

Asset Work Order History 10155554

CSHOP-2017-5110

Comments: **SPARE ENGINE AT 21**

Date Opened: 8-30-2017

Date Finished

12-14-2017

Meter 1 Reading:

63,525

TASKS PERFORMED

Q PARTS

FIRE FIGHTING EQUIPMENT
TANK-RESERVOIR
FUEL SYSTEM

1 5TN; TFT ROTATION LOCK INSERT

Service Requests:

08/30/2017

SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
MODERATE LEAK COMING FROM THE PUMP COMPARTMENT. UNKNOWN EXACT LOCATION.

CSHOP-2017-5250

Date Opened: 9-7-2017

Date Finished

9-7-2017

Meter 1 Reading:

63,146

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS
QUARTZ LIGHT

CSHOP-2017-5581

Date Opened: 9-26-2017

Date Finished

9-26-2017

Meter 1 Reading:

63,146

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-6033

Date Opened: 10-19-2017

Date Finished

10-19-2017

Meter 1 Reading:

63,146

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CHARGING SYSTEM

Service Requests:

10/18/2017

ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS. CHARGER FOR SAFETY PAD NOT WORKING. SPOKE TO ROAD MECHANIC ON PHONE WHEN HE
CALLED ABOUT LIGHT BOXES NOT WORKING ON RESCUE.

Asset Work Order History 10155554

CSHOP-2017-6191

Comments: **SPARE ENGINE AT STATION 17**

Date Opened: 10-27-2017 Date Finished 10-27-2017 Meter 1 Reading: 63,146

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR ALARM OR OTHER WARNING

Service Requests:

10/26/2017 ALARMS / 28: IMPROPERLY INSTALLED / INSPECT
ALARM SIGNALS PRESSURE ALARM GOING OFF ON THE PUMP PANEL ALSO DIFFICULT TO START AT TIMES BUT VOLTAGE IS READING 14.1

CSHOP-2017-7370

Date Opened: 12-27-2017 Date Finished 1-24-2018 Meter 1 Reading: 64,084

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
ENGINE AND ACCESSORIES
ELECTRICAL

Service Requests:

12/23/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SHORELINE WAS CAUGHT IN REAR PASSENGER REAR DOOR AND FAILED TO DETACH AND NEEDS TO BE REATTACHED.

12/28/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
PRIMER HANDLE ON PUMP PANEL NOT WORKING. THERE IS ALSO ONE ON OFFICER SIDE THAT IS WORKING SO STILL ABLE TO PULL DRAFT WITH THE TRUCK IF NEEDED

12/28/2017 ENGINE / 18: LEAKING / REPAIR
TRUCK IS MAKE A SQUEAKING SOUND PERIODICALLY WHILE DRIVING, SOUNDS LIKE A BELT. VISUAL INSPECTION OF BELTS SHOW NO FRAYING. NEED 2 JUGS OF COOLANT FOR THE STATION AS WELL, COOLANT A LITTLE LOW AND NO COOLANT HERE

CSHOP-2017-85

Comments: **A-INSPECTION**

Date Opened: 1-4-2017 Date Finished 1-5-2017 Meter 1 Reading: 58,515

TASKS PERFORMED

NO PARTS USED

A INSPECTION

CSHOP-2018-1761

Date Opened: 3-28-2018 Date Finished 6-7-2018 Meter 1 Reading: 66,060

TASKS PERFORMED

Q PARTS

REAR TIRES

6 NTH; EXTENSN
3 NTH; EXTENSN

Asset Work Order History 10155554

CSHOP-2018-2232

Comments: **E27**

Date Opened: 4-23-2018

Date Finished

5-10-2018

Meter 1 Reading:

65,673

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE FIGHTING EQUIPMENT
ELECTRICAL
AIR SYSTEM
DOOR ALARM OR OTHER WARNING

1 9AP; 2
-1 2IH; VALVE
1 2IH; VALVE
1 9HD; 3 WAY SOLENOID
1 MBI; AIR PRESSURE VALVE
6 5SC; ROLLER

Service Requests:

04/23/2018 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS. DECK GUN ALARM GOING OFF. AUDIBLE AND VISUAL

04/27/2018 ALARMS / 11: BINDS/STICKS / ADJUST
ALARM SIGNALS DOOR AJAR ALARM GOING OFF

CSHOP-2018-2266

Comments: **SPARE ENGINE AT 27**

Date Opened: 4-25-2018

Date Finished

4-25-2018

Meter 1 Reading:

64,997

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STROBE LIGHTS

Service Requests:

04/24/2018 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
LIGHT BAR EMERGENCY SIGNALS INOP IN THE CENTER OF THE RUN

CSHOP-2018-2371

Comments: **E27**

Date Opened: 5-1-2018

Date Finished

5-15-2018

Meter 1 Reading:

65,673

TASKS PERFORMED

NO PARTS USED

FIRE FIGHTING EQUIPMENT
EQUIPMENT MOUNTING BRACKETS

Service Requests:

04/30/2018 SERVICE REQUEST / 38: SHORTED / EXCHANGE - REBUILT
THE TIC CHARGER IS NOT CHARGING, THANK YOU,

05/02/2018 SERVICE REQUEST / 44: WORN / REPAIR
HOSE CLAMP VELCRO NEEDS TO BE REPLACED - CANNOT ATTACH HOSE CLAMP TO BACK OF TRUCK

Asset Work Order History 10155554

CSHOP-2018-2594

Comments: **E27**

Date Opened: 5-11-2018

Date Finished

5-24-2018

Meter 1 Reading:

65,673

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

05/11/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

TYPE PROBLEM INTO DESCRIPTION: BACK UP E27 HAS AIR LEAK, MOST NOTED IN REAR SUSPENSION. ENGINE RIDES "HEAVY" ON REAR AXLE UNTIL PRESSURE BUILDS UP.

CSHOP-2018-2743

Comments: **E27**

Date Opened: 5-17-2018

Date Finished

5-24-2018

Meter 1 Reading:

65,673

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

Service Requests:

05/17/2018

LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT

VEHICLE LIGHTS NOT WORKING...OFFICER SIDE TELESCOPING SCENE LIGHT HAS ONE BULB OUT

CSHOP-2018-292

Comments: **SPARE ENGINE AT 58**

Date Opened: 1-12-2018

Date Finished

2-6-2018

Meter 1 Reading:

64,084

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

Service Requests:

01/12/2018

ALARMS / 18: LEAKING / REPAIR

ALARM SIGNALS, OFFICERS SIDE QUARTZ LIGHT ALARM. LIGHT IS POSITIONAL TO ALARM SOUNDING. SHORT?

Asset Work Order History 10155554

CSHOP-2018-3186

Comments: **POSSIBLE CAB AIR BAG OR VALVE LEAKING ALSO DUE FOR PM**

Date Opened: 6-7-2018

Date Finished

7-27-2018

Meter 1 Reading:

66,177

TASKS PERFORMED

Q PARTS

FOAM SYSTEM	1	5TN; ESP12MOTORPRIMERPUMPWPVGPIMERVLV
PRIMING PUMP FIRE PUMP	1	NTH; REGULATR
FIRE PUMP	1	5AB; 3- 3.5 BALL KIT COMPOSITE
DISCHARGE GAUGE	1	5AB; 3- 3.5 BALL KIT COMPOSITE
HOSE BED BODY	2	9IP; 529-0080-10-0 1 1/4 ANODE KIT
SIDE COMPARTMENT BODY	1	5AB; 15BALLVALVESUBASSYSS
WIPER BLADES	2	9IP; SCREEN6IN
ENGINE AND ACCESSORIES	2	5TN; GAUGE
SPOT LIGHTS	1	TWD; SWITCH
PARK-CLEARANCE LIGHTS	4	5SC; HELMET/HEADSET HOOK
TIRES ALL	1	9IP; LATCH TRIGER W/O LOCK
AIR SYSTEM	1	5TN; SWITCH DOOR DPST NC MOM
HVAC SYSTEM	2	1AN; WIPER BLADE 24 IN
	1	2FL; OIL PRESSURE SWITCH
	-2	9IP; BULB QUARTZ HAL. 12V 150W
	2	9IP; BULB QUARTZ HAL. 12V 150W
	1	LMP; LAMP
	2	9IP; EJG120V-750WC BULB
	2	LMP; LAMP

CSHOP-2018-3611

Date Opened: 6-26-2018

Date Finished

6-26-2018

Meter 1 Reading:

66,060

TASKS PERFORMED

NO PARTS USED

STARTER

VENDOR? CUMMINS POWER SOUTH LLC

CSHOP-2018-3800

Date Opened: 7-5-2018

Date Finished

7-10-2018

Meter 1 Reading:

66,142

TASKS PERFORMED

Q PARTS

PM SERVICE C	1	FIL; FUEL WATER SEPARATOR
	4	1AD; BATTERY 31 SERIES
	1	FIL; NAPAGOLD OIL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	25	4PC; 15W40 PREMIUM BLUE OIL
	10	NTH; ADAPPLG

Asset Work Order History 10155554

CSHOP-2018-4458

Comments: **SPARE ENGINE AT 46**

Date Opened: 8-9-2018

Date Finished

8-10-2018

Meter 1 Reading:

66,195

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
INSTRUMENTS-GAUGES-METERS

Service Requests:

08/09/2018

ALARMS / 18: LEAKING / REPAIR

ALARM SIGNALS DOOR ADJAR ALARM DOES NOT STOP BUZZING WHILE DRIVING THE VEHICLE.

CSHOP-2018-5692

Comments: **E34**

Date Opened: 10-9-2018

Date Finished

10-12-2018

Meter 1 Reading:

67,778

TASKS PERFORMED

NO PARTS USED

BRAKES
HVAC SYSTEM

Service Requests:

10/06/2018

A/C / 18: LEAKING / REPAIR

A/C REAR COMPRESSOR IS NOT WORKING PROPERLY, MAKES LOUD NOISE ON AND OFF

CSHOP-2018-5805

Comments: **E34**

Date Opened: 10-15-2018

Date Finished

11-1-2018

Meter 1 Reading:

68,175

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
CAB-INTERIOR ACCESSORIES

Service Requests:

10/13/2018

SERVICE REQUEST / 18: LEAKING / REPAIR

SPARE ENGINE AT STATION 34 HAD THE LETTERS/CODE "EP" SHOWING UP INTERMITTENT WHILE PUMPING.

Asset Work Order History 10155554

CSHOP-2018-6077

Date Opened: 10-25-2018 Date Finished 11-5-2018 Meter 1 Reading: 68,257

COOLANT LEAK

TASKS PERFORMED

Q PARTS

COOLING SYSTEM

1 NBH; SERPENTINE BELT
1 2CU; PULLEY
1 9HY; HOSE MADE
1 9IP; COOLER 14032
1 NBH; V-BELT
1 FIL; NAPA COOLANT FILTER
1 TFW; HD WATER PUMP
5 9OC; COOLANT
1 NBH; V-BELT
1 NBH; TENSIONER-HEAVY DUTY
1 2CU; THERMOSTAT

CSHOP-2018-6694

Comments: **EXTENDED CRANK TIMES WHEN STARTING PUMP TEST FOLLOW-UP REPAIRS MASTER DRAIN VALVE LEAKED DURING TEST LOW ON COOLANT, NOT SHOWING IN SIGHT GLASS DISCHARGE VALVES DIFFICULT TO OPEN AND CLOSE UNDER PRESSURE, NEED LUBED OR REBUILT RELIEF VALVE OR MANIFOLD LEAKING ON THE RIGHT SIDE**

Date Opened: 11-27-2018 Date Finished 12-28-2018 Meter 1 Reading: 68,310

TASKS PERFORMED

Q PARTS

FIRE PUMP PLUMBING
FIRE APPARATUS
COOLING SYSTEM
PARK-CLEARANCE LIGHTS
CRANKING SYSTEM
HVAC SYSTEM

1 9IP; SPRINGVALVE QG RELIEF VALVE
1 5HP; HALE 2.5 VALVE REPAIR KIT
1 5TN; QG RELIEF VALVE KIT
2 LIT; LED M C LAMP
2 LIT; LED M C LAMP
1 BK; PTEX ULTRA BLACK 30Z
1 TEM; FILTER DRIER
1 9HY; HOSE MADE
2 9XX; 134A 10194654
1 TEM; NEW COMP

CSHOP-2018-7365

Comments: **DECK WARNING LIGHT**

Date Opened: 12-28-2018 Date Finished 1-8-2019 Meter 1 Reading: 68,310

TASKS PERFORMED

Q PARTS

PUMP PANEL
BODY EXTERIOR
DOOR ALARM OR OTHER WARNING

2 TWD; CAP/NUT
1 9AP; DETAIL 10155554
1 GRO; SWITCH

Asset Work Order History 10155554

CSHOP-2019-1023

Date Opened: 2-25-2019 Date Finished 3-6-2019 Meter 1 Reading: 69,797

NO PUMP THROTTLE

TASKS PERFORMED

Q PARTS

THROTTLE CONTROLS

1 NW; FUSE HOLDER
1 2FR; FRC THROTTLE EXCEL
1 5SC; D-DECK ELEC HAND THROTTLE
12 9AP; BRAKE CLEAN
1 9AP; SORBENT PAD

Service Requests:

02/25/2019 SERVICE REQUEST / 12: BROKEN / INSTALLED NEW PUMP THROTTLE
INOPERABLE PUMP THROTTLE NO POWER TO THE THROTTLE

CSHOP-2019-1284

Date Opened: 3-11-2019 Date Finished 4-12-2019 Meter 1 Reading: 70,274

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 2FL; CAB AIR BAG
1 9IP; 18-2108 FIVE BLADE FAN 3382
2 TEM; BLOW/MOT
1 2RD; FILTER, 17.5X5.5, MASTER PK (2)
4 9XX; 134A 10194654

Service Requests:

03/09/2019 A/C / 18: LEAKING / REPAIR
A/C ISSUE REAR AC NOT BLOWING COLD AT ALL BAD COMPRESSOR. FRONT AC BLOWS COOL BUT VERY LOW ON FAN SPEED.

CSHOP-2019-1384

Comments: **SPARE ENGINE AT 26**

Date Opened: 3-14-2019 Date Finished 3-28-2019 Meter 1 Reading: 70,179

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
FUEL GAUGE

Service Requests:

03/14/2019 FUEL / 12: BROKEN / EXCHANGE - NEW
LOW FUEL/OUT OF FUEL AT STATION 26 THE ENGINE 10155554 FUEL GAUGE IS NOT WORKING .

CSHOP-2019-1731

Date Opened: 4-4-2019 Date Finished 4-4-2019 Meter 1 Reading: 70,225

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

Asset Work Order History 1015554

CSHOP-2019-1798

Comments: **SPARE ENGINE AT 55**

Date Opened: 4-8-2019

Date Finished

5-13-2019

Meter 1 Reading:

70,335

TASKS PERFORMED

Q PARTS

FOAM SYSTEM

1

9IP; XE-IO3100PT3-S0B 600 TRANSDUCER INT

DISCHARGE GAUGE

1

5TN; GAUGE, 3.5 0-400 WH

FIRE APPARATUS

1

5TN; GAUGE 3.5 CLASS1 -30/400

TANK-RESERVOIR

1

5AB; 3- 3.5 BALL KIT COMPOSITE

QUARTZ LIGHT

AIR SYSTEM

Service Requests:

04/08/2019

SERVICE REQUEST / 12: BROKEN / REPAIR

PUMP PANEL MASTER DISCHARGE GAUGE GIVING INACCURATE READINGS. DIGITAL GAUGE FLUCTUATES DRASTICALLY IN ITS READINGS.

04/08/2019

SERVICE REQUEST / 12: BROKEN / REPAIR

DRIVER SIDE TELESCOPIC SCENE LIGHT NOT WORKING.

04/08/2019

SERVICE REQUEST / 18: LEAKING / REPAIR

NEED TO HAVE WATER TANK CHECKED. TRUCK LEAKING A LOT OF WATER WHILE MOVING.

CSHOP-2019-2732

Date Opened: 5-28-2019

Date Finished

6-6-2019

Meter 1 Reading:

70,335

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

4

5SC; BUCKLEASSYWSTRAPS

HOSE BED BODY

2

LIT; LED M C LAMP

LIGHTING SYSTEM

2

9AP; HORN KIT, PAI, 3390-1094

BRAKES

2

2FR; COVER, SAFETY BAR 18"

AIR HORN

CAB STEP

CSHOP-2019-3039

Date Opened: 6-12-2019

Date Finished

6-13-2019

Meter 1 Reading:

70,459

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

AIR HORN

CSHOP-2019-3177

Date Opened: 6-19-2019

Date Finished

7-8-2019

Meter 1 Reading:

70,517

TASKS PERFORMED

NO PARTS USED

A INSPECTION

Asset Work Order History 10155554

CSHOP-2019-3207

Date Opened: 6-20-2019 Date Finished 6-26-2019 Meter 1 Reading: 70,497

TASKS PERFORMED

Q PARTS

PM SERVICE C

1 TWD; AD-9KIT MINOR
1 FIL; FUEL WATER SEPARATOR
1 TWD; AD-9KIT
1 2DD; FILTER KIT, TRANS, SUMP 4"
1 FIL; NAPAGOLD AIR FILTER
1 BK; RADIATOR CAPS
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA COOLANT FILTER
1 5HP; HALERELIEFVALVESTRAINER
1 FIL; NAPA HYDRAULIC FILTER

CSHOP-2019-3371

Comments: **REPAIRS FROM PM NEEDED SEE WORK ORDER 2019-3207 FILE SHOWS INSPECTION REPORT.**

Date Opened: 6-27-2019 Date Finished 7-1-2019 Meter 1 Reading: 70,517

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - BRAKES

2 2GU; SLACKADJUSTERKIT
2 TWD; BRAKEDRUM
-2 TWD; SLACK ADJUSTER KIT
2 TWD; SLACK ADJUSTER KIT
-2 TWD; BRAKE DRUM
2 TWD; BRAKE DRUM
12 9AP; BRAKE CLEAN
2 MBI; GRIP/KIT

Service Requests:

06/26/2019 BRAKES / 44: WORN / EXCHANGE - NEW
BRAKES DOES NOT PULL OR DRAG BUT PASSENGER SIDE REAR BREAK DRUMS ARE MORE THAN 50% WORN

CSHOP-2019-4388

Date Opened: 8-19-2019 Date Finished 9-12-2019 Meter 1 Reading: 71,279

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 LMP; LAMP

Service Requests:

08/18/2019 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
SIDE SCENE LIGHTS NOT WORKING

08/31/2019 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
TYPE PROBLEM INTO DESCRIPTION RIGHT TELESCOPE LIGHT REMAINS ON CONSTANTLY

Asset Work Order History 10155554

CSHOP-2019-5052

Date Opened: 9-25-2019 Date Finished 9-30-2019 Meter 1 Reading: 71,615

TASKS PERFORMED

NO PARTS USED

DOOR ALARM OR OTHER WARNING

CSHOP-2019-5069

Date Opened: 9-25-2019 Date Finished 9-30-2019 Meter 1 Reading: 71,615

TASKS PERFORMED

Q PARTS

BATTERY

4 1AD; BATTERY GROUP 31

Service Requests:

09/25/2019 STARTER / 12: BROKEN / EXCHANGE - NEW
VEHICLE WILL NOT START, MECHANIC CAME AND SWAPPED OUT BATTERIES AT STATION 34.

CSHOP-2019-5161

Comments: **COOLANT NEEDS TO BE ADDED EVERY COUPLE DAYS ALSO LOW P/S FLUID LET ME KNOW IF YOU NEED ME TO SEND ALEX THANKS**

Date Opened: 10-1-2019 Date Finished 10-3-2019 Meter 1 Reading: 71,615

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT

1 9IP; IMMF11358A SEAT BELTS

Service Requests:

10/01/2019 RADIATOR / 18: LEAKING / REPAIR
COOLANT FLUID LEAK

CSHOP-2019-518

Comments: **SPARE ENGINE AT 53**

Date Opened: 1-28-2019 Date Finished 1-30-2019 Meter 1 Reading: 68,800

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

01/28/2019 SERVICE REQUEST / 18: LEAKING / REPAIR
VEHICLE'S ON BOARD HALO FOAM SYSTEM IS NOT OPERATING .

CSHOP-2019-5375

Date Opened: 10-11-2019 Date Finished 10-11-2019 Meter 1 Reading: 72,105

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10155554

CSHOP-2019-6083

Date Opened: 11-20-2019 Date Finished 1-7-2020 Meter 1 Reading: 72,659

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
LIGHTING SYSTEM
GLOVE BOX
HEATING AND VENTILATION

2 9IP; BULB QUARTZ HAL 12V 150W
3 2FL; VENT DEFROST DASH

CSHOP-2019-6136

Comments: **SPARE AT 52**

Date Opened: 11-25-2019 Date Finished 1-7-2020 Meter 1 Reading: 72,659

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

11/22/2019 LIGHTS / 19: LOOSE / INSPECT
LEFT (DRIVER SIDE) TELESCOPE LIGHT BULB NOT WORKING

CSHOP-2019-6247

Date Opened: 12-2-2019 Date Finished 2-20-2020 Meter 1 Reading: 73,803

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
SCBA BRACKETS
FIRE FIGHTING EQUIPMENT
FIRE PUMP CONTROLS
FIRE PUMP
SPOT LIGHTS
CHARGING SYSTEM
AIR SYSTEM
SIREN

3 6ZA; EZO LATCH ASSY
1 9IP; XE IO3100PT3 S0B 600 TRANSDUCER INT
1 2FR; KIT THROTTLE EXCEL 200 CUM IS J1939
-10 9OC; DELO SYN GL5 GEAR OIL QTS
10 9OC; DELO SYN GL5 GEAR OIL QTS
10 9IP; GEAR OIL SYN QT
2 5HP; SWITCH GEAR SHIFT
1 5HP; HALE QG RELIEF VALVE KIT
1 6KU; COVER, ROUND, RED
1 6KU; COVER ROUND WHITE AUTO EJECT
2 2FL; CAB AIR BAG
1 2FL; CAB LEVEL VALVE
1 1WL; SIREN AMPLIFIER

Service Requests:

12/02/2019 SERVICE REQUEST / 15: FOREIGN MATERIAL / REPAIR
SPARE ENGINE AT STATION 52. PUMP PANEL ELECTRIC THROTTLE INTERMITTENTLY WORKING. UNABLE TO BYPASS WITH MANUALLY THROTTLE IN CAB. HAVE COMPLETELY SHUT THE TRUCK DOWN AND THE MASTER SWITCH AND STILL UNABLE TO THROTTLE UP WITH PUMP PANEL ELECTRIC THROTTLE. ONLY FIX IT TO PULL THE FUSE UNDER PANEL AND ELECTRICAL CONNECTION IS STILL INTERMITTENT. "THROTTLEXCEL" ELECTRIC THROTTLE ON PANEL HAS POWER TO IT, BUT THE GREEN "THROTTLE READY" LIGHT DOES NOT COME ON OR FLASHES.

CSHOP-2020-3178

Date Opened: 6-22-2020 Date Finished 6-23-2020 Meter 1 Reading: 73,951

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

Asset Work Order History 10155554

CSHOP-2020-3292

Date Opened: 6-22-2020 Date Finished 6-23-2020 Meter 1 Reading: 73,951

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2020-3813

Date Opened: 7-22-2020 Date Finished 7-22-2020 Meter 1 Reading: 73,953

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-4578

Date Opened: 9-2-2020 Date Finished 9-30-2020 Meter 1 Reading: 73,953

BATTERY BOX SLIDES BROKE

TASKS PERFORMED

Q PARTS

BATTERY TRAY

1 5AH; DRAWER SLIDES 18
1 8HD; CORD ELECTRIC 100
1 9IP; CABLE BATT NEG

CSHOP-2020-744

Comments: **SPARE ENGINE AT 24**

Date Opened: 2-10-2020 Date Finished 7-16-2020 Meter 1 Reading: 73,953

EXTEND A GUN ALARM WHEN OFF WHEN YOU PUSH OFF PARK BRAKE

TASKS PERFORMED

Q PARTS

WIPER BLADES
ENGINE AND ACCESSORIES
BATTERY
TIRES & WHEELS
AIR SYSTEM
SEAT BELTS
SEAT FRONT
DOOR ALARM OR OTHER WARNING

-2 1AN; WIPER BLADE 24 IN
2 1AN; WIPER BLADE 24 IN
2 1AN; 1AN
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
26 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; FUEL WATER SEPARATOR
4 1AD; 1000 CCA 31 SERIES BATTERY
1 MBI; VALVE
1 9IP; IMMF11358A SEAT BELTS

Service Requests:

02/07/2020 SERVICE REQUEST / 18: LEAKING / REPAIRED
AIR LEAK IN FRONT TANK - DROPS TO ALARM LEVEL WITHIN 30 MINUTES

Asset Work Order History 1015554

CSHOP-2020-943

Date Opened: 2-18-2020 Date Finished 3-27-2020 Meter 1 Reading: 73,885

TASKS PERFORMED

Q PARTS

FOAM SYSTEM
AIR SYSTEM

1 5HP; FEED BACK SENSOR

Service Requests:

02/16/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
FOAM SYSTEM IS NOT WORKING. ATTEMPTED TO FLUSH MULTIPLE TIMES WITH NO CHANGE.

RADIO-2018-221

Comments: **REMOVAL OF 10141407, INSTALL OF 10208398 INTO SPARE ENGINE 7 - 1015554**

Date Opened: 3-30-2018 Date Finished 3-30-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

03/30/2018 RADIO / /
REMOVAL & INSTALL OF MOTOROLA MOBILE RADIO INTO SPARE ENGINE 7

RADIO-2019-722

Date Opened: 8-30-2019 Date Finished 8-30-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

08/29/2019 RADIO / /
RADIO ISSUES- VHF RADIO NOT WORKING LOW BATTERIES ON THE ENGINE. RADIO TESTED OK.

RADIO-2019-723

Comments: **FIXED**

Date Opened: 8-31-2019 Date Finished 8-31-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

08/17/2019 RADIO / /
THIS IS A SPARE ENGINE FOR STATION 20. TESTED VHF RADIOS TODAY AS PART OF HURRICANE PREP AND VHF RADIO ON THIS TRUCK HAS A TON OF STATIC AND YOU CANNOT UNDERSTAND THE TRANSMISSION FROM THE SENDER. TRANSMISSIONS APPEAR TO HAVE BEEN CLEAR SENDING FROM THIS RADIO JUST THE SPEAKER WHEN RECEIVING THE TRANSMISSION VERY MUFFLED