



7/2/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V4193

In Date: 08/31/2006
Close Date: 09/08/2006

Meter Reading: 340.00

Problem?

TINT WINDOWS AT SIXTY MIN R54

Task performed:

	Parts	Quantity
	NO PARTS USED	

Vendor?: 60 MINUTE

Workorder: V4338

In Date: 09/08/2006
Close Date: 09/13/2006

Meter Reading:

Problem?

SHORE LINE BECOMES HOT, THEN SMOKES WHEN PLUGGED INTO NEW TRUCK. R54

Task performed:

	Parts	Quantity
	NO PARTS USED	

Workorder: V4171

In Date: 08/29/2006
Close Date: 09/15/2006

Meter Reading: 327.00

Problem?

MOUNT EQUIPMENT, R-54

Task performed:

	Parts	Quantity
	14-7014HGR-1 HELMET HOOK	3
	5269LPVM-5 SM MOUNT	3
	LPVM-7LG MOUNT	2

Workorder: V4389

In Date: 09/11/2006
Close Date: 09/25/2006

Meter Reading:

Problem?

water enters pt.comp.through rear door gasket.R54

Task performed:

	Parts	Quantity
1. READJUST DOOR PINS.	NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V4900

In Date: 10/15/2006

Meter Reading:

Close Date: 10/25/2006

Problem?

Driver and Drivers rear power windows are not working R-54

Task performed:

Parts

Quantity

1. INSTALLED RESETTABLE FUSE.

516595MINI 25 AMP CB211-25 CIRCUIT BREAKER

6

Workorder: V4787

In Date: 10/07/2006

Meter Reading:

Close Date: 10/26/2006

Problem?

FRONT PASSENGER AIR SEAT DOES NOT FUNCTION R54

Task performed:

Parts

Quantity

1. TRAVELED TO STN 54. FOUND AIR LINE PINCH UNDER SEAT BELT BRACKET REMOVE LINE AND REPAIRED.

NO PARTS USED

Workorder: V4789

In Date: 10/07/2006

Meter Reading:

Close Date: 10/26/2006

Problem?

VEHICLE EMITS A BURNING SMELL (UNKNOWN IF TRANSMISSION OR BRAKES) AFTER USE. R54

Task performed:

Parts

Quantity

1. TRAVELED TO STN 54. ROAD TESTED AND FOUND NO PROBLEMS. TOLD D/O TO CALL SHOP IF ANY FURTHER PROBLEMS WERE NOTED.

NO PARTS USED

Workorder: V4788

In Date: 10/07/2006

Meter Reading:

Close Date: 11/03/2006

Problem?

VEHICLE ELECTRICAL DISPLAY KEEPS "SHOWING SHORT CIRCUIT N4" R54

Task performed:

Parts

Quantity

1. AF WILL LOOK AT TRUCK.

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V4786

In Date: 10/07/2006

Meter Reading:

Close Date: 11/06/2006

Problem?

PASSENGER SIDE EQUIPMENT COMPARTMENT DOOR DOES NOT CLOSE PROPERLY, STRIKER NOT ALIGNED. R54

Task performed:

Parts

Quantity

1. TRAVELED TO STN 54. INSTALLED NEW STRIKER PIN.

STP594115449 STRIKER PIN

3

Workorder: V5536

In Date: 11/26/2006

Meter Reading:

Close Date: 11/29/2006

Problem?

Both main and auxilliary A/C are not blowing cold air. R54

Task performed:

Parts

Quantity

1. TRAVELED TO STN 54. RECHARGED SYSTEM AND CHECKED FOR LEAKS. NO LEAKS FOUND.

NO PARTS USED

Workorder: V5992

In Date: 12/28/2006

Meter Reading:

497.00

Close Date: 01/03/2007

Problem?

cab a/c blows hot. R54

Task performed:

Parts

Quantity

1. A/C leak at condensor

NO PARTS USED

Workorder: V6013

In Date: 12/29/2006

Meter Reading:

Close Date: 01/03/2007

Problem?

burning smell from rear R54

Task performed:

Parts

Quantity

1. Found left rear inner tire off rim had all six tires replaced

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V5924

In Date: 12/22/2006
Close Date: 01/05/2007

Meter Reading: 411.10

Problem?

Driver side small rectangle compartment on the box cab. Left hinge broke upon opening the compartment door. R54

Task performed:

- 1. Replaced latch on compt.

Parts

HLD44614446 1/4 LATCH

Quantity

3

Workorder: V6163

In Date: 01/08/2007
Close Date: 01/11/2007

Meter Reading: 537.40

Problem?

DASH A/C IN R54 CAB IS BLOWING WARM

Task performed:

- 1. Replaced a/c fitting supplied by red dot

Parts

NO PARTS USED

Quantity

Workorder: V6200

In Date: 01/09/2007
Close Date: 01/16/2007

Meter Reading: 537.40

Problem?

-when driving, noise is heard and felt when hitting the usual bumps in the roadways. -rear passenger side cab door does not close easily and prevents a potential safety issue. r54

Task performed:

- 1. Checked rear doors and found on problem with rear cab door
- 2. Checked for noise when hitting bumps no problem found

Parts

NO PARTS USED

Quantity

Workorder: V6541

In Date: 01/30/2007
Close Date: 02/01/2007

Meter Reading: 676.00

Problem?

R54 found with low engine oil. Remainder of station supply used to fill oil. Levels are still low and station is out of oil to refill.

Task performed:

- 1. Dropped off oil to sta54

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V6015

In Date: 12/29/2006 Meter Reading: 5,351.00
Close Date: 02/05/2007

Problem?

replace tires at sta 54 callaghan ent

Task performed:

Replace tires at Sta54 Callaghan Ent

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN ENT

Workorder: V6667

In Date: 02/08/2007 Meter Reading: 234.30
Close Date: 02/14/2007

Problem?

Engine coolant below the "LOW LEVEL" line. r54

Task performed:

Refilled to full will monitor. Pressure tested

Parts

Quantity

NO PARTS USED

Workorder: V6881

In Date: 02/22/2007 Meter Reading: 8,012.00
Close Date: 02/27/2007

Problem?

repair a/c r54

Task performed:

1. TRAVELED TO STN 54. CLEANED CONDENCER
FANS ON A/C UNIT.

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V7136

In Date: 03/09/2007

Meter Reading: 8,794.00

Close Date: 03/15/2007

Problem?

B inspection and related repairs R54

Task performed:

1. B Inspection
2. Replaced belts
3. Serviced air dryer
4. Repaired leak at trans cooler line. Repaired hose bracket

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
285147HOSE	1
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
921LIGHT BULB	1
9550 BELT	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	2
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V7222

In Date: 03/15/2007

Meter Reading: 0.09

Close Date: 03/19/2007

Problem?

Check radiator fan due to overheating when truck is at an idle in neutral. alarm goes off in cab. R54

Task performed:

- Reconnection air line to fan

Parts	Quantity
NO PARTS USED	

Workorder: V7606

In Date: 04/09/2007

Meter Reading: 10,387.00

Close Date: 04/11/2007

Problem?

coolant level is below "low" line when warmed up. r54

Task performed:

1. Added coolant and checked for leaks ok
2. Checked rear a/c found no problem

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V8564

In Date: 06/04/2007
Close Date: 06/14/2007

Meter Reading: 12,777.00

Problem?

TAIL LIGHTS 10-7 R54

Task performed:

Parts

Quantity

1. Traced out problem with tail lights not working - found bad connection in rear

NO PARTS USED

Workorder: V8623

In Date: 06/06/2007
Close Date: 06/26/2007

Meter Reading: 13,079.00

Problem?

repair /ac r54

Task performed:

Parts

Quantity

1. Recharged system and checked temp

NO PARTS USED

Workorder: V9067

In Date: 06/29/2007
Close Date: 07/06/2007

Meter Reading: 13,716.00

Problem?

damage to comp door r54

Task performed:

Parts

Quantity

1. Adjusted side door due to damage

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V9097

In Date: 07/02/2007
Close Date: 07/06/2007

Meter Reading: 13,716.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

1. B INSPECTION
2. DOOR HINGE BENT. REMOVE DOOR AND REPLACE HINGE AND HOLD OPEN.
3. REPLACE GRILL MOUNT.
4. CHECKED ALL TIRES. NECESSARY TO REPLACE ALL TIRES.
5. CHANGED ALL FOUR REAR TIRES. CHECK OIL, TRANS FLUID, COOLANT-OK. ROAD TEST-OK.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
42809AIR FILTER M2	1
516593MINI 15 AMP CB211-15 CIRCUIT BREAKER	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
HLD374211 IN HOLD-OPEN 30LB	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S693AIR CHUCK	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V9101

In Date: 07/02/2007
Close Date: 08/01/2007

Meter Reading: 13,716.00

Problem?

RPLACE TIRES AT CALLAGHAN ENT R54

Task performed:

Replace tires - Callaghan

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN

Workorder: V9896

In Date: 08/14/2007
Close Date: 08/30/2007

Meter Reading: 15,657.00

Problem?

park brake wont release r54

Task performed:

1. road tested & chkd all conn & tested ok
2. Air pack falling out of seat; readj all air pack brkts

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V10040

In Date: 08/22/2007
Close Date: 09/11/2007

Meter Reading: 1,518.00

Problem?

BRAKE LIGHT ON DASH KEEPS COMING ON AND ALARM SOUNDS WHILE VEHICLE IS IN DRIVE AND PARKING BRAKE IS NOT APPLIED r54

Task performed:

1. Replc air valve
2. Rear cab A/C warm; recharged unit

Parts	Quantity
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	1

Workorder: V10431

In Date: 09/13/2007
Close Date: 09/24/2007

Meter Reading: 1,629.00

Problem?

Front (Dashboard) A/C is not working. No air is blowing. R54

Task performed:

1. DROVE TO STA 54, R54 CAB AC FAN PLUG WAS LOOSE, REPAIRED PLUG AND R/R FILTER IN AC.

Parts	Quantity
VCC/36000006A/C FILTER CAB M2	1

Workorder: V10303

In Date: 09/07/2007
Close Date: 09/25/2007

Meter Reading: 15,791.00

Problem?

rear a/c 10-7

Task performed:

1. Traced out A/C leak and Recharged.

Parts	Quantity
NO PARTS USED	

Workorder: V10640

In Date: 09/24/2007
Close Date: 10/01/2007

Meter Reading: 17,284.00

Problem?

dash board fascia on passenger side is coming of of dash board. r54

Task performed:

1. REPAIRED DASH BOARD

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V10641

In Date: 09/24/2007
Close Date: 10/01/2007

Meter Reading: 17,284.00

Problem?

hand light bracket behind the driver seat is coming off the wall of rescue. r54

Task performed:

1. REINSTALLED HANDLIGHT CHARGER THAT WAS FALLING OFF
2. ADJUSTED AIR HORN

Parts

NO PARTS USED

Quantity

Workorder: V10770

In Date: 10/02/2007
Close Date: 10/03/2007

Meter Reading: 17,766.00

Problem?

REPAIR MAP LIGHT R54

Task performed:

1. INSTALLED NEW MAP LIGHT ON DASH

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1

Workorder: V6540

In Date: 01/30/2007
Close Date: 10/15/2007

Meter Reading: 676.00

Problem?

R54 engine coolant low.

Task performed:

1. Pressure tested system and topped off ok

Parts

NO PARTS USED

Quantity

Workorder: V10927

In Date: 10/10/2007
Close Date: 10/22/2007

Meter Reading: 1,739.00

Problem?

Front Cab A/C not blowing air! Rear Cab A/C works. R-54

Task performed:

1. found bad connection on blower motor. replaced/repaired and tested.
2. adjusted rear door latch. door hard to open.

Parts

S775COUPLER
S778COUPLING
VCC/35000003BLOWER MOTOR VCCT1000904A M2
VCC/36000006A/C FILTER CAB M2
VCC/83000038AC WIRE HARNESS
WKL7281LIGHT THINLINE

Quantity

2
2
1
1
1
1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V8716

In Date: 06/11/2007 Meter Reading: 1,261.10
Close Date: 10/25/2007

Problem?

alignment needed when it goes in for the next PM

Task performed:

PROBLEM NOTED FOR PM

Parts

NO PARTS USED

Quantity

Workorder: V11506

In Date: 11/07/2007 Meter Reading: 1,917.00
Close Date: 11/28/2007

Problem?

AIR CONDITIONING IN CREW CAB IS NOT FUNCTIONING. R54

Task performed:

Recharged A/C system j

Parts

NO PARTS USED

Quantity

Workorder: V11560

In Date: 11/11/2007 Meter Reading: 19,713.00
Close Date: 11/29/2007

Problem?

Back up camera not working R54

Task performed:

1. Front A/C blower not working removed blower motor and wiring harness and filter installed new motor and harness and filter.
2. Installed 3 hooks in cab.
3. Checked problem with back up cam found lose connection on back of vista.

Parts

NO PARTS USED

Quantity

Workorder: V11561

In Date: 11/11/2007 Meter Reading: 1,927.50
Close Date: 11/29/2007

Problem?

Hooks missing in cab R54

Task performed:

1. Drivers airride seat not working- repaired air line that was kinked.

Parts

14-7014HGR-1 HELMET HOOK

Quantity

5



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V11731

In Date: 11/23/2007
Close Date: 11/29/2007

Meter Reading: 1,992.30

Problem?

flash light mount behind driver is coming unattached, preventing flashlight from attaching. R54

Task performed:

Parts

Quantity

- 1. Replaced flashlight that was falling off...

NO PARTS USED

Workorder: V11980

In Date: 12/08/2007
Close Date: 12/12/2007

Meter Reading: 718.00

Problem?

R54 is in need of alignment as reported several months back. it pulls severly to the right. also R54 has a small oil leak.

Task performed:

Parts

Quantity

- 1. Travel to 54.
- 2. Found dip stick not fully inserted in tube, informed driver and LT.
- 3. Found not pulling enough to have alignment.

NO PARTS USED

Workorder: V11640

In Date: 11/16/2007
Close Date: 12/17/2007

Meter Reading: 20,017.00

Problem?

repair cab a/c r54

Task performed:

Parts

Quantity

VCC/35000003BLOWER MOTOR VCCT1000904A M2
VCC/83000038AC WIRE HARNESS

1
1

Workorder: V12123

In Date: 12/18/2007
Close Date: 12/31/2007

Meter Reading: 21,878.00

Problem?

R54 NEEDS OIL AT MIN NOW

Task performed:

Parts

Quantity

- 1. Dropped off oil for rescue.

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V9094

In Date: 07/02/2007

Meter Reading: 13,716.00

Close Date: 01/14/2008

Problem?

REPAIR DAMAGED COMP DOOR R54

Task performed:

Parts

Quantity

HNG1918HINGE 87 IN STAINLESS

1

Workorder: V13573

In Date: 02/28/2008

Meter Reading: 25,508.00

Close Date: 03/06/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

Parts

Quantity

- "B: inspection
- 1A assist with "B" inspection
- Replace front shocks
- Replace one marker light, repair 2 other marker lights
- Replace wiper blades
- Relocate battery cables that were hitting cross member
- Re-route dryer piping, hose rubbing on driveshaft
- Replace bracket on L rear tire for hose

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

15W40BSYN OIL BULK QTS

24

66406USE 65140 FRONT SHOCK RESCUE 10-12390-000

2

906-181-00-86OIL FILTER M2 SPINNER 57140

1

91-22WIPER BLADE

2

AMH-1AMH-1 VALVE EXTENSION

1

CLR9185109186-1500-10 MARKER LT. RED LED

1

CLR9185209186-1500-20 MARKER LT.AMBER LED

1

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

Workorder: V13030

In Date: 02/04/2008

Meter Reading: 24,041.00

Close Date: 04/14/2008

Problem?

replace tires at sta 54 callaghan

Task performed:

Parts

Quantity

- replace all 4 tires. checked tires all 4 are due.

NO PARTS USED

Replace tires at Stn54 - Callaghan (Completed 2/15/08)

j

Vendor?: CALLAGHAN



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V14570

In Date: 04/20/2008 Meter Reading: 28,013.00

Close Date: 05/09/2008

Problem?

PASSENGER SIDE DOOR OF PT COMPARTMENT (CREW ENTRY DOOR) PIN FELL OUT OF RETAINING ARM, DOOR SWIN WITH NO RESTRAINT. R54

Task performed:

	<u>Parts</u>	<u>Quantity</u>
Replc door spring that was broken. j	HLD374211 IN HOLD-OPEN 30LB	2

Workorder: V15104

In Date: 05/15/2008 Meter Reading: 29,113.00

Close Date: 06/10/2008

Problem?

REAR DOOR HANDLE FELL OFF, R-54

Task performed:

	<u>Parts</u>	<u>Quantity</u>
5-14 Repaired rear door handle that fell off	NO PARTS USED	

Workorder: V14417

In Date: 04/11/2008 Meter Reading: 2,197.20

Close Date: 06/17/2008

Problem?

SHOR LINE PORT DOES NOT FUNCTION, VEHICLE DOES NOT ACCEPT CHARGE AND ROOF A/C DOES NOT FUNCTION--SHORELINE HAS LIVE VOLTAGE (TESTED) R54

Task performed:

	<u>Parts</u>	<u>Quantity</u>
1. found breaker needed to be reset.	NO PARTS USED	

Workorder: V15762

In Date: 06/16/2008 Meter Reading: 30,583.00

Close Date: 06/25/2008

Problem?

belts out of alignment r54

Task performed:

	<u>Parts</u>	<u>Quantity</u>
1. Belts look ok at this time; chk belts on bracket ok. j	NO PARTS USED	
2. Driver said that truck pulls to right; may need alignment but tire may need replaced on front. j		



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V15668

In Date: 06/10/2008
Close Date: 07/01/2008

Meter Reading: 2,946.00

Problem?

NEED MODIFICATION FOR INSTALLATION OF NEW LARGER SHARPS CONTAINER IN PT COMPARTMENT. R54

Task performed:

1. cut out sharps box to fit new container
2. left rear door not opening from inside- readjusted door linkage

Parts

NO PARTS USED

Quantity

Workorder: V15757

In Date: 06/16/2008
Close Date: 07/01/2008

Meter Reading: 30,583.00

Problem?

on call a/c belt came off r 54

Task performed:

1. patient A/C belt is damaged, remove belt and install new belt. check unit . compressor operating good idle pulley and tensioner pulley both misaligned. need to properly align belts.

Parts

95609560 BELT

1

Quantity

Workorder: V16360

In Date: 07/14/2008
Close Date: 07/21/2008

Meter Reading: 3,055.00

Problem?

a/c blowing warm in pt compartment R54

Task performed:

1. Chk rear A/C; fnd no leaks; top off; R134S; cold at this time; may have been starter valve leak; tighten both; travel time from shop & repair. j

Parts

NO PARTS USED

Quantity

Workorder: V16553

In Date: 07/24/2008
Close Date: 07/30/2008

Meter Reading: 31,924.00

Problem?

repair paitent a/c r54

Task performed:

1. Clnd condensor fans & tested.
2. Air horns inop; adj air horns. j

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V17041

In Date: 08/14/2008
Close Date: 08/22/2008

Meter Reading: 32,825.90

Problem?

REAR A/C INOP, R-54

Task performed:

1. cleaned cond. fans recharged unit and tested
2. rear door hard to open readjusted rear door linkage

Parts

NO PARTS USED

Quantity

Workorder: V17804

In Date: 09/19/2008
Close Date: 09/30/2008

Meter Reading: 33,992.80

Problem?

UNIT WILL NOT START, R-54

Task performed:

no start-found batteries shorted out-replaced batteries

Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY
HP-31DBATTERY 950CCA HP-31D

Quantity

4
4

Workorder: V17974

In Date: 09/27/2008
Close Date: 10/07/2008

Meter Reading: 3,335.00

Problem?

R54 is requesting an scba bracket mounted in the tool compartment door for easy use by the driver.

Task performed:

- 1- AS PER BC-5 NOT INSTALLING BRACKET.
- 2- AIR HORN INOP- REPROGRAMED MODE AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V18560

In Date: 10/24/2008
Close Date: 10/27/2008

Meter Reading: 35,685.00

Problem?

n call r54 repair door

Task performed:

Rear door not opening; rem door panel & adj linkage.
j

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V18727

In Date: 10/30/2008

Meter Reading: 36,049.80

Close Date: 11/17/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

1. Clean work area & floor.
2. Help Bill Hines with C-Inspection; test/cln batry cables etc.; chk 12V & 110V outlets on patient area.
3. C-Inspection
4. C-Inspection.
5. Replc L/R pat compt plexi-glass door.
6. R/R/ air dryer.
7. R/R air filter.
8. Tighten all door latches.
9. Torque u-bolts.
10. Svc diff.
11. R/R b elts.
12. Svc cooling sys.
13. R/R right rear mud flap.
14. R/R rear brake shoes & drums.
15. C/O pat compt A/C; fnd & rep burnt wires on relay.

j

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
3744BRAKE DRUM REAR	2
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
ACX-84534LUG NUT COVER PK10	4
B2420LP-SMUD FLAP 24 X 24	1
DOOR5LEXAN 9 X 38 1/2 IN	1
E-600013-3052 NUT	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V19034

In Date: 11/13/2008

Meter Reading: 36,253.00

Close Date: 12/02/2008

Problem?

AIR LEAK, PURGE VALE, R-54

Task performed:

- Replaced purge valve that was leaking. j

Parts	Quantity
800404USE K022105 PURGE KIT AD-IP-IS	2



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V19409

In Date: 12/01/2008
Close Date: 12/16/2008

Meter Reading: 37,348.90

Problem?

STRECTHER LATCH INOP, R-54

Task performed:

1. Stretcher latch inop; readj latch.
2. 02 leak; traced out 02 leak; fnd bottle leaking.
3. Cab leaks water; resealed top roof. j

Parts

NO PARTS USED

Quantity

Workorder: V19725

In Date: 12/13/2008
Close Date: 01/05/2009

Meter Reading: 3,627.30

Problem?

Rear brake lighr do not come on r54

Task performed:

1. Replcd air solenoid for brake lights. j

Parts

501-3090-00PRIMER PUMP MOTOR

NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M

Quantity

1

1

Workorder: V19890

In Date: 12/21/2008
Close Date: 01/13/2009

Meter Reading: 3,675.50

Problem?

R54 is leaking red fluid onto ground just below the engine fan (possibly anti-freeze). Leak is significant.

Task performed:

1. Coolant leak/water pump; pressure test; fnd defective water pump.
2. Replc water pump; rem water pump & ordered parts.
3. A-Inspection.
4. Rear door panels loose; tightened door panels.
5. R/S mirror loose; tightened mounting bolts.
6. R/S washer inop; nozzle clogged; cleared nozzle. j

Parts

9062030015PIPE SOCKET TO WP

DDE-0052035975A0052032675 THERMOSTAT ELEMENT M

DDE-9062030180GASKET SOCKET TO HEAD M2

DDE-R90620043019062006301 WATER PUMP SOME M2 CI

DDE/0209971148A0249972848 SEAL RING

DDE/A0279976048O-RINGS M2 WATER PUMP

Quantity

1

2

1

1

2

2



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V20138

In Date: 01/05/2009 Meter Reading: 38,781.00

Close Date: 01/27/2009

Problem?

REPLACE FAN CLUTCH, R-54

Task performed:

1- Fan clutch inop. Replaced fan clutch.

Parts

Quantity

HOR/991450HT 650 FAN ASY.

1

Workorder: V20553

In Date: 01/23/2009 Meter Reading: 3,777.00

Close Date: 02/13/2009

Problem?

front left headlight is not working R54

Task performed:

Left headlight out; replcd headlight. j

Parts

Quantity

9006XSLLEHEADLAMP M2 HI

2

Workorder: V17811

In Date: 09/19/2008 Meter Reading: 33,992.80

Close Date: 03/02/2009

Problem?

replace tires at sta 54 r54

Task performed:

Replace tires at Stn54, R54 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V21334

In Date: 02/25/2009 Meter Reading: 3,943.40

Close Date: 03/06/2009

Problem?

Inside the Pt compartment, the overhead A/C unit is falling down, as it is missing some screws. r54

Task performed:

1. Rep 110 A/C that was falling down.
2. Air bottle brkt brkn; rep brck that was brkn.
3. Stretcher hard to unlatch; cind/readj stretcher latch. j

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V21907

In Date: 03/18/2009
Close Date: 05/04/2009

Meter Reading: 42,370.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

- B-Inspection
- 2. R/R body mnt bolt-loose; tightened body bolt; nut was stripped; had to rem & install new nut.
- 3. Popping noise w/turning right; L/F spring eye bolt loose; tightened bolt.
- 4. Pat compt A/C not cooling; well low refrigerant; fnd/rep leak at discharge port.
- 5. Mirros loose; tightened brackts.
- 6. Seat belts hard to pull & retract; dried, cld & silicone used.
- 7. Svc A/C filters - dirty; cld washable filters & replcd cab filter.
- 8. Rear door panels/latches loose; svcd rear doors.
- 9. O2 sys leaks; replcd nipple.
- 10. R/S washer inop; nozzle clogged; cleared nozzle & tank P/U tube.
- 11. Paint fuel cap.
- 12. L/S markers inop; (1) bulb bad & (1) connector brkn; rep lights. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
906-181-00-86OIL FILTER M2 SPINNER 57140	1
M54-13SPM5413 NIPPLE	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V22524

In Date: 04/13/2009
Close Date: 05/11/2009

Meter Reading: 43,727.00

Problem?

replace front tires at south shop callaghan

Task performed:

Replace front tires at South Shop - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V23230

In Date: 05/12/2009
Close Date: 05/26/2009

Meter Reading: 45,221.10

Problem?

replace brake hose r 54

Task performed:

- 1. Installed new brake hose.
- 2. Door open light on; readj door switch. j

Parts

Quantity

12-21022-023M2 FRONT BRAKE LINES	1
----------------------------------	---



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V23505

In Date: 05/24/2009

Meter Reading:

Close Date: 06/02/2009

Problem?

Engine coolant below low and the cover for the shore line broke off. R54

Task performed:

Parts

Quantity

Press tested sys & chkd for leaks. j

NO PARTS USED

Workorder: V23587

In Date: 05/27/2009

Meter Reading: 45,918.00

Close Date: 06/19/2009

Problem?

power outlet flip is broken r54

Task performed:

Parts

Quantity

1. Rear 110 A/C inop; rep rear A/C.
2. Rear door hard to open; readj rear door. j

091-3YWCOVER KUSSMAUL AUTO EJECT

1

Workorder: V24027

In Date: 06/12/2009

Meter Reading: 4,367.10

Close Date: 06/23/2009

Problem?

patient a/c not working R54

Task performed:

Parts

Quantity

Pat compt A/C inop; defective crimp @ comp discharge; rerouted hose; rem crimp & work hose; installed new crimp. j

NO PARTS USED

Workorder: V24313

In Date: 06/24/2009

Meter Reading: 46,965.00

Close Date: 07/02/2009

Problem?

COOLANT LEAK, R-54

Task performed:

Parts

Quantity

1. C/O cooling sys, pressure test; run truck; hookup lap top.
2. C/O charging sys; rem/cln all connections; chk for voltage drops. j

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V23967

In Date: 06/10/2009
Close Date: 07/06/2009

Meter Reading: 4,367.10

Problem?

pt A/C not cooling ,also check engine light came on this morning

Task performed:

1. Chk eng light; chkd codes; fnd unit low on oil; refilled.
2. A/C rear inop; fnd condensor fans inop; rep/tested.
3. Side step falling off; rep side step. j

Parts

Quantity

05-17223-002RAD CAP 20 LB

1

Workorder: V24338

In Date: 06/25/2009
Close Date: 07/08/2009

Meter Reading: 46,965.00

Problem?

TOW VEHICLE FROM STA-54 TO SHOP, COOLANT LEAK R-54

Task performed:

Tow veh from Stn54 to shop, coolant leak R54 - Sisters
Towing j

Parts

Quantity

NO PARTS USED

Vendor?: SISTERS TOWING



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V24618

In Date: 07/07/2009

Meter Reading: 46,965.00

Close Date: 07/20/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

1. C-Inspection
2. Remove 9/11 decals.
3. Rem frnt wheels; inspected bearing on right frnt; fnd suspect marking on inner bearin races.
4. Inspected left frnt wheel bearing.
5. Replcd auto-eject cover.
6. Replcd marker LEDS on pat compt; wrng wires used on frnt left; had to jump off anchor marker lit to get working & same w/rear marker.
7. Replcd burn bulb in pat compt frnt left dome.
8. Replcd squad bench assist cyl.
9. Rem, cind & reinstalled rear cab & pat compt A/C filters.
10. installed new 9/11 decals.
11. Replcd bearings & races on frnt hubs; install/torque to spec; lube hubs; test drive & chk lube level again.
12. Lubed/tightened airpack release.
13. Replcd frn cab A/C filter.
14. Put frnt hubcaps back on.
15. cind eng comp & rear comp under door.
16. P/S svc.
17. Went to Bldg 3 & picked out/installed (4) rear tires.
18. Air dryer svc.
19. R/R rear LED reverse light; had to make device connector.
20. T-shoot alt; poss not charging properly; fails to delvr volt under a load; R/R alt; replc btry wires w/factory _____.
21. Rep latch on cabinet in left rear of pat comp.
22. Cind work area.
23. Airpack releases still binding; mod cable routing; now releases is smooth. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
15W40BSYN OIL BULK QTS	28
23-12337002RIVET PLASTIC	1
322502BULB PATIENT GH22	1
330-3024HUB COVER GASKET	2
370001ASEAL 35066	3
3720BEARING WB	2
3782BEARING	2
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
60C00FCRCLEAR BACKUP 600 SERIES	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HA49102C2-32-15 LATCH NON LOCKING	1
HM212011BEARING WB	2
HM212049BEARING FW	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V24885

In Date: 07/20/2009
Close Date: 07/28/2009

Meter Reading: 47,602.40

Problem?
CAB A/C 10-7 R 51

Task performed:

rep co ndensor fans; clnd coils & recharged unit. j

Parts

Quantity

NO PARTS USED

Workorder: V25133

In Date: 07/29/2009
Close Date: 08/05/2009

Meter Reading: 47,806.00

Problem?
REAR A/C INOP, R-54

Task performed:

1. Recharged rear A/C that was not blowing cool.
2. rear door hard to open; rep linkage. j

Parts

Quantity

NO PARTS USED

Workorder: V24731

In Date: 07/13/2009
Close Date: 08/26/2009

Meter Reading: 46,965.00

Problem?
replace rear tires at shop r54 callaghan

Task performed:

Replace rear tires at shop R54 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V25418

In Date: 08/10/2009
Close Date: 08/27/2009

Meter Reading: 48,420.90

Problem?
REAR DOOR HARD TO OPEN, R-54

Task performed:

1. Readj rear door linkage.
2. Belts making noise; readj A/C belts.
3. Roof mntd spotlight; replc rear wiring that was melted.

Parts

Quantity

NO PARTS USED

j



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V26572

In Date: 09/30/2009
Close Date: 10/13/2009

Meter Reading: 50,155.90

Problem?

flat repair R54 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V26489

In Date: 09/28/2009
Close Date: 10/14/2009

Meter Reading: 50,155.90

Problem?

A/C 10-7 R54

Task performed:

Parts

Quantity

1. Recharged rear A/C.
2. Rep stretcher latch & tested. j

NO PARTS USED

Workorder: V26657

In Date: 10/04/2009
Close Date: 10/20/2009

Meter Reading: 50,155.90

Problem?

rear end of the rescue slammed twice while i was slowing down .it sounds as if a spring shifted . R54

Task performed:

Parts

Quantity

Rear end slammed; harsh downshift; reset trans & road tested. j

NO PARTS USED

Workorder: V27313

In Date: 10/30/2009
Close Date: 11/20/2009

Meter Reading: 52,439.30

Problem?

R54 is making noises that sound like a loose belt.

Task performed:

Parts

Quantity

1. Rem fan clutch; rebuild fan clutch; install fan clutch.
2. Assist w/fan clutch; R/R.
3. Eng fan hitting A/C clutch; chk two other rescues; fnd not hitting fan; sent to shop. j

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V27091

In Date: 10/22/2009
Close Date: 12/09/2009

Meter Reading: 4,849.20

Problem?

"R-54 Engine coolant low" Check for leak.

Task performed:

- 1. Press tested & rep leaks.
- 2. Rep pat lights that were out. j

Parts

Quantity

NO PARTS USED

Workorder: V27398

In Date: 11/04/2009
Close Date: 12/09/2009

Meter Reading: 4,926.00

Problem?

The hook where we hang helmets, coats etc. broke off. It seems the hole for the screw is too large and comes out. Drivers side, 1 double compartment. r54

Task performed:

- No emergency lights in rear; fnd bad connection. j

Parts

Quantity

NO PARTS USED

Workorder: V27400

In Date: 11/04/2009
Close Date: 12/09/2009

Meter Reading: 4,926.00

Problem?

front emergency light bar on cab are not working when turning on emergency lights. wig wag works not the upper light bar R54

Task performed:

- No emergency lights; FNP with lights. j

Parts

Quantity

NO PARTS USED

Workorder: V28121

In Date: 12/04/2009
Close Date: 12/17/2009

Meter Reading: 54,113.50

Problem?

STUCK IN THE MUD R54

Task performed:

- Stuck in the mud; pulled out of the mud & chkd for damage; all ok. j

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V28247

In Date: 12/09/2009

Meter Reading:

Close Date: 12/21/2009

Problem?

Lt. door alarm sensor does not work. It remains on even though door is firmly shut. Also, patient compartment light is out. (above bench) r54

Task performed:

1. Went to Stn54; replcd pat compt light that was out.
2. Officer door switch faulty; needs new switch; panel of dash brkn; ordered new pass side dash piece.
j

Parts

Quantity

A22-54059-000DASH PANEL R/H M2

1

Workorder: V28065

In Date: 12/02/2009

Meter Reading: 54,113.50

Close Date: 01/14/2010

Problem?

Truck still has air leak. When truck is off it leans to the left. When off for extended periods of time, requires time to refill to disengage the air brake. r54

Task performed:

Chkd for air leak; replcd fittings. j

Parts

Quantity

NO PARTS USED

Workorder: V28565

In Date: 12/24/2009

Meter Reading: 5,111.20

Close Date: 01/14/2010

Problem?

Anilog O2 guage on main O2 reads over 1000 and the digital reads 500 and alarm is going off R54

Task performed:

Replcd O2 gauge. j

Parts

Quantity

NO PARTS USED

Workorder: V28593

In Date: 12/27/2009

Meter Reading: 5,165.00

Close Date: 01/14/2010

Problem?

right headlight, low beam is out. High beab works.R54

Task performed:

Replcd headlight bulb. j

Parts

Quantity

9006XSLLEADLAMP M2 HI

1

H6054USE CV TYPE SEALED BEAM

4



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V28627

In Date: 12/28/2009

Meter Reading: 55,466.70

Close Date: 01/15/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

B-Inspection.

1. Air leaks down; fnd numerous leaks frm fittings, connectors & drain valves.
3. A/C filters dirty; replcd frnt cab filter; clnd rear cab & pat compt filters.
4. L/R cab door tread palte brkn; replcd.
5. R/R body marker inop; defective rimp in side body - wiring; locate/rep defective wiring.
6. Rear brakes worn; replcd rear drakes/drums.
7. P/S leak; clamp loose; tightened clamp.
8. L/R/I tire low press; valve stem ext loose; locate leak & tightened ext.
9. Install fan guard-safety item.
10. Replc brkn dash valve & parking brake valve.
11. Btry hold down brkn; made a new holddown.
12. Replc air horn solenoid-leaking; had to mod brkt to mke solenoid fit.
13. Maplight holder brkn; mde new holder.
14. Coat hooks msng/stripped threads; replc (2) coathooks & rethreaded as needed.
15. Inside pat compt dome lights dim/inop; replcd (2) bulbs & grnd to other.
16. Rear door panels loose; msng/stripped screws; svc rear doors.
17. Grill loose/msng hardware; install new w/nuts & bolts
18. R/S fuel tank trim loose; msng hardware; tightened/replc msng hardware as needed.
19. Install SCBA brkts. j

Parts

Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
101202001S301GF15N8AC9 AIR HORN SOLENOID	1
14-7014HGR-1 HELMET HOOK	2
15W40BSYN OIL BULK QTS	28
18-46375-00018-46375-004 TREAD PLATE LH M2	1
322502BULB PATIENT GH22	2
3744BRAKE DRUM REAR	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V28694

In Date: 12/30/2009

Meter Reading: 55,466.70

Close Date: 01/20/2010

Problem?

REPLACE FRONT TIRES CALLAGHAN

Task performed:

Replace front tires - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V29549

In Date: 01/29/2010
Close Date: 02/11/2010

Meter Reading: 5,260.80

Problem?

Rear air bags: Very rough and stiff while transporting or driving around, especially for patients. Takes too long to deflate while taking stretcher in and out. Seems like bags might be over inflated. R54

Task performed:

Readj rear air bags. j

Parts

NO PARTS USED

Quantity

Workorder: V29483

In Date: 01/27/2010
Close Date: 02/12/2010

Meter Reading: 56,474.20

Problem?

r54 Leaking air bad!

Task performed:

1. Travel to Stn54; chk air leak.
2. Replc L/side & R/side rear leveling valves & adj air bags. j

Parts

S4640024430VALVE LEVELIN

2

Quantity

Workorder: V29035

In Date: 01/12/2010
Close Date: 02/22/2010

Meter Reading: 5,205.20

Problem?

still has air leak , also no heat in back R54

Task performed:

1. Traced out air leak; fnd no leaks.
2. Rear A/C warm; recharged unit. j

Parts

NO PARTS USED

Quantity

Workorder: V29081

In Date: 01/13/2010
Close Date: 03/19/2010

Meter Reading: 56,114.40

Problem?

Coolant levels being refilled weekley with water. Do we need coolant? r54

Task performed:

Press tested & fnd no leaks at this time. j

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V31410

In Date: 04/09/2010
Close Date: 04/28/2010

Meter Reading: 60,634.20

Problem?

rear a/c not cooling passenger compartment r54

Task performed:

Cbk pat A/C; evac & recharge sys. j

Parts

NO PARTS USED

Quantity

Workorder: V31493

In Date: 04/13/2010
Close Date: 04/29/2010

Meter Reading: 60,985.50

Problem?

R54 cab a/c not working, blowing warm.

Task performed:

1. R/R A/C compressor; R/R dryers & o-ring.
2. Assist w/A/C job. j
3. Recharged A/C & rep leak at hi-press switch. j

Parts

533303-0609 A/C COMPRESSOR M2 4485
 719707-0614A AC DRIER M2
 RD-5-7063-OP07-2618AA/C DRIER 7155

Quantity

1
1
1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V32283

In Date: 05/18/2010

Meter Reading: 62,706.90

Close Date: 06/07/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

- C-Inspection
- 2. R/R auto-eject; install super auto-eject.
- 3. Wiper blades.
- 4. R/R UV light.
- 5. Svc air dryer.
- 6. Svc trans.
- 7. Install new grnd lights/brckts on left/right rear cab.
- 8. T-shoot charging sys; low volt; rech btrys; cln/tighten all btry cable connections; start R/R alt.
- 9. Tighten/adj all compt door.
- 10. Resecure pat compt tool holder brkts.
- 11. Resecure btry slide out tray slides; adj latches.
- 12. Finish install new alt.
- 13. Run new wire for left/rear pat compt inner warning light; t-shoot brkn wire.
- 14. Help w/alt install.
- 15. R/R R/rear inner pat compt door handle/bezel.
- 16. T-shoot pat compt A/C; rem expansion block; full of ____; replc block/dryer; rem/blow out all lines.
- 17. Continue t-shoot pat compt A/C; blow out all lines again; R/R compressor.
- 18. R/R btry tender light.
- 19. R/R pat compt A/C door shocks.
- 20. R/R frnt brake shoes/drums;also R/front oil seal.
- 21. R/R pat step grip tape. j

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
032-0116549297 BATTERY INDICATOR	1
071601A07-0602A DRIER A/C 7118	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
0915520120AUTO EJECT 20 AERO OTL3925	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
160012-2012A EXPANSION VALVE 71R8301	1
29526898 29548988 TRANS FILTER ALLISON	1
2FC00ZCR4 IN ROUND LED	2
3753BRAKE DRUM RUMPER FRONT	2
4070091740 GROMMET T/L 4 IN	2
5008414CARTRIDGE DC100	1
5269LPVM-5 SM MOUNT	1
5790COMPRESSOR A/C	1
78R536078R5360M 2PK FILTER AIR COND	2
8201L17-3428 ESTER OIL E7	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC	1
ACX-84534LUG NUT COVER PK10	6
CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	1
HAN-1LBEZEL AND HANDLE	1
HLD3999GSS1715UV 30LB STRUT GAS	2
K022105PURGE VALVE AD-IP-IS	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RES	2
MFG01876GROUND LT BRACKET	2
R134AFREON LB	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
T0R00FRR2 IN LED	1
TRANSYNDALLISON TRANS FLUID GAL	32
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	2



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V32452

In Date: 05/26/2010
Close Date: 06/14/2010

Meter Reading: 55,466.70

Problem?

Replace rear tires (outside agency-Boulevard)

Task performed:

Replace rear tires - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE

Workorder: V33097

In Date: 06/24/2010
Close Date: 06/29/2010

Meter Reading: 5,260.80

Problem?

stuck in mud R54 (callout repair)

Task performed:

Pulled rescue to roadway - stuck in mud. j

Parts

NO PARTS USED

Quantity

Workorder: V33240

In Date: 06/30/2010
Close Date: 06/30/2010

Meter Reading: 62,706.90

Problem?

MDT randomly powers down and will not power up right away..... 3 shifts now. also entered in communications.... r54

Task performed:

reported to radio shop 06/30

Parts

NO PARTS USED

Quantity

Workorder: V27363

In Date: 11/02/2009
Close Date: 07/13/2010

Meter Reading: 52,439.30

Problem?

radiator fan hitting a/c compressor clutch R54

Task performed:

Verified job. j

Parts

78R536078R5360M 2PK FILTER AIR COND
ACX-84534LUG NUT COVER PK10
DOOR6RED HAZ DOOR
HOR/991450HT 650 FAN ASY.
HOR/994317REPAIR KIT FAN CLUTCH

Quantity

1
10
1
1
1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V27958

In Date: 11/27/2009
Close Date: 07/13/2010

Meter Reading: 5,015.00

Problem?

air lkeak is getting bad on rescue 54.the truck is taking a long time to build up R54

Task performed:

Verified job. j

Parts

Quantity

NO PARTS USED

Workorder: V33872

In Date: 07/29/2010
Close Date: 08/18/2010

Meter Reading: 65,909.90

Problem?

A/C 10-7 R54

Task performed:

Air leak - rep rear Air tank that was leaking. ja

Parts

Quantity

NO PARTS USED

Workorder: V33896

In Date: 07/29/2010
Close Date: 08/18/2010

Meter Reading: 65,909.90

Problem?

front cab a/c works intermittenly r54

Task performed:

1. Fnd bad grnd wire for blower motor.
2. Rep air line for driers seat.
3. Adj stretcher latch. ja

Parts

Quantity

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V33953

In Date: 08/02/2010
Close Date: 09/08/2010

Meter Reading: 66,183.30

Problem?

RESCUE 54 HAS AIR LEAK... CREW WILL BE AT EVOC MORNING AUG 2 AND WILL BE ABLE TO GO TO SHOP IF CONTACTED VIA PAGER... CAPT SCHULTZ

Task performed:

Chkd for leaks & rep all air leaks. j

Parts

Quantity

K022105PURGE VALVE AD-IP-IS

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V34038

In Date: 08/05/2010
Close Date: 09/08/2010

Meter Reading: 66,293.00

Problem?

when truck stopped and idling air pressure drop to low for E brake to be released or rear of truck to come up . R54

Task performed:

1. Dia air sys (2) problems; air hose frm compressor to tank has hole in it; R/R hose & fab new one; also rear air bags ready to go bad; R/R (2) rear air bags on suspension.
2. Assist K. Flerx in dia air sys failure - McIntosh
3. Fnd another air leak; R/R air tank drain valve. j

Parts	Quantity
103385NDRAIN COCK	1
16-15762-00016-19471-000 AIR BAG	2

Workorder: V34815

In Date: 09/08/2010
Close Date: 09/08/2010

Meter Reading: 67,238.00

Problem?

Main oxygen sytem continually leaking. Depleting an M tank every 2-3 days. R54

Task performed:

1. check for O2 leak, spray soap and water on M bottle and fittings, remove panel in pat. compt. spray fittings. found 2 fittings loose in panel area, remove and install threaded tape and retighten, recheck for leak ok

Parts	Quantity
NO PARTS USED	

Workorder: V34400

In Date: 08/20/2010
Close Date: 09/17/2010

Meter Reading: 66,293.00

Problem?

CHECK OUT LIGHTS 10-7 R 54

Task performed:

- Rep bad connection on relay. j

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V34814

In Date: 09/08/2010

Meter Reading: 67,238.00

Close Date: 09/23/2010

Problem?

brakes lights work intermittently. R54

Task performed:

1. travel to walmart on 441 in boca, was told by Ed.E it was R-56 and they were training there. got to walmart and it was R-54 that was still at 54, travel to 54 check brake lights. had R-54 come to south shop, travel back to south shop
2. check for intermittent brake lights, check LED lights, check air brake valve, replace air brake valve
3. install missing lug nut covers on front wheels

Parts	Quantity
ACX-84534LUG NUT COVER PK10	6
NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M	1

Workorder: V34820

In Date: 09/08/2010

Meter Reading: 67,238.00

Close Date: 09/28/2010

Problem?

replace front tires r54 boulevard

Task performed:

Replc front tires R54 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE

Workorder: V34443

In Date: 08/23/2010

Meter Reading: 67,238.00

Close Date: 10/20/2010

Problem?

r54 back a/c not working

Task performed:

Recharged rear A/C & rep leak. j

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V35938

In Date: 10/26/2010

Meter Reading: 70,439.00

Close Date: 11/01/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

- 1. B-Inspection
- 2. R/R eng air filter dated 7/09.
- 3. R/R cab aux A/C filter.
- 4. R/R cab A/C air filter in dashboard.
- 5. Rep brkn dash where door ajar switch mnts for R/S frnt cab door.
- 6. R/R (2) under truck lights.
- 7. R/R elns; R/R bulbs in (2) pat area ceiling lights.
- 8. Adj all (6) tire press to 100 PSI - all were low.
- 9. R/R wiper blades.
- 10. No svc date on air dryer; find out frm parts when last changed out & paint that date on dryer.
- 11. Install cab door switch R/S frnt door.
- 12. Install new caps on A/C sys svc parts.
- 13. Replc inner compt door struts in pat compt.
- 14. Dlua cab A/C sys not cold; fnd leak at bulkhead fitting hoses in right side rear at aux unit; discharge A/C sys.
- 15. Assist t-shoot cab A/C; fnd leak at fitting in left rear of cab; rem lines & had new ones made up; installed new lines; vac/charged sys.
- 16. Press tested cooling sys; fnd coolant leak at thermo hsng; rem top of hsng; R/R t-stats/gskts; put hsng back tog & press test.
- 17. Go light vibrating where light swivels at base is loose; replc lights.
- 18. Rear A/C not cold enough; chk charge - low; look for leaks; vac/tested/recharged; test sys opn - all ok.
- 19. Adj air horns.
- 20. Final test drive & chks. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
322502BULB PATIENT GH22	2
42809AIR FILTER M2	1
607141-05USE 61H01 COPMPARTMENT LIGHT	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE/0209971148A0249972848 SEAL RING	2
HLD3999GSS1715UV 30LB STRUT GAS	6
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1
PH660412A/C CAP	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V36022

In Date: 10/29/2010

Meter Reading: 67,238.00

Close Date: 11/05/2010

Problem?

replace 4 rear tires R54 (outside agency-boulevard)

Task performed:

- Replc (4) rear tires R54 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V35520

In Date: 10/08/2010
Close Date: 12/22/2010

Meter Reading: 68,893.50

Problem?

Both AC's in the front compartment are blowing hot air. R54

Task performed:

(1) BOTH A/C UNITS IN THE FRONT COMPARTMENT OF R54 ARE BLOWING HOT AIR. RAN BOTH A/C UNITS FOR 30 MIN AND CHECKED OUT COLD/OK. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V37397

In Date: 12/24/2010
Close Date: 12/28/2010

Meter Reading: 73,050.00

Problem?

R54 MDT no communicating with dispatch. Reset the modem and rebooted but still no conection.

Task performed:

reported to radio shop 12/27

Parts

NO PARTS USED

Quantity

Workorder: V35246

In Date: 09/28/2010
Close Date: 12/29/2010

Meter Reading: 68,507.00

Problem?

Rescue 54 front A/C st off and on. Sometimes workes with a wire wiggle under dash passanger side. Same problem as before. Lt Barksdale

Task performed:

(1) A/C BLOWER MOTOR DEFECTIVE. REPLACED BLOWER MOTOR AND HARNESS.

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2
VCC/83000038AC WIRE HARNESS

Quantity

1
1

J.W.

Workorder: V37583

In Date: 01/03/2011
Close Date: 01/03/2011

Meter Reading: 73,988.60

Problem?

travel to sta-54 pick up R-54 and drive to c/shop, travel back to s/shop

Task performed:

1. travel to sta-54 pick up R-54 drive unit to c/shop, travel back to s/shop

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V37580

In Date: 01/03/2011

Meter Reading: 73,988.60

Close Date: 01/06/2011

Problem?

ON CALL BRAKES 10-7 R54

Task performed:

(1) OT. TRAVELED TO ST-54 TO REPAIR BRAKES ON R54. FOUND BAD BRAKE CAN ON LEFT REAR LEAKING INTO ABS VALVE. CAPEDED OFF LINES CAGE CHAMBER. RESCUE WENT BACK TO ST54. OOS. J.W.

Parts

NO PARTS USED

Quantity

Workorder: V36978

In Date: 12/07/2010

Meter Reading: 72,421.40

Close Date: 01/11/2011

Problem?

R 54's engine continuously needs engine oil added. no noticeable leaking. added 6 quarts recently and is now low.

Task performed:

1. Chkd for oil leaks; fnd no leaks.
2. Adj rear air bags that was leaning to the left. j

Parts

NO PARTS USED

Quantity

Workorder: V37584

In Date: 01/03/2011

Meter Reading: 73,988.60

Close Date: 01/19/2011

Problem?

replace bad brake chambers r54

Task performed:

1. Dia problem w/brake chambers; fnd L/rear park brake diaphragm leaking into svc side.
2. Rem L&R brake chambers; order chambers/clevis; none in stock.
3. Install brake chambers; cut push rod to proper length; swapped out fittings; clocked body of chambers for hoses to reach; cut new clevis pins to size; adj brakes; chk stroke; chk for leaks.
4. Fnd air leak at double chk valve at foot valve; rem valve; ordered parts; install part; replc splice on park brake line; road test ok. j

Parts

1245-P-1030USE 13047
 278614278614 CHECK VALVE
 GC2430XLLONG STROKE BRAKE CHAMBER

Quantity

2
1
2



7/2/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V38128

In Date: 01/28/2011
Close Date: 01/31/2011

Meter Reading: 75,760.30

Problem?

MDT is saying error and will not allow me to do any thing after call is responded to .MDT then locks up R54

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V37348

In Date: 12/21/2010
Close Date: 02/07/2011

Meter Reading: 72,994.20

Problem?

REPROGRAM NODE 1 / CONDENSER FAN 10-7 R56

Task performed:

Parts

Quantity

Chkd fan & fnd unit working; fnd bad grnd wire & tested.
j

NO PARTS USED

Workorder: V38216

In Date: 02/01/2011
Close Date: 02/15/2011

Meter Reading: 75,760.30

Problem?

A/C in pt compartment not blowing cold air. r54

Task performed:

Parts

Quantity

Went to 54; pat A/C inop; fnd sys low on charge;
charged sys. j

NO PARTS USED

Workorder: V38526

In Date: 02/15/2011
Close Date: 02/23/2011

Meter Reading: 76,730.90

Problem?

on call compt door 10-7 r54

Task performed:

Parts

Quantity

Pat compt door will not open; force door open; fnd nader
pin wedged betwn lock & striker pin; rem nader pin;
traighten & reassemble. j

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V38244

In Date: 02/03/2011

Meter Reading: 75,760.30

Close Date: 03/09/2011

Problem?

truck will start and when placed in drive it starts to move and then shuts off . truck will start again but then does the same thing . R

Task performed:

No start; fnd plug not ejecting frm plug; isntalled new auto-eject plug. j

Parts

0915520120AUTO EJECT 20 AERO OTL3925

Quantity

1

Workorder: V38671

In Date: 02/21/2011

Meter Reading: 77,106.30

Close Date: 03/15/2011

Problem?

pt compartment A/C unit is not cooling at all R54

Task performed:

Chkd A/C & tested good. j

Parts

60027FAN A/C COND 12IN 860026-2-W

Quantity

1

Workorder: V38779

In Date: 02/25/2011

Meter Reading: 67,238.00

Close Date: 03/21/2011

Problem?

replace 4 rear tires R54 (outside agency-boulevard)

Task performed:

Replace (4) rear tires R54 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V38996

In Date: 03/07/2011

Meter Reading: 77,518.00

Close Date: 04/04/2011

Problem?

ON CALL BATTERIES 10-7 R54

Task performed:

R54 - Replc all btrys & tested. j

Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

HP-31DBATTERY 950CCA HP-31D

Quantity

4

4



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V39416

In Date: 03/24/2011

Close Date: 04/04/2011

Meter Reading: 78,813.00

Problem?

COOLANT LEAK R54

Task performed:

1. R/R EGR valve & EGR cooler; includes dia time.
2. Continue R/R EGR valve & cooler. j

<u>Parts</u>	<u>Quantity</u>
A9061420580GASKET	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
DDE/A0039973352EGR COOLING HOSE	2
DDE/A02799760480-RINGS M2 WATER PUMP	1
EA9061420619RA9061420619 EGR VALVE	1
N917003022003GASKET/SEAL M2 WATER PUMP	1
S775COUPLER	3



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V38701

In Date: 02/22/2011

Meter Reading: 77,373.00

Close Date: 04/07/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R54

Task performed:

Parts

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Road test & C-Inspection

2. R/front axle oil cap leak; cln area, inspect cap; cap has no crack; chk torque on cap screws; fnd loose bolts; sec olts & chk, lube.

3. Frnt shocks leaking fluid; rem both frnt shocks & install new shocks.

4. Rear brakes svc; rem tires, diss rear brake & install new brake shoes & ___; remnt tires; lift & adj slack adjuster to mfr specs as per manual.

5. Coolant low; press sys; no leak fnd; fill reservoir to proper level.

6. P/S fluid level low; no leaks fnd; bring fluid level up to specs.

7. Rad overflow hose rubbing on eng components; shield hose w/protective hose & snaps.

8. Rear A/C condensor fan turning slow; rem/install new fan; sys operating normal.

9. Pat compt A/C filter dirty- none in stock; cut/install free roll of filter element.

10. Pat compt 110 A/C filter dirty; blow out filter to reinstall.

11. Cab dash A/C filter dirty & damp; rem, cln A/C duct drain tube; install filter.

12. Pat compt UV bulb blown; rem/install new UV bulb.

13. Officers door open - light switch brkn; rem, super blue; rep plastic hole damage & install new switch.

14. Mod rear door window coming out; rem glass seal, cln seal & channe; reinstall.

15. Pat compt A/C blowing cool; fnd sys low on freon; recvr, pull vac test, no leak; fnd charge sys, operate, chk press & temp at 23 degrees; sys operating normal; cln oil stain off compressor fitting.

16. Cab L&R side step non-skid tape msng; cln surface, cut/install non-skid tape.

17. Loose compt door panel screws; secure loose panel screw R-1, R-2, L-2, L-3.

18. compt door locks out of timing; rem door panel; loosen lock rods; adj rods; sec door panels R-1, R-2, L-2, L-3.

19. R-1 compt vent fell out; install used vent slot.

20. Pat entrance rear flip step cracked; drill/tap plate; install screw w/med strength locktite & secure.

21. L/rear brake light 10-7; dia fault; fnd weak electrical connector; rem, cln & recrimp.

22. Pat compt light lt inop; R/R blown bulb.

23. Windshield blade & reservoir svc.

24. Road test after new tires install; unit no longer wanders to right.

j

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
322502BULB PATIENT GH22	1
60027FAN A/C COND 12IN 860026-2-W	1
65140FRONT SHOCK NEW M2	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V39699

In Date: 04/05/2011 Meter Reading: 79,446.00

Close Date: 04/14/2011

Problem?

Repair stretcher R54 (outside agency-medco equipt. repair)

Task performed:

Rep stretcher R54 - Medco j

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO

Workorder: V40026

In Date: 04/20/2011 Meter Reading: 80,466.00

Close Date: 04/22/2011

Problem?

non stip reving on high idle, air leak.

Task performed:

1. Changed out faulty alt - shorted diode.
2. Replcd leaking drain valve on air tank.
3. Recovered, vac & recharged pat compt A/C - low on freon. j

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC 1

Workorder: V39596

In Date: 04/01/2011 Meter Reading: 79,233.90

Close Date: 05/05/2011

Problem?

R54 will not keep its air pressure when Rescue is turned off.

Task performed:

Replcd air fittings on foot valve. j

Parts

Quantity

NO PARTS USED

Workorder: V39673

In Date: 04/05/2011 Meter Reading: 79,446.00

Close Date: 05/10/2011

Problem?

Air leaks out while the truck is turned off. R54

Task performed:

Air leaks; traced out air leaks & rep. j

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V40433

In Date: 05/05/2011
Close Date: 05/10/2011

Meter Reading: 81,105.30

Problem?

repair air leaks r 54

Task performed:

1. Chk for air leaks; fnd ABS vcalve asy leaking; R/R valve asy; rechk - ok.
2. Assist in valve replacement & air leaks. j

Parts

472-500-121-0ABS ASSBLY

Quantity

1

Workorder: V39854

In Date: 04/12/2011
Close Date: 05/13/2011

Meter Reading: 79,929.90

Problem?

AIR LEAK, LOSS OF AIR PRESSURE DOWN TO 25PSI TAKES EXTENDED TIME TO BUILD UP PRESSURE. E 54

Task performed:

1. Chkd for air leaks & rep.
2. Rep R/side rear door that was hard to open. j

Parts

NO PARTS USED

Quantity

Workorder: V39884

In Date: 04/13/2011
Close Date: 05/13/2011

Meter Reading: 80,078.50

Problem?

air leak R54

Task performed:

- chkd for air leaks. j

Parts

NO PARTS USED

Quantity

Workorder: V41154

In Date: 06/06/2011
Close Date: 06/28/2011

Meter Reading: 83,430.80

Problem?

cab a/c not cooling, Sta 54.

Task performed:

- checked for leaks and recharged unit
- checked for air leaks and found none at this time ak

Parts

78R536078R5360M 2PK FILTER AIR COND

Quantity

4



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V41310

In Date: 06/13/2011
Close Date: 06/30/2011

Meter Reading: 84,021.50

Problem?

map light broken R 54

Task performed:

replc maplight & tested. j

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1

Workorder: V41424

In Date: 06/18/2011
Close Date: 07/11/2011

Meter Reading: 84,302.70

Problem?

Front cab and pt compartment a/c is not cooling well. R54

Task performed:

Recharged sys & rep leak. j

Parts

NO PARTS USED

Quantity

Workorder: V41910

In Date: 07/10/2011
Close Date: 07/18/2011

Meter Reading: 84,629.20

Problem?

rear nader pin cover broken r 54

Task performed:

1. nader pin cover broken, drill holes in new cover and mount

Parts

NO PARTS USED

Quantity

Workorder: V41436

In Date: 06/18/2011
Close Date: 07/19/2011

Meter Reading: 84,302.70

Problem?

AC not working R54

Task performed:

CAB AC INOP RECHARED SYSTEM AND CHECKED FOR LEAKS AK

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V41485

In Date: 06/21/2011

Meter Reading: 84,302.70

Close Date: 07/19/2011

Problem?

ac rear not working R54

Task performed:

REAR PT AC INOP CLEAN CONDENCER FANS AND TESTED OK AK

Parts

NO PARTS USED

Quantity

Workorder: V41812

In Date: 07/05/2011

Meter Reading: 86,130.00

Close Date: 07/19/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 54

Task performed:

1. B inspection
2. service air drier
3. replace pat.compt a/c filter
4. found red led lite not flashing in l-1 compt door, remove diamond plate panel found bad ground repair ground wire.
5. rear entry door window's seals falling out. remove all 4 seals on windows and clean, reinstall seals. remove side entry door window seals and clean reinstall seals.
6. check rear pat. a/c not blowing cold, charge system and check for leaks found o rings leaking at drier replace o rings, refill and recheck leaks found more leaks, found crimp on high side of compressor leaking, and o rings on compressor leaking, replace high side comp. fitting replace o rings on compressor recharge and check for leaks. ok now
7. check front cab a/c blows cool, found low on freon, fill system and check for leaks found o rings on compressor leaking and o rings on drier leaking, replace drier recharge system, recheck for leaks, found more leaks at condensor fans under cab replace o rings recharge and recheck for leaks, no more leaks found.
8. found lites under cab door inop, check wiring, found water in connector's dry out connectors lites work ok now.
9. travel to c/shop for parts a/c parts and air drier parts, travel back to s/shop
10. replace rear lug nut covers. they were missing

Parts

- 000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT
- 0000902051FILTER FUEL 03 MERCEDES
- 0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH
- 010263488-5010263488-5W CLEARANCE LIGHT LED
- 1501450007750USE 0775145
- 16-31455533 CAP LOW SIDE BLUE
- 16-31498925 VALVE CORE
- 16-3443CAP-BLUE R134 NEW #5574
- 16-3444CAP R134A - RED 5575/5557
- 16-3445CAP-BLACK 134A 5579 KOOL TEMP
- 16-34465580 CAP-BLACK R134A
- 4507SFITTING AC SB1312-3
- 4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT
- 4512S08-6933BS A/C FITTING STEEL
- 719707-0614A AC DRIER M2
- 906-181-00-86OIL FILTER M2 SPINNER 57140
- ACX-84534LUG NUT COVER PK10
- K022105PURGE VALVE AD-IP-IS
- S3226FL02FUEL FILTER 33813 L/F # LFF5851

Quantity

- 1
- 1
- 1
- 1
- 1
- 2
- 2
- 2
- 2
- 2
- 2
- 1
- 1
- 1
- 1
- 1
- 10
- 1
- 1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V42524

In Date: 08/03/2011
Close Date: 08/04/2011

Meter Reading: 114,640.00

Problem?

oxygen supply leaking at unknown location r54

Task performed:

1. travel to sta-54
2. check for o2 leak, spray down all o2 fittings in pat. compt. o2 wall outlets and behind wall at emt bench, found leak at fittings on gauge in o2 compt. on M bottle, remove fittings and put thread tape on them and instal

Parts

Quantity

NO PARTS USED

Workorder: V42439

In Date: 08/01/2011
Close Date: 08/25/2011

Meter Reading: 114,640.00

Problem?

The front AC in the cab is not blowing cold. The unit is blowing but air is just cool. The rear unit in the cab is working fine. Sta 54.

Task performed:

recharged a/c unit and checked for leaks

Parts

Quantity

NO PARTS USED

Workorder: V43410

In Date: 09/04/2011
Close Date: 09/06/2011

Meter Reading: 88,538.40

Problem?

truck radio turns on and off intermittently R 54

Task performed:

REPORTED TO READIO SHOP 09/6

Parts

Quantity

NO PARTS USED

Workorder: V43576

In Date: 09/11/2011
Close Date: 09/13/2011

Meter Reading: 88,986.90

Problem?

R54 LEAKING FLUID, APPEARS TO BE AXLE FLUID FROM REAR. RIGHT REAR WHEEL APPEARS "WET" WHEN LOOKING UNDERNEATH TRUCK. R54

Task performed:

C/O oil leak in truck; fnd R/rear axle leaking bad 005; take to 42, get truck. j

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V43624

In Date: 09/13/2011

Meter Reading: 88,986.90

Close Date: 09/16/2011

Problem?

rear axel seal leaking, R-54

Task performed:

1. travel to c/shop for brake parts
2. remove wheels, brake drums, hubs and bearings, and brake shoes, remove oil seals clean bearings and inspect, all ok. install bearings in hub install new oil seals, remove brake shoes, clean oil off of r/rear spindle, replace brake shoes and hardware, install hubs, install new brake drums, install wheels, refill rear axel and adjust rear brakes, road test vehicle and recheck brake adjustment and rear axel fluid level.
3. cab a/c blows cool, check freon found low, add freon and check for leaks, could not find any.

Parts	Quantity
3744BRAKE DRUM REAR	2
380003ASEAL	2
401581GASKET AXLE FL80 R002435	2
E-2436R002436 GASKET-REAR AXLE	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2

Workorder: V42012

In Date: 07/14/2011

Meter Reading: 84,629.20

Close Date: 09/20/2011

Problem?

REPLACE REAR TIRES

Task performed:

Replace rear tires - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD

Workorder: V44010

In Date: 09/29/2011

Meter Reading: 89,814.90

Close Date: 10/07/2011

Problem?

Back brake lights not working properly. Sta 54.

Task performed:

replaced air sender for rear brakes

Parts	Quantity
NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V43966

In Date: 09/27/2011

Meter Reading: 89,639.70

Close Date: 10/14/2011

Problem?

outside air line on Rt. rear tire no good. Tire mechanic removed and placed a valve cover on the tire for now. Sta 54.

Task performed:

CHECKED TIRE AIR VALVE AND CHECKED OK

Parts

AMH-1AMH-1 VALVE EXTENSION

Quantity

1

AIR LEAK CHECKED FOR LEAKS FOUND NONE AT THIS TIME

Workorder: V44081

In Date: 10/02/2011

Meter Reading: 89,814.90

Close Date: 10/21/2011

Problem?

BACK UP CAMERA NOT WORKING ON R54. SCREEN IS BLANK. R54

Task performed:

repaired rear cam found bad connection

Parts

NO PARTS USED

Quantity

Workorder: V44234

In Date: 10/08/2011

Meter Reading: 89,814.90

Close Date: 10/21/2011

Problem?

back up camera on R54 is not working

Task performed:

repaired comera and tested

Parts

9006XSSLHEADLAMP M2 HI

Quantity

1

head light out replaced



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V44663

In Date: 10/25/2011

Meter Reading:

Close Date: 10/25/2011

Problem?

Truck stops and shakes when brakes are applied, Sta 54.

Task performed:

1. travel to sta-54
2. check brakes, ok. road test vehicle could not reproduce problem, talked with driver could possibly be in transmission, hook up laptop check for trans. codes found code for F solenoid open 21 counts, have them swap out
3. travel back to s/shop
4. Trans code 45-21I; open ckt in "F" solenoid; follow dia procedures; switching parts frm one veh to another & back; 100 mile road test, etc, etc. j

Parts

Quantity

NO PARTS USED

Workorder: V44341

In Date: 10/12/2011

Meter Reading:

Close Date: 10/31/2011

Problem?

Front driver headlight out, back-up camera not working, and bolt missing from officer side running board causing vibration. Driver headlight and back up camera fixed by Tommy 10/12/2011. Running board still needs bolt. Sta 54.

Task performed:

1. Rep headlight
2. Rep backup cam
3. Rep diamond plate. j

Parts

Quantity

NO PARTS USED

Workorder: V44817

In Date: 10/31/2011

Meter Reading: 91,332.20

Close Date: 11/02/2011

Problem?

Check front a/c.

Task performed:

check out probelm with front a/c system, found small lek @ connect, evacuate system, replace o ring at connector, vaccum down and recharge to full capacity, also found inside air intake filter very dirty, replace

Parts

Quantity

78R536078R5360M 2PK FILTER AIR COND

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V44850

In Date: 11/01/2011

Meter Reading: 91,640.00

Close Date: 11/02/2011

Problem?

A inspection.

Task performed:

a inspection

top off eng. oil, 6 qts low

wiper blades, replacement

fill washer fluid bottle, add additive

correct all tire pressures, too low

Parts

Quantity

05-17223-002RAD CAP 20 LB

1

91-22WIPER BLADE

2

VCC/36000006A/C FILTER CAB M2

1

Workorder: V44919

In Date: 11/02/2011

Meter Reading: 91,332.20

Close Date: 11/09/2011

Problem?

replace front tires r 54

Task performed:

Replace front tires R54 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD

Workorder: V44924

In Date: 11/03/2011

Meter Reading:

Close Date: 11/21/2011

Problem?

Black plastic gaurd on stretcher keeps getting caught on tailgate of rescue. R54

Task performed:

Rep stretcher guard & tested. j

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V45494

In Date: 11/29/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

Round light on ceiling of pt. compartment, officer side, towards front is broken. Sta 54

Task performed:

Parts

Quantity

replaced bulb

NO PARTS USED

Workorder: V46044

In Date: 12/23/2011

Meter Reading: 94,644.40

Close Date: 12/28/2011

Problem?

A/C not cooling properly in cab and pt compartment.

Task performed:

Parts

Quantity

PAT AND CAB A/C BLOWING WARM. CHARGED SYSTEM AND LOOKED FOR LEAKS. SUSPECT CAB A/C LEAKING AT CONDESER LINES. WILL REPAIR NEXT. PM.

NO PARTS USED

Workorder: V45698

In Date: 12/07/2011

Meter Reading:

Close Date: 01/03/2012

Problem?

R54 OOS due to truck stalling after being started x's 2 when master light switch activated. Error code DIAG 1 and ECU 130, Sta54

Task performed:

Parts

Quantity

replaced master battery switch and tested

75908SWITCH BATTERY MASTER 300A

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V46156

In Date: 12/29/2011

Meter Reading:

Close Date: 01/06/2012

Problem?

LARGE LEAK UNDER ENGINE. LIKELY RADIATO OR POWER STEERING.. R 54

Task performed:

TRAVEL TO STATION, DIAGNOSE REPORTED LEAK, FOUND AIR COMPRESSOR HEAD GASKET LEAKING, ATTEMPTED TO TIGHEN SCREW, WAS UNABLE TO STOP LEAK, UNIT OUT OF SERVICE AND TOWED TO SHOP

CHECK OUT COOLANT LEAK, REMOVE AIR COMPRESSOR, TRANSFER FITTINGS AND COMPONENTS TO NEW REBUILT COMPRESSOR, BEFORE INSTALLATION IT WAS NECESSARY TO REMOVE ECM AND COMPLETE FUEL SYSTEM FILTER HOUSING AND REPALCE PLASTIC COOLING LINES TO COMPRESSOR, REASSEMBLE ALL AND INSTALL COMPRESSOR CHECK FOR LEAKS

LONG ROAD TEST, RECHECK REPAIRS WHEN RETURNED TO SHOP

Parts

Quantity

A0249972148SEAL	1
A9062030102A9062037102 COOLANT LINE	1
A9062030702A9062037302 COMPRESSOR LINE	1
N000000001069SEAL BANJO	4
RA9061301415AIR COMPRESSOR	1

Workorder: V46352

In Date: 01/05/2012

Meter Reading:

Close Date: 01/06/2012

Problem?

r54 leaking fluid

Task performed:

1. check for coolant leak, pressure test system. found coolant tank leaking, order tank
2. replace coolant tank, pressure test for leaks, ok

Parts

Quantity

05-17223-002RAD CAP 20 LB	1
05-23195-000Z05-30740-000 SURGE TANK	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V46092

In Date: 12/27/2011

Meter Reading: 94,644.40

Close Date: 01/09/2012

Problem?

C INSPECTION AND REPAIRS R 54

Task performed:

1. C INSPECTION
2. INSTALL REAR AIR BAGS, AIR FILTER, WIPER BALDES, GRIP TAPE AND BOTH SIDE STEPS.
3. R&R JUMP SEAT, TORQUE U-BOLTS, REAR DIFF SERVICE.
4. INSTALL A/C AND SERPENTINE BOLT.
5. INSTALL NADER PLATE, CLEAN AND REINSTALL REAR GLASS RUBBER, TIGHTEN COMPARTMENT SCREWS.
6. SWAP OUT AIR PACKAGE BRACKET AND ADJUST.
7. REPLACE HOSES TO CAB A/C CONDENSER - EVALUATE AND RECHARGE AND REPLACE A/C FILTER.

Parts

Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
1501450007750USE 0775145	1
16-15762-00016-19471-000 AIR BAG	2
31-22USE 91-22 WIPER BLADES	2
398575HOSE & FITTING ASSY	1
42809AIR FILTER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
9550 BELT	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V45568

In Date: 12/01/2011

Meter Reading: 93,302.40

Close Date: 01/13/2012

Problem?

need air pak bracket mounted on L1 door. Location now is not easily accessible. Thank you. Sta 54

Task performed:

WILL INSTALL NEW AIR PACKS WHEN THEY COME IN.

Parts

Quantity

NO PARTS USED

Workorder: V46441

In Date: 01/09/2012

Meter Reading: 95,477.00

Close Date: 01/13/2012

Problem?

cab a/c is blowing warm air. Pt compartment is blowing cold air. Sta 54

Task performed:

RECHARGED SYSTEM AND CHECKED FOR LEAK.

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V46534

In Date: 01/12/2012

Meter Reading: 95,477.00

Close Date: 01/23/2012

Problem?

no a/c in front cab, Sta 54

Task performed:

Parts

Quantity

1. NO CAB A/C, RECHARED SYSTEM AND REPAIRED LEAK.

NO PARTS USED

2. OVER HEATING, REPAIRED ENGINE FAN AIR LINE.

Workorder: V46658

In Date: 01/18/2012

Meter Reading: 95,960.50

Close Date: 01/23/2012

Problem?

rear tires need to be replaced ASAP. Sta 54

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Workorder: V46685

In Date: 01/19/2012

Meter Reading: 95,960.50

Close Date: 01/23/2012

Problem?

REPLACE TIRES

Task performed:

Parts

Quantity

REPLACE TIRES

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V47172

In Date: 02/08/2012

Meter Reading:

Close Date: 02/09/2012

Problem?

Engine smoking at belt area R54

Task performed:

1. travel to sta-54, check unit for smoke found cab a/c clutch locked up, disconnect compressor. travel back to s/shop
2. remove a/c compressor belt, a/c compressor, and drier for cab a/c, remove d/side rear cab step and replace redot system's drier, install new a/c compressor and both dries's for cab a/c, replace all o rings, evecaute and charge system, add 4oz of a/c oil to system (2 for each drier), check for leaks, reinstall d/side step.

Parts	Quantity
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614AAC DRIER M2	1
8201L17-3428 ESTER OIL E7	1
87401RY-30T RELAY 5 PIN 12V	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

Workorder: V46864

In Date: 01/26/2012

Meter Reading: 96,389.00

Close Date: 02/10/2012

Problem?

R54 OUT OF SERVICE, BACK DOOR WILL NOT OPEN R54

Task performed:

REMOVED DOOR PANEL AND READJUSTED DOOR LINKAGE TO OPEN DOOR - REPAIRED LINKAGE AND REPAIRED DOOR.

Parts	Quantity
NO PARTS USED	

Workorder: V47468

In Date: 02/21/2012

Meter Reading: 98,392.50

Close Date: 03/06/2012

Problem?

cab a/c blowing hot air from both units(front and rear). R54

Task performed:

RECHARGED UNIT AND REPAIRED CONNECTION ON PRESSURE SWITCH.

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V43946

In Date: 09/27/2011 Meter Reading: 89,639.70
Close Date: 03/09/2012

Problem?

Rt. rear inside tire is flat. Sta 54.

Task performed:

Parts	Quantity
91-20WIPER BLADE 20 IN	2

Workorder: V47818

In Date: 03/08/2012 Meter Reading: 99,763.80
Close Date: 03/16/2012

Problem?

Both A/C Units within the Rescue Units cab do not cool when set at it's proper settings. Sta 54

Task performed:

RECHARGED UNIT AND REPAIRED LEAK.

Parts	Quantity
NO PARTS USED	

Workorder: V48045

In Date: 03/19/2012 Meter Reading: 99,913.40
Close Date: 04/16/2012

Problem?

Pt compartment A/C is malfunctioning. Occasionally starts to blow warm R 54

Task performed:

1. PT COMPARTMENT A/C INOP/REPLACED RELAY AND CONDENSER FAN.
2. CAB A/C INOP. RECHARGED A/C AND TESTED.

Parts	Quantity
60027FAN A/C COND 12IN 860026-2-W	2
87401RY-30T RELAY 5 PIN 12V	1

Workorder: V48315

In Date: 03/31/2012 Meter Reading: 101,089.10
Close Date: 04/16/2012

Problem?

Front Cab AC not working. r 54

Task performed:

1. RECHARGED SYSTEM AND CHECKED FOR LEAKS.
2. REPAIRED STRETCHER LATCH.

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V48321

In Date: 04/01/2012

Meter Reading: 101,089.10

Close Date: 04/16/2012

Problem?

Rear patient compartment AC not working. RV54

Task performed:

REPLACED CONDENSER FANS RECHARGED
SYSTEM AND REPAIRED LEAK.

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V48472

In Date: 04/05/2012

Meter Reading: 101,730.60

Close Date: 04/16/2012

Problem?

B INSPECTION R 54 on going a/c leak filled several times

Task performed:

1. B-INSPECTION.
2. R/R INNER TIRE LOW INFLATE TIRE LOOK FOR NAILS SOAP CHECK FOR LEAKS FOUND EXT HOSE LEAKING HAD TO JACK UP VEHICLE AND REMOVE OUTER TIRE TO R&R HOSE AND MOVE HOSE BRACKET INVLATE ALL TIRES TO PROPER PRESSURE ALL LOW.
3. R&R WIPER BLADES.
4. R&R PATIENT CEILING LIGHT BULB.
5. R&R DOOR HOLD OPEN CYLINDERS IN PATIENT COMPARTMENT.
6. R&R CENTER FUGAL OIL FILTER COVER AND BRNG ASSY.
7. SECURE LOOSE WIRING HANGING DOWN INSIDE VEHICLE AT CONDENSER FAN ASSY.
8. R&R CAB AUX A/C FILTER.
9. R&R DRIVERS DOOR PANEL AND GRAB HANDLES REINSTALL BOLT ON DOOR HANDLE WITH LOCTITE
10. R&R NON SKID ON PASS SIDE CAB STEP.
11. R&R R/S OF DASH BOARD HAD TO REMOUNT MAP LIGHT AND HANDLES SPOT LIGHT TO NEW DASH. DRILL HOLES AND REWIRE ETC.
12. A/C CHARGE A/C SYSTEM TO LEAK TEST (EMPTY) DISCHARGE SYSTEM R&R HOSE FROM COMPRESSOR TO STEP CONDENSER.
13. EVACUATE AND RECHARGE A/C SYSTEM WASH STEP CONDENSER HOUSING OF OIL AND REMOVE DIRT. WASH AND RINSE CONDENSER COIL. RUN SYSTEM AND ROAD TEST VEH - CHECK TEMPS AT BOTH EVAPS - OK.
14. CAB FRONT A/C BLOWER MOTOR FAILED DURING ABOVE TEST. DIAGNOSE FOUND BLOWER MOTOR HARNESS BURNED R&R LOWER DASH PANEL R&R BLOWER MOTOR HARNESS.
15. TRANS HAS CODES HOOK UP LAP TOP DIAGNOSE CODE R&R ALUM SUB ELEC PANEL COVER CHECK ALL ALLISON COMPUTER FUSES AND CONNECTIONS CLEAR CODES.
16. Q. C. TRUCK.
17. R&R 2 NADER PIN COVER BRACKETS AT REAR DOORS DRILL AND CONTERSINK NEW BRACKETS. REPAIR THREADS ON 2 HOLES STRIPPED THREADS

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	2
322502BULB PATIENT GH22	1
404-100 VALVE CORE	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A22-54059-000DASH PANEL R/H M2	1
A9061840408SPINNER OIL FILTER COVER M2	1
HLD3999GSS1715UV 30LB STRUT GAS	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/83000038AC WIRE HARNESS	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V48419

In Date: 04/04/2012
Close Date: 04/20/2012

Meter Reading: 101,089.10

Problem?

A/C in the cab blowing hot air. Pt compartment not cooling properly. Bracket for scba on rear medic seat not working properly. R5

Task performed:

RECHARGED A/C AND REPAIRED LEAK.

Parts

NO PARTS USED

Quantity

Workorder: V48830

In Date: 04/23/2012
Close Date: 04/25/2012

Meter Reading:

Problem?

*There is no signal from the remote control key to the bay door, despite have a solid red light so the stay stays unsecured. *We were unable to communicate to dispatch via truck radio, loose radio connections. R54

Task performed:

forwarded to radio shop and build maint

Parts

NO PARTS USED

Quantity

Workorder: V49987

In Date: 06/08/2012
Close Date: 06/14/2012

Meter Reading: 104,856.00

Problem?

REPAIR COOLANT LEAK R 54

Task performed:

1. REPLACE RADIATOR/LEAKING/REPLACED RADIATOR.
2. REPLACED RADIATOR/LEAKING/REPLACED RADIATOR.
3. REPLACE RADIATOR/LEAKING/REPLACED RADIATOR.
4. A-INSPECTION.
5. BOOST HOSE NOT LINED UP PROPERLY FROM BURBO/OUT OF ALIGNMENT/CLOCKED TURBO OUTLET TUBE AND CORRECTED HOSE ROUTING.

Parts

15W40BSYN OIL BULK QTS
 23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LONG
 ANTICOOLANT ANTIFREEZE GAL
 C1673FRE04 RADIATOR

Quantity

3
4
6
1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V49724

In Date: 05/30/2012
Close Date: 07/03/2012

Meter Reading: 104,602.90

Problem?

*A loud loose noise in the lt rear wheel well *Pig tail adapter end stuck on oxygen wall mount. *Bottom latch rear door pt compartment is loose preventing door from closing tightly

Task performed:

1. NOISE IN REAR LEFT HUB - AXLE BOLT FELL OUT - REINSTALLED AND CHECKED OTHERS.
2. PIG TAIL FOR Q2 - REMOVED FROM TRUCK THAT WAS LOCKED ON UNIT.
3. EMERGENCY LIGHT BUTTON REPLACED.

Parts	Quantity
0K00-1957-00KEY PAD 4 POSITION	2
0K00-1958-00KEY PAD 7 POSITION	1

Workorder: V49904

In Date: 06/05/2012
Close Date: 07/03/2012

Meter Reading: 104,856.00

Problem?

Check out lights in pt compartment not working. Leaks air and takes a while to charge brake system. Pt compartment camera not working.

Task performed:

1. ALL LIGHT IN PATIENR COMPARTMENT OPERATING NORMAL COULD NOT GET THEM TO FAIL. PATIENT LIGHT ACTION AREA LIGHT AND O2 COMP. LIGHT.
2. PATIENT COMPART CAMERA INOP - DIAGNOSE FAULT CHECK CAMERA GOOD TRACE FAULT TO BROKEN COMMUNICATION CABLE - SPLICE BROKEN SHIELFED WIRE, REMOVE CONNECTION SOLDER NEW RCA CABLE MALE END INSULATE AND SECURE CABLE - REASSEMBLE AND OPERATE.
3. AIR LEAK - FOUND - PURGE VALVE MAL FUNCTION - REMOVE PURGE VALVE AND FILTER - INSTALL NEW PURGE VALVE AND DRYER - OPERATE UNIT - COULD NOT FIND ANY OTHER AIR LEAK.

Parts	Quantity
5008414CARTRIDGE DC100	1
K022105PURGE VALVE AD-IP-IS	1

Workorder: V50514

In Date: 07/01/2012
Close Date: 07/09/2012

Meter Reading:

Problem?

*INTERMITTING CHECK ENGINE LIGHT *RT SIDE READ CAB DOOR ACTIVES RED CAB LIGHT DESPITE BEING CLOSE, H TO CONSTANTLY OPEN/ CLOSE TO STOP LIGHT ACTIVATION. R 54

Task performed:

work completed on w/o#50617

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V50617

In Date: 07/05/2012
Close Date: 07/10/2012

Meter Reading: 105,507.00

Problem?

pat. a/c blower motor inop, air leak, check engine lite intermittent, R-54

Task performed:

1. check pat. compt. a/c, found blower motor inop, r&r blower motor, run a/c ok, cools to 33deg.
2. check for interminntent check engine lite, hook up laptop, found codes for low coolant, coolant was full, pressure test no leaks found, replace coolant probe in overflow tank, road test vehicle, check engine lite went on again and had code for EGR valve, remove EGR cooler and EGR valve, found antifreeze in valve, install new EGR cooler and EGR valve. refill coolant and road test.
3. check for air leak, use soap and water to check, found muplitable air leaks, replace all air line fittings on foot valve, rehack and found air tank bleeder leaking replace valve, recheck and let sit overnight, held air

Parts	Quantity
23520380SENSOR COOLANT	1
A9061420580GASKET	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
DDE/A0039973352EGR COOLING HOSE	2
EA9061420619RA9061420619 EGR VALVE	1

Workorder: V51235

In Date: 07/31/2012
Close Date: 08/03/2012

Meter Reading: 107,473.80

Problem?

REPLACE FRONT TIRES R 54

Task performed:

REPLACE FRONT TIRES R-54.

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V51444

In Date: 08/07/2012

Meter Reading: 108,340.00

Close Date: 08/15/2012

Problem?

C INSPECTION R 54

Task performed:

1. C inspection
2. coolant leak, found EGR valve gasket leaking, remove air cleaner assy, drain coolant, remove coolant hoses, EGR cooler, remove EGR valve and replace gasket, reassemble cooler and install, fill cooling system and pressure test no leaks found, run engine and recheck for leaks, none found
3. red dot a/c condenser fan making noise, remove side step, and replace both condenser fans, reinstall step.
4. headlight dull, use 3M headlight restorer
5. r/rear entry door window seal falling apart, remove window seal and clean, reattach seal
6. rear entry door striker plates missing, drill holes for new plates and install
7. air leak in system, drains down overnight, use soap and water to check, found lines leaking on foot valve, replace fittings, recheck for air leak, found l/side leveling valve leaking, replace both leveling valves, road test, and readjust hight.
8. paint fuel cap yellow
9. l/side rear entry lite inop. in rear lite bar, remove lite bar lens and replace lite assy.
10. both cab a/c filters dirty, replace both
11. pat. compt. a/c filter dirty, replace filter
12. both driver side cab door entry lites inop, replace both LED entry lites
13. adjust headlights
14. 110v a/c not cooling, found freon low add freon and check for leaks, found leak at compressor, evecuate system and replace O rings, vacuum down system and recharge, recheck for leaks, none found
15. degrease engine, clean condenser fans under truck

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	26
39045HEADLITE KIT WITH SEALER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A9061421080GASKET EGR COOLER	1
AMH-1AMH-1 VALVE EXTENSION	1
ANTICOOLANT ANTIFREEZE GAL	4
MR1135 WATT BULB	2
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S4640024430VALVE LEVELIN	2
VCC/36000006A/C FILTER CAB M2	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V51652

In Date: 08/16/2012
Close Date: 08/16/2012

Meter Reading: 133,448.00

Problem?

cab a/c blower motor stopped working, R-54

Task performed:

1. went to go pull rescue into sta-42 so crew could swap into it and cab a/c blower motor stopped working, found melted pin on blower motor and wire harness, replace motor and harness

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/830000038AC WIRE HARNESS	1

Workorder: V51690

In Date: 08/17/2012
Close Date: 09/13/2012

Meter Reading: 133,448.00

Problem?

*

Task performed:

REPLACE 4 TIRES

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE CENTE

Workorder: V51406

In Date: 08/06/2012
Close Date: 09/14/2012

Meter Reading:

Problem?

Engine light comes on and off r 54

Task performed:

FOUND UNIT LOW ON COOLANT PRESSURE TESTED/TESTED OK.

Parts	Quantity
NO PARTS USED	

Workorder: V51873

In Date: 08/25/2012
Close Date: 09/17/2012

Meter Reading:

Problem?

rattling noise coming from left rear wheel-well. R54

Task performed:

REPAIRED BROKEN AXLE STUD INSTALLED NEW STUD NUT.2. REPAIRED 110 A/C THAT WAS NOT WORKING.

Parts	Quantity
NO PARTS USED	



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V51923

In Date: 08/27/2012

Meter Reading: 108,641.20

Close Date: 09/25/2012

Problem?

ENGINE OIL SAMPLE ASAP R54

Task performed:

SAMPLES OF ENGINE OIL TAKEN.

Parts

NO PARTS USED

Quantity

Workorder: V52798

In Date: 10/02/2012

Meter Reading:

Close Date: 10/02/2012

Problem?

rear door will not open by outside handle and inside handle Thank you! r54

Task performed:

1. remove r/rear door grab handles and door panels,
replace door latch and adjust rods and lube.

Parts

HND5948TM22676-02 HANDLE DOOR ENTRY

1

Quantity

Workorder: V52804

In Date: 10/03/2012

Meter Reading: 111,083.00

Close Date: 10/04/2012

Problem?

Yesterday, the engine slipped displayed by a sudden jerk and the tran light remained on.. Vehicle would not change gear (ie.. neutral or reverse).. Turn vehicle off/ on, light went off and vehicle drove normal R54

Task performed:

CHECKED CODES CHECKED ALL ELECTRICAL
CONNECTIONS FOR WATER TEST DROVE TRUCK NO
PROBLEMS.

Parts

NO PARTS USED

Quantity

RAN CHECKS LOOKED AT CODES TEST DROVE
TRUCK FOUND NO PROBLEMS RELEASED TO
CREW.



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V52845

In Date: 10/04/2012

Meter Reading:

Close Date: 10/12/2012

Problem?

transmission, a/c sporatic, tailboard loose R54

Task performed:

1. A INSP
2. ADJUST REAR RADIO BOX LATCHES.
3. REPLACE R/F DOOR LIGHT.
4. SCAN COMPUTER CLEAR ALL INACTIVE CODES
NEED TEST NO CODE.
5. INSTALL REAR BRAKE SHOES AND DRUMS CLEAN
AND GREASE SLACK ADJ BRAKES.
6. TRACE WIRING FOR R/S MIDDLE PATIENT DOME
LIGHT AND REPAIR WIRING.
7. FABRICATE NEW VENT FOR L4 COMPT AND
INSTALL.
8. CHK REAR CAB A/C REMOVED FREON FOUND
FULLY CHARGED VACCUMED SYST.
9. INSTALL L/R CLEARANCE LIGHT.

Parts

Quantity

010263488-5010263488-5W CLEARANCE LIGHT LED	1
3744BRAKE DRUM REAR	2
6819634625SLENS	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DUFDT04-4P-RT03EL35674 DIODE PACK GRAY	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2

Workorder: V52848

In Date: 10/04/2012

Meter Reading: 111,083.00

Close Date: 12/17/2012

Problem?

HAVE ALLISON CHECK TRANSMISSION

Task performed:

HAVE ALLISON CHECK TRANSMISSION.

Parts

Quantity

NO PARTS USED

Vendor?: FLORIDA DETROIT DIES



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V54397

In Date: 12/12/2012

Close Date: 12/28/2012

Meter Reading: 116,176.00

Problem?

B INSPECTION R54

Task performed:

Parts

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

1. B-INSPECTION.
2. B-INSPECTION AND LOWER FLUID LEVEL IN REAR AXLE. INSTALL NEW AIR FILTER.
3. DASH RIGHT SIDE SWITCH TO A/C DUCT SUPPORT BROKEN - FABRICATE DRILL AND CUT/TAP ANCHOR HOLE IN PLATE, REASSEMBLE AND INSTALL A/C DUCT TUBE AND DOOR OPEN SWITCH
4. PATENT COMP DOME LIGHTS - REMOVE 3 BLOWN BULBS AND INSTALL NEW BULBS, FOUND ON ASSEMBLY SHORT TO GROUND REPAIR BAD CONNECTION.
5. FABRICATE SUPPORT TO REPLACE A/C FILTER KICK PANEL BROKEN SCREW HOLDERS - INSTALL.
6. AIR LEAK - FOUND SEVERAL AIR LINE CONNECTION SPLICE AND SHAFING LEAKS, CORRECT ALL FAULTS INCLUDING REPLACING WORN FITTINGS.
7. GROUND LIGHT OUT - FOUND BULB BLOWN AND GROUND CABEL CUT, REPAIR OUT CABLE AND INSTALL NEW BULB.
8. BATTERY TRAY JAMED - PRY LOOSE BATTERY TRAY - CLEAN SLIDES AND LOCK - LUBRICATE AND SLIDE TO ENSURE FREE ROLLING OF SLIDES ROLLER.
9. CAB A/C AND CAB REAR A/C COMPLAIN OF HIGH TEMP - CHECK SYSTEM PRESSURES HI AND LOW SIDE WITHIN NORMAL RANGE, FAN OPERATING NORMAL AUXILARY CONDENSOR OPERATING NORMAL TEMP OUT PUT REAR 28 DEGREES FRONT 29 DEGREES NO LEAK FOUND SYSTEM WORKING NORMAL.
10. REAR A/C BLOWING COOL - CHECK SYSTEM FOUND LOW ON FREON - RECOVER AND VACUUM SYSTEM, CHECK FOR VACUUM LOST NO PRESSURE LOST - CHARGE AND CHECK PRESSURES - PRESSURES NORMAL RANGE - NO LEAK FOUND CHANGE REAR FILTER AND UV BULB.
11. R-1 COMP. VENT MISSING - CUT AND INSTALL COVER PLATE.
12. DIAGNOSE ENGINE NOISE ON SHUT DOWN - PULL TURBO BOOTH, AIR FILTER, FOUND EGR FLEX PIPE BROKEN REMOVE PART.
12. FOUND EGR HEAD GASKET LEAKING - DRAIN COOLANT AND REMOVE EGR MANIFOLD. CLEAN PARTS - REASSEMBLE EGR MANIFOLD NEW GASKETS, NUT AND BOLT, INSTALL ON UNIT, FILL WITH COOLANT AND OPERATE, NO LEAKS.
13. LIGHT BOX NOT CHARGING - CHECK CHARGER OUT PUT 12.8 VOLTS. SYSTEM WORKING NORMAL REPLACE LIGHT BOX.
14. CAB NEAR CABINET LOCK INOP - LOCK MECHANISM SPRING MISSING - REMOVE LOCK INSTALL REPLACEMENT SPRING. REINSTALL, ADJUST LATCH AND SECURE.

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
2FC00ZCR4 IN ROUND LED	1
42809AIR FILTER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A9061420404PIPE	1
A9061420580GASKET	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
N000000001140BOLT	2
N910105008011BOLT	6
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

15. Q. INSPECTION.

Workorder: V53975

In Date: 11/25/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

When driving, a loud high pitched spitting sound is heard when the turbo is initiated. Despite the sound, there is no acceleration issues. R 54

Task performed:

Parts

Quantity

ROAD TESTED FOUND NO PROBLEM WITH MOTOR.

NO PARTS USED

Workorder: V55356

In Date: 01/29/2013

Meter Reading: 117,870.00

Close Date: 01/29/2013

Problem?

transmission getting stuck

Task performed:

Parts

Quantity

TRANSMISSION SHIFT AND POWER LOST CODES. SUPPLYING OUT UNIT. DRIVER COMPLAIN OF MULTIPLE OCCURANCE TRAVEL TO SHOP.

NO PARTS USED

Workorder: V55567

In Date: 02/05/2013

Meter Reading: 118,511.40

Close Date: 02/06/2013

Problem?

Check trans lite comes on and the vehicle remains in 3rd gear.. The vehicle also remains in D and would not switch to N to apply parking breaks.. No acceleration, when accelerator engage. R54

Task performed:

Parts

Quantity

CHECKED TRANS FOUND CODES - NEED TO SWAP OUT.

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V55388

In Date: 01/29/2013
Close Date: 02/07/2013

Meter Reading: 117,870.00

Problem?

repair transmission

Task performed:

1. DIAGNOSED TRANSMISSION PROBLEM PUT TRUCK ON LIFTS AND READ CODES.
2. DRAINED FLUID IN TRANSMISSION REMOVED VALVE BODY STARTED DISASSEMBLING VALVES AND SOLINIODS.
3. CONTINUED CLEAN UP ON TRANS PARTS AND STARTED REASSEMBLEY.
4. REBUILT VALVE BODY WITH NEW SOLINIODS AND SENSORS GASKETS AND INSTALLED INTO UNIT. FILLED WITH FLUID CHECKED ROAD TEST CHECKED FOR CODES.
5. ASSIST WITH LIFTING AND REMOVINGVALVE BODY.

Parts

Quantity

29506484PRESSURE SENSOR	1
29526898 29548988 TRANS FILTER ALLISON	1
29536722SOLENOID	2
29537371SOLENOID	4
29542681HARNESSE INTERNAL	1
29543433SPEED SENSOR	1
29544785KIT FILTER ASSY	1
2954479229544784 KIT-MD CONTROL GASKT	1
29545638SOLENOID	1

Workorder: V55152

In Date: 01/18/2013
Close Date: 02/12/2013

Meter Reading: 117,870.00

Problem?

Informed by both A&B shift that the vehicle has been hesitating and sometimes get stuck in gear (ie.. reverse). The vehicle has to be turned off/ on to operate normally. Has been an ongoing issue. R54

Task performed:

ROAD TESTED DID NOT HAVE PROBLEM. NO CODES - WILL NEED TO SWAP OUT.

Parts

Quantity

NO PARTS USED

Workorder: V56091

In Date: 03/01/2013
Close Date: 03/22/2013

Meter Reading: 119,237.00

Problem?

check transmission

Task performed:

ROAD TEST AND DIAGNOSE TRANSMISSION FAULT - TRANSMISSION SKIP AND SLAM INTO 1ST, 3RD STUCK IN 6TH WOULDNOT GO INTO NEUTRAL OR REVERSE. HAS STORED CODES.

Parts

Quantity

29543300MODULE TRANSMISSION CONTROL TCM	1
---	---



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V55629

In Date: 02/07/2013
Close Date: 04/04/2013

Meter Reading: 118,511.40

Problem?

repair transmission

Task performed:

1. SCAN COMPUTER CHECK TRANSMISSION CODES ALL INACTIVE RECORD CODES CLEAR AND TEST DRIVE.
2. FINISH DIAGNOSING TRANSMISSION REPLACE OUTPUT SPEED SENSOR CLEAR ALL CODES TEST DRIVE SECOND TIME ALSO LET IDLE 20MIN AND DRIVE.
3. TAKE ON LONG TEST DRIVE.

Parts	Quantity
29544139REAR SPEED SENSOR ALLISON	1

Workorder: V56227

In Date: 03/07/2013
Close Date: 04/05/2013

Meter Reading: 119,237.00

Problem?

repair transmission

Task performed:

REPAIR TRANSMISSION.

Parts	Quantity
NO PARTS USED	

Vendor?: FLORIDA DETROIT DIES

Workorder: V49891

In Date: 06/05/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

R54 is leaking coolant which emptied the resevoir

Task performed:

Parts	Quantity
012-1510-00-0HANDLE	1

Workorder: V52632

In Date: 09/25/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

rear outside patient compartment door handle is broken R 54

Task performed:

Parts	Quantity
HND5948TM22676-02 HANDLE DOOR ENTRY	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V56715

In Date: 03/29/2013

Close Date: 04/15/2013

Meter Reading: 119,237.00

Problem?

A-inspection

Task performed:

Parts

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

1. A-INSPECTION; ENGINE 3 QUTZ LOW ADD OIL.
2. LIGHTS - PATIENT COMPARTMENT LOW LIGHT INOP AND LEFT SIDE MARKER LIGHT INOP - REMOVE BLOWN LIGHTS AND INSTALL NEW BULBS
3. BUMPING NOISE AT SPEED BELOW 30 MPH - DIAGNOSING CAUSE. ROAD TEST FOUND BODY BUSHING BOLT LOOSE - RETORQUE AND CHECK ALL OTHER FOR LOOSENESS.
4. NATER PIN COVER - REMOVE DAMAGE COVER - REMOVE LOWER COMPARTMENT, NADER PIN LOOSE IN FRAME - RETAP PIN HOLD DOWN BOLT HOLE - REASSEMBLE - OVER SIZE PLATE AS NATER PIN COVER AND INSTALL.
5. L-2 TOOL HOLDER BROKEN; COAT HOOK DAMAGE OR BROKEN - REMOVE BROKEN TOOL HOLDER INSTALL REPLACEMENT ONE - CUT PLATE AND MOUNT OVER WOBBLE OUT HOLEN AND RETRY NEW HOLD DOWN FOR COAT HOOK AND MOUNT.
6. L-2 HOLD OPEN BENT - SUPPORT HOLE DAMAGE - REMOVE PART RETAP SUPPORT HOLE AND INSTALL NEW HOLD OPEN.
7. PATENT COMP - CABINET METAL STRAP FELL OFF - RETAP SUPPORT HOLES AND INSTALL METAL STRIP.
8. COOLANT LEAK PRESSURE TEST SYSTEM - FOUND EGR COOLER LEAKING - DRAIN COOLANT AND REMOVE EGR ASSEMBLEY - BENCH TEST EGR FOUND SUPPORT BRACKET CRACK ON PIPE - INSTALL NEW EGR TUBE RESECURE EGR ROTARY VALVE AND INSTALL NEW GASKETS. FILL AND OPERATE.
9. REAR TIRES WEAR GETTING CLOSE ROAD TECHS AND STATION DRIVERS WILL VISUALLY CHECK.
10. TRANSMISSION SHIFTING ROUGH - FAST ADAPT TRANSMISSION AND ROAD TEST.
11. RECHECK TRANSMISSION AND EGINE CODES AFTER ROAD TEST - NO CODE RETURN.
12. DIAGNOSING PARK BRAKE DASH LIGHT INOP - CHECK PRESSURE SW MODULE "A" GOOD, CHECK AND DOWN LOAD NODE #1FILES, CHECK WIRING HARNESS, PARK BRAKE CONTROLE MODULE INTERMITTING OPERATING - REMOVE INSTALL NEW MODULE FAULT CORRECTED.
13. ASSIST IN TROUBLESHOOTING PARK BRAKE LIGHT CIRCUIT.
14. ASSIST IN PARK BRAKE LIGHT CIRCUIT.
15. CAB A/C INTERMITING OPERATION - CHECK ALL ELECTRICAL CONNECTION AND FOUND A/C CONTROLE SWITCH SHOR - REMOVE AND INSTALL NEW CONTROLLER.
16. QC TRUCK.

- 322502BULB PATIENT GH22 1
- A22-57054-003A/C SWITCH 1
- A9061420580GASKET 1
- A90614206791EA9061421179 EGR COOLER 1
- A9061420880GASKET 1
- A9061421080GASKET EGR COOLER 1
- CLR9185209186-1500-20 MARKER LT.AMBER LED 1
- DDE/A0039973352EGR COOLING HOSE 2
- HLD374211 IN HOLD-OPEN 30LB 1
- NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS 1
- S777COUPLING NIPPLE 1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V57080

In Date: 04/16/2013
Close Date: 04/22/2013

Meter Reading: 120,176.00

Problem?

Flat L/R/O R-54

Task performed:

FLAT L/R/O R-54

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V57181

In Date: 04/22/2013
Close Date: 04/29/2013

Meter Reading: 120,563.00

Problem?

ON CALL NO A/C HEADLIGHT OUT R54

Task performed:

RECHARGED REAR A/C AND REPAIRED LEAK.
REPAIRED BAD GROUND ON CAB A/C. REPAIRED
CONNECTION ON LEFT SIDE HEAD LIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V57129

In Date: 04/18/2013
Close Date: 05/03/2013

Meter Reading:

Problem?

Master switch QO loader trips when the pt compartment ceiling AC is turned on.. *The M tank O2 guaze reads empty, depite a full M tank bottle..

Task performed:

1. REPAIRED O2 GAUGE AND TESTED.
2. TRACED OUT PROBLEM WITH 110, A/C UNIT
FOUND NEEDS NEW ONE.

Parts

Quantity

NO PARTS USED

Workorder: V57424

In Date: 05/02/2013
Close Date: 05/03/2013

Meter Reading:

Problem?

hard shift when changeing gears ,also slams into Drive or Reverse R54

Task performed:

FAST ADAPTED TRANS AND ROAD TESTED.

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V57368

In Date: 04/30/2013

Meter Reading:

Close Date: 05/16/2013

Problem?

Pt compartment AC is out.. r 54

Task performed:

Parts

Quantity

1. RECHARGED A/C AND REPAIRED LEAKS.

NO PARTS USED

Workorder: V57809

In Date: 05/17/2013

Meter Reading: 122,237.00

Close Date: 05/24/2013

Problem?

Rear a/c inop R54

Task performed:

Parts

Quantity

1. RECHARGE AND REPAIRED LEAK.

NO PARTS USED

2. REPAIRED REAR DOOR THAT WAS HARD TO OPEN.

Workorder: V57871

In Date: 05/21/2013

Meter Reading: 122,531.70

Close Date: 05/31/2013

Problem?

Roof leak R54

Task performed:

Parts

Quantity

1. RESEAL ROOF DUE TO HEAVY RAIN.

NO PARTS USED

2. REPAIRED REAR DOORS THAT WOULD NOT OPEN FROM THE INSIDE.

Workorder: V57872

In Date: 05/21/2013

Meter Reading: 122,531.70

Close Date: 05/31/2013

Problem?

No start R57

Task performed:

Parts

Quantity

1. FOUND BAD CONNECTION AT ECM REPAIRED AND TESTED.

NO PARTS USED

2. REPAIRED COOLANT LEAK AT VALVE ON RIGHT OF MOTOR.



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V58455

In Date: 06/15/2013

Meter Reading: 124,517.00

Close Date: 06/24/2013

Problem?

C inspection R54

Task performed:

1. C inspection
2. found broken headlight bulbs in both front headlights, and very dull, replace both front headlights and adjust
3. r/side officer step non skid tape missing, replace tape
4. parking brake valve knob hitting dash board when pushing in, remove material from dash to clear knob from hitting.
5. replace wiper blades
6. cab a/c blows cool, top off freon and check for leaks, none found at this time
7. map lite broken, replace lite
8. replace red dot a/c filter in cab
9. 2 knobs missing from red dot a/c in cab, install new knobs
10. L-2 inner compt. door will not open, adjust latches and strikers
11. replace pat. compt a/c filter
12. door struts on o2 pat compt. door inop, replace both struts
13. seat belt for EMT seat in pat. compt. falling off tighten bolts
14. stretcher locking bar broken, replace bar and adjust
15. pat. compt. lite over bench seat dim, replace bulb, pull lite assy. down found wires hooked up wrong, correct wiring. ok
16. striker covers for rear entry door broken, drill out new covers and install
17. l/side rear weather striping falling off entry door window, clean and reinstall
18. r/side upper amber marker lite inop, replace lite
19. service air dryer
20. service p/s
21. replace ultra violet lite in pat. a/c
22. air system leaks down overnight, trace out leak with soap and water, found air drain fitting leaking on air tank, replace fitting
23. 110v roof mounted a/c tripping breaker, remove and install new roof a/c, after install unit would not turn on, check wiring, check install, remove roof cover and found condenser fan hitting fan housing, adjust fan to clear housing, unit now turns on and blows cold 26 deg.
24. windshield washer inop, remove lines and clean out

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
090-0278STRECHER BAR NEW	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	26
322502BULB PATIENT GH22	1
39045HEADLITE KIT WITH SEALER	1
5008414CARTRIDGE DC100	1
63152HVAC UNIT ROOF MOUNTED	1
71R406018-2664 KNOB	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A06-51039-001A06-75732-005 RH HEAD LIGHT ASSY	1
A06-75732-004HEADLAMP LH M2	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	2
HLD3999GSS1715UV 30LB STRUT GAS	2
K022105PURGE VALVE AD-IP-IS	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V58494

In Date: 06/17/2013
Close Date: 06/24/2013

Meter Reading: 124,644.00

Problem?

*Broken bulb in the rt head light *Vehicle constantly low on oil, despite putting several quarts every shift. *Pt compartment compressor needs replacement, per tommy. *Vehicle needs restart to re cool cab.

Task performed:

repairs made on w/o#58455

Parts

Quantity

NO PARTS USED

Workorder: V58599

In Date: 06/21/2013
Close Date: 06/28/2013

Meter Reading: 124,517.00

Problem?

replace 4 rear tires 265/70/19.5

Task performed:

REPLACE 4 REAR TIRES 265/70/19.5

Parts

Quantity

297518265/70R19.5 BRIDGESTONE R250

4

Vendor?: BOULEVARD TIRE CENTE

Workorder: V59071

In Date: 07/14/2013
Close Date: 07/19/2013

Meter Reading: 125,346.00

Problem?

R54 front tires wearing badly and uneven. Outside of R front tire severely worn.

Task performed:

ORDER NEW TIRES.

Parts

Quantity

NO PARTS USED

Workorder: V59214

In Date: 07/19/2013
Close Date: 07/30/2013

Meter Reading: 12,616.00

Problem?

Replace front tires

Task performed:

REPLACE FRONT TIRES.

Parts

Quantity

297518265/70R19.5 BRIDGESTONE R250

4

Vendor?: BOULEVARD TIRE CENTE



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V59512

In Date: 08/02/2013
Close Date: 08/09/2013

Meter Reading: 127,179.00

Problem?

pat a/c inop

Task performed:

CHECK A/C R&R COMPRESSOR, FLUSH LINES,
REPLACE BELT AND DRYER, CLEAN CONDENSOR.

Parts

Quantity

071601A07-0602A DRIER A/C 7118

1

5790COMPRESSOR A/C

1

95609560 BELT

1

Workorder: V59434

In Date: 07/30/2013
Close Date: 08/12/2013

Meter Reading: 126,834.00

Problem?

cab a/c inop

Task performed:

REAR A/C IN CAB WAS NOT WORKING REMOVED
AND REPLACED RELAY.

Parts

Quantity

87401RY-30T RELAY 5 PIN 12V

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V61133

In Date: 10/09/2013

Meter Reading: 131,942.00

Close Date: 10/22/2013

Problem?

B insp. and repairs as needed. R-54

Task performed:

1. b insp.
2. mount N.Y hooks
3. radio speaker bracket broken in cab
4. belts squeel, replace fan belt and a/c belt
5. change pat. compt a/c filter
6. change red dot a/c filter
7. remove metal number plates, and install plastic plates and numbers
8. handle on bio hazzard door fell off, repair
9. air leak overnight, trace out air leaks and repair
10. remove rear wheels, drums and brakes, install new brake shoes, brake hardware and drums, install wheels, adjust brakes, road test, recheck brakes
11. replace wiper blades
- 12.cab a/c blows cool, check for leaks and repair, recharge system
13. replace missing lug nut covers

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
1501450007750USE 0775145	1
3744BRAKE DRUM REAR	2
5269LPVM-5 SM MOUNT	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9550 BELT	1
95609560 BELT	1
ACX-84534LUG NUT COVER PK10	20
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
RD4172-0THERMOSTAT	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V62411

In Date: 12/02/2013

Meter Reading: 134,745.00

Close Date: 12/12/2013

Problem?

R54 won't start

Task performed:

WONT START FOUND FUEL FILTER CAP CRACKED, REPLACED CAP AND PRIMED SYSTEM TEST DROVE AND STARTED TO CONFIRM REPAIR.

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V57857

In Date: 05/20/2013

Meter Reading:

Close Date: 01/21/2014

Problem?

water leaking into pt compartment

Task performed:

Parts

Quantity

REPAIRES COMPLETE.

NO PARTS USED

Workorder: V62908

In Date: 12/23/2013

Meter Reading: 136,156.00

Close Date: 01/24/2014

Problem?

front grill is loose and missing bolts R54

Task performed:

Parts

Quantity

1. REPAIRED GRILL AND REINSTALLED BACK ON TRUCK.
2. RECHARGED REAR A/C AND CHECKED FOR LEAKS.

NO PARTS USED

Workorder: V63020

In Date: 12/30/2013

Meter Reading: 136,874.00

Close Date: 01/24/2014

Problem?

replace rear vista screen

Task performed:

Parts

Quantity

REMOVED AND REPROGRAMMED VISTA SCREEN AND INSTALLED.

NO PARTS USED

Workorder: V63187

In Date: 01/07/2014

Meter Reading: 137,591.00

Close Date: 01/24/2014

Problem?

AIR LEAK R 54

Task performed:

Parts

Quantity

1. REPLACED PURGE VALVE - AND TESTED.
2. RECHARGED CAB A/C AND TESTED.

K022105PURGE VALVE AD-IP-IS

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V62732

In Date: 12/15/2013
Close Date: 01/27/2014

Meter Reading: 135,768.40

Problem?

Patient compartment door latch not working proeprly R54

Task performed:

REMOVED DOOR LATCH AND PANELS AND REPAIRED LATCH.

Parts

NO PARTS USED

Quantity

Workorder: V62733

In Date: 12/15/2013
Close Date: 01/27/2014

Meter Reading: 135,768.40

Problem?

Front cab A/C not blowing cold air R54

Task performed:

1. RECHARGED A/C SYSTEM AND CHECKED FOR LEAKS.
2. REAR DOOR HANDLE INOP REPLACED DOOR HANDLE.

Parts

HND5948TM22676-02 HANDLE DOOR ENTRY

Quantity

1

Workorder: V63757

In Date: 01/27/2014
Close Date: 02/03/2014

Meter Reading: 139,201.70

Problem?

cab a/c inop

Task performed:

1. A/C COMPRESSOR IMPLoded START REMOVE CAB A/C COMPRESSOR AND DRYER.
2. FINISH INSTALL COMPRESSOR AND DRYER CLEAN OUT LINES FROM COMPRESSOR TO DRYEF

Parts

533303-0609 A/C COMPRESSOR M2 4485

719707-0614A AC DRIER M2

Quantity

1

1

Workorder: V63552

In Date: 01/20/2014
Close Date: 02/12/2014

Meter Reading:

Problem?

airconditioning in cab blowing hot air R54

Task performed:

1. A/C INOP NEED NEW COMPRESSOR UNIT SENT TO SHOP.
2. INSTALL NEW SEAT BASE- AND TESTED.

Parts

181503PSSEAT SUSPENSION

Quantity

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V63992

In Date: 02/05/2014
Close Date: 02/25/2014

Meter Reading: 139,755.00

Problem?

seat base issue

Task performed:

INSTALLED NEW SEAT BASE AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V63866

In Date: 01/31/2014
Close Date: 02/26/2014

Meter Reading:

Problem?

The vehicle continue to have a freon leak of the front cab. The compressor was replaced last shift at the shop.

Task performed:

CHECK FOR LEAKS, FOUND THREE LINES LEAKING
REMOVE LINES SENT TO MAKO TO HAVE MADE,
INSTALL NEW LINES AND DRYER.

Parts

460153HOSE & FITTINGS ASSY
RD-5-7063-OP07-2618A/C DRIER 7155

Quantity

1
1

Workorder: V64620

In Date: 03/02/2014
Close Date: 03/03/2014

Meter Reading: 141,584.00

Problem?

no voltage

Task performed:

VOLTAGE Q.W WOULD NOT START. REPLACED
BATTERIES WOULD NOT CRANK FASTALTERNATOR
COCKED UP. SWAPTED UNIT INTO SPARE.

Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY
HP-31DBATTERY 950CCA HP-31D

Quantity

4
4

Workorder: V64199

In Date: 02/13/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

Stretcher bracket on the floor of the rescue has a broken weld.

Task performed:

1. REMOVED AND REPLACED STRETCHER
BRACKET.
2. REPAIRED MUD FLAP THAT WAS FALLING OFF.

Parts

NO PARTS USED

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V64684

In Date: 03/04/2014

Meter Reading: 141,584.00

Close Date: 03/18/2014

Problem?

Replace frozen alternator R54

Task performed:

1. REPLACE ALT, CUT BELT OFF AND MOVED TRUCK INTO SHOP- DISCONNECT BATT, REMOVED PATIENT COMP, BRKT AIR CLEANER AND TUBE AND ALT.
2. REPLACE ALT CONT SWAPTED PULLEY- REPLACED ALT- INSTALLED BRKTS MT BOLTS-R&R BELTS AND TENSIONER.
3. REPLACE ALT CONT; INSTALLED COMPRESSOR- REPLACED MOUNT BOLTS- INSTALLED AIR CLEANER- ASSEMBLY BATT CABLES- RAN AND CHK CHARGING SYSTEM- CHK OK.
4. CHK PATA/C- RAN UNIT- RECOVER FREON SYSTEM EMPTY LEAK TEST SYSTEM- FOUND HOSE BLOWN- REMOVED FENDER CLAMPS AND DISCHARGE HOSE- REPLACED ENDS AND HOSE.
5. CHK PAT A/C CONT LEAK TEST- TROUBLESHOOT AND REPAIR LEAKS- R&R DRIER- VAC AND CHARGE SYSTEM0 REASSEMBLED ALL PARTS.

Parts

Quantity

01-29866-118BELT ALT. M2	1
08-3001B4479 SPLICER B/L	1
4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT	1
95609560 BELT	1
A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1
HLD3999GSS1715UV 30LB STRUT GAS	2
RD-5-7063-OP07-2618A A/C DRIER 7155	1

Workorder: V64248

In Date: 02/15/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

Need engine oil for the rescue, the oil is at the low level and no oil at the station. Put two quarts in rescue and John (mechanic) said it should be good for weekend.R54

Task performed:

DROPPED OFF ENGINE OIL AT STATION.

Parts

Quantity

15W40QSYN OIL QT	12
------------------	----

Workorder: V64304

In Date: 02/18/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

The plastic placard holders are coming apart, losing adhesive

Task performed:

REPLACED ALL HOLDERS.

Parts

Quantity

NO PARTS USED	
---------------	--



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V64517

In Date: 02/25/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

AC blowing hot air in front cab R54

Task performed:

TRACED OUT PROBLEM FOUND BAD DIOADE.

Parts

Quantity

DUFDT04-4P-RT03EL35674 DIODE PACK GRAY

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V64694

In Date: 03/04/2014

Close Date: 03/24/2014

Meter Reading: 141,672.00

Problem?

C inspection R54

Task performed:

Parts

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

1. C-SERVICE.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
2. C-SERVICE.	0000902051FILTER FUEL 03 MERCEDES	1
3. CHK BATT SLIDES-PRIED OPEN BOX FOUND SLIDES LOOSE TIGHTENED MOUNT- CLEANED AND LUBED SLIDES AND LATCHES- CHK OK.	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
4. FOUND OFFICERS KICK PANEL BROKEN- CUT, DRILLED AND TILT ANGLE MOUNT PLATES- CHK OK	1501450007750USE 0775145	1
5. REPAIR AIR LEAKS- FRIED UP TRACK SPRAYED FITTINGS AND LINES R&R AIR TANK FITTINGS- RESEAL LINES- RAN AND CHK OK.	16-31498925 VALVE CORE	1
6. REPAIR VALVE COVER LEAK- REMOVED AIR TUBE- DISCONNECT BATT.	401581GASKET AXLE FL80 R002435	1
7. REPAIR VLAVE COVER LEAK- REMOVED EGR AND GRID HEATER CABLES, HOSES, BRKTS AND VALVE COVER- R&R COVER GASKET-CLEARED HEAD REASSEMBLED.	5008414CARTRIDGE DC100	1
8. REPAIR VALVE COVER LEAK; REPLACED AND REPAIRED HEATER CABLE AND TIED UP HOSES AND WIRES.	906-181-00-86OIL FILTER M2 SPINNER 57140	2
9. SERVICE AIR DRIER- R&R FILTER AND PURGE VALVE.	91-22WIPER BLADE	2
10. CHK COOLANT LEAKS- DRAW RAD- REMOVED HOSES CLAMPS RESREVOIR- REPAIRED LEAK AT RESEVOIR- REASSEMBLED FILED AND PRESS CHK OK.	A0000160521GASKET VALVE COVER	1
11. CHK CAB A/C- FOUND CAB A/C NOT COOLING-FOUND LEVEL LOW- RECOVER FREON- LEAK TEST-FOUND FITTING LEAKING- REDRIMMPED AND SEALED-R&R SHRADER CORES- LEAK TEST- VAC AND CHARGE- CHK OK.	A0000180133DIAPHRAM SEAL	1
12. FOUND PAT DOOR PANELS AND LATCHES LOOSE- TIGHTEN ALL SCREWS- REPLACED MISSING SCREWS- CHK OK.	A0079932401SPRING DIAPHRAM	1
13. FOUND NUMBER PLATE HOLDER OOSE- REMOVED PLATE BRKTS- REMOVED TYPE FROM HOLDERS AND TRUCK- REMOUNTED HOLDERS.	A9060160080GROMET VALVE COVER	7
14. FOUND L-REAR AXLE LEAKING- REMOVED AND WRONG STUDS- CLEANED AXLE AND HUB- ORDERED STUDS.	K022105PURGE VALVE AD-IP-IS	1
15. REPLACED WIPER BLADES.	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
16. REPLACED PATIENT COMP A/C FILTER.	VCC/36000006A/C FILTER CAB M2	1
17. INSTALLED NEW A.C FILTER COMPARTMENT DOOR LATCH (MISSING) FOR PATIENT A/C.		
18. INSTALLED 3 AXLE FLAME STUDS IN LEFT REAR CLEAN SURFACED INSTALLED NEW GASKET AND INSTALL AXLE. ROAD TESTED PUT TRUCK ON LIFT AND TOP OFF FLUID, PUT TRUCK ON JACK STANDS FOR TI5RE GUY.		
19. TOOK TRUCK OFF JACK STANDS, PERFORMED Q.A INSPECTION.		



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V65074

In Date: 03/20/2014

Meter Reading: 141,584.00

Close Date: 03/24/2014

Problem?

Replace rear tires

Task performed:

REPLACE REAR TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V65294

In Date: 03/29/2014

Meter Reading:

Close Date: 04/03/2014

Problem?

ac not blowing cold R54

Task performed:

PAT A/C HOT FOUND CHARGER LOW. WHILE CHARGING FOUND FAN CLUTCH BAD SWAPPED INTO SPARE.

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V65359

In Date: 04/01/2014

Meter Reading: 142,479.40

Close Date: 04/15/2014

Problem?

fan clutch faulty and water pump starting to get damaged

Task performed:

1. FAULTY FAN CLUTCH AND WATER PUMP- R&R FAN CLUTCH AND WATER PUMP AND FUEL PUMP AND COOLANT LINE AND FUEL LINE.
2. PAT COMPARTMENT A/C INOP-FREON LEAK AT CRIMP- REMOVED OLD CRIMP AND REPLACED WITH NEW- DELIVERED TO STATION.
3. Q.A TRUCK FROM FAN CLUTCH AND WATER PUMP REPAIR DURING TEST DRIVE, ASSIST WITH AN AUTO ACCIDENT AT 45TH STREET AND HAVERHILL.

Parts	Quantity
0128042000PULLY TENSON	1
08-3001B4479 SPLICER B/L	1
4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT	1
9060910580FUEL PUMP GASKET M2	1
9062030015PIPE SOCKET TO WP	1
9550 BELT	1
A0020941580GASKET FUEL HOUSING	2
A17-14297-000HOOD LIFT CLY A17-14297-002 M2	1
A9060901276A9060903376 FUEL LINE	1
A9061302457PIPE AIR INLET COMPRESSOR	1
A9062030102A9062037102 COOLANT LINE	1
A9062032402WATER LINE M2	1
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R0040910501FUEL PUMP M2	1
DDE-R90620043019062006301 WATER PUMP SOME M2 CI	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/A0279976048O-RINGS M2 WATER PUMP	2
FREIGHTSHIPPING CHARGES	3
HOR/991450HT 650 FAN ASY.	1
N000000001069SEAL BANJO	4

Workorder: V65856

In Date: 04/21/2014

Meter Reading: 133,294.40

Close Date: 04/22/2014

Problem?

replace two tires

Task performed:

replace two tires

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V66625

In Date: 05/20/2014
Close Date: 05/21/2014

Meter Reading: 145,689.40

Problem?

R54 no rear pt lights

Task performed:

TRACED OUT PROBLEM FOUND BAD CONNECTION ON NODE-2 REPROGRAMMED NODE-2 AND TESTED OK.

Parts

Quantity

NO PARTS USED

Workorder: V66020

In Date: 04/28/2014
Close Date: 05/22/2014

Meter Reading:

Problem?

The stretcher hook that keeps the Stryker stretcher in place came off. R54

Task performed:

1. REINSTALLED STRETCHER HOOK IN REAR OF RESCUE.
2. READJUSTED REAR DOORS THAT WERE HARD TO OPEN.

Parts

Quantity

NO PARTS USED

Workorder: V66434

In Date: 05/12/2014
Close Date: 06/11/2014

Meter Reading:

Problem?

THEYELLOW SHORE LINE CAP HAS BROKEN. NEEDS REPLACEMENT, CAN NOT BE REPAIRED.

Task performed:

- 1) replaced auto eject cover.
- 2) repaired stretcher latch and tested.

Parts

Quantity

NO PARTS USED

Workorder: V66913

In Date: 06/02/2014
Close Date: 06/23/2014

Meter Reading:

Problem?

A/C NOT WORKING IN PATIENT COMPARTMENT

Task performed:

traced out problem found a/c broken removed and replaced

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V67439

In Date: 06/24/2014
Close Date: 07/03/2014

Meter Reading: 148,063.30

Problem?

Coolant leak

Task performed:

REPAIRED COOLANT LEAK AT LOWER HOSE OF ENGINE.

Parts

NO PARTS USED

Quantity

Workorder: V67955

In Date: 07/16/2014
Close Date: 07/25/2014

Meter Reading:

Problem?

AIR CONDITIONER IN RESCUE 54 CAB FRONT VENTS AND REAR VENTS NOT WORKING

Task performed:

R&R BLOWER MOTOR .
R&R BATTERY SW.

Parts

75908SWITCH BATTERY MASTER 300A
VCC/35000003BLOWER MOTOR VCCT1000904A M2

Quantity

1
1

Workorder: V67995

In Date: 07/18/2014
Close Date: 07/25/2014

Meter Reading: 150,048.00

Problem?

rear door not opening

Task performed:

READJUSTED REAR DOOR LINKAGE.

Parts

NO PARTS USED

Quantity

Workorder: V68382

In Date: 08/04/2014
Close Date: 08/04/2014

Meter Reading:

Problem?

R54 WILL NOT START. R54 WAS PULLED OUT TO BE REFUELED AND IT WOULD NOT TURNOVER. THE BATTERY COMPARTMENT IS LOCKED.

Task performed:

1. travel to sta. 54 check for no start, found starter bad, hit starter to work, have crew drive to s/shop, put up on lift and replace starter..

Parts

83000266831 38MT 11 TOOTH STARTER

Quantity

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V68383

In Date: 08/04/2014

Meter Reading:

Close Date: 08/04/2014

Problem?

turned truck off and now it wont start

Task performed:

repaired on w/o#68382

Parts

Quantity

NO PARTS USED

Workorder: V68452

In Date: 08/06/2014

Meter Reading:

Close Date: 08/06/2014

Problem?

It took several attempts to get the vehicle to started on each call (x3) we ran last night.

Task performed:

1. check for no start, when starting loud click sound from start solenoid intermittly, check battery's found 3 bad, replace 3 battery's, replace start solenoid. seems to start ok

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY

3

HP-31DBATTERY 950CCA HP-31D

3

Workorder: V68434

In Date: 08/05/2014

Meter Reading: 151,552.20

Close Date: 08/07/2014

Problem?

pat a/c inop

Task performed:

TRAVEL TO STA,54 FOUND PATIENT A/C INOP CHARGED UNIT AND TESTED NO LEAKS VISABLE.

Parts

Quantity

NO PARTS USED

Workorder: V68484

In Date: 08/07/2014

Meter Reading: 151,621.00

Close Date: 08/08/2014

Problem?

truck intermittent no start

Task performed:

1.Check unit for no start. Test ignition switch, fire wall, solenoid and started. Found starter motor not working right. Remove and replace condition still .Check system again. Found new starter is doing the same. Replaced starter with AC. Delco factory starter and condition. Went away , unit is good now.
2.Assisted with troubleshoot of no start condition.

Parts

Quantity

83000266831 38MT 11 TOOTH STARTER

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V67896

In Date: 07/14/2014
Close Date: 08/15/2014

Meter Reading: 150,524.00

Problem?

B inspection R54 by OCS

Task performed:

B inspection
oil and filter

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Vendor?: OCS

Workorder: V68354

In Date: 08/02/2014
Close Date: 08/18/2014

Meter Reading:

Problem?

needs windshield replaced, crack to passneger side of windshield R54

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: SAFELITE AUTOGLASS

Workorder: V68768

In Date: 08/19/2014
Close Date: 08/22/2014

Meter Reading: 15,259.40

Problem?

no cab a/c

Task performed:

recharged system and ck, for leaks.

Parts	Quantity
NO PARTS USED	

Workorder: V69156

In Date: 09/03/2014
Close Date: 09/19/2014

Meter Reading:

Problem?

Patient a/c

Task performed:

REAR A/C ,CLEANED CONDENCER FANS AND ROAD TESTED
REAR STEP ,WRONG SIZE WILL REORDER.

Parts	Quantity
W000349RUNNING BOARD	1



7/2/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V69759

In Date: 09/29/2014
Close Date: 10/03/2014

Meter Reading: 155,602.50

Problem?
starter inop

Task performed:

Replaced starter.

Parts

Quantity

820007539MT 11 TOOTH

1

Workorder: V69353

In Date: 09/13/2014
Close Date: 10/31/2014

Meter Reading: 154,653.00

Problem?
Right scene light is out. The one near the back of the truck. R54

Task performed:

Repaired rear scene light

Parts

Quantity

NO PARTS USED

Workorder: V70118

In Date: 10/14/2014
Close Date: 11/04/2014

Meter Reading: 156,670.50

Problem?
r54 no pat a/c

Task performed:

Patient A/C inop-Checked for leaks , filled with b4 and tested.

Parts

Quantity

0775145PANEL FILTER

1

4411S08-6962BS 90 DEGREE SB1322

1

W000349RUNNING BOARD

1



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V70608

In Date: 10/31/2014
Close Date: 11/04/2014

Meter Reading: 157,860.00

Problem?
no pat a/c

Task performed:

Parts

Quantity

1. Diagnose leaks in patient A/C also found leak in cab A/C system-help Norris with repairs.
2. Remove and replace step bumper-had to drill all new holes in hinge and steel frame at rear of vehicle also had to remove petrified masking tape and adhesive from replacement bumper.
3. A/C diagnostics-find leaks in patient compartment A/C system,bad crimp in high pressure hose-Recrimp crimp and retest all leaks fixed. Vaccum and recharge.
4. Cab A/C leak , freon leak at condensor bad crimp 90 degree elbow. Remove 90 degree elbow and install new elbow and crimp hose, retest system. All leaks fixed vaccumed system and recharged system.

NO PARTS USED

Workorder: V69894

In Date: 10/04/2014
Close Date: 11/05/2014

Meter Reading: 156,210.80

Problem?
All four rear tires have low tread on R54 10167685

Task performed:

Parts

Quantity

Checked tires and will have installed all four rear.

NO PARTS USED

Workorder: V70300

In Date: 10/20/2014
Close Date: 11/10/2014

Meter Reading: 157,098.00

Problem?
Scene light is not functioning R54

Task performed:

Parts

Quantity

Repaired scene light that was not working

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V70867

In Date: 11/12/2014

Close Date: 11/24/2014

Meter Reading: 157,860.00

Problem?

C inspection R54

Task performed:

Parts

Quantity



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

1. "C" inspection, replaced air filter and air tires.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
2. Replaced wiper blades	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
3. Windshield washers inop-found pinched hoses and nozzle position not correct. Straighten out washer tube and position nozzles correctly. Tie strap nozzles and hose to arm.	06-52125-036HORN ASSEMBLY M2	1
4. Replaced cracked washer bottle cap	15W40BSYN OIL BULK QTS	25
5. Replaced broken r front cab door switch. Test switch for operation of dome and ground lights-ok.	18-46375-00018-46375-004 TREAD PLATE LH M2	2
6. Replaced front cab and rear A/C filters. Install screw missing from front cover.	18-46375-00118-46375-005 TREAD PLATE RH M2	1
7. Replaced L rear cab floor board rocker panel.	22-58581-000WASHER RESIVOR CAP	1
8. Rpelaced R front compt. dome light bulb	27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
9. Removed mastic from missing reflector on R rear cab door. Installed new reflector	29526898 29548988 TRANS FILTER ALLISON	1
10. Remove R54 decals, accredited decals and campaign frames. Remove adhesive and buff out body with compound.	322502BULB PATIENT GH22	1
11. Replaced 3 flashlight charger bases-wire basses and protect with loom.	341-R341-R REFLECTOR RED	1
12. Replaced rear brake shoes,drums and hardware-adjusted brake shoes.	3744BRAKE DRUM REAR	2
13. Trans service	42809AIR FILTER M2	1
14. Replaced map light-splice wires cut out opening in base and opened up hole in dash.	487389HOSE & FITTINGS	1
15. Tighten L-4 latch screws	621714 IN LIGHT	1
16. Patient compt. step light missing-found light inside body. Retrieve light clean light socket. Install in rubber light gromet.	78R536078R5360M 2PK FILTER AIR COND	1
17. O2 compartment light inop-found bad light. Replaced with new style, splice in wires. Test ok	91-22WIPER BLADE	2
18. Clean fuel cap and paint	94993PIGTAIL TRUCKLITE 3-WIRE	1
19. Replaced L front and R front missing lug nut covers	A0149974148SEAL RING CAP	1
20. Remove non skid safety stripping-remove glue,cut and install new strip.	A3660180106CAP DIPSTICK	1
21. Rear patient compt. door nader pin loose-remove nader cover. Adjusted nader pin and tightened, lubricate latches. Install cover.	H50SN12BULB	1
22. Side patient door weather strip loose. Remove strip, clean and glue back on body.	KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
23. Replaced bulb in R side rear scene light. Remove broken socket from fixture	LF18TS-LEDMAP LIGHT LED 18 IN	1
24. Left rear scene light not bright. No LED in stock, ordered part.	MG-C23SPMGC23 GAUGE	1
25. Replaced patient compt. fire extinguisher not secure-found bracket bent. Straightened bracket and secure extinguisher	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
26. Rear patient compt fire extinguisher not secure found bracket bent. Straightened bracket and secure extinguisher.	UVAPS253 UNIT UV LIGHT A/C RESCUES	1
27. L-3 hinge block bolts loose, tightened screws	UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
28. Tighten L-2 coat hooks	VCC/36000006A/C FILTER CAB M2	1
29. L-2 inside door won't open-removed door panel and unstick latches on nader pins. Found tap nader pin to		



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

high, shimmed pin with washer. Adjusted nader pins-lube latches and hold opens, install panel.

30. o2 gauge reads inaccurate-replaced gauge battery tray won't open. Pry battery open remove cover from tray to expose linkage. Found lever on handle not actuating latch due to lever being bent. Remove linkage and handle, straighten lever. Reinstall linkage and handle tie strap linkage to secure. Adjust linkage-install cover and lube latches-test ok.

31. Vehicle pulls right-raise and support vehicle. Removed front wheels and switched left and right wheels, straighten out bent hubcaps. Test drive ok

32. Diagnose city horns inop-found both horns bad. Replaced horn assembly-test ok.

33. B post trim panel loose-found missing screws and broken trim piece. Rpelaced screws and installed with washers to secure broken trim piece.

34. Rear AC blowing only cool-diagnose problem found freon low. Leak check and found leak at hose.

35. Rear AC blowing only cost-diagnose problem. Found freon low-leak check and found leak at hose splice. Recover freon remove right aluminium step,removed hose for repair and install hose back from Mako. Install heat shield around hoses, secure with tie straps and clumps. Vacuum system and charge.

36. Front AC only blowing cool, diagnose problem-found freon leak at both ends of discharge hose. Remove hose after recovering freon,sent out for new hose to be made by Mako hose. Install hose back from Mako secure hose, vacuum system, charge and test ok.

37. Diagnose air leaks-found air leaks at foot valve fittings and replaced fittings

38. AC UV light inop. removed assembly replaced bulb, reinstall assembly. Test-no good, replaced new bulb with another new bulb-test ok.

LINES 39-50 ON WO#



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V71168

In Date: 11/24/2014

Meter Reading: 157,860.00

Close Date: 12/01/2014

Problem?

P.M. follow up repairs continued from W.O. 70786

Task performed:

Parts

Quantity

CONTINUED FROM WO# 70867

NO PARTS USED

39. Measure truck height, make decals for height clearance and asset number and apply to windshield.

40. Replace drivers rocker panel

41. Right side ground light bracket bent-remove bracket. Straighten bracket, reinstall-found screw threads stripped. Repair threads.

42. Check torque on all U-bolts

43. Replaced R front rocker panel37. Diagnose air leaks-found air leaks at foot valve fittings and replaced fittings

44. Air horns inop-free up trumpet from base lubricate threads. Adjusted horns for sound quality.

45. P/S leak-clean area. Found loose hose clamp at reservoir, tighten clamp. Test for leak-ok.

46. Oil leak by oil filter housing-found loose hose clamps on road draft blow by hose. Tightened clamps and degrease area-check for leak,ok.

47. Oil leak at dipstick tube-found bad o-ring and cap on dipstick. Replaced o-ring and cap clean area, check for leaks.

48. Battery charger inop-found blown fuse replaced fuse test ok.

49. L side B-post trim pieces loose-remove rocker panel for access. Install missing screw on outside seat belt trim piece and reinstall rocker panel.

50. Q&A

Workorder: V71472

In Date: 12/08/2014

Meter Reading: 158,454.00

Close Date: 12/08/2014

Problem?

a/c not working

Task performed:

Parts

Quantity

Traced out problem found bad connection on compressor

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V71611

In Date: 12/12/2014

Meter Reading:

Close Date: 12/15/2014

Problem?

Front Brake on R/46 has a strong smell of burning.

Task performed:

Parts

Quantity

Brakes smell-test drove truck-check drum temps-adjusted all brakes-checked stroke-right/ r was to tight

NO PARTS USED

Workorder: V72377

In Date: 01/15/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Stretcher Asset # 10192793 continues to go to the up position. R91

Task performed:

Parts

Quantity

called EMSAR

NO PARTS USED

Workorder: V71767

In Date: 12/19/2014

Meter Reading: 159,380.00

Close Date: 01/20/2015

Problem?

A inspection

Task performed:

Parts

Quantity

1. A inspection-straighten L R I valve stem
2. Diagnose no dome or flashing light on door with door open-found bad doorswitch. Replaced switch
3. Diagnose no city horns-found no power to horns. Checked fuses at elft fender ok. Checked horn switch (ok) checked node book for info-no corners build date. Removed radio counsel cover-checked for relay. Removed drivers kick panel and rocker cover remove siren control head. Could not locate horn relay only one for siren switch thorough node need node sheets if wired by whelery.

S986AIR GAUGE 160 PSI

2



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V70176

In Date: 10/15/2014
Close Date: 01/23/2015

Meter Reading: 156,670.50

Problem?

changed rear tires

Task performed:

changed rear tires

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V73828

In Date: 03/12/2015
Close Date: 03/17/2015

Meter Reading:

Problem?

Ater parking there is an airleak sound from the rear drivers side. The MOD did not raise up and rear appaers to be riding low. We are not getting a low air pressure alarm. We are at HQ for WPE training.

Task performed:

1. Leak in air system. Found left air ride leveling valve leaking. Repalced both leveling valve and adjusted ride height.

Parts

Quantity

S4640024430VALVE LEVELIN

2

Workorder: V74513

In Date: 04/08/2015
Close Date: 04/21/2015

Meter Reading: 163,445.30

Problem?

REPLACE STEER TIRES

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX

Workorder: V74504

In Date: 04/08/2015
Close Date: 04/23/2015

Meter Reading:

Problem?

A/C 10/7 in the cab(4 door) back A/C

Task performed:

1. Travel to station 16. Check out A/C inop. Found no problem with cab A/C. Add freon to pt compt A/C. Had to go to shop for freon.

Parts

Quantity

NO PARTS USED



7/2/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10167685

ALS RESCUE VEHICLE ADVANCED LIFE SUPPORT

Workorder: V73625

In Date: 03/04/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Volume control of radio in the cab is not working R43

Task performed:

Parts

Quantity

1. Repaired AM/FM radio that was out.

NO PARTS USED

Workorder: V73850

In Date: 03/12/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

The main AC does not always blow cold, but the unit does operate when setting knob is turned. The AC unit in the rear cab has been shutting off on its own while the rescue is moving. @43

Task performed:

Parts

Quantity

1. Tested unit found no problem at this time.

NO PARTS USED

Workorder: V74068

In Date: 03/21/2015

Meter Reading:

Close Date: 05/04/2015

Problem?

The rear AC unit in the cab will shut off on its own while the vehicle is on. This is intermittent, happened once during my 12 hour shift. R43

Task performed:

Parts

Quantity

1. Repaired bad connection on A/C.

NO PARTS USED

Workorder: V74243

In Date: 03/27/2015

Meter Reading: 163,264.00

Close Date: 05/06/2015

Problem?

A inspection

Task performed:

Parts

Quantity

1. A-Inspection. Top off low oil level. Fill windshield washer add bug slovent.

27-102A22-54259-000 DOOM LIGHT SWITCH M2

1

2. a) A/C vent register fell off. Reinstall. b) Removed damage A/C filter- install new filter.

78R536078R5360M 2PK FILTER AIR COND

1

3. Officers door switch broken- Remove and install new door switch.



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10167685) 2006 - AMERICAN LAFRAN M2 Advanced Life Support Vehicle

10167685

CSHOP-2015-1217

Comments: A INSPECTION SR6

Date Opened: 6-16-2015

Date Finished

6-23-2015

Meter 1 Reading:

166,645

TASKS PERFORMED

NO PARTS USED

A INSPECTION
FAULT CODE

CSHOP-2015-2395

Comments: TOW UNIT TO FLA. DETROIT

Date Opened: 8-19-2015

Date Finished

12-1-2015

Meter 1 Reading:

169,582

TASKS PERFORMED

NO PARTS USED

TOWING HITCH

VENDOR? WESTWAY TOWING

CSHOP-2015-3197

Comments: SR6 CAB A/C INOP

Date Opened: 10-2-2015

Date Finished

10-2-2015

Meter 1 Reading:

167,549

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2015-3491

Comments: R37 IN SPARE, WONT START

Date Opened: 10-19-2015

Date Finished

10-26-2015

Meter 1 Reading:

168,249

TASKS PERFORMED

Q PARTS

RADIATOR
STARTER
AIR DRIER

1	HOSE; UPPER RAD HOSE M2
1	HOSE; HOSE - LOWER RAD.
1	RADIATOR; FRE04 RADIATOR
1	MODULE; MODULE BULK HEAD FIREWALL
1	NEWPART; PROGRAM MODULE
1	BRAKE; CARTRIDGE DC100
1	VALVE; PURGE VALVE AD-IP-IS

Asset Work Order History 10167685

CSHOP-2015-3671

Comments: **ADJUST STRETCHER BRACKET AT ST81**

Date Opened: 10-29-2015 Date Finished: 11-2-2015 Meter 1 Reading: 168,326

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FIRE APPARATUS

1 **BAR; STRECHER BAR NEW**

CSHOP-2015-3693

Comments: **SPARE RESCUE AT AIRPORT, BACK UP CAM INOP AND 12 V PLUG IN CAB INOP**

Date Opened: 11-2-2015 Date Finished: 11-17-2015 Meter 1 Reading: 168,431

TASKS PERFORMED

Q PARTS

A INSPECTION
WIPER BLADES
WIPERS-WASHER
CHARGING SYSTEM
CAMERA-MONITOR
HVAC SYSTEM

2 **WIPER; WIPER BLADE**

Service Requests:

10/31/2015 BODY / 12: BROKEN / REPAIR
BACK UP CAMERA NOT WORKING.

10/31/2015 BODY / 12: BROKEN / REPAIR
12 VOLT CHARGER NOT WORKING IN CAB OF VEHICLE. NOT ABLE TO UTILIZE TO KEEP SAFETY PAD CHARGED.

CSHOP-2015-4059

Comments: **SR@36 AIR LEAK**

Date Opened: 11-19-2015 Date Finished: 12-8-2015 Meter 1 Reading: 170,177

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

11/19/2015 A/C / 19: LOOSE / REPAIR
A/C IN THE PATIENT COMPARTMENT KEEPS BLOWING COLD THEN HOT HUMID ARI.

11/27/2015 ALARMS / 19: LOOSE / REPAIR
AIR HORN ON RESCUE IS NOT WORKING. EVEN WHEN THE RESCUE IS FULL OF AIR IT WILL NOT WORK.

Asset Work Order History 10167685

CSHOP-2015-4594

Comments: **SR6 B INSPECTION**

Date Opened: 12-22-2015 Date Finished 12-23-2015 Meter 1 Reading: 170,892

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; FUEL FILTER 33813 L/F # LFF5851

CSHOP-2015-4595

Comments: **REPAIRS FROM INSPECTION**

Date Opened: 12-22-2015 Date Finished 12-23-2015 Meter 1 Reading: 170,892

TASKS PERFORMED

Q PARTS

SWITCH
SERPENTINE BELT
OIL
LIGHTING SYSTEM
BATTERY
DOOR PANEL

1 WIPER; A06-36956-003 WIPER-TURN SWITCH
1 BELT; BELT
1 BELT; BELT ALT. M2
1 GROMMET; 91740 GROMMET T/L 4 IN
1 LIGHT; LED GROUND LITE CLEAR
2 LIGHT; 9186-1500-20 MARKER LT.AMBER LED
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D

CSHOP-2015-4709

Date Opened: 12-30-2015 Date Finished 1-5-2016 Meter 1 Reading: 170,850

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-532

Comments: **A INSPECTION SR6**

Date Opened: 5-8-2015 Date Finished 5-11-2015 Meter 1 Reading: 164,450

TASKS PERFORMED

NO PARTS USED

A INSPECTION
DOOR
HVAC SYSTEM

Asset Work Order History 10167685

CSHOP-2015-594

Comments: **ENGINE LIGHT ON SR @ 19**

Date Opened: 5-12-2015 Date Finished 5-13-2015 Meter 1 Reading: 164,450

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

CSHOP-2015-908

Comments: **SPARE RESCUE AT 19, LEFT AIRBAG MALFUNCTION**

Date Opened: 6-1-2015 Date Finished 6-1-2015 Meter 1 Reading: 164,450

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 BRAKE; NGR-27-SWA-110R BRAKE MODULE M2
A12-19776-010
1 VALVE; A12-19772-355 AMU03 M2 VALVE ASSY

CSHOP-2015-991

Comments: **SUSPENSION LEANING SPARE RESCUE AT 19**

Date Opened: 6-4-2015 Date Finished 6-4-2015 Meter 1 Reading: 166,645

TASKS PERFORMED

NO PARTS USED

SUSPENSION

CSHOP-2016-1719

Comments: **NO CAB A/C**

Date Opened: 4-11-2016 Date Finished 4-11-2016 Meter 1 Reading: 177,420

TASKS PERFORMED

Q PARTS

A/C BLOWER OPERATES
HVAC SYSTEM

1 9IP; AC WIRE HARNESS
1 HARNESS; JUMPER HARNESS
1 MOTOR; BLOWER MOTOR VCCT1000904A M2
1 A/C; 17-3428 ESTER OIL E7

CSHOP-2016-1754

Comments: **SR AT ST52**

Date Opened: 4-13-2016 Date Finished 4-20-2016 Meter 1 Reading: 177,585

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
HVAC SYSTEM

1 9IP; SWITCH DIMM

Service Requests:

04/13/2016 LIGHTS / 19: LOOSE / A
LEFT TURN SIGNALS NOT WORKING SHOWS IN THE TRUCK THAT IT WORKING AND PANEL LIGHT DON'T COME ON AT NIGHT. THIS WASN'T FOUND UNTIL 1ST CALL WAS AT NIGHT AFTER SWAPPING RESCUE.

Asset Work Order History 10167685

CSHOP-2016-1952

Comments: **CHECK ALL TIRES ON R52**

Date Opened: 4-25-2016 Date Finished 4-26-2016 Meter 1 Reading: 177,874

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TIRES & WHEELS
HVAC SYSTEM

Service Requests:

04/23/2016 TIRES / 19: LOOSE / REPAIR
ALL TIRES HAVE LOW TREAD

CSHOP-2016-2090

Comments: **REPLACE FRONT TIRES**

Date Opened: 5-2-2016 Date Finished 5-2-2016 Meter 1 Reading: 178,127

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-230

Date Opened: 1-19-2016 Date Finished 1-25-2016 Meter 1 Reading: 171,991

TASKS PERFORMED

NO PARTS USED

DOOR PANEL

Service Requests:

01/17/2016 DOOR / 19: LOOSE / ADJUST
BACK DOOR TO PATIENT COMPARTMENT NOT LATCHING AT THE TOP, ONLY LATCHES AT THE BOTTOM.

CSHOP-2016-2329

Comments: **SR @ ST52**

Date Opened: 5-16-2016 Date Finished 5-24-2016 Meter 1 Reading: 178,909

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
HVAC SYSTEM

2 LAMP; HEADLAMP M2 HI

Service Requests:

05/15/2016 LIGHTS / 19: LOOSE / A
DRIVER SIDE HEADLIGHT OUT, ST 52

05/15/2016 A/C / 19: LOOSE / S
SHORE LINE AC UNIT LEAKING WATER INTO PASSENGER COMPARTMENT

Asset Work Order History 10167685

CSHOP-2016-2737

Date Opened: 6-8-2016 Date Finished 7-4-2016 Meter 1 Reading: 179,817

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
HVAC SYSTEM

1 SIREN; SIREN DRIVER SMALL

CSHOP-2016-3333

Comments: **FREON ONLY**

Date Opened: 7-11-2016 Date Finished 8-6-2016 Meter 1 Reading: 181,222

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

3 A/C; FREON LB

CSHOP-2016-3711

Comments: **SPARE RESCUE AT 52 O2 LEAK**

Date Opened: 8-1-2016 Date Finished 8-6-2016 Meter 1 Reading: 181,222

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS
INSTRUMENTS-GAUGES-METERS

Service Requests:

07/29/2016 SERVICE REQUEST / 44: WORN / EXCHANGE - NEW
O2 SYSTEM ON SPARE RESCUE AT 52 HAS BIG LEAK AT GAUGE

CSHOP-2016-4021

Date Opened: 8-16-2016 Date Finished 8-16-2016 Meter 1 Reading: 181,222

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-4489

Comments: **SPARE RESCUE AT ST52**

Date Opened: 9-15-2016 Date Finished 9-15-2016 Meter 1 Reading: 182,259

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL
HVAC SYSTEM

Service Requests:

09/14/2016 A/C / 19: LOOSE / REPAIR
A/C ISSUE. HOT AIR BLOWING FROM BOTH CAB AC UNITS

Asset Work Order History 10167685

CSHOP-2016-4552

Comments: **REPAIRS FROM PM**

Date Opened: 9-19-2016

Date Finished 10-13-2016

Meter 1 Reading: 182,730

TASKS PERFORMED

A INSPECTION
COMPARTMENT LIGHT BODY
WASHER NOZZLE
COOLING SYSTEM
DOME LIGHTS
TURN SIGNAL LIGHTS
TIRES ALL
A/C LEAK TEST
A/C LOW FREON
A/C FILTER
HOSES-LINES & FITTINGS

Q PARTS

1 LAMP; LED TURN SIGNAL LAMP
1 9IP; BULB PATIENT GH22
1 FILTER; PANEL FILTER
1 FILTER; 78R5360M 2PK FILTER AIR COND
1 FILTER; A/C FILTER CAB M2
1 DRYER; 07-2618A A/C DRIER 7155
1 SWITCH; 11-0616 BINARY SWITCH
1 NEWPART; HOSE & FITTINGS
1 NEWPART; HOSE & FITTINGS
1 NEWPART; HOSE & FITTINGS

Service Requests:

09/18/2016 A/C / 12: BROKEN / REPAIR
A/C ISSUE, FRONT CAB BLOWS ONLY HOT AIR

CSHOP-2016-4971

Comments: **PART 241637 ON ORDER CHECK ON PART AIR LEAK NEAR POSSIBLE AIR BAG CHECK AC**

Date Opened: 10-18-2016

Date Finished 12-6-2016

Meter 1 Reading: 184,997

TASKS PERFORMED

SUSPENSION

Q PARTS

2 BRAKE; 16-19471-000 AIR BAG

CSHOP-2016-5058

Comments: **SR6 AT 16 A/C NOT WOKRING.**

Date Opened: 10-24-2016

Date Finished 11-8-2016

Meter 1 Reading: 184,036

TASKS PERFORMED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Q PARTS

1 COMPRESSOR; 03-0609 A/C COMPRESSOR M2 4485
1 DIODE; EL35674 DIODE PACK GRAY
1 DRYER; 07-0614A AC DRIER M2

Service Requests:

10/23/2016 A/C / 12: BROKEN / REPAIR
A/C ISSUE IN FRONT CAB OF TRUCK. DRIVER AND OFFICER SIDE AC BLOWS OUT HOT AND REAR PARAMEDIC SEAT IN FRONT CAB AC DOESN'T BLOW OUT INTERMITTENTLY. FRONT CAB AC BUTTON IS ENGAGED ON COMPUTER DISPLAY HOWEVER PROBLEM CONTINUES.

CSHOP-2016-5243

Comments: **ROAD CALL BROKEN REAR DOOR LATCH**

Date Opened: 11-7-2016

Date Finished 11-7-2016

Meter 1 Reading: 184,036

TASKS PERFORMED

DOOR HANDLES INSIDE-OUTSIDE

Q PARTS

1 HANDLE; TM22676-02 HANDLE DOOR ENTRY

Asset Work Order History 10167685

CSHOP-2016-5645

Date Opened: 12-5-2016

Date Finished

12-5-2016

Meter 1 Reading:

184,997

TASKS PERFORMED

PM SERVICE C RESCUE

Q

PARTS

24 FLUID; SYN OIL BULK QTS
1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE
1 FILTER; AIR FILTER M2
1 9IP; OIL DRAIN GASKET M2
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; FUEL FILTER 33813 L/F # LFF5851

CSHOP-2016-5679

Comments: **REPAIRS FROM PM**

Date Opened: 12-5-2016

Date Finished

1-26-2017

Meter 1 Reading:

186,985

TASKS PERFORMED

GROUND LIGHT BODY
EQUIPMENT MOUNTING BRACKETS
SIDE DOOR
WIPER BLADES
FAN SHROUD
OIL
DOME LIGHTS
BACK UP LIGHTS
AUTO-EJECT
HOSES-LINES & FITTINGS
REPAIR FROM PM - BELTS
RESERVOIR
BRAKES
AIR SYSTEM
WINDOW CHANNEL
AIR HORN
DOOR STRIKER PLATE
INTERIOR TRIM-MOLDINGS-UPHOLS
DOOR PANEL
SEAT REAR
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

Q

PARTS

1 MEDIC MASTER; HGR-1 HELMET HOOK
1 DOOR; 02840048 DOOR GRABBER
2 WIPER; WIPER BLADE
2 1AN; 22" WIPER BLADE
1 NONSTOCK; M2 SHROUD
1 9IP; A22-54259-000 DOOM LIGHT SWITCH M2
1 CHARGER; CHARGER 2000
2 FLUID; ALLISON TRANS FLUID GAL
1 NEWPART; HOSE & FITTING
1 BELT; BELT
1 BELT; BELT ALT. M2
1 GASKET; GASKET RVR PWR STRG M2
1 FILTER; 2503221C1 FILTER POWER STEERING
2 BRAKE; BRAKE DRUM RUMPER FRONT
2 BRAKE; FRONTBRAKE KIT RUMPER AND 4DR RESCUE
1 VALVE; VALVE LEVELIN
1 VALVE; DUMP VLVE AIR SLOAN
1 VALVE; DRAIN VALVE M2
1 DRYER; DRIER ASSBLY AD-IS 5011074 5011075
1 VALVE; PURGE VALVE AD-IP-IS
2 HORN; KIT-AIR HORN-GROVER
1 9IP; STRIKER PIN
1 9IP; 18-46375-004 TREAD PLATE LH M2

CSHOP-2016-746

Date Opened: 2-16-2016

Date Finished

2-16-2016

Meter 1 Reading:

171,995

TASKS PERFORMED

CAB-INTERIOR ACCESSORIES

Q

PARTS

1 NEWPART; MAGNET STRETCHER STRYKER

Service Requests:

02/16/2016 SEATS / 19: LOOSE / EXCHANGE - NEW

Asset Work Order History 10167685

CSHOP-2016-890

Comments: **SPARE RESCUE AT ST42**

Date Opened: 2-24-2016 Date Finished 3-7-2016 Meter 1 Reading: 171,995

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

02/24/2016 A/C / 19: LOOSE / REPAIR
A/C IN FRONT CAB NOT WORKING/BLOWING AIR

CSHOP-2017-107

Date Opened: 1-5-2017 Date Finished 1-5-2017 Meter 1 Reading: 185,203

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2017-1199

Comments: **SR AT ST27**

Date Opened: 2-27-2017 Date Finished 4-5-2017 Meter 1 Reading: 188,457

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

4 9XX; AC FREON 10174676
1 9HY; AC HOSE

Service Requests:

02/24/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE. CAB A/C IS BLOWING HOT.

CSHOP-2017-149

Date Opened: 1-7-2017 Date Finished 1-19-2017 Meter 1 Reading: 186,793

TASKS PERFORMED

NO PARTS USED

DOOR STRIKER PLATE
HVAC SYSTEM

Asset Work Order History 10167685

CSHOP-2017-1959

Date Opened: 4-3-2017 Date Finished 4-5-2017 Meter 1 Reading: 188,457

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

04/01/2017 A/C / 49: CAN NOT DUPLICATE CONCERN / INSPECT
A/C ISSUE

04/01/2017 A/C / 49: CAN NOT DUPLICATE CONCERN / INSPECT
THE REAR CAB AC, NOT PASSENGER COMPARTMENT, IS NOT WORKING AT ALL. THE POWER BUTTON ON THE
MODULE WAS SELECTED FOR REAR CAB AUX AND THE AC WOULD NOT COME ON AT ALL.

CSHOP-2017-2459

Comments: **QC CHECK**
Date Opened: 4-26-2017 Date Finished 4-26-2017 Meter 1 Reading: 188,743

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	9AP; LIGHT
COMPARTMENT LIGHT BODY	1	BULB; 35 WATT BULB
LIGHT BAR	1	9IP; STRIKER PIN
FIRE EXTINGUISHER		
DOOR LOCKS		

CSHOP-2017-263

Comments: **SPARE RESCUE AT 33 A/C PROBLEMS**
Date Opened: 1-12-2017 Date Finished 1-23-2017 Meter 1 Reading: 186,985

TASKS PERFORMED

Q PARTS

HVAC SYSTEM	2	9IP; 01-2616 MOTOR 12V 73R-0542 3512
-------------	---	--------------------------------------

Service Requests:

01/12/2017 A/C / 12: BROKEN / REPAIR
A/C ISSUE

01/12/2017 A/C / 12: BROKEN / REPAIR
A/C ISSUE, AIR CONDITIONING IS HOT. COLD IS NOT WORKING.

Asset Work Order History 10167685

CSHOP-2017-3806

Date Opened: 6-27-2017

Date Finished

7-10-2017

Meter 1 Reading:

188,847

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 TEM; REF OIL
1 NBH; FLEETRANNER BELT
1 9IP; 12-0617A EXPANSION VALVE VCC88000030
10 TEM; TEM
10 TEM; WASHER
10 TEM; SHRADER CORE
2 TEM; PAG 100 OIL
1 TEM; FILTER DRIER
1 9AP; AC FLUSH
1 TEM; REF OIL
1 TEM; NEW COMPRESSOR
10 TEM; WASHER

CSHOP-2017-4502

Date Opened: 8-3-2017

Date Finished

9-5-2017

Meter 1 Reading:

189,275

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 9HD; 9HD
1 9IP; 0000925208 FILTER HEAD CAP NEW NUMBER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2017-4511

Date Opened: 8-3-2017

Date Finished

9-5-2017

Meter 1 Reading:

189,246

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
SUSPENSION
REAR BRAKE PADS-SHOES
AIR SYSTEM

2 1AN; 22" WIPER BLADE
2 2TP; BRAKE DRUM REAR
-2 2TP; BRAKE DRUM REAR
2 2TP; BRAKE SHOES

CSHOP-2017-5327

Date Opened: 9-14-2017

Date Finished

9-14-2017

Meter 1 Reading:

189,246

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

Asset Work Order History 10167685

CSHOP-2017-5786

Date Opened: 10-5-2017 Date Finished 10-10-2017 Meter 1 Reading: 190,087

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

10/03/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
SR6 @57 IS MISSING SUNPASS STICKER ON FRONT WINDSHIELD

CSHOP-2017-5796

Date Opened: 10-6-2017 Date Finished 10-10-2017 Meter 1 Reading: 190,087

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

10/05/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE / DRIVER AREA / CREW COMPARTMENT

10/10/2017 A/C / 18: LEAKING / REPAIR
FRONT CAB A/C NOT WORKING

CSHOP-2017-5878

Date Opened: 10-11-2017 Date Finished 10-12-2017 Meter 1 Reading: 190,244

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

1 9IP; FUEL CAP

CSHOP-2017-6114

Date Opened: 10-23-2017 Date Finished 10-25-2017 Meter 1 Reading: 190,402

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 FIL; NAPA CABIN AIR FILTER
3 9XX; AC FREON 10174676
1 9HY; HOSE MADE
1 BK; SPRAYER

CSHOP-2017-6653

Comments: **PRE TRIP AND CHECK ISSUE WITH REAR DOOR**

Date Opened: 11-17-2017 Date Finished 11-28-2017 Meter 1 Reading: 190,412

TASKS PERFORMED

NO PARTS USED

A INSPECTION

Asset Work Order History 10167685

CSHOP-2017-6912

Date Opened: 12-4-2017 Date Finished 12-4-2017 Meter 1 Reading: 190,606

TASKS PERFORMED

NO PARTS USED

FUEL TANK

CSHOP-2017-6919

Comments: **SPARE RESCUE AT STATION 18**

Date Opened: 12-4-2017 Date Finished 12-6-2017 Meter 1 Reading: 190,719

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL SYSTEM

1 9IP; FUEL CAP M2

Service Requests:

12/04/2017 HAZARD / 12: BROKEN / EXCHANGE - NEW
HAZARDOUS ISSUE. WHILE RESPONDING TO CALLS, SMELL OF GAS, AND FUEL LEAKING FROM GAS CAP ON SPARE RESCUE. MECHANIC CALLED LAST NIGHT TO POSSIBLY REPLACE CAP, AND MECHANIC STATED HE WOULD NOTIFY EDDIE, OR JOHN IN THE MORNING OF THIS ISSUE.

CSHOP-2017-7230

Comments: **STATION 18 SPARE RESCUE**

Date Opened: 12-19-2017 Date Finished 12-22-2017 Meter 1 Reading: 191,394

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
A/C BLOWER OPERATES

Service Requests:

12/18/2017 A/C / 19: LOOSE / REPAIR
A/C ISSUE. THE DRIVER AND OFFICER AC VENTS ARE NOT BLOWING ANY AIR.

CSHOP-2018-1165

Date Opened: 2-26-2018 Date Finished 2-27-2018 Meter 1 Reading: 192,862

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2018-1287

Date Opened: 3-2-2018 Date Finished 3-13-2018 Meter 1 Reading: 192,880

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 2IH; CONNECTOR/PINS

Asset Work Order History 10167685

CSHOP-2018-131

Date Opened: 1-8-2018 Date Finished 1-8-2018 Meter 1 Reading: 192,020

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

CSHOP-2018-1996

Date Opened: 4-10-2018 Date Finished 4-13-2018 Meter 1 Reading: 194,665

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 TEM; STEEL FILTER DRIER

CSHOP-2018-2240

Comments: **R55**

Date Opened: 4-23-2018 Date Finished 4-23-2018 Meter 1 Reading: 195,109

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

04/23/2018 SERVICE REQUEST / 18: LEAKING / REPAIR
STRETCHER COMING UNLOCKED FROM LOCKED POSITION IN BACK OF RESCUE WHILE DRIVING.

CSHOP-2018-2883

Date Opened: 5-24-2018 Date Finished 5-31-2018 Meter 1 Reading: 195,954

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2018-2993

Comments: **SPARE RESCUE AT ST39**

Date Opened: 5-30-2018 Date Finished 8-14-2018 Meter 1 Reading: 197,892

TASKS PERFORMED

NO PARTS USED

DOOR
HVAC SYSTEM

Service Requests:

05/30/2018 A/C / 12: BROKEN / REPAIR
CAB A/C NOT WORKING

06/03/2018 DOOR / 12: BROKEN / REPAIR
VEHICLE DOORS -- STAIR CHAIR CABINET DOOR SENSOR HAS BROKE. TRUCKS READS THAT THE DOOR IS OPEN
WHEN IT IS SHUT.

Asset Work Order History 10167685

CSHOP-2018-3243

Comments: **R39**

Date Opened: 6-11-2018

Date Finished

6-12-2018

Meter 1 Reading:

197,892

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

4 9XX; 134A 10194654
1 NBH; FLEETRANNER BELT
-1 NBH; FLEETRANNER BELT
1 SVP; COMPRSOR
1 TEM; EXPANSION VALVE

Service Requests:

06/11/2018 A/C / 12: BROKEN / EXCHANGE - NEW
FRONT CAB A/C NOT WORKING

CSHOP-2018-3254

Date Opened: 6-11-2018

Date Finished

6-12-2018

Meter 1 Reading:

196,933

TASKS PERFORMED

NO PARTS USED

STRETCHER

Service Requests:

06/11/2018 SERVICE REQUEST / 12: BROKEN / REPAIR
R39 STRETCHER HYDRAULIC LEAK IN THE HEAD OF THE STRETCHER. STRETCHER HEAD WILL NOT STAY IN
SUPINE POSITION AND IS LEAKING FLUID

CSHOP-2018-3309

Date Opened: 6-13-2018

Date Finished

6-18-2018

Meter 1 Reading:

197,892

TASKS PERFORMED

NO PARTS USED

COMPRESSOR

Service Requests:

06/13/2018 A/C / 12: BROKEN / REPAIR
A/C ISSUE AIR CONDITIONING IN THE FRONT CAB STOPPED WORKING AGAIN LAST NIGHT. BLOWING HOT AIR

06/14/2018 A/C / 12: BROKEN / REPAIR
A/C ISSUE A/C IN FRONT COMPARTMENT DOES NOT HAVE COLD AIR AND ONLY HAS WARM AIR

Asset Work Order History 10167685

CSHOP-2018-3478

Comments: **SWAPPED OUT AT ST39 COMING INTO SHOP 6-22-18**

Date Opened: 6-21-2018 Date Finished 9-14-2018 Meter 1 Reading: 197,892

TASKS PERFORMED

NO PARTS USED

TOWING HITCH
COOLING SYSTEM
TIRES ALL
HVAC SYSTEM

VENDOR? SISTERS TOWING

Service Requests:

06/20/2018	A/C / 12: BROKEN / REPAIR A/C ISSUE CAB AC ONLY BLOWING HOT AIR, NO COLD AIR IS PRESENT.
06/21/2018	A/C / 12: BROKEN / REPAIR A/C ISSUE. CAB AC NOT WORKING. ITS HOT OUTSIDE AND WE PUT THE WINDOWS DOWN FOR AIR. WE ARE FORCED TO RUN CALLS CODE 3 WITH WINDOWS DOWN. THERE IS NO EAR PROTECTION(WITH RADIO HOOKUP) ON THE TRUCK. ITS BECOMING A SAFETY ISSUE.
06/22/2018	RADIATOR / 18: LEAKING / REPAIR RADIATOR LEAKING

CSHOP-2018-416

Comments: **AIR LEAK**

Date Opened: 1-19-2018 Date Finished 1-24-2018 Meter 1 Reading: 192,394

TASKS PERFORMED

Q PARTS

SUSPENSION

1	2TP; DUMP VALVE
1	TWD; SLOAN DUMP VALVE

CSHOP-2018-486

Date Opened: 1-22-2018 Date Finished 1-23-2018 Meter 1 Reading: 192,392

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

01/22/2018	A/C / 18: LEAKING / REPAIR A/C ISSUE
01/22/2018	A/C / 18: LEAKING / REPAIR A/C ISSUE. CAB A/C NOT WORKING.

Asset Work Order History 10167685

CSHOP-2018-5562

Date Opened: 10-1-2018

Date Finished

10-17-2018

Meter 1 Reading:

197,902

CAB AC INOP.

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

4 9XX; 134A 10194654
1 TEM; FILTER DRIER
1 FIL; NAPA CABIN AIR FILTER
1 9HY; HOSE MADE
1 9HY; HOSE MADE
1 2RD; FILTER, 17.5X5.5, MASTER PK (2)
1 9HY; HOSE MADE

CSHOP-2018-5687

Date Opened: 10-9-2018

Date Finished

10-11-2018

Meter 1 Reading:

197,902

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

-1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPAGOLD FUEL FILTER
-1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA GOLD OIL FILTER
30 4PC; 15W40 PREMIUM BLUE OIL
1 TWD; PURGE VALVE ASSY KIT
2 1AN; 22" WIPER BLADE
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2018-5734

Date Opened: 10-10-2018

Date Finished

10-10-2018

Meter 1 Reading:

197,902

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
REPAIR FROM PM - DECALS/CLEANLINESS

1 9PB; LARGE PLACARD HOLDER

Asset Work Order History 10167685

CSHOP-2018-6822

Date Opened: 12-3-2018

Date Finished

1-24-2019

Meter 1 Reading:

198,263

TASKS PERFORMED

QUALITY CHECK-REPAIRS
A INSPECTION
FAN CLUTCH
FAN
SERPENTINE BELT TENSIONER
SERPENTINE BELT
AIR SYSTEM
HVAC SYSTEM

<u>Q</u>	<u>PARTS</u>
1	2FL; FAN
2	BRG; ALTERNATOR BEARING
1	2FL; TENSIONER
1	NBH; FLEETRANNER BELT
1	NBH; V-BELT
1	2FL; PRESSURE VALVE
1	2FL; FITTING
1	2FL; CLUSTER
1	NTE; VAC PUMP OIL 32 OZ
4	9XX; 134A 10194654
1	2FL; FAN CLUTCH

CSHOP-2018-873

Date Opened: 2-9-2018

Date Finished

2-12-2018

Meter 1 Reading:

192,862

REAR AC INOP. BAD COMPRESSOR

TASKS PERFORMED

HVAC SYSTEM

<u>Q</u>	<u>PARTS</u>
1	TEM; FILTER DRIER
-1	TEM; FILTER DRIER
4	9XX; AC FREON 10174676
1	NBH; V-BELT
1	2TP; COMPRESSOR
-1	2TP; COMPRESSOR
1	SVP; COMPRESOR
1	TEM; FILTER DRIER

CSHOP-2018-905

Date Opened: 2-12-2018

Date Finished

2-13-2018

Meter 1 Reading:

192,862

B-SER.

TASKS PERFORMED

PM SERVICE B

<u>Q</u>	<u>PARTS</u>
1	FIL; NAPAGOLD FUEL FILTER
22	9OC; SYN 15W40
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER

Asset Work Order History 10167685

CSHOP-2018-936

Date Opened: 2-12-2018 Date Finished 2-13-2018 Meter 1 Reading: 192,862

NEED TO BE SER. BECAUSE OF DATE

TASKS PERFORMED

BATTERY
DEF FLUID

<u>Q</u>	<u>PARTS</u>
4	1AD; BATTERY 31 SERIES
16	GEAR; GEAR OIL SYN QT
16	9OC; GEAR OIL BULK
-16	9OC; GEAR OIL BULK

CSHOP-2019-1006

Comments: **WHEN DIPSTICK COMES IN PLEASE INSTALL ON ASSET# 10167686 DONE**

Date Opened: 2-22-2019 Date Finished 3-15-2019 Meter 1 Reading: 198,263

TASKS PERFORMED

QUALITY CHECK-REPAIRS
DIPSTICK AND TUBE

<u>Q</u>	<u>PARTS</u>
1	2FL; DIP STICK

CSHOP-2019-1481

Date Opened: 3-20-2019 Date Finished 4-2-2019 Meter 1 Reading: 198,980

TASKS PERFORMED

CAB-INTERIOR ACCESSORIES

<u>Q</u>	<u>PARTS</u>
2	BK; CLR RTV SILCN SEALANT
3	LUC; LUCAS RED-TACKY GRS

Service Requests:

03/19/2019 SERVICE REQUEST / 18: LEAKING / ROOF LEAKING
SR6 LOCATED AT ST47. UNABLE TO SWAP INTO SPARE RESCUE DUE TO MAJOR WATER LEAK NOTED IN PATIENT COMPARTMENT. FLOOR IS ALL WET FROM PUDDLING WATER. BENCH SEAT WALL DRIPPING WATER AND NOTED MOLD AND PANELING PEELING AWAY.

CSHOP-2019-2294

Date Opened: 4-30-2019 Date Finished 4-30-2019 Meter 1 Reading: 200,373

TASKS PERFORMED

HVAC SYSTEM

<u>Q</u>	<u>PARTS</u>
3	9XX; AC FREON 10199801
1	FIL; NAPA CABIN AIR FILTER

Asset Work Order History 10167685

CSHOP-2019-2394

Comments: **SPARE AT 31**

Date Opened: 5-7-2019

Date Finished

5-17-2019

Meter 1 Reading:

202,002

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL

Service Requests:

05/07/2019

SERVICE REQUEST / 12: BROKEN / REPAIR

WALL SOCKET/ELECTRIC OUTLET IS NOT WORKING IN THE PASSENGER COMPARTMENT. UNABLE TO CHARGE BATTERIES NEEDED.

CSHOP-2019-2548

Date Opened: 5-15-2019

Date Finished

6-6-2019

Meter 1 Reading:

201,998

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
FAULT CODE
DOOR GLASS
STROBE LIGHTS
HOOD
CAMERA-MONITOR

1 5AH; GAS SPRING, 20", 94LB
2 9IP; BULB PATIENT GH22
2 1WL; LED LIGHTHEADS HORIZONTAL 3 SERIES

CSHOP-2019-2775

Comments: **CAB REAR AC BLOWER INOP**

Date Opened: 5-30-2019

Date Finished

7-15-2019

Meter 1 Reading:

202,500

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2019-2850

Comments: **REAR CAB A/C INOP**

Date Opened: 6-3-2019

Date Finished

6-4-2019

Meter 1 Reading:

202,002

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 TEM; BLOW/MOT
1 2RD; FILTER, 17.5X5.5, MASTER PK (2)

CSHOP-2019-3121

Comments: **WOULDN`T GO INTO REVERSE ON A CALL**

Date Opened: 6-17-2019

Date Finished

8-5-2019

Meter 1 Reading:

202,500

TASKS PERFORMED

NO PARTS USED

TRANSMISSION
INSTRUMENTS-GAUGES-METERS

Asset Work Order History 10167685

CSHOP-2019-4098

Date Opened: 8-5-2019

Date Finished

9-9-2019

Meter 1 Reading:

202,249

TASKS PERFORMED

WIPER BLADES
TRANSMISSION
STEERING COLUMN-SHAFT-BOOT
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

Q PARTS

2	1AN; 22WIPERBLADE
2	1AN; 22 WIPER BLADE
1	2DD; PRESSURESWITCH
1	2DD; FILTER
12	9AP; BRAKECLEAN
1	2IH; SEAL, DIPSTICK-ALLISON
1	2DD; VALVE BODY HARNESS
25	9OC; BULKTRANS SYN
1	2DD; SOLENOIDASM
1	2DD; FILTERKITTRANS SUMP4
1	2DD; CONTROL MODULE
4	2DD; SOLENOID
1	ATP; ATP SENSOR
2	2DD; SOLENOID
1	2FL; INPUTSTEERINGSHAFT
1	5SC; REPAIR VISTA, S/N 10005477
1	6WL; LABELVISTA3ALFMEDICFRONT
1	NCB; DEGREASER MULTI PURP
1	9XX; 134A10194654
1	9HC; CUSTOMHOSES

CSHOP-2019-449

Date Opened: 1-24-2019

Date Finished

2-21-2019

Meter 1 Reading:

198,263

TASKS PERFORMED

ELECTRICAL

NO PARTS USED

CSHOP-2019-4755

Date Opened: 9-9-2019

Date Finished

9-9-2019

Meter 1 Reading:

202,357

TASKS PERFORMED

PM SERVICE C RESCUE

Q PARTS

24	4PC; 15W40 PREMIUM BLUE OIL
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD FUEL FILTER
1	FIL; NAPAGOLD OIL FILTER

Asset Work Order History 10167685

CSHOP-2019-4756

Date Opened: 9-9-2019

Date Finished

9-11-2019

Meter 1 Reading:

202,357

TASKS PERFORMED

WIPERS-WASHER
LIGHTING SYSTEM
CRANKING SYSTEM
ELECTRICAL
SUSPENSION
BRAKES
AIR SYSTEM
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

Q PARTS

2	1AN; 22 WIPER BLADE
1	1WL; FLANGE 4 FLSH MT 4 RND 01 0463512 01
-1	1WL; FLANGE 4 FLSH MT 4 RND 01 0463512 01
1	GRO; CLR MKR LAMP
1	1WL; LENS, CLEAR, 4" FLAT RND
-1	1WL; LENS CLEAR 4 FLAT RND
1	9IP; 54-525 CIRCUIT BREAKER
2	TWD; SHOE KIT
2	2DD; AIR BAG
12	CRC; BRAKLEEN20OZ
1	TWD; PURGE VALVE ASSY KIT
1	FIL; NAPAGOLD AIR FILTER
1	2FL; SWITCHAIR
1	2FL; SWITCHAIR
1	9HD; FILTER CABIN 7 75X14 5

CSHOP-2019-5369

Date Opened: 10-11-2019

Date Finished

10-16-2019

Meter 1 Reading:

202,357

TASKS PERFORMED

QUALITY CHECK-REPAIRS
DOOR LATCH
HVAC SYSTEM

Q PARTS

1	9IP; 8 IN HOLD OPEN 30 LB
1	2FL; DISTRIBUTION BLOCK

CSHOP-2019-6079

Date Opened: 11-19-2019

Date Finished

11-19-2019

Meter 1 Reading:

203,807

TASKS PERFORMED

GROUND LIGHT BODY

Q PARTS

1	5GI; LED LIGHT
1	GRO; RUBBER GROMMET

Asset Work Order History 10167685

CSHOP-2019-6276

Date Opened: 12-3-2019

Date Finished

1-6-2020

Meter 1 Reading:

205,000

TASKS PERFORMED

QUALITY CHECK-REPAIRS
PRE TRIP INSPECTION
WIPERS-WASHER
COOLING SYSTEM
ENGINE AND ACCESSORIES
AIR SYSTEM
CAB-INTERIOR ACCESSORIES
CAMERA-MONITOR
INSTRUMENTS-GAUGES-METERS
COMPRESSOR

Q	PARTS
-10	9OC; COOLANT
10	9OC; COOLANT
1	9IP; Z05 30740 000 SURGE TANK
10	FLUID; COOLANT ANTIFREEZE GAL
2	2DD; THERMOSTAT
1	2DD; 2DD
1	1AD; ALTERNATOR 320A
5	2DD; 2DD
1	2FL; OIL GASKET
1	2FL; 2FL
1	2DD; 2DD
1	2FL; 2FL
12	1CH; BRAKE CLEANER MOPAR
1	2FL; 2FL
1	2DD; WATER PUMP
1	9AP; SORBENT PAD
1	FIL; NAPAGOLD OIL FILTER
1	2DD; 2DD
3	TWD; C 1COCK DRAIN
2	CRC; FOAMING COIL CLEANER
1	NCB; GOJO SCRUB WIPES 72CT
2	1AN; WIPER BLADES
3	9HY; FITTINGS
1	9IP; A22 54259 000 DOOM LIGHT SWITCH M2
1	9IP; DC23-5011 50 # HOLD-OPEN RESCUE
1	9IP; 434 LATCH TRIGGER S O
1	9ES; CAMERA REAR VIEW
1	BK; BLK LIQ ELEC TAPE
1	TEM; PAG 100 OIL
1	FIL; NAPA CABIN AIR FILTER
1	9HC; HOSE S AC
2	9ES; BATTERY 303 357 3 PK
2	SVP; CNDSRFAN

CSHOP-2020-1179

Comments: **SPARE RESCUE AT 25**

Date Opened: 2-28-2020

Date Finished

3-5-2020

Meter 1 Reading:

207,003

TASKS PERFORMED

COOLING SYSTEM
FAULT CODE
AIR SYSTEM

Q	PARTS
6	2IH; 50 50 COOLANT FLEETGUARD
1	2FL; RAD CAP 20 LB

Service Requests:

02/28/2020 AIR RIDE / 12: BROKEN / REPAIR
AIR RIDE ISSUE, LOOSING AIR PRESSURE

Asset Work Order History 10167685

CSHOP-2020-120

Date Opened: 1-9-2020 Date Finished 1-9-2020 Meter 1 Reading: 205,000

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

CSHOP-2020-1250

Date Opened: 3-3-2020 Date Finished 3-24-2020 Meter 1 Reading: 207,003

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	-5	90C; COOLANT
GROUND LIGHT BODY	5	90C; COOLANT
ANTIFREEZE	1	9HC; 90 EL 1 00
ELECTRICAL	3	9HY; 7 8 90 DEGREE HOSE
AIR DRIER	5	FLUID; COOLANT ANTIFREEZE GAL
AIR SYSTEM	1	9HD; DIODE PACK CONNECTOR
DOOR PANEL	1	TWD; PURGE VALVE ASSY KIT
	1	FIL; NAPAGOLD AIR FILTER
	2	2FL; SCREW
	1	2FL; LINE COMP TO BLK
	2	2FL; HOLLOW SCREW
	1	2FL; SEAL
	1	2FL; LINE
	4	2FL; 2FL
	4	2FL; SEAL RING
	1	9IP; A22 54259 000 DOOM LIGHT SWITCH M2

Service Requests:

03/03/2020 RADIATOR / 18: LEAKING / REPLACED
RADIATOR LEAKING, COOLANT LEVEL DROPPED TO LOW AFTER BEING FILLED YESTERDAY MORNING. COOLANT LEVEL WAS FULL PRIOR TO RUNNING 5 CALLS

CSHOP-2020-1773

Date Opened: 3-31-2020 Date Finished 4-1-2020 Meter 1 Reading: 207,206

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

CSHOP-2020-2007

Date Opened: 4-14-2020 Date Finished 4-23-2020 Meter 1 Reading: 207,939

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER CRANKING SYSTEM MIRRORS	1	2FL; MIRROR CONVEX
--	---	--------------------

Service Requests:

04/14/2020 MIRROR / 12: BROKEN / REPAIR
DRIVERS SIDE BOTTOM WIDE VIEW MIRROR WONT STAY SNAPPED INTO HOUSING

Asset Work Order History 10167685

CSHOP-2020-2132

Date Opened: 4-21-2020 Date Finished 5-11-2020 Meter 1 Reading: 208,149

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

04/21/2020 STARTER / 12: BROKEN / REPAIR BATT CHANGED AT SHOP
VEHICLE BARELY STARTED. YES HAS BEEN PLUGGED IN WHENEVER PARKED IN BAY

CSHOP-2020-2246

Date Opened: 4-28-2020 Date Finished 4-29-2020 Meter 1 Reading: 208,149

TASKS PERFORMED

Q PARTS

PM SERVICE B

22 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD OIL FILTER

CSHOP-2020-2256

Date Opened: 4-28-2020 Date Finished 4-29-2020 Meter 1 Reading: 208,149

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY
WIPERS-WASHER
OXYGEN SENSOR
HANDLIGHT
BATTERY
FILTER
TRANSMISSION
POWER STEERING PUMP

2 1AN; 22 WIPER BLADE
2 6ZA; ZICO RATCHET STRAPS
4 1AD; 1000 CCA 31 SERIES BATTERY
5 9OC; BULK TRANS SYN
1 2DD; FILTER KIT TRANS SUMP 4
1 FIL; POWER STEERING FILTER
1 FIL; POWER STEERING FILTER

CSHOP-2020-3023

Date Opened: 6-8-2020 Date Finished 6-9-2020 Meter 1 Reading: 208,149

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

5 9XX; AC 10210647

CSHOP-2020-3202

Date Opened: 6-17-2020 Date Finished 7-2-2020 Meter 1 Reading: 208,944

TASKS PERFORMED

Q PARTS

AIR SYSTEM

2 NTL; AXL GSKT

Asset Work Order History 10167685

CSHOP-2020-3418

Date Opened: 6-29-2020 Date Finished 6-30-2020 Meter 1 Reading: 208,149

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR HANDLES INSIDE-OUTSIDE

1 5HA; HANDLE HORTON RH 2PT W LOCK

CSHOP-2020-3529

Date Opened: 7-6-2020 Date Finished 7-8-2020 Meter 1 Reading: 209,206

TASKS PERFORMED

Q PARTS

WIPER ARM

2 1AN; 22 WIPER BLADE
1 2FL; 2FL
1 2FL; ARM, WIPER RH

Service Requests:

07/06/2020 W/S WIPER / 12: BROKEN / EXCHANGE - USED
WINDSHIELD WIPER DETACHED OFF OF MOTOR. ONLY ONE WORKING WIPER ON FRONT WINDSHIELD.

CSHOP-2020-393

Comments: **COOLANT LEAK**

Date Opened: 1-23-2020 Date Finished 4-16-2020 Meter 1 Reading: 207,583

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
AIR SYSTEM
HOOD LATCH

2 2FL; CAB AIR SPRING
1 2FL; VALVE CAB LEVELING
2 2FL; LATCH

CSHOP-2020-3972

Date Opened: 8-3-2020 Date Finished 8-5-2020 Meter 1 Reading: 209,206

TASKS PERFORMED

NO PARTS USED

SIREN

CSHOP-2020-4047

Date Opened: 8-7-2020 Date Finished 8-23-2020 Meter 1 Reading: 209,206

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPER MOTOR
WIPER BLADES

1 2IH; WIPERMOTORASM
1 2FL; MOTOR WIPER
2 1AN; 22 WIPER BLADE

Service Requests:

08/06/2020 W/S WIPER / 12: BROKEN / EXCHANGE - NEW
WIPERS BAD

Asset Work Order History 10167685

CSHOP-2020-4273

Date Opened: 8-18-2020 Date Finished 8-23-2020 Meter 1 Reading: 209,206

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

08/18/2020 ENGINE / 12: BROKEN / REPAIR CK OK
ENGINE TRUCK STRUGGLES TO TURN OVER. CONTINUALLY CRANKS WITHOUT STARTING.

CSHOP-2020-4358

Date Opened: 8-22-2020 Date Finished 8-31-2020 Meter 1 Reading: 211,337

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 FIL; NAPA CABIN AIR FILTER

Service Requests:

08/21/2020 A/C / 18: LEAKING / ADJUST
THE FRONT CAB AIR CONDITIONER IS BLOWING HOT AIR IN R273, WILL NOT COOL.

CSHOP-2020-4449

Date Opened: 8-26-2020 Date Finished 9-2-2020 Meter 1 Reading: 211,337

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS
AIR SYSTEM
HVAC SYSTEM

2 2IH; LEVELING VALVE FRTLNE
6 9XX; AC 10210647
2 NCB; DEGREASER MULTI PURP
4 1AD; BRAKE CLEAN

Service Requests:

08/26/2020 AIR RIDE / 18: LEAKING / INSPECT
AIR RIDE ISSUE. THE REAR AIR BAGS / LINES ARE LEAKING. WHEN THE TRUCK IS PARKED AND SHUT OFF YOU CAN AUDIBLY HEAR AIR LEAKING FROM REAR OF VEHICLE.

CSHOP-2020-450

Date Opened: 1-28-2020 Date Finished 2-24-2020 Meter 1 Reading: 206,699

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION
AIR HORN

Service Requests:

01/28/2020 SERVICE REQUEST / 12: BROKEN / REPLACED NEW
AIR HORN NOT WORKING

Asset Work Order History 10167685

CSHOP-2020-4635

Date Opened: 9-6-2020 Date Finished 9-15-2020 Meter 1 Reading: 211,608

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

Service Requests:

09/06/2020 SERVICE REQUEST / 12: BROKEN / REPAIR
TYPE PROBLEM INTO DESCRIPTION: WIRE HANGING FROM UNDERCARRIAGE AND DRAGGING ON THE GROUND

CSHOP-2020-4887

Date Opened: 9-17-2020 Date Finished 9-18-2020 Meter 1 Reading: 212,220

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
CAB-INTERIOR ACCESSORIES

1 9AM; BULB OTC REPLACEMENT
1 1WL; BULB 35 WATT 12V SNAP IN

CSHOP-2020-5145

Date Opened: 9-30-2020 Date Finished 10-1-2020 Meter 1 Reading: 212,869

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2020-5153

Date Opened: 10-1-2020 Date Finished 10-5-2020 Meter 1 Reading: 212,869

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
ENGINE AND ACCESSORIES

Service Requests:

10/01/2020 ENGINE / 18: LEAKING / EXCHANGE - USED
ENGINE

CSHOP-2020-5277

Date Opened: 10-7-2020 Date Finished 10-7-2020 Meter 1 Reading: 212,869

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10167685

CSHOP-2020-5287

Comments: **HARD START FUEL GAUGE EXHAUST FUMES**

Date Opened: 10-7-2020 Date Finished 12-9-2020 Meter 1 Reading: 213,200

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	2	5AH; DRAWER SLIDE SHARPS
WIPER BLADES	2	1AN; 22 WIPER BLADE BEAM STYLE
ENGINE AND ACCESSORIES	2	2DD; VALVE CHECK FUEL FILTER ASSEMBLY
LIGHTING SYSTEM	1	2FL; 2FL
SAFTEY-EMERGENCY EQUIPMENT	1	2DD; GASKET
	8	2FL; SEAL O RING
	1	2FL; FUEL SENDING UNIT

CSHOP-2020-6524

Date Opened: 12-14-2020 Date Finished 12-16-2020 Meter 1 Reading: 213,200

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER HVAC SYSTEM	3	9XX; 134A 10194654
---	---	--------------------

CSHOP-2020-6826

Comments: **NEEDS TO BE TENTED FOR ROACHES WHEN RETURNED TO THE SHOP WE BUG BOMBED THIS 2 TIMES SO IT SEEMS TO BE GOOD. WE WILL GET A DPO GOING IF IT HAS FURTHER ISSUES**

Date Opened: 12-30-2020 Date Finished 3-17-2021 Meter 1 Reading: 214,894

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

Service Requests:

12/29/2020 HAZARD / 12: BROKEN / CLEAN
ROACH INFESTATION IN CAB AND PT COMPARTMENT OF RESCUE TRUCK.

CSHOP-2020-69

Comments: **SPARE AT 43**

Date Opened: 1-6-2020 Date Finished 1-14-2020 Meter 1 Reading: 205,199

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	1	2FL; STARTER 38MT
STARTER	1	BK; BACK UP ALARM
BACK-UP ALARM	1	NBH; FLEETRANNER BELT
HVAC SYSTEM		

Service Requests:

01/06/2020 ALARMS / 12: BROKEN / REPAIR
ALARM SIGNALS REVERSE ALARM DOES NOT SOUND

Asset Work Order History 10167685

CSHOP-2021-319

Date Opened: 1-20-2021 Date Finished 3-12-2021 Meter 1 Reading: 214,361

TASKS PERFORMED

Q PARTS

GROUND LIGHT BODY	1	GRO; LAMP
OIL	1	4PC; 15W40 PREMIUM BLUE OIL
HVAC SYSTEM	1	9AP; OIL SAMPLE TEST KIT PETRO CANADA
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD FUEL FILTER
	1	FIL; NAPAGOLD OIL FILTER

CSHOP-2021-710

Date Opened: 2-8-2021 Date Finished 3-26-2021 Meter 1 Reading: 215,600

TASKS PERFORMED

Q PARTS

WIPERS-WASHER	2	1AN; 22 WIPER BLADE
REPAIR FROM PM - REAR SUSPENSION	2	9AP; HAND SOAP PUM TOTAL TRK
AIR SYSTEM	1	FREIGHT
AIR HORN	2	TWD; SLOAN DUMP VALVE
HVAC SYSTEM	2	9AP; HORN KIT PAI 3390 1094
	1	9IP; AC WIRE HARNESS
	1	2FL; MOTOR BLOWER
	1	2FL; SWITCH AIR

Service Requests:

02/07/2021 SERVICE REQUEST / 18: LEAKING / REPAIR
MULTIPLE PROBLEMS -- AIRBAGS LEAK AIR -- PARKING BRAKE ALARM WILL ACTIVATE WHEN BRAKE IS NOT ON -- AIR
HORNS DO NOT WORK

CSHOP-2021-9

Date Opened: 1-2-2021 Date Finished 1-20-2021 Meter 1 Reading: 214,114

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

RADIO-2016-280

Date Opened: 5-10-2016 Date Finished 5-11-2016 Meter 1 Reading: 182,259

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

05/10/2016 RADIO / /
TRUCK CAB RADIO. RADIO MIC NOT WORKING. RADIO IN PATIENT COMPARTMENT WORKS FINE. LOOK LIKE THE
WIRING IS BAD ON THE MIC. SPARE RESCUE CURRENTY @52

Asset Work Order History 10167685

RADIO-2016-423

Date Opened: 7-11-2016 Date Finished 7-11-2016 Meter 1 Reading: 182,259

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

07/10/2016 RADIO / /
RESCUE 10167685 AT ST 52 CAN NOT KEY UP VHF RPT 1 FROM ANYWHERE AROUND STATION. E52 CAN KEY IT UP
EVEN WHEN IN THE BAY. SUSPECT ANTENNA.

RADIO-2018-500

Comments: REMOVE 10141664, INSTALL 10205600 INTO SR15 10167685
Date Opened: 5-16-2018 Date Finished 5-16-2018 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

05/16/2018 RADIO / /
REMOVE AND INSTALL NEW MOBILE RADIO INTO SPARE RESCUE 15

RADIO-2019-522

Comments: SR15 VHF RADIO NO PROBLEM FOUND > NPF
Date Opened: 6-14-2019 Date Finished 6-14-2019 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

04/19/2019 RADIO / /
RADIO ISSUES - VHF RADIO IS NOT COMMUNICATING WHEN ON RPT1 - NO COMMUNICATION BETWEEN UNITS OR HQ
- SPARE RESCUE 15

RADIO-2020-575

Comments: MIC REPLACED
Date Opened: 6-30-2020 Date Finished 6-30-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

PORTABLE RELATED

Asset Work Order History 10167685

RADIO-2020-585

Comments: **RADIO TESTED NPF SERVICE REQUEST - WHILE TESTING ALL RADIOS FOR HURRICANE PREPAREDNESS, NOTICED THAT THE 800MHZ RADIO HAS STATIC WHILE TRANSMITTING TO THE STATION ON 7F.**

Date Opened: 7-3-2020 Date Finished 7-6-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

06/19/2020 SERVICE REQUEST / /
WHILE TESTING ALL RADIOS FOR HURRICANE PREPAREDNESS, NOTICED THAT THE 800MHZ RADIO HAS STATIC WHILE TRANSMITTING TO THE STATION ON 7F. SPARE RESCUE 273

RADIO-2020-807

Comments: **SWAPPED OUT MICROPHONE ON FRONT CONTROL HEAD.**

Date Opened: 9-25-2020 Date Finished 9-25-2020 Meter 1 Reading: 0

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

09/25/2020 RADIO / /
RADIO ISSUES- RADIO MICROPHONE ON THE RESCUE, CANNOT KEY UP TO GO ON AIR. ABLE TO HEAR RADIO
