Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 117.90 Labor: 7,839.20 Parts: 6,039.46 Comm: 4,035.21 Charged: 17913.87

Work Order: 1512607 Meter: 324 In Date: 12/14/2015 Closed: 12/30/2015

Problem: replace fire ext

 Work Completed
 Parts Issued
 Quantity

 - Replace fire ext
 Used Fire X Refurbished
 1.00

 Hours: 0.00
 Comm: 0.00
 Labor: 0.00
 Parts: 19.29
 Total: 19.29

Work Order: 1512622 Meter: 322 In Date: 12/14/2015 Closed: 12/14/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1604084 Meter: 5273 In Date: 04/19/2016 Closed: 04/29/2016

Problem: Service. Tow in, won't stay running.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	er	1.00
- Diagnose trailer power error r	nessage.replace and rewire corroded trailer	5w20 Engine Oil		7.00
plug.		Washer Fluid Con	centr	1.00
- Rotate and balance all tires.		trailer plug		1.00
- Transport vehicle to dealer fo	defective throttle body.	Shop Supplies		1.00
- Shop Supplies				
Hours: 6.2	5 Comm: 0.00	Labor: 375.00	Parts: 33.01	Total: 408.01

Work Order: 1604094 Meter: 5192 In Date: 04/19/2016 Closed: 04/19/2016

Problem: Won't stay running/ PM Service

Work Completed

- Tow From: 8100 Forest Hill Blvd

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1604383 Meter: 5192 In Date: 04/16/2016 Closed: 04/26/2016

Problem: transported

Work Completed

- Tow From: 5850 Okeechobee Blvd To: 8100 Forest Hill Blvd

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1607693 Meter: 8244 In Date: 07/27/2016 Closed: 08/09/2016

Problem: P.M. service and left rear tire going flat.

Work Completed		Parts Issued		Quantity
- P.m. Service.	5w20 Engine Oil		7.00	
- Repair left rear tire, rotate and balance all four.		Napagold Oil Filter	ſ	1.00
- Shop Supplies		Washer Fluid Conc	entr	1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 28.61	Total: 268.61

Work Order: 1700442 Meter: 16039 In Date: 01/13/2017 Closed: 01/31/2017

Problem: P.M. service and light bar inop.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Diagnose inop lightbar.dissassemble switch box and replace	e defective	Napagold Oil Filte	r	1.00
rocker switch.		Napagold Air Filte	er	1.00
- Replace one bent toolbox strut.		22" Wiper Blade		2.00
- Rotate and balance tires.		Washer Fluid Cond	centr	1.00
- Shop Supplies		Used Fire X Refurb	ished	1.00
		Support		1.00
		Rocker Switch		1.00
		Shop Supplies		1.00
Hours: 4.25 Cor	mm: 0.00	Labor: 255.00	Parts: 88.16	Total: 343.16

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1703949 Meter: 20812 In Date: 04/19/2017 Closed: 04/28/2017

Problem: Left front tire going flat.

Work CompletedParts IssuedQuantity- Replace two front tires road force and balance reinstall on vehicle183114470 P245-70r172.00.nitrogen fill all tires.Shop Supplies1.00- Shop SuppliesTire Disposal Fee2.00

Meter: 22999

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 410.01 Total: 470.01

06/08/2017 **Closed:** 06/12/2017

In Date:

Problem: flat tire, put spare on

Work Completed

Work Order: 1705807

- Tow From: Croc near the carwash

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 1705961 Meter: 23531 In Date: 06/15/2017 Closed: 06/23/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		7.00
- Replace two tires,rotate and balance all four.		Napagold Oil Filte	r	1.00
- Complete wheel alignment.test drive.		22" Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	ished	1.00
		Free Replaces Pent	tron	1.00
		183114470 P245-70r17 Shop Supplies		2.00
				1.00
		Tire Disposal Fee		2.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 475.62	Total: 865.62

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1709598 Meter: 28430 In Date: 10/02/2017 Closed: 10/17/2017

Problem: P.M. Service.Flat tire.Broken stop lamp.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
- Repair one tire.rotate and high speed balance all four when	els.nitro fill all.	Napagold Oil Filter	r	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Conc	entr	1.00
		Napa Gear 80w-90	Qt	1.00
		Shop Supplies		1.00
Hours: 4.00 Co	omm: 0.00	Labor: 240.00	Parts: 34.31	Total: 274.31

Work Order: 1711015 Meter: 28430 In Date: 10/17/2017 Closed: 11/06/2017

Problem: Damage to tail gate, right side of bed, right rear tail light & rear bumper

Work Completed

- Damage to tail gate, right side of bed, right rear tail light & rear bumper

Hours: 0.00 Comm: 2,003.72 Labor: 0.00 Parts: 0.00 Total: 2,003.72

Work Order: 1712141 Meter: 29032 In Date: 12/11/2017 Closed: 12/19/2017

Problem: needs 2 spare keys

Work Completed		Parts Issued		Quantity
- Make and program 2 spare keys		ford side key		2.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 166.58	Total: 226.58

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1802111 Meter: 31345 In Date: 02/26/2018 Closed: 03/06/2018

Problem: P.M. service and light bar inop and detail.

Work Completed		Parts Issued		Quantity
- P.m. service.	5w20 Engine Oil		7.00	
- Diagnoise inop light bar .r&r defective control box for li	ight bar. Retest.	Napagold Oil Filter	<u> </u>	1.00
- Rotated and balanced all four tires.nitrogen filled all.		22" Wiper Blade		2.00
- Shop Supplies		Pawer Control Boss	S	1.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 207.76	Total: 477.76

Work Order: 1802395 Meter: 31267 In Date: 03/02/2018 Closed: 03/02/2018

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1806213 Meter: 36425 In Date: 06/18/2018 Closed: 06/27/2018

Problem: P.M. Service.Computer stand loose.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Replace two worn tires .nitrogen fill and rotate and balance all four tires	5w20 Engine Oil	7.00
- Resurface both rear brake rotors and service calipers .replace brake	22" Wiper Blade	2.00
pads.flush and bleed brake system.	Used Fire X Refurbished	1.00
- Perform front end alignment.	Non-chlor Brake Clnr	1.00
- Remove and tighten computer stand bolts and retest.	Mac Wite Lithium Gres	1.00
- Shop Supplies	Wd40 Spr	1.00
	16.5 Oz Aero Kroil	1.00
	183114470 P245-70r17	2.00
	lube	1.00
	Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 11.00 Comm: 0.00	Labor: 660.00 Parts: 566.58	Total: 1,226.58

Hours: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1810013 Problem: P.M. service , brake	Meter: noise ,spare on left rear			In Date:	09/27/2018	Closed:	10/11/2018
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter				1.00
- Check starting and charging sy	stems . Battery failed loa	d test . R&r	5w20 Engine Oil				7.00
defective battery .			22" Wiper Blade				2.00
- Replace two tires . Rotate and I	high speed balance all fo	ur tires . Nitrogen	Used Fire X Refurbish	ied			1.00
fill tires . - Resurface both front and resar rotors . Sertvice front and rear calipers and replace front brake pads . flush and bleed brake system . Test drive. - Perform complete front end alignment and road test.		Battry Motorcraft				1.00	
		Tpms Sens Kit				1.00	
		245/70/17 Tire Mich				2.00	
		Brake Pad				1.00	
- Shop Supplies			Napagold Air Filter				1.00
			Shop Supplies				1.00
			Tire Disposal Fee				2.00
Hours: 13.0	0	Comm: 0.00	Labor: 871.00	Parts: 854	1.82	Total:	1,725.82
Work Order: 1810081 Problem: Rear Driver FLat tire	Meter: (Change Out)	41596		In Date:	09/26/2018	Closed:	09/28/2018
Work Completed							
- Tow From: 8100 Forest Hill Blvd	d						
Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 0.0	0	Total:	0.00
Work Order: 1810355 Problem: 1 - Detail Vehicle Wa	Meter: ash Ticket(s) Issued	41596		In Date:	10/05/2018	Closed:	10/05/2018
Work Completed							
- 1 - Detail Vehicle Wash Ticket(s	s) Issued						

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1900669 Meter: 46417 In Date: 01/16/2019 Closed: 01/29/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace failed struts for tool box and repair hinge and	rivet. Replace	5w20 Engine Oil		7.00
broken screws in trailer connector mount .		Washer Fluid Cond	centr	1.00
- Rotate and balance all four tires . Nitrofill all.		22" Wiper Blade		2.00
- Shop Supplies		Support		2.00
		Shop Supplies		1.00
Hours: 4.00	Comm: 0.00	Labor: 268.00	Parts: 76.70	Total: 344.70

Work Order: 1903630 Meter: 50558 In Date: 04/03/2019 Closed: 04/10/2019

Problem: P.M. service and pulls to the left and bumpy ride.

Work Completed	Parts Issued	Quantity
- P.m. service	Napagold Oil Filter	1.00
- Pressure test and inspect cooling system . Flush and refill cooling system	5w20 Engine Oil	6.00
- Replace two tires . Rotate and hiogh speed balance all four tires . Nitrofill	Washer Fluid Concentr	1.00
all.	22" Wiper Blade	2.00
- Test and replace damaged thrid brake light .	Anti Freeze Motorcraft	2.00
- Test drive . Perform complete front end alignment . Road test .	245/70/17 Tire Mich	2.00
- Shop Supplies	Boxed Miniatures	1.00
	Lamp Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 9.00 Comm: 0.00	Labor: 603.00 Parts: 675.73	Total: 1,278.73

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1907097 Meter: 55571 In Date: 07/09/2019 Closed: 07/16/2019

Problem: P.M. service and long crank after fueling.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Computer diagnose long crank , codes P1450 ,p2196 and P2198 . Perforevap test . R&r defective stuck open evap purge valve . Clear codes and		5w20 Engine Oil Washer Fluid Concentr		7.00
				1.00
retest.		22" Wiper Blade Ford Triton Pvc Swc Purge Valve		2.00
- Rotate and balance all four tires . Nitrofill all.				1.00
- Shop Supplies				1.00
		Shop Supplies		1.00
Hours: 5.50	Comm: 0.00	Labor: 368.50	Parts: 98.49	Total: 466.99

Work Order: 1910085 Meter: 60181 In Date: 09/30/2019 Closed: 10/10/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace two tires . Rotate and high speed balance all	four wheels . Nitrofill	5w20 Engine Oil		7.00
all .		22" Wiper Blade		2.00
- Diagnose missfire . Perform complete tune up . Replace	ce all six spark plugs	Washer Fluid Concentr		1.00
and intake gasket . Retest .		Used Fire X Refurbished		1.00
- Perform air intake decarb and cleaning . Flush injecto	rs.	245/70/17 Tire Mich		2.00
- Shop Supplies		Spark Plugs		6.00
		Gasket		1.00
		Motor Tune-up 16	DOZ	1.00
		Intake Cleaner Kit Throttle Body Cleaner Shop Supplies		1.00
				1.00
				1.00
		Tire Disposal Fee		2.00
Hours: 9.00	Comm: 0.00	Labor: 657.00	Parts: 612.40	Total: 1,269.40

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2000301 Meter: 63914 In Date: 01/10/2020 Closed: 01/13/2020

Problem: Left rear turn signal bulb is out.

Work CompletedParts IssuedQuantity- Diagnose left rear turn signal . R&r defective bulb .Boxed Miniatures1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.77 Total: 37.27

Work Order: 2000716 Meter: 64485 In Date: 01/22/2020 Closed: 01/24/2020

Problem: Screw in pass. rear tire.

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2001253 Meter: 65105 In Date: 02/05/2020 Closed: 02/12/2020

Problem: P.M. service, check light bar and airbag light on.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Replace cabin air filter and clean fresh air intake .	5w20 Engine Oil	6.00
- Replace two tires . Rotate and balance all four tires . Nitrofill all.	22" Wiper Blade	2.00
- Computer diagnose airbag light , code B0002 . Perform pinpoint test . R&r	Cabin Air Filter	1.00
defective clock spring . Clear code and retest system .	245/70/17 Tire Mich	2.00
- Test operation of light bar . repair open circuit at switch box . Retest .	Cover And	1.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.40 Comm: 0.00	Labor: 540.20 Part	s: 654.28 Total: 1,194.48

Work Order: 2005135 Meter: 69350 In Date: 05/21/2020 Closed: 05/27/2020

Problem: Left rear tire going flat and fill washer fluid .

Work Completed		Parts Issued		Quantity
- Repair left front tire and balance . Nitrofill all. Fill	washer fluid .	Washer Fluid Con	ncentr	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 5.83	Total: 78.83

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	2005652 P.M. service and detail.	Meter:	69857		In Date:	06/05/2020	Closed:	06/15/2020
Work Com	pleted			Parts Issued			Qı	ıantity
- P.m. servi	ce.			Napagold Oil Filter				1.00
- Inspectan	nd service rear differential .			5w20 Engine Oil				7.00
- Rotate an	nd balance all four tires . Nitrofill all.			22" Wiper Blade				2.00
- Shop Sup	plies			Washer Fluid Concer	ntr			1.00
				1qt Syngear Oil 75-9	0			3.00
				Px Grey Rtv Silicone				1.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 93.	19	Total:	385.19
Work Order: Problem:	2005781 1 - Detail Vehicle Wash Ticket(s) Iss	Meter: sued	69753		In Date:	06/10/2020	Closed:	06/10/2020
Work Com	pleted							
- 1 - Detail	Vehicle Wash Ticket(s) Issued							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:	2008012 Dead battery	Meter:	72474		In Date:	08/12/2020	Closed:	08/17/2020
Work Com	pleted			Parts Issued			Qı	ıantity
- Charge b	attery fully . Test battery and charging	g system	. Battery failed load	Battry Motorcraft				1.00
	efective battery . Hook up Ids to rese	0 ,		Shop Supplies				1.00
- Shop Sup	pplies Hours: 1.50		Comm: 0.00	Labor: 109.50	Parts: 187	7.48	Total:	296.98
Work Order:		Meter:	73558		In Date:	09/30/2020		10/05/2020
	Naii iii ieit iiont tire,							
	·			Parts Issued			Qı	ıantity
Problem: Work Com	·			Parts Issued Shop Supplies			Qı	uantity 1.00
Problem: Work Com	pleted ft front tire and balance . Nitrofill all.						Qı	•

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2011976 Meter: 75146 In Date: 12/02/2020 Closed: 12/14/2020

Problem: P.M. service

Work Completed		Parts Issued		Quantity
- performed pm service		5w20 Engine Oil		7.00
- check, resurfaced both rear brakes rotors,replaced pad	ls,service	Napagold Oil Filter		1.00
calipers, flush fluid then road test		22" Wiper Blade		2.00
- replace two tires ,balance and rotate all 4 . Nitro fill all.		Used Fire X Refurbi	shed	2.00
- completed front end alignment and road test		Napagold Air Filte	r	1.00
- Shop Supplies		Brake Pad		1.00
		245/70/17 Tire Mic	h	2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 10.00	Comm: 0.00	Labor: 730.00	Parts: 626.75	Total: 1,356.75

Work Order: 2102111 Meter: 76245 In Date: 02/24/2021 Closed: 03/08/2021

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Check circuit to strobe light switch inop,bad switch, check co		5w20 Engine Oil		7.00
over head lighting, all light switch inop open box to repair		Washer Fluid Concentr		1.00
Rotate and speed balance all, nitro fillCheck and replace cabin filter . Clean fresh air intake .		22" Wiper Blade		2.00
		Steering Wheel Cover Large		1.00
- Shop Supplies		Mac Wite Lithium Gres Rocker Switch Led Rocker Switch Round Cabin Filter		1.00
				1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 4.50 Com	nm: 0.00	Labor: 328.50	Parts: 115.12	Total: 443.62

Palm Beach County Fleet Management Asset Maintenance History 10199072 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2109230 Meter: 77934 In Date: 08/25/2021 Closed:

Problem: P.M. service.

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Work Order: 2109297 Meter: 77934 In Date: 07/26/2021 Closed: 08/27/2021

Problem: : Need estimate on repainting bed where fire damage accrued & replace bed liner.

Work Completed

- : Need estimate on repainting bed where fire damage accrued & replace

bed liner.

Hours: 0.00 Comm: 1,551.49 Labor: 0.00 Parts: 0.00 Total: 1,551.49

Work Order: 2110527 Meter: 78133 In Date: 09/29/2021 Closed: 09/29/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 117.90 Total Labor: 7,839.20 Total Comm: 4,035.21 Total Parts: 6,039.46