



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V327

In Date: 10/27/2005
Close Date: 12/02/2005

Meter Reading:

Problem?
SET UP NEW UNIT

Task performed:

Parts	Quantity
0041BRACKET TOOL	3
14-7014HGR-1 HELMET HOOK	10
5025TERMINAL BOX	2
5269LPVM-5 SM MOUNT	12

Workorder: V905

In Date: 12/13/2005
Close Date: 12/14/2005

Meter Reading:

Problem?
REAR COMPT. DOORS JAMED, R-23

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V915

In Date: 12/13/2005
Close Date: 12/15/2005

Meter Reading:

Problem?
PROBLEM WITH WINDOWS R23

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V953

In Date: 12/16/2005
Close Date: 12/19/2005

Meter Reading:

Problem?
STEERING WHEEL ADJUSTMENT PEDAL BROKEN, R-23

Task performed:

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1052

In Date: 12/28/2005

Meter Reading:

Close Date: 12/30/2005

Problem?

L/REAR DOOR OPEN ALARM INOP, CHECK FRONT PASS. SEAT R-23

Task performed:

Parts

Quantity

52-624SWITCH DOOR

1

Workorder: V1006

In Date: 12/22/2005

Meter Reading:

Close Date: 02/03/2006

Problem?

AIR HORNS INOP, WINDOWS INOP, R-23

Task performed:

Parts

Quantity

516593MINI 15 AMP CB211-15 CIRCUIT BREAKER

5

Workorder: V1416

In Date: 02/06/2006

Meter Reading:

Close Date: 02/13/2006

Problem?

WATER LEAK IN FRONT CAB UNDER SIREN/LIGHT PANEL, R-23

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1821

In Date: 03/10/2006
Close Date: 03/23/2006

Meter Reading: 7,195.00

Problem?

B INSPECTION R-23

Task performed:

See B Inspection pre-printed form

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
05-17223-002RAD CAP 20 LB	1
11-23853-000U BOLT REAR SPRING M2	4
23-00461-007NUT FOR U BOLT	8
29526898 29548988 TRANS FILTER ALLISON	1
42809AIR FILTER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
ACX-8453LUG CAPS WHEELED COACH # CH27321 OLD	9
H3LIGHT BULB BP1255/H3 H	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
U-7421SWITCH - ROCKER FOR UNITY LIGHT	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1

Workorder: V1931

In Date: 03/22/2006
Close Date: 04/06/2006

Meter Reading:

Problem?

REPLACE HOOD SHOCK, R-23

Task performed:

Parts	Quantity
215R052SCREW NEW GOLD CUTTER	1
A17-14297-000HOOD LIFT CLY A17-14297-002 M2	1

Workorder: V2011

In Date: 03/29/2006
Close Date: 04/12/2006

Meter Reading:

Problem?

REPLACE 6 TIRES, R-23

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: TCI



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V2195

In Date: 04/11/2006

Meter Reading:

Close Date: 04/14/2006

Problem?

ROOF LEAKS WATER. R-23

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2221

In Date: 04/13/2006

Meter Reading:

Close Date: 04/19/2006

Problem?

PEDEL FOR STEERING COLUMN BROKEN, R-23

Task performed:

Parts

Quantity

RGT-452258FFOOT PEDAL STERRING COLUMN

1

Workorder: V2431

In Date: 05/01/2006

Meter Reading:

Close Date: 05/04/2006

Problem?

STEERING WHEEL COVER BROKEN, R-23

Task performed:

Parts

Quantity

22-57855-000LOWER COVER M2

1

23-12982-770COVER SCREWS M2

2

6809881078DZ STUD

2

A22-57853-000UPPER COVER M2

1

ABPN8332229011-3050 SWITCH BLOWER

1

S30TLBULB

1

Workorder: V1767

In Date: 03/07/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

REPLACE WINSHIELD R23

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V806

In Date: 12/05/2005

Meter Reading:

Close Date: 05/11/2006

Problem?

REMOUNT SCBA BRAKET R23

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2510

In Date: 05/08/2006

Meter Reading:

Close Date: 05/25/2006

Problem?

REAR LIGHT BAR LENS BROKEN, R-23

Task performed:

Parts

Quantity

68-3983813-30LENS 4500 BAR CLEAR

1

Workorder: V2608

In Date: 05/14/2006

Meter Reading:

Close Date: 05/25/2006

Problem?

Left Rear pt. compartment doors not closing completely.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2856

In Date: 06/05/2006

Meter Reading:

Close Date: 06/07/2006

Problem?

driver's side rear emergency strobe bulb out (small clear/red light)

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V3013

In Date: 06/16/2006

Close Date: 06/27/2006

Meter Reading:

Problem?

LED LIGHT INOP, R-23

Task performed:

Parts

Quantity

RSR03ZCRLIGHT LED RED TIR3 SERIES

1

Workorder: V3054

In Date: 06/20/2006

Close Date: 06/27/2006

Meter Reading:

Problem?

WILL NOT START, R-23

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3404

In Date: 07/11/2006

Close Date: 07/12/2006

Meter Reading:

Problem?

ROOF LEAK R 23B

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3648

In Date: 07/26/2006

Close Date: 07/28/2006

Meter Reading:

Problem?

REAR AC 10-7 CHECK SHORT NODE 3

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V3808

In Date: 08/07/2006

Meter Reading:

Close Date: 08/07/2006

Problem?

ON CALL TIRE LEAKING R23 B

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3809

In Date: 08/07/2006

Meter Reading:

Close Date: 08/18/2006

Problem?

TIRE REPAIR AT STA 23 ELPEX TIRE R23

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: TIRESOLES

Workorder: V3826

In Date: 08/07/2006

Meter Reading: 15,318.00

Close Date: 08/22/2006

Problem?

B INSPECTION AND REPAIRS AS NESS. R23B

Task performed:

REPLACE OFICEFS SEAT

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0000902051FILTER FUEL 03 MERCEDES 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

032-0116549297 BATTERY INDICATOR 1

42809AIR FILTER M2 1

5008414CARTRIDGE DC100 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

A17-14297-000HOOD LIFT CLY A17-14297-002 M2 1

HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING 1

MISC PARTMISC PART 1

RGT-452258FFOOT PEDAL STERRING COLUMN 1

RSR03ZCRLIGHT LED RED TIR3 SERIES 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

VCC/36000006A/C FILTER CAB M2 1

VML/T1808D2503221C1 FILTER POWER STEERING 1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4054

In Date: 08/22/2006

Meter Reading:

Close Date: 08/28/2006

Problem?

REPLACE PLEXIGLASS DOOR IN PATIENT COMP.

Task performed:

Parts	Quantity
HA49102C2-32-15 LATCH NON LOCKING	1
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1

Workorder: V4111

In Date: 08/24/2006

Meter Reading:

Close Date: 08/28/2006

Problem?

ac not cooling in rear compartment. r23

Task performed:

Parts	Quantity
4909SCUT AND FAB FITTING	2

Workorder: V3871

In Date: 08/10/2006

Meter Reading:

Close Date: 09/01/2006

Problem?

replace all tires at callaghan

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor?: VC-15214

Workorder: V4680

In Date: 10/02/2006

Meter Reading: 18,302.00

Close Date: 10/10/2006

Problem?

CAB A/C 10-7 R23

Task performed:

1. CHARGE A/C & FOUND HIGH SIDE HOSE LEAK.

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4700

In Date: 10/02/2006
Close Date: 10/16/2006

Meter Reading: 1,697.00

Problem?

repair map light. light not working. R-23

Task performed:

1. TRAVELED TO STN 23 INSTALLED NEW MAP LIGHT.

Parts

87141USE LED MAP LIGHT 24"

Quantity

1

Workorder: V4857

In Date: 10/11/2006
Close Date: 10/27/2006

Meter Reading: 1,744.00

Problem?

spot light atop of rescue not working. R-23

Task performed:

1. TRAVELED TO STN 23. REPAIRED WIRE AT SPOTLIGHT.

Parts

H9SPOT LIGHT BULB

Quantity

1

Vendor?: *

Workorder: V4898

In Date: 10/14/2006
Close Date: 10/27/2006

Meter Reading: 1,765.00

Problem?

A/C NOT COOLING IN FRONT CAB R-23

Task performed:

1. TRAVELED TO STN 23. REMOVED COMPRESSOR HIGH LINE. SENT TO MAKE HOSE FOR REPAIR, REINSTALLED LINE W/ NEW BRACKET FOR SUPPORT. CHARGED & LEAK TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V5044

In Date: 10/24/2006
Close Date: 10/30/2006

Meter Reading: 19,580.00

Problem?

CAB A/C LEAKING R23

Task performed:

1. TRAVELED TO STN 23. LEAKING FREON. NEED TO COME TO SHOP TO FILL WITH FREON.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5118

In Date: 10/27/2006
Close Date: 11/01/2006

Meter Reading: 1,828.00

Problem?

a/c on unit needs another charge r23

Task performed:

1. CHARGED A/C.
2. REPAIRED SPOT LIGHT.
3. REPLACED MAP LIGHT.

Parts

Quantity

8714287142 LIGHT MAP 12"

1

Workorder: V5169

In Date: 10/30/2006
Close Date: 11/02/2006

Meter Reading: 1,846.00

Problem?

STRETCHER WAS PULLED OUT ON A CALL AND CREW NOTICED ONE OF THE WHEELS ON THE STRETCHER WAS WOBBLY AND NEEDED TO BE LOOKED AT. r23

Task performed:

1. SWAP OUT STRECHER CALL MEDCO INC FOR REPAIR.

Parts

Quantity

NO PARTS USED

Workorder: V5218

In Date: 11/02/2006
Close Date: 11/06/2006

Meter Reading: 19,967.00

Problem?

reair strecher r23 medco equip repair

Task performed:

STRECHER REPAIR

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO EQUIPMENT REPA

Workorder: 4881

In Date: 11/16/2006
Close Date: 11/17/2006

Meter Reading: 20,548.00

Problem?

FUEL CAP LEAKING / REPAIR WIPERS R23

Task performed:

- 2 WORK ORDER'S WERE OPEN FOR 4881
1. repair fuel leak
2. repair turn sigal switch

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5452

In Date: 11/20/2006

Meter Reading: 1,928.00

Close Date: 11/21/2006

Problem?

Minor diesel leak from front passenger side of rescue. R23

Task performed:

Parts

Quantity

1. REMOVED STEP CLEAN FUEL AND STEP. STRAIGHTENED GROUND LIGHT BRACKETS, PULLED "J" BRACKET INOT ALIGNMENT, SEALED FUEL TANK CAP. ROAD TEST.

NO PARTS USED

Workorder: V5801

In Date: 12/13/2006

Meter Reading: 2,068.10

Close Date: 12/22/2006

Problem?

Windshield wipers come on by themselves. r23

Task performed:

Parts

Quantity

1. Drive to station installed wiper assy. Tested ok

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1

Workorder: V5954

In Date: 12/25/2006

Meter Reading: 21,451.00

Close Date: 12/29/2006

Problem?

A/C IN CAB DOES NOT BLOW COLD AIR R23

Task performed:

Parts

Quantity

1. Charged A/C system

NO PARTS USED

Workorder: V5964

In Date: 12/27/2006

Meter Reading: 23,335.00

Close Date: 01/03/2007

Problem?

On call service lost air pressure R23

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6120

In Date: 01/06/2007

Meter Reading: 2,156.50

Close Date: 01/30/2007

Problem?

Passenger side rear box light does not turn on. R23

Task performed:

Parts

Quantity

1. TRAVEL TO STN 23. REPLACE ALL HAND LIGHTS WITH STREAMLIGHT BRAND.

NO PARTS USED

2. A/C LEAK - DRIAN A/C SYSTEM & REPLACE FITTINGS TO COMP.

3. REPLACE BELTS- REFUT FAN CLUTCH TO PULLY.

Workorder: V6215

In Date: 01/10/2007

Meter Reading: 23,335.00

Close Date: 01/30/2007

Problem?

-flashlight holder in cab broken -front a/c not working -front cab roof leak from lights -driver side compartment smells very moldy
-back cab side door handle broken -back cab rear door hard to open from inside. R23

Task performed:

Parts

Quantity

1. RESEALED LIGHTBAR CABLES THROUGH CAB ROOF.

NO PARTS USED

2. DISINFECTED SIDE COMPARTMENT WITH MOLD & MILDEW REMOVER.



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6221

In Date: 01/11/2007

Meter Reading: 23,335.00

Close Date: 01/30/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED R23

Task performed:

1. PERFORM PM-B INSPECTION.
2. SERVICE TRANI, FILTER & FLUIDS.
3. R/R BATT & CABLES.
4. TOURQU U-BOLTS.
5. MUD FLAP RIPPED - LOOSEN & REAJUST AS NESS
6. W/WASHER TANK LOOSE ON MOUNTS- TIGHTEN AS NESS.
7. WATER IN LED - REMOVE LENSE & DRAIN WATER.
8. R/R REAR BRAKES & DRUMS.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
08-6962BFITTING A/C USE SB1322	1
29526898 29548988 TRANS FILTER ALLISON	1
3744BRAKE DRUM REAR	2
42809AIR FILTER M2	1
4407S08-6462BS 45 DEG FITTING 8 SB1312	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
9420BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V6241

In Date: 01/12/2007

Meter Reading: 23,335.00

Close Date: 02/05/2007

Problem?

replace tires at callaghan ent r23

Task performed:

Replace tires at Callaghan Ent R23

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN ENT



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7519

In Date: 04/03/2007

Meter Reading: 2,681.00

Close Date: 04/09/2007

Problem?

poss alternator problem. smoke coming from area. R23

Task performed:

Checked out problem. Found cab a/c compressor locked up. Clutch burnt up. Took driver to shop for spare unit

Parts

NO PARTS USED

Quantity

Workorder: V8165

In Date: 05/09/2007

Meter Reading: 30,335.00

Close Date: 05/17/2007

Problem?

coolant reservoir leaking R23

Task performed:

Replaced coolant reservoir
Swapped into on-call truck

Parts

05-23195-000Z05-30740-000 SURGE TANK

Quantity

1

Workorder: V8339

In Date: 05/21/2007

Meter Reading: 31,245.00

Close Date: 06/01/2007

Problem?

on call cab a/c 10-7 r23

Task performed:

1. Drive to Sta check unit, found no problem, test ok

Parts

VCC/36000006A/C FILTER CAB M2

VCC/83000036PROBE

Quantity

1

1

Workorder: V8349

In Date: 05/21/2007

Meter Reading: 31,245.00

Close Date: 06/05/2007

Problem?

cab a/c blower innop R23

Task performed:

1. diagnose no frt blower. check power + ground. (ok)
ck. fan speed volts (ok) removed blower, removed elec.
board and reinstall. install motor, now wkg. bad
connection

2. install new spot lgt switch. connector on harness
burnt. splice in new connector.

3. repair portable radio

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V8214

In Date: 05/11/2007

Meter Reading: 2,836.60

Close Date: 06/06/2007

Problem?

right air horn is not working, and left one is leaking air. R-23

Task performed:

Parts

Quantity

1. Drive to Sta adjust both air horns - test OK

NO PARTS USED

Workorder: V8568

In Date: 06/04/2007

Meter Reading: 29,990.00

Close Date: 06/19/2007

Problem?

air horns are out of service on r23

Task performed:

Parts

Quantity

Drive to station, adjusted air horn, test OK

NO PARTS USED

Workorder: V8596

In Date: 06/05/2007

Meter Reading: 29,990.00

Close Date: 06/20/2007

Problem?

new rescue at st. 23 needs oil, have none at station.

Task performed:

Parts

Quantity

1. Drive to sta drop off oil

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V8651

In Date: 06/07/2007

Meter Reading: 32,141.00

Close Date: 06/29/2007

Problem?

B inspection and related repairs R23

Task performed:

1. B inspection
2. Replaced a/c condensor fan and replaced leaking fitting at condensor. Evacuate and recharge system
3. Found leaking line at p.s. pump- fitting loose in pump. Removed fitting and replaced O ring. Reinstalled fitting and line. Cleaned area-OK
4. Serviced power steering
5. Serviced air dryer
6. Replaced all tires and valve extensions
7. Adjusted a/c compressor belt
8. Repaired door ajar system
9. Replaced u/v bulb and a/c filters
10. Replaced cab door sills and inner door handle
11. Replaced blown emergency lights
12. Replaced fender flair and repaired rub rail
13. Replaced blown headlight
14. Replaced wiper blades
15. Trouble shoot O2 system
16. Shop meeting
17. Patient compt door panels loose and missing screws/ tightened and replaced missing screws. Lubed all doors and adjusted as needed.
18. Shop meeting
19. Trouble shoot O2 system

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
08-6962BFITTING A/C USE SB1322	1
18-46375-00018-46375-004 TREAD PLATE LH M2	1
18-46375-00118-46375-005 TREAD PLATE RH M2	1
2FC00ZCR4 IN ROUND LED	2
373-2.5E-Z LOK BRACKET	1
5008414CARTRIDGE DC100	1
50R03ZCRLIGHT LED RED TIR 6	1
60027FAN A/C COND 12IN 860026-2-W	1
9006XSLLEHEADLAMP M2 HI	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
FND3991FENDER FLAIR RUBBER PER FT	5
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SWT1277EL57755 SWITCH DOOR 2PCS	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	2

Workorder: V8683

In Date: 06/08/2007

Meter Reading: 32,141.00

Close Date: 07/02/2007

Problem?

replace tires at callaghan ent r23

Task performed:

1. replace tires

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V9283

In Date: 07/12/2007 Meter Reading: 33,415.00
Close Date: 07/17/2007

Problem?

won't build air pressure over 20 psi R23A

Task performed:

1. TRAVEL TO OKEECHOBEE & MILITARY. GOT TANK TO BUILD AIR AND FOLLOWED TO SHOP FOR REPAIRS. REPLACED PURGE VALVE IN DRYER.

Parts	Quantity
800404USE K022105 PURGE KIT AD-IP-IS	1

Workorder: V9328

In Date: 07/16/2007 Meter Reading:
Close Date: 07/20/2007

Problem?

right air horn is not working..... R23

Task performed:

1. DRIVE TO STA. ADJ 4 AIR HORNS AND REWORK PT COMPT LOCKS FOR BENCH PANEL. TEST- OK.

Parts	Quantity
NO PARTS USED	

Workorder: V9595

In Date: 07/28/2007 Meter Reading: 3,214.90
Close Date: 08/01/2007

Problem?

front a/c in cab does not blow r23

Task performed:

1. travel to sta 23 check unit blower motor not working replace blower motor and harness recheck a/c npf

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1

Workorder: V9929

In Date: 08/15/2007 Meter Reading: 35,406.00
Close Date: 08/28/2007

Problem?

ON CALL NO WIPERS R23

Task performed:

Fnd wipers inop w/engirunning, but they run wjen the eng is off; will gring to shop for further diagnosing

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V9937

In Date: 08/15/2007 Meter Reading: 35,406.00

Close Date: 08/31/2007

Problem?

WINDSHIELD WIPER PROBLEM R23

Task performed:

Parts

Quantity

dia with getting in the dash; could not locate the problem;
drive to dealer

NO PARTS USED

Workorder: V9938

In Date: 08/15/2007 Meter Reading: 35,406.00

Close Date: 08/31/2007

Problem?

starting problem R23

Task performed:

Parts

Quantity

Dia starting; charge conn at solenoid & did not fix
problem; drive to dealer

27-102A22-54259-000 DOOM LIGHT SWITCH M2

1

Workorder: V10353

In Date: 09/10/2007 Meter Reading: 35,406.00

Close Date: 09/20/2007

Problem?

CHECK BATTERY AND VERIFY REPAIR AT FREIGHTLINER R23

Task performed:

Parts

Quantity

Drive to Str; R/R/ btry; chk for codes; H6-165; test run
ok

NO PARTS USED

Workorder: V10550

In Date: 09/19/2007 Meter Reading: 35,406.00

Close Date: 09/24/2007

Problem?

a inspection back from freightliner r23

Task performed:

Parts

Quantity

- 1. A-Inspection
- 2. Repair rear door latch tight to open
- 3. Cln/lube air pump magnets on rear door
- 4. Rear compt door #3 hinges bolts pull out; rep
- 5. Installed new step mirror R-side door
- 6. Replc grnd light under truck
- 7. Top off all fluids
- 8. Replc wiper blades
- 9. install new glass in rear compt. of truck

2FC00ZCR4 IN ROUND LED 1
 4070091740 GROMMET T/L 4 IN 1
 91-22WIPER BLADE 2
 A22-54624-001DOWN VIEW MIRROR M2 1
 DOOR5LEXAN 9 X 38 1/2 IN 1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10494

In Date: 09/17/2007

Meter Reading: 35,406.00

Close Date: 09/28/2007

Problem?

Repair electrical problem R23 (Outside agency-Atlantic truck)

Task performed:

Parts

Quantity

Rep electrical problem - Atlantic Truck

NO PARTS USED

Vendor?: ATLANTIC TRUCK

Workorder: V10776

In Date: 10/02/2007

Meter Reading: 35,407.00

Close Date: 10/22/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED

Task performed:

Parts

Quantity

1. perform b service
2. shop meeting
3. shop meeting
4. replaced engine air filter
5. replaced rear cab a/c filter
6. replace patient compartment a/c filter
7. mounted blind spot mirror on passenger door window frame.
8. removed under hood light.
9. replaced flag stickers
10. replaced non skid tape on passenger cab step
11. replaced door latch bezel on side patient compartment entry door.
12. replaced top front amber body marker light assembly.
13. cpr and aed training
14. removed broken positive frame rail mounting stud and throw away. cut and splice cable from battery box to alternator.
15. serviced batteries
16. clean shop after p.m.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0000902051FILTER FUEL 03 MERCEDES 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

42809AIR FILTER M2 1

680-10LAMERICAN FLAG W UV CLEAR LEFT 1

680-10RAMERICAN FLAG W UV CLEAR RIGHT 1

78R536078R5360M 2PK FILTER AIR COND 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

CLR9185209186-1500-20 MARKER LT.AMBER LED 1

HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

UNT7744USE PINK A/C FILTER MEDIC MASTER 1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V11328

In Date: 10/30/2007

Meter Reading:

Close Date: 11/09/2007

Problem?

air horns not working properly. R-23

Task performed:

Drive to stn; rebuild air valve; adj; test ok

Parts

1094KIT-AIR HORN-GROVER

Quantity

1

Workorder: V11899

In Date: 12/04/2007

Meter Reading: 38,306.00

Close Date: 12/05/2007

Problem?

on call r23 charging system 10-7

Task performed:

chk charging sys; bad alt; took out of svc. j

Parts

NO PARTS USED

Quantity

Workorder: V11860

In Date: 12/02/2007

Meter Reading: 3,617.90

Close Date: 12/10/2007

Problem?

ground light broken/ missing, airhorn not working appropriately R23

Task performed:

1. PROGRAM AND INSTALL NEW GROUND LIGHT

Parts

NO PARTS USED

Quantity

Workorder: V11901

In Date: 12/04/2007

Meter Reading: 38,306.00

Close Date: 12/10/2007

Problem?

charging system 10-7

Task performed:

1. TRUCK WAS OUT OF SERVICE FOR NO CHARGING. ALTERNATOR BAD. REMOVED ALL BRACKETS AND BELTS AND TRIED TO REMOVE ALT. FROM BOTTOM WILL NOT GO. REMOVED AIR CLEANER AND HOSES, A/C COMP AND LINES TO REMOVE FROM TOP. R&R ALT. AND REASSEMBLE TRUCK. VACUMED AND RECHARGED A/C. TESTED ALL SYSTEMS OK

Parts

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

Quantity

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V8245

In Date: 05/14/2007
Close Date: 12/11/2007

Meter Reading: 2,888.10

Problem?

LEFT HEADLIGHT OUT (LOW BEAM) R-23

Task performed:

Parts	Quantity
90069006 BULB ASSY	2

Workorder: V11787

In Date: 11/28/2007
Close Date: 12/12/2007

Meter Reading: 38,306.00

Problem?

repair under truck lights r23

Task performed:

1. Done at shop.

Parts	Quantity
NO PARTS USED	

Workorder: V5162

In Date: 10/30/2006
Close Date: 12/17/2007

Meter Reading: 1,846.00

Problem?

feeling hot,hot,hot.....gimme some gas R23

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V12590

In Date: 01/15/2008
Close Date: 01/28/2008

Meter Reading: 3,827.40

Problem?

Recuse 23 tires rear callaghan

Task performed:

Rescue 23 tires rear - Callaghan j

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12668

In Date: 01/17/2008
Close Date: 02/01/2008

Meter Reading: 3,827.40

Problem?

electrical cord hanging under cab. Temporarily tied off. R23

Task performed:

Drive to Stn; tie warp cord up. j

Parts

NO PARTS USED

Quantity

Workorder: V12760

In Date: 01/23/2008
Close Date: 02/05/2008

Meter Reading: 3,944.00

Problem?

replace windshield wipers r23

Task performed:

drive to Stn; L/R wiper blades; test - ok. j

Parts

91-22WIPER BLADE

Quantity

2

Workorder: V3799

In Date: 08/06/2006
Close Date: 02/07/2008

Meter Reading:

Problem?

spot light out.R23

Task performed:

CHECK FOR OBJECT IN REAR TIRE

Parts

H9SPOT LIGHT BULB

Quantity

1

Workorder: V4784

In Date: 10/06/2006
Close Date: 02/07/2008

Meter Reading: 1,697.00

Problem?

both front and back a/c blowing warm air in the cab R23

Task performed:

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V13108

In Date: 02/07/2008

Meter Reading: 4,006.70

Close Date: 02/11/2008

Problem?

The sharp shuttle drawer needs modification to accomadate the different shape sharps shuttle. R-23

Task performed:

Parts

Quantity

1. Drive to station, remove metal holder, grind down, (replace), test OK

NO PARTS USED

Workorder: V13294

In Date: 02/16/2008

Meter Reading: 4,091.40

Close Date: 02/20/2008

Problem?

Front grill of R23 is missing a couple screws and is flooping around.

Task performed:

Parts

Quantity

1. Drive to station, installed bolts and tightened grill

NO PARTS USED

Workorder: V13372

In Date: 02/20/2008

Meter Reading: 43,713.00

Close Date: 02/20/2008

Problem?

on call r23 siren 10-7

Task performed:

Parts

Quantity

1. Travel to Stn; rep siren on truck; mic keyed.
j

NO PARTS USED

Workorder: V13424

In Date: 02/22/2008

Meter Reading: 43,876.00

Close Date: 03/12/2008

Problem?

IN PATIENT COMPARTMENT, DOME LIGHT ON OFFICER SIDE CIELING, LAST LIGHT FROM THE BACK DOOR. R23

Task performed:

Parts

Quantity

1. Drive to station, R & R dome light in patient compartment, tested OK

322502BULB PATIENT GH22

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14016

In Date: 03/20/2008
Close Date: 03/20/2008

Meter Reading: 45,223.00

Problem?

replace tires at callaghan ent r23

Task performed:

Replace tires R23 - Callaghan

j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V13943

In Date: 03/17/2008
Close Date: 03/21/2008

Meter Reading: 4,131.60

Problem?

r23 back door handle is sticking and unable to open from the inside.

Task performed:

1. Drive to station, take door apart, adjust rods, test OK

Parts

NO PARTS USED

Quantity

Workorder: V13962

In Date: 03/18/2008
Close Date: 03/27/2008

Meter Reading: 45,223.00

Problem?

b inspection and repairs as needed r23

Task performed:

- 1. b inspection
- 2. service trans
- 3. service rear end
- 4. r/r belts

Parts

0000900087DDE/A0000900087 FILTER HEAD SM MERCED 1

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0000902051FILTER FUEL 03 MERCEDES 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

15W40BSYN OIL BULK QTS 24

322502BULB PATIENT GH22 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

921LIGHT BULB 1

ACX-84534LUG NUT COVER PK10 2

HA141LIGHT RED WARNING 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V15609

In Date: 06/08/2008
Close Date: 07/07/2008

Meter Reading: 39,890.00

Problem?

front ac not working R23

Task performed:

1. front A/C inop. intermittent problem, loses blower. checked a/c system didnot pinpoint problem. unit working now.

Parts

VCC/36000006A/C FILTER CAB M2

Quantity

1

Workorder: V15714

In Date: 06/12/2008
Close Date: 07/07/2008

Meter Reading: 39,890.00

Problem?

front passenger headlights out r23

Task performed:

1. r/r right front headlight

Parts

9006XSLLEADLAMP M2 HI

Quantity

2

Workorder: V16027

In Date: 06/27/2008
Close Date: 07/07/2008

Meter Reading: 39,890.00

Problem?

Need Engine Oil R-23

Task performed:

1. drive to station. put 2.5 quarts in engine. gave station oil.

Parts

NO PARTS USED

Quantity

Workorder: V16051

In Date: 06/30/2008
Close Date: 07/07/2008

Meter Reading: 50,203.00

Problem?

ON CALL R23 AIR LEAK

Task performed:

1. replaced air dryer, purge valve leaking.

Parts

800404USE K022105 PURGE KIT AD-IP-IS

Quantity

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V16364

In Date: 07/14/2008

Meter Reading: 4,818.20

Close Date: 07/17/2008

Problem?

Internal Mechanism for handle of Lt Rear cab door is broken not allowing door to open. Unable to load stretcher and transport pts. R23

Task performed:

1. drive to st 23 r&r inside rear door handle

Parts

HND5948TM22676-02 HANDLE DOOR ENTRY

Quantity

1

Workorder: V16147

In Date: 07/03/2008

Meter Reading: 50,203.00

Close Date: 07/21/2008

Problem?

both rear outside tires worn down severely r23

Task performed:

Both rear outside tires worn down severely - Callaghan

Parts

NO PARTS USED

Quantity

j

Vendor?: CALLAGHAN

Workorder: V17090

In Date: 08/16/2008

Meter Reading: 4,994.00

Close Date: 08/28/2008

Problem?

a/c in front cab not blowing cold. R23

Task performed:

Drive to Stn; rep leak at fitting; top off freon; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V17383

In Date: 08/28/2008

Meter Reading: 53,417.30

Close Date: 09/02/2008

Problem?

steering pulls to rt r 23

Task performed:

Test drive unit; swap front wheels fixed problem; sent out for new front tires. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V17495

In Date: 09/03/2008

Meter Reading: 5,096.00

Close Date: 09/29/2008

Problem?

a/c blower cutting out. R23

Task performed:

Parts

Quantity

1. replace blower motor for rear a/c

NO PARTS USED

PARTS CHARGED ON WO 17835

Workorder: V17835

In Date: 09/20/2008

Meter Reading: 55,106.80

Close Date: 09/29/2008

Problem?

N3: Patient compartment AC intermittent. R-23

Task performed:

Parts

Quantity

1. replace both a/c condensor fans

60027FAN A/C COND 12IN 860026-2-W

2

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 110 A/

1

Workorder: V17320

In Date: 08/26/2008

Meter Reading: 53,417.30

Close Date: 10/01/2008

Problem?

INSTALL DIVIDERS IN MAP BOX R23

Task performed:

Parts

Quantity

1. Drive to Sta-23 to install divider for map box.

NO PARTS USED

(R.T.)

Workorder: V19070

In Date: 11/14/2008

Meter Reading: 58,232.50

Close Date: 11/20/2008

Problem?

check brakes r23

Task performed:

Parts

Quantity

Drive to Stn; chk brakes; 20% left; rivots rubbing on drum; take out of service; send to sop. j

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19211

In Date: 11/20/2008

Meter Reading: 58,232.50

Close Date: 11/25/2008

Problem?

INSTALL HOOK IN COMP

Task performed:

installed SCBA mounting brket on L-2 compt door.

Parts

Quantity

CYBS27299011 STRAP 36IN

1

KD-UN-7-SFKD-UN-7-SF BRACKET-AIR

1

Workorder: V19073

In Date: 11/14/2008

Meter Reading: 58,232.50

Close Date: 01/07/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED R23

Task performed:

1. C-Inspection - Hines/Reed
2. R/R front/rear brakes.
3. R/R belts.
4. Torque u-bolts.
5. Svc coolant.
6. R/R auto-eject cover & btry tender; change indicator.
7. Adj rear door handles.
8. R/R front shocks.
9. Truck drifting to right; swap front wheels - ok.
10. Tighten all door latches.
11. Cln work area.

Parts

Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MERCED

1

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0000902051FILTER FUEL 03 MERCEDES

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

0127110042BELT MERCEDES MOTORS

1

032-0116549297 BATTERY INDICATOR

1

05-17223-002RAD CAP 20 LB

1

091-3YWCOVER KUSSMAUL AUTO EJECT

1

15W40BSYN OIL BULK QTS

24

16302RETAINER CLIP

4

2673HYDRAULIC HOSE

1

3744BRAKE DRUM REAR

2

3753BRAKE DRUM RUMPER FRONT

2

42809AIR FILTER M2

1

5008414CARTRIDGE DC100

1

65140FRONT SHOCK NEW M2

2

800404USE K022105 PURGE KIT AD-IP-IS

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

91-22WIPER BLADE

2

9420BELT

1

EAA-8200-60EAA-8200-60 LIFT STRUTS

2

KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE

2

KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT

2

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

UVBULBAPS253PLS11W/TUV BULB A/C RESCUES

1

VCC/36000006A/C FILTER CAB M2

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V20213

In Date: 01/08/2009
Close Date: 02/05/2009

Meter Reading: 60,874.60

Problem?

INSTALL BATTERY CHARGER FOR STRYKER STRECTHER, R-23

Task performed:

Installed btry charger in pat comp. j

Parts

NO PARTS USED

Quantity

Workorder: V20990

In Date: 02/09/2009
Close Date: 02/12/2009

Meter Reading: 5,842.30

Problem?

On box, top right side clearance light inop (2-inch rectangle amber LED lamp)

Task performed:

1- Drive to station. installed lite. test ok.

Parts

CLR9185209186-1500-20 MARKER LT.AMBER LED

Quantity

1

Workorder: V20949

In Date: 02/08/2009
Close Date: 02/19/2009

Meter Reading: 62,008.00

Problem?

power steering fluid low engine coolant low R23

Task performed:

Drive to Stn; add P/S; look for leak; non; add coolant; press check; tighten clamp; test ok. j

Parts

15W40QSYN OIL QT

Quantity

12

Workorder: V21041

In Date: 02/11/2009
Close Date: 02/23/2009

Meter Reading: 62,008.00

Problem?

on call r23 battery switch 10-7 r23

Task performed:

Call out to Stn12; Fnd shorted master disconnect swtch; R/R swtch. j

Parts

75908SWITCH BATTERY MASTER 300A

Quantity

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V21140

In Date: 02/17/2009
Close Date: 02/23/2009

Meter Reading: 62,008.00

Problem?

NO EMERGENCY LIGHTS, R-23

Task performed:

Drive test; cln contacts on vista screen control button; needs new button kit; will be ok until permanent repair.
j

Parts

NO PARTS USED

Quantity

Workorder: V21143

In Date: 02/17/2009
Close Date: 02/23/2009

Meter Reading: 62,008.00

Problem?

NO EMERGENCY LIGHTS, V-MUX SCREEN BUTTONS INOP. R-23

Task performed:

Rem panels & vista screen; disassemble screen; replcd & push button asy; cut/made mnt studs for screen; mntd screen; ck opn; ck ok; reinstalled all panels.
j

Parts

0K00-1957-00KEY PAD 4 POSITION
0K00-1958-00KEY PAD 7 POSITION

Quantity

1
1

Workorder: V21231

In Date: 02/20/2009
Close Date: 02/25/2009

Meter Reading: 62,008.00

Problem?

COOLANT LEAK, R-23

Task performed:

Drive to Stn23; T-shoot coolant leak & fnd 3-way tee broken; replc tee; fill cooling sys & chk for leaks; rinse coolant off eng.
j

Parts

ALA00350-50 EXTENDED LIFE COOLANT GAL

Quantity

3

Workorder: V20884

In Date: 02/05/2009
Close Date: 02/28/2009

Meter Reading: 62,008.00

Problem?

REPAIR GROUND LIGHTS R23

Task performed:

1. drive to Stn; started to install lights; truck gets a call.
2. Drive to Stn; replc (2) brkts & lights & wire on (2) more lights; test ok.
j

Parts

607141-05USE 61H01 COPMPARTMENT LIGHT
MFG01876GROUND LT BRACKET

Quantity

2
2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V21436

In Date: 03/02/2009

Meter Reading: 64,055.40

Close Date: 03/03/2009

Problem?

ON CALL COOLANT LEAK R23

Task performed:

Parts

Quantity

Drive to Stn23; chk coolant leak; fnd tee broken; replc tee & refill cooling sys. j

NO PARTS USED

Workorder: V21571

In Date: 03/05/2009

Meter Reading: 64,476.70

Close Date: 03/06/2009

Problem?

CHECK ENG LT ON R23

Task performed:

Parts

Quantity

Chkd eng codes; 110-00/110-14 active; chkd cooling sys; added fluid & press tested; ok; fan clutch also works; c leared codes; ok. j

NO PARTS USED

Workorder: V21746

In Date: 03/12/2009

Meter Reading: 86,113.10

Close Date: 03/17/2009

Problem?

passenger side running board light hanging down. also engine light is still on! r23

Task performed:

Parts

Quantity

1. T-shoot check eng light; ECR code occured one time ____; clear code & rechk.
2. Replc both grnd lights/brkts on right side of cab. j

2FC00ZCR4 IN ROUND LED

2

Workorder: V22854

In Date: 04/28/2009

Meter Reading: 66,119.20

Close Date: 04/29/2009

Problem?

power steering fluid below min line R-23

Task performed:

Parts

Quantity

Added P/S fluid; ck level=ck ok; ck/leaks; none fnd; ck ok. j

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V21913

In Date: 03/18/2009

Meter Reading: 65,429.20

Close Date: 05/01/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED R23

Task performed:

- 1. B-Inspection
- 2. B-Inspection - add (3) qts trans fluid.
- 3. Cln btrys, cables & hold down.
- 4. Tighten hose clamps for coolant leaks.
- 5. Cln shop & organize library.
- 6. Dia air leaks.
- 7. Rem air horn solenoid & reseal fittings.
- 8. Rem cab lift bags.
- 9. Install cab lift bags.
- 10. Rem EGR cooler.
- 11. Chk for codes S146 inacti ve (1) count; erase code.
- 12. Secure clamps on turbo.
- 13. Replcd R-center dome bulb.
- 14. Rem EGR valve frm cooler & order parts.
- 15. R/R wheels.
- 16. Install EGR & cooler.
- 17. Codctor appnt
- 18. Change out coolant drum.
- 19. Fill radiator, pressure chk for leaks.
- 20. Erase EGR code & ABS codes; chk wheel speed sensors.
- 21. Degrease eng; test drive & chk for leaks.
- 22. Tighten/straighten exh tail pipe.
- 23. Replcd cab A/C filter.
- 24. Install lift control box & replc hyd valve.
- 25. Road test for EGR code.
- 26. County physical
- 27. P/S leak at pump; Class 2 leak; tried to tighten fasteners; bolts were tight; let go per Ed Ehrke. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A9061420580GASKET	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
DDE/A0039973352EGR COOLING HOSE	2
DDE/A02799760480-RINGS M2 WATER PUMP	1
EA9061420619RA9061420619 EGR VALVE	1
N917003022003GASKET/SEAL M2 WATER PUMP	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V22155

In Date: 03/27/2009

Meter Reading: 65,429.20

Close Date: 05/11/2009

Problem?

replace tires at shop callaghan

Task performed:

Replace tires at shop - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23044

In Date: 05/04/2009
Close Date: 05/19/2009

Meter Reading: 6,325.50

Problem?

Rubber seal between the cab and the box is torn. r23

Task performed:

Drive to Stn; installed new book from cab to box; test ok.
j

Parts

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WIDE

Quantity

6

Workorder: V23310

In Date: 05/16/2009
Close Date: 05/27/2009

Meter Reading: 68,365.10

Problem?

Back seat cab A.C. not working. R23

Task performed:

Chk cab rear A/C; fnd only low speed blower working; started to diss unit; unit had call; needs air filter & screw msg. j

Parts

NO PARTS USED

Quantity

Workorder: V23493

In Date: 05/22/2009
Close Date: 06/01/2009

Meter Reading: 68,862.20

Problem?

The roof leaks in the pt compartment where the shore line a/c on the ceiling is located. This was found transporting in a heavy rain R23

Task performed:

T-shoot water leak in upper A/C unit; fnd mntng bolts loose; tightened all bolts. j

Parts

NO PARTS USED

Quantity

Workorder: V23683

In Date: 06/01/2009
Close Date: 06/17/2009

Meter Reading: 68,941.70

Problem?

Right front headlight is out. No extra bulbs were found in the station to replace it. r23

Task performed:

Replc headlight bulb. j

Parts

9006XSLLEDHEADLAMP M2 HI

FTT5392USE 1432 SWITCH PRESSURE AC LO LIMITER

Quantity

1

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V24035

In Date: 06/12/2009
Close Date: 06/19/2009

Meter Reading: 69,432.40

Problem?

air leak in rear of truck R23

Task performed:

Left side leveling valve leaking; rem/install new leveling valve & adj latch. j

Parts

S4640024430VALVE LEVELIN

Quantity

1

Workorder: V23969

In Date: 06/10/2009
Close Date: 06/24/2009

Meter Reading: 69,432.40

Problem?

REPAIR HOLE IN REAR COMP R23

Task performed:

Replcd hole in L3 compt. j

Parts

NO PARTS USED

Quantity

Workorder: V24309

In Date: 06/24/2009
Close Date: 06/29/2009

Meter Reading: 865,345.00

Problem?

Right rear inside tire valve stem bracket broken r23

Task performed:

Rem wheel cover, nut & brkn brkt; replcd brkt; reassembled. j

Parts

NO PARTS USED

Quantity

Workorder: V24693

In Date: 07/10/2009
Close Date: 07/22/2009

Meter Reading: 86,665.90

Problem?

The Remote control spot light on the top of the vehicle is not working. Its not the bulb, the light doesnt move at all or come on. R2:

Task performed:

traced & rewired shorted plug for spotlight. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25088

In Date: 07/27/2009 Meter Reading: 72,298.50
Close Date: 07/30/2009

Problem?

auto eject outlet on rescue not working. R23

Task performed:

Drive to Stn; replc 110 plug; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V25158

In Date: 07/29/2009 Meter Reading: 72,298.50
Close Date: 08/05/2009

Problem?

Top of exhaust pipe fell off. R-23

Task performed:

1. drive to Stn; old parts bad; go to shop; PU parts; replc; test ok. j
2. cut stack pipe. j

Parts

20A-400CLAMP 4" 33969
29206CHROME STACK 24 IN 4 IN
33961C35976 MUFFLER CLAMP

Quantity

1
1
1

Workorder: V25232

In Date: 08/02/2009 Meter Reading: 72,298.50
Close Date: 08/10/2009

Problem?

power steering fluid leak, spoke to oncall mechanic on the phone, power steering fluid was low and the crew had just filled the reservoir last shift. Also ground light fell off and the rear A/C only blows on the low sett R-23

Task performed:

Drive to Stn; bring to shop lift truck. tightene fitting; bad grnd on A/C; test ok. j

Parts

NO PARTS USED

Quantity

Workorder: V25324

In Date: 08/05/2009 Meter Reading: 2,523.80
Close Date: 08/20/2009

Problem?

ground lights missing R23

Task performed:

Drive to Stn; wait for truck; installed brkts & lights; wired; test ok. j

Parts

607141-05USE 61H01 COPMPARTMENT LIGHT
MFG01876GROUND LT BRACKET

Quantity

2
2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25432

In Date: 08/10/2009

Meter Reading: 72,298.50

Close Date: 08/25/2009

Problem?

The Cab A/C in R23B is not working.

Task performed:

A/C filter clogged; replc filter; sys press low; chk for leak-none fnd; charge sys; 4.3 lbs; sys ____ back sys only working on low speed; bad T-stat switch; none in stock; part on order. j

Parts

VCC/36000006A/C FILTER CAB M2

Quantity

1

Workorder: V25445

In Date: 08/11/2009

Meter Reading: 72,298.50

Close Date: 08/25/2009

Problem?

R23B Needs New Rear Tires. Two Of The Four Rear Tires Are Down To The Wear Indicators. Please Arrange To Have These Changed.

Task performed:

R23B Replaced (4) rear tires - Tiresole j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLES

Workorder: V25662

In Date: 08/20/2009

Meter Reading: 73,364.90

Close Date: 08/25/2009

Problem?

repair comt door latch r23

Task performed:

Replc rear pat compt entry door latch/handle & also replc lower door striker latch. j

Parts

HA24219 LATCH WHEEL COACH

HND5948TM22676-02 HANDLE DOOR ENTRY

Quantity

1

1

Workorder: V25886

In Date: 08/29/2009

Meter Reading: 86,885.00

Close Date: 09/01/2009

Problem?

Power steering problem due to noise when turning. R23

Task performed:

Call out; P/S leak; fnd P/S press hose fitting leak at pump. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25902

In Date: 08/31/2009

Meter Reading: 73,364.90

Close Date: 09/24/2009

Problem?

CINSPECTION AND REPAIRS AS NEEDED R23

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

C-Inspection	0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
2. Chkd P/S leak; traced problem to loose fitting on steer pump @ compressor; tightened fittin & rechkd for leak; topped off P/S reservoir.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
3. Replcd all (4) btrys & post/neg btry jumpers; (out of date)	0000902051FILTER FUEL 03 MERCEDES	1
4. Straighten exh stack & tighten band clamp.	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
5. Svc diff.	0041BRACKET TOOL	1
6. Svc air brake dryer.	0127110042BELT MERCEDES MOTORS	1
7. Replcd rear axle air bags.	1045-255-101SEAT CONTROL CABLE LEFT 61 IN	1
8. Replcd eng air filter.	1045-257-101SEAT CONTROL CABLE RIGHT 51 IN	1
9. Replcd rear cab A/C filter.	15W40BSYN OIL BULK QTS	28
10. Replcd pat compt A/C filter.	16-15762-00016-19471-000 AIR BAG	2
11. Replcd belts.	29526898 29548988 TRANS FILTER ALLISON	1
12. Svc P/S.	42809AIR FILTER M2	1
13. Diss left rear pat compt entry door; replcd lower latch; adj linkage; adj door strikers & lubed.	5008414CARTRIDGE DC100	1
14. Sec stretcher hood to floor of pat compt (loose).	71R0872SWITCH OFF/ON/ON	1
15. installed "out of svc" stickers.	71R145011-2613 SWITCH 1220	1
16. Tightened all cab grab handles (loose).	78R536078R5360M 2PK FILTER AIR COND	1
17. Install new velcro hold down for O2 wrench in L1 compt.	906-181-00-86OIL FILTER M2 SPINNER 57140	1
18. Changed pat compt side entry door asy; (cracked/brkn).	9060910580FUEL PUMP GASKET M2	1
19. Change pat compt rear entry door; bezel handle & lock mechanism over to new style asy; (cracked/brkn).	9060920510FUEL CHECK VALVE	2
20. Replcd fuel pump.	91-22WIPER BLADE	2
21. Replcd fuel return line & chk valve (update).	9420BELT	1
22. Replcd wiper blades.	A0631087000CABLE BATT. POS.	1
23. Replcd reflector tape on pass frt door.	A0631088000CABLE BATT. NEG.	1
24. Paint fuel cap.	A18-42549-003DOOR LATCH RIGHT	1
25. Replcd non-skid on all cab steps.	A9060901276A9060903376 FUEL LINE	1
26. Replcd axe hold down asy in L-2 compt (brkn).	ACX-84534LUG NUT COVER PK10	4
27. Replcd large plexiglass compt door inside pat compt	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
28. Drilled new mntng holes & replcd hinges in over wheel compt door. (L3 comp).	DDE-0076030102007603016102 WASHER OIL SENDER	1
29. Rep all (3) air park release asys to facilitate ease of release; replcd one cable & tested opn of all.	DDE-R0040910501FUEL PUMP M2	1
30. Cln water out of right rear turn signal light & reseal.	DOOR5LEXAN 9 X 38 1/2 IN	1
31. T-shoot rear cab A/C inop; traced problem to faulty fan resistor; replcd resistor. also replcd fan control swtch.	HAN-1LBEZEL AND HANDLE	2
32. Lube, tighten & adj all cab & body door latches & holdopens, strikers & door checks.	HLD44614446 1/4 LATCH	1
33. R/R dash & fab mntng plate for parking brake valve; (brkn dash).	HP-31DBATTERY 950CCA HP-31D	4
34. Installed msng lug nut covers.	K022105PURGE VALVE AD-IP-IS	1
35. Polished headlights to rem cloudiness due to sun damage.	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
36. Adj air horns.	VML/T1808D2503221C1 FILTER POWER STEERING	1
37. Rem steering wheel.		
38. R/R steering wheel to straighten & road test.		
39. Chkd air solenoids under truck for door alarms; fnd no problems.		



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26351

In Date: 09/21/2009
Close Date: 09/25/2009

Meter Reading: 74,444.50

Problem?

CAB A/C INOP, R-23B

Task performed:

Went to Stn28; rem dash panels; ck connections; ck ok;
R/R filter; cld not find problem; sys ck ok. j

Parts

VCC/36000006A/C FILTER CAB M2

Quantity

1

Workorder: V26108

In Date: 09/08/2009
Close Date: 10/14/2009

Meter Reading: 73,364.90

Problem?

REPLACE FRONT TIRES AT SHOP R23 TIRESOLES

Task performed:

Replace front tires at shop R23 - Tiresoles j

Parts

NO PARTS USED

Quantity

Vendor?: TIRESOLES

Workorder: V26619

In Date: 10/01/2009
Close Date: 10/19/2009

Meter Reading: 7,028.80

Problem?

ac blower not working in front cab. r23

Task performed:

A/C blower faulty; replcd blower & harness & chkd opn.
j

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2

VCC/83000038AC WIRE HARNESS

Quantity

1

1

Workorder: V26711

In Date: 10/06/2009
Close Date: 10/20/2009

Meter Reading: 87,076.00

Problem?

muffler exhauast pipe is bent, appears it will fall off.

Task performed:

Rem tailpipe & clamp; straighten pipe; install tailpipe with
new clamp. j

Parts

20A-400CLAMP 4" 33969

Quantity

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26661

In Date: 10/05/2009
Close Date: 10/23/2009

Meter Reading: 87,076.00

Problem?

RIGHT SIDE CAB STEP LIGHT BECAME DISLODGED....NEEDS REPAIR R23

Task performed:

Drive to Stn; replcd light & hsng; test ok. j

Parts

Quantity

607141-05USE 61H01 COPMPARTMENT LIGHT
MFG01876GROUND LT BRACKET

1
1

Workorder: V26982

In Date: 10/19/2009
Close Date: 11/02/2009

Meter Reading: 76,589.00

Problem?

RPAIR O2 LEAK R23

Task performed:

Drive to Stn; wait for truck; reg bad; replcd O2 reg; test ok. j

Parts

Quantity

REG041462369 O2 REGULATOR

1

Workorder: V27424

In Date: 11/04/2009
Close Date: 11/16/2009

Meter Reading: 76,944.40

Problem?

repair stretcher medco equip

Task performed:

Repair stretcher - Medco j

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO

Workorder: V27651

In Date: 11/14/2009
Close Date: 11/30/2009

Meter Reading: 7,283.80

Problem?

stretcher mount on rescue 23 bravo is npt locking into stretcher when stretcher is being placed into rescue. takes manipulation to get lock to engage to secure stretcher

Task performed:

Adj/lubed stretcher lock. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23886

In Date: 06/08/2009
Close Date: 12/01/2009

Meter Reading: 69,432.40

Problem?

ON CALL R23 A/C 10-7

Task performed:

Road call; meet unit at shop; replc blower fan & rep fuse holder. j

Parts

Quantity

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

Workorder: V24939

In Date: 07/21/2009
Close Date: 12/03/2009

Meter Reading: 70,921.20

Problem?

Interior 'Door Ajar' light and alarm is malfunctioning. Alarm and interior cab lights come on spontaneously when driving. r23

Task performed:

see 25902

Parts

Quantity

23-12337002RIVET PLASTIC

3

Workorder: V27423

In Date: 11/04/2009
Close Date: 12/11/2009

Meter Reading: 76,944.40

Problem?

fab brakets for map box van linda

Task performed:

Fab brkts for map box - Van Linda j

Parts

Quantity

NO PARTS USED

Vendor?: VAN LINDA IRON WORKS

Workorder: V28315

In Date: 12/14/2009
Close Date: 12/22/2009

Meter Reading: 87,427.00

Problem?

R23 front cab a.c. is not working. The air does not come out when turned on.

Task performed:

replc melted fuse holder for A/C. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29010

In Date: 01/11/2010
Close Date: 02/04/2010

Meter Reading: 80,962.60

Problem?

B INSPECTION AND REPAIRS AS NEEDED R23

Task performed:

- B-Inspection
- 2. Replcd all SCBA brkts w/new style.
- 3. Tightened hinge mnt on L-3 compt.
- 4. L-2 inner compt; replc gas spring assist.
- 5. Pat heater inp; heat control valves clsd under hood.
- 6. Replc door entry moldings in cab; out of stock on 1 left one; will defer; part ordered.
- 7. Replcd burnt bulbs in pat comp dome light.
- 8. Replc cab & pat A/C filters.
- 9. Water nozzle for wiper inop; fnd hose disconnected btwn wirewall/bottle.
- 10. Rep L-1 compt door; new piece of plexi was too thick; had to mod to fit.
- 11. Rep torn off grd lite; had to redrill mntng hoes; had return light to get cooler light & program to stay on _____.
- 12. Fnd air leak at foot valve on firewall; replc to air line fittings; tested for leaks; all ok.
- 13. Adj air horns.
- 14. Test drove to chk heat in pat compt.
- 15. Fault code displaying on dash; no check engine light; eng & trck run good; no fault on ECU or ABS; fnd info in book; fault BHM module; fnd poor connection on connector; test drove to mk sure fault stayed off.
- 16. Tried to polish all covers; need to be wetsanded.

j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
18-46375-00018-46375-004 TREAD PLATE LH M2	1
18-46375-00118-46375-005 TREAD PLATE RH M2	1
2FC00ZCR4 IN ROUND LED	1
322502BULB PATIENT GH22	2
4070091740 GROMMET T/L 4 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
DOOR3LEXAN 23 X 12	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
MFG01876GROUND LT BRACKET	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V29171

In Date: 01/15/2010
Close Date: 02/25/2010

Meter Reading: 80,962.60

Problem?

REPLACE REAR TIRES

Task performed:

Replace reat tires - Callaghan j

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29650

In Date: 02/02/2010

Meter Reading: 7,642.30

Close Date: 03/03/2010

Problem?

FRONT CAB AC BLOWING WARM/HOT R23

Task performed:

1. R/R cab A/C compressor.
2. Assisted with A/C compressor change.
3. T-shoot cab A/C; R/R H-block & dryer; did not fix; will bring trk back.
4. T-shoot cab A/C; rerimp line at condensor; R/R dryer at condensor, vac & charge ok.

Parts	Quantity
0K00-1957-00KEY PAD 4 POSITION	2
0K00-1958-00KEY PAD 7 POSITION	1
16-3148VALVE CORE A/C 8926	1
161812-0617A EXPANSION VALVE VCC88000030	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
8201L17-3428 ESTER OIL E7	1
ABPN833181091512 SWITCH A/C 22-36474	1
RD-5-7063-OP07-2618AA/C DRIER 7155	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V29827

In Date: 02/09/2010

Meter Reading: 82,417.40

Close Date: 03/04/2010

Problem?

passanger rear tire: stem valve bracket loose r23

Task performed:

1. Went to Stn23; fnd both pedalstals msng; rem lugnuts; installed mnts; ck press; ck ok; replc (1) nut cvr.
2. Ck vista screen; fnd button jmmcd; ordered buttons (be in next week); fnd vista screen replcd. j

Parts	Quantity
ACX-84534LUG NUT COVER PK10	1

Workorder: V29874

In Date: 02/10/2010

Meter Reading: 82,417.40

Close Date: 03/04/2010

Problem?

officer side rear wheel valve stem bracket found broken. vehicle making clicking noise while in motion. broken piece removed from vehicle. R23

Task performed:

Rep done 2-12/10 W.O. 29827. j

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V30498

In Date: 03/05/2010 Meter Reading: 84,086.80
Close Date: 03/17/2010

Problem?

ABS Tractor light came on while driving R23 today.

Task performed:

1. anti lock It on 2 counts rt rear sensor check sensor gap test drove npf

Parts

Quantity

NO PARTS USED

Workorder: V30497

In Date: 03/05/2010 Meter Reading: 84,086.80
Close Date: 03/25/2010

Problem?

R23 needs motor oil. We need motor oil here at St23.

Task performed:

Cldn ABS codes & gave crew (1) case of oil. j

Parts

Quantity

15W40QSYN OIL QT

12

Workorder: V26189

In Date: 09/11/2009 Meter Reading: 6,941.70
Close Date: 04/13/2010

Problem?

NEED TWO NEW NUMBER PLATES FOR THE RESCUE. THE ONES WE HAVE ARE REALLY FADED AND SCRATCHED. r23

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V30886

In Date: 03/19/2010 Meter Reading: 84,938.80
Close Date: 04/28/2010

Problem?

Wire running to the light underneath the running board on driver side is severed. Casing that holds the wire is also severed at that spot. R23

Task performed:

Fnd wires brkn under drivers step; rep wires; ck ok; R/R R/frnt step lite bulb; rep R/rear cab step lite/mnt; chk lites; ck ok. j

Parts

Quantity

2FC00ZCR4 IN ROUND LED

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V30222

In Date: 02/25/2010

Meter Reading: 83,459.30

Close Date: 05/03/2010

Problem?

Front and rear a/c inop R23 on call

Task performed:

1. Chk frt A/C; fnd freon low; add freon & leak chk; leak tester NG; fnd rear A/C problem due to bad vista node; look for node (none in stock); swap out veh.
2. T-shoot vista screen; fnd ckt board damaged; replc/repprogrammed; also replc cracked vista bezel in pat compt.
3. A/C in frnt has leak; searched for leaks; fnd faulty hose in cond cab under step; rem line & replc w/new one; leak tested sys.
4. Completed A/C rep; reinstalled cab step at condensor; charged A/C says; ran sys/chk press & cooling; all working normal at this time. j

Parts

Quantity

354044HOSE ASSY	1
6201-0010-00VISTA I	1
OB59164500VISTA 111 CASE	1
OQ30164410FRONT LABLE	1
RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401737ESPRING PEDAL RETURN	1
RGT401741CRETURN SPRING	1

Workorder: V31540

In Date: 04/14/2010

Meter Reading: 84,938.80

Close Date: 05/11/2010

Problem?

REPLACE FRONT TIRES R23 BOULEVARD

Task performed:

Replc front tires R23 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE

Workorder: V31731

In Date: 04/22/2010

Meter Reading: 86,588.40

Close Date: 05/17/2010

Problem?

Battery Status indicator for the shoreline is not working. Unknown whether the vehicle is charging when plugged in or not. r23

Task performed:

Went to Stn23; ck shoreline charges; reset breaker; fnd charges working; needs lites on charger replcd; went to Stn23; R/R charge panel lites; ck opn; ck ok. j

Parts

Quantity

032-0116549297 BATTERY INDICATOR	1
----------------------------------	---



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V32244

In Date: 05/17/2010

Meter Reading: 86,588.40

Close Date: 05/24/2010

Problem?

repair damaged ground light R23B

Task performed:

Travel to Stn23; fnd grnd lite dragging on grnd & bent; straightened frame; rem lite; bolt holes stripped out; travel home. j

Parts

NO PARTS USED

Quantity

Workorder: V31999

In Date: 05/04/2010

Meter Reading: 87,704.00

Close Date: 06/01/2010

Problem?

Perform "C" service R23.

Task performed:

1. C-Inspection
2. R/R pat compt side steps grip tape.
3. Torque u-bolts.
4. Replce bulbs in pat compt.
5. R/R rear brake shoes & drums; also replce R/rear wheel seal.
6. Rep wires & mnt (2) new grnd light brkts on R/side of cab.
7. C/O cab A/C; rem freon, vac down & recharge.
8. R/R btry tender lights.
9. Rem, dry & reseal R/R T/S.
10. Adj drivers door.
11. Remnt L-3 comp hinge brkts.
12. Tighten, lube/adj all compt door hinges/latches.
13. Rem top slides for biohazard disposal; install new plastic slides.
14. R/R left rear door entry sill.
15. Adj air horns.
16. Sand/polish headlight lens.
17. Replc R/side windshield washer line.
18. Quality check. j

Parts

0000900087DDE/A0000900087 FILTER HEAD SM MERCED 1

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0000902051FILTER FUEL 03 MERCEDES 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

032-0116549297 BATTERY INDICATOR 1

1229F4634SKIT RING/LOCK WASHER 1

15W40BSYN OIL BULK QTS 24

18-46375-00018-46375-004 TREAD PLATE LH M2 1

322502BULB PATIENT GH22 1

3744BRAKE DRUM REAR 2

380003ASEAL 1

39008USE 39045 KIT 1

401581GASKET AXLE FL80 R002435 1

607141-05USE 61H01 COPMPARTMENT LIGHT 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

921LIGHT BULB 1

KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT 2

LTC7771NA200 HANDLE 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V32309

In Date: 05/19/2010
Close Date: 06/14/2010

Meter Reading: 88,656.90

Problem?

replace all 4 rear tires (outside agency-boulevard tire)

Task performed:

Replace all (4) tires - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V29662

In Date: 02/02/2010
Close Date: 07/08/2010

Meter Reading: 7,642.30

Problem?

R23B TO RETURN TO THE SHOP ON 2/3/10 FIRST THING IN THE AM TO CONTINUE WORK ON THE AC/ALSO BUTTONS C CONTROL PANEL NEED REPLACING AS EMERGENCY LIGHTS DO NOT TURN ON WITH EASE DUE TO WORN OUT BUTT PER FAST EDDY

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V33331

In Date: 07/05/2010
Close Date: 07/29/2010

Meter Reading: 90,955.00

Problem?

Cab AC oos R23

Task performed:

Fnd cab A/C blower inop; R/R blower/harness; R/R cab filter; reassembled; ck opn; ck ok. ja

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2

VCC/36000006A/C FILTER CAB M2

VCC/83000038AC WIRE HARNESS

Quantity

1

1

1

Workorder: V34095

In Date: 08/06/2010
Close Date: 08/31/2010

Meter Reading: 92,835.40

Problem?

shoreline plugin truck is not working to charge truck. we already checked the exstension cord and it works. r23

Task performed:

C/O shoreline eject-ok; C/O charger lights dim on charger pull rack; C/O put on charger not working; find 110V ckt brkr- tripped; reset brkr; rechk ok; wrng info from driver. ja

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34206

In Date: 08/11/2010
Close Date: 09/03/2010

Meter Reading: 92,835.40

Problem?

When shutting vehicle off, very large air leak from rear of vehicle, possibly rear air bags. Causes delays when responding. R23

Task performed:

1. went to 23; fnd leveling valve leaking; cld not get under truck safely; brought truck to shop; R/R level valve; ran/ck ok.
2. Went to 23; adj air bag level; ck ok. js

Parts

Quantity

S4640024430VALVE LEVELIN

1

Workorder: V34432

In Date: 08/22/2010
Close Date: 09/03/2010

Meter Reading: 93,381.50

Problem?

AUTO EJECT ON BATTERY CHARGER/SHORELINE OUTLET NOT WORKING R23

Task performed:

- Went to 23; chk opn of auto-eject; ck ok; NPF. js

Parts

Quantity

NO PARTS USED

Workorder: V34135

In Date: 08/09/2010
Close Date: 09/08/2010

Meter Reading: 84,938.80

Problem?

rear step falling off R23 (callout repair)

Task performed:

- Rep rear step that was falling off. j

Parts

Quantity

NO PARTS USED

Workorder: V34572

In Date: 08/27/2010
Close Date: 09/09/2010

Meter Reading: 93,381.50

Problem?

Leaking air dump, A/C coolant vent line hanging loose under officer side pt door, and 2 lights out in pt compartment. r23

Task performed:

1. Air leak from secondary air line; hose to rear tank has a hole in it; rep air leak.
2. Pat compt A/C condensor mnt brkn; R/R condensor; replc brkt; reinstall unit. j

Parts

Quantity

RG1006BZEE BRACKET HOSELINE CONDENSOR

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34841

In Date: 09/09/2010

Meter Reading: 94,531.00

Close Date: 09/27/2010

Problem?

PAITIENT A/C 10-7 / REPAIR BRAKE LTS R23

Task performed:

1. Dia pat compt A/C failure.
2. Dia rep rear brake light failure; fnd in freight line break in sys solenoid; install new air solenoids.
3. Dia A/C problem
4. Dia/replc brake light air manifold switch.
5. Dia A/C sys failure; use of manual & contact tech support for assistance;
6. Dia A/C problem; replc node #3 & reprogram; chk electrical schematcs; chk power at node #1; pin in ok; chk diodes; call tech support for node #3, pin 11 & 14.
7. Open up E-mail & inntall in laptop files; download program into node #3; chk opn of condensor fan-ok; protect wire harness at cond & secure.
8. Assist w/above repair - Flerx.
9. R/R volume on/off knob on fire main radio. j

Parts

Quantity

107796DRYER KIT AD9 -NEW

1

Workorder: V34864

In Date: 09/10/2010

Meter Reading: 94,531.00

Close Date: 09/28/2010

Problem?

on call brake lts 10-7 r23

Task performed:

No brake light; fnd node #7 no replay; reboot wld not take; take to shop; download all nodes; node 6 was not taking right; tried number of times; it took brake light; started to work in rear of truck & outside; also ok at this time. j

Parts

Quantity

NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34917

In Date: 09/13/2010
Close Date: 09/29/2010

Meter Reading: 94,531.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 23

Task performed:

- B-Service.
- 2. Replcd frt cab A/C filter.
- 3. Replc rear cab A/C filter.
- 4. Replc pat compt A/C filter.
- 5. Replc wiper blades.
- 6. Clnd wtr out of R/rear t-signal & resealed - water intrusion.
- 7. Straigten grnd light brkt & replc rubber bezel - bent/torn.
- 8. Adj air horns.
- 9. Installed msng screws in console cvr for center console in cab.
- 10. T-shoot A/C; low air flow & not cooling well; replc fan motor asy; replc A/C cntrl in dash; also accuator motor for blend door; chk all other accuator doors; recovered A/C sys & replc expansion valve; vac/recharged; A/C now works normally.
- 11. Replc buckle asy for right frnt cab seat & straighten out belt - twisted/brkn.
- 12. Rep faulty connection for backup camera - loose. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
161812-0617A EXPANSION VALVE VCC88000030	1
4070091740 GROMMET T/L 4 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A22-57054-003A/C SWITCH	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/32000022ACTUATOR	1
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V35192

In Date: 09/26/2010
Close Date: 10/07/2010

Meter Reading: 95,609.00

Problem?

Front AC not blowing hot or cold air R23

Task performed:

- 1. travel to station 23; check and found blower motor inop; removed panel, repaired connection at blower; check opertion, checked ok. jab

Parts

Quantity

NO PARTS USED

Workorder: V36004

In Date: 10/28/2010
Close Date: 11/03/2010

Meter Reading: 97,190.00

Problem?

REPAIR STRETCHER ON CALL R23

Task performed:

- Went to 23; adj/lubed lock; ck opn; ck ok; return home. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V36690

In Date: 11/28/2010

Meter Reading: 99,493.90

Close Date: 12/02/2010

Problem?

PRESSURE RELEASE PIN ON TRUCK MOUNTED STRETCHER BRACKET NOT FUNCTIONING CORRECTLY. SOMETIMES BRACKET WILL NOT CLOSE WHEN STRETCHER IS READY TO BE SECURED IN TRUCK. R23

Task performed:

(1) TRAVELED TO STATION 23 TO REPAIR STRETCHER BRACKET PRESSURE RELEASE PIN IN R23. REMOVED AND REPLACED BRACKET AND ADJUSTED IT. OK. J.W.

Parts

090-0278STRECHER BAR NEW

Quantity

1

Workorder: V36694

In Date: 11/28/2010

Meter Reading: 99,493.90

Close Date: 12/03/2010

Problem?

LEFT HEADLIGHT, LOW BEAM NO LONGER WORKING r23

Task performed:

(1) TRAVELED TO STATION 23 TO REPAIR LEFT HEAD LIGHT ON R23. REMOVED HEAD LIGHT AND INSTALLED A NEW ONE. TESTED OK. J.W.

Parts

9006XSLLEHEADLAMP M2 HI

Quantity

1

Workorder: V36613

In Date: 11/22/2010

Meter Reading: 97,190.00

Close Date: 12/07/2010

Problem?

replace all 6 tires R23 (outside agency-TCI tire center)

Task performed:

Replace all (6) tires - TCI Tire j

Parts

NO PARTS USED

Quantity

Vendor?: TCTI TIRE

Workorder: V36806

In Date: 12/01/2010

Meter Reading: 99,493.90

Close Date: 12/22/2010

Problem?

DOMELIGHT OUT - PATIENT COMPARTMENT e23

Task performed:

(1) TRAVELED TO ST 23 TO REPAIR DOME LIGHT IN PATIENT COMPARTMENT. CHECKED OUT AND FOUND THE BULB WAS BURNT OUT. REPLACED WITH NEW ONE. J.W.

Parts

322502BULB PATIENT GH22

Quantity

2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V36805

In Date: 12/01/2010
Close Date: 01/06/2011

Meter Reading: 99,493.90

Problem?

AUTO-EJECTOR FOR SHORELINE NOT EJECTING POWER CORD r23

Task performed:

Travel to stn; auto-eject inop - sticking; clnd/lubed auto-eject. j

Parts

NO PARTS USED

Quantity

Workorder: V36807

In Date: 12/01/2010
Close Date: 01/06/2011

Meter Reading: 99,493.90

Problem?

LEFT REAR INSIDE TIRE AIR LINE CLIP BROKEN 23

Task performed:

Travel to stn; LRI valve stem ext mnt brkn; replc valve stem ext & aired tire. j

Parts

440-44 1/8 IN VALVE EXT
440-5 VALVE EXT.
AMH-1AMH-1 VALVE EXTENSION

Quantity

1
1
1

Workorder: V37823

In Date: 01/15/2011
Close Date: 01/25/2011

Meter Reading: 103,018.80

Problem?

leaking air - sound as if from driver side. air pressure gauge still reading good and still dumping fine R23

Task performed:

Repaired on WO 37824. j

Parts

NO PARTS USED

Quantity

Workorder: V37824

In Date: 01/15/2011
Close Date: 01/25/2011

Meter Reading: 103,018.80

Problem?

leaking air, still reading good pressure on gauges R23

Task performed:

Travel to stn; brought back to shop.

Parts

5008414CARTRIDGE DC100

Quantity

1

Air leak air dryer filter gskt; replc filter; had to use a chisel to remove. j



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V38883

In Date: 03/01/2011

Meter Reading: 105,824.50

Close Date: 03/22/2011

Problem?

REPAIR EXHAUST R 23

Task performed:

Temp repair exhaust stack. j

Parts

20A-400CLAMP 4" 33969

Quantity

1

Workorder: V39598

In Date: 04/01/2011

Meter Reading: 108,468.20

Close Date: 04/13/2011

Problem?

CAB DOOR AJAR ALARM CONSTANTLY TURNING ON AND OFF, TURNING CAB LIGHTS AND GROUND LIGHTS ON AT NIC NO DOORS ARE OPEN. R23

Task performed:

Travel to 23; replc door switch on right door. j

Parts

27-102A22-54259-000 DOOM LIGHT SWITCH M2

Quantity

1

Workorder: V39866

In Date: 04/12/2011

Meter Reading: 108,818.70

Close Date: 04/14/2011

Problem?

repair stretcher mount

Task performed:

Went to Stn23; fnd stretcher lock loose; adj/tighten lock; ck opn - ck ok; return to shop. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V38474

In Date: 02/13/2011

Meter Reading: 105,542.00

Close Date: 04/26/2011

Problem?

C inspection and repairs as needed R23

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

- Road test & C-Inspection
- 2. Eng compt btry; spray down compt w/degreaser; latch down compt.
- 3. Rear condensor fan mnt brkn; rem, fab new mntng brkt; install/secure.
- 4. Fuel cap only & greasy - cln up.
- 5. Windshield wiper blades worn; install new blades.
- 6. Bench seat struts weak; rem/install new struts.
- 7. Cab struts weak; rem struts/install new ones.
- 8. Cab A/C filter - rem clogged filter; install new one.
- 9. UV bulb blow; rem blown bulb; install new bulb.
- 10. Cab A/c in dash dirty; rem cab dash filter; install new filter.
- 11. Steering tilt & ____scopic pedal twisted; diss unit; install bolt spring & pedal asy.
- 12. Cab A/C only at shradr - unit blowing cool; chk press; sys low on freon; vac & chk for leak - none fnd; sys lost no vac; charged sys & operate cooling to 28 degrees; still no leak fnd.
- 13. Roof top 110 A/C cool discharge; cln filter, condensor, fan; compressor operating; fnd debris blowing exh vent; rem unit; operating normal.
- 14. Cab A/C hi-side shradr valve leaking; recvr freon; rem shradr valve & install new valve; vac sys; test/vac loss - pass test; charge sys; sys operating normal; cab temp 38 degrees.
- 15. Grill holddown inserts msng; sec grill w/stainless net/bolts.
- 16. Grill # holder falling off; rem, cln surface & install w/fresh 2-sided tape.
- 17. Windshield washer nozzle inop; rem/cln clogged parts; install/operate.
- 18. Modular box glass popping out; rem rubber retaining strips; cln rubber & insert channel; reinstall.
- 19. Modular box 110 A/C cvr loose; replc msng screw & secure cvr.
- 20. Action area light 10-7; rem blown bulb & install (2) new bulbs.
- 21. A/C belt - rem old belt & install new belt.
- 22. Serpentine eng belt; rem/install new belt.
- 23. Exh vent in modular compt brkn; rem; fnd vent slip out of retaining groove; sec/install.
- 24. Dash defroster inop; diss dash; air distribution actuator not cycling thru modes; rem unit; install new air distrubtion actuator & time to proper cntrl setting; operate unit; all functions working normal.
- 25. Modular unit compt door lock needs timing; loosen panel, time locks & reassem panels.
- 27. modular unit door panels screw loose; sec loose panel & replc msng screws & bolts.
- 28. Modular unit & cab partition torn; rem modling, partition rubber booth; cut new booth; install, secure ends w/adhesive; reinstall molding & secure.
- 29. Headlight cloudy; sand, cln & polish headlight lens.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0127110042BELT MERCEDES MOTORS	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
16-31438915 VALVE CORE A/C 3544706C1	1
39008USE 39045 KIT	2
42809AIR FILTER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
A-1A-1 LINE TAP 110V A/C	1
ACX-84534LUG NUT COVER PK10	4
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WIDE	7
HLD39914GSS7139UK STRUT 90#	2
HLD3999GSS1715UV 30LB STRUT GAS	2
RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401737ESPRING PEDAL RETURN	1
RGT401741CRETURN SPRING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/32000022ACTUATOR	1
VCC/36000006A/C FILTER CAB M2	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

30. Rem damage L-4 compt vent asy; fab plate cvr ventilation access area.

31. Sec loose electronic cables along frame rail. j

Workorder: V39969

In Date: 04/17/2011

Meter Reading: 109,884.00

Close Date: 04/26/2011

Problem?

R231 stretcher would not stay in load position, while Pt on it, in order to put in Rescue. Taken OOS. 1013259 R231

Task performed:

Send Medco Eqmpt j

Parts

NO PARTS USED

Quantity

Workorder: V40289

In Date: 04/30/2011

Meter Reading: 110,678.80

Close Date: 05/13/2011

Problem?

front a/c not working R23

Task performed:

Travel to 23; rewired blower motor harness for cab A/C. j

Parts

VCC/83000038AC WIRE HARNESS

Quantity

1

Workorder: V40892

In Date: 05/26/2011

Meter Reading: 111,147.30

Close Date: 05/31/2011

Problem?

Officer side mirror will not tighten. Saftey issue, Sta 23.

Task performed:

1. Officers mirror loose; secure loose mirror adjustment bolt.
2. Pat compt camera mnt loose; secure mntng.
3. Windshield wipers come on by themselves; rem defective combo cntrl unit(wiper & t-signal cntrl) install new cntrl switch. j

Parts

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

Quantity

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40918

In Date: 05/27/2011
Close Date: 06/07/2011

Meter Reading: 111,147.30

Problem?

Passenger side mirror will not stay in place and the driver can not see out the side of the vehicle. Sta 23.

Task performed:

Adj mirrors. j

Parts

Quantity

NO PARTS USED

Workorder: V41082

In Date: 06/03/2011
Close Date: 06/07/2011

Meter Reading: 113,577.70

Problem?

chrome exhaust tip on stack is missing, Sta 23.

Task performed:

Travel to 23; Replc msng stack. j

Parts

Quantity

20A-400CLAMP 4" 33969

1

29206CHROME STACK 24 IN 4 IN

1

35799FLAT CLAMP 4 IN

1

Workorder: V41843

In Date: 07/06/2011
Close Date: 07/12/2011

Meter Reading: 114,594.70

Problem?

passenger side mirror holder loose, bottom hex bolt stripped, Sta 23.

Task performed:

REMOVED MIRROR BRACKET AND SECURED BOLT
AK

Parts

Quantity

NO PARTS USED

Workorder: V41566

In Date: 06/23/2011
Close Date: 07/13/2011

Meter Reading: 114,594.70

Problem?

replace rear tires r 23

Task performed:

Replc rear tires R23 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V41444

In Date: 06/20/2011

Meter Reading: 114,970.00

Close Date: 07/14/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED R23

Task performed:

- B-Inspection
- 2. Svc btrys, tested - NG; replc btrys; cln terms/cables; replc msgng btry holddown; bend all thread to size; cut/install.
- 3. Add coolant to reservoir & preess chk sys for leaks - ok.
- 4. Replc wiper blades; fill up reservoir; rep right squirter.
- 5. Add frt wheel hub grease.
- 6. Dia RF door light inop; rem door panel latch linkages/latch; test electrical switch on latch ok; reinstall latch/linkages; install door panel; fnd door switch msgng from dash; because dash brkn, ordered dash.
- 7. Replc R/rear strobe light; splice wires/heat shrink connections.
- 8. Replc rear brake shoes/drums; adj brakes; test drive.
- 9. Rep grnd lights wiring.
- 10. Chk computer codes; fnd code for ABS inactive; erase code & test drive - ok.
- 11. Rebuild air horns/adj.
- 12. Charge frt A/C.
- 13. Quality check. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1094KIT-AIR HORN-GROVER	2
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
3744BRAKE DRUM REAR	2
906LIGHT BULB 12CP	10
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1

Workorder: V41851

In Date: 07/07/2011

Meter Reading: 114,594.70

Close Date: 07/20/2011

Problem?

Install dash.

Task performed:

- travel to 23 install new dash section
- travel to 23 installed missing door switch ak

Parts

Quantity

27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
A22-54059-000DASH PANEL R/H M2	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42503

In Date: 08/02/2011

Meter Reading: 114,594.70

Close Date: 08/03/2011

Problem?

won't start r 23

Task performed:

Parts

Quantity

ARRIVED AT 23 CHECKED BATTERIES 12.8 TRUCK
STARTED UP NO PROBLEM STARTED TRUCK
SEVERAL TIMES NO PROBLEM FOUND. AK

NO PARTS USED

Workorder: V42572

In Date: 08/05/2011

Meter Reading: 117,355.00

Close Date: 08/05/2011

Problem?

won't start.

Task performed:

Parts

Quantity

TRAVEL TO 23 STARTER 10-7 R&R STARTER

DR/190260358300026 38MT 11 TEETH STARTER

1

Workorder: V42605

In Date: 08/06/2011

Meter Reading: 117,355.00

Close Date: 08/09/2011

Problem?

Cab AC blows hot after 1-2 min of use. R 23

Task performed:

Parts

Quantity

travel to 23 a/c condenssor falling off
came to shop for spare truck took to 23 assist with swap
out

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42636

In Date: 08/08/2011

Meter Reading: 117,562.10

Close Date: 08/16/2011

Problem?

REPAIR A/C CONDENSOR FALLING OFF BLOWER 10-7 R 23

Task performed:

1. Ck cab A/C blower; fnd blower/harness bad; rem panel harness/blower; replc blower/harness; rep kick panel cvr mnt; ck ok.
 2. Fnd L/rear spring shfited & air bag not aligned; loosen u-bolts; reposition spring; torque bolts; ck ok; adj air bags.
 3. Fnd pat A/C condensor mnt brkts brkn; rem brkts & condensor; replc brkts; remntd condensor; ran pat A/C; ck opn & ck ok.
 4. Fnd air bags not dumping; ck brakes;, relay ckt; ck/cln connection at relay valve; ran/ck opn; ck ok.
- j

Parts	Quantity
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LONG	2
HA141LIGHT RED WARNING	1
RG1006BZEE BRACKET HOSELINE CONDENSOR	2
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000038AC WIRE HARNESS	1

Workorder: V42903

In Date: 08/18/2011

Meter Reading: 117,798.00

Close Date: 08/30/2011

Problem?

1. biohazard drawer broken. 2. the door alarm for the patient compartment does not sound. ((the back door to the pt compartment was open while driving and the alarm did not sound)). Sta 23.

Task performed:

1. Replc bio drawer slides.
2. Chkd door alarm - NPF. j

Parts	Quantity
2220-10SLIDE 10 IN	2
5632-1010 IN DRAWER SLIDES PR	2

Workorder: V43106

In Date: 08/28/2011

Meter Reading: 11,873.00

Close Date: 08/30/2011

Problem?

ENGINE FAN NOT RUNNING CORRECTLY, MAKES ALOT OF NOISE R23

Task performed:

went to elmhurst rd wpb found eng belt broken replaced belt ck pulleys alt ac com started eng belt making a little noise shut off truck restarted belt locked called tow company went to shop swapted rescue 23 into sr 11 ---went to 15

Parts	Quantity
0127110042BELT MERCEDES MOTORS	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V43116

In Date: 08/29/2011

Meter Reading: 11,873.00

Close Date: 09/14/2011

Problem?

possible water pump r 23

Task performed:

water pump faulty also found ecg cooler leaking excessive iol on valve checked and cleaned crankcase breath -- mesh removed pump and --cooler

put pump and cooler back on installed new ecg valve coolant line from pump housing to air compressor faulty ordered part removed line

put coolant line back in put everything back together started motor to check for leaks tighten c--where leaks present

Parts	Quantity
9062010080GASKET M2 WATER PUMP	1
9062030015PIPE SOCKET TO WP	1
A0000180133DIAPHRAM SEAL	1
A0079932401SPRING DIAPHRAM	1
A0149972845ORING WATER PUMP M2	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
A9062032402WATER LINE M2	1
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R90620043019062006301 WATER PUMP SOME M2 CI	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/A0039973352EGR COOLING HOSE	2
DDE/A0279976048O-RINGS M2 WATER PUMP	2
DDE/N00000001072SEAL RING M2 WATER PUMP	1
EA9061420619RA9061420619 EGR VALVE	1
N917003022003GASKET/SEAL M2 WATER PUMP	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V43201

In Date: 09/01/2011

Meter Reading: 118,859.00

Close Date: 09/14/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R 23

Task performed:

C INSPECTION

REPLACED REAR STRUTS IN PAT COMP

REPLACED CAB AND PAT A/C FILTERS

WINDSHIELD WASHER INOP FOUND HOSES KINKIED AT WIPER ARMS AND UNDERHOOD

VOLTAGE INCORRECT ON DASH DISPLAY FOUND A LITTLE CORROSION AT BULKHEAD MODULE CLEANED TERMINALS AND VOLTAGE NOW DISPLAYS CORRECCTLY

REPLACED FOGGED UP LENSES ON GRILL

POWER STEERING SERVICE

EXHAUST TIP AND LMAP AT AN ANGLE AND LEAKING REMOVED CLAMP REALIGNED CLEANED TIP AND RELCAMPED AT CORRECT ORIENTATION

A/C CONDENSOR FAN FAULTY REMOVE STEP TO ACCESS UNIT REMOVE COVER ARM RE--FAN FOUND A/C LINE LEAKING RE--SYSTEM REPLACE LINE TEST AND CHARGE SYSTEM

QUALITY CHECK

REPAIR AIR LEAK AND ADJUST --VALVES

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
68118358130600 SER OPTIC CLEAR	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	6
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V43657

In Date: 09/14/2011

Meter Reading: 119,198.60

Close Date: 09/15/2011

Problem?

AC is broken st 23

Task performed:

ravel to 23 checked unit found all a/c systems working

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V43541

In Date: 09/09/2011

Meter Reading: 11,873.00

Close Date: 09/16/2011

Problem?

truck leaning to the left.

Task performed:

Parts

Quantity

Reinstall adjusting rod & adj both sides; cut rods down so they dont hit air vac fitting. j

NO PARTS USED

Workorder: V43682

In Date: 09/14/2011

Meter Reading: 119,198.60

Close Date: 10/20/2011

Problem?

CAB A/C 10-7 R23

Task performed:

Parts

Quantity

found unit low on charge checked for leaks charged a/c all ok

NO PARTS USED

Workorder: V45239

In Date: 11/17/2011

Meter Reading: 123,651.30

Close Date: 11/29/2011

Problem?

B INSPECTION R 23 oil change services

Task performed:

Parts

Quantity

1. B INSPECTION OIL CHANGE SEVICES

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

0000902051FILTER FUEL 03 MERCEDES

1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH

1

906-181-00-86OIL FILTER M2 SPINNER 57140

1

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1

Vendor?: OIL CHANGE SERVICES



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45266

In Date: 11/18/2011

Meter Reading: 123,651.30

Close Date: 12/01/2011

Problem?

Compressor locked up

Task performed:

Found eng belt off and cab a/c comp locked up leak test system comp leaking bad had to replace and install comp to leak test found discharge hoses to cont. and --leaking removed 4 hoses cut and made hoses

a/c cont: had to completely flush system removed rear a/c panels r&r exp valvecon rear unit and removed air cleaner coolant tank r&r cab exp valve r&r o rings replaced eng belts leak test ch ok vac and charge a/c ck ok

ck air bags found linkage off of rt bag reassembled and installed linkage adjusted

Parts	Quantity
07-14488-000DIPSTICK	1
071601A07-0602A DRIER A/C 7118	1
08-6061B4402 FITTING HOSE A/C	1
08-6062BUSE 08-6962BS FITTING A/C 4403 SB1302	2
1512BINARY SWITCH 22-36474	1
160012-2012A EXPANSION VALVE 71R8301	1
161812-0617A EXPANSION VALVE VCC88000030	1
4410S 08-6961B FITTING	3
4411S08-6962BS 90 DEGREE SB1322	2
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614AAC DRIER M2	1
PH660412A/C CAP	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45390

In Date: 11/23/2011

Meter Reading: 123,651.30

Close Date: 12/01/2011

Problem?

COMPLETE REPAIRS FROM B INSPECTION

Task performed:

replace missing lug nut covers

Parts

Quantity

ACX-84534LUG NUT COVER PK10

6

check ut brakes for wear

HLD44614446 1/4 LATCH

1

check out power steering leak, clean and wash down side of frame and gear box, repair hose connection on return line to reservoir

replace bent up side door holder bracket, some modifications necessary to install new bracket

found stretcher j hook loose, removed and remounted hook

round left rear spring shifted loosened u bolts reposition spring retorque rear axle ubolts ck ok

found steer tires worn, -- both tires got tires from building 3 -- tires test drove

deliver vehicle to station

assist mac with delivery

Workorder: V45581

In Date: 12/02/2011

Meter Reading:

Close Date: 12/05/2011

Problem?

engine oil is low, Sta 23

Task performed:

Parts

Quantity

travel to 23 checked engine oil level good also checked compartment lights all ok

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V46359

In Date: 01/05/2012
Close Date: 01/10/2012

Meter Reading: 126,687.20

Problem?

check engine light came on approx. 19:30. stryker stretcher has a dead spot when lifting up, Sta 23

Task performed:

CHECK ENGINE CODES - FOUND HIGH COOLANT TEMP, INACTIVE CODE - RAN ENGINE - TROUBLESHOOT FAN ENGAGEMENT - RAN AND CHECK OK - CLEARED.

Parts

NO PARTS USED

Quantity

Workorder: V46833

In Date: 01/25/2012
Close Date: 01/26/2012

Meter Reading: 128,290.00

Problem?

Siren inop.

Task performed:

TRAVEL TO STA 23 - FOUND SIREN IN/OP. REMOVED COUNSUL COVER AND CHECKED WIRING AND PLUG (OK). TEST SIREN AFTER CHECKING PLUG AND WIRING NOW SIREN WORKS INSTALL COVER TRAVEL HOME.

Parts

NO PARTS USED

Quantity

Workorder: V46874

In Date: 01/26/2012
Close Date: 02/07/2012

Meter Reading: 128,450.00

Problem?

stretcher mount is lose R23

Task performed:

TRAVEL TO STATION REMOVE STRETCHER ADJUST JHOLD BRACKETS REINSTALL STRETCHER CHECK OPERATION. OK.

Parts

NO PARTS USED

Quantity

Workorder: V47356

In Date: 02/15/2012
Close Date: 02/27/2012

Meter Reading: 130,118.00

Problem?

replaced rear tires

Task performed:

1. REMOVE BALLED TIRES AND INSTALL NEW TIRE REAR.
2. R&R REAR TIRES.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47401

In Date: 02/17/2012
Close Date: 02/27/2012

Meter Reading: 130,497.00

Problem?

replce front tires

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V45112

In Date: 11/11/2011
Close Date: 03/09/2012

Meter Reading:

Problem?

LEANS TO THE PASSENGER SIDE ALL THE TIME, POSSIBE AIR BAG PROBLEM

Task performed:

service call to road truck broke down a/c compressor
frozen up towed to shop

Parts

NO PARTS USED

Quantity

dont close this work order, still waiting for more
paperwork

Workorder: V47745

In Date: 03/04/2012
Close Date: 03/19/2012

Meter Reading: 131,630.00

Problem?

Map light broken. Does not turn on. The base of the light is no longer attached to the center console Sta23

Task performed:

TRAVEL TO STATION INSTALL NEW LIGHT.

Parts

LF18TS-LEDMAP LIGHT LED 18 IN

Quantity

1



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47918

In Date: 03/12/2012

Meter Reading: 132,128.10

Close Date: 03/28/2012

Problem?

BACK UP CAMERA WORKS ON AND OFF, ALSO NEW DASH LIGHT WAS JUST INSTALLED BUT DOES NOT WORK. R23

Task performed:

1. DASH BOARD LIGHT INOP - REMOVE FACE PEACE - FOUND LOOSE WIRE CONNECTION FOR DASH LIGHT - SECURE WIRE HARNESS.
2. BACKUP CAMERA - DIAGNOSING CAMERA INTERMITTING FAILURE UNABLE TO GET CAMER TO FAIL.
3. Q. & A. INSPECTION
4. HEADLIGHT LENSE POLISH.

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47889

In Date: 03/12/2012

Close Date: 03/30/2012

Meter Reading: 132,128.10

Problem?

C INSPECTION R23

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

1. C-Inspection.
2. Air Dryer Service.
3. Cab to chassis ground strap broken - remove part - cut new cable solder ends to install.
4. Coolant system service.
5. Windshield wiper blade and fluid reservoir service add 2 bottles of eng. solvent.
6. Patient compartment a/c filter service R&R.
7. Cab rear a/c filter damage - remove and install new filter.
8. Officer side a/c filter service and secure loose cover panel.
9. Cab front a/c blowing cool - close heater circulation valve.
10. Patient compartment UV bulb inop - remove and found bulb blown - install new bulb.
11. 110 a/c not blowing unit cold - found condenser froze over defrost - clean condenser core - reassemble and operate.
12. Driver window switch broken - remove window switch and install new switch.
13. Driver door step under garage light unsecure - replace grommet to install light.
14. L&R side cab mid ship LED light 10-7 - remove LEDs rewire new LED warning light and install.
15. Map light 10-7 found blown bulb and lamp fuse - replace bulb and fuse.
16. Electronic fan cab compartment 10-7. Found fan inop - loose ground to temperature switch - correct fault.
17. Cab center partition loose - clean and resecure.
18. R-2 ground light 10-7 - found LED assembly failure - remove and install new assembly.
19. Left front and left rear mod marker light 10-7, remove blown LED marker light and install 2 replacement marker light.
20. Mid shop warning LED light 10-7 - remove and install new LED assembly.
21. Fuel cap need painting - clean cap - paint fuel cap yellow.
22. Cab to Mod partition booth loose - clean and reseal booth seam.
23. Patient side door panel missing screws and has loose ones. Install new replacement screws and securely fasten all door panel screws.
24. R-1 door panel loose - remove screws and retap holes securely fasten door panel.
25. Unit drift and pull to right - check toe-in found toe-out at 1/16 adjust toe in to 1/16 in.
26. City horn inop - diagnose fault found horns malfunction. remove and install 2 new horn.
27. Air horn out of tune - tune air horn.
28. L-2 compartment tool holder loose - secure tool holder.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
39045HEADLITE KIT WITH SEALER	1
50R03ZCRLIGHT LED RED TIR 6	2
8550A250A8550A250A BULB	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A06-30769-027DOOR LOCK SWITCH	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48630

In Date: 04/12/2012

Meter Reading: 133,909.00

Close Date: 04/13/2012

Problem?

REPLACE REAR TIRES

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V49085

In Date: 05/03/2012

Meter Reading: 135,388.60

Close Date: 05/09/2012

Problem?

There is a air leak coming from under the rescue.

Task performed:

Parts

Quantity

CHECK FOR AIR LEAK - FOUND AIR LINE BETWEEN COMP. OUT PUT AND DRYER. CUT LOOSE AND REMOVED LINE FOUND PARTS IN PARTS ROOM. CUT HOSE. INSTALLED ENDS. REPLACED LINE AND TIED UP. CHECK OK.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V49411

In Date: 05/16/2012

Meter Reading: 136,564.00

Close Date: 05/30/2012

Problem?

A INSPECTION SR 14 POSS WHEEL SEAL LEAK

Task performed:

1. WHEEL SEAL REPLACEMENT: WHEEL SEAL LEAKED ALL OVER BRAKES, HUB, AXLE AND SUSPENSION.
2. CONTINUE WHEEL SEAL AND BRAKE SHOE REPLACEMENT: CLEANED ALL RELATED PARTS DURING DISASSEMBLY.
3. CONTINUED WHEEL SEAL AND BRAKE SHOE REPLACEMENT: CONTINUED CLEANING AND BEGAN REASSEMBLY.
4. CONTINUED WHEEL AND BRAKE SHOE REPLACEMENT. HAD TO REMOVE HUB ASSEMBLY A SECOND TIME, NEW SEAL WAS DAMAGED DURING FIRST REPLACEMENT. REPLACED BRAKE SHOES ON BOTH SIDES OF DRIVE AXLE, REASSEMBLED, ADJUSTED BRAKES, ROAD TESTED TRUCK FOR EXTENDED PERIOD, RECHECKED SEAL AND FOUND NO FURTHER LEAKAGE. RECHECKED BRAKE ADJUSTMENT AND TOPPED OFF DIFFERENTIAL.
5. REPLACED BROKEN SWITCH WITH SPARE KEY FROM OFFICE.
6. PERFORM "A" SERVICE.
7. REPLACED WIPER BLADES, CLEAN OUT CLOGGED WINDSHIELD SQUIRTS, ADDED WASHER FLUID AND TOPPED OFF RESERVIOR.
8. REPLACED PATIENT COMPARTMENT DOME LIGHT BULB. (BURNT).
9. STRAIGHTENED AND SECURED DRAWER SLIDES FOR BIO HAZARD DRWER TO PATIENT COMPARTMENT. (BENT/FALLING OFF). REINSTALLED DRAWER.
10. STRAIGHTENED AND REMOUNTED GROUND LIGHT ASSEMBLIES. (BENT/FALLING OFF)

Parts

Quantity

322502BULB PATIENT GH22	1
380003ASEAL	2
401581GASKET AXLE FL80 R002435	1
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	7
E-600013-3052 NUT	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2

Workorder: V49946

In Date: 06/06/2012

Meter Reading: 136,564.00

Close Date: 06/13/2012

Problem?

REPAIR FLAT

Task performed:

REPAIR FLAT

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50331

In Date: 06/22/2012

Close Date: 06/26/2012

Meter Reading: 13,798.70

Problem?

A inspection

Task performed:

ADJUST AIR HORNS.

Parts

Quantity

TOR00FRR2 IN LED

1

Workorder: V50820

In Date: 07/12/2012

Close Date: 07/18/2012

Meter Reading: 138,253.90

Problem?

REPAIR FLAT

Task performed:

REPAIR FLAT

Parts

Quantity

NO PARTS USED

Vendor?: ELPEX



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50704

In Date: 07/09/2012

Close Date: 08/02/2012

Meter Reading: 138,253.90

Problem?

B INSPECTION SR 14

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

1. B-INSPECTION.
2. FAILED BATTERY TEST - REMOVE ALL BATTERIES AND REPLACE - REPAIR TWO ACC. WIRES AND BATTERY HOLD DOWN RODS.
3. A/C AIR INTAKE FILTERS - REPLACE ALL A/C AIR INTAKE FILTERS - NOTE: CAB DASH FILTER COVER TO HOUSING HAD ALL SCREWS STRIPPED OUT - REPAIR COVER HOUSING.
4. FILTER GUARD - A/C - CAB REAR A/C FILTER GUARD (KICK PLATE) MISSING CUT OUT A PIECE OF EXPANDED METAL AND TRIM TO FIT FILTER HOUSING - INSTALL.
5. BATTERY SLIDE DRAWER - BATTERY SLIDE DRAWER AND LATCHES HANG UP, DRAWER VERY HARD TO OPEN - WASH OUT ROAD DEBRIS FROM DRAWER ROLLERS AND LATCHES - LUBE AND WORK DRAWER AND LATCHES UNTIL FREE.
6. ENGINE AIR INTAKE FILTER - REPLACE ENGINE AIR INTAKE FILTER.
7. BUFF OUT TAIL, BRAKE, TURN, BACK UP AND BODY SIDE EMERGENCY LIGHT LENSES.
8. CAB DOOR LATCHES INOP- R/FRONT AND L/REAR CAB DOORS ARE HARD TO OPEN FROM OUTSIDE VEHICLE - REMOVE DOOR PANELS FROM BOTH DOORS - FOUND LATCHING SET SCREWS MISSING FROM INNER DOOR MECHANISM - FISH AROUND BOTTOM OF DOOR FOR SCREWS AND REINSTALL ADJUST LEVER PULL - REINSTALL DOOR PANELS.
9. GROUND LITES AND AIR DUMP FUNCTION - INOP - CHECK OUT PROBLEM WITH NO GROUND LIGHTS AND NO AIR DUMP FUNCTION - RESET FUNCTIONS ON V-MUX PANEL - CYCLE BATT SWITCH - ALL FUNCTIONS NOW WORKING.
10. WIPER PIVOT POST - WIPER ARM PIVOT POST ON R/SIDE VERY LOOSE - TIGHTEN POST.
11. WIPER ARMS ADJUSTMENT - RETIME BOTH WIPER ARMS - BOTH WERE RUNNING OVER WINDSHIELF RUBBER MOLDING.
12. WIPER BLADES - INSTALL NEW WIPER BLADES.
13. FRONT TIRES - REMOVE TIRES - TO BE REPLACED ON FRONT ONLY - REINSTALL TIRES AND WHEELS AFTER NEW TIRES MOUNTED RECHECK TIRE PRESSURES AND FILL TO PROPER LEVEL.
14. AUTO EJECT INOP - CHECK OUT PROBLEM - PLUNGER HAS NO KICK - ORDER PARTS - INSTALL NEW AUTO EJECT MECHANISM.
15. AIR LEAKS - START SEARCHING FOR AIR OLEAK - SPRAY DOWN ALL COMPONENTS UNDER VEHICLE, ENGINE COMPARTMENT - BEHIND DASH ETC. FOUND TWO SMALL LEAKS AT AIR TANK FITTINGS - MAKE REPAIR - TWO BIG LEAKS AT DASH AIR GAUGES - REMOVE INSTALLMENT CLUSTER DISASSEMBLE AND CHANGE OUT GAUGE.
16. AIR BAG SUSPENSION - AIR BAGS GO FLAT IN

0/2-311-610-372SDUEL AIR GAUGE M2	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0915520120AUTO EJECT 20 AERO OTL3925	1
1501450007750USE 0775145	1
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LONG	6
42809AIR FILTER M2	1
684-4 VALVE - FILL AIR TANK	1
78R539018-2699 A/C FILTER	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A2252082003WIPER ARM RIGHTSIDE M2	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S4640024430VALVE LEVELIN	1
VCC/36000006A/C FILTER CAB M2	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

ABOUT 5 HOURS - CHECK FOR LEAKS IN COMPLETE SYSTEM - FOUND HEIGHT ADJUSTMENT RODS IMPROPERLY SET UP AND ADJUSTED WRONG - RESET ALL RODS TO PROPER LENGTH - NOW ADJUST HEIGHT VALUES TO PROPER HEIGHT.

Workorder: V51129

In Date: 07/25/2012

Meter Reading: 138,253.90

Close Date: 08/03/2012

Problem?

REPLACE FRONT TIRES

Task performed:

REPLACE FRONT TIRES.

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V51912

In Date: 08/27/2012

Meter Reading: 139,736.10

Close Date: 09/11/2012

Problem?

A INSPECTION SR14

Task performed:

1. A INSP
2. INFLATE BOTH R/R TIRES CHK FOR LEAKS REPAIR LEAKS AT INFLATOR HOSES.
3. TAKE OIL SAMPLE AND FILL INFO CARD.
4. PROBLEMS R&R BULB L/R PATIENT CEILING LT

Parts

322502BULB PATIENT GH22

Quantity

1

Workorder: V51683

In Date: 08/17/2012

Meter Reading:

Close Date: 09/13/2012

Problem?

Flat rear exterior tire(passenger side) Bridgestone 265 70R19.5

Task performed:

FLAT REAR EXTERIOR TIRE (PASS SIDE).

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRES



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V52385

In Date: 09/14/2012

Meter Reading: 140,251.00

Close Date: 10/04/2012

Problem?

A INSPECTION AND NEEDED REPAIRS

Task performed:

1. A INSPECTION.
2. INSTALLED NEW DRAWER SLIDES - REPAIRED RATTLES - HAD NEW TIRES TEST DROVE.

Parts

Quantity

5632-1010 IN DRAWER SLIDES PR

2

Workorder: V53144

In Date: 10/16/2012

Meter Reading: 140,685.30

Close Date: 10/17/2012

Problem?

door ajar lite going off, SR-14

Task performed:

1. door alarm going off, check doors found problem in small rear door above folding step in rear entry, door would not open key lock frozen, sprayed lube and tried to open, drilled out lock to open compt. door, found compt. loaded with dirt, clean compt. and sensors, install new lock, alarm still going off, check wiring found wires cut for sensor in harness, install new sensor and wires, test ok

Parts

Quantity

03910030SWITCH COMPARTMENT DOORS

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V53496

In Date: 11/02/2012

Meter Reading: 142,383.40

Close Date: 12/13/2012

Problem?

A inspection

Task performed:

1. A INSP
2. ADD 2 QTS TRANS AND 2 QTS OIL.
3. CHK TRANS CODE 3500 POWER INTERUPTION (INTERACTIVE CODES) ERASE CODE.
4. WHEEL SHIMMY ABOVE 45 MPH. CHK FRT END R WHEREKING/ PIN MOVEMENT. NEED TO CHECK WHEEL BALANCE SMALL AMOUNT OF WHEEL BEARING MOVEMENT.
5. SECURE RADIATOR VENT HOSE (STRAP BROKEN) INSTALL TIE STRAP TO SECURE.
6. REAR NADAR PIN COVERS BROKEN DRILL HOLES IN NEW COVERS AND COUNTER SINK HOLES INSTALL COVERS AND CHECK OPERATION OF DOOR OK.
7. REPLACED L-2 TOOL BRACKET.
8. BACKUP CAMERA NOT WORKING DURING ROAD TEST. CAMERA NOW WORKING IN SHOP.
9. A/C CONTROL HEAD LOOSE NO FASTNERS FOUND NO RETAINER THREADS IN DASH M2 DASH. INSTALL DOUBLE SIDED TAPE TO SECURE CONTROL HEAD PER EDE.
10. SWAP LFT AND RGT FRT WHEELS PER EDE.
11. ADJ AIR HORNS FOR SOUND.
12. BELT CHIRP R&R FAN AND REPLACED BELTS.
13. INSTALL MISSING RAD SHROUD BELT.
14. REPLACED DIPSTICK BOOT AND O-RING.

Parts

Quantity

01-29866-118BELT ALT. M2	1
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/2 LONG	4
9420BELT	1
A0149974148SEAL RING CAP	1
A3660180106CAP DIPSTICK	1

Workorder: V54385

In Date: 12/11/2012

Meter Reading:

Close Date: 12/13/2012

Problem?

a/c in pt compartment is no blowing any cool air (Spare being used at Station 32)

Task performed:

1. CHK PAT A/C INSTALLED A/C MACHINES-TROUBLESHOOT ELECTRICAL SYSTEM. R&R DIVIDE CONDENSOR, FOUND A/C COMPRESSOR BAD REMOVED AIR TUBE, HOSES, BELT, COMPRESSOR AND DRIER SWAPTED ALL. BRACKETS ADJUSTER AND HOSE GUARD, REPLACED COMP AND DRIER VAC AND CHARGE SYSTEM CHK OK.

Parts

Quantity

071601A07-0602A DRIER A/C 7118	1
5790COMPRESSOR A/C	1
EL35675BLACK DIODE PLUG DT04-49-RT01	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54632

In Date: 12/26/2012

Meter Reading: 143,901.50

Close Date: 01/24/2013

Problem?

A inspection

Task performed:

1. A-INSPECTION
2. REPAIR PATIENT AREA - SIDE ENTRY DOOR LATCH - DISASSEMBLE DOOR REALIGN HANDLE ON FRAME AND GRIND DOWN OUTER FACE PLATE FOR CLEARANCE REASSEMBLE.
3. PRESSURE TEST COOLANT SYSTEM TO FIND LEAKS - RAD BAD - ALSO HAS A LEAK BEHIND ALTERNATOR - HAD TWO SMALL LEAKS FROM HOSE CLAMPS - TIGHTENED CLAMPS - ALL RAD CLAMPS AND HOSE NEED REPLACEMENT.
4. COOLANT LEAK. RADIATOR LEAKING REMOVE RADIATOR DISASSEMBLE AND REASSEMBLE RADIATOR AND SUPPORT BRACKETS.
5. COOLANT LEAK. DIAGNOSE FAULT - REMOVE ENGINE MOUNT, WATER PUMP, WATER PUMP BACKING PLATE AND FAN ASSEMBLY - FOUND REAR SEAL O-RING LEAKING. ORDER PARTS - CLEAN AND INSPECT ALL PARTS. REASSEMBLING AND TORQUING ALL PARTS TO MANUFACTORY SPECS. OPERATE UNIT NO LEAKS.
6. Q.A. TRUCK, TIGHTEN ALTERNATOR BLOCK MOUNTING BOLT TEST DRIVE, TIGHTEN ALL AIR INTAKE HOSE CLAMPS.

Parts	Quantity
9062030015PIPE SOCKET TO WP	1
A0149972845ORING WATER PUMP M2	1
A9061840780GASKET	1
A9261840080GASKET	1
C1673FRE04 RADIATOR	1
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE-9061840280GASKET FILTER HOUSING	1
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/A0279976048O-RINGS M2 WATER PUMP	2
DDE/N00000001072SEAL RING M2 WATER PUMP	1
N000000001069SEAL BANJO	4
N007603014102SEAL	2
N917003022003GASKET/SEAL M2 WATER PUMP	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55515

In Date: 02/04/2013

Meter Reading: 144,078.40

Close Date: 02/05/2013

Problem?

A inspection

Task performed:

1. A-INSPECTION.
2. A/C COMPRESSOR BOLT BROKEN AND LOOSE - REMOVE NUT AND BOLTS - INSTALL NEW NUT, WASHER AND BOLTS - ADJUST TECION AND SECURE NUT AND BOLTS.
3. MAP LIGHT 10-7 FOUND BULB BLOWN ??? TO SHORT TO BODY. REPLACE BLOWN BLUB AND CORRECT SHORT.
4. CAB TO BOX PARTICIAN BOOTH TORN AND LOOSE - CLEAN AREA APPLY WEATHER ADHESIVE TO SURFACE AND BOND SECTION, RESET IN SUPPORT GROVE.
5. GROUND LIGHT INOP - CHECK WIRING - REPROGRAM NODE LIGHT OPERATING NORMAL.
6. AIR PUMP VALVE INOP AND SWITCH INOP - PONG NODES NODE REPLACE NO FAULT FOUND. CHECK CONNECTIONS FOUND LOOSE STICKING VISTA SCREEN BUTTON. SYSTEM OPERATING NORMAL.

Parts

Quantity

8550A250A8550A250A BULB

1

Workorder: V56085

In Date: 03/01/2013

Meter Reading: 145,585.00

Close Date: 03/22/2013

Problem?

Driver side head light is out. R54

Task performed:

REPAIRED BAD GROUND IN HEADLIGHT.

Parts

Quantity

9006XSLLEHEADLAMP M2 HI

1

Workorder: V47346

In Date: 02/15/2012

Meter Reading:

Close Date: 04/04/2013

Problem?

Map light in officers seat needs repair, electronic stretcher does not go up by itself initially,r 23

Task performed:

DUPLICATE WORK DONE ON W.O. #V47745.

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54100

In Date: 11/30/2012

Meter Reading: 48,435.00

Close Date: 04/08/2013

Problem?

A inspection

Task performed:

1. A INSP
2. SET ALL TIRE PRESSURES TO PROPER LEVELS- TO PROPER LEVELS. INSTALL NEW SHREADER ON R/F AND REPLACE TWO BROKEN FLEX HOSE BRACKETS ON REAR TIRES.
3. REPLACE CONTROL HEAD FOR ROOF MOUNT SPOT LT. NOTE NECESSARY TO CUT OFF ORIGINAL WIRE CONNECTORS AND BVT SPLICE AS NEW CONTROL IS OF NEWER STYLE AND CONNETORS DONT MATE.

Parts

Quantity

2020-DDASH MOUNT REMOTE CONTROL

1

Workorder: V52830

In Date: 10/03/2012

Meter Reading: 140,251.00

Close Date: 04/09/2013

Problem?

REPLACE REAR TIRES SR14

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56242

In Date: 03/07/2013

Meter Reading: 146,488.00

Close Date: 04/16/2013

Problem?

C inspection SR14

Task performed:

1. C-INSPECTION.
2. MAKE UP AND INSTALL ASSET TAG ON WINDSHIELD.
3. INSTALL NEW WIPER BLADES.
4. DISASSEMBLE R/SIDE OF REAR LT BAR AND REPLACE REAR SCENE/BACK UP LIGHT.
5. REPLACE L/SIDE-FRONT CLEARANCE LIGHT ASSEMBLY - (ON-BOX)
6. MAP LIGHT - INOP - INSTALL NEW DASH MAP LIGHT.
7. INSTALL ALL NEW A/C INTAKE FILTERS.
8. COOLANT LEAK - BOTTOM RAD HOSE LEAKING - (WRONG STYLE HOSE CLAMP) - REMOVE HOSE CLAMP AND INSTALL PROPER STYLE CLAMP.
9. STRETCHER MOLDING - STRETCHER HOOK AT BACK DOOR FLOOR - LOOSE - FIND LONGER SCREWS AND INSTALL.
10. LIGHT LENSES DULL - BUFF OUT ALL REAR LIGHT LENSES - (BRAKE, TURN, TAIL AND BACK UP LENSES.)
11. REMOVE ACCREDITATION DECALS.
12. EXHAUST SYSTEM HIT - HITTING BODY - LOOSE ALL BOLTS HOLDING EXHAUST PIPE AND MUFFLER - PRY OVER EXHAUST PIPE AND BLOCK UP MUFFLER TO GAIN BODY CLEARANCE - AND RETIGHTEN IN PLACE.
13. A/C CONDENSER - BROKE - ALL BUT ONE BRACKET HOLDING A/C CONDENSER UNDER VEHICLE INSTALL NEW CONDENSER MOUNTING BRACKETS ONTO CONDENSER VEHICLE BODY BRACKET ALSO BROKEN - MAKE UP NEW BRACKET AND MOUNT TO BODY FLOOR - NOW MOUNT CONDENSER TO BODY BRACKETS.

Parts

Quantity

000000001085OIL DRAIN GASTKET M2	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	27
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
MR1135 WATT BULB	1
RG1006BZEE BRACKET HOSELINE CONDENSOR	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V57150

In Date: 04/19/2013

Meter Reading: 149,513.00

Close Date: 04/23/2013

Problem?

spare rescue at 28, steering wheel adjustment not staying locked

Task performed:

travel to 28 adjusted lock for steering wheel.

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V58216

In Date: 06/05/2013

Meter Reading: 151,122.00

Close Date: 06/14/2013

Problem?

replace number placards sr at 53

Task performed:

1. REPLACED NUMBER SIGNS.
2. REPAIRED AIR LEAK AT REAR.

Parts

Quantity

L PLACARD INSERTLARGE PLACARD INSERT CARD

1

S PLACARD INSERTFRONT AND BACK INSERT CARD

1

Workorder: V58106

In Date: 05/31/2013

Meter Reading: 150,759.20

Close Date: 06/17/2013

Problem?

The air horn on the spare Rescue is not working. R54

Task performed:

1. REPAIRED HOLE IN AIR HOSE FOR AIR LINE AND ADJUSTED AIR HORNS.
2. RECHARGED REAR A/C AND REPAIRED LEAK.

Parts

Quantity

NO PARTS USED

Workorder: V59020

In Date: 07/11/2013

Meter Reading: 151,711.00

Close Date: 07/15/2013

Problem?

CHECK ENGINE LT ON UNIT OVERHEATS

Task performed:

TRAVEL TO STA 16 FOUND UNIT OVERHEATING NO AIR TO FAN CLUTCH. REPLACED SOLENOID BHANK VALVE ON REAR FRAME RAIL AND GOT AIR TO FAN. FAN STILL NOT WORKING. BAD CLUTCH TRUCK RUNS ROUGH WHEN CHECK ENGINE LIGHT ON COULD NOT DIAGNOSE BECAUSE PROGRAM IS OUT OF DATE. SENT TO SHOP FOR FAN CLUTCH AND CHECK ENGINE LIGHT.

Parts

Quantity

NRG-27-SNC-010RA12-19779-0 VALVE ASSY

1



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60822

In Date: 09/27/2013

Meter Reading: 151,711.00

Close Date: 10/10/2013

Problem?

B inspection SR14

Task performed:

1. B-INSPECTION.
2. FOUND L-2 PROTECTIVE COVER FOR BATH CHARGER OFF REINSTALLED REPLACED MISSING BOLTS.
3. FOUND NUMBER PLATE HOLDERS OFF AND LOOSE REMOVED OLD DOUBLE STICK TAPE REINSTALLED NUMBER PLATES.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT

1

S3226FL02FUEL FILTER 33813 L/F # LFF5851

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60122

In Date: 08/27/2013

Close Date: 10/18/2013

Meter Reading: 151,711.00

Problem?

repair damaged camshaft

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

1. CHECK CODES FOUND #4 INJECTOR MISFIRE - REMOVED AIR TUBE, BRACKET INJECTOR LINE, I.C.V. FOUND CAMSHAFT BAD.
2. FOUND DAMAGED CAMSHAFT AND I.C.V.
3. REPLACE CAMSHAFT INSTALLED I.C.V. AND FUEL LINE - MOVED TRUCK REMOVED DRIVESHAFT CABLE BRACKETS.
4. REPLACE CAMSHAFT CONT.
5. REMOVE CAMSHAFT CONT. REMOVED TRANS.
6. REPLACE CAMSHAFT CONT. REMOVED FLAP PLATE AND FLYWHEEL, EXH. PIPE AND CLAMP - MOTOR MOUNTS.
7. REPLACE CAMSHAFT CONT: REMOVED STARTER AND CABLES.
8. REPLACE CAM CONT. REMOVED RT- MOTOR MOUNT, FRAME MT ON LEFT AND RT.
9. REPLACE CAM CONT: REMOVED WATER TUBE, BELL HOUSING, CHAIN ENG. BLOCK.
10. REPLACE CAM CONT: DRAINED ANTIFREEZE, REMOVED TRANS. COOLER/REMOVED FRONT AXLE U-BOLTS - RAISED FRAME.
11. ASSISTED WITH CAM REMOVAL.
12. REPLACE CAM CONT: REMOVED OIL PAN - REMOVED VALVE COVER, RACKER SHAFT, PUSH RODS AND CAMSHAFT.
13. REPLACE CAM CONT: REMOVED OIL PAN GASKET - CLEANED BELL HOUSING OIL PAN AND ENGINE BLOCK.
14. REPLACE CAM CONT: CLEANED VALVE COVER ROCKER SHAFT, PUSHRODS, AND CYLINDER HEAD
15. REPLACE CAM CONT: REPLACED LIFTERS, REPLACED AND INSTALLED CAM SHAFT.
16. REPLACE CAM CONT: R&R REAR MAIN SEAL - CLEANED AND INSTALLED BELL HOUSING.
17. REPLACE CAM CONT: INSTALLED MOTOR MOUNTS AND OIL PAN.
18. REPLACE CAM CONT: INSTALLED STARTER, CABLES, I.P.V.S, ROCKER SHAFT PUSH RODS.
19. REPLACE CAM CONT: ADJUST ALL VALVES - REPLACED INJ LINES - REASSEMBLED BRACKETS AND FUEL LINES - FILLED WITH OIL INSTALLED VALVE COVER.
20. REPLACE CAM CONT: FILLED COOLING SYSTEM - BLED FUEL SYSTEM RAN ENGINE - CHECKED FOR LEAKS - CHECKED OIL - INSTALLED HOSES - INSTALLED FLEE PLATE AND TRANS.
21. ASSIST WITH TRANS INSTALLATION.
22. REPLACE CAM CONT: INSTALLED TORQUE CONV. BOLTS, DRIVELINE AND HARNESS.
23. REPLACE CAM CONT: INSTALLED TRANS, TUBE, LINES, REPLACED FRT. AXLE U-BOLTS - INSTALLED FRT. SHOCKS, FILLED TRANS. RAN AND CHECK LEVEL CHECK OK.
24. CHECK ENGINE CODES - FOUND A RID HEATER

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
20A-400CLAMP 4" 33969	1
2950782329546229 SEAL FILL TUBE	1
8T3416U BOLTS	4
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A0259975047REAR SEAL	1
A0280749102UNIT PUMP MBE ENGINES	6
A9060140922GASKET OIL PAN M2	1
A9060170524PIPE CONN	6
A9060541001TAPPET	12
A9060702433FUEL LINE	6
A9069970310PIN CAMSHAFT	1
AMG-300300 AMP FUSE	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1
DN34NUT FOR UBOLT	8
HOR/991450HT 650 FAN ASY.	1
NRG-27-SNC-010RA12-19779-0 VALVE ASSY	1
RA9060503401CAMSHAFT REBUILT	1
SUW34WASHER U BOLT	8



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

OPEN CIRCUIT - TROUBLESHOOT SYSTEM - R&R
POWER FUSE.

25. CHECK FOR AIR LEAKS FOUND FITTING AT FOOT
VALVE LEAKING REMOVED HOSE - R&R FITTING -
RAN AND CHECK OK.

26. CHECK ENGINE FAN - RAN ENGINE TO TEMP
FOUND ENGINE FAN INOP - CHECK AND
TROUBLESHOOT FAN CIRCUIT.

27. CHECK ENGINE FAN CONT: FOUND AIR
SOLENOID INOP - DRAINED AIR AND REMOVED
SOLENOID CLUSTER - R&R SOLENOID - RAN AND
CHECK FOR AIR LEAKS - CHECK OK INSTALLED AIR
LINES AND CLUSTER.

28. CHECK TRANS LEAK - FOUND DIPSTICK TUBE
LEAKING - REMOVED TUBE AND GROMMET -
REPLACED GROMMET - RAN AND CHECK FOR
LEAKS - CHECK OK FILLED TRANS.

29. CHECK ENGINE CODES CONT: FOUND INTAKE
HEATER CODE GOING ON AND OFF CHECK
SOLENOIDS AND WIRING.

30. CHECK ENGINE CODES CONT: TROUBLESHOOT
INTAKE HEATER FOUND AND REPAIR GROUND WIRE
- RAN AND CHECK OK - ERASE CODES.

31. REPAIR PAT BOX BREAKER - INSTALLED WIRES,
BREAKER AND COVER IN BOX.

32. CHECK FOR ENGINE FAN INOP - RAN ENGINE TO
TEMP - TROUBLESHOOT BAD FAN CHECK OK -
REMOVE FAN. SHROUD RAD SUPPORTS AND FAN
ASSEMBLY - REPLACED CLUTCH AND INSTALLED
FAN AND CLUTCH ASSEMBLY.

33. CHECK ENGINE FAN CONT: INSTALL FAN
SHROUD AND RAD. SUPPORT BRACKETS - TEST
DROVE AND CHECK FAN OPERATION - CHECK OK -
CHECK FOR LEAKS - CHECK OK - CHECK ALL
LEVELS - CHECK OK.

34. REPLACE CAM SHAFT CONT: PACK AND
RETURN CORES.

35. REPLACE CAM CONT: FINISH CORES AND
CLEAN BENCH.

36. CHECK STEERING WHEEL NOT STRAIGHT -
ADJUSTED FRONT TIRE AIR PRESSURE - SWAPTED
FRONT TIRES AROUND TEST DROVE CHECK OK.

37. CHECK ENGINE BELT NOISE - REMOVED FAN
CLUTCH AIR LINE, PAT A/C BELT, ENGINE BELT AND
TENSIONER - R&R TENSIONER AND BELT -
REASSEMBLED ALL BELTS - CHECK OK.



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V61359

In Date: 10/18/2013
Close Date: 10/25/2013

Meter Reading: 153,078.90

Problem?

Coolant leak

Task performed:

CHECK FOR COOLANT LEAK, FOUND HOSE AT TANK LEAKING DRAIN DOWN FLUID, CUT HOSE AT CUT, REINSTALL.

Parts

NO PARTS USED

Quantity

Workorder: V61365

In Date: 10/18/2013
Close Date: 10/25/2013

Meter Reading: 153,078.90

Problem?

a/c 10-7 r411

Task performed:

TRAVEL TO ST 41 CHECK OUT A/C SYSTEM FOUND A/C LINE LEAKING. GO TO ST 42 FOR PARTS TO REPAIR TRUCK. DIDN'T HAVE PARTS NEEDED AT SOUTH SHOP GO TO NORTH SHOP WITH TRUCK RECYCLE FREON REPLACE HOSE END ON PRESSURE LINE VACUUM SYSTEM REFILL TEST.

Parts

4359FITTING
R134AFREON LB

Quantity

1
30

Workorder: V61366

In Date: 10/22/2013
Close Date: 10/25/2013

Meter Reading: 54,580.00

Problem?

A/c inop

Task performed:

1. DRIVER COMPLAINT LEFT UPPER LED LIGHT OUT REPLACED LED LIGHT AND ALSO LED ON LOWER LIGHT 2 WERE OUT.
2. WORK ON A/C HOSE, FITTINGS, LEAKING RECOVER SYSTEM AND PREP SO JOHN ????? TO REPAIR.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V61278

In Date: 10/15/2013

Meter Reading: 153,078.90

Close Date: 11/20/2013

Problem?

A inspection SR14

Task performed:

1. R&R WIPER BLADES REPAIR F/S WASHER AND FILL WASHER RESEVOIR.
2. R&R CAB A/C FILTER R&R CAB AUX A/C FILTER.
3. R&R PATENT COMPT DOME LT BULB.
4. R&R R/S GROUND LIGHTS.
5. R&R CENTER CONSOLE CHECK AND CLEAN VIDEO CAMERO CONNECTIONS AT NODE FOR BOTH CAMERAS.
6. OVERHAUL AIR DRYER.
7. SERVICE ALLISON TRANS.
8. SERVICE P/S SYSTEM AND R&R FLUID AND FILTER.
9. SERVICE REAR AXLE ASSY.
10. FIND AND REPAIR AIR LEAKS.
11. MOVE L/S TRAILING ARM ON AXLE TO ALIGN AIR SPRING MOUNT.
12. R&R 2 REAR AIR SPRING.
13. C-INSP.
14. REPAIRS AFTER C INSPECTION.
15. CLEAN HEAD LIGHTS LENSES.
16. DIAGNOSING WINDOW CONTROL FAILURE.
17. LUBRICATE WINDOW REGULATOR AND REASSEMBLE DOOR, DOOR PANEL AND GRAB BHRS.
18. DIAGNOSE AND LEAK TEST PATIENT A/C SYSTEM.
19. ROAD TEST FOR PULL AND STEERING WHEEL OFF CENTER.
20. R&R REAR SWAY BAR BUSHINGS.
21. R&R AIRHORN SOLENOID (AIR LEAK).
22. JACK UP VEH. CHECK FRONT BRAKES FOR DRAG AND BRAKE ADJ CHECK AIR PRESSURES SWAP FRONT TIRES LEFT TO RIGHT.
23. START DIAGNOSIS OF CAB A/C SYSTEM.
24. DIAGNOSE CAB A/C DISCHARGE EVACUATE AND RECHARGE SYSTEM.
25. ROAD TEST PULL AFTER SWITCHING TIRES.
26. R&R STEERING WHEEL TO MAKE STRAIGHT WHILE DRIVING.
27. Q.A TRUCK.

Parts

Quantity

14-15612-000GASKET RVR PWR STRG M2	1
16-15762-00016-19471-000 AIR BAG	2
29526898 29548988 TRANS FILTER ALLISON	1
2FC00ZCR4 IN ROUND LED	1
322502BULB PATIENT GH22	1
39045HEADLITE KIT WITH SEALER	1
5008414CARTRIDGE DC100	1
6814600340A14-15472-000 HORN BUTTON	1
78R536078R5360M 2PK FILTER AIR COND	1
91-22WIPER BLADE	2
956223BUSHING SWAY BAR	4
EL360081760611 SOLENOID AIR HORN	1
FREIGHTSHIPPING CHARGES	20
K022105PURGE VALVE AD-IP-IS	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62420

In Date: 12/02/2013
Close Date: 12/03/2013

Meter Reading: 153,961.00

Problem?

replace tire

Task performed:

REPLACE TIRE

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V62415

In Date: 12/02/2013
Close Date: 12/04/2013

Meter Reading: 153,961.00

Problem?

R57 steering wheel will not lock

Task performed:

REPAIRED STEERING WHEEL LOCK.

Parts

NO PARTS USED

Quantity

Workorder: V62267

In Date: 12/02/2013
Close Date: 12/06/2013

Meter Reading: 154,142.90

Problem?

stretcher latch SR@57

Task performed:

1. TRAVEL TO ST 57 CHECK OUT STRETCHER LOCK ADJUST LOCK WORKS OK.
2. REAR DOOR ON SIDE STUCK PULL DOOR PANEL ADJUST LATCHES AND HINGE BENT.

Parts

NO PARTS USED

Quantity

Workorder: V62463

In Date: 12/04/2013
Close Date: 12/19/2013

Meter Reading: 154,503.40

Problem?

A-inspection @33

Task performed:

1. A INSPECTION.
2. REPAIR DOOR HANDLE FALLING OUT AND ADJUST LATCHES ON R-1 COMPT.
3. TURBO MAKING NOISE ADJUST TURBO HOSE CLAMPS AND RETEST TEST OK.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62597

In Date: 12/09/2013

Meter Reading: 154,142.90

Close Date: 12/27/2013

Problem?

Perform "A" inspection

Task performed:

a inspection not done at this time

Parts

Quantity

AST4000ASENSOR O2 REGULATOR

1

Workorder: V62717

In Date: 12/14/2013

Meter Reading: 154,771.00

Close Date: 01/23/2014

Problem?

The right rear blinker light is out. R33

Task performed:

1. WENT TO 33 FOUND LIGHT OUT REMOVED LIGHT FOUND LIGHT INOP RETURN TO SHOP FOR PART.
2. TRAVEL TO ST 33, CHECK OUT TURN SIGNAL. BAD LIGHT R&R LIGHT REWIRE TEST OK.

Parts

Quantity

60A00TARLED TURN SIGNAL LAMP

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V63477

In Date: 01/17/2014

Meter Reading: 158,070.60

Close Date: 02/03/2014

Problem?

A inspection from R33

Task performed:

1. A INSP.
2. ADD TRANS FLUID AND ADD ENG OIL.
3. PRESSURIZE COOLING SYSTEM- HAS A LEAK BUT CANT PIN POINT SOURCE- NEED VEH ON HOISTS TO SEE- COULD BE WATER PUMP.
4. R&R LEAKING BRAIDED EXT HOSE ON L/R OUTER TIRE INFLATE TO CORRECT PSI AND CHECK FOR LEAK-OK.
5. LUBRICATE ALL 4 REAR DOUBLE DOOR LATCHES. ADJ 2 LOWER STRIKER BOLTS. ADJ L/S STRIKER BOLT COVER.
6. R&R R/STOP MARKER LT. HAD TO R&R L/STOP EMER LT TO ACCESS WIRES TO PASS THROUGH HOLE.
7. CHECK FOR COOLANT LEAKS. TIGHTEN ALL LEAKY HOSE CLAMPS. HEATER CORE LEAKING- R&R DASH INTERIOR VERIFY.
8. R&R R/ROUTER TIRE AND WHEEL ASSY. REPLACE BOTH INFLATION HOSES AND ONE BAD LUG NUT.

Parts

Quantity

AMH-1AMH-1 VALVE EXTENSION	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
E-600013-3052 NUT	1

Workorder: V63748

In Date: 01/27/2014

Meter Reading:

Close Date: 02/07/2014

Problem?

Metal door handle on side entrance to patient compartment is split in half making the door unable to be opened and unusable. The actual metal has split in half. R37

Task performed:

1. TRAVEL TO ST-37 CHECK DOOR HANDLE AND R&R SIDE PT. COMPT DOOR HANDLE OUTER AND ADJUST LATCHES.
2. MOUNT NY HOOK IN REAR COMPT.

Parts

Quantity

5269LPVM-5 SM MOUNT	2
HND5948TM22676-02 HANDLE DOOR ENTRY	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V64284

In Date: 02/17/2014

Meter Reading:

Close Date: 02/19/2014

Problem?

Right head light on rescue is out!! SR@37

Task performed:

TRAVEL TO ST 37. HEAD LIGHT OUT R&R HEADLIGHT BULB.

Parts

Quantity

9006XSSLHEADLAMP M2 HI

1

H11H11-55WLL BULB LOW BEAM 92095787

1

Workorder: V64381

In Date: 02/20/2014

Meter Reading:

Close Date: 02/24/2014

Problem?

Low Voltage Being Displayed On The Center Control Console And Battery Symbol Lit Up On Dash With Audible Alarm Sounding Inside The Cab. The Unit Has Been Placed Out Of Service R37

Task performed:

REPAIRED ON ANOTHER WO.

Parts

Quantity

NO PARTS USED

Workorder: V64378

In Date: 02/20/2014

Meter Reading: 159,952.00

Close Date: 02/25/2014

Problem?

low voltage alarm

Task performed:

TRAVEL TO ST-37 CHECK OUT LOW VOLTAGE CHECK BATTs AND ALT BAD ALT SEND TO SHOP.

Parts

Quantity

NO PARTS USED

Workorder: V64447

In Date: 02/21/2014

Meter Reading: 159,952.00

Close Date: 02/25/2014

Problem?

low voltage

Task performed:

1. CHARGE BATTERIES RECOVER FREON. REMOVE AIR CHARGE COOLER PIPING. REMOVE A/C BELT A/C LINES AND COMPRESSOR REMOVE ALT BELT, ALT AND BRACKETS. ELECTRICAL CABLES INSTALL ALT COMPRESSOR, BELTS EVACUATE SYSTEM AND CHARGE WITH FREON. TEST DRIVE OK.

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V64588

In Date: 02/27/2014

Meter Reading:

Close Date: 03/03/2014

Problem?

R16 is in a spare. Spare needs at least 3 old box lights. Hook on the floor of the pt compartment to catch the stretcher is loose. Needs immediate attention.

Task performed:

Parts

Quantity

1. STRETCHER CATCH LOOSE, ADJUSTED STRETCHER CATCH.
2. 2 MARKERS INOP, BULBS INSTALLED BULBS AS NEEDED.

NO PARTS USED

Workorder: V65236

In Date: 03/26/2014

Meter Reading: 160,128.00

Close Date: 03/27/2014

Problem?

replace 4 rear tires

Task performed:

Parts

Quantity

REPLACE 4 REAR TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V64974

In Date: 03/17/2014

Close Date: 04/07/2014

Meter Reading: 160,128.00

Problem?

C Inspection SR14

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

1. C-INSPECTION. AIR TIRES, FILL WASHER RESEVOIR
2. REPLACE BATTERIES CLEAN CABLE ENDS AND TERMINALS.
3. REMOVE INACTIVE CODES FROM ENGINE AND TRANS.
4. REMOVE DRIVERS SEAT CUSHION FOR REPAIRS
5. DIAGNOSE COOLAT LEAK- FOUND HEATER CORE LEAKING DRAIN COOLANT. REMOVE AIR CLEANER, COOLANT RESEVOIR A/C FILTER LOWER DASH PANEL. BLEND DOOR MOTOR, CENTER DASH TRIM, RIGHT AND TOP DASH REMOVE CENTER CONSOLE TOP AND REMOVED SIDE BOLTS HOLDING CONSOLE. PULL BACK CONSOLE. REMOVED SCREWS ATTACHED TO HEATER CORES AND HOSES. CUT OUT OPENING IN PLENUMN HOUSING. REMOVE HEATER CORE.
6. REPLACED FRT BRAKES AND DRUMS.
7. REMOVE WHEELS INSTALL FITTING IN AIR BAG TANK TO INFLATE AIR BAGS FOR REAR WHEEL REMOVAL. INSTALL BEST TWO FROM REAR FRT. INSTALL 4 NEW ON REAR. INSTAL NEW BRACKETS AND EXT HOSES.
8. INSTALL HEATER CORE, COOLANT RESEVOIR HOSES AIR CLEANER ELECTRICAL AND FILL WITH COOLANT. PRESSURE CHECK AND LOOK FOR LEAKS. INSTALL CONSOLE DASH, HEATER DOOR MOTOR, TEMP PROBE AND LOWER COVER. DRILL HOLES FOR ALIGNMENT OF CONSOLE. INSTALL NEW HEATER CORE COVER. RUN VEHICAL AND CHECK OPERATION. TOP OFF COOLANT.
9. REPLACE WIPER BLADES.
10. SECURE DRIVERS ROCKER COVER.
11. CLEAN AUX A/C FILTER.
12. REPLACE BOTH R-1 DOOR HOLD OPEN LINKS, RODS AND PINS.
13. REPAIR L-4 DOOR HOLD OPEN LINK PINS. INSTALL NEW PUNS.
14. REPLACED DOOR HOLD OPEM LINK PINS ON L-2 DOORS.
15. P/S CLAMP RUBBING ON COOLER HOSE. REMOVED COOLER HOSE. REPOSITION CLAMP AND REINSTALL HOSE.
16. REPLACE REAR A/C FILTER. REMOVE COVER AND CHECK UV LIGHT OK.
17. SMALL O2 LEAK AT GUAGE FITTING, TIGHTEN FITTING AND TEST OK. REMOVED GUAGE AND RESEAL.
18. INSTALL DRIVERS SEAT BACK FROM BEING REPAIRED.
19. REPLACED STEERING WHEEL.
20. REAR COMPT DOOR HANDLE LOOSE WHEN IN LOCKED POSITION. CHECKED ON PARTS. (SPECIAL ORDER). BENT LOCKING LEVER TO KEEP DOOR

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1094KIT-AIR HORN-GROVER	1
1152258DOOR SEAL WPB PER IN	70
1501450007750USE 0775145	2
15W40BSYN OIL BULK QTS	26
18-40977-00018-52651-000 AIR SPRING CAB M2	2
22-53753-000VENT OUTBOARD LEFT	1
23-11345-707SCREW DASH	10
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
31000005HEATER CORE M2	1
322502BULB PATIENT GH22	1
3753BRAKE DRUM RUMPER FRONT	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1
A14-12612-002STEERING WHEEL M2	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
EXT4534RUBRAIL EXTRUSION PER FT	6
HP-31DBATTERY 950CCA HP-31D	4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2
MFG01876GROUND LT BRACKET	1
MFG9928PL17008 VERSACELL DECAL BACKING	6
RBR7862GA48800 RUBRAIL INSET	6
RGT-452258FFOOT PEDAL STERRING COLUMN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

TIGHT TO BODY.

21. LEFT AIR BAY OFF CENTER WITH FRAME LOOSEN U-BOLTS AND PRY LOWER FRAME TO LINE UP AIR BAG. TORQUE U-BOLTS.

22. DIAGNOSE VARIOS AIR LEAKS. FOUND FITTINGS AT AIR HORN SOLENOID AND AIR BAG TANK DRAIN. REMOVE FITTINGS, CLEAN AND APPLY SEALER TO THREADS AND RETIGHTEN. FOUND LEAK AT HOSE RUBBING CROSS MEMBER. CUT AND ADD SPLICE TO GOOD PART OF TUBING. FOUND AIR BAG FOR CAB LEAKING REPLACED BOTH AIR BAGS. TEST REPAIRS FOR LEAKS OK.

23. R/FRT PATIENT DOME LIGHT OUT. REMOVE LENS, REPLACED BULB. TEST OK INSTALL LENS.

24. REPLACED BROKEN LIGHT BOX CHARGERS SPLICE WIRING.

25. REMOVE GASKETS FROM REAR PATIENT DOOR WINDOWS. CLEAN GASKETS AND WINDOW TRACK. REINSTALL GASKETS. CLEAN WINDOWS. TIGHTEN INSIDE FRAME SCREWS.

26. REPLACE PATIENT REAR DOOR WEATHERSTRIP. CUT TO FIT.

27. REPLACED DAMAGED STEP SIDE RAIL. CUT TO SIZE DRILL AND RETHREAD HOLES. INSTALL RUBBER INSERT. COUNTER SINK AND DRILL OUT RUBBER INSERT. CUT AND INSTALL DECAL PNL DRILL AND SECURE PANEL. CUT AND INSTALL NONSKID STRIP.

28. R/FRT DOOR WONT ACTIVATE DOME LIGHTS. FOUND CORRODED CONTACTS IN SWITCH. REPLACED SWITCH.

29. GROUND LIGHTS INOP-FOUND BAD CONNECTION AT RELAY. REPAIR OPEN CONNECTION.

30. R/SIDE GROUND LIGHT BENT. REPLACED BRACKET. DRILL NEW HOLES AND SECURE. DRILL AND INSTALL WIRE FRAME CLAMP.

31. WIRE PLUG HANGING DOWN BY AIR MANIFOLD CLEAN MALE AND FEMALE CONTACTS RECONNECT. CHECKED OPERATION OK.

32. PEDAL BROKEN FOR TILT STEERING REMOVE DASH LOWER PANELS REPLACED WISH BONE LEVEL AND ASSEMBLE SPRINGS REPLACED MISSING SCREWS IN LOWER DASH PANELS.

33. LEFT A/C REGISTER BROKEN. REPLACED REGISTER.

34. DEGREASE ENGINE SET UP AND TEAR DOWN EQUIPMENT. RAISE VEHICLE AND SPOT CLEAN. DRIVE VEHICLE RAISE ON HEIST AND CHECK FOR LEAKS FOUND LEAK AT ONE OIL PAN BOLT P/S CLAMP, TIGHTENED BOLT AND REPLACED P/S SPRING CLAMP WITH WORM GEAR TYPE CHANGE OIL AND TAKE SAMPLE. CLEAN AREAS OF REPAIR. TEST DRIVE AND CHECK REPAIRS OK.



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

- 35. Q.A.
- 36. ADJ AIR HORNS COULD NOT GET RIGHT AIR HORN SOUND QUALITY, REBUILD RIGHT AIR HORN, ADJ FOR SOUND QUALITY.
- 37. WIPERS COME ON BY THEMSELVES. CHECKED SERVICE

Workorder: V64827

In Date: 03/10/2014 Meter Reading: 160,128.00
 Close Date: 04/15/2014

Problem?
 coolant leaks

Task performed:

1. CHECK OUT COOLANT LEAKS FOUND HOSE CLAMP LOOSE, CHECK AND TIGHTEN A LOT OF HOSE CLAMP, TOP OFF SYSTEM, RECHECK LOK OK, CHANGED AIR FILTERS.
2. CHECK OUT IN A/M AFTER ALL NIGHT SITTING LOOK TO BE HEATER CORE LEAKING. PARTS ON ORDER.

Parts	Quantity
VCC/36000006A/C FILTER CAB M2	1

Workorder: V66027

In Date: 04/28/2014 Meter Reading: 161,617.60
 Close Date: 05/05/2014

Problem?
 air dump not working

Task performed:

CHECK OUT AIR DUMP 10-7, NODE CHECK AFTER WORK AT THIS TIME.

Parts	Quantity
NO PARTS USED	

Workorder: V65971

In Date: 04/25/2014 Meter Reading: 161,617.60
 Close Date: 05/07/2014

Problem?
 A inspection

Task performed:

1. A-INSP.
2. A-INSP.
3. ADJUST AIR HORNS.
4. REPAIR AND REMOUNT SHARPIES DRAIN SLIDES
5. REPAIR CITY HORNS.
6. TROUBLESHOOT AIR DUMP INTERMITTENT INOP
7. TROUBLESHOOT AIR DUMP, FOUND BAD CONNECTION ON RELAY.

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V66258

In Date: 05/05/2014

Meter Reading:

Close Date: 05/13/2014

Problem?

TIC mount in old R32 asset# 10156658 needs to be swapped in new R32 asset# 10163704.

Task performed:

1. INSTALLED AND WIRED T.I.C CHARGER.
2. FOUND CAB A/C BLOWER INOP.
3. R&R RADIO.

Parts

Quantity

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V66524

In Date: 05/16/2014

Meter Reading:

Close Date: 06/10/2014

Problem?

Interior bulb burnt out in pt compartment @32

Task performed:

replaced bulb in rear pt, compartment and repaired lenes.

Parts

Quantity

NO PARTS USED

Workorder: V66852

In Date: 05/29/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

outlets in the patient compartment are not working while truck is running. R32

Task performed:

truck has no inverter in it .

Parts

Quantity

NO PARTS USED

Workorder: V66896

In Date: 05/31/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

Need engine oil. R32

Task performed:

dropped off motor oil and filled truck.

Parts

Quantity

15W40QSYN OIL QT

12

6808300174VENT A/C RH

1

ABPN83322930CONTROL HEAD AC/HEAT

1



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V66935

In Date: 06/03/2014
Close Date: 06/23/2014

Meter Reading:

Problem?

R32 oil level is at low level. It has been burning fuel off while running. There is no fuel on the bay floor. We also need oil for the station.

Task performed:

readjusted rear door that were hard to open
ck, for oil leaks and road tested ok.

Parts

Quantity

NO PARTS USED

Workorder: V67219

In Date: 06/15/2014
Close Date: 07/03/2014

Meter Reading:

Problem?

Rescue 32 back-up camera not working.

Task performed:

REPAIRED REAR BACK UP CAMERA.

Parts

Quantity

NO PARTS USED

Workorder: V67461

In Date: 06/25/2014
Close Date: 07/09/2014

Meter Reading:

Problem?

12V chargers in truck not charging triptix when truck is plugged in to shoreline SR@32

Task performed:

Repaired on another ticket

Parts

Quantity

NO PARTS USED

Workorder: V67480

In Date: 06/26/2014
Close Date: 07/09/2014

Meter Reading:

Problem?

12 volt plug to charge triptix (cig lighter attachment) not working. Spare rescue is located at station 32

Task performed:

Repaired 12 volt plug for triptix

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V68116

In Date: 07/23/2014

Meter Reading:

Close Date: 07/23/2014

Problem?

Bolt in left front tire. Tire holding air r32

Task performed:

Parts

Quantity

PULLED SCREW FROM TIRE NO LEAK FOUND

NO PARTS USED

Workorder: V68000

In Date: 07/18/2014

Meter Reading: 167,564.60

Close Date: 07/25/2014

Problem?

air horn inop

Task performed:

Parts

Quantity

REPAIRED AND ADJUSTED AIR HORNS.

NO PARTS USED

Workorder: V68078

In Date: 07/21/2014

Meter Reading:

Close Date: 07/25/2014

Problem?

Stretcher shifts back and fourth when unit is in motion. R32

Task performed:

Parts

Quantity

1. Adjusted stretcher stick mount. (loose).
2. Checked out back-up camera inop. Could not reproduce concern. Camera worked normally every time.
3. Sent to shop for rear leveling valve.
 - . Reduced suspension air bags. (Chafed/ Peeling) also replaced leveling valves and dump valves. (Leaking.)

NO PARTS USED

Workorder: V68247

In Date: 07/29/2014

Meter Reading:

Close Date: 08/01/2014

Problem?

No power to shoreline connection on rescue 32

Task performed:

Parts

Quantity

Circuit breaker was tripped. Reset breaker.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V66941

In Date: 06/03/2014

Meter Reading:

Close Date: 08/18/2014

Problem?

foggy headlight lenses

Task performed:

Parts

Quantity

spare unit know SR-14 WORK IS DONE

NO PARTS USED

Workorder: V68565

In Date: 08/11/2014

Meter Reading: 169,667.10

Close Date: 08/21/2014

Problem?

B inspection spare at R32

Task performed:

Parts

Quantity

b service

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

Vendor?: OCS

Workorder: V66281

In Date: 05/06/2014

Meter Reading:

Close Date: 08/25/2014

Problem?

Dashboard AC not turning on. Pt compartment and aux AC work fine. R32

Task performed:

Parts

Quantity

WORK WAS COMPLETE ON OTHER W/O

NO PARTS USED

Workorder: V68079

In Date: 07/21/2014

Meter Reading:

Close Date: 08/25/2014

Problem?

Back up camera/display not working R32

Task performed:

Parts

Quantity

GETTING NEW TRUCK OUT FOR REFURBED TRUCI

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V68841

In Date: 08/29/2014

Meter Reading: 170,269.90

Close Date: 09/08/2014

Problem?

air dump inop from rear door, check rear brakes

Task performed:

TESTED PUMP VALUE AND CHANGE DOOR SW, AND TESTED OK.
REPAIRED CAB A/C BLOWER THAT WAS SHORTTING OUT.

Parts

NO PARTS USED

Quantity

Workorder: V68039

In Date: 07/19/2014

Meter Reading:

Close Date: 09/11/2014

Problem?

air leaking from rear while truck is off and running R32

Task performed:

GETTING NEW TRUCK OUT FOR REFURBED TRUK.

Parts

16-15762-00016-19471-000 AIR BAG
401148DUMP VLVE AIR SLOAN
S4640024430VALVE LEVELIN

Quantity

2
1
2

Workorder: V69273

In Date: 09/10/2014

Meter Reading:

Close Date: 09/19/2014

Problem?

Connection between rescue vehicle and shore power shorted out. It left a black burn mark at the connection. R32

Task performed:

REPLACED 110V OUTLET AND TESTED UNIT OK.
TRIP TIX INOP REPAIRED CHARGER AND TESTED UNIT.

Parts

NO PARTS USED

Quantity

Workorder: V69479

In Date: 09/18/2014

Meter Reading: 172,330.10

Close Date: 10/10/2014

Problem?

The yellow floor hook needs to be moved in order to have safe removal of stretcher. R32

Task performed:

Installed new floor hook.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V69519

In Date: 09/19/2014

Meter Reading: 172,330.10

Close Date: 10/30/2014

Problem?

Cab a/c inop R32 Add another stretcher hook

Task performed:

Diagnose A/C system. R & R both cab A/C filters.
Repair cab a/c filter access door, leaking air bypassing core.

Parts

Quantity

78R536078R5360M 2PK FILTER AIR COND

1

VCC/36000006A/C FILTER CAB M2

1

Workorder: V69818

In Date: 10/01/2014

Meter Reading: 173,263.60

Close Date: 11/05/2014

Problem?

A inspection

Task performed:

1. "A" inspection
2. Remove and replace R/S fender marker light.
3. Remove and replace top body marker light
4. Remove and replace wiperblades and refill water reservoir
5. Remove and replace patient compartment light-also had to repalce screws and retap 4 holes.
6. Start remove and replace of fan motor on 4 step condensor assembly
7. Finish remove and replace of fan motor o n4s step condensor assy
8. Rear brake job
9. Finish rear brake job
10. Roadtest vehicle after brake job to check operation-OK
11. Remove and replace 4 F headlight and housing assy. had to repair mounting studs that came out during removal of assembly.
12. Remove and replace R/F headlight and housing assembly.
13. Remove and replace number frame on 4s of vehicle-Remove old adhesive from body and frame also old adhesive left on from metal number frame

Parts

Quantity

194-ABULB

1

322502BULB PATIENT GH22

1

91-22WIPER BLADE

2

A06-51039-001A06-75732-005 RH HEAD LIGHT ASSY

1

A06-75732-004HEADLAMP LH M2

1

CLR9185209186-1500-20 MARKER LT.AMBER LED

1

KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT

2

RD571290 01-2616 MOTOR 12V 73R-0542 3512

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V71228

In Date: 11/26/2014
Close Date: 12/01/2014

Meter Reading: 175,270.00

Problem?

flat tire

Task performed:

Found right rear tire flat-removed extension hose
R/R shades core-aired tire and reinstalled hose, check
ok.

Parts

404-100 VALVE CORE

Quantity

8

Workorder: V70954

In Date: 11/15/2014
Close Date: 12/03/2014

Meter Reading:

Problem?

head lights are pointed up and they need to be readjusted r43

Task performed:

Readjusted headlights and tested

Parts

NO PARTS USED

Quantity

Workorder: V71217

In Date: 11/26/2014
Close Date: 12/08/2014

Meter Reading: 175,270.00

Problem?

A inspection SR14

Task performed:

1. A inspection
2. Repair mounting for R/R marker LT, drive out broken screw install new screen.

Parts

NO PARTS USED

Quantity

Workorder: V72156

In Date: 01/09/2015
Close Date: 01/09/2015

Meter Reading:

Problem?

Need couple cases of motor oil. R 16 needs some

Task performed:

delieverd to station

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72055

In Date: 01/05/2015

Meter Reading:

Close Date: 01/15/2015

Problem?

This is R16's spare truck. It has a broken drawer (biohazard) in the patient compartment. The exhaust stack appears to be loose, needs to be looked at.

Task performed:

Travel to 16. Replaced drawer slides and tested OK.

Parts

5632-1010 IN DRAWER SLIDES PR

Quantity

1

Workorder: V72168

In Date: 01/09/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Stretcher mount is not holding stretcher in place. Forward and backward movement allowed as vehicle accelerates/ decelerates. SR14 AT sta 16

Task performed:

Traavel to ST 16. Check out stretcher. Readjust mount. Test - ok.

Parts

NO PARTS USED

Quantity

Workorder: V72206

In Date: 01/11/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Tilt lever for steering wheel is broken, and steering wheel will not adjust. R16

Task performed:

1. Replaced TH lever and springs.

Parts

15W40BSYN OIL BULK QTS

27

RGT-452258FFOOT PEDAL STERRING COLUMN

1

RGT401737ESPRING PEDAL RETURN

1

RGT401741CRETURN SPRING

1

TRANSYNDALLISON TRANS FLUID GAL

7

Workorder: V72255

In Date: 01/12/2015

Meter Reading:

Close Date: 01/20/2015

Problem?

Front tires down to wear bars.

Task performed:

WORK REPAIRS REQUESTED.

Parts

NO PARTS USED

Quantity

Vendor?: BLVD TIRE CENTER



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72382

In Date: 01/16/2015

Meter Reading:

Close Date: 01/21/2015

Problem?

Smoke stack tip fell off the vehicle. Unable to trace where or what time the tip came off the vehicle.

Task performed:

Travel to ST 16. Replaced exhaust stack and lubricated drawer slides.

Parts

Quantity

29206CHROME STACK 24 IN 4 IN

1

357884 IN CLAMP

1

Workorder: V69615

In Date: 09/23/2014

Meter Reading: 172,928.70

Close Date: 01/23/2015

Problem?

a/c in cab not blowing cold air. Was working fine until 30 minutes ago. R32

Task performed:

Traced out problem found diode was bad. Removed and replaced.

Parts

Quantity

DUFDT04-4P-RT03EL35674 DIODE PACK GRAY

2

Workorder: V72497

In Date: 01/21/2015

Meter Reading:

Close Date: 01/26/2015

Problem?

Rear outside tires need replacement , balding.

Task performed:

WORK REPAIRS REQUESTED.

Parts

Quantity

NO PARTS USED

Vendor?: BLVD TIRE CENTER

Workorder: V73635

In Date: 03/04/2015

Meter Reading: 179,872.00

Close Date: 03/26/2015

Problem?

A-inspection

Task performed:

1. A- Inspection.

Parts

Quantity

15W40BSYN OIL BULK QTS

26

906-181-00-86OIL FILTER M2 SPINNER 57140

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V74330

In Date: 03/31/2015

Meter Reading: 183,139.00

Close Date: 04/30/2015

Problem?

stretcher lock inop

Task performed:

Parts

Quantity

1. Check stretcher not looking in at right time. Readjust lock in truck at right time.

NO PARTS USED

Workorder: V74069

In Date: 03/21/2015

Meter Reading:

Close Date: 05/08/2015

Problem?

Air leak getting worse R33

Task performed:

Parts

Quantity

1. Check truck for air leaks. Found hose leak. R&R fitting.

NO PARTS USED

Workorder: V73825

In Date: 03/12/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

Cab A/C not functioning

Task performed:

Parts

Quantity

1. Travel to ST-33. Check out A/C out. Found wiring for blower bad. Tighten pins in connector for now. Will get parts to repair.

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

2. Travel to ST-33. R&R Blower motor and harness. Test unit ok.

VCC/83000038AC WIRE HARNESS

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163704

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V73249

In Date: 02/18/2015

Meter Reading: 179,727.40

Close Date: 05/15/2015

Problem?

C-INSP SR14

Task performed:

1. C-Inspection.
2. SCBA door bumpers damaged. Remove bent screws. Install new bumpers and screws with a corn nuts.
3. Replaced wiper blades.
4. Replace front/aux and rear A/C filters. Clean filter expanded metal protector.
5. Replaced broken left front rocker panel.
6. Left rear strobe broken. Replaced strobe. Removed bent screws and replaced with new splice wiring and heat shrink adjust pattern.
7. Flash light switch bad and won't charge. Swap out flash light.
8. Left squirter not spraying properly. Replace nozzle.
9. Coolant reservoir hose loving on clamp and collapsed. Reposition hose and clamp.
10. Left rear turn lens has condensation. Removed lens. Found lens cracked, dried out fixture and replaced lens.
11. P/S leak, diagnose leak. Found leak at hose clamp for reservoir. Tighten clamp. Degrease reservoir. Top off reservoir. Test for leaks ok.
12. Service dryer. Replaced purge valve.
13. Torque U-bolts.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
0775145PANEL FILTER	1
18-46375-00018-46375-004 TREAD PLATE LH M2	1
18-46375-00118-46375-005 TREAD PLATE RH M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
A18-53531-000LOWER PILLAR PANEL	1
CH27007BUMPER DOOR	2
K022105PURGE VALVE AD-IP-IS	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
TRI-F98999-225NOZZLE KIT	1
VCC/36000006A/C FILTER CAB M2	1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10163704) 2005 - AMERICAN LAFRAN M2 Advanced Life Support Vehicle

10163704

CSHOP-2015-1378

Comments: SPARE RESCUE AT 55 - COOLANT LEAK POSSIBLE WATER PUMP -

Date Opened: 6-25-2015 Date Finished 7-23-2015 Meter 1 Reading: 185,728

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM

Q PARTS

-2	9IP; O-RINGS M2 WATER PUMP
2	9IP; O-RINGS M2 WATER PUMP
1	9IP; GASKET M2 WATER PUMP
2	9IP; SEAL RING M2 WATER PUMP
-2	9IP; SEAL RING M2 WATER PUMP
1	PUMP; RA906200620 WATER PUMP REMAN M2
-1	PUMP; RA906200620 WATER PUMP REMAN M2
1	9IP; ORING WATER PUMP M2
-1	9IP; ORING WATER PUMP M2
-1	GASKET; GASKET SOCKET TO HEAD M2
1	GASKET; GASKET SOCKET TO HEAD M2
-1	PIPE; PIPE SOCKET TO WP
-1	9IP; GASKET/SEAL M2 WATER PUMP
1	PIPE; PIPE SOCKET TO WP
1	9IP; GASKET/SEAL M2 WATER PUMP

CSHOP-2015-1458

Comments: SPARE RESCUE A INSPECTION.

Date Opened: 6-29-2015 Date Finished 7-2-2015 Meter 1 Reading: 185,020

TASKS PERFORMED

A INSPECTION
COOLING SYSTEM

Q PARTS

3	SWITCH; SWITCH COMPARTMENT DOORS
2	LIGHT; HEADLITE KIT WITH SEALER
1	LIGHT; LIGHT LED RED TIR 6

CSHOP-2015-2330

Comments: A INSPECTION SR14

Date Opened: 8-14-2015 Date Finished 8-15-2015 Meter 1 Reading: 186,346

TASKS PERFORMED

A INSPECTION
HVAC SYSTEM

NO PARTS USED

Asset Work Order History 10163704

CSHOP-2015-2607

Comments: REPAIR FLAT

Date Opened: 8-31-2015 Date Finished 8-31-2015 Meter 1 Reading: 186,346

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? CENTRAL AUTO TRIM CO.

CSHOP-2015-28

Comments: A/C FILTERS , TRIM PIECES , A/C HOSE LEAK, DASH RATTLE , DRYER SERVICE, DOOR PANELS

Date Opened: 4-13-2015 Date Finished 4-14-2015 Meter 1 Reading: 183,619

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

CSHOP-2015-3018

Comments: REPLACE RIGHT REAR INSIDE TIRE

Date Opened: 9-21-2015 Date Finished 9-21-2015 Meter 1 Reading: 186,346

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2015-3657

Comments: R91 CHECK POWER STEERING LEAK

Date Opened: 10-29-2015 Date Finished 10-29-2015 Meter 1 Reading: 191,563

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
STEERING

Service Requests:

10/29/2015 ENGINE / 12: BROKEN / REPAIR
POWER STEERING FLUID IS LOW AND THERE IS NO RESERVE FLUID AT STATION 93 TO FILL IT UP WITH

CSHOP-2015-3676

Comments: PATIENT AC INOP SR@ 93

Date Opened: 10-30-2015 Date Finished 11-3-2015 Meter 1 Reading: 192,059

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Asset Work Order History 10163704

CSHOP-2015-3681

Comments: **R93 CAB A/C INOP**

Date Opened: 10-30-2015 Date Finished 11-9-2015 Meter 1 Reading: 193,450

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 HARNESS; JUMPER HARNESS
1 MOTOR; BLOWER MOTOR VCCT1000904A M2
1 HARNESS; JUMPER HARNESS
1 MOTOR; BLOWER MOTOR VCCT1000904A M2
1 9IP; AC WIRE HARNESS
1 FILTER; A/C FILTER CAB M2
1 9IP; AC WIRE HARNESS

Service Requests:

10/30/2015 A/C / 43: WEAK / EXCHANGE - NEW
R93 - A/C IN THE FRONT CAB IS NOT BLOWING AT ALL. A/C LIGHT COMES ON BUT NO A/C.

CSHOP-2015-369

Comments: **REPLACE SWAY BAR BRACKET R39**

Date Opened: 4-30-2015 Date Finished 5-20-2015 Meter 1 Reading: 183,719

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SWAY BAR LINKS
HVAC SYSTEM

1 FREIGHT CHARGE
1 9IP; BAR CLAMP

CSHOP-2015-3829

Comments: **R93 CAB AIR BAG LEAKING**

Date Opened: 11-8-2015 Date Finished 11-12-2015 Meter 1 Reading: 193,500

TASKS PERFORMED

Q PARTS

AIR BAG SYSTEM

2 SPRING; 18-52651-000 AIR SPRING CAB M2

CSHOP-2015-3963

Comments: **R93 REPLACED 4 REAR TIRES**

Date Opened: 11-16-2015 Date Finished 11-16-2015 Meter 1 Reading: 193,560

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

Asset Work Order History 10163704

CSHOP-2015-4086

Comments: **R93 SHORE LINE A/C INOP**

Date Opened: 11-23-2015 Date Finished 12-4-2015 Meter 1 Reading: 195,127

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

11/22/2015 SERVICE REQUEST / 12: BROKEN / REPAIR
SHORELINE IS PLUGGED IN, BUT IT IS NOT OPERATING. WE DID CHECK THE STATION ELECTRICAL PANEL AND THE BREAKER WAS OFF. RESET THE BREAKER, BUT STILL NO RESPONSE FROM THE SHORELINE ON THE TRUCK.

CSHOP-2015-42

Comments: **FINISH REPAIRS FROM P.M. INSTALL SWAY BAR BRACKET ORDERED IN R39**

Date Opened: 4-14-2015 Date Finished 4-29-2015 Meter 1 Reading: 183,619

TASKS PERFORMED

Q PARTS

EXHAUST SYSTEM	1	9IP; TURBO CLAMP M2
COOLING SYSTEM	2	BRACKET; GROUND LT BRACKET
ENGINE AND ACCESSORIES	1	NONSTOCK; STEERING COLUMN
LIGHTING SYSTEM	1	BRAKE; 16-19471-000 AIR BAG
BELT	1	BRAKE; 16-19471-000 AIR BAG
ELECTRICAL	1	ASSEMBLY; ABS ASSBLY
REPAIR FROM PM - HOSES	1	BULB; PLS11W/TUV BULB A/C RESCUES
STABILIZER BAR		
SUSPENSION		
AIR SYSTEM		
DOOR		
FENDER		
BODY EXTERIOR		
INTERIOR TRIM-MOLDINGS-UPHOLS		
DASH PAD		
POWER SEAT MOTOR - CONTROLS		
CAB-INTERIOR ACCESSORIES		
HEATING AND VENTILATION		
HOSES-LINES & FITTINGS		

CSHOP-2015-4508

Comments: **B-INSPECTION**

Date Opened: 12-16-2015 Date Finished 12-17-2015 Meter 1 Reading: 194,194

TASKS PERFORMED

Q PARTS

PM SERVICE B	1	FILTER; FUEL FILTER 33813 L/F # LFF5851
	1	FILTER; OIL FILTER M2 SPINNER 57140
	1	FILTER; OIL FILTER 03 57215 WIX
		MERCEDES/FREIGHTLINER
	1	FILTER; 33634 FUEL FILTER WIX
		MERCEDES/FREIGHTLINE

Asset Work Order History 10163704

CSHOP-2015-4530

Comments: **REPAIRS FROM PM**

Date Opened: 12-17-2015 Date Finished 12-23-2015 Meter 1 Reading: 195,509

TASKS PERFORMED

Q PARTS

COOLING SYSTEM	1	LAMP; LED TURN SIGNAL LAMP
ENGINE AND ACCESSORIES	1	LIGHT; DOME LED ROUND
LIGHTING SYSTEM	2	9IP; 13-3052 NUT
TIRES & WHEELS	1	NODE; 6444-0000-00 VDR RVCAN
SUSPENSION	2	BRAKE; 16-19471-000 AIR BAG
HVAC SYSTEM		

CSHOP-2015-4694

Comments: **R43 NO FRONT CAB A/C**

Date Opened: 12-29-2015 Date Finished 12-30-2015 Meter 1 Reading: 194,270

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

12/29/2015 A/C / 19: LOOSE / REPAIR
THIS TRUCK IS CURRENTLY AT STATION 43. THE CAB FRONT AIR VENTS ARE NOT BLOWING ANY AIR. THE REAR CAB VENTS WORK AND ARE ABLE TO KEEP THE CAB SLIGHTLY COOLED.

CSHOP-2015-4718

Comments: **R43 SHORELINE INOP**

Date Opened: 12-31-2015 Date Finished 1-14-2016 Meter 1 Reading: 195,195

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM
CHARGING SYSTEM
AIR SYSTEM
HVAC SYSTEM

Service Requests:

12/31/2015 SERVICE REQUEST / 17: BREAKER TRIPPED / REPAIR
TRUCK WILL NOT CHARGE WHEN PLUGGED INTO SHORELINE.

12/31/2015 A/C / 17: INSUFFICIENT LUBRICANT / REPAIR
A/C NOT WORKING IN PASSENGER COMPARTMENT WHEN SHORE LINE PLUGGED IN. NOTE: PASSENGER COMPARTMENT A/C IS WORKING WHEN VEHICLE ENGINE IS RUNNING.

01/09/2016 A/C / 18: LEAKING / REPAIR
THE SHORELINE AC WILL NOT BLOW WHEN PLUGGED IN. THE UNIT MAKES NOISES WHEN THE MOTOR CONTROL KNOB IS TURNED BUT NO AIR BLOWS WHEN THE UNIT IS ON.

CSHOP-2015-746

Comments: **SPARE RESCUE BROKE DOWN OVERHEATING**

Date Opened: 5-20-2015 Date Finished 6-2-2015 Meter 1 Reading: 185,019

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Asset Work Order History 10163704

CSHOP-2015-769

Comments: **ENGINE FAN CAME OFF, WATER PUMP FAULTY**

Date Opened: 5-22-2015

Date Finished

6-11-2015

Meter 1 Reading:

185,020

TASKS PERFORMED

Q PARTS

THERMOSTAT
COOLING SYSTEM
SERPENTINE BELT TENSIONER
SERPENTINE BELT

1 GASKET; GASKET SOCKET TO HEAD M2
1 BELT; BELT
1 BELT; BELT ALT. M2
1 PUMP; 9062006301 WATER PUMP SOME M2 CHASSIS
1 PIPE; PIPE SOCKET TO WP
2 9IP; A0052032675 THERMOSTAT ELEMENT M2
1 GASKET; GASKET SOCKET TO HEAD M2
2 9IP; O-RINGS M2 WATER PUMP
1 COMPRESSOR; SCREW AIR COMPRESSOR MTG
1 9IP; GASKET/SEAL M2 WATER PUMP
1 BELT; BELT TENSIONOR MERCEDES
1 PULLY

CSHOP-2016-1061

Date Opened: 3-7-2016

Date Finished

3-10-2016

Meter 1 Reading:

195,450

TASKS PERFORMED

Q PARTS

A INSPECTION
SAFTEY-EMERGENCY EQUIPMENT
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

2 SLIDE; 10 IN DRAWER SLIDES PR
1 NEWPART; HOSE & FITTING
1 PORT; 08-6932BS 90 DEGREE FEMALE W/SERVICE PORT
1 LIGHT; UNIT UV LIGHT A/C RESCUES
1 9IP; 11-3084 THERMOSTAT A/C 1331
1 DRYER; 07-0602A DRIER A/C 7118
1 9IP; 12-2012A EXPANSION VALVE 71R8301

CSHOP-2016-1453

Date Opened: 3-28-2016

Date Finished

3-29-2016

Meter 1 Reading:

195,450

TASKS PERFORMED

NO PARTS USED

WAIT TIME TO BE CHARGED TO WORK ORDER
TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

03/27/2016

A/C / 23: NOT CONNECTED / REPAIR

THIS VEHICLE IS AT STATION 30. BOTH AC CONDENSATION LINES WERE DISCONNECTED IN PATIENT COMPARTMENT.
LINES WERE CONNECTED BUT SHOULD BE CHECKED BY MECHANIC.

CSHOP-2016-2781

Date Opened: 6-10-2016

Date Finished

7-1-2016

Meter 1 Reading:

197,366

TASKS PERFORMED

NO PARTS USED

A INSPECTION

Asset Work Order History 10163704

CSHOP-2016-2794

Comments: **COOLANT LEAK ON SPARE RESCUE FROM 91**

Date Opened: 6-13-2016

Date Finished

8-1-2016

Meter 1 Reading:

197,366

TASKS PERFORMED

Q PARTS

SYSTEM TEST	1	BELT; BELT
COOLING SYSTEM	1	FAN; HT 650 FAN ASY.
OIL FILTER HOUSING	3	BATTERY; BATTERY 950CCA HP-31D
BATTERY	1	NEWPART; PUMP WATER
ALTERNATOR-GENERATOR	1	GASKET; GASKET RVR PWR STRG M2
BRAKES	1	PIPE; PIPE SOCKET TO WP
AIR SYSTEM	1	NEWPART; PIPE SOCKET
HVAC SYSTEM	1	GASKET; GASKET
	2	SEAL; SEAL RING
	1	NEWPART; GASKET
	1	FILTER; 2503221C1 FILTER POWER STEERING
	1	FILTER; AIR FILTER M2
	1	NEWPART; SENSOR
	1	GASKET; GASKET
	1	HOSE; HOSE BREATHER
	2	9IP; O-RINGS M2 WATER PUMP
	1	NEWPART; OIL COOLER
	1	NEWPART; GASKET COOLER
	1	NEWPART; SEAL RING
	1	NEWPART; ROTOR
	1	GASKET; GASKET SOCKET TO HEAD M2
	1	CAP; RAD CAP 20 LB
	1	BELT; BELT ALT. M2
	1	NEWPART; SENSOR
	1	NEWPART; SEAL RING
	1	CAP; CAP-FILL RESERVOIR
	1	MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUNT
	3	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
	2	BRAKE; BRAKE DRUM REAR
	1	9IP; AMH-1 VALVE EXTENSION
	2	BRAKE; KSMA3124710QP REAR BRAKE SHOE KIT
	1	DRYER; DRIER ASSBLY AD-IS 5011074 5011075
	1	NEWPART; HOSE & FITTING
	1	VALVE; A12-19772-355 AMU03 M2 VALVE ASSY
	1	VALVE; 8925 VALVE CORE
	1	A/C; 17-3428 ESTER OIL E7
	1	9IP; VALVE CORE A/C 8926

Asset Work Order History 10163704

CSHOP-2016-2886

Date Opened: 6-16-2016

Date Finished

8-1-2016

Meter 1 Reading:

197,366

TASKS PERFORMED

PM SERVICE C RESCUE

Q

PARTS

1 FILTER; PANEL FILTER
1 FILTER; FUEL FILTER 33813 L/F # LFF5851
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; A/C FILTER CAB M2
22 FLUID; SYN OIL BULK QTS
2 WIPER; WIPER BLADE
1 BRAKE; CARTRIDGE DC100
1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER
1 FILTER; 78R5360M 2PK FILTER AIR COND
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE

CSHOP-2016-3654

Date Opened: 8-1-2016

Date Finished

8-1-2016

Meter 1 Reading:

197,366

TASKS PERFORMED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

NO PARTS USED

CSHOP-2016-3918

Comments: **QC SPARE RESCUE**

Date Opened: 8-9-2016

Date Finished

8-22-2016

Meter 1 Reading:

198,008

TASKS PERFORMED

A INSPECTION

NO PARTS USED

CSHOP-2016-4355

Comments: **QUALITY CHECK**

Date Opened: 9-6-2016

Date Finished

9-7-2016

Meter 1 Reading:

198,453

TASKS PERFORMED

AIR SYSTEM
EVAPORATOR-EVAPORATOR MOTOR
QUALITY CHECK-REPAIRS
HVAC SYSTEM

Q

PARTS

2 VALVE; DUMP VLVE AIR SLOAN
1 MOTOR; BLOWER MOTOR VCCT1000904A M2
1 HARNESS; JUMPER HARNESS
1 9IP; AC WIRE HARNESS
1 A/C; HVAC UNIT ROOF MOUNTED

Asset Work Order History 10163704

CSHOP-2016-4527

Comments: **QUALITY CHECK**

Date Opened: 9-17-2016 Date Finished 9-19-2016 Meter 1 Reading: 198,829

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT
BODY EXTERIOR
DOOR LOCKS
QUALITY CHECK-REPAIRS

1 LIGHT; LIGHT LED RED TIR 6
1 LATCH; 11656-16 LATCH R/H MEDIC MASTER
1 LATCH; 11657-16 LATCH L/H MEDIC MASTER

CSHOP-2016-5095

Comments: **A INSPECTION**

Date Opened: 10-25-2016 Date Finished 10-25-2016 Meter 1 Reading: 199,048

TASKS PERFORMED

NO PARTS USED

A INSPECTION

CSHOP-2016-5260

Date Opened: 11-8-2016 Date Finished 11-8-2016 Meter 1 Reading: 199,085

TASKS PERFORMED

Q PARTS

SUSPENSION

1 VALVE; DUMP VLVE AIR SLOAN

CSHOP-2016-6072

Date Opened: 12-28-2016 Date Finished 12-28-2016 Meter 1 Reading: 201,082

TASKS PERFORMED

NO PARTS USED

TIRES & WHEELS

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-1657

Date Opened: 3-17-2017 Date Finished 3-22-2017 Meter 1 Reading: 204,182

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; OIL FILTER M2 SPINNER 57140
1 FIL; NAPAGOLD OIL FILTER
3 9IP; 15W40 MOTOR OIL NON SYN
1 9IP; 33634 FUEL FILTER WIX MERCEDES/FR
2 MAC; NON-CHLOR BRAKE CLNR
1 FILTER; FUEL FILTER 33813 L/F # LFF5851

Asset Work Order History 10163704

CSHOP-2017-1658

Comments: **REPAIRS FROM PM**

Date Opened: 3-17-2017 Date Finished 3-24-2017 Meter 1 Reading: 204,182

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
WIPER BLADES
WIPERS-WASHER
ALTERNATOR-GENERATOR
REPAIR FROM PM - REAR SUSPENSION
BACK UP CAMERA-MONITOR
HVAC SYSTEM

2 1AN; WIPERS
2 2DD; REAR AIR BAG
1 SVP; CNDSRFAN

CSHOP-2017-2005

Comments: **STRETCHER MOUNT LOOSE**

Date Opened: 4-5-2017 Date Finished 4-7-2017 Meter 1 Reading: 204,182

TASKS PERFORMED

NO PARTS USED

STRETCHER

CSHOP-2017-2416

Comments: **A INSPECTION**

Date Opened: 4-24-2017 Date Finished 4-26-2017 Meter 1 Reading: 204,441

TASKS PERFORMED

Q PARTS

A INSPECTION
HVAC SYSTEM

3 9XX; 134A 10194654
1 9AP; 9AP
2 9IP; VALVE CORE

CSHOP-2017-3126

Date Opened: 5-29-2017 Date Finished 5-30-2017 Meter 1 Reading: 204,815

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

3 9XX; 134A 10194654
1 9IP; FAN A/C COND 12IN 860026-2-W

CSHOP-2017-3361

Date Opened: 6-7-2017 Date Finished 6-14-2017 Meter 1 Reading: 205,673

TASKS PERFORMED

NO PARTS USED

INSTRUMENTS-GAUGES-METERS

Service Requests:

06/07/2017 OIL / 18: LEAKING / REPAIR
LOW ENGINE OIL

Asset Work Order History 10163704

CSHOP-2017-3450

Date Opened: 6-12-2017 Date Finished 6-14-2017 Meter 1 Reading: 205,673

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

Service Requests:

06/10/2017 OIL / 18: LEAKING / REPAIR
LOW ENGINE OIL. ENGINE OIL READING AT MINIMUM.

CSHOP-2017-378

Comments: **R68 MAKING LOUD NOISE UNDER HOOD**

Date Opened: 1-18-2017 Date Finished 1-20-2017 Meter 1 Reading: 202,035

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DRIVE BELT

CSHOP-2017-4010

Comments: **SPARE RESCUE AT STATION 39 COOLANT LEAK**

Date Opened: 7-7-2017 Date Finished 7-27-2017 Meter 1 Reading: 207,276

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
EXHAUST SYSTEM
COOLING SYSTEM
ENGINE AND ACCESSORIES
SHORELINE CHARGER
AIR SYSTEM
HVAC SYSTEM

1	2DD; GASKET
2	2DD; HOSE
1	2DD; TRANSFER TUBE
1	2DD; WATER PUMP
1	2DD; GASKET
1	9IP; GASKET
2	2DD; ORING
1	9IP; ORING WATER PUMP M2
1	2DD; GASKET
1	2DD; O-RING
2	2DD; THERMOSTAT
7	FLUID; COOLANT ANTIFREEZE GAL
-14	9OC; COOLANT
7	9OC; COOLANT
7	9OC; COOLANT
1	9IP; GASKET
1	NCB; PURPLE POWER 40 OZ
7	9IP; GROMET VALVE COVER
1	9IP; GASKET VALVE COVER
1	BK; AUTOMOTIVE GOOP
1	6KU; COVER, ROUND, YELLOW
1	TWD; GOVERNOR
4	9XX; 134A 10194654
1	9HY; HOSE MADE

Service Requests:

07/07/2017 ENGINE / 18: LEAKING / REPAIR
COOLANT LEAK UNDER RESERVE RESCUE

Asset Work Order History 10163704

CSHOP-2017-4405

Date Opened: 7-31-2017 Date Finished 8-3-2017 Meter 1 Reading: 207,641

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - WHEEL SEALS

4 9IP; 13-3052 NUT
1 NCB; DEGREASER MULTI PURP
1 NCB; DEGREASER MULTI PURP
1 GASKET; GASKET AXLE FL80 R002435

Service Requests:

07/31/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
CONTINUOUSLY LEAKING OIL.

CSHOP-2017-487

Comments: **A INSPECTION**

Date Opened: 1-23-2017 Date Finished 2-3-2017 Meter 1 Reading: 203,014

TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH
HVAC SYSTEM

2 9IP; 10 IN DRAWER SLIDES PR
3 9XX; 134A 10194654
1 BULB; PLS11W/TUV BULB A/C RESCUES
1 9AP; AC FLUSH
1 BELT; BELT
1 9IP; 9IP
1 9IP; 12-2012A EXPANSION VALVE 71R8301
1 COMPRESSOR; COMPRESSOR A/C

CSHOP-2017-5064

Comments: **PATIENT A/C INOP**

Date Opened: 8-28-2017 Date Finished 8-29-2017 Meter 1 Reading: 208,279

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

2 9IP; FAN A/C COND 12IN 860026-2-W
2 9XX; AC FREON 10174676

CSHOP-2017-5156

Comments: **NEEDS TO BE TENTED BUG PROBLEM**

Date Opened: 9-1-2017 Date Finished 9-14-2017 Meter 1 Reading: 208,486

TASKS PERFORMED

NO PARTS USED

PRE TRIP INSPECTION

Service Requests:

08/31/2017 HAZARD / 39: SOILED/STAINED / INSPECT
ROACH INFESTATION IN BOTH PASSENGER AND PATIENT COMPARTMENTS

Asset Work Order History 10163704

CSHOP-2017-5605

Date Opened: 9-26-2017 Date Finished 9-29-2017 Meter 1 Reading: 208,486

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

1 9IP; 16-3408 A/C FITTING LOW SIDE
1 9IP; 1513 SW PRES.A/C
1 9HY; AC HOSE
1 9IP; 16-3409 A/C FITTING HIGH SIDE

CSHOP-2017-5730

Date Opened: 10-3-2017 Date Finished 10-3-2017 Meter 1 Reading: 208,697

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 GRO; CLR MKR LAMP

CSHOP-2017-6315

Comments: **UNIT BROKE DOWN**

Date Opened: 11-1-2017 Date Finished 11-3-2017 Meter 1 Reading: 210,257

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2017-6425

Comments: **REPAIRS FROM PM**

Date Opened: 11-7-2017 Date Finished 11-29-2017 Meter 1 Reading: 210,326

TASKS PERFORMED

Q PARTS

GROUND LIGHT BODY
WIPERS-WASHER
INSTRUMENT PANEL LIGHTS
DOME LIGHTS
HVAC SYSTEM

1 9IP; GROUND LT BRACKET
1 LIT; GROMMET
2 9IP; 4 IN ROUND LED
1 9IP; MAP LIGHT LED 18 IN
1 9IP; BULB PATIENT GH22
1 9IP; LIGHT BULB
1 DRYER; 07-0614A AC DRIER M2
1 8GR; FILTER
1 SVP; COMPRSOR
2 1AN; 22" WIPER BLADE

Asset Work Order History 10163704

CSHOP-2017-6429

Date Opened: 11-7-2017 Date Finished 11-13-2017 Meter 1 Reading: 210,324

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

26 FLUID; SYN OIL BULK QTS
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA GOLD OIL FILTER
-26 9OC; SYN 15W40
26 9OC; SYN 15W40
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2017-7217

Comments: **SPARE RESCUE AT STATION 47**

Date Opened: 12-18-2017 Date Finished 12-18-2017 Meter 1 Reading: 211,161

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

12/18/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE CAB AC IS INOPERABLE. BLOWS HOT AIR BOTH CAB AND AUX. AC UNITS

CSHOP-2017-7257

Comments: **C/E LIGHT**

Date Opened: 12-19-2017 Date Finished 1-22-2018 Meter 1 Reading: 212,403

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
MAP SENSOR

1 9IP; SENSOR PRESSURE

Service Requests:

12/18/2017 HAZARD / 15: FOREIGN MATERIAL / CLEANED OLD FOOD AND WRAPPERS FROM CAB FOUND NC
TRUCK CAB FOUND TO BE INFESTED BY ROACHES.

CSHOP-2017-7258

Comments: **SPARE RESCUE AT 47**

Date Opened: 12-20-2017 Date Finished 12-28-2017 Meter 1 Reading: 212,039

TASKS PERFORMED

Q PARTS

AIR SYSTEM
BODY EXTERIOR
HVAC SYSTEM

2 8GR; FABULOSO CLEANER

Service Requests:

12/19/2017 A/C / 18: LEAKING / REPAIR
A/C ISSUE, CAB AC DOESNT WORK WELL. NOT COLD AND BARELY ANY PRESSURE.

Asset Work Order History 10163704

CSHOP-2017-765

Date Opened: 2-6-2017 Date Finished 2-9-2017 Meter 1 Reading: 203,745

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2017-773

Date Opened: 2-6-2017 Date Finished 2-6-2017 Meter 1 Reading: 203,366

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

02/06/2017 A/C / 18: LEAKING / ADJUST

CSHOP-2017-879

Date Opened: 2-12-2017 Date Finished 2-14-2017 Meter 1 Reading: 204,149

PATIENTS AC INOP.

TASKS PERFORMED

NO PARTS USED

HOSES-LINES & FITTINGS

Service Requests:

02/12/2017 A/C / 18: LEAKING / REPAIR

CSHOP-2018-1563

Comments: **WHITE SMOKE**

Date Opened: 3-16-2018 Date Finished 5-16-2018 Meter 1 Reading: 213,580

TASKS PERFORMED

Q PARTS

PUMP ENGINE BELTS	1	TWD; GOVERNOR
ENGINE COOLANT TEMPERATURE SE	1	2FL; EGR COOLER
BATTERY	1	2FL; GASKET
TIRES & WHEELS	1	2FL; GASKET
REPAIR FROM PM - AIR COMPRESSOR	1	2FL; AIR COMPRESSOR
	2	2FL; HOSE
	1	2FL; GASKET
	1	9HY; FITTING
	1	9HY; FITTING

CSHOP-2018-2

Date Opened: 1-1-2018 Date Finished 1-1-2018 Meter 1 Reading: 212,403

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Asset Work Order History 10163704

CSHOP-2018-2584

Comments: **SPARE RESCUE AT ST51**

Date Opened: 5-11-2018 Date Finished 5-17-2018 Meter 1 Reading: 213,580

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

1 9IP; 10 IN DRAWER SLIDES PR

Service Requests:

05/10/2018 A/C / 18: LEAKING / REPAIR
A/C ISSUE- FRONT CAD AC BLOW AIR BUT NOT COLD. LEAKING WATTER AT LT FEET

CSHOP-2018-2827

Comments: **R51 HIT ROOF A/C AT WEST BOCA**

Date Opened: 5-21-2018 Date Finished 5-22-2018 Meter 1 Reading: 213,580

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2018-2962

Comments: **R51**

Date Opened: 5-29-2018 Date Finished 5-30-2018 Meter 1 Reading: 214,215

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

05/29/2018 A/C / 18: LEAKING / OVERHAUL
A/C FRONT DASH BLOWING HOT. WAS CHARGED HAS A LEAK IN THE HOSE

CSHOP-2018-4193

Date Opened: 7-26-2018 Date Finished 8-1-2018 Meter 1 Reading: 214,338

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
2 1AN; WIPERS
28 4PC; 15W40 PREMIUM BLUE OIL

Asset Work Order History 10163704

CSHOP-2018-4194

Comments: **REPAIRS FOR PM ROOF A/C COVER TWEAKED REAR OF UNIT LEANS TO ONE SIDE**

Date Opened: 7-26-2018 Date Finished 8-16-2018 Meter 1 Reading: 214,338

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - PATIENT COMPT LIGHTING SYSTEM	1	9PB; 316 POLY DOOR
CHARGING SYSTEM	1	MMM; MARINE ADH FAST CURE
BACK UP CAMERA-MONITOR	1	9AP; LIGHT
HVAC SYSTEM	1	LIT; GROMMET
	3	9AP; BRAKE CLEAN

CSHOP-2018-5326

Comments: **SPARE RESCUE AT 32**

Date Opened: 9-18-2018 Date Finished 10-12-2018 Meter 1 Reading: 215,479

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER	2	1AN; 22" WIPER BLADE
WIPER BLADES	2	2FL; AIR BAGS
SUSPENSION	2	9IP; 1852651000 AIR SPRING CAB M2
CAB & BODY MOUNT	1	2FL; VALVE
HVAC SYSTEM	3	9OC; 30 LB FROM CARLOS

Service Requests:

09/18/2018 A/C / 18: LEAKING / REPAIR
AC IN BACK UP RESCUE NOT WORKING PROPERLY.

CSHOP-2018-6012

Date Opened: 10-22-2018 Date Finished 10-30-2018 Meter 1 Reading: 215,866

NEED A SLIDE ON SHARPS BOX

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	9IP; BULB PATIENT GH22
DOMELIGHTS	1	5AH; 1125 DRAWER SLIDE PR
CAB-INTERIOR ACCESSORIES		

Service Requests:

10/22/2018 SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW
THE MEDICAL WASTE DRAWER ON THE INTERIOR FELL OUT AND IS BROKE .

CSHOP-2018-6455

Date Opened: 11-13-2018 Date Finished 11-14-2018 Meter 1 Reading: 215,866

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	4	1AD; BATTERY 31 SERIES
CRANKING SYSTEM	2	1WL; LIGHT, 900 SERIES RED W/CLR LENS
SHORELINE CHARGER	1	FIL; NAPA CABIN AIR FILTER
STROBE LIGHTS		
HVAC SYSTEM		

Asset Work Order History 10163704

CSHOP-2018-7378

Comments: **PRE-TRIP**

Date Opened: 12-28-2018 Date Finished 12-31-2018 Meter 1 Reading: 216,435

TASKS PERFORMED

NO PARTS USED

SIDE COMPARTMENT BODY
PRE TRIP INSPECTION

CSHOP-2018-832

Comments: **CAB A/C INOP**

Date Opened: 2-8-2018 Date Finished 2-13-2018 Meter 1 Reading: 212,426

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
HVAC SYSTEM

3 9XX; AC FREON 10174676
1 FIL; NAPA CABIN AIR FILTER

CSHOP-2019-1377

Date Opened: 3-13-2019 Date Finished 4-2-2019 Meter 1 Reading: 218,308

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
QUALITY CHECK-REPAIRS
PRE TRIP INSPECTION
AIR SYSTEM
DOOR

CSHOP-2019-1902

Comments: **SPARE RESCUE AT 28**

Date Opened: 4-12-2019 Date Finished 4-12-2019 Meter 1 Reading: 218,385

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

04/12/2019 OIL / 18: LEAKING / INSPECT
ENGINE OIL IS LEAKING AT A PRETTY SOLID RATE. RESCUE IS LOCATED AT STATION 28 CURRENTLY.

CSHOP-2019-2045

Date Opened: 4-18-2019 Date Finished 5-1-2019 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - DECALS/CLEANLINESS

1 9AP; DETAIL

Asset Work Order History 10163704

CSHOP-2019-2282

Date Opened: 4-30-2019

Date Finished

5-10-2019

Meter 1 Reading:

218,473

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPAGOLD FUEL FILTER
26 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER

CSHOP-2019-2347

Date Opened: 5-3-2019

Date Finished

5-28-2019

Meter 1 Reading:

218,473

TASKS PERFORMED

Q PARTS

DOOR LATCH

1 9IP; LATCH TRIGGER W/LOCK

WIPERS-WASHER

2 1AN; 22" WIPER BLADE

COOLING SYSTEM

7 2FL; INSERT

VALVE COVER-GASKETS

1 2DD; GASKET

ENGINE AND ACCESSORIES

1 2FL; SPINNER FILTER O RING

LIGHTING SYSTEM

1 2FL; SEAL

FUSE

1 2FL; GASKET

UNIVERSAL JOINT

1 BK; HELICOIL

ALIGNMENT

7 2FL; COLLAR

U-BOLTS

1 2DD; SEALRING

POWER STEERING PUMP

1 FIL; NAPA GOLD OIL FILTER

AIR DRIER

1 2FL; GASKET

AIR SYSTEM

1 FIL; NAPAGOLD AIR FILTER

AIR HORN

1 FIL; POWER STEERING FILTER

BODY EXTERIOR

1 2FL; GASKET

CABIN AIR FILTER

1 FIL; NAPAGOLD AIR FILTER

A/C CONDENSER FAN

1 TWD; PURGE VALVE ASSY KIT

A/C FILTER

1 TWD; PURGEVALVEKIT

HVAC SYSTEM

-1 TWD; PURGEVALVEKIT

2 TWD; RPR KIT

2 NS; SHOCK

1 FIL; NAPA CABIN AIR FILTER

1 8GR; FILTER

-1 SVP; COMPRSOR

1 SVP; COMPRSOR

1 9HY; FIRESLEEVEAMPACFITINGS

1 TEM; NEW COMPRESSOR

CSHOP-2019-2439

Date Opened: 5-9-2019

Date Finished

5-9-2019

Meter 1 Reading:

218,385

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10163704

CSHOP-2019-319

Comments: **SPARE RESCUE AT ST55**

Date Opened: 1-17-2019 Date Finished 1-28-2019 Meter 1 Reading: 216,987

TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

01/17/2019 OIL / 18: LEAKING / REPAIR
LOW ENGINE OIL VEHICLE IS SPARE AT STATION 55. OIL IS NOT LOW BUT VEHICLE HAS OIL LEAK. FOUND OIL ON FLOOR THIS MORNING. CHECKED OIL LEVEL AND STILL FULL AT THE MOMENT.

CSHOP-2019-3900

Date Opened: 7-26-2019 Date Finished 8-21-2019 Meter 1 Reading: 220,705

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	8GR; GRIPTAPE2
CHARGING SYSTEM	1	2TK; UNIV INSIDE
SAFTEY-EMERGENCY EQUIPMENT	1	2TK; BRISK 2
HVAC SYSTEM		

CSHOP-2019-4170

Date Opened: 8-8-2019 Date Finished 8-19-2019 Meter 1 Reading: 220,705

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	1	2FL; COVERSTEERINGCOLUMNLOWER
REAR DOOR	3	9ME; ZICORATCHETSTRAPS
REPAIR FROM PM - O2 SYSTEM	1	2FL; BRACKET
TURN SIGNAL LIGHTS	1	2FL; SWITCHSIGNAL
ELECTRICAL	2	2FL; COVERSCREWSM2
REPAIR FROM PM - DECALS/CLEANLINESS	1	2FL; COVERSTEERINGCOLUMNUPPER
INSTRUMENTS-GAUGES-METERS	1	2FL; COVER
	2	2FL; SCREW
	1	9IP; KEYPAD7POSITION

CSHOP-2019-4584

Comments: **SPARE RESCUE AT ST32**

Date Opened: 8-27-2019 Date Finished 8-28-2019 Meter 1 Reading: 220,802

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
BODY EXTERIOR

Service Requests:

08/27/2019 DOOR / 18: LEAKING / REPAIR
VEHICLE DOORS REAR PATIENT COMPARTMENT OFFICER SIDE GETS STUCK AND MAKES ITS HAD TO OPEN. MAY BECOME A SAFETY ISSUE IF NEEDED TO GET OUT QUICKLY OR CAUSE DELAY IN PATIENT CARE.

Asset Work Order History 10163704

CSHOP-2019-4692

Date Opened: 9-4-2019 Date Finished 9-5-2019 Meter 1 Reading: 221,000

TASKS PERFORMED

Q PARTS

BODY EXTERIOR

1 1WL; LED LIGHTHEADS HORIZONTAL 3 SERIES

CSHOP-2019-4776

Date Opened: 9-9-2019 Date Finished 10-8-2019 Meter 1 Reading: 221,692

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 TWD; AIRDRYR

CSHOP-2019-4795

Date Opened: 9-10-2019 Date Finished 10-16-2019 Meter 1 Reading: 221,834

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 1AN; 22 WIPER BLADE

WIPERS-WASHER

1 2FL; LIGHT CLEARANCE LT ROOF M2

LIGHTING SYSTEM

1 2BE; VALVE PARK CONTROL

AIR SYSTEM

2 1GM; LEVEL VALVE FRTLINER

AIR HORN

2 9AP; HORN KIT PAI 3390 1094

CSHOP-2019-5136

Date Opened: 9-30-2019 Date Finished 1-10-2020 Meter 1 Reading: 224,090

TASKS PERFORMED

Q PARTS

STRETCHER

1 5SP; BAR RAIL LOCK

Service Requests:

09/29/2019 SERVICE REQUEST / 12: BROKEN / REPAIR
STRETCHER IS HAVING A CONSTANT DRAW ON THE BATTERY, POWER INDICATOR LIGHT ON THE FRONT IS STAYING
ACTIVATED IN STORED POSITION AND WILL NOT GO OFF WHILE BATTERY IS INSERTED

CSHOP-2019-5309

Date Opened: 10-8-2019 Date Finished 11-1-2019 Meter 1 Reading: 221,834

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

1 LMP; BOXEDMINIATURES

GROUND LIGHT BODY

1 1WL; SIREN AMPLIFIER

DOMELIGHTS

LICENSE PLATE LIGHTS

VENDOR TIRE REPAIR/CHANGE

SIREN

DOOR HANDLES INSIDE-OUTSIDE

Asset Work Order History 10163704

CSHOP-2019-6277

Date Opened: 12-3-2019 Date Finished 12-10-2019 Meter 1 Reading: 223,438

TASKS PERFORMED

Q PARTS

PM SERVICE B

2 FIL; FIL
2 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPA GOLD OIL FILTER
25 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; FIL
2 1AN; WIPERS

CSHOP-2019-6288

Date Opened: 12-4-2019 Date Finished 12-11-2019 Meter 1 Reading: 223,438

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS

AIR SYSTEM

AIR HORN

DOOR LOCKS

HVAC SYSTEM

1 2AD; AIR VALVE
2 9AP; HORN KIT PAI 3390 1094
1 2FL; DOOR HANDLE M2
2 TEM; BLOW/MOT
1 9IP; BLACK DIODE PLUG DT04 49 RT01
3 9XX; AC FREON 10199801

CSHOP-2019-6458

Date Opened: 12-13-2019 Date Finished 12-13-2019 Meter 1 Reading: 223,438

TASKS PERFORMED

NO PARTS USED

VENDOR TIRE REPAIR/CHANGE

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2020-1218

Date Opened: 3-2-2020 Date Finished 3-10-2020 Meter 1 Reading: 226,503

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

HVAC SYSTEM

Service Requests:

03/02/2020 A/C / 12: BROKEN / REPAIR
A/C ISSUE, CAB JUST BLOWS AIR, PATIENT COMPARTMENT STILL OPERATIONAL AS NORMAL.

CSHOP-2020-1556

Date Opened: 3-17-2020 Date Finished 3-18-2020 Meter 1 Reading: 226,503

TASKS PERFORMED

Q PARTS

WIRING

FUSE

HVAC SYSTEM

1 BK; HI AMP FLUSH MOUNT
1 9HD; DIODE PACK CONNECTOR

Asset Work Order History 10163704

CSHOP-2020-1672

Comments: **SPARE AT RESCUE 29**

Date Opened: 3-24-2020

Date Finished

4-13-2020

Meter 1 Reading:

226,772

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL
HOSES-LINES & FITTINGS
HVAC SYSTEM

1 BK; LEAK DETECT DYE AC
1 TEM; PAG 100 OIL
1 SVP; SVP
1 9HD; DIODE PACK CONNECTOR
1 TEM; NEW COMPRESSOR

Service Requests:

03/24/2020

A/C / 12: BROKEN / EXCHANGE - NEW
A/C ISSUE

CSHOP-2020-1693

Date Opened: 3-25-2020

Date Finished

3-26-2020

Meter 1 Reading:

226,772

TASKS PERFORMED

NO PARTS USED

SAFTEY-EMERGENCY EQUIPMENT

CSHOP-2020-2240

Comments: **QC**

Date Opened: 4-27-2020

Date Finished

5-2-2020

Meter 1 Reading:

0

TASKS PERFORMED

Q PARTS

A INSPECTION
WIPERS-WASHER
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
DASH PAD
SEAT FRONT

2 1AN; 22 WIPER BLADE
1 1WL; 2 LED FLASHER RED RED LENS
1 BK; HALOGEN BULB
1 2FL; COVER DASH PANEL TOP

CSHOP-2020-3561

Date Opened: 7-8-2020

Date Finished

7-9-2020

Meter 1 Reading:

226,975

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS
STORAGE CABINET EMERGENCY VEH
ROTATE TIRES
SAFTEY-EMERGENCY EQUIPMENT
A/C FILTER
HVAC SYSTEM

2 5AH; 11 25 DRAWER SLIDE PR
1 9HD; FILTER CABIN 7 75X14 5
3 9XX; AC FREON 10174676
1 FIL; NAPA CABIN AIR FILTER

CSHOP-2020-5408

Date Opened: 10-14-2020

Date Finished

12-8-2020

Meter 1 Reading:

228,228

TASKS PERFORMED

NO PARTS USED

ELECTRICAL

Asset Work Order History 10163704

CSHOP-2020-5490

Date Opened: 10-17-2020 Date Finished 11-6-2020 Meter 1 Reading: 228,228

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

26 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 9AP; OIL SAMPLE TEST KIT PETRO CANADA

CSHOP-2020-5877

Date Opened: 11-6-2020 Date Finished 11-12-2020 Meter 1 Reading: 228,228

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
CRANKING SYSTEM
DIAGNOSE ELECTRICAL
STEERING
BRAKES
AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT
BODY EXTERIOR
HVAC SYSTEM

2 1AN; 22 WIPER BLADE
4 1AD; 1000 CCA 31 SERIES BATTERY
1 FIL; POWER STEERING FILTER
2 TWD; TRUCK AIR SLEEVE
1 8AM; TUVPLS 11W UV BULB 9
3 9XX; 134A 10194654

CSHOP-2020-622

Date Opened: 2-5-2020 Date Finished 2-13-2020 Meter 1 Reading: 225,308

TASKS PERFORMED

Q PARTS

HVAC SYSTEM

3 9XX; 134A 10194654

Service Requests:

02/04/2020 A/C / 18: LEAKING / A/C LINE REPAIR
A/C ISSUE - FRONT AND REAR CAB A/C DOES NOT BLOW COLD. RESCUE WAS BACKUP FOR R15, SWAPPED OUT OF
ON 2/4/20.

Asset Work Order History 10163704

CSHOP-2020-6465

Date Opened: 12-10-2020 Date Finished 12-26-2020 Meter 1 Reading: 228,237

TASKS PERFORMED

EGR COOLER
STARTER
DIAGNOSE ELECTRICAL
HVAC SYSTEM

Q PARTS

1 2DD; CORE DEPOSIT
1 2FL; 2FL
1 2DD; EGR VALVE
1 2DD; 2DD
1 2FL; 2FL
1 2FL; 2FL
1 2FL; 2FL
1 2FL; 2FL
1 NW; BATT CABLE CONNECTOR
1 1AD; STARTER 12V 11T 38MT
-2 9IP; 18 2108 FIVE BLADE FAN 3382
2 9IP; 18 2108 FIVE BLADE FAN 3382
2 TEM; BLOW/MOT
1 9HY; HOSE CUSTOM MAKO

CSHOP-2020-6769

Date Opened: 12-28-2020 Date Finished 1-12-2021 Meter 1 Reading: 228,272

TASKS PERFORMED

ELECTRICAL
BRAKES

Q PARTS

2 BRAKE; M2 FRONT BRAKE LINES
2 TWD; BRK DRUM
2 2IH; 4703 MERITOR
2 2FL; BRAKE CHAMBER FRONT TYPE 20
2 9LO; FRONT BRAKE LINES
-2 9LO; FRONT BRAKE LINES

CSHOP-2021-1639

Date Opened: 3-28-2021 Date Finished 3-29-2021 Meter 1 Reading: 229,649

TASKS PERFORMED

BELT

NO PARTS USED

Asset Work Order History 10163704

CSHOP-2021-1840

Date Opened: 4-7-2021

Date Finished

4-16-2021

Meter 1 Reading:

230,249

TASKS PERFORMED

Q PARTS

DOOR PROP CYLINDER
HVAC SYSTEM

1 9IP; DC23 5011 50 HOLD OPEN RESCUE
1 TEM; STEEL FILTER DRIER
-1 9IP; 07 0614A AC DRIER M2
1 9IP; 07 0614A AC DRIER M2
1 TEM; EXPANSION VALVE
1 NBH; V BELT
1 TEM; TEM
1 SVP; COMPRSOR
1 NBH; FLEETRANNER BELT

Service Requests:

03/27/2021 DOOR / 12: BROKEN / EXCHANGE - NEW
VEHICLE DOORS: HINGE IS BROKEN ON THE OFFICER SIDE PATIENT COMPARTMENT DOOR.

CSHOP-2021-2023

Date Opened: 4-16-2021

Date Finished

4-16-2021

Meter 1 Reading:

230,249

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

1 9ES; LIGHT BAR 20 RIGID FLD SPT

Service Requests:

04/15/2021 HAZARD / 43: WEAK / EXCHANGE - NEW
FRONT HEADLIGHTS DO NOT ILLUMINATE TO SEE WHILE DRIVING AT NIGHT ON LOXAHATCHEE ROADS.

CSHOP-2021-2053

Date Opened: 4-16-2021

Date Finished

6-8-2021

Meter 1 Reading:

233,580

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
INSTRUMENTS-GAUGES-METERS

CSHOP-2021-2414

Comments: **SPARE RESCUE AT 22**

Date Opened: 5-3-2021

Date Finished

5-13-2021

Meter 1 Reading:

231,950

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SWITCH

1 TWD; SWROT2POSLEVER2STUDS

Service Requests:

05/01/2021 SERVICE REQUEST / 38: SHORTED / EXCHANGE - NEW
BATTERY SWITCH HAS A SHORT IN IT CAUSING THE BATTERY TO STAY ON AFTER THE BATTERY SWITCH HAS BEEN
MOVED TO THE OFF POSITION.

Asset Work Order History 10163704

CSHOP-2021-2986

Date Opened: 5-31-2021 Date Finished 6-4-2021 Meter 1 Reading: 233,207

TASKS PERFORMED

NO PARTS USED

DOOR HANDLES INSIDE-OUTSIDE

CSHOP-2021-3050

Date Opened: 6-2-2021 Date Finished 6-2-2021 Meter 1 Reading: 233,172

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
REAR DOOR LATCH ASSEMBLY

CSHOP-2021-3097

Date Opened: 6-6-2021 Date Finished 6-11-2021 Meter 1 Reading: 233,751

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2021-3353

Comments: **NEEDS REAR BRAKES REPLACED 20% NEEDS REAR TIRES REPLACED 6/32 PAT A/C CONDENSER MT BRKT
BROKEN-TEMP REPAIR**

Date Opened: 6-18-2021 Date Finished 6-30-2021 Meter 1 Reading: 235,100

TASKS PERFORMED

NO PARTS USED

INSPECTION

CSHOP-2021-3354

Date Opened: 6-18-2021 Date Finished 8-10-2021 Meter 1 Reading: 0

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 1AN; 22 WIPER BLADE

CSHOP-2021-855

Date Opened: 2-12-2021 Date Finished 2-18-2021 Meter 1 Reading: 228,272

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Asset Work Order History 10163704

RADIO-2018-579

Comments: **REMOVAL OF 10157650, INSTALL OF 10204834 INTO SR9 - 10163704**

Date Opened: 6-1-2018

Date Finished

6-1-2018

Meter 1 Reading:

0

TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

Service Requests:

06/01/2018

RADIO / /

REMOVAL & INSTALL OF MOBILE RADIO INTO SPARE RESCUE 9
