



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V452

In Date: 11/03/2005
Close Date: 12/07/2005

Meter Reading:

Problem?

set up new unit R53

Task performed:

Parts	Quantity
0041BRACKET TOOL	2
14-7014HGR-1 HELMET HOOK	7
5025TERMINAL BOX	2
5269LPVM-5 SM MOUNT	4

Workorder: V478

In Date: 11/04/2005
Close Date: 12/07/2005

Meter Reading:

Problem?

set up new unit

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V779

In Date: 12/02/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

AIR LEAK FROM BRAKES WHILE SITTING, AIR HORN WILL NOT WORK WHEN RESPONDING TO CALLS, R-53

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V799

In Date: 12/02/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

possible air leak from brakes while sitting long-air horn inop when responding with lights and siren R53

Task performed:

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V854

In Date: 12/09/2005

Meter Reading:

Close Date: 12/12/2005

Problem?

STRETCHER WALL MOUNT LOCKING MECH. STICKS R-53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V908

In Date: 12/12/2005

Meter Reading:

Close Date: 12/15/2005

Problem?

right air horn inoperative R53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V952

In Date: 12/16/2005

Meter Reading:

Close Date: 12/19/2005

Problem?

BACK UP CAMERA FOR REAR AND PAT, COMPT, INOP, SHORE LINE AUTO EJECTOR NOT EJECTING, R-53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V800

In Date: 12/02/2005

Meter Reading:

Close Date: 12/27/2005

Problem?

adjust height of airpacks R27

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1082

In Date: 01/03/2006

Meter Reading:

Close Date: 01/06/2006

Problem?

L/SIDE WHEEL SEAL LEAKING, R-53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1249

In Date: 01/23/2006

Meter Reading:

Close Date: 01/24/2006

Problem?

EXHAUST LEAK, R-53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1498

In Date: 02/14/2006

Meter Reading:

Close Date: 03/03/2006

Problem?

MAP LIGHT INOP, R-53

Task performed:

Parts

Quantity

284358GOVERNOR D-2

1

800405PURGE VALVE KIT

1

VHD18537USE 284358 AIR GOVERNOR D-2 KN18537

1

Workorder: V1742

In Date: 03/06/2006

Meter Reading:

Close Date: 03/27/2006

Problem?

SPOT LIGHT DAMAGED, EXHAUST PIPE TIP LOOSE, R-53

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1974

In Date: 03/27/2006

Meter Reading:

Close Date: 03/29/2006

Problem?

STEERING WHEEL TILT MECHANISM BROKEN, R-53

Task performed:

Parts

Quantity

RGT-452258FFOOT PEDAL STERRING COLUMN

1

Workorder: V2068

In Date: 04/03/2006

Meter Reading:

Close Date: 04/05/2006

Problem?

COOLING SYSTEM LOW, R-53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1765

In Date: 03/07/2006

Meter Reading:

Close Date: 04/07/2006

Problem?

LIGHT BAR BOLTS ON R/SIDE OF CAB RIPPED LOOSE, R-53

Task performed:

Parts

Quantity

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT

1

RMKEZ7LIGHT BAR MOUNT PERMENET MKEZ29

1

Workorder: V2205

In Date: 04/11/2006

Meter Reading:

Close Date: 04/20/2006

Problem?

LED LIGHT ON OFFICERS SIDE BETWEEN DOORS INOP, R-53

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2397

In Date: 04/27/2006

Meter Reading:

Close Date: 05/01/2006

Problem?

STRETCHER LATCH INOP, DOOR LATCH INOP, R-53

Task performed:

Parts	Quantity
090-0278STRECHER BAR NEW	3
28400-ZM7-003REWIND ASSY	1

Workorder: V1439

In Date: 02/08/2006

Meter Reading:

Close Date: 05/11/2006

Problem?

STRETCHER WALL MOUNT STICKS, R-53

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V889

In Date: 12/09/2005

Meter Reading:

Close Date: 05/11/2006

Problem?

STRETCHER WALL MOUNT LOCK STICKS, HARD TO LOCK IN PLACE, R-53

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V2646

In Date: 05/17/2006

Meter Reading:

Close Date: 05/22/2006

Problem?

FRONT WINDSHIELD LEAKING, R-53

Task performed:

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2669

In Date: 05/18/2006

Meter Reading: 8,777.00

Close Date: 05/22/2006

Problem?

B INSPECTION, R-53

Task performed:

See B Inspection pre-printed form

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
032110401150 VALVE AIR SEAT	1
29526898 29548988 TRANS FILTER ALLISON	1
31-22USE 91-22 WIPER BLADES	2
42809AIR FILTER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
ACX-8453LUG CAPS WHEELED COACH # CH27321 OLD	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VBK-HBRACKET FOR WHEEL AIR EXTENSION	4

Workorder: V3058

In Date: 06/20/2006

Meter Reading:

Close Date: 06/27/2006

Problem?

A INSPECTION, R-53

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V3322

In Date: 07/06/2006

Meter Reading:

Close Date: 07/11/2006

Problem?

ROOF LEAKING R53

Task performed:

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2702

In Date: 05/22/2006

Meter Reading:

Close Date: 07/12/2006

Problem?

REPLACE 6 TIRES, R-53 (CALLAGHAN)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: VC-15214

Workorder: V3600

In Date: 07/23/2006

Meter Reading:

Close Date: 07/26/2006

Problem?

squeaking from undercarriage while driving. possibly driveshaft bearing or similar.R53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3621

In Date: 07/25/2006

Meter Reading:

Close Date: 07/28/2006

Problem?

driver complaint howl at 45mph poss rear end r53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4036

In Date: 08/21/2006

Meter Reading:

Close Date: 08/23/2006

Problem?

shoreline plug is broken. plug is loose when engaged in truck. Will not make connection to truck. R53

Task performed:

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V4208

In Date: 09/01/2006

Meter Reading:

Close Date: 09/08/2006

Problem?

replace windshield (saflite)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: SAFELITE

Workorder: V4124

In Date: 08/25/2006

Meter Reading:

Close Date: 09/11/2006

Problem?

driver a/c not cooling R53

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4403

In Date: 09/12/2006

Meter Reading: 11,702.00

Close Date: 09/25/2006

Problem?

several fasteners missing from grill R53

Task performed:

Parts

Quantity

1. INSTALL NEW SCREWS IN GRILLE.

NO PARTS USED

Workorder: V4970

In Date: 10/19/2006

Meter Reading: 13,204.00

Close Date: 11/02/2006

Problem?

RESCUE 53 / DRIVERS DOOR LOCKING MECHANISM STICKING. HARD TO OPEN AT TIMES.

Task performed:

Parts

Quantity

1. TRAVELED TO STN 53. ADJUSTED DRIVERS DOOR LATCH.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5313

In Date: 11/08/2006
Close Date: 11/09/2006

Meter Reading: 1,527.20

Problem?

A/C in front cab not working, no cold air. r53

Task performed:

- 1. CLEAN A/C INTAKE
- 2. RECHARGE A/C
- 3. REPLACE A/C FILTER

Parts	Quantity
VCC/36000006A/C FILTER CAB M2	2

Workorder: V5458

In Date: 11/20/2006
Close Date: 11/27/2006

Meter Reading: 1,527.20

Problem?

unable to tighten stretcher locking bar .stretcher keeps coming loose r53

Task performed:

- 1. REPLACE STRECHER LOCKING BAR

Parts	Quantity
NO PARTS USED	

Workorder: V5599

In Date: 11/29/2006
Close Date: 12/01/2006

Meter Reading: 1,618.00

Problem?

Radiator fluid reservoir is less than low.R53

Task performed:

- 1. TRAVELED TO STN 53. TOP OFF COOLANT AND CHECK FOR LEAKS.

Parts	Quantity
NO PARTS USED	

Workorder: V5804

In Date: 12/13/2006
Close Date: 12/15/2006

Meter Reading: 1,727.00

Problem?

front A/C on dashboard is blowing hot air. r53

Task performed:

- 1. TRAVELED TO STN 53. RECHARGED FRONT A/C SYSTEM.

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5808

In Date: 12/14/2006

Meter Reading: 1,727.00

Close Date: 12/15/2006

Problem?

Wig wags are not functioning and four lights in the upper light bar are not functioning. R-53

Task performed:

Parts

Quantity

1. TRAVELED TO STN 53. FOUND ALL LIGHTS WORKING, DRIVER FORGOT TO PUSH PARK OVER RIDE.

NO PARTS USED

Workorder: V5982

In Date: 12/28/2006

Meter Reading: 1,763.60

Close Date: 01/03/2007

Problem?

R53 SAYS SHORT CIRCUIT N4 ON SCREEN R53

Task performed:

Parts

Quantity

1. Replaced wiring for camera in dog house

NO PARTS USED

Workorder: V6003

In Date: 12/28/2006

Meter Reading: 1,763.60

Close Date: 01/03/2007

Problem?

Front AC blowing hot air. R53

Task performed:

Parts

Quantity

1. Condensor leaking

NO PARTS USED

Workorder: V6161

In Date: 01/08/2007

Meter Reading: 1,798.00

Close Date: 01/11/2007

Problem?

front A/C blowing hot again. r53

Task performed:

Parts

Quantity

1. replaced a/c fitting supplied by red dot

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6121

In Date: 01/06/2007

Meter Reading: 17,456.00

Close Date: 01/17/2007

Problem?

B Inspection and all needed repairs R53

Task performed:

1. B Inspection
2. Air dryer service
3. Secure loose exhaust pipe heat shield
4. O2 regulator and gauge missing lines cut retrieve regulator and gauge from south road tech. Cut and rewire sensor and attach assy. to tank
5. Clean and replaced all a/c filters
- 6.
7. Tech meeting and road test
8. Replaced handlights with update model
9. Repaired seat lumbar cushions
10. Checked after cooler hose. Part on order
11. Reroute positive battery cable to starter chaffing on frame. Rewrapped in loom
12. Traced and repaired bad ground to LED lights on cab. Replaced 1 LED 50% of bulbs out. Repaired bad connection at node 4
13. Serviced batteries
14. Had Ehrke check belt was told not to replace at this time.
15. Reroute air line for air horn chaffing
16. Replaced stripped nut cert in door panel
17. Found loose crank case vent loose secure loose clamp
18. R&R wiper blades and refilled washer tank

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
50R03ZCRLIGHT LED RED TIR 6	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
ACX-8453LUG CAPS WHEELED COACH # CH27321 OLD	5
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V6212

In Date: 01/10/2007

Meter Reading: 17,456.00

Close Date: 01/23/2007

Problem?

REPLACE TIRES AT SHOP R53 CALLAGHAN ENT

Task performed:

1. UNIT SENT TO CALLAGHEN TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6329

In Date: 01/18/2007

Meter Reading: 17,653.00

Close Date: 01/29/2007

Problem?

repair air leak r53

Task performed:

1. TRAVELED TO STN 53. REPLACED PURGE VALVE. TEST/OK.

Parts

Quantity

01-28905-000AIR COOLER HOSE

1

284358GOVERNOR D-2

1

800404USE K022105 PURGE KIT AD-IP-IS

2

Workorder: V6542

In Date: 01/30/2007

Meter Reading: 18,000.00

Close Date: 02/01/2007

Problem?

RT. AIR HORN INOP. LT. AIR HORN WEAK. - R53

Task performed:

1. Adjusted air horns

Parts

Quantity

NO PARTS USED

Workorder: V6884

In Date: 02/22/2007

Meter Reading: 19,375.00

Close Date: 02/27/2007

Problem?

REPAIR STROBE LT R53

Task performed:

1. REPAIRED BAD CONNECTION. TEST/ OK.

Parts

Quantity

NO PARTS USED

Workorder: V7265

In Date: 03/19/2007

Meter Reading: 2,258.60

Close Date: 03/20/2007

Problem?

The hinge screws are stripped and the hinges keep falling out. R53

Task performed:

Nut certed door hinge

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7360

In Date: 03/24/2007
Close Date: 03/30/2007

Meter Reading: 2,286.10

Problem?

red flashing exterior light between officer side door and passenger door is out. r53

Task performed:

Parts

Quantity

Replc LED light w/new
Rep chrome exhaust tip
Adj rear entrance door linkage
Rep air line on officer side air seat

NO PARTS USED

Workorder: V7591

In Date: 04/09/2007
Close Date: 04/11/2007

Meter Reading: 2,360.00

Problem?

stretcher release is broken. spring came out of handle. pole slides through clamp, needs tightening or replace.

Task performed:

Parts

Quantity

Replaced stretcher latch

090-0278STRECHER BAR NEW

1

Workorder: V7502

In Date: 04/03/2007
Close Date: 04/18/2007

Meter Reading: 2,360.00

Problem?

search light is burned out on r53

Task performed:

Parts

Quantity

Found bad connection

NO PARTS USED

Workorder: V7716

In Date: 04/16/2007
Close Date: 04/25/2007

Meter Reading: 2,437.20

Problem?

R53 A/C in the front portion of the cab is not working

Task performed:

Parts

Quantity

Cleaned A/C condenser fans & tested.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7871

In Date: 04/23/2007

Meter Reading:

Close Date: 04/30/2007

Problem?

Both the front and rear a/c in R53's cab are blowing hot air.

Task performed:

Parts

Quantity

Replaced diode for A/C system

DUFDT04-4P-RT03EL35674 DIODE PACK GRAY

1

Workorder: V8111

In Date: 05/05/2007

Meter Reading: 23,269.00

Close Date: 05/18/2007

Problem?

Spotlight on rescue 53 10-7

Task performed:

Parts

Quantity

Rep bad connection

NO PARTS USED

Rep rear door ltch; adj linkage

Workorder: V8124

In Date: 05/06/2007

Meter Reading: 2,545.00

Close Date: 05/31/2007

Problem?

front A/C not blowing R-53

Task performed:

Parts

Quantity

Replaced A/C filter

9545BELT M2 ENGINE

1

Readjusted latch/stretcher

DECAL 10-610FT 6IN CLEARANCE

4

DECAL 1111FT CLEARANCE DECAL

4

VCC/36000006A/C FILTER CAB M2

1

Workorder: V8247

In Date: 05/14/2007

Meter Reading: 23,549.00

Close Date: 06/06/2007

Problem?

rebuild stretcher rails (outside agency-emsar medco equipt. repair)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor?: MEDCO EQUIPMENT



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8259

In Date: 05/14/2007

Meter Reading: 2,578.80

Close Date: 06/06/2007

Problem?

R53 a/c in cab not cooling. Dash a/c or rear cab a/c. r53

Task performed:

Parts

Quantity

1. Troubleshoot A/C electrical system, found compressor wires shorted to high side line - repaired short, found burned diode - no part on truck return to shop
2. Install diode pack for front A/C - rode call install diode pack

NO PARTS USED

Workorder: V8563

In Date: 06/04/2007

Meter Reading: 24,445.00

Close Date: 06/14/2007

Problem?

AIR DUMP 10-7 R53

Task performed:

Parts

Quantity

1. Adjusted level of air bags
2. Adjusted rear door of rescue due to not opening from inside

NO PARTS USED

Workorder: V8882

In Date: 06/17/2007

Meter Reading: 27,436.00

Close Date: 06/21/2007

Problem?

front a/c not blowing R53

Task performed:

Parts

Quantity

1. No cab A/C checked all wiring found open circuit at power point at blower motor connector burned at motor and harness. replaced wiring harness and blower motor check operation no problem found.

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V8947

In Date: 06/21/2007

Meter Reading: 25,032.00

Close Date: 06/21/2007

Problem?

wipers come on when turn signals are activated r53

Task performed:

Parts

Quantity

1. Turn signals activating wiper switch found combo switch defective R&R combo switch check operation NPF

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8618

In Date: 06/05/2007

Meter Reading: 2,672.00

Close Date: 06/26/2007

Problem?

front a/c not blowing r53

Task performed:

Parts

Quantity

1. Replaced blower motor sensor for A/C system

VCC/83000036PROBE

1

Workorder: V9009

In Date: 06/25/2007

Meter Reading: 25,032.00

Close Date: 07/02/2007

Problem?

replace tires at callaghan ent r53

Task performed:

Parts

Quantity

1. replace tires

NO PARTS USED

Vendor?: CALLAGHAN TIRE

Workorder: V5792

In Date: 12/12/2006

Meter Reading:

Close Date: 07/03/2007

Problem?

WS was replaced never had clearance height letters re-added to windshield r53

Task performed:

Parts

Quantity

Work needs to be done at shop

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8920

In Date: 06/19/2007

Meter Reading: 25,032.00

Close Date: 07/05/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED R53

Task performed:

1. B inspection completed
2. Shop meeting
3. Replace tires (worn) replaced 5. Callaghan replaced 1
4. Battery box loose and missing screws/ repaired battery box
5. Storage compt doors loose and missing screws. Repaired all doors also repaired door latch l/r and door inside plastic cover
6. Tighten body U-bolts/ tightened U-bolts
7. Washers inop/ nozzle clogged/ cleaned nozzle
8. Service trans/ fluid overheated service trans
9. Replace engine belts/ due/ replaced belts
10. Replace front shocks/ worn/ replace shocks
11. UV light inop/ bulb/ replace bulb
12. Air leaks down overnight/ bulkhead connector l/s frame leaks/ repaired leak
13. Shop meeting
14. Front a/c not cooling well/ leak at comp discharge line and condenser inlet fitting/ replaced defective fittings and modified comp fitting
15. Exhaust stack loose and bent/ repaired stack
16. Lower radiator hose hitting spring/ drained coolant and reassembled hose properly
17. Medic seat belt inop/ disassembled seat to rewind belt
18. R/F door open warning inop/ door switch defective replaced switch
19. Patient comp. floor grip tape/ worn/ replaced tape as needed

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
203FFBEARING PULLEY	1
22-53754-000VENT INBOARD LH	1
22-53754-001VENT INBOARD RH	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
29526898 29548988 TRANS FILTER ALLISON	1
4909SCUT AND FAB FITTING	1
65140FRONT SHOCK NEW M2	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
ABPN83319744USE 7197 DRYER M2	1
ACX-84534LUG NUT COVER PK10	8
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1

Workorder: V9180

In Date: 07/06/2007

Meter Reading: 25,585.00

Close Date: 07/18/2007

Problem?

replace folding step R53

Task performed:

1. REPLACED REAR FOLDING STEP THAT WAS DAMAGED.
2. ROOF LEAKS- RESEALED TOP OF ROOF.

Parts

Quantity

MFG9980B351262 FOLDING STEP 45.25	1
-----------------------------------	---



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9997

In Date: 08/20/2007 Meter Reading: 27,425.00
Close Date: 08/31/2007

Problem?

TRANSMISSION SHIFTS HARD, R-53

Task performed:

Road tested truck & found no problem with shifting hard

Parts

NO PARTS USED

Quantity

Workorder: V10036

In Date: 08/21/2007 Meter Reading: 30,142.00
Close Date: 09/11/2007

Problem?

search light not working. light does not light or rotate from dash controller R53

Task performed:

1./ Spotlight inop; traced out; fnd bad connection
2. Adj stretcher mount

Parts

NO PARTS USED

Quantity

Workorder: V10230

In Date: 09/04/2007 Meter Reading: 28,157.00
Close Date: 09/25/2007

Problem?

ON CALL BATTERY 10-7

Task performed:

1. Burning Smell, Bateriaes Shorted, Replaced Batteries.

Parts

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER BATTERY
HP-31D BATTERY 950CCA HP-31D

Quantity

4

4

Workorder: V10722

In Date: 09/28/2007 Meter Reading: 28,591.00
Close Date: 10/01/2007

Problem?

air pack braket broken r53

Task performed:

1. REPAIRED BROKEN AIR PACK BRACKET
2. REAR DOOR HARD TO OPEN, ADJUSTED REAR DOOR LINKAGE

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11575

In Date: 11/13/2007

Meter Reading: 31,160.00

Close Date: 12/04/2007

Problem?

b inspection and repairs as needed r53

Task performed:

1. "B" inspection
2. "B" inspection
3. Rear brakes/ worn/ replaced rear brakes and drums.
4. Search light Inop. Toggle broken and connection pin burnt, replaced switch assy and repaired wiring.
5. Washer Inop. Nozzles clogged, cleaned nozzles.
6. R/F door sill broken, Installed new sill.
7. Coat hooks missing, not mounted in metal drill tapped and installed new coat hooks also replaced R/S curb mirror.
8. Comp door panels loose and tool clips broken tightend comp doors and replaced axe clips.
9. Medic camera Inop, connector in dog house loose, reconnected
10. Rear light bar lens cracked, Installed new lens , also replaced marker bulbs as needed.
11. O-V light inop. bulb, none in stock
12. Light bar L/R marker Inop. lens broken, none in stock.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
0040BRACKET	1
14-7014HGR-1 HELMET HOOK	2
18-46375-00118-46375-005 TREAD PLATE RH M2	1
3744BRAKE DRUM REAR	2
42809AIR FILTER M2	1
68-3983813-30LENS 4500 BAR CLEAR	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A22-54624-001DOWN VIEW MIRROR M2	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V11698

In Date: 11/20/2007

Meter Reading: 31,374.00

Close Date: 12/04/2007

Problem?

replace tires callaghan r53

Task performed:

Replace tires Callaghan R53

Parts	Quantity
NO PARTS USED	

Vendor?: CALLAGHAN TIRES



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12096

In Date: 12/17/2007

Meter Reading: 3,594.00

Close Date: 12/21/2007

Problem?

drivers side headlight out R-53

Task performed:

1. Replaced head light bulb.
2. Repaired rear door latch that was falling off.

Parts

9006XSSLHEADLAMP M2 HI
H6054USE CV TYPE SEALED BEAM

Quantity

2
2

Workorder: V12108

In Date: 12/17/2007

Meter Reading: 3,629.00

Close Date: 12/21/2007

Problem?

Metal locking mechanism on top door at rear of rescue 53 is not secured in door. Entire mechanism can pull out from wood door, preventing lock from working.

Task performed:

1. Repaired latch in rear of rescue that was falling off.

Parts

NO PARTS USED

Quantity

Workorder: V11818

In Date: 11/29/2007

Meter Reading: 31,785.00

Close Date: 01/11/2008

Problem?

repair fuel system r53

Task performed:

Repair fuel system R53 - Florida Detroit Diesel j

Parts

NO PARTS USED

Quantity

Vendor?: FLORIDA DETROIT

Workorder: V12428

In Date: 01/08/2008

Meter Reading: 3,742.00

Close Date: 01/25/2008

Problem?

There are 3 lights overhead lights out in the patient compartment. They do not work in high or low. r53 TK

Task performed:

1. Replaced three Pt. lights.

Parts

322502BULB PATIENT GH22

Quantity

5



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12864

In Date: 01/28/2008

Meter Reading: 35,399.00

Close Date: 01/28/2008

Problem?

COMPT LIGHTS 10-7 R53

Task performed:

1. R+R auto plug cover, check out rear compartment lights.

Parts

091-3YWCOVER KUSSMAUL AUTO EJECT

Quantity

1

Workorder: V13445

In Date: 02/23/2008

Meter Reading:

Close Date: 03/05/2008

Problem?

R53 will not start, it will not turn over R53

Task performed:

1. No start, replaced started

Parts

DR/190260358300026 38MT 11 TEETH STARTER

Quantity

1

Workorder: V13742

In Date: 03/07/2008

Meter Reading: 673.00

Close Date: 03/14/2008

Problem?

The tilt/telescopic pedal is broken. It moves freely, and obstructs the brake pedal. r53

Task performed:

1. Installed new pedal for tilt wheel

Parts

RGT-452258FFOOT PEDAL STERRING COLUMN

Quantity

1

Workorder: V13887

In Date: 03/13/2008

Meter Reading: 715.80

Close Date: 03/17/2008

Problem?

accident damage to front and passenger side of R53. minor body damage to front of vehicle, and damage to footstep passenger side of vehicle

Task performed:

Inspected body damage; did not warrant coming out of service. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13964

In Date: 03/18/2008

Meter Reading: 772.10

Close Date: 03/24/2008

Problem?

station 53 C-shift. R53 is having a problem with the airhorn foot switch. foot switch only works periodically

Task performed:

Parts

Quantity

1. air horns inop-repaired bad ground wire and tested.

NO PARTS USED

Workorder: V13461

In Date: 02/25/2008

Meter Reading: 36,681.00

Close Date: 04/21/2008

Problem?

UNIT WILL NOT START, R-53

Task performed:

Parts

Quantity

No start; fnd starter bad. j

190114036842 29MT 9 TOOTH STARTER

1

Workorder: V14730

In Date: 04/28/2008

Meter Reading: 40,335.00

Close Date: 04/29/2008

Problem?

lights go on by themselves r53

Task performed:

Parts

Quantity

1. lighs coming on and off-replaced master control bottons.

0K00-1958-00KEY PAD 7 POSITION

1

Workorder: V14576

In Date: 04/20/2008

Meter Reading: 39,771.00

Close Date: 04/30/2008

Problem?

the plug will not stay plugged for the pt compartment to stay cool. R53

Task performed:

Parts

Quantity

1. repaired 110 outlet for plug that was ran over by truck

0915520120AUTO EJECT 20 AERO OTL3925

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15411

In Date: 05/29/2008

Meter Reading: 4,581.50

Close Date: 06/05/2008

Problem?

POSSIBLE LEAK IN THE COOLANT RESEVOIR, WENT FROM HIGH TO LOW IN LESS THAN 1 WEEK R-53

Task performed:

Parts

Quantity

Coolant leak; fnd overflow tank has hole; sent to shop.

NO PARTS USED

j

Workorder: V15424

In Date: 05/30/2008

Meter Reading: 42,111.00

Close Date: 06/05/2008

Problem?

COOLANT OVER FLOW TANK LEAKING, R-53

Task performed:

Parts

Quantity

R/R coolant; overlow tank. j

05-17223-002RAD CAP 20 LB

1

05-23195-000Z05-30740-000 SURGE TANK

1

Workorder: V15327

In Date: 05/26/2008

Meter Reading: 4,569.20

Close Date: 06/06/2008

Problem?

all the tires are down to the tread bar except for the driver front.

Task performed:

Parts

Quantity

Need all (6) tires. j

NO PARTS USED

Workorder: V15351

In Date: 05/27/2008

Meter Reading: 41,881.00

Close Date: 06/12/2008

Problem?

replace tires at sta 53 callaghan

Task performed:

Parts

Quantity

Replace tires Stn53 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15459

In Date: 06/02/2008

Meter Reading: 42,242.00

Close Date: 06/16/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED R53

Task performed:

- B-Inspection
- 2. Replc bulbs in pat compt.
- 3. Meeting w/Tim.
- 4. Tighten all loose screws in door panels in pat compt.
- 5. Dash broken on Lt. side; nesss to remove dash & rep; reassemble.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
15W40BSYN OIL BULK QTS	24
15W40QSYN OIL QT	4
27-102A22-54259-000 DOOM LIGHT SWITCH M2	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A22-54059-000DASH PANEL R/H M2	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V16197

In Date: 07/07/2008

Meter Reading: 43,909.00

Close Date: 07/07/2008

Problem?

ON CALL R53 BATTERY SWITCH 10-7

Task performed:

- 1. call out to station 53 to replace battery switch.

Parts	Quantity
M-284-01SWITCH BATTERY MASTER	1

Workorder: V15969

In Date: 06/25/2008

Meter Reading: 43,245.00

Close Date: 07/10/2008

Problem?

o2 regulator on truck main has a hole in it and needs a new one. r53

Task performed:

- 1. deck gun handle broken / removed handle and instaled new one.

Parts	Quantity
REG041462369 O2 REGULATOR	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16192

In Date: 07/07/2008

Meter Reading: 1,383.50

Close Date: 07/24/2008

Problem?

Front left park over drive light out. (drivers side on the left side of the hood). Appears the bulb is out. R53

Task performed:

Traced problem w/bulb; fnd broken wires; rep wires.
j

Parts

NO PARTS USED

Quantity

Workorder: V16519

In Date: 07/22/2008

Meter Reading: 44,516.00

Close Date: 07/28/2008

Problem?

repair stretcher at sta 53

Task performed:

Repair stretcher Stn53 - Emsar j

Parts

NO PARTS USED

Quantity

Vendor?: MEDCO EQUIPT

Workorder: V16514

In Date: 07/22/2008

Meter Reading: 44,516.00

Close Date: 07/30/2008

Problem?

changes out to bigger sharps box r53

Task performed:

1. rear 110 a/c inop,found bad connection in 110 plug
- 2.lft. side led light in op replaced light
3. cut sharps box to fit new boxes
4. stretcher latch inop readjusted latch

Parts

50R03ZCRLIGHT LED RED TIR 6
H35DSN12BULB 35W DUAL FILAMENT DOME

Quantity

1
2

Workorder: V16625

In Date: 07/28/2008

Meter Reading: 44,641.00

Close Date: 07/30/2008

Problem?

110V A/C INOP, LED LIGHTS INOP, R-53

Task performed:

1. 110 a/c inop repaired 110 power cord
2. replaced left side led light

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17210

In Date: 08/21/2008

Meter Reading: 45,055.40

Close Date: 08/22/2008

Problem?

REPAIR COOLANT LEAK

Task performed:

Parts

Quantity

Drained coolant; replcd temporary 3-way; coolant fitting installed on road; call with permanent fitting & refilled with coolant. j

NO PARTS USED

Workorder: V17098

In Date: 08/17/2008

Meter Reading: 4,996.80

Close Date: 08/28/2008

Problem?

AIR DUMP NOT WORKING R-53

Task performed:

Parts

Quantity

Checked out valve; fnd nothgin wrong; working at this time. j

NO PARTS USED

Workorder: V17464

In Date: 09/02/2008

Meter Reading: 46,713.10

Close Date: 09/29/2008

Problem?

plastic door on "shoreline power" outlet broken off. backup camera intermittent (especially after washdown. seatbelt on rear jumpseat does not retract. r53

Task performed:

Parts

Quantity

1. Chkd backup camera & fnd no problem at this time.
2. Rear seat belt inop; rep rear seat belt that was not retracting. j

NO PARTS USED

Workorder: V17611

In Date: 09/10/2008

Meter Reading: 47,104.00

Close Date: 09/29/2008

Problem?

O2 leak, R-53

Task performed:

Parts

Quantity

Repaired leak at main O2 Bottle.
Hard starting - check all battery connection and repaired.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17952

In Date: 09/26/2008
Close Date: 10/07/2008

Meter Reading: 47,860.70

Problem?

air door r53

Task performed:

Parts

Quantity

1- REAR 110 AC INOP- FOUND NO POWER TO 110 PLUG- RESERT BREAKER.
2- ROOF SPOT INOP- TRAILER OUT PROBLEM FOUND SHORTED WIRE IN CONSOL REPAIRED TESTED

NO PARTS USED

Workorder: V18178

In Date: 10/07/2008
Close Date: 10/15/2008

Meter Reading: 48,338.00

Problem?

AIR HORN INOP, R-53

Task performed:

Parts

Quantity

1-Air horn inop/ replaced air horn solenoid.

EL360081760611 SOLENOID AIR HORN

1

Workorder: V18387

In Date: 10/17/2008
Close Date: 10/28/2008

Meter Reading: 1,880.40

Problem?

air leak, all the air is leaking out of the system while truck is off. R53

Task performed:

Parts

Quantity

Air leaks; fnd fitting on brake valves leaking; rem/replc.
j

NO PARTS USED

Workorder: V18337

In Date: 10/15/2008
Close Date: 10/29/2008

Meter Reading: 48,515.40

Problem?

REPAIR AIR LEAK R53

Task performed:

Parts

Quantity

Air leak; replc fittings on brake valve that were leaking.
j

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V18667

In Date: 10/28/2008

Meter Reading: 48,970.10

Close Date: 10/31/2008

Problem?

rear patient doors hard to open R53 (on-call)

Task performed:

Parts

Quantity

Door hard to open; clnd latches & adj doors. j

NO PARTS USED

Workorder: V19857

In Date: 12/19/2008

Meter Reading: 52,073.60

Close Date: 01/06/2009

Problem?

plastic on door handle is broken on the side door in the pt. compartment. R53

Task performed:

Parts

Quantity

Replcd inner door handle. j

NO PARTS USED

Workorder: V19631

In Date: 12/09/2008

Meter Reading: 51,340.00

Close Date: 01/13/2009

Problem?

front end alignment r53

Task performed:

Parts

Quantity

Front end alignment R53 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V19603

In Date: 12/08/2008

Meter Reading: 51,340.00

Close Date: 01/14/2009

Problem?

replace front tires at sta 53

Task performed:

Parts

Quantity

Replace front tires at Stn53 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20595

In Date: 01/26/2009

Meter Reading: 5,789.20

Close Date: 02/09/2009

Problem?

R53 belts are squealing loudly

Task performed:

1. Traced out problem with belts making noise; fnd truck not charging; swapped out.
2. Replc alt not charging. j

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20007

In Date: 12/29/2008

Meter Reading: 52,759.10

Close Date: 02/10/2009

Problem?

C inspection and repairs as needed r53

Task performed:

- C-Inspection
- 2. L-strobe on hood inop; rem lite; rem connection at mini-node; T-shoot connections at node; rep connector; ck opn; ck ok; reassemble all parts.
- 3. Complete all paperwork & parts from on-call for W/E.
- 4. Replc shoreline plug cover; rem receptacle & replc cover.
- 5. A/C filters dirty; R/R frnt cab filter & rear A/C filter; clnd pat filter.
- 6. Door msgng on oxygen compt; fnd door in drawer; replc msgng hardware; installed door.
- 7. R/R wiper blades; washer inop; rep washer tubing on driverside; ck opn; ck ok.
- 8. P/S leaking at pump; clnd pump; tightened hose; ck ok.
- 9. Muffler guard & exh pipe tip loose; rep/tighten muffler guard; rem/rep exh tip; replc exh seal clamp.
- 10. Svc Dryer; R/R cartrdige & purge valve.
- 11. tighten all pat door latches; adj rear shelf; tighten bench hinges.
- 12. Center dome light out; rem lense; R/R bulbs.
- 13. Positive wires at btry rubbed thru on box; rep wires; rerouted/tied up wires.
- 14. Pat A/C not blowing; rem covers/control panel; rep mnt bolts; rem chute-rep; reinstalled all parts; ck opn; ck ok.
- 15. Ck UV light at rear A/C; rem panel ck ok.
- 16. Grnd strap frm frame to cab brkn; rem all cables; clnd connections & reinstalled grnds; mk new grnd; installed all grnds.
- 17. Pass mirror loose; tighten mirror/brkts; ck ok.
- 18. Replc water pump; rem fan, shroud, belts, pulleys, hoses, rad supports, tensioner, etc; replc water pump, t-stats, belts, tensioner; reassembled/filled rad; ran/chk for leaks; ck ok.
- 19. Rplc stretcher lock; replc lock; drove truck to stretcher; adj lock; ck ok.
- 20. L.R.O tire -aired up tire; fnd valve stem leaking; tighten ose; ck ok. j

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
090-0278STRECHER BAR NEW	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
33961C35976 MUFFLER CLAMP	1
42809AIR FILTER M2	1
6806970098SEAL DOOR	1
78R536078R5360M 2PK FILTER AIR COND	1
800404USE K022105 PURGE KIT AD-IP-IS	1
84871GROUND STRAP 12 IN	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
9062030015PIPE SOCKET TO WP	1
91-22WIPER BLADE	2
921LIGHT BULB	1
9420BELT	1
ACX-84534LUG NUT COVER PK10	5
DDE-0052035975A0052032675 THERMOSTAT ELEMENT M	2
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R90620043019062006301 WATER PUMP SOME M2 CI	1
DDE/9062002470BELT TENSIONER MERCEDES	1
DDE/A0279976048O-RINGS M2 WATER PUMP	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20264

In Date: 01/08/2009
Close Date: 02/18/2009

Meter Reading: 53,004.50

Problem?

repair cab a/c r53

Task performed:

Parts

Quantity

Cab A/C inop; connector loose at temp probe; also low refrigerant; rep connector; also rep leak @ condensor inlet & add (1) lb R-134A. j

NO PARTS USED

Workorder: V21219

In Date: 02/20/2009
Close Date: 03/05/2009

Meter Reading: 55,411.40

Problem?

SIDE DOOR WONT OPEN R53

Task performed:

Parts

Quantity

Side door not opening; readj door linkage. j

NO PARTS USED

Workorder: V21304

In Date: 02/24/2009
Close Date: 03/13/2009

Meter Reading: 6,093.00

Problem?

left front headlight out need bulb r53

Task performed:

Parts

Quantity

1. Rear back door not closing; readj rear door linkage.
2. Front lights inop on hood; rep bad connection on relay.
3. Auto-eject not working; fnd 110 plug damage on cord; rem/replcd. j

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22129

In Date: 03/27/2009

Meter Reading: 57,382.30

Close Date: 04/06/2009

Problem?

a/c 10-7 r53

Task performed:

Parts

Quantity

1. A/c inop; chkd for leaks; Fnd no leaks; recharged sys.
2. Rear dome lights out; rep bad connection on node #4.
3. Truck pulling to left; road tested & fnd truck drives fine. j

NO PARTS USED

Workorder: V22313

In Date: 04/03/2009

Meter Reading: 6,267.20

Close Date: 04/17/2009

Problem?

ac not blowing air, and n3 circuit fault on lcd display screen center console. R53

Task performed:

Parts

Quantity

1. A/C warm; recharged sys.
2. Alt bolts falling out; rep bolts. j

NO PARTS USED

Workorder: V22244

In Date: 04/01/2009

Meter Reading: 57,938.00

Close Date: 04/23/2009

Problem?

repair turn signals r53

Task performed:

Parts

Quantity

Turn signals inop; fnd bad connection. j

NO PARTS USED

Workorder: V22297

In Date: 04/03/2009

Meter Reading: 57,938.00

Close Date: 04/23/2009

Problem?

MAP LIGHT INOP, R-53

Task performed:

Parts

Quantity

Map lite inop; replcd maplight. j

LF18TS-LEDMAP LIGHT LED 18 IN

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22685

In Date: 04/20/2009

Meter Reading: 6,234.20

Close Date: 04/29/2009

Problem?

Ac system not cooling. System blowing hot air. r53

Task performed:

Parts

Quantity

1. A/C not cooling; traced problem; fnd A/C compressure locked up; needs to come to shop.

NO PARTS USED

2. No start; fnd starter solenoid had loose connection.

3. Stretcher latch inop; adj latch/tested.

4. A/C compressor locked up; needs to come to shop.

j

Workorder: V22717

In Date: 04/21/2009

Meter Reading: 58,562.00

Close Date: 04/29/2009

Problem?

won't start R53 (at 441 and clint moore rd.)

Task performed:

Parts

Quantity

No start; fnd loose connection. j

NO PARTS USED

Workorder: V22751

In Date: 04/23/2009

Meter Reading: 58,562.00

Close Date: 04/29/2009

Problem?

on call wont start r53

Task performed:

Parts

Quantity

No start - intermittent problem; started truck, tightened cables; seemed too loose; main power to start solenoid on fire wall; swapped out. j

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22754

In Date: 04/23/2009

Meter Reading: 58,562.00

Close Date: 05/13/2009

Problem?

a/c 10/ 7 intermittent no start R53

Task performed:

1. R/R A/C compressor for frt & cab A/C.
2. R/R A/C compressor for frt & cab A/C. replc dryer & evac sys & charge; install belt.
3. Dianio clutch opn for frt A/C.
4. Dia no clutch opn for frt A/C; replcd oi press swtch-NG; chk wiring harness; fnd bad splice; rep splice & heat shrink connection.
5. Dia blower inop; fnd b ad connector term at blower motor; replcd harness.
6. Dia starter problem; fnd bad ign swtchs; intermittant; doesn't work; ordered swtch; rem dash to rem ign swtch
7. Dia rear A/C; one condenser fan inop; fnd node #3 pin D opn; cln connection now working.
8. Install ign swtch & dash.
9. Hookup laptop & chk for ABS codes.
10. Dia squeal; rem alt belt & chkd pulleys.
11. Replcd alt belt & tensioner; R/R A/C belt. j

Parts

Quantity

01-29866-118BELT ALT. M2	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
A06-22717-002IGNITION SWITCH	1
DDE-0041534928A0071530828 OIL PRESSURE SENDING U	1
DDE/9062002470BELT TENSIONER MERCEDES	1
VCC/83000038AC WIRE HARNESS	1

Workorder: V22976

In Date: 05/01/2009

Meter Reading: 59,300.50

Close Date: 05/14/2009

Problem?

engine overheating R53

Task performed:

Went to Stn53; fnd R53 overheating; air line on fan came loose; connected air line & ran evac to watch for proper opn. j

Parts

Quantity

NO PARTS USED

Workorder: V23080

In Date: 05/05/2009

Meter Reading: 59,420.00

Close Date: 05/21/2009

Problem?

repair mirrors r53

Task performed:

Installed right side mirrors that were damaged. j

Parts

Quantity

A22-54624-001DOWN VIEW MIRROR M2	1
A22-58516-001MIRROR HEAD	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23052

In Date: 05/05/2009

Meter Reading: 59,420.00

Close Date: 05/26/2009

Problem?

repair cover over fuel tank r53

Task performed:

1. Rep cover over fuel tank that was falling off.
2. Air leak; rep air leaks.
3. Rear light bar inop; fnd bad connection. j

Parts

NO PARTS USED

Quantity

Workorder: V23513

In Date: 05/24/2009

Meter Reading: 6,460.80

Close Date: 06/01/2009

Problem?

headlight and hi beam out on r 53 driver side

Task performed:

Replcd headlight. j

Parts

9006XSLLEADLAMP M2 HI

Quantity

1

Workorder: V23426

In Date: 05/21/2009

Meter Reading: 60,077.40

Close Date: 06/02/2009

Problem?

REPAIR A/C R53

Task performed:

Recharged rear A/C & checked for leaks. j

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2

VCC/36000006A/C FILTER CAB M2

Quantity

1

1

Workorder: V23974

In Date: 06/10/2009

Meter Reading: 60,513.60

Close Date: 06/18/2009

Problem?

repair air leak r53

Task performed:

1. Air leak; purge valve sitcking; replcd purge valve.
2. Cab A/C not cooling; low refrigerant; leak @ condensor; will go to shop in the AM. j
3. C/O truck on side of road; wld not shift; road or pump damages to UPS valve; tow to Stn42 & rep VPS valve. j

Parts

5003547USE K022105 PURGE VALVE REB KIT M2

5460370530VPS SHIFT KIT 546-0370-53-0

K022105PURGE VALVE AD-IP-IS

Quantity

1

1

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23934

In Date: 06/09/2009
Close Date: 06/19/2009

Meter Reading: 6,498.30

Problem?

Shore line will not plug into the rescue. Have tried multiple times, multiple ways. Will go partially in but not seat. Once let go of plu it will fall out. R53

Task performed:

Replcd shoreline plug. j

Parts

NO PARTS USED

Quantity

Workorder: V23976

In Date: 06/10/2009
Close Date: 06/22/2009

Meter Reading: 60,513.60

Problem?

B INSPECTION AND REPAIRS AS NEEDED R53

Task performed:

- 1. B-Inspection
- 2. R/R btrys
- 3. tighten/adj/lube all door latches.
- 4. Torque u-bolts.
- 5. R/R frnt drums & shoes; adj.
- 6. Rep comp L3 hinge mntng bolts - stripped out.
- 7. Svc diff.
- 8. T-shoot condensor fan; R/R fan.
- 9. R/R squad bench shocks & tighten mntg.
- 10. Rep L/R pat compt light.
- 11. R/R parking brake light.
- 12. R/R wiper blades.
- 13. Rep air horns.
- 14. Chk/recharge cab A/C.
- 15. Rep city horn.
- 16. Cln work area. j

Parts

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1
194-ABULB 2
2FC00ZCR4 IN ROUND LED 1
322502BULB PATIENT GH22 1
3744BRAKE DRUM REAR 2
3753BRAKE DRUM RUMPER FRONT 2
60027FAN A/C COND 12IN 860026-2-W 1
78R536078R5360M 2PK FILTER AIR COND 1
906-181-00-86OIL FILTER M2 SPINNER 57140 1
91-22WIPER BLADE 2
921LIGHT BULB 1
ACX-84534LUG NUT COVER PK10 8
AMH-1AMH-1 VALVE EXTENSION 1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY 4
EL360081760611 SOLENOID AIR HORN 1
EST-1THERMAL TREATMENT 4
EST-2DDIAMOND TREATMENT 4
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB 2
HA141LIGHT RED WARNING 1
HP-31DBATTERY 950CCA HP-31D 4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE 2
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT 2
S3226FL02FUEL FILTER 33813 L/F # LFF5851 1
VCC/36000006A/C FILTER CAB M2 1

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23960

In Date: 06/10/2009

Meter Reading: 60,513.60

Close Date: 07/08/2009

Problem?

AUTO EJECT 10-7 R53

Task performed:

1. Aut0-eject inop; replcd auto-eject.
2. Frnt A/C warm; recharged sys. j

Parts

Quantity

0915520120AUTO EJECT 20 AERO OTL3925

1

Workorder: V24030

In Date: 06/12/2009

Meter Reading: 60,513.60

Close Date: 07/09/2009

Problem?

REPLACE ALL 6 TIRES R53 (outside agency-callaghan tire)

Task performed:

Replace all (6) tires R53 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V24663

In Date: 07/09/2009

Meter Reading: 61,789.00

Close Date: 07/15/2009

Problem?

WONT START R53

Task performed:

Travel to stn; dia electrical problem; fnd loose btry switch cable connection, blown fuse; correct faults; unable to dupe no start situation; unit in svc. j

Parts

Quantity

NO PARTS USED

Workorder: V25066

In Date: 07/26/2009

Meter Reading: 6,706.20

Close Date: 07/27/2009

Problem?

Radio has continous tone as if keyed. Unable to reset.

Task performed:

GAVE WORK ORDER TO STEVEN LEE

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V24644

In Date: 07/08/2009
Close Date: 07/28/2009

Meter Reading: 61,789.00

Problem?

Left rear tire was replaced. Rep from callaghan asked us to go to the shop in morning and have the short valve stem replaced. (Mechanic was out of Long ones).R53

Task performed:

1. Replc valve stems on rar tires.
2. Recalibrated foam gauge. j

Parts

NO PARTS USED

Quantity

Workorder: V24651

In Date: 07/09/2009
Close Date: 08/17/2009

Meter Reading: 61,789.00

Problem?

repair flat tire callaghan

Task performed:

- Repair flat tire - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor?: CALLAGHAN

Workorder: V25120

In Date: 07/28/2009
Close Date: 08/17/2009

Meter Reading: 6,749.70

Problem?

R53 is missing the ID plate for the Drivers side rear compartment. Mechanic did not have it in his vehicle as was thought. Please make a new ID Plate: R53

Task performed:

- Installed new bracket & number plate. j

Parts

NO PARTS USED

Quantity

Workorder: V25442

In Date: 08/10/2009
Close Date: 08/27/2009

Meter Reading: 6,775.00

Problem?

A/C does not blow any air at all. r53

Task performed:

1. Installed new blower motor & harness.
2. Rep rear stretcher latch. j

Parts

VCC/35000003BLOWER MOTOR VCCT1000904A M2

VCC/830000038AC WIRE HARNESS

Quantity

1

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25991

In Date: 09/03/2009

Meter Reading: 64,521.30

Close Date: 09/21/2009

Problem?

PATIENT COMPT A/C INOP R53

Task performed:

1. Pat comp A/C inop-unknown; A/C is working normally at this time; chk for poss problems w/connector switches, etc.
2. Cab A/C not cooling well - intermittent problem with evap temp probe & connector; replc probe & ordered new connector. j

Parts

Quantity

3134931349 RADIATOR CAP	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1
VCC/83000038AC WIRE HARNESS	1

Workorder: V26300

In Date: 09/16/2009

Meter Reading: 65,080.00

Close Date: 09/21/2009

Problem?

paitient a/c 10-7 r53

Task performed:

1. Ck for not starting; fnd pos cable at starter, isolation term & grnds at frame loose; tightened all connections; ck opn; ck ok.
2. Fnd clutch drive plate off of pat A/C compressor; installed/shimmed plate; replc msng bolt & installed plate; ran & ck opn; ck ok. j

Parts

Quantity

NO PARTS USED

Workorder: V26704

In Date: 10/06/2009

Meter Reading: 65,934.00

Close Date: 10/20/2009

Problem?

CAB A/C NOT COOLING

Task performed:

- Cab A/C not cooling; leak @ condensor inlet; locate/rep leak. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26190

In Date: 09/11/2009

Meter Reading: 64,861.00

Close Date: 11/06/2009

Problem?

ON CALL UNIT HIT CURB BLEW OUT TIR BENT RIM R53

Task performed:

Parts

Quantity

1. Drove to shop; PU spare; drove to Stn53 & installed.
2. Rear door hard to open; rep door linkage.
3. Air bags inop; rep rear air bags. j

NO PARTS USED

Workorder: V27477

In Date: 11/06/2009

Meter Reading: 67,345.00

Close Date: 11/17/2009

Problem?

R53 broke down NE corner of glades and 441

Task performed:

Parts

Quantity

Drive down to Glades Road & 441 to rep truck; return to shop to restock svc truck. j

M-284-01SWITCH BATTERY MASTER

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28003

In Date: 11/30/2009

Meter Reading: 68,811.20

Close Date: 12/16/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED R53

Task performed:

1. R/R air dryer & purge valve.
2. Rem/adj L/R inner pat compt door handle.
3. C/O for air leaks; tighten air tank drain valves.
4. R/R pat A/C clutch.
5. Torque u-bolts.
6. R/R officer side 12V receptacle.
7. R/R cab fresh air filter.
8. R/R frnt brake air lines.
9. Chk/readj frnt brakes.
10. R/R wiper blades.
11. Tighten/adj all comp doors.
12. rep marker lights frnt of box.
13. R/R fan, fan shroud & belts.
14. R/R SCBA brkts.
15. Adj air horns.
16. Cvr fan in center cabinet.
17. Install new marker light L/R cover on top of light bar.
18. Cln/reinstall rear A/C filter; R/R UV light.
19. R/R right rear inner pat compt door handle/bezel.
20. Rep left side washer line.
21. Loosen/realign left frnt bumper.
22. R/R officers side strobelight. j
23. C-Inspection
24. Chk for P/S leak; replc o-ring on steering box line.
25. Chk A/C for leaks; vac down & recharge. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
02-0363589-RRASSY RIGHT CORNER ICC LED FOR NEW	1
032-0116549297 BATTERY INDICATOR	1
12-21022-023M2 FRONT BRAKE LINES	2
15W40BSYN OIL BULK QTS	28
18-46375-00018-46375-004 TREAD PLATE LH M2	1
2FC00ZCR4 IN ROUND LED	1
42809AIR FILTER M2	1
5005624SINGLE CHECK VALVE KIT	1
5008414CARTRIDGE DC100	1
50R03ZRRLIGHT 500 TIR LED	1
56415CIG. LIGHTER ACCES.	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
ACX-84534LUG NUT COVER PK10	3
CLR9185209186-1500-20 MARKER LT.AMBER LED	2
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HAN-1LBEZEL AND HANDLE	1
K022105PURGE VALVE AD-IP-IS	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V27908

In Date: 11/24/2009

Meter Reading: 67,345.00

Close Date: 01/13/2010

Problem?

RESCUE PULLS TO LEFT WHEN BRAKES APPLIED. TIRE WEAR ON DRIVERS FRONT AND OFFICER REAR. r53

Task performed:

Road tested & tested ok. j

Parts	Quantity
01-20152-004CLAMP	2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V27939

In Date: 11/25/2009

Meter Reading: 67,345.00

Close Date: 01/15/2010

Problem?

replace front tires r53

Task performed:

Parts

Quantity

Repairs done on W/O 27889 j

NO PARTS USED

Replace front tires R53 j

Vendor?: CALLAGHAN

Workorder: V28057

In Date: 12/02/2009

Meter Reading: 68,811.20

Close Date: 01/15/2010

Problem?

replace 4 rear tires R53 (outside agency-callaghan tire)

Task performed:

Parts

Quantity

Replace (4) rear tires R53 - Callaghan j

NO PARTS USED

Vendor?: CALLAGHAN

Workorder: V29233

In Date: 01/19/2010

Meter Reading: 71,021.00

Close Date: 01/28/2010

Problem?

on call patient door wont open r53

Task performed:

Parts

Quantity

Rear door not opening; Readj rear door linkage. j

NO PARTS USED

Workorder: V28890

In Date: 01/07/2010

Meter Reading: 7,555.00

Close Date: 02/22/2010

Problem?

front driver side door lock mechanism, torc screws are backing out of housing cause lock mechanism to become loose and lock driver out of truck, air horn doesnt sound at all, works sumtimes when hitting brakes?? R53

Task performed:

Parts

Quantity

1. Replcd cable for cramps
2. Cab door screws coming out.
3. Rear door handle fell out; rep/tested. j

LP-30EXTENSION CABLE

2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29801

In Date: 02/08/2010

Meter Reading: 72,236.00

Close Date: 03/19/2010

Problem?

Can't open left door, entire handle falls out. Modification safety plate over striker pops up, door won't close. r53

Task performed:

1. Siren inop; FNP with siren.
2. Rear door hard to open; adj door hinge.
3. Headlight inop; FNP with headlights. j

Parts

Quantity

295SLSA1SIREN

1

9006XSLLEHEADLAMP M2 HI

2

Workorder: V30295

In Date: 02/27/2010

Meter Reading: 72,236.00

Close Date: 03/26/2010

Problem?

R53. the nader pin cover came loose and jammed the door. the door was able to be forced open. the nader pin cover was removed. R53

Task performed:

Installed new pin cvr & tested. j

Parts

Quantity

NO PARTS USED

Workorder: V31477

In Date: 04/13/2010

Meter Reading: 75,760.00

Close Date: 04/29/2010

Problem?

ON CALL DOOR LOCK 10-7 R53

Task performed:

Door lock brkn; diss door; rem locking asy; install/adj locking asy; reassembled door. j

Parts

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

1

Workorder: V31433

In Date: 04/10/2010

Meter Reading: 75,760.00

Close Date: 05/01/2010

Problem?

Patient compartment rear right door not closing. Handle appears to be broken.R53

Task performed:

Readj door latch linkage that was out of adjustment. j

Parts

Quantity

HAN-1LBEZEL AND HANDLE

1

HND5948TM22676-02 HANDLE DOOR ENTRY

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31659

In Date: 04/20/2010

Meter Reading: 76,162.00

Close Date: 05/04/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED R53

Task performed:

- B-Inspection
- 2. (1) fan for pat A/C inop; replc both fans.
- 3. Replc cab rear A/C filter & pat compt A/C filter.
- 4. Svc trans.
- 5. Svc P/S.
- 6. Replc maplite.
- 7. Replc bulb for R/S fender turn & marker lite.
- 8. Rem rear entry door window molding; cln out dirt; reinstall weather molding.
- 9. Replc L/side bottom rear LED lite.
- 10. Replc all (4) btrys.
- 11. Clan P/S box; chk for leak; fnd betwn hose on bottom of reservoir loose; tighten clamp.
- 12. Replc bulbs in pat compt dome lites.
- 13. Rem windshield washer sprayers both sides; cln out w/paper clip; cln rubber hose lines also. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	26
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	3
60027FAN A/C COND 12IN 860026-2-W	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
921LIGHT BULB	3
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
LF18TS-LEDMAP LIGHT LED 18 IN	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VML/T1808D2503221C1 FILTER POWER STEERING	1

Workorder: V31661

In Date: 04/20/2010

Meter Reading: 76,162.00

Close Date: 05/11/2010

Problem?

need at least 4 new tires on R 53

Task performed:

- Install (4) new tires. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31666

In Date: 04/20/2010
Close Date: 05/19/2010

Meter Reading: 76,162.00

Problem?

replace front tires r53 boulevard

Task performed:

Replace front tires R53 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE

Workorder: V32129

In Date: 05/11/2010
Close Date: 05/20/2010

Meter Reading: 76,552.00

Problem?

passenger side headlight is out r53

Task performed:

Went to Stn53 right HL inop; faulty bulb; replc bulb. j

Parts

9006XSSLHEADLAMP M2 HI

Quantity

1

Workorder: V32595

In Date: 06/02/2010
Close Date: 06/02/2010

Meter Reading: 78,157.00

Problem?

onboard radio stayed keyed opened

Task performed:

reported to radio shop 06/02/10

Parts

NO PARTS USED

Quantity

Workorder: V32512

In Date: 05/29/2010
Close Date: 06/25/2010

Meter Reading: 76,552.00

Problem?

REAR AC IS NOT COOLING R53

Task performed:

No rear A/C - condensor fans inop; A/C compressor not coming on. j

Parts

11-26521487 SWITCH NC O 340 - C 210 HIGH PRESS

60027FAN A/C COND 12IN 860026-2-W

Quantity

1

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28380

In Date: 12/15/2009

Meter Reading: 68,944.30

Close Date: 07/13/2010

Problem?

INSTALL INTAKE HOSE PARTS ORDERED IN R53

Task performed:

Verified job. j

Parts

Quantity

NO PARTS USED

Workorder: V32978

In Date: 06/18/2010

Meter Reading: 78,560.00

Close Date: 07/20/2010

Problem?

Battery switch on R53 intermittently will not work. When we jiggle the switch back and forth it usually works within a few times. R5

Task performed:

Replace btry switch. j

Parts

Quantity

75908SWITCH BATTERY MASTER 300A

1

Workorder: V33486

In Date: 07/12/2010

Meter Reading: 79,903.00

Close Date: 07/22/2010

Problem?

A/C in rear cab and front cab are blowing warm air. Uncomfortable for patients. R53

Task performed:

1. Chk frnt A/C; replc cab A/C filter; evac/recharge sys; chk/leaks.

2. Chk rear pat A/C; evac/recharge A/C; chk for leaks.

j

Parts

Quantity

NO PARTS USED

Workorder: V33599

In Date: 07/17/2010

Meter Reading: 80,157.00

Close Date: 07/23/2010

Problem?

Air leak R53

Task performed:

C/O air leak on truck; rescue had a fan clutch air line blower out of clutch; no parts; switch out truck; take driver to shop to get truck & chk on parts - none. j

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34114

In Date: 08/08/2010

Meter Reading: 80,157.00

Close Date: 09/09/2010

Problem?

Water leaks into pt compartment during rain. Leaks through lighting fixtures and ac. Large amt of water leaks in when braking or moving from stopped position. R53

Task performed:

1. Chkd for leak; fnd 110 A/C unit falling off of truck; rep screws & resealed.
2. Adj rear leveling valves that ruck was leaning. j

Parts

NO PARTS USED

Quantity

Workorder: V34174

In Date: 08/11/2010

Meter Reading: 80,157.00

Close Date: 09/17/2010

Problem?

repair power steering leak r53

Task performed:

1. Replc steering box-leaking;
2. Assit John w/steering gear. js
3. Air leak; purge valve leaking; replcd purge valve.
4. Air press goes to 150 PSI; replc air gov. j

Parts

14-15612-000GASKET RVR PWR STRG M2 1
 14-17722-000RTHP60001R STEERING GEAR ASSY 1
 5004049GOV CHK VALVE KIT M2 2
 800405PURGE VALVE KIT 2
 VML/T1808D2503221C1 FILTER POWER STEERING 1

Quantity

Workorder: V34513

In Date: 08/11/2010

Meter Reading: 80,157.00

Close Date: 09/28/2010

Problem?

repair body and paint per estimate R53 (outside agency-southeast truck)

Task performed:

Repair body & paint per estimate R53 - Southeast truck

j

Vendor?: SOUTHEAST TRUCK

Parts

NO PARTS USED

Quantity

Workorder: V35078

In Date: 09/21/2010

Meter Reading: 80,157.00

Close Date: 09/28/2010

Problem?

on call fan clutch not coming on R53

Task performed:

Eng overheats; air line to fan off; rep air line. j

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34982

In Date: 08/11/2010

Meter Reading: 81,413.00

Close Date: 09/29/2010

Problem?

A inspection and repairs R53

Task performed:

- A-Inspection
- 2. Added oil.
- 3. Added coolant.
- 4. Replc wipers.
- 5. Rep washers.
- 6. Adj tire press.
- 7. Replc belts/tensioner. j

Parts	Quantity
01-29866-118BELT ALT. M2	1
91-22WIPER BLADE	2
DDE/9062002470BELT TENSIONER MERCEDES	1

Workorder: V33615

In Date: 07/19/2010

Meter Reading: 80,157.00

Close Date: 10/19/2010

Problem?

REPLACE FAN CLUTCH R53

Task performed:

completed j

Parts	Quantity
4DA2545W LAMP	1
HOR/991450HT 650 FAN ASY.	1

Workorder: V36139

In Date: 11/02/2010

Meter Reading: 82,596.40

Close Date: 11/16/2010

Problem?

replace rear tires r53 boulevard

Task performed:

Replace rear tires R53 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor?: BOULEVARD TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36816

In Date: 12/06/2010

Meter Reading: 83,479.00

Close Date: 12/07/2010

Problem?

A/C comp locked up at glades and lyons r53

Task performed:

1. travel to glades and lyons road check out unit reported caught on fire, found a/c compressor for pat. compt. locked up, follow unit back to station and put back in service.

2. replace pat. compt a/c compressor, flush out a/c lines replace air dryer, remove fan to install a/c belt

Parts

Quantity

5790COMPRESSOR A/C

1

9420BELT

1

RD-5-7063-OP07-2618AA/C DRIER 7155

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36334

In Date: 11/09/2010

Meter Reading: 83,932.00

Close Date: 12/20/2010

Problem?

C INSPECTION AND REPAIR AS NEEDED R53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

- (1) "C" INSPECTION
- (2) REBUILT DRYER & PURGE VALVE. DRYER CARTRIDGE FROZEN ON THREADS. REMOVED WHOLE ASSEMBLY & REMOVED WITH PIPE WRENCH.
- (3) REPLACED WIPER BLADES. REPAIRED RIGHT SPRAYER NOZZEL.
- (4) TOP OFF TRANS FLUID TO PROPER LEVEL.
- (5) SERVICED BATTERIES. REMOVED BATTERY HOLD DOWN TO REMOVE PINCHED WIRE & CONNECTED TO POSSITIVE BATTERY POST.
- (6) ADJ TIRES FOR CORRECT PRESSURE.
- (7) REPAIR TIRE LEAK AT LRI VALVE STEM EXT.
- (8) ADD WHEEL LUBE TO RT FRT.
- (9) CHECKED COMPUTOR CODES. FOUND INACTICE HIGH COOLANT TEMP. CLEARED CODES.
- (10) REMOVED LOWER DASH PANEL & REPLACED FRT A/C FILTER.
- (11)REPAIRED REAR PATIENT DOOR. REPLACED LATCH. REPLACED HANDLE GASKET. ADJ DOOR RODS. LUBRICATED LATCHES. DRILL, TAP & COUNTER SUNK DOOR PANEL SCREW HOLES.
- (12) REPLACED FRT TIRES R&R WHEELS. REMOVED DRUMS & INSPECTED LINNING THICKNESS. CHECK WHEEL BEARINGS.
- (13) REPLACED REAR BRAKE SHOES & DRUMS, ADJ BRAKES.
- (14) REPLACED LEFT REAR MUD FLAP. CUT & DRILL TO SIZE.
- (15) REMOVED JUMP SEAT. REMOVED UPHOLSTERY TO GET TO SEAT BELT RETRACTOR. REMOVED SEAT BELT RETRACTOR & UNJAMED MECHANISM. REINSTALLED RETRACTOR COVERING & SEAT.
- (16) REPLACED REAR SHOCKS.
- (17) REPLACED REAR AIR BAGS.
- (18) REPLACED DRAIN VALVE IN TANK.
- (19) TORQUE ALL U- BOLTS.
- (20) STRAIGHTENED ANTI SWAY BAR BRACKET TO FRAME & TIGHTENED.
- (21) REPLACED LEFT ROCKER PANEL.
- (22) ORDERED R F KICK PANEL.
- (23) GLUED STAINLESS STEEL TRIM PIECE ON PATIENT COMT WALL SEAM,BY STRETCHER.
- (24) COMPOUNDED SURFACE OF HEAD LIGHT LENS, LEFT & RIGHT SIDE.
- (25) PRESSURE CHECK COOLING SYSTEM FOR LEAKS. RADIATOR CAP BAD.REPLACED CAP.FOUND RESERVOIR VENT HOSE PINCHED. REPOSITIONED HOSE & SECURED TO BODY.
- (26) TIGHTENED ALL DOOR PANEL SCREWS. DRILLED AND TAPPED NEW THREADS & INSTALLES NEW SCREWS THAT WERE MISSING. FILED SHARP EDGE ON L-3 DOOR & ADJ STRIKER. LUBED ALL

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
05-17223-002RAD CAP 20 LB	1
0K00-1957-00KEY PAD 4 POSITION	2
0K00-1958-00KEY PAD 7 POSITION	1
12105QUICK DRAIN	1
15W40BSYN OIL BULK QTS	24
16-15762-00016-19471-000 AIR BAG	2
161657700065489 SHOCK REAR NEW RESCUE	2
18-40977-00018-52651-000 AIR SPRING CAB M2	2
18-46375-00118-46375-005 TREAD PLATE RH M2	1
371508HOSE N FITTINGS	1
3744BRAKE DRUM REAR	2
39008USE 39045 KIT	1
42809AIR FILTER M2	1
4411S08-6962BS 90 DEGREE SB1322	1
5008414CARTRIDGE DC100	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A18-53531-000LOWER PILLAR PANEL	1
ACX-84534LUG NUT COVER PK10	7
AMH-1AMH-1 VALVE EXTENSION	1
B2420LP-SMUD FLAP 24 X 24	1
FREIGHTSHIPPING CHARGES	20
HAN-1LBEZEL AND HANDLE	1
IMMF14487REAR SEAT BELT M2	1
K022105PURGE VALVE AD-IP-IS	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
LTC594111656-16 LATCH R/H MEDIC MASTER	1
OQ30164410FRONT LABLE	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

LATCHES.

(27) DIAGNOSED PROBLEM WITH COMPARTMENT LIGHT ON L-1. FOUND BAD SWITCH. REPLACED WITH NEW SWITCH.

(28) REMOVED L R SEAT BELT. (LOCKED UP) ORDERED PARTS.

(29) DIAGNOSED PROBLEM WITH R GROUND LIGHT & REAR GROUND LIGHTS. L SIDE. FOUND BAD WIRING FOR RT & LT SIDES. RESPLICED, HEAT SHRINK TO PROTECT WIRING. TESTED OK.

(30) REPLACED RT KICK PANEL.

(31) REPLACED SIDE PATIENT COMP HANDLE INSERT.

(32) GLUED DOOR WEATHER STRIPPING ON L-2 R-1 R-3 DOORS.

(33) REPLACED A/C COMPARTMENT DOOR SHOCKS. NO PARTS USED FROM PARTS ROOM.

(34) CLEANED 110 VOLT A/C FILTER.

(35) ADJ L-2 INNER DOOR STRIKER.

(36) PAINTED FUEL CAP.

(37) REPLACE CAB LEVELING AIR BAGS.

(38) REPLACED R&F ROCKER PANEL.

(39) CHECKED TOE ADJUSTMENT, CHECKED OUT WNL.

(40) DIAGNOSED REAR A/C PROBLEM. FOUND SYSTEM LOW ON FREON. LEAK TESTED. FOUND DISCHARGE LINE FITTING LEAKING. SPLICED FITTING WITH SWITCH PORT. HAD MAKO HOSE FAB NEW HOSE WITH FITTINGS. SPLICED LINE, INSTALLED HP SWITCH, CRIMPED & HEAT SHRINKED WIRE CONNECTIONS. VAC DOWN SYSTEM, TESTED FOR LEAKS, RECHARGED SYSTEM WITH FREON. PROTECT HOSES. INSTALLED NEW PORT CAPS.

(41) DIAGNOSED FRT A/C PROBLEM. FOUND SYSTEM LOW ON FREON. EVACUATED DOWN SYSTEM, LEAK TEST, FOUND FITTING AT CONDENSER LEAKING. SPLICED NEW FITTING, VAC SYSTEM DOWN, RECHARGED & LEAK TESTED. PROTECT HOSES & WIRING.

(42) REPAIR AIR LINE LEAK AT HORN SOLENOID.

(43) DEGREASE MOTOR AT P/S PUMP/ AIR COMPRESSOR & AT TURBO INLET.

(44) ADJ AIR HORN.

(45) ROAD TEST VEHICLE & BURNISH REAR BRAKE LININGS.

(46) INSTALLED L REAR SEAT BELT, A/C LINE COVER SIDE PANEL TRIM, CAB TRIM PANEL & ROCKER PANEL.

(47) REPLACED MISSING LUG NUT COVERS.

(48) REPLACED VISTA FACE PLATE & PUSH BUTTONS, TESTED ALL SWITCHES.

(49) POSSIBLE LEAKING AT AIR COMPRESSOR HEAD GASKET. CLEANED AREA & WILL MONITOR POSSIBLE LEAKING / MIKE LEHAN ORDERS.



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33276

In Date: 07/01/2010
Close Date: 12/22/2010

Meter Reading: 78,560.00

Problem?

Requesting 3 quarts of oil for R53. Thanks.

Task performed:

Parts	Quantity
15W40QSYN OIL QT	12

Workorder: V34023

In Date: 08/04/2010
Close Date: 12/22/2010

Meter Reading: 80,157.00

Problem?

1. Loud humming in steering when turning. 2. Driver side rear mud flap falling off. R53

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V35242

In Date: 09/28/2010
Close Date: 12/22/2010

Meter Reading: 81,807.00

Problem?

AIR LEAKS R 53

Task performed:

(1) TRAVELED TO ST53 TO REPAIR AN AIR LEAK IN R53. FOUND TWO PIGGY BACK VALVES LEAKING AIR. WENT TO VENDER FOR PARTS. REPLACED TWO VALVES AND ONE PRESSURE SAFETY VALVE. RAN AND CHECKED FOR LEAK. OK. J.W.

Parts	Quantity
284142VALVE SAFETY ST-3	1
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	1
NRG-27-SWB-013RA12-19777-013 AMU006 VALVE ASSY	1

Workorder: V35289

In Date: 09/30/2010
Close Date: 12/22/2010

Meter Reading: 81,807.00

Problem?

Cab and pt compartment ac not working. Off going crew stated system worked off and on during their shift. R53

Task performed:

CAB & PT COMP A/C NOT WORKING ALL THE TIME. FIXED FREON LEAK AND RECHARGED SYSTEM, TESTED OK.

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36565

In Date: 11/02/2010
Close Date: 12/22/2010

Meter Reading: 82,596.40

Problem?

replace 2 front tires R53(outside agency- boulevard)

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V36718

In Date: 11/29/2010
Close Date: 01/11/2011

Meter Reading: 83,479.00

Problem?

repair rear suspension r53 total truck

Task performed:

Parts

Quantity

Repair rear suspension R53 - Total Truck j

NO PARTS USED

Vendor?: TOTAL TRUCK

Workorder: V38117

In Date: 01/28/2011
Close Date: 01/31/2011

Meter Reading: 86,487.00

Problem?

ON CALL coolant leak R 53

Task performed:

Parts

Quantity

Went to 53; filled rad w/wtrt;press tested; fnd rad tank on drivers side crkcd & leaking; went to shop w/driver; gave driver SR4; return home. j

NO PARTS USED

Workorder: V38127

In Date: 01/28/2011
Close Date: 02/14/2011

Meter Reading: 86,487.00

Problem?

radiator leaking r53

Task performed:

Parts

Quantity

1. Replc radiator - cracked/leaking; replc coolant, road tested; chkd for leaks; no leaks fnd.
2. Replc belts - out of date.
3. Replc cab roof marker light. j

01-29866-118BELT ALT. M2

1

9420BELT

1

A06-40578-000TOP CLEARANCE LIGHT M2

1

C1673FRE04 RADIATOR

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38121

In Date: 01/28/2011

Meter Reading: 86,487.00

Close Date: 02/16/2011

Problem?

tow from Station 53 to Vista shop R 53 (outside agency-westway towing)

Task performed:

Parts

Quantity

Tow from Stn53 to Vista shop R53 - Westway Towing

NO PARTS USED

j

Vendor?: WESTWAY TOW

Workorder: V37851

In Date: 01/18/2011

Meter Reading: 86,487.00

Close Date: 02/25/2011

Problem?

ON CALL A/C 10-7 R 53

Task performed:

Parts

Quantity

Fnd low on freon; chkd for leaks; fnd air dryer leaking;

NO PARTS USED

rep/tested. j

Workorder: V39336

In Date: 03/21/2011

Meter Reading: 90,016.00

Close Date: 04/05/2011

Problem?

drivers side, patient compartment outside door will not open. Hinges seem damaged. Can not access gear and equipment in compartment. R53

Task performed:

Parts

Quantity

1. check I-2 compt. door, door hit bay wall when leaving and jammed the striker pin, pry open door, reshape the striker, replace hold open assy. for door.

NO PARTS USED

2. Open doors that were damaged by pole. j



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39868

In Date: 04/12/2011

Meter Reading: 91,880.00

Close Date: 04/28/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 53

Task performed:

- B-Service
- 2. Rep washer on right side & fill fluid washer.
- 3. Repair wires to blower in dash; not blowing at all.
- 4. Rep cvr to filter in cap; all mnts brkn; mk up new mnts; sys ok.
- 5. Replc both A/C filters in cap.
- 6. R/R driver seat; chk for parts;had to order; reinstall seat in truck; ok to go; deferred to parts - on order. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	3
39008USE 39045 KIT	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
ACX-84534LUG NUT COVER PK10	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

Workorder: V39571

In Date: 03/30/2011

Meter Reading: 90,641.70

Close Date: 05/05/2011

Problem?

Wire that connects to the handle near the head of the stretcher is frayed. It looks like it is barely hanging on. Please fix as soon as possible. R53

Task performed:

- Need stretcher preaired, will call tech. j

Parts	Quantity
NO PARTS USED	

Workorder: V39572

In Date: 03/30/2011

Meter Reading: 90,641.70

Close Date: 05/05/2011

Problem?

Air Conditioner in the front of the cab does not appear to be working. The air conditioner in the rear of the cab appears to be ok. Thank you.R53

Task performed:

- 1. Recharged A/C 7 Rep leak at dryer.
- 2. Readjusted rear door linkage. j

Parts	Quantity
NO PARTS USED	

ref to wo 39220



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40029

In Date: 04/20/2011

Meter Reading: 91,644.00

Close Date: 05/09/2011

Problem?

Replace all 6 tires R53 (outside agency-Boulevard tire)

Task performed:

Replc all (6) tires R53 - Boulevard j

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD

Workorder: V40582

In Date: 05/12/2011

Meter Reading: 93,209.00

Close Date: 05/12/2011

Problem?

driver stated fuel leak from r/side fuel tank, also blower motor for cab a/c inop, R-53

Task performed:

1. driver stated fuel leak from r/side fuel tank, found r/side tank wet but no leak, use brakclean to clean off and hose off with water recheck for leak w/driver and found none, check cap ok, will keep an i on it
2.cab a/c blower motor inop, check fuses, and wiring harness, found wiring harness going to blower motor burnt, replace harness, ok

Parts

VCC/83000038AC WIRE HARNESS

Quantity

1

Workorder: V40694

In Date: 05/18/2011

Meter Reading: 93,513.30

Close Date: 05/18/2011

Problem?

door ajar alarm going off, R-53

Task performed:

1, door ajar alarm oging off, found r/side door setting off alarm, replace door switch.

Parts

2234934MASTER CYLINDER ASL

27-102A22-54259-000 DOOM LIGHT SWITCH M2

ASL3369972HYDRO-BOOST

Quantity

1

1

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40613

In Date: 05/13/2011

Meter Reading: 93,278.00

Close Date: 06/03/2011

Problem?

Leak in air bag used to raise/lower driver side seat. R 53

Task performed:

Air bags leak air; sent to shop. j

Parts

NO PARTS USED

Quantity

Workorder: V40838

In Date: 05/25/2011

Meter Reading: 93,413.30

Close Date: 06/09/2011

Problem?

door open alrm on r 53

Task performed:

Rep door switch that was loose in door jam. j

Parts

NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS

1

NRG-27-SWB-013RA12-19777-013 AMU006 VALVE ASSY

1

Workorder: V41496

In Date: 06/21/2011

Meter Reading: 94,262.40

Close Date: 06/22/2011

Problem?

Check engine light is being displayed on dash. Sta 53.

Task performed:

1. check for check engine lite on, hook up laptop check for codes, found code 146 EGR valve 1 count, per Ed. E erase code and advise driver if comes back on again to put it in the IBM.

Parts

NO PARTS USED

Quantity

Workorder: V41715

In Date: 06/30/2011

Meter Reading: 95,152.00

Close Date: 07/19/2011

Problem?

Check engine light came on enroute to training.

Task performed:

CONNECTED LAPTOP FOUND LOW COOLANT LEVEL
CEHCKED FOR LEAKS NO LEAKS AK

Parts

15W40QSYN OIL QT

5

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V42177

In Date: 07/21/2011

Meter Reading: 96,776.70

Close Date: 07/21/2011

Problem?

Pt. a/c inop.

Task performed:

Parts

Quantity

patient compt ac inop low refrigerant leak at hi side
charger sticking add refrigerant stopped leak ok add 1 lb
13 ya ak

NO PARTS USED

Workorder: V39220

In Date: 03/15/2011

Meter Reading: 89,622.40

Close Date: 08/05/2011

Problem?

a/c 10-7 R53

Task performed:

Parts

Quantity

ref to wo 39572

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43151

In Date: 08/29/2011

Meter Reading: 98,888.00

Close Date: 09/16/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R 53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

C INSPECTION X 2 DAYS	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
SERVICE BATTERIES	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
REPALCE VALVE STEM CORE IN RRO TIRE AND AIR ALL TIRES TO PROPER PSI	01-29866-118BELT ALT. M2	1
REPLACE FRT BRAKES AND DRUMS ADJ BRAKES	088319-007165 DRYER	1
REPLACED A/C COMPRESSOR FOR REAR AC AND DRYER RECOVER EVACUATE AND CHARGE AC	1094KIT-AIR HORN-GROVER	2
REPLACE BELTS AND R&R RAN	3753BRAKE DRUM RUMPER FRONT	2
JACK UP VEHICLE FOR TIRE REMOVAL	404-100 VALVE CORE	1
CHECK FRT A/C RECOVER EVACUATE AND RECHARGE	5790COMPRESSOR A/C	1
REMOVE DASH PANEL AND REPLACED AC FILTER	906-181-00-86OIL FILTER M2 SPINNER 57140	1
CLEAN PATIENT COMPT AC FILTER	9420BELT	1
REPLACED AUX CAB AC FILTER REPAIR BOTH FILTER HOLDERS	AMH-1AMH-1 VALVE EXTENSION	1
JACK UP VEHICLE AND CHEK WHEEL BEARINGS AND KING PINS FOR LOOSENESS OK	EL35675BLACK DIODE PLUG DT04-49-RT01	1
REPLACED R CENTER DOME BULB IN PATIENT COMPT	KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE	2
REPLACED WIPER BLADES	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
ADD COOLANT	TRI-F98999-225NOZZLE KIT	1
O2 SENSOR WIRES BROKEN OR CUT OFF REPLACED SENSOR AND SPLICED WIRING PROTECT WIRING WITH LOOM AND SECURE TEST O2 GAUGE INOP DIAGNOSE PROBLEM FOUND NO POWER TO SENSOR LOCATE BLOWN FUSE AND REPLACE RECHECK GAUGE OK CHEKC FOR O2 LEAKS	VCC/36000006A/C FILTER CAB M2	1
INSTALL MISSING LUG NUT VOERS ON FRT WHEEL: TIGHTEN ALL COMPT DOOR PANELS		
REPLACE BROKEN L2 TOOL BRACKET DRILL OUT HOLES IN BRACKET LARGER FOR ALIGNMENT WITH THREADED HOLES		
TIGHTEN LOOSE TOOL BRAK CET SCREWS		
TIGHTEN LOOSE NADER PINS		



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

INSTALL NEW BOLTS AND WING NUTS ON 02 BOTTLE BRACKET

INSTALL AIR HORN KITS IN LEFT AND RIGHT AIR HORNS AND TUNE BOTH FOR SOUND QUALITY

REPAIR WNDOW SQUIRTERS UNKINK R SQUIRTER HOSE CLEAN NOZZEL ON L SQUIRTER AND TEST LEFT SQUIRTER NO GOOD REPLACED L SQUIRTER NOZZEL TEST OK

GLUE REAR DOOR WEATHER STRIP

PAINT GAS CAP

DIAGNOSE PROBLEM WITH HIGH IDELE CHECK ALL REQUIRED INPUTS OK REMOVE OUT PUT CONNECTOR FROM NODE 1 AND CHECK PIN FOUND BAD CONNECTION REPAIR CONNECTION AND TEST OK

CHECK ENGINE TRANS AND ABS CODES ERASE INACTIVE CODES TEST DRIVE AND RECHECK OIK

QA TRUCK

REMOVE STEERING COLUMN TO CHECK FOR LOOSENESS CUT OFF STRIPPED BOLT FOUND COLLAR FOR TILT WITH ACCEPTABLE PLAY REINSTALL COVERS WITH NEW FASTENER

Workorder: V43756

In Date: 09/19/2011

Meter Reading: 98,978.00

Close Date: 09/21/2011

Problem?

transmission losing power.

Task performed:

found trans loosing power when turning left found wires grounded under cab repair wires repaired --laced wire loom clamp cleared codes test drove ran and ck ok

ck cab a/c not cooling found level low topped off system ran and ck operation ck ok

pat a/c not cooling recover freon leak test system found discharge hose fitting leaking removed air filter tubes brkts hoses etc -- of hose went to mako for parts replaced fitting and hose leak test vac and charge test drove ck ok

Parts

Quantity

391587HOSE&FITTING ASSY

1

4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43793

In Date: 09/20/2011

Meter Reading: 98,978.00

Close Date: 09/21/2011

Problem?

Transmission problem.

Task performed:

Parts

Quantity

checked codes found 1 code indicating power loss
started tracing harness swapped crew to spare

NO PARTS USED

2. Trans won't stay in gear-unknow; brought to shop to
t-shoot; had Scott help me; seems to be a wiring issue;
swapped out.

NOTE: Scott was already @ the shop; had him take
over so I cld work on R47. j

Workorder: V43638

In Date: 09/13/2011

Meter Reading: 987,722.00

Close Date: 09/23/2011

Problem?

head light 10-7

Task performed:

Parts

Quantity

replaced head light and repaired lens cover

9006XSLLEHEADLAMP M2 HI

2

readjusted rear door handle that was hard to close

Workorder: V44493

In Date: 10/19/2011

Meter Reading: 100,251.00

Close Date: 10/28/2011

Problem?

ON CALL DOOR OPEN LT ON R 53

Task performed:

Parts

Quantity

found bad cab door switch

27-102A22-54259-000 DOOM LIGHT SWITCH M2

2

52-624SWITCH DOOR

4



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43528

In Date: 09/08/2011

Meter Reading: 987,722.00

Close Date: 11/07/2011

Problem?

replace titres R 53

Task performed:

Parts

Quantity

Replace tires R53 - Tiresoles j

NO PARTS USED

Vendor?: TIRESOLES

Workorder: V45339

In Date: 11/21/2011

Meter Reading: 102,682.00

Close Date: 11/23/2011

Problem?

Pt. a/c and cab a/c inop.

Task performed:

Parts

Quantity

ck pat. a/c, freon low, topped off unit, ran and ck ok

071601A07-0602A DRIER A/C 7118

1

repair and replace a/c parts front unit and hoses replacement, dryer, both

4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT

1

4579S08-3422BS SPLICE

1

533303-0609 A/C COMPRESSOR M2 4485

1

ck cab a/c, found comp. bad, r&r compressor, r&r 2 dryers, r&r eng. belt, r&r cab blower and harness, vac and charge system, ck ok

719707-0614AAC DRIER M2

1

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V45790

In Date: 12/12/2011

Meter Reading: 103,668.40

Close Date: 12/16/2011

Problem?

R53 no siren

Task performed:

Parts

Quantity

NO SIREN; FOUND PA MIKE WAS KEYED OP - 7:00 - 8:30

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45956

In Date: 12/19/2011

Meter Reading:

Close Date: 12/19/2011

Problem?

Low on oil, Sta 53

Task performed:

parts only, no labor.

Parts

Quantity

15W40QSYN OIL QT

12

Workorder: V46637

In Date: 01/17/2012

Meter Reading: 106,293.00

Close Date: 01/27/2012

Problem?

PAT A/C INOP

Task performed:

1. RECOVERED SYSTEM. REPLACED PATIENT COMPARTMENT A/C COMPRESSOR. VACUUMED SYSTEM AND RECHARGED LEAK TESTED. FOUND COMPRESSOR CYCLING ERRATICALLY.
2. BYPASS HIGH AND LOW PRESSURE SWITCHES. COMPRESSOR. NOW OPERATES NORMALLY. ORDERED NEW SWITCHES.

Parts

Quantity

11-26521487 SWITCH NC O 340 - C 210 HIGH PRESS

1

1432A/C PRESSURE SWITCH NO OPENS 25 CLOSES 34

1

1450SWITCH PRESS OPEN-10 CLOSE-35 11-2028

1

5790COMPRESSOR A/C

1

EL35675BLACK DIODE PLUG DT04-49-RT01

1

FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CLOSE-2

1

Workorder: V46868

In Date: 01/01/2012

Meter Reading: 106,293.00

Close Date: 01/27/2012

Problem?

Replace tires

Task performed:

REPLACE TIRES.

Parts

Quantity

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46675

In Date: 01/18/2012

Close Date: 02/03/2012

Meter Reading: 106,293.00

Problem?

B INSPECTION R 53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. B Inspection.
2. After checking tire pressure 3 tires leaks air - couldn't lift vehicle to finish B Inspection. Had to go to Bldg 3 get another tire R&R l/rovter temporarily to lift vehicle.
3. B-Inspect.
4. Force open rear step compt. clean lube readjust latch and lock.
5. W/washers don't work. Test pump - OK. Found blockage in hoses system - clean out debries. Also hoses on wiper arms parted wrong kinked route hoses correctly.
6. R&R wiper blades.
7. Replace 3 schrader valves in 3 tires - leaked after checking pressures.
8. R&R patient ceiling light bulb.
9. Replace missing hardware and adjust drawer latch assy in patient area.
10. Replace incorrect hardware fabricate one special support plate fabricate 3 special flat washers - paint all black and install.
11. R&R one L/S step condenser fanmotor - had to R&R step to access.
12. Tighten bolts on all stanchions holding rear patient interior grab bar.
13. Start repairs on cab/aux patient a/c leak test system discharge system cut leaking fitting out. Install new fitting at side condenser unit.
14. R&R ground light assy straighten mounting plate replace rubber insert for light.
15. Finish cab and cab aux a/c systems repairs evacuate and recharge system leak test new crimps and check temps of dash and cab axu unit.
16. Laver Rad hoses and pipe hitting in 3 places. Loosened all Rad mounting bolts and rad frame bolts to move want move. Drain coolant, remove hoses and pipe assy replace both hoses reverse bolt on frame rail cut lowest hoses to provide clearance fabricate clamp to attach pipe to chassis bracket refill cooling system.
17. Patient a/c switches bad and wiring cut install new switches and wiring run system - compressor not cycling correctly - add and subtract freon - no good tried another low side switch no good - something wrong with system.
18. Set up truck on stand for tire to be removed.
19. Raise vehicle and remove jack stands.
20. Repair interior trim panel in patient area - hanging. Repair attaching hardware.
21. R&R 4 a/c lovers on patient a/c.
22. Travel to sta 53 to drop off rescue and back to shop
23. Deliver R-53 to sta 53 and return to c/s.
24. Patient a/c parts gave me 3 wrong low side switches system coolers not work right kept diagnosing to find out why.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
05-16062-051LOWER RAD HOSE M2	1
11-26521487 SWITCH NC O 340 - C 210 HIGH PRESS	1
142211-2028 SWITCH PRESS OPEN-6 CLOSE-34	1
1450SWITCH PRESS OPEN-10 CLOSE-35 11-2028	1
23-12705-002NUT GRILLE INSERT FRTL M2	3
23-12814-730BOLT GRILLE M2 FRTL	4
322502BULB PATIENT GH22	1
404-100 VALVE CORE	3
4579S08-3422BS SPLICE	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
HE50477VENT	4
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

25. A/C compressor fans shutting off. Intermittently used lap top to diagnose why 3 different nodes control system ohm test all. Circuits called weldon for tech support to help repair vehicle.

Workorder: V46994

In Date: 01/31/2012 Meter Reading: 106,874.00
Close Date: 02/03/2012

Problem?
INTERIOR PASSENGER SIDE FLAT TIRE. Sta 53

Task performed:	Parts	Quantity
TRIED TO REPAIR TIRE - NEED TO CALL TIRE COMPANY - REPAIRED.	NO PARTS USED	

Workorder: V47007

In Date: 02/01/2012 Meter Reading: 106,874.00
Close Date: 02/10/2012

Problem?
The interior cab camera is not working.

Task performed:	Parts	Quantity
1. TRACED OUT PROBLEM WITH CAM AND REPAIRED BAD CONNECTION IN CABLE.	NO PARTS USED	
2. AIR LEAK - CHECKED AND REPAIRED AIR LEAKS.		

Workorder: V47324

In Date: 02/14/2012 Meter Reading: 107,655.20
Close Date: 02/28/2012

Problem?
one side of stretcher locking antlers broke at the weld point. Stretcher wiggles. on Rescue 53, Sta 53

Task performed:	Parts	Quantity
REPLACED BROKEN ANTLERS FOR STRETCHER.	NO PARTS USED	

Workorder: V43635

In Date: 09/13/2011 Meter Reading: 987,722.00
Close Date: 03/09/2012

Problem?
front head light is out.

Task performed:	Parts	Quantity
	NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48459

In Date: 04/05/2012
Close Date: 04/05/2012

Meter Reading: 111,220.00

Problem?

check engine light

Task performed:

CHECKED ENGINE CODES - FOUND E.C.L. SENSOR CODE - TROUBLESHOOT AND COOLANT SENSOR - SENSOR BAD - R&R SENSOR - PRESSURE TEST SYSTEM - TIGHTENED CLAMPS - FILLED RAD AND CHECK OK.

Parts

Quantity

23520380SENSOR COOLANT

1

Workorder: V48467

In Date: 04/05/2012
Close Date: 04/20/2012

Meter Reading: 111,220.00

Problem?

Check Engine light relight after being serviced for the same problem. Sta 53

Task performed:

REPLACED FILTER FOR ENGINE OIL BLOW BY.

Parts

Quantity

CV5060300CV50628 CRANKCASE FILTER ISL

1

Workorder: V48495

In Date: 04/06/2012
Close Date: 04/20/2012

Meter Reading: 111,572.00

Problem?

nail in rear passenger tire.

Task performed:

SENT TIRE REPAIR OUT.

Parts

Quantity

NO PARTS USED

Workorder: V48728

In Date: 04/17/2012
Close Date: 04/24/2012

Meter Reading:

Problem?

Cab AC not cooling.

Task performed:

1. travel to sta-53
2. check cab a/c blows warm, also pat. a/c blows cool, chack fans, ok, hook up gauges both cab and pat. a/c low on freon, top off system, check for leaks none found at this time, will need to come to shop next time.

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49054

In Date: 05/02/2012

Meter Reading: 112,977.70

Close Date: 05/02/2012

Problem?

cab a/c inop, R-53

Task performed:

Parts

Quantity

1. check cab a/c found low on freon, top off and check for leak, remove d/side cab step, check for leak, none found, put vehicle up on lift, check hoses from front of vehicle to rear of vehicle, found a/c hose that had been spliced on frame rail not crimped enough, (T fitting was loose) remove and install new T splice and crimp. evacaute system, held vacuum, recharge a/c...

NO PARTS USED

Workorder: V49635

In Date: 05/25/2012

Meter Reading: 11,406.10

Close Date: 06/08/2012

Problem?

officer requested to have brakes on recuse looked at. R53

Task performed:

Parts

Quantity

ROAD TESTED AND TESTED OK.

NO PARTS USED

Workorder: V49993

In Date: 06/08/2012

Meter Reading: 114,467.00

Close Date: 06/11/2012

Problem?

A INSPECTION R 53

Task performed:

Parts

Quantity

A-INSPECTION.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49936

In Date: 06/06/2012
Close Date: 06/13/2012

Meter Reading: 114,467.00

Problem?

WONT STSRT R 53

Task performed:

1. REPLACE STARTER/WORN/REPLACED STARTER
2. INTERMITTEN NO START/LOOSE GROUND/ CHECK FOR GROUND PROBLEM.
3. NO START/ FOUND CORROSION BEHIND GROUND TERMINAL ON L-S FRAME RAIL BEING BATTERY BOX REPAIRED GROUND.
4. REPLACE BATTERY SWITCH/CANNOT TIGHTEN STUD TERMINALS/REPLACED BATTERY SWITCH.

Parts

Quantity

75908SWITCH BATTERY MASTER 300A	1
DR/190260358300026 38MT 11 TEETH STARTER	1
ESX120105112STARTER RELAY ESX-120-105112	1

Workorder: V49925

In Date: 06/06/2012
Close Date: 06/14/2012

Meter Reading: 114,467.00

Problem?

ON CALL WONT START R 53

Task performed:

TRAVEL TO ST 53 TEST BATTERIES AND STARTER TRY AND JUMP STARTER. TRAVEL TO CENTRAL SHOP GET SPARE UNIT.

Parts

Quantity

NO PARTS USED

Workorder: V50116

In Date: 06/13/2012
Close Date: 06/15/2012

Meter Reading: 114,826.00

Problem?

(1)Air horn not functioning (2)Open compartment alarm malfunctioning R53

Task performed:

1. AIR HORN INOP/ REPLACED AIR HORN SOLENOID.
2. REPLACE TWO AIR VALVES FOR PARKING BRAKE.

Parts

Quantity

HDY-H005700SOLENOID HORN AIR	1
NRG-27-SWB-011RNRG27SWB311R A12-19777-011 VLV AS	1
NRG-27-SWB-013RA12-19777-013 AMU006 VALVE ASSY	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50265

In Date: 06/20/2012

Meter Reading: 115,038.60

Close Date: 06/20/2012

Problem?

front grill falling off, R-53

Task performed:

Parts

Quantity

1. check front grill found 3 screws missing, install new screws and washers

NO PARTS USED

Workorder: V50491

In Date: 06/29/2012

Meter Reading: 115,771.10

Close Date: 07/02/2012

Problem?

CHECK ENGINE LIGHT ON AND EMERGENCY SENSOR KEEPS GOING ON WHILE DRIVING. R 53

Task performed:

Parts

Quantity

TRAVEL TO ST 53 SCAN COMPUTER ON R53 #4 INJECTOR BALANCE PROBLEM SEND TO SHOP HAD TO WAIT ON UNIT.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49329

In Date: 05/14/2012

Close Date: 07/03/2012

Meter Reading: 113,721.90

Problem?

C INSPECTION R 53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. C INSPECTION.
2. C INSPECTION.
3. REPLACE BATTERIES.
4. TAKE SAMPLES OF ENGINE, TRANS, AND REAR AXLE. FILL OUT PAPERWORK.
5. LRO TIRE LEAK AND WON'T TAKE AIR. REPLACE CORE AND VALVE EXT. HOSE. AIR TIRE AND CHECK FOR LEAK. OK.
6. REPLACE R REAR INSIDE VALVE STEM EXTENSION.
7. REMOVE NAIL FROM R R OUTSIDE TIRE AND LEAK CHECK. OK.
8. REBUILD DRYER AND REPLACED PURGE VALVE.
9. REPLACE REAR BRAKE SHOES AND DRUMS. ADJUST BRAKES.
10. REPLACED BELTS. R&R FAN.
11. DIAGNOSE REAR A/C WARMER FOUND LOW FREON. LEAK CHECK SYSTEM FOUND LEAK AT HOSE CRIMP AT CONDENSOR.
12. R WINDOW SQUIRTER IN/OP. REMOVE SQUIRTER AND CLEAN OUT ORFICES REPLACED WIPER BLADES.
13. RECOVER FREON FROM REAR A/C SYSTEM. REMOVE FITTING FROM CONDENSOR. REMOVE FRAME CLAMPS TIE STRAPS AND LOOM FROM A/C HOSE CUT HOSE BACK ALONG FRAME. SPLICE NEW SECTION OF HOSE TO OLD. SPLICE 90 DEGREE FITTING. INSTALL BHOSE TO CONDENSOR. EVACUATE SYSTEM. ADD 8 OZ. FREON TO SYSTEM AND LEAK CHECK CRIMPS. OK. RECOVER FREON AND EVACUATE SYSTEM FOR 45 MON. CHARGE SYSTEM WITH FREON. OPERATE A/C FOR 10 MIN. LEAK CHECK SPLICES AFTER OPERATION. (OK) INSTALL FRAME CLAMPS, TIE STRAPS AND HOSE LOOM.
14. REPLACE R ROOF CLEARANCE BULB.
15. DIAGNOSE PROBLEM WITH DOOR OPEN ALARM. FOUND BAD DOOR SWITCH ON PASSENGER DOOR. REPLACED SWITCH.
16. REPLACED L-4 DOOR OPEN BRACKET, LINK AND PIN.
17. TIGHTEN DOOR PANEL SCREWS ON ALL DOORS
18. CLEAN MOTOR.
19. ROAD TEST VEHICLE AND BURNISH BRAKES. CHECK TRANS LEVEL HOT AFTER TAKING SAMPLE. ADD 2 QUARTERS TRANS FLUID.
20. Q.C. TRUCK.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
15W40BSYN OIL BULK QTS	26
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
3744BRAKE DRUM REAR	2
42809AIR FILTER M2	1
4411S08-6962BS 90 DEGREE SB1322	1
4579S08-3422BS SPLICE	1
5008414CARTRIDGE DC100	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
K022105PURGE VALVE AD-IP-IS	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50846

In Date: 07/13/2012

Meter Reading: 115,771.10

Close Date: 08/02/2012

Problem?

diagnosis engine problem

Task performed:

REMOVE #4 CYLINDER, INJECTOR FUEL PUMP - FOUND PUMP BROKEN TURNED SIDEWAYS ON CAM AND WORE OUT CAM LOBE - THEN REMOVE #2 CYLINDER FOR FURTHER INSP. FOUND OK THEN REMOVE REMAINDER AND INSPEC ALL SIX - FOUND #6 CYLINDER ALSO WORE OUT THE CAM AND ROLLER OF FUEL PUMP.

Parts

Quantity

684-4 VALVE - FILL AIR TANK

1

Workorder: V51319

In Date: 08/02/2012

Meter Reading: 115,771.10

Close Date: 08/08/2012

Problem?

R53 AIR LEAK

Task performed:

SEVERE AIR LEAK - VEHICLE WOULD LOOSE ALL AIR IN SYSTEM IN ONE AND A HALF HOURS - CHECKOUT ALL SYSTEMS AND FOUND TWO BAD LEAKS ONE IN PRIM AIR TANK AND ALSO ONE IN SEC. AIR TANK - MAKE REPAIRS - RETEST AFTER REPAIRS - BETTER BUT STILL LOOSES ALL AIR OVER NIGHT.

Parts

Quantity

NO PARTS USED

Workorder: V51507

In Date: 08/09/2012

Meter Reading: 115,771.10

Close Date: 10/18/2012

Problem?

REPLACE ENGINE R 53

Task performed:

REPLACE ENGINE R53

Parts

Quantity

NO PARTS USED

Vendor?: FLORIDA DETROIT DIES



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53047

In Date: 10/12/2012

Meter Reading: 115,771.10

Close Date: 10/26/2012

Problem?

B INSPECTION / NO FILTERS NEW ENGINE

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. B INSP
2. REPLACE BATTERIES.
3. CHKED OUT AIR BRAKE COMPRESSOR BUILDING SLOWLY, TRACED PROBLEM TO PORIS AIR LINE FROM STEEL LINE TO DRYER. MADE NEW LINE AND INSTALLED COMPRESSOR NOW BUILDSAIR NORMALLY.
4. CHKING TRUCK OVER FOR AIR LEAKS REPLACED ALMOST ALL FITTINGS IN FOOT VALVE (LEAKING) TIGHTENING FITTING AT COMPRESSOR AND RESERVED AND FITTING ON AIR TRUCK.
5. CHK FOR POWER STEERING LEAK.
6. CONT POWER STEERING DIAG. FOUND FITTINGS TO POWER STEERING BAR LEAKING. DRAINED FLUID REMOVED FITTINGS, RESERVED AND REINSTALLED ALSO REPLACED FITTER (2 YEARS OLD).
7. CHKD PASSENGER SIDE MIRROR LOOSE AND ORDERED PARTS.
8. INSTALLED HEATER HOSE AND WIRE TIRES ON RADIATOR BLEEDER HOSE TO PROTECT AGAINST RUB THROUGH.
9. REPLACED WIPER BLADES AND SECURED PASSENGER SIDE WINDSHIELD SQUIRTER.
10. CHECKED OUT A/C WARM, FOUND SYSTEM EMPTY. WAS PROBABLY NOT CHARGED AT DEALERSHIP. VACCUMED SYSTEM HELD VACCUM OVERNIGHT CHARGED SYSTEM AND LEAK CHECKED. FOUND NO LEAKS AND SYSTEM COOLING NORMALLY.
11. REPLACED BELTS.
12. CHECKED AND ADJUSTED WHEEL END PLAY IN FRT AXLE.
13. CHKD TRANS CODES, FOUND NOT ACTIVE CODES ERASED.
14. RECIEVED PREVIOUSLY ORDERED PARTS FROM PARTS DEPARTMENT FOR PASSENGER SIDE MIRROR ASEMBLY AND INSTALLED.
15. REPLACED ROOF (CAB) MARKER LIGHT HAD REMOVE HEAD LINER PANEL TO ACCESS MOUNTING BELTS, SCAPE AWAY ALL OLD SILICONE AND REPAIR WIRE HARNESS AT PLUG CONNECTION.
16. REPLACED STREAM LIGHT CHARGER IN CAB.
17. ADJUSTED TIGHTENED AND LUBED L-2 COMPARTMENT DOOR HOLD OPEN.
18. FOUND ADDITIONAL LEAKS FOR POWER STEERING AT RES R&R RESEVIOR CLEANED CUT OFF END OF SUPPLY HOSE AND RECLAMP FILLED SYSTEM AND PURGED AIR.
19. ROAD, TESTED TRUCK TO CHK ALL LEAKS (P/S AND ENGINE) RECHECKED ALL FLUIDS, FLUIDS GOOD, FOUND NO FURTHER LEAKS.
20. REPLACED PASSENGER SIDE HEADLIGHT

01-29866-118BELT ALT. M2	1
14-15612-000GASKET RVR PWR STRG M2	1
91-22WIPER BLADE	2
A06-40578-000TOP CLEARANCE LIGHT M2	1
A06-51039-001A06-75732-005 RH HEAD LIGHT ASSY	1
A06-75732-004HEADLAMP LH M2	1
A22-58515-001MIRROR CASE	1
A22-58516-001MIRROR HEAD	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
VML/T1808D2503221C1 FILTER POWER STEERING	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

ASSEMBLY AND ORDER DRIVERS SIDE.
21. REPLACED DRIVERS SIDE HEADLIGHT.

Workorder: V53712

In Date: 11/12/2012 Meter Reading:
Close Date: 11/14/2012

Problem?
transmission fluid leak

Task performed:	Parts	Quantity
COOLANT LEAK LOOSE HOSE CLAMP TO PATIENT COMPT HEATER TIGHTENED CLAMPS AND SECURED HOSE TOP OFF COOLANT TEST OK.	NO PARTS USED	

Workorder: V53328

In Date: 10/26/2012 Meter Reading:
Close Date: 11/28/2012

Problem?
rear camera about to fall off. Rear med compartments inside of box need several new hydraulic rods to keep doors open. Rear AC not working when plugged into shore line (AC breaker not tripped).

Task performed:	Parts	Quantity
1. REPAIRED BACK UP CAM THAT WAS FALLING OFF. REPLACED DOOR PISTIONS IN REAR OF BOX AND ADJUSTED DOOR.	HLD3999GSS1715UV 30LB STRUT GAS	6

Workorder: V53338

In Date: 10/27/2012 Meter Reading:
Close Date: 11/28/2012

Problem?
roof mounted spot light over cab not working. R 53

Task performed:	Parts	Quantity
REPAIRED BAD GROUND IN LIGHT.	NO PARTS USED	

Workorder: V53896

In Date: 11/19/2012 Meter Reading:
Close Date: 12/14/2012

Problem?
Install hook for officer's radio/strap on A-post, high up by mirror to keep radio secure R53

Task performed:	Parts	Quantity
INSTALLED TOOLS IN L-1 COMPT.	NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54578

In Date: 12/23/2012

Meter Reading:

Close Date: 01/18/2013

Problem?

R53 located at the shop. rear door gets stuck and unable to open from inside of patient compartment.

Task performed:

REPAIRS DONE ON WO #54648

<u>Parts</u>	<u>Quantity</u>
15W40BSYN OIL BULK QTS	27
33936FUEL FILTER SUPTHEN	1
33965FILTER FUEL SUTPHEN	1
370120ASEAL	1
401581GASKET AXLE FL80 R002435	1
HPH6349AOIL FILTER 51748	1
PR338324070 WIX FILTER WATER	1
RWTG1234LED PRESSURE CAP	2



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54648

In Date: 12/27/2012

Meter Reading: 119,075.40

Close Date: 01/18/2013

Problem?

C inspection

Task performed:

1. C INSP
2. REPAIR R/F TIRE VALVE CORE AND REFILL TO PROPER LEVEL.
3. REMOVE REAR PATIENT DOOR PANEL AND ADJUST INSIDE HANDLE AND LATCH ASSEMBLY ADJUST DOOR NADAR PINS.
4. REPLACE A/C COMPRESSOR AND DRYER EVACUATE AND RECHARGE SYSTEM.
5. REPLACE RADIATOR ASSEMBLY.
6. PRESSURE TEST COOLING SYSTEM SYTEM TEST DRIER.
7. INSTALL WIPER BLADES INSTALL WIPER BLADES INSTALL L/F FENDER MARKER LIGHT.
8. REPLACE L/2 TOOL STRAP BRACKET.
9. TIGHTEN 02 BY-PASS KNOB.
10. REPLACE BOTH CAB A/C FITTERS AND PATIENT A/C FILTER.
11. REPLACE AUX A/C VENT.
12. REMOVE # PLATES HOLDER AND REPLACE MAKE NEW # PLATES.
13. REMOVE ACCELERATION STICKERS AND GLUE.
14. REPLACE BOTH REAR AIR BAGS ADJ LOWER ARMS AND TORQUE BOLTS.
15. INSTALL R/F CORNER CLEARANCE LIGHT.
16. REPLACE SPOT LIGHT AND SWITCH REPAIR WIRING.
17. REPAIR CENTER CONSOLE DRILL AND TAP SCREW HOLES INSTALL 1/4 SCREWS.
18. INSTALL SERPINTINE BELT.
19. TIGHTEN LINES TO P/S PUMP CLEAN OFF OIL AND TEST.
20. LIFT TRUCK PUT ON JACK STANDS FOR TIRE GUY.
21. Q.A INSP.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
01-29866-118BELT ALT. M2	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
16-15762-00016-19471-000 AIR BAG	2
1878042C91FUEL FILTER 2008 HORTON	1
194-ABULB	4
2506656C124316 WIX CAB A/C FILTER	1
297518265/70R19.5 BRIDGESTONE R250	6
426089HOSE& FITTING ASSY	1
533303-0609 A/C COMPRESSOR M2 4485	1
5774457744XD OIL FILTER	1
719707-0614AAC DRIER M2	1
72R31001720 DIFFUSER A/C 3.5 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
8201L17-3428 ESTER OIL E7	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A18-44184-001COVER PILLAR POST R/H	1
AMH-1AMH-1 VALVE EXTENSION	1
C1673FRE04 RADIATOR	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	2
E-600013-3052 NUT	6
H9SPOT LIGHT BULB	1
HAN-1LBEZEL AND HANDLE	1
L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1
RWTG1234LED PRESSURE CAP	6
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	2
VML/T1808D2503221C1 FILTER POWER STEERING	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55105

In Date: 01/16/2013

Meter Reading: 119,075.40

Close Date: 01/22/2013

Problem?

Replace all tires [Labor only]R53

Task performed:

Parts

Quantity

REPLACE ALL TIRES (LABOR ONLY) R53.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V55465

In Date: 02/01/2013

Meter Reading: 120,206.40

Close Date: 02/22/2013

Problem?

INTERIOR DRIVER SIDE DOOR HANDLE LOOSE.

Task performed:

Parts

Quantity

REPAIRED HANDLE AND REPAIRED DOOR PANEL

NO PARTS USED

Workorder: V55928

In Date: 02/22/2013

Meter Reading: 121,439.60

Close Date: 02/25/2013

Problem?

Coolant leak

Task performed:

Parts

Quantity

R&R COOLANT TANK AND TEST DRIVE FOUND LEAK AT COOLAN LEVEL SENSOR PUT NEW O-RING ON SENSOR.

05-23195-000Z05-30740-000 SURGE TANK

1

Workorder: V56632

In Date: 03/25/2013

Meter Reading: 124,369.60

Close Date: 04/10/2013

Problem?

SHORELINE TO RESCUE OVER HEATING AND THE TIP OF PLUG IS MELTED/BURNT. R53

Task performed:

Parts

Quantity

REMOVED AND REPLACED PLUG.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56964

In Date: 04/11/2013

Meter Reading: 125,292.00

Close Date: 04/16/2013

Problem?

pat. a/c inop, R-53

Task performed:

1. vehicle came to s/shop, replace pat. a/c compressor per Tommy, (clutch slipping) remove air filter assy, evecaute system, remove a/c belt, remove and install new compressor, vac. down system and recharge, clutch still slipping, check gauges found system going into vac. on low side, put unit back in service till next day. (vehicle left shop at 5:30 cool outside)
2. bring unit back to s/shop, evecaute system, high side line frozen in expansion valve, had to work free without breaking line, remove hoseline a/c unit from pat. compt. found dryer dessiant bag broke in system, expansion valve and hoses were clogged, remove all a/c lines and flush out system, and bottom condensor, install new expansion valve, dryer, thermostat switch, and all O rings, reinstall hoseline unit back in pat. compt. evacuate system and recharge, cools down to 29deg. and compressor operates normal

Parts

Quantity

088319-007165 DRYER	1
160012-2012A EXPANSION VALVE 71R8301	1
5790COMPRESSOR A/C	1
71R31001331 THERMOSTAT A/C	1
EL35675BLACK DIODE PLUG DT04-49-RT01	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1

Workorder: V56633

In Date: 03/25/2013

Meter Reading: 124,369.60

Close Date: 04/26/2013

Problem?

Can mech install hook on the passeneger side A post, inside panel, to hold officer's radio? R 53

Task performed:

1. AUTO EJECT INOP - REPAIRED BAD CONNECTION.
2. REPLACE LATCH FOR STRETCHER.

Parts

Quantity

090-0278STRECHER BAR NEW	1
0915520120AUTO EJECT 20 AERO OTL3925	1
UMVS056511STRAP	20
UMVS111611STRAP	20

Workorder: V56143

In Date: 03/04/2013

Meter Reading: 122,595.00

Close Date: 05/03/2013

Problem?

REPLCE WINDOW REGULATOR PREVIOUSLY ORDERED R 53

Task performed:

REPAIRED WINDOW THAT WAS NOT GOING UP.

Parts

Quantity

A18-58283-000WINDOW REGULATOR L/H A18-42743-000	1
---	---



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58477

In Date: 06/17/2013
Close Date: 06/17/2013

Meter Reading: 127,221.00

Problem?

involved in an accident

Task performed:

FRONT TIRE BENT ROAD TESTED SWAPTED OUT.

Parts

NO PARTS USED

Quantity

Workorder: V57923

In Date: 01/01/1900
Close Date: 06/20/2013

Meter Reading: 127,221.00

Problem?

Tow to FDDA FT Pierce ENG oil cooler [Warranty]

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V58711

In Date: 06/26/2013
Close Date: 06/27/2013

Meter Reading: 127,221.00

Problem?

Quality check [back from FDDA] Cab a/c warm

Task performed:

1. Q & A.
2. AIR R/F TIRE TO 120 PSI AND REPLACED SENSOR.
3. REPLACE ROOF CLEARANCE LIGHT. REMOVE HEADLINER GLOVE BOX TO ACCESS LIGHT FASTENERS. SEAL NEW ASSEMBLY WITH SILICONE.
4. DIAGNOSE CAB A/C WARM - FOUND FREON LOW. LEAK CHECK SYSTEM - FOUND HOSE AT CONDENSER LEAKING. RECOVER FREON. MAKE UP HOSE AND REPLACED VACUUM SYSTEM AND CHARGE.

Parts

4411S08-6962BS 90 DEGREE SB1322
 4503SFITTING AC
 A06-40578-000TOP CLEARANCE LIGHT M2
 RWTG1234LED PRESSURE CAP
 VCC/36000006A/C FILTER CAB M2

Quantity

1
1
1
1
1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57836

In Date: 05/20/2013

Close Date: 07/03/2013

Meter Reading: 127,221.00

Problem?

B inspection R53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. B-INSPECTION.
2. REPLACED BATTERIES.
3. DIAGNOSE NO WINDSHIELD WASHERS. FOUND BOTH WASHER TUBES KINKED. UNKINK HOSES AND POSITION NOZZELS. TEST LEFT OK, NO RIGHT BLOW OUT RIGHT SIDE AND TEST BETTER BUT NOT CORRECT. REPLACED RIGHT NOZZEL AND BRACKETS. TEST OK.
4. REPLACE WIPER BLADES.
5. EXHAUST CLAMP AT FLEX PIPE NOT PROPERLY CLAMPED. REPLACE CLAMP AND POSITION CORRECTLY. TIGHTEN CLAMP.
6. REPLACE RESERVOIR CAP FOR WINDSHIELD WASHER.
7. DIAGNOSE LOW AIR LRO TIRE - FOUND LEAKING VALVE STEM EXT. HOSE TIGHTEN HOSE AND AIR TO 120 PSI.
8. REPLACE 4 TIRE PRESSURE SENSORS.
9. CLEAN REAR A/C FILTERS. STRAIGHTEN BENT FILTER CLAMP.
10. FIRE EXTINGUISHER LOOSE ON BRACKET. BENT BRACKET TO TIGHTEN BRACKET CLAMPING.
11. REAR PATIENT DOOR HARD TO OPEN - FOUND STRIKER PLATE BENT UP AND LOOSE. STRAIGHTENED PLATE AND SECURED SCREWS. LUBRICATE LATCHES.
12. DIPSTICK FOR TRANS RESTING ON STEERING SHAFT. LOOSENED CLAMPS AND TRIED TO REPOSITION DIPSTICK TUBE. DIPSTICK NOW NOT INTERFERING WITH STEERING SHAFT BUT NOT CORRECT. CHECK WITH PARTS DEPT. FOUND TUBE TO BE WRONG ONE FOR VEHICLE. ORDERED CORRECT TUBE.
13. EXHAUST LOOSE AT TURBO. REMOVE AIR FILTER HOUSING AND HEATER HOSES. POSITION CLAMP ON TURBO AND TIGHTENED REINSTALL REMOVED PARTS. TEST OK.
14. TIGHTEN TRANS COOLER LINE BRACKET CLAMPS AND POSITION TO KEEP FROM RUBBING ON HOSES AND METAL.
15. SECURE LOOSE WIRING AND BLOCK HEATER CABLE.
16. BRACKET HOLDING WATER PUMP TUBE TO BLOCK MISSING ONE BOLT. ORDERED BOLT B-29.30
17. TIGHTEN BOLT HOLDING A/C LINE CLAMP.
18. REPLACE MELTED AND MISSING WIRE AND HOSE LOOM. CONNECT DISCONNECTED AIR FILTER RESTRICTION SENSOR WIRE TIE UP A/C CLUTCH WIRING AND DIODE.
19. HOSE LAYING ON A/C BRACKET WITH CUT MARKS. DRAIN COOLANT, REPLACED HOSE AND REFILL COOLANT.
20. P/S LEAK AT RESERVOIR HOSE. REMOVED AIR

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	2
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	2
05-23281-001COOLANT HOSE ECR	1
20A-400CLAMP 4" 33969	1
22-58581-000WASHER RESIVOR CAP	1
23-13301-412COMPRESSOR FITTING	1
906-181-00-86OIL FILTER M2 SPINNER 57140	2
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
RWTG1234LED PRESSURE CAP	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	2
TRI-F98999-225NOZZLE KIT	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

INTAKE HOSE AND RESERVOIR. REPLACED CLAMP AND TIGHTENED REINSTALL RESERVOIR. FILL RESERVIOR AND INSTALL INTAKE HOSE BLEED SYSTEM OF AIR.

21. RELOCATE HOSE FROM RADIATOR TO EXPANSION TANK. SECURE AND PROTECT HOSE.

22. DIAGNOSE VARIOUS AIR LEAKS - FOUND DRAIN FITTING FOR TANK LOOSE AND LEAK AT FITTING FOR AIR HORN SOLENOID. TIGHTEN DRAIN VALVE AND REPLACED FITTING FOR AIR HORN - FOUND BAD FITTING ON AIR COMPRESSOR. REMOVE DISCHARGE LINE AND REPLACED FITTING. INSTALL DISCHARGE LINE AND RETEST (OK).

23. Q & A VEHICLE.

24. INSTALL MISSING BOLT IN COOLANT HOSE CLAMP TO ENGINE BRACKET.

Workorder: V58914

In Date: 07/08/2013

Meter Reading: 127,879.60

Close Date: 07/11/2013

Problem?

coolant leak

Task performed:

FOUND HEATER HOSE BLOWN REPAIRED HOSE WITH NEW FILLED WITH COOLANT RETURNED TO SERVICE.

Parts

NO PARTS USED

Quantity

Workorder: V58917

In Date: 07/08/2013

Meter Reading: 127,879.60

Close Date: 07/19/2013

Problem?

R53 shoreline not ejecting when truck starts. Eject piston inside socket on rescue appears to have lost it's spring action. R53

Task performed:

1. REPAIRED SHORELINE - PLUG THAT WAS NOT EJECTING OUT.

2. REPAIRED 110 A/C UNIT DRAIN LINE.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59962

In Date: 08/21/2013

Meter Reading: 130,137.50

Close Date: 08/26/2013

Problem?

replace front tires

Task performed:

Parts

Quantity

REPLACE FRONT TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE CENTE

Workorder: V59998

In Date: 08/23/2013

Meter Reading: 130,294.00

Close Date: 08/26/2013

Problem?

front AC blowing warm

Task performed:

Parts

Quantity

WENT TO 53 RAN CAB A/C CHECK OK FILLED SYSTEM THE DAY BEFORE.

NO PARTS USED

Workorder: V59922

In Date: 08/20/2013

Meter Reading: 130,104.00

Close Date: 08/30/2013

Problem?

The front tires of R53 are wearing on the outside edges and will need to be replaced soon. Please check.

Task performed:

Parts

Quantity

NEED TO REPLACE TWO TIRES.

NO PARTS USED

Workorder: V59997

In Date: 08/23/2013

Meter Reading: 130,294.00

Close Date: 09/16/2013

Problem?

emergency LED light not working on rear left side of back bumper

Task performed:

Parts

Quantity

ALL LED LIGHTS INOP - TRACED OUT PROBLEM AND FOUND BAD CONNECTION, REPAIRED CONNECTION AND RETESTED.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59999

In Date: 08/23/2013

Meter Reading: 130,294.00

Close Date: 09/16/2013

Problem?

Install hook for officer's radio on the "A" post in the front right side of crew cab. Install hook higher than the handle that is there.

Task performed:

Parts

Quantity

INSTALL TOOLS IN L-1 REMOUNTED TOOLS IN L-1 COMPARTMENT.

NO PARTS USED

Workorder: V60376

In Date: 09/08/2013

Meter Reading: 131,059.30

Close Date: 09/16/2013

Problem?

rear tires need to be replaced R53

Task performed:

Parts

Quantity

ALL FOUR REAR TIRES NEED TO BE REPLACED.

NO PARTS USED

Workorder: V60560

In Date: 09/17/2013

Meter Reading: 131,667.00

Close Date: 09/18/2013

Problem?

Rear tires worn

Task performed:

Parts

Quantity

REAR TIRES WORN

56415CIG. LIGHTER ACCES.

4

BPR6ESSPARK PLUG 7131

4

Vendor?: BOULEVARD TIRE CENTE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60643

In Date: 09/20/2013
Close Date: 09/24/2013

Meter Reading: 132,017.60

Problem?

Pt compartment A/C unit is still leaking water onto the pt's

Task performed:

1. TEST DRIVE CHECK FOR NOISE COMING FROM REAR DRIVER THINKS IS COMING FROM BRAKES FOUND R REAR INNER TIRE LOW ON AIR 20 PSI LEAKING ON SCREEN HOSE RR HOSE AIR UP IS OK
2. CHECK A/C PT COMPARTMENT FOUND UNIT HAD A BROKEN BOLT TO BRAKE REMOVE AND REPLACE UNIT RESEAL, BOOT AND TEST FOR OPERATION IS GOOD NOW.

Parts	Quantity
435 VALVE CAP	2
63152HVAC UNIT ROOF MOUNTED	1
AMH-1AMH-1 VALVE EXTENSION	1

Workorder: V60527

In Date: 09/16/2013
Close Date: 10/10/2013

Meter Reading: 131,667.00

Problem?

rear top mount AC unit leaking water all over stretcher when plugged into shoreline. Drain line possibly clogged

Task performed:

WATER LEAK A/C UNCLOGGED DRAIN TO A/C UNIT WILL MONITOR IF STILL LEAKING.

Parts	Quantity
NO PARTS USED	

Workorder: V60575

In Date: 09/18/2013
Close Date: 10/10/2013

Meter Reading: 131,928.00

Problem?

Passenger side rear brakes are making noise under braking.

Task performed:

REPAIRED DRAW LATCH - THAT WAS BROKEN REMOVED AND REPLACED.

Parts	Quantity
LTC5993SSM1-63-8 LATCH STAINLESS	4

Workorder: V61449

In Date: 10/22/2013
Close Date: 11/04/2013

Meter Reading:

Problem?

Radiator support bar/bracket hanging freely. Needs to be bolted to frame support. AT John is aware. R53

Task performed:

1. SUPPORT BRACKET MISSING BOLD, INSTALLED NEW BOLT IN SUPPORT BRACET.

Parts	Quantity
NO PARTS USED	



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61466

In Date: 10/22/2013

Meter Reading:

Close Date: 11/04/2013

Problem?

Both tire pressure sensor caps are flashing red on the driver's side rear tires. E53

Task performed:

Parts

Quantity

FILL TIRES AND INSTALLED NEW VALVE STEM SENSORS.

NO PARTS USED

Workorder: V61551

In Date: 10/27/2013

Meter Reading:

Close Date: 11/08/2013

Problem?

multiple LED ground lights not working under R53. 7 total R53

Task performed:

Parts

Quantity

REPAIRED GROUND LIGHTS THAT WERE OUT TOTAL LIGHT OUT WERE TWO.

607141-05USE 61H01 COPMPARTMENT LIGHT

7

Workorder: V62070

In Date: 11/16/2013

Meter Reading:

Close Date: 11/25/2013

Problem?

Low coolant in engine, oil level is a little low as well R53

Task performed:

Parts

Quantity

LOW ON COOLANT- REPAIRED SMALL LEAK.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V62416

In Date: 12/02/2013

Close Date: 01/03/2014

Meter Reading: 136,353.80

Problem?

C inspection R53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. C INSP.
2. R-SIDE W/WASHER WASHER HOSE BROKEN INSIDE WIPER ARM- PULL OUT BROKEN PIECES AND INSTALL NEW HOSE.
3. L-SIDE DASH- CHECK OUT PROBLEM W/ L/SIDE OF DASH BOARD-VERY LOOSE- DISASSEMBLE AND FOUND MANY OF SCREW SECURING TAPS BROKEN-CHECK W/ PARTS DEPT ON AVAILABILITY OF REASSEMBLE DASH.
4. DRIVERS SEAT BACK CUSHION ON DRIVERS SEAT HAS SPRING POKING THROUGH MATERIAL- REMOVE TO BE TAKEN TO OUTSIDE VENDER- REINSTALL BACK SEAT CUSHION- NOTE; NEW BOLTS NEEDED TO BE INSTALLED AND SOME MODIFICATIONS WERE NEEDED.
5. A/C AIR FILTERS, REMOVE ALL A/C AIR INTAKE FILTERS.
6. LT. LENSES BUFF OUT BRAKE TURN TAIL BACK UP TWO REAR EMERG AND TWO FRONT EMERG LT LENSES FOR CLARITY.
7. COMPT L/2 DOOR LT- L/2 COMPT 2ND DOOR RED FLASHING WHEN DOOR IS OPEN WAS PUSHED INSIDE OF DOOR- REMOVE DOOR PANEL FETCH FIXTURE AND REINSTALL IN PANEL- REINSTALL PANEL IN DOOR.
8. TIRE INFLATION KITS-BOTH SIDES REAR TIRES NEED AIR INFLATION KITS INSTALLED IN-ORDER TO CHECK AND INSTALL AIR INSTALL KITS BOTH SIDES
9. CAB A/C SYSTEM-BOTH FRONT AND BACK A/C ONLY BLOW COOL- CHECK OUT SYSTEM AND FOUND CONDENSOR FANS BAD ONLY HALF SPEED AND OTHER DOSENT WORK AT ALL, REPLACE BOTH FAN AND MOTOR ASSEMBLIES.
10. STEERING COLUMN- STEERING COLUMN MOVES ALL OVER-REMOVE ALL PLASTIC SHROUDING TO CHECK OUT PROBLEM-FOUND THE TILT PIVOTS COMPLETELY WORN OUT- CHECK W/ PARTS ON AVAILABILITY- AHD ON THAT WAS ORDERED FOR ANOTHER VEHICLE- USED IT- TRANSFER ALL NECESSARY PARTS AND INSTALL- NOTE ALOT OF THE SHROUDING WAS BROKEN- NO PARTS AVAILABLE.
11. MUD FLAP-R/REAR MUD FLAP MISSING-CUT TO SIZE A NEW MUD FLAP- PUNCH OUT MOUNTING HOLES AND INSTALL NEW FLAP.
12. WIPER BLADES- REPLACE WORN OUT WIPER BLADES.
13. COMPT 5 DOOR LATCH PATIENT AREA COMPARTMENT 5 DOOR LATCH VERY HARD TO CLOSE- READJUST LATCH ASSEMBLY TO LATCH FREELY.
14. WIPER MOTOR- WIPERS COME ON BY THEMSELF- EVEN WHEN SWITCH IS IN THE OFF POSITION- REPLACE WIPER SWITCH ASSEMBLY.

0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
09-3210SHELL CRIMP 4270	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
2FC00ZCR4 IN ROUND LED	2
330-3024HUB COVER GASKET	2
3744BRAKE DRUM REAR	2
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
91-22WIPER BLADE	2
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1
A14-12612-002STEERING WHEEL M2	1
A23102Z3458TIE ROD ASSBY M2	1
A9061840408SPINNER OIL FILTER COVER M2	1
AMH-1AMH-1 VALVE EXTENSION	1
B2420LP-SMUD FLAP 24 X 24	1
E-600013-3052 NUT	6
GC2430XLLONG STROKE BRAKE CHAMBER	2
K022105PURGE VALVE AD-IP-IS	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHOE KIT	2
R802446AUTO SLACK ADJ	1
R802447AUTO SLACK ADJ	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S4640024430VALVE LEVELIN	2
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



10/29/2021

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

15. UNDER TRUCK LTS- SEVERAL OF THE UNDER TRUCK LTS BRACKETS ARE VERY LOOSE- ALMOST FALLING OFF- FIRST STRAIGHTEN BENT UP BRACKETS- MANY OF THE SCREWS STRIPPED OUT- REPAIR ALL TO BE SECURELY FASTENED.

16. SERV AIR DRYER.

17. STEERING PULLS TO RIGHT- TIE ROD ENDS WERE FROZEN IN TUBE- REMOVE ENTIRE TIE ROD. AFTER SOAKING TUBE IN RUST DESLOVERS, USED NEW ENDS TO CLEAN UP TUBE- ANTI SEIZE ALL THREADS- INSTALL IN VEHICLE AND ADJUST TOE.

18. WHEEL BEARINGS- REMOVE CAPS ON FRT WHEEL BEARING AND READJUST BEARING PRE-LOAD.

19. POWER/STEERING SERVICE POWER STEERING UNIT.

20. AIR LEAK-FOUND SERVERAL FITTINHGS ON AIR TANKS LEAKING, REPLACE PUSH ONS W/ COMPRESSION TYPE FITTINGS.

21. REAR SUSPENSION LOOSEN U-BOLTS HOLDING REAR SUPPORT FROM UNDER AIR BAGS- OVER SUSPENSION ARMS UNITL AIR BAGS SET UP STRAIGHT- TIGHTEN ALL U-BOLTS AND TORQUE TP SPECT.

22. AIR RIDE SUSPENSION- INSTALL NEW AIR BAG HEIGHT SENSING VALVES- MAKE UP ALL NEW RODS AND SET ADJUSTMENTS TO PROPER LENGTHS.

23. REAR BRAKES- REPLACE ALL BRAKE COMPONENTS- ONE SHOE WAS NEVER FIFNISHED BEING MACHINE FROM FACTORY. REMOVE SHOE AND REINSTALL ANOTHER NOW ALL IS OK. FINISH BRAKE JOB.

24. Q.A TRUCK.

Workorder: V60766

In Date: 09/24/2013

Meter Reading: 132,017.60

Close Date: 01/21/2014

Problem?

REPLACE TRANSMISION DIPSTICK R53

Task performed:

REPAIRES COMPLETED.

Parts

Quantity

A07-18904-002DIP STICK ASSY

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64134

In Date: 02/11/2014

Meter Reading:

Close Date: 03/12/2014

Problem?

Spot light out

Task performed:

Parts

Quantity

1. REPAIRED CONTROLLER FOR SPOT LIGHT.

NO PARTS USED

Workorder: V64270

In Date: 02/17/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

Spot light is out on the top of the rescue R53

Task performed:

Parts

Quantity

REPAIRED BAD GROUND WIRE IN LIGHT.

NO PARTS USED

Workorder: V64452

In Date: 02/22/2014

Meter Reading:

Close Date: 03/19/2014

Problem?

Spot light not working. Need it repaired R53

Task performed:

Parts

Quantity

REMOVED AND REPLACED CONTROLLER.

NO PARTS USED

Workorder: V65217

In Date: 03/25/2014

Meter Reading: 143,115.00

Close Date: 03/26/2014

Problem?

Replace rear tires

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65315

In Date: 03/31/2014

Meter Reading:

Close Date: 04/03/2014

Problem?

All tires replaced a few days ago. Truck now has whinning noise that gets loud during acceleration.

Task performed:

Parts

Quantity

REPAIRS DONE ON WORK ORDER #65336.

NO PARTS USED

Workorder: V65336

In Date: 03/31/2014

Meter Reading:

Close Date: 04/03/2014

Problem?

The Rescue 53 is making a loud squeeling noise when excelerating and at idle. Sound is getting progressively worse the past 3 days. Not sure if it is a belt, but it is getting louder.

Task performed:

Parts

Quantity

TRAVEL TO STATION CHECKED TRUCK VISUAL OK TEST DROVE TRUCK DOES HAVE WHINE FROM DRIVE DRAIN TRANSMISSION FLUID HIGH AAND DISEALED BROUGHT CREW TO SHOP SWAPPED OUT.

NO PARTS USED

Workorder: V65400

In Date: 04/02/2014

Meter Reading: 143,577.00

Close Date: 04/03/2014

Problem?

CHECK TRANSMISSION R 53

Task performed:

Parts

Quantity

CHECK TRANS FLUID- FOUND IT OVER FULL AND DARK COLOR CHECKED FOR CODES (NONE) ROAD TEST VEHICLE- WHINE FROM TRANS TO BE TOWED TO ALLISON

NO PARTS USED

Workorder: V65250

In Date: 03/27/2014

Meter Reading:

Close Date: 04/08/2014

Problem?

REAR TIRES MOUNTED SEVERAL DAYS AGO, FRONT TIRES WERE NOT DONE, SPOKE WITH TOMMY, HE SAID HAVE 2 FRONT TIRES MOUNTED.

Task performed:

Parts

Quantity

REAR TIRES MOUNTED SEVERAL DAYS AGO, FRONT TIRES WERE NOT DONE, SPOKE WITH TOMMY, HE SAID HAVE 2 FRONT TIRES MOUNTED.

NO PARTS USED

Vendor?: BOULEVARD TIRE



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65084

In Date: 03/21/2014

Meter Reading:

Close Date: 04/17/2014

Problem?

ALL TIRES and REAR BUMPER WELD COMING APART.

Task performed:

Parts

Quantity

REPLACED REAR TIRES.

NO PARTS USED

Workorder: V65409

In Date: 04/02/2014

Meter Reading: 143,577.00

Close Date: 04/30/2014

Problem?

REBUILD TRANSMISSION

Task performed:

Parts

Quantity

REBUILD TRANSMISSION

NO PARTS USED

Vendor?: FLORIDA DETROIT



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65564

In Date: 04/08/2014

Close Date: 05/01/2014

Meter Reading: 143,577.00

Problem?

B inspection R53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. B-INSP.
2. DIAGNOSE LEAKS ON REAR OUTSIDE TIRES. FOUND GASKETS FOR EXT BAD. REPLACED EXTENSIONS AIR ALL TIRES TO 120 PSI.
3. REPLACE BATTERIES.
4. REMOVE AUX AND REAR PATIENT COMPT A/C FILTERS CLEAN FILTERS AND REINSTALL.
5. REPLACE TOOL BRACKETS IN L-2 COMPT.
6. REPLACE REAR NADAR PIN COVERS . DRILL HOLES IN NEW COVER. REPAIR TREADS ON RIGHT COVER BOLT HOLES.
7. REPLACED LEFT PATIENT COMPT. DOME LIGHT BULB.
8. L/FRT GROUND LIGHT DAMAGED. REPLACED GROUND LIGHT FRAME. DRILL AND THREAD NEW HOLES.
9. TORQUE ALL U-BOLTS.
10. TIGHTEN P/S DRAIN PLUG. CLEAN AREA OF OIL.
11. TIGHTEN TRANS COOLER LINE. CLEAN AREA OF OIL.
12. P/S PUMP OIL. CLEAN AREA OF OIL. CHECK BOLTS FOR TIGHTNESS.
13. TIGHTEN ALL COMPT DOOR FASTNERS.
14. DRILL AND INSTALL NUTSERCT IN L-2 DOOR FOR COAT HOOK. INSTALL NEW BOLT.
15. EXHAUST COVERS LOOSE, TIGHTEN CLAMPS.
16. WINDSHIELD WASHERS INOP. FOUND BROKEN TEE PLUGGED WASHER NOZZLES AND WASHER HOSE KINKED. REPLACED TEE REMOVE BROKEN PIECES FROM HOSES. CLEAN NOZZLES AND REPOSITION SQUIRTERS NOZZLE ON LEFT SIDE. SECURE NOZZLE AND HOSES. FILL RESEVOIR.
17. REAR TAIL BOARD SWING STEP WELDS BROKEN. DRILL AND TAP HOLES CLEAN HOLES AND INSTALL SCREWS WITH MEDIUNM LOCK TIGHT.
18. LUBRICATION. CHECK MOTOR MOUNTS DRIVE SHAFT PHASE WEIGHTS TRANS MOUNTS CENTER BEARING. ROAD TEST VIBRATION AT 45 MPH THEN AT 65-75 MPH. CHECK TOE 1/4 TOE OUT NO GOOD.
19. SET TOE AND ROAD TEST VEHICLE. WHEEL BALANCE PROBLEM PRONOUNCED AT 70-75 MPH. ACCEPTABLE AT THIS TIME PER JOHN M. AND STEVE.
20. P/S LEAK AT PUMP GEAR BOX PLUG AND TRANS COOLER LINE TIGHTENED LINE AND PLUG FOUND P/S SUCTION LINE CLAMP AREA. REMOVE PUMP. REPLACED CLAMP TEST NO GOOD. TRIED ANOTHER TYPE OF CLAMP.L NO GOOD DRAIN FLUID REPLACED HOSE R&R RESEVOIR INSTALL COMPONENTS.
21. Q.C TRUCK.
22. BLEED P/S SYSTEM REATTACH COOLANT HOSES FILL RESEVOIR AND PRESSURE CHECK SYSTEM. TIGHTEN LEAKING LOWER HOSE CLAMP.

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
322502BULB PATIENT GH22	1
5269LPVM-5 SM MOUNT	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTERY	4
HP-31DBATTERY 950CCA HP-31D	4
L2643655P/S HOSE 3/4	4
MFG01876GROUND LT BRACKET	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

INSTALL ELECTRICAL BRACKETS AND CLAMPS
INSTALL CLAMP FOR TRANS COOLER LINES
INSTALL LOOM OVER P/S SUCTION HOSE AND SECURE WITH TIE STRAPS
WASH DOWN ENGINE AND INSPECT P/S PUMP FOR LEAKS OK.

Workorder: V66135

In Date: 05/01/2014 Meter Reading: 143,577.00
Close Date: 05/07/2014

Problem?

A/C not cooling

Task performed:

TROUBLESHOOT A/C FOUND 5-15 21LBS OVER CHARGED REMOVED LEAKING LINES AND DRIER, INSTALL NEW LINES AND DRIER.

Parts	Quantity
071601A07-0602A DRIER A/C 7118	1
468282HOSE & FITTINGS	1

Workorder: V67013

In Date: 06/06/2014 Meter Reading:
Close Date: 06/09/2014

Problem?

Per Tommy, a SCBA bracket mount needs to be installed in the driver's compartment on R53. Prefer the back wall inside the compartment.

Task performed:

move helmet hook put together scba bracket, install on back wall of L-2 compt. reinstall helmet hook

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MERCED	1
101-124-000CRASH RESTRAINT STRAPS	1
44-US07RRADIO ANTENNA	1
FHLP-6TANK CLIP	2
KD-UN-6-SFBRACKET	1

Workorder: V66937

In Date: 06/03/2014 Meter Reading: 145,887.90
Close Date: 06/18/2014

Problem?

Side door inop for patient compt

Task performed:

side door inop, replaced broken door handle.

Parts	Quantity
284-0863REAR DOOR HANDLE R/H HORTON	1
284-0864HANDLE REAR DOOR L/H HORTON	1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66890

In Date: 05/31/2014

Meter Reading:

Close Date: 06/23/2014

Problem?

latch broken on officer side pt compartment door

Task performed:

repaired latch and door spring

Parts

NO PARTS USED

Quantity

Workorder: V67509

In Date: 06/27/2014

Meter Reading: 147,224.10

Close Date: 07/07/2014

Problem?

Cab a/c inop

Task performed:

- CHECKED OUT REAR CAB A/C INOP. INTERMITTENTLY COULD NOT REPRODUCE CONCERN. REMOVED EVAP FRT COVER CHECKED RESISTER, CONNECTIONS AND SWITCHES, FOUND NO PROBLEMS. REASSEMBLED. RESERVED AND RECHARGED SYSTEM.
- REPLACED GLOVE BUTTER IN CAB (BROKEN).
- SECURED DRIVERS SIDE DASH WITH SCREWS AND WASHERS (BROKEN/RATTLING).
- INSTALLED RUBBER INSULATOR UNDER REAR ENTRY FOLD UP STEP (BANGING AND WEARING).

Parts

78R536078R5360M 2PK FILTER AIR COND

Quantity

1

Workorder: V67689

In Date: 07/05/2014

Meter Reading:

Close Date: 07/07/2014

Problem?

R53 running taillights are out. break lights are in working order running lights in rear are out.

Task performed:

Traced out problem with tail lights and marker lights, needed to swap out.

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67747

In Date: 07/08/2014

Meter Reading: 147,576.50

Close Date: 07/10/2014

Problem?

maker lites inop, on pat. box, cab a/c inop R-53

Task performed:

1. check for no marker and tail lites, work with steve r on wiring schematic, trace wiring from body module to rear of vehicle, found wire cut on r/side rear inner frame rail, reconnect wire and reroute wire harness.
2. check cab /ac found rear cab red dot a/c blower motor inop ,remove red dot assy. and replace blower motor, check freon found low, add and check for leak, found both schrader valves leaking, replace both valves recheck for leak, non found at this time

Parts

Quantity

73R4422BLOWER MOTOR

1

FRT V67259FREIGHT CHARGE

1

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 110 A/

1

Workorder: V68289

In Date: 07/30/2014

Meter Reading:

Close Date: 08/01/2014

Problem?

R53 battery light on. A/C malfunctioning in cab

Task performed:

- 1.Remove and replace ALT. we had to recover AC system to move compressor and recharge AC system.
- 2.Assist.

Parts

Quantity

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V68341

In Date: 08/01/2014

Meter Reading: 148,786.30

Close Date: 08/05/2014

Problem?

Wont start

Task performed:

No start. Lost prime. Checked and tightened fuel lines at seperator. Started , tested ok.

Parts

Quantity

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68740

In Date: 08/17/2014

Meter Reading: 149,578.20

Close Date: 08/19/2014

Problem?

ON CALL OVERHEATING R53

Task performed:

Parts

Quantity

Went to station. Found air line to fan clutch fitting broken off installed new fan clutch.

HOR/991450HT 650 FAN ASY.

1

Workorder: V69069

In Date: 08/30/2014

Meter Reading:

Close Date: 09/19/2014

Problem?

fluid leaking from under dash. R53

Task performed:

Parts

Quantity

FOUND COOLANT LEAK REPAIRED LEAK AND ROAD TESTED.
REPAIRED REAR DOOR LATCHES THAT WAS HARD TO OPEN.

NO PARTS USED

Workorder: V69600

In Date: 09/23/2014

Meter Reading: 151,078.00

Close Date: 10/30/2014

Problem?

A/C motor in rear of cab is malfunctioning.

Task performed:

Parts

Quantity

Tested unit and repaired fan motor that was making noise

NO PARTS USED

Workorder: V70320

In Date: 10/21/2014

Meter Reading: 152,077.30

Close Date: 10/31/2014

Problem?

The cage that hold the electronics in the drivers side compartment where the tools and SCBA are stored has lost it weld holding it on the front side and no hangs occasionally.

Task performed:

Parts

Quantity

1. Repaired cage in L1 compartment.

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69664

In Date: 09/24/2014

Close Date: 12/03/2014

Meter Reading: 151,078.00

Problem?

C inspection R53

Task performed:

Parts

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

1. C Inspection.	000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT	1
2. C Inspection.	0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH	1
	032-0116549297 BATTERY INDICATOR	1
3. R & R cab auxilliary A/C. R & R patient A/C filter. Replace missing screws on filter access panel. No screws in Parts Dept. Had to use general hardware.	0775145PANEL FILTER	1
	15W40BSYN OIL BULK QTS	26
	16-15762-00016-19471-000 AIR BAG	2
4. R & R and wash 110V A/C unit filters.	194-ABULB	1
	23-12982-712COVER SCREW	1
5. Trip panels on steering column loose. Hardware missing. Upper half broken. Ordered.	23-12982-770COVER SCREWS M2	1
	31000005HEATER CORE M2	1
6. R & R wiper blades.	4070091740 GROMMET T/L 4 IN	1
	61H01LED GROUND LITE CLEAR	3
7. Repair Power steering leak at hose assembly. Wash area and recheck for leak.	78R536078R5360M 2PK FILTER AIR COND	1
	906-181-00-86OIL FILTER M2 SPINNER 57140	1
	91-22WIPER BLADE	2
8. R & R battery charger status indicator panel.	A22-57853-000UPPER COVER M2	1
9. Check olygen bypass valve operation. Indicator says off when valve on. Reset indicator to correct position.	ANTICOOLANT ANTIFREEZE GAL	1
	FRT 65616FREIGHT CHARGE	1
10. Repair 4 F fender marker light out.	S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
	UVAPS253 UNIT UV LIGHT A/C RESCUES	1
11. Remove driver's seat. Remove seat in patient area. Send for upholstery repair.	UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
	VCC/36000006A/C FILTER CAB M2	1
12. Repair windshield washer system. Repair driver's side hose and nozzle.		
13. Re-install driver's seat and seat in patient compartment.		
14. Drill and tap holes for new R/F guard light bracket. Install and wire light assembly and isolator. Also R & R 2 other defective ground lights.		
15. R & R 2 rear air bags. Check for leaks. R & R air fittings. Both leaked.		
16. LED panel for battery charger out again. Test LEDs - OK. Test charger on output - OK. Test new panel at charger term strip - no good. Needs new battery charger.		
17. 2 transmission codes. Check with laptop. Diagnose engine speed sensor code. Check wiring and sensor. Check second code. Check all transmission electric connectors, pins and sockets.		
18. Start removal of heater core. Drain coolant. Cut heater box. Move center ambulance console. Remove heater core.		



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

19. Finish heater core. R & R. See above.

20. Quality Assessment.

Workorder: V71680

In Date: 12/16/2014
Close Date: 12/17/2014

Meter Reading: 155,420.00

Problem?

replace rear tires

Task performed:

Replace rear tires

Parts

NO PARTS USED

Quantity

Vendor?: BOULEVARD TIRE CENTE

Workorder: V71758

In Date: 12/19/2014
Close Date: 01/07/2015

Meter Reading: 155,627.00

Problem?

Check engine light is on

Task performed:

1. Traced out problem-found code for egr valve it needs to swap out
2. Repaired stretcher latch and tested

Parts

NO PARTS USED

Quantity

Workorder: V72145

In Date: 01/09/2015
Close Date: 01/28/2015

Meter Reading:

Problem?

Left side rear passenger door in crew cab is not closing properly. The door appears to be sagging and the hinge seems loose.

Task performed:

1. Checked door. Will need door hinges. Will order.
2. Rear condensor fans falling off. Repaired bracket.

Parts

NO PARTS USED

Quantity

Workorder: V73555

In Date: 03/02/2015
Close Date: 03/02/2015

Meter Reading:

Problem?

New battery for Drager CO2 monitor

Task performed:

Forwarded to radio shop

Parts

NO PARTS USED

Quantity



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73697

In Date: 03/06/2015

Meter Reading:

Close Date: 03/10/2015

Problem?

Front tires close to wear bar. driver rear outer tire has a slow leak

Task performed:

Parts

Quantity

replace front tires

NO PARTS USED

Vendor?: ELPEX

Workorder: V73820

In Date: 03/12/2015

Meter Reading: 161,611.20

Close Date: 04/22/2015

Problem?

B inspection R53

Task performed:

Parts

Quantity

B inspection R53 outside vendor

1. bolts that hold bumper on rear loose r/side

2. R/brakes low

3. Check engine light on

4. L/center dome light out(pat compartment)

5. L/rear cab door loose. hinges worn

000090155133634 FUEL FILTER WIX MERCEDES/FREIGHT 1

0001801709OIL FILTER 03 57215 WIX MERCEDES/FREIGH 1

906-181-00-86OIL FILTER M2 SPINNER 57140 1

S3226FL02FUEL FILTER 33813 L/F # LFF5851 1

Vendor?: OIL CHANGE SERVICES

Workorder: V73958

In Date: 03/17/2015

Meter Reading: 161,753.00

Close Date: 04/22/2015

Problem?

Replace rear brakes

Task performed:

Parts

Quantity

PM FOLLOW UP REPAIRS

1. bolts that hold bumper on rear loose r/side

2. R/brakes low

3. Check engine light on

4. L/center dome light out(pat compartment)

5. L/rear cab door loose. hinges worn

NO PARTS USED



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74264

In Date: 03/28/2015

Meter Reading:

Close Date: 04/22/2015

Problem?

electrical malfunction showing low voltage and alarms while truck is running, on console panel. R53

Task performed:

Parts

Quantity

1. Road tested and checked charging system and tested ok.
2. Repaired side door that was hard to open.

NO PARTS USED

Workorder: V73045

In Date: 02/11/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Front AC goes on and off. Wiring for front dashboard blower in the cab is loose behind the air filter panel on the officer's side near the floor. Tommy is aware R53

Task performed:

Parts

Quantity

1. Repaired bad connection on cab A/C unit.

VCC/35000003BLOWER MOTOR VCCT1000904A M2

1

VCC/83000038AC WIRE HARNESS

1

Workorder: V73429

In Date: 02/25/2015

Meter Reading:

Close Date: 04/30/2015

Problem?

Back up camera and patient compartment camera not displaying in cab. also Exterior driver compartment vent broken allowing dirt to fill in compartment. Front seat A/C not working. R53

Task performed:

Parts

Quantity

1. Repaired bad connection on back-up camera.

NO PARTS USED

Workorder: V74242

In Date: 03/27/2015

Meter Reading: 162,385.50

Close Date: 05/05/2015

Problem?

BRAKE LIGHTS INOP

Task performed:

Parts

Quantity

1. Repair air leak and no brake lights.
2. Continue repair and go home.

NRG-27-SWA-010R BRAKE NGR-27-SWA-110R MODULE M

1



10/29/2021

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10163698

2005 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74262

In Date: 03/28/2015

Meter Reading:

Close Date: 06/16/2015

Problem?

Power window does not work R53

Task performed:

<u>Parts</u>	<u>Quantity</u>
A06-30769-027DOOR LOCK SWITCH	1
A18-58283-000WINDOW REGULATOR L/H A18-42743-000	1

Workorder: V73866

In Date: 03/13/2015

Meter Reading:

Close Date: 06/30/2015

Problem?

Driver side rear passenger door hinges broken.

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10163698) 2005 - AMERICAN LAFRAN M2 Advanced Life Support Vehicle

10163698

CSHOP-2015-1045

Comments: R53 DOWNWARD FACING FLOOD LIGHT ON UNDERSIDE OF CARRIAGE IS HANGING DOWN. DRIVER SIDE LIGHT STILL WORKS BUT IS NOT CLIPPED IN.

Date Opened: 6-8-2015 Date Finished: 6-11-2015 Meter 1 Reading: 163,640

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
DIAGNOSE ELECTRICAL

CSHOP-2015-1299

Comments: CAB AC NOT WORKING THERE WAS A POWER SURGE WHEN PROBLEM BEGAN R53

Date Opened: 6-22-2015 Date Finished: 6-22-2015 Meter 1 Reading: 163,740

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

CSHOP-2015-1324

Comments: R53 A/C BLOWER INOP

Date Opened: 6-23-2015 Date Finished: 6-23-2015 Meter 1 Reading: 163,850

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

1 9IP; AC WIRE HARNESS
1 HARNESS BLOWER MOTOR
1 MOTOR; BLOWER MOTOR VCCT1000904A M2

CSHOP-2015-1354

Comments: AC WARM R53

Date Opened: 6-24-2015 Date Finished: 6-24-2015 Meter 1 Reading: 163,960

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2015-1527

Comments: LARGE AIR LEAK FROM UNDER VEHICLE R53

Date Opened: 7-2-2015 Date Finished: 7-23-2015 Meter 1 Reading: 163,970

TASKS PERFORMED

Q PARTS

AIR SYSTEM

1 BRAKE; NGR-27-SWA-110R BRAKE MODULE M2
A12-19776-010

Asset Work Order History 10163698

CSHOP-2015-1703

Comments: **REPAIRS FROM INSPECTION LOUD KNOCKING WHILE ENGINE IS AT IDLE R53**
Date Opened: 7-13-2015 Date Finished 8-4-2015 Meter 1 Reading: 169,673

INSTALLED NEW ROOF TOP A/C

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
RESTRAINT	2	COVER; MANSAYER COVER
OVERFLOW TANK	1	CAP; RAD CAP 20 LB
EGR COOLER	1	GASKET; GASKET EGR COOLER
FAULT CODE	1	9IP; EA9061421179 EGR COOLER
ENGINE AND ACCESSORIES	2	9IP; EGR COOLING HOSE
DOME LIGHTS	1	TANK; Z05-30740-000 SURGE TANK
BRAKES	1	VALVE; RA9061420619 EGR VALVE
AIR DRIER	1	9IP; GASKET
UPHOLSTERY	1	GASKET; GASKET
A/C HOSES/FITTINGS	1	FILTER; AIR FILTER M2
HVAC SYSTEM	1	9IP; MASTER INTAKE KIT
	2	BRAKE; KSMA3124710QP REAR BRAKE SHOE KIT
	1	9IP; BULB PATIENT GH22
	1	VALVE; PURGE VALVE AD-IP-IS
	1	PLATE; 18-46375-005 TREAD PLATE RH M2
	1	COMPRESSOR; 03-0609 A/C COMPRESSOR M2 4485
	1	COMPRESSOR; 03-0609 A/C COMPRESSOR M2 4485
	1	DRYER; 07-0614A AC DRIER M2
	1	VALVE; 12-0617A EXPANSION VALVE VCC88000030
	1	A/C; HVAC UNIT ROOF MOUNTED
	1	DRYER; 07-0614A AC DRIER M2

CSHOP-2015-1713

Comments: **ON-CALL R53 NO START**
Date Opened: 7-13-2015 Date Finished 7-13-2015 Meter 1 Reading: 163,970

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM

CSHOP-2015-1867

Comments: **C INSPECTION R53**
Date Opened: 7-21-2015 Date Finished 7-23-2015 Meter 1 Reading: 169,673

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
PM SERVICE C RESCUE	1	FILTER; OIL FILTER 03 57215 WIX MERCEDES/FREIGHTLINER
	1	FILTER; FUEL FILTER 33813 L/F # LFF5851
	1	FILTER; OIL FILTER M2 SPINNER 57140
	1	FILTER; 33634 FUEL FILTER WIX MERCEDES/FREIGHTLINE

VENDOR? ELPEX TIRE TIRESOLES

Asset Work Order History 10163698

CSHOP-2015-2152

Comments: **REPAIR FLAT**

Date Opened: 8-5-2015 Date Finished 8-5-2015 Meter 1 Reading: 169,673

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2015-2220

Comments: **R53 REAR A/C INOP BUZZER SOUND IN CAB WON`T TURN OFF AND NOT SURE WHAT IS CAUSING IT.**

Date Opened: 8-10-2015 Date Finished 8-30-2015 Meter 1 Reading: 169,700

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

1 BLOWER; BLOWER MTR. + SQU IRREL CAGE ASSY. 110
A/C

CSHOP-2015-2604

Comments: **CALL OUT FOR R53 BRAKE ALARM GOING OFF**

Date Opened: 8-29-2015 Date Finished 9-14-2015 Meter 1 Reading: 171,964

TASKS PERFORMED

Q PARTS

BRAKES

1 VALVE; A12-19779-0 VALVE ASSY

CSHOP-2015-2628

Comments: **PARK BRAKE SIGNAL IN CAB INTERMITTANT**

Date Opened: 9-1-2015 Date Finished 9-2-2015 Meter 1 Reading: 171,556

TASKS PERFORMED

Q PARTS

BRAKES

1 VALVE; A12-19777-013 AMU006 VALVE ASSY
1 VALVE; NRG27SWB311R A12-19777-011 VLV ASSY

CSHOP-2015-311

Comments: **PROBLEM WITH REAR DOOR R53**

Date Opened: 4-27-2015 Date Finished 4-28-2015 Meter 1 Reading: 163,340

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
DOOR

1 LATCH; 11656-16 LATCH R/H MEDIC MASTER
1 LATCH; 11657-16 LATCH L/H MEDIC MASTER

Asset Work Order History 10163698

CSHOP-2015-3326

Comments: **AIR LEAK R53**

Date Opened: 10-9-2015 Date Finished 10-9-2015 Meter 1 Reading: 174,168

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

10/08/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
SIGNIFICANT AIR LEAK IN ENGINE COMPARTMENT NEXT TO THE OIL DIP STICK. BLACK AIR HOSE IS MELTED BY THE
HOT OIL DIPSTICK TUBE

CSHOP-2015-3530

Comments: **R53 REPLACED FRONT TIRES**

Date Opened: 10-21-2015 Date Finished 10-21-2015 Meter 1 Reading: 174,911

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-3867

Comments: **R53**

Date Opened: 11-9-2015 Date Finished 11-25-2015 Meter 1 Reading: 177,285

TASKS PERFORMED

Q PARTS

BODY EXTERIOR 1 9IP; COVER, SQUARE, YELLOW
INSTRUMENTS-GAUGES-METERS

Service Requests:

11/09/2015 SERVICE REQUEST / 17: INSUFFICIENT LUBRICANT / REPAIR
CAP TO CHARGING PORT FOUND BROKEN OFF IN MORNING CHECK OUT.

CSHOP-2015-4195

Comments: **R53 NEEDS REAR TIRES**

Date Opened: 11-30-2015 Date Finished 12-8-2015 Meter 1 Reading: 178,190

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? ELPEX TIRE TIRESOLES

Service Requests:

11/27/2015 TIRES / 44: WORN / EXCHANGE - NEW
RESCUE NEEDS 4 REAR TIRES REPLACED.

11/29/2015 TIRES / 44: WORN / EXCHANGE - NEW
TIRES STILL HAVE NOT BEEN REPLACED ON THE REAR

Asset Work Order History 10163698

CSHOP-2015-4399

Comments: **R53**

Date Opened: 12-9-2015

Date Finished

12-10-2015

Meter 1 Reading:

178,255

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

1 SWITCH; 19-1045 MASTER SWITCH 175 AMP
1 SWITCH; SWITCH BATTERY MASTER 300A

Service Requests:

12/09/2015

ENGINE / 19: LOOSE / REPAIR

BATTERY SWITCH IS NOT WORKING PROPERLY. BATTERY SWITCH ALTHOUGH SOMETIMES BEING TURNED TO OFF POSITION WILL STAY ON.

CSHOP-2015-4619

Comments: **OLD R53 REPAIRS**

Date Opened: 12-23-2015

Date Finished

1-4-2016

Meter 1 Reading:

179,239

TASKS PERFORMED

Q PARTS

GROUND LIGHT BODY
WASHER NOZZLE
WASHER RESERVOIR
WIPER BLADES
MUFFLER
RADIATOR
COOLING SYSTEM
IGNITION SWITCH
BATTERY
DIPSTICK AND TUBE
HOSES-LINES & FITTINGS
TIRES ALL
POWER STEERING PUMP
AIR DRIER
WINDOW ELECTRIC MOTOR
BODY EXTERIOR
A/C FILTER
QUALITY CHECK-REPAIRS

1 FERRARA; NOZZLE KIT
1 9IP; WASHER PUMP W/GROMMET
2 WIPER; WIPER BLADE
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D
1 SEAL; 29546229 SEAL FILL TUBE
1 VALVE; PURGE VALVE AD-IP-IS
1 LIGHT; LED GROUND LITE CLEAR
1 BRAKE; CARTRIDGE DC100
4 9IP; INSTRUMENT CLUSTER SCREWS 1 1/2 LONG
1 FILTER; A/C FILTER CAB M2

CSHOP-2015-4645

Comments: **R53 B INSPECTION**

Date Opened: 12-28-2015

Date Finished

1-4-2016

Meter 1 Reading:

179,239

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FUEL FILTER 33813 L/F # LFF5851
1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE

Asset Work Order History 10163698

CSHOP-2015-517

Comments: **R53 AC INOP 4 RUNNING LIGHTS INOP**

Date Opened: 5-8-2015 Date Finished 5-19-2015 Meter 1 Reading: 163,440

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
HOSE UPPER
PARK-CLEARANCE LIGHTS
HVAC SYSTEM

CSHOP-2015-834

Comments: **R53 A/C WARM**

Date Opened: 5-27-2015 Date Finished 5-27-2015 Meter 1 Reading: 163,540

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
EVACUATE AND RECHARGE
HVAC SYSTEM

CSHOP-2016-1334

Date Opened: 3-21-2016 Date Finished 3-24-2016 Meter 1 Reading: 185,015

TASKS PERFORMED

NO PARTS USED

DOOR

Service Requests:

03/19/2016 BODY / 12: BROKEN / REPAIR
PATIENT COMPARTMENT SIDE DOOR GETS STUCK WHEN OPENING FROM INSIDE

CSHOP-2016-143

Comments: **R37 CHECK REAR DOORS, CHECK SIDE PAT DOORS, CHECK GROUND LIGHTS**

Date Opened: 1-12-2016 Date Finished 1-12-2016 Meter 1 Reading: 179,251

TASKS PERFORMED

NO PARTS USED

GROUND LIGHT BODY
DOOR LATCH
REAR DOOR LATCH ASSEMBLY

CSHOP-2016-2045

Comments: **R-37 TRANS GOES OUT OF GEAR.**

Date Opened: 4-29-2016 Date Finished 4-29-2016 Meter 1 Reading: 188,270

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
TRANSMISSION
TIRES & WHEELS

Asset Work Order History 10163698

CSHOP-2016-2234

Comments: **R37 CHECK TIRE WEAR**

Date Opened: 5-9-2016

Date Finished

5-11-2016

Meter 1 Reading:

189,242

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM
TIRES & WHEELS

1 LAMP; HEADLAMP M2 HI

Service Requests:

05/07/2016

LIGHTS / 12: BROKEN / REPAIR
RIGHT SIDE HEADLIGHT OUT

CSHOP-2016-2438

Comments: **R37**

Date Opened: 5-20-2016

Date Finished

6-3-2016

Meter 1 Reading:

191,173

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

Service Requests:

05/20/2016

AIR RIDE / 12: BROKEN / REPAIR
IT TAKES ABOUT 1 MINUTE FOR THE AIR TO COME TO A HIGH ENOUGH PRESSURE FOR THE TRUCK TO GO INTO DRIVE.

CSHOP-2016-2823

Comments: **C INSPECTION R37 H2 FIRE**

Date Opened: 6-13-2016

Date Finished

6-24-2016

Meter 1 Reading:

191,173

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FUEL FILTER 33813 L/F # LFF5851
1 FILTER; OIL FILTER M2 SPINNER 57140
1 FILTER; OIL FILTER 03 57215 WIX
MERCEDES/FREIGHTLINER
1 FILTER; 33634 FUEL FILTER WIX
MERCEDES/FREIGHTLINE

VENDOR?

H2 FIRE SERVICES

Asset Work Order History 10163698

CSHOP-2016-2840

Comments: **PM FOLLOW UPS R37**

Date Opened: 6-14-2016

Date Finished

7-14-2016

Meter 1 Reading:

191,196

TASKS PERFORMED

AIR FILTER
BY-PASS HOSES
SPOT LIGHTS
DOME LIGHTS
LIGHTING SYSTEM
AIR SYSTEM
LIGHT BAR
HVAC SYSTEM

Q PARTS

1	FILTER; AIR FILTER M2
1	HOSE; COOLANT HOSE ECR
1	9IP; BULB PATIENT GH22
1	LIGHT; LED GROUND LITE CLEAR
1	BRAKE; BRAKE VALVE E-6 NEW
1	FILTER; A/C FILTER CAB M2
2	A/C; FREON LB
1	9IP; 5580 CAP-BLACK R134A
1	9IP; VALVE CORE A/C 8926
1	FILTER; 78R5360M 2PK FILTER AIR COND
1	9IP; CAP-BLACK 134A 5579 KOOL TEMP

CSHOP-2016-3419

Date Opened: 7-17-2016

Date Finished

8-16-2016

Meter 1 Reading:

192,942

TASKS PERFORMED

STARTER

Q PARTS

1	STARTER; 39MT 11 TOOTH
---	------------------------

CSHOP-2016-4163

Comments: **OLD R37 REPAIR POWER CABLE AT LEFT FRONT FRAME RAIL**

Date Opened: 8-23-2016

Date Finished

8-29-2016

Meter 1 Reading:

192,942

TASKS PERFORMED

WIPERS-WASHER
BATTERY CABLE
WHEEL BEARINGS
SUSPENSION
REAR BRAKE PADS-SHOES
BRAKE CHAMBER
HVAC SYSTEM

Q PARTS

2	WIPER; WIPER BLADE
1	BATTERY; BATTERY JUNCTION BLOCK
2	BRAKE; 16-19471-000 AIR BAG
2	BRAKE; LONG STROKE BRAKE CHAMBER
1	NEWPART; SLACK ADJUSTER
1	NEWPART; SLACK ADJUSTER
2	BRAKE; KSMA3124710QP REAR BRAKE SHOE KIT
2	9IP; SEAL
2	NEWPART; BEARING KIT 572/580
2	GASKET; GASKET AXLE FL80 R002435
2	NEWPART; BEARING SET 594/594A
2	BRAKE; BRAKE DRUM REAR
2	BRAKES; CLEVIS KIT

Asset Work Order History 10163698

CSHOP-2016-4749

Date Opened: 10-3-2016 Date Finished 10-17-2016 Meter 1 Reading: 195,091

TASKS PERFORMED

Q PARTS

WAIT TIME TO BE CHARGED TO WORK ORDER
HVAC SYSTEM

4 A/C; FREON LB

Service Requests:

10/02/2016 A/C / 18: LEAKING / EXCHANGE - NEW
A/C ISSUE, FRONT CAB AIR IS NOT BLOWING COLD AIR.

CSHOP-2016-4895

Comments: **SR 37 TWO FRONT GRILL LIGHTS OUT.**

Date Opened: 10-13-2016 Date Finished 10-13-2016 Meter 1 Reading: 194,482

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Service Requests:

10/12/2016 LIGHTS / 19: LOOSE / REPAIR
TWO EMERGENCY LIGHTS ON THE FRONT GRILL ARE OUT.

CSHOP-2016-4910

Date Opened: 10-14-2016 Date Finished 10-17-2016 Meter 1 Reading: 195,091

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM

Service Requests:

10/14/2016 ENGINE / 11: BINDS/STICKS / REPAIR

CSHOP-2016-4953

Comments: **DOOR OPEN ALARM**

Date Opened: 10-17-2016 Date Finished 10-20-2016 Meter 1 Reading: 195,165

TASKS PERFORMED

Q PARTS

BATTERY
DOOR ALARM OR OTHER WARNING

4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
4 BATTERY; BATTERY 950CCA HP-31D
1 9IP; A22-54259-000 DOOM LIGHT SWITCH M2

Asset Work Order History 10163698

CSHOP-2016-5136

Comments: **R33 AT HQ CHECK AC**

Date Opened: 10-28-2016 Date Finished 12-12-2016 Meter 1 Reading: 202,445

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM
HVAC SYSTEM

1 LIGHT; HEADLIGHT EXTRA BRIGHT

Service Requests:

10/28/2016 SERVICE REQUEST / 12: BROKEN / REPAIR
BACK UP CAMERA NOT WORKING. DOES NOT DISPLAY IN CAB

11/23/2016 AIR RIDE / 18: LEAKING / REPAIR
WHEN THE TRUCK IS PARKED AND SHUT OFF THERE IS A LARGE AIR LEAK.

CSHOP-2016-5549

Comments: **R33 STRETCHER LOCK ISSUE**

Date Opened: 11-29-2016 Date Finished 11-29-2016 Meter 1 Reading: 200,817

TASKS PERFORMED

Q PARTS

SAFTEY-EMERGENCY EQUIPMENT

1 NEWPART; MAGNET STRETCHER STRYKER
1 NEWPART; STRIKER BAR/RAIL ASSY

CSHOP-2016-6048

Comments: **SR 37 AIR RIDE ISSUE**

Date Opened: 12-28-2016 Date Finished 1-19-2017 Meter 1 Reading: 205,073

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

Service Requests:

12/28/2016 AIR RIDE / 19: LOOSE / REPAIR
AIR RIDE ISSUE

CSHOP-2016-6094

Date Opened: 12-29-2016 Date Finished 1-19-2017 Meter 1 Reading: 205,073

TASKS PERFORMED

Q PARTS

SUSPENSION

2 9IP; 9IP

Asset Work Order History 10163698

CSHOP-2016-6121

Comments: **R-33 CURRENTLY IN SPARE RESCUE 10163698 TIRES ACROSS THE REAR CALLED IN BY ED 12/30/2016 8:30AM**

Date Opened: 12-30-2016 Date Finished 1-10-2017 Meter 1 Reading: 205,073

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

12/30/2016 TIRES / 12: BROKEN / EXCHANGE - NEW
BAD TIRES....DRIVER SIDE REAR OUTSIDE IS WORN AND NEEDS TO BE REPLACED. STATION 33 R33

CSHOP-2017-110

Date Opened: 1-5-2017 Date Finished 1-12-2017 Meter 1 Reading: 205,073

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; A/C FILTER CAB M2
2 WIPER; WIPER BLADE
1 9IP; 9IP
1 9IP; 9IP

CSHOP-2017-1137

Comments: **CAB A/C**

Date Opened: 2-23-2017 Date Finished 3-14-2017 Meter 1 Reading: 206,938

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
REAR WINDOW
HVAC SYSTEM

1 LIGHT; LED GROUND LITE CLEAR
1 DRYER; 07-0614A AC DRIER M2
1 9IP; 12-2012A EXPANSION VALVE 71R8301
1 TEM; STEEL FILTER DRIER
4 9XX; 134A 10194654
1 9HY; HOSE MADE

CSHOP-2017-1585

Comments: **A INSPECTION**

Date Opened: 3-14-2017 Date Finished 3-22-2017 Meter 1 Reading: 206,938

TASKS PERFORMED

Q PARTS

A INSPECTION
SERPENTINE BELT
LIGHTING SYSTEM
DIAGNOSE ELECTRICAL
SUSPENSION
HVAC SYSTEM

1 NBH; FLEETRANNER BELT
2 9IP; BULB PATIENT GH22
2 BULB; LIGHT BULB
1 2IH; LEVELING VALVE FRTLIN
1 NONSTOCK; FREIGHT CHARGE

Asset Work Order History 10163698

CSHOP-2017-1869

Date Opened: 3-28-2017 Date Finished 3-28-2017 Meter 1 Reading: 206,938

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2017-2017

Date Opened: 4-5-2017 Date Finished 4-6-2017 Meter 1 Reading: 207,717

DOOR ALARM GOING OFF

TASKS PERFORMED

NO PARTS USED

SWITCH

CSHOP-2017-2297

Date Opened: 4-19-2017 Date Finished 4-19-2017 Meter 1 Reading: 208,180

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

Service Requests:

04/19/2017 FUEL / 29: PART OMITTED / ADJUST

CSHOP-2017-2639

Date Opened: 5-5-2017 Date Finished 5-16-2017 Meter 1 Reading: 208,530

TASKS PERFORMED

Q PARTS

DOOR
BODY EXTERIOR
CAB-INTERIOR ACCESSORIES

6 5SC; ZICO STOPS BRACKETS
9 5SC; ZICO RATCHET STRAP

Service Requests:

05/05/2017 DOOR / 19: LOOSE / REPAIR

CSHOP-2017-3154

Date Opened: 5-30-2017 Date Finished 6-14-2017 Meter 1 Reading: 210,424

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

05/28/2017 ENGINE / 18: LEAKING / REPAIR
SPARE R54 HAD A BARRACK THAT WAS LOOSE THAT WAS ATTACHED TO THE ALTERNATOR, PIECE OF METAL WAS
TAKEN OFF DUE TO HAZARD TO THE HOSES AND FAN

Asset Work Order History 10163698

CSHOP-2017-321

Comments: **SPARE RESCUE AT 22 WINDOW AND AC NOT WORKING**

Date Opened: 1-17-2017

Date Finished 1-20-2017

Meter 1 Reading: 205,073

TASKS PERFORMED

Q PARTS

REAR WINDOW
HVAC SYSTEM

1 2FL; WINDOW SWITCH
2 FAN; FAN A/C COND 12IN 860026-2-W
1 9IP; FREON LB

Service Requests:

01/17/2017 WINDOW / 38: SHORTED / REPAIR
REAR DRIVER SIDE WINDOW WILL NOT ROLL UP

01/17/2017 A/C / 18: LEAKING / ADJUST
AC IN CAB OF RESCUE IS NOT BLOWING COLD, AC IN THE BACK PART OF THE CAB IS NOT BLOWING AT ALL

CSHOP-2017-3971

Date Opened: 7-5-2017

Date Finished 7-7-2017

Meter 1 Reading: 211,365

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 CRC; CLEAN-R-CARB 200Z
1 FIL; NAPA GOLD OIL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPAGOLD AIR FILTER

Asset Work Order History 10163698

CSHOP-2017-4259

Comments: **REPAIRS FROM PM**

Date Opened: 7-21-2017

Date Finished

7-31-2017

Meter 1 Reading:

211,463

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
STRETCHER	1	9IP; ANTLER BAR
STORAGE CABINET EMERGENCY VEH	1	9IP; STRIKER PIN
STEP	2	1AN; WIPERS
REAR DOOR	1	9IP; 35 WATT BULB
WIPER BLADES	-1	GRO; SEALED BACK-UP LAMP
LIGHTING SYSTEM	1	GRO; SEALED BACK-UP LAMP
BATTERY CABLE	1	GRO; LAMP
SHORELINE CHARGER	1	LIT; GROMMET
U-BOLTS	1	9IP; GROUND LT BRACKET
RESERVOIR	1	6KU; AUTO CHAGER AC2000 12V
AIR DRIER	-1	BK; TAPE
AIR SYSTEM	1	BK; TAPE
HVAC SYSTEM	1	5TN; (USE 6KU) AUTOCHARGE 2000
	-1	5TN; (USE 6KU) AUTOCHARGE 2000
	1	FIL; NAPAGOLD AIR FILTER
	1	MBI; PURG/VLV
	1	2FL; PRES VALVE
	1	9IP; A12-19772-285 VALVE ASSY AMU02
	1	8GR; FILTER
	4	9XX; AC FREON 10174676
	1	FIL; NAPA CABIN AIR FILTER

CSHOP-2017-4303

Date Opened: 7-24-2017

Date Finished

8-28-2017

Meter 1 Reading:

212,234

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
OIL	28	FLUID; SYN OIL BULK QTS
	28	9OC; SYN 15W40
	-28	9OC; SYN 15W40

CSHOP-2017-4982

Date Opened: 8-24-2017

Date Finished

9-6-2017

Meter 1 Reading:

212,332

TASKS PERFORMED

	<u>Q</u>	<u>PARTS</u>
QUALITY CHECK-REPAIRS	1	9IP; 11656-16 LATCH R/H MEDIC MASTER
DOOR LATCH	1	9IP; BULB PATIENT GH22
REPAIR FROM PM - O2 SYSTEM	1	9IP; LIGHT BULB
DOMELIGHTS	2	GRO; CLR MKR LAMP
PARK-CLEARANCE LIGHTS	2	1WL; SURFACE MOUNT LED
LIGHTING SYSTEM	2	9AP; 20MR11
STROBE LIGHTS	1	2FL; GRILL
GRILLE	1	2FL; GRILL
	2	9IP; 600 NON OPTIC RED LENS

Asset Work Order History 10163698

CSHOP-2017-5936

Comments: **SPARE RESCUE AT ST29**

Date Opened: 10-16-2017 Date Finished 10-17-2017 Meter 1 Reading: 213,423

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIATOR
CONDENSER

Service Requests:

-
- 10/15/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
R26 SPARE (ASSET #: 10163698) HAS BROKEN BRACKET ON FANS (COOLANT?). CONCERN IS THEY COULD GET CAUGHT ON ROAD DEBRIS AND BE TORN OFF. AFTER A CALL, IN ACREAGE, RETURNED TO STATION DRAGGING DEBRIS.
 - 10/15/2017 SERVICE REQUEST / 49: CAN NOT DUPLICATE CONCERN / INSPECT
SHORELINE DID NOT AUTO EJECT WHEN THE TRUCK WAS STARTED
 - 10/15/2017 ENGINE / 49: CAN NOT DUPLICATE CONCERN / INSPECT
VEHICLE STALLED AND HAD TO BE STARTED AGAIN
-

CSHOP-2017-6067

Comments: **SPARE RESCUE AT ST26**

Date Opened: 10-20-2017 Date Finished 10-23-2017 Meter 1 Reading: 213,589

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SHORELINE CHARGER

1 5SC; AUTO EJECT KIT W/YELLOW CVR

Service Requests:

-
- 10/19/2017 SERVICE REQUEST / 12: BROKEN / REPAIR
SERVICE REQUEST: SHORELINE POWER STUCK TO TRUCK WHEN RESPONDING TO CALLS. WILL NOT EJECT WHEN TRUCK STARTS
-

CSHOP-2017-6454

Comments: **PRETRIP INSPECTION**

Date Opened: 11-8-2017 Date Finished 11-8-2017 Meter 1 Reading: 213,851

TASKS PERFORMED

Q PARTS

PRE TRIP INSPECTION
OXYGEN SENSOR

1 9IP; SPMGC23 GAUGE

Asset Work Order History 10163698

CSHOP-2017-6460

Comments: **PRETRIP**

Date Opened: 11-8-2017

Date Finished

11-27-2017

Meter 1 Reading:

213,853

TASKS PERFORMED

Q PARTS

WIPERS-WASHER
COOLING SYSTEM
PARK-CLEARANCE LIGHTS
BATTERY
DOOR
CAB STEP
CAB-INTERIOR ACCESSORIES

2 1AN; WIPERS
1 2FL; CHECK VALVE
1 2FL; O-RING
1 2FL; SENSOR
1 9IP; RAD CAP 20 LB
1 BK; PTEX ULTRA BLACK 30Z
1 2FL; TOP CLEARANCE LIGHT M2

CSHOP-2017-7187

Date Opened: 12-18-2017

Date Finished

1-20-2018

Meter 1 Reading:

216,259

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

1 9AP; VISTA

Service Requests:

12/17/2017

SERVICE REQUEST / 12: BROKEN / EXCHANGE - NEW

SERVICE REQUEST - OPEN DOOR SENSOR IS FAULTY FOR THE FRONT PASSENGER SIDE DOOR. THE OPEN DOOR ALARM KEEPS GOING OFF AND ALL THE INTERIOR LIGHTS TURN ON MAKING IT EXTREMELY DIFFICULT TO SEE THE MIRRORS AT NIGHT. ALSO THE FRONT PASSENGER SIDE MIRROR WONT GO DOWN. ALSO THE LCD SCREEN ON THE MOD CONTROLS IS NOT TURNING ON.

CSHOP-2017-728

Comments: **SPARE RESCUE AT STATION 22**

Date Opened: 2-3-2017

Date Finished

2-9-2017

Meter 1 Reading:

206,165

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Service Requests:

02/03/2017

A/C / 18: LEAKING / ADJUST

A/C ISSUE, AC IN CAB IS BLOWING WARM

CSHOP-2018-1028

Date Opened: 2-20-2018

Date Finished

2-20-2018

Meter 1 Reading:

216,259

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

CSHOP-2018-107

Date Opened: 1-5-2018

Date Finished

1-12-2018

Meter 1 Reading:

216,222

TASKS PERFORMED

NO PARTS USED

LIGHTING SYSTEM

Asset Work Order History 10163698

CSHOP-2018-3114

Date Opened: 6-5-2018 Date Finished 6-5-2018 Meter 1 Reading: 216,259

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM

CSHOP-2018-5217

Date Opened: 9-13-2018 Date Finished 9-13-2018 Meter 1 Reading: 216,393

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

VENDOR? REV RTC

CSHOP-2018-70

Comments: **PASS WINDOW INOP AND LEFT FRONT TIRE HAS A GASH**

Date Opened: 1-4-2018 Date Finished 1-20-2018 Meter 1 Reading: 216,259

TASKS PERFORMED

Q PARTS

SENSOR
TIRE
WINDOW REGULATOR
CAB-INTERIOR ACCESSORIES
HVAC SYSTEM

1 TEM; BLMOTOR
1 2FL; A/C WIRE HARNESS

Service Requests:

01/03/2018 A/C / 12: BROKEN / EXCHANGE - NEW
A/C DOES NOT WORK IN FRONT CAB

01/03/2018 SERVICE REQUEST / 12: BROKEN / ADJUST
DISPLAY DOES NOT LIGHT UP ON CAB CONTROL PANEL

CSHOP-2019-114

Date Opened: 1-7-2019 Date Finished 4-2-2019 Meter 1 Reading: 216,542

TASKS PERFORMED

Q PARTS

SCBA BRACKETS
BODY EXTERIOR

1 9AP; DETAIL 10163968

CSHOP-2019-2292

Date Opened: 4-30-2019 Date Finished 5-1-2019 Meter 1 Reading: 216,542

TASKS PERFORMED

NO PARTS USED

HVAC SYSTEM

Asset Work Order History 10163698

CSHOP-2019-4553

Date Opened: 8-26-2019 Date Finished 8-30-2019 Meter 1 Reading: 216,651

TASKS PERFORMED

Q PARTS

COOLING SYSTEM
TURN SIGNAL LIGHTS
HVAC SYSTEM

1 2FL; RADIATOR
1 1WL; LED TURN SIGNAL LAMP

CSHOP-2019-4554

Date Opened: 8-26-2019 Date Finished 8-30-2019 Meter 1 Reading: 216,651

TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

CSHOP-2019-4575

Date Opened: 8-27-2019 Date Finished 8-27-2019 Meter 1 Reading: 216,647

TASKS PERFORMED

NO PARTS USED

EQUIPMENT MOUNTING BRACKETS

CSHOP-2019-4636

Date Opened: 8-30-2019 Date Finished 10-2-2019 Meter 1 Reading: 216,658

TASKS PERFORMED

Q PARTS

AIR GAUGE

1 2FL; CLUSTER
1 9IP; A22 49250 003 CLUSTER ASSY
-1 9IP; A22 49250 003 CLUSTER ASSY

CSHOP-2019-5794

Comments: **REPAIRED AT SHOP**

Date Opened: 11-4-2019 Date Finished 3-17-2020 Meter 1 Reading: 216,665

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

Service Requests:

11/04/2019 A/C / 18: LEAKING / REPAIR
A/C ISSUE. THE FRONT AND PATIENT COMPARTMENT. NO COLD AIR BLOWING OUT OF THE A/C. UNIT IS LOCATED AT HQ TRAINING BAY.

Asset Work Order History 10163698

CSHOP-2019-6464

Comments: **LOSING COOLANT**

Date Opened: 12-13-2019

Date Finished

1-13-2020

Meter 1 Reading:

216,665

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR FILTER
FUEL SYSTEM
THERMOSTAT
COOLING SYSTEM
SERPENTINE BELT
OIL FILTER
STARTER RELAY-SOLENOID
BATTERY
DIAGNOSE ELECTRICAL
AIR SYSTEM

1 FIL; NAPAGOLD AIR FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 2FL; W S FILTER HOUSING
2 2DD; O RING SEAL
2 2DD; 2DD
1 2DD; 2DD
2 2DD; SEAL RING
1 2DD; TEMP SENSOR OIL
1 2DD; HOSE 1134D
1 2DD; HOSE UPPER RAD
3 2IH; 50 50 COOLANT FLEETGUARD
2 2DD; THERMOSTAT
1 2DD; 2DD
1 2DD; 2DD
1 2DD; WATER PUMP
1 NBH; FLEETRANNER BELT
1 NBH; FLEETRANNER BELT
1 FIL; NAPAGOLD OIL FILTER
1 FIL; FIL
30 4PC; 15W40 PREMIUM BLUE OIL
1 2FL; RELAY
4 1AD; BATTERY GROUP 31
1 2FL; PARKING BRAKE SWITCH
1 6KU; COVER ROUND YELLOW
1 6KU; AC2000 12V PLC TEN 8
1 9IP; A12 19777 213 MODULE

CSHOP-2020-3683

Date Opened: 7-15-2020

Date Finished

8-5-2020

Meter 1 Reading:

216,846

TASKS PERFORMED

NO PARTS USED

DOOR ALARM OR OTHER WARNING
COMPRESSOR

Service Requests:

07/15/2020

A/C / 18: LEAKING / INSPECT
A/C ISSUE

Asset Work Order History 10163698

CSHOP-2020-4206

Date Opened: 8-14-2020

Date Finished

8-17-2020

Meter 1 Reading:

216,989

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
22 4PC; 15W40 PREMIUM BLUE OIL
1 FIL; FIL
1 FIL; FIL

CSHOP-2020-4242

Date Opened: 8-17-2020

Date Finished

8-25-2020

Meter 1 Reading:

216,989

TASKS PERFORMED

Q PARTS

GROUND LIGHT BODY
WIPER BLADES
COOLING SYSTEM
LIGHTING SYSTEM
REAR TIRES
REAR SPRING
DOOR HANDLES INSIDE-OUTSIDE
CAB-INTERIOR ACCESSORIES
INSTRUMENTS-GAUGES-METERS
HVAC SYSTEM

1 GRO; LAMP
2 1AN; 22 WIPER BLADE
1 2FL; SENSOR
1 2FL; KIT SURGE TANK
1 6WL; 6WL
2 2FL; AIR BAGS
1 5AH; LATCH LH TRIMARK
1 9IP; A22 54259 000 DOOM LIGHT SWITCH M2
1 9ME; VISTA V MUX DISPALY
1 TEM; EXPANSION VALVE
1 TEM; SWITCH
-1 TEM; FIL/DRY
1 TEM; FIL/DRY
1 9HY; FITTINGS MAKO
2 9XX; AC FREON 10199801
1 TEM; FILTER DRIER
1 TEM; TEM
1 TEM; STEEL FILTER DRIER

CSHOP-2020-523

Date Opened: 1-31-2020

Date Finished

1-31-2020

Meter 1 Reading:

216,665

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
AIR SYSTEM

1 FIL; NAPAGOLD AIR FILTER
1 TWD; PURGE VALVE ASSY KIT

CSHOP-2020-5330

Date Opened: 10-9-2020

Date Finished

10-9-2020

Meter 1 Reading:

216,989

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Asset Work Order History 10163698

CSHOP-2021-2474

Date Opened: 5-4-2021 Date Finished 6-1-2021 Meter 1 Reading: 217,039

TASKS PERFORMED

Q PARTS

AIR SYSTEM
SAFTEY-EMERGENCY EQUIPMENT

2 2FL; CAB AIR BAG

Service Requests:

05/03/2021 BRAKES / 18: LEAKING / REPAIR
BRAKE ISSUES - CAPTAIN WATSON IS REQUESTING THAT SOMEONE COME OUT AND LOOK AT THE AIR BRAKE COMPRESSOR ON R-778 (10163698).

CSHOP-2021-3027

Date Opened: 6-1-2021 Date Finished 6-17-2021 Meter 1 Reading: 217,039

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

06/01/2021 STARTER / 18: LEAKING / REPAIR
VEHICLE WILL NOT START, POSSIBLE BATTERY ISSUE

CSHOP-2021-3597

Date Opened: 6-29-2021 Date Finished 7-1-2021 Meter 1 Reading: 217,235

TASKS PERFORMED

Q PARTS

BATTERY

4 1AD; 1000 CCA 31 SERIES BATTERY

CSHOP-2021-3771

Date Opened: 7-7-2021 Date Finished 7-9-2021 Meter 1 Reading: 217,240

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM

CSHOP-2021-4683

Comments: **INSPECT ONLY**

Date Opened: 8-17-2021 Date Finished 8-27-2021 Meter 1 Reading: 217,936

TASKS PERFORMED

NO PARTS USED

INSPECTION

Asset Work Order History 10163698

CSHOP-2021-4684

Comments: **NOTED IN PM FOLLOW UP REPAIRS LUBE OIL AND FILTERS**

Date Opened: 8-17-2021

Date Finished

9-16-2021

Meter 1 Reading:

217,936

TASKS PERFORMED

Q PARTS

QUALITY CHECK-REPAIRS	2	9IP; SLIDE 10 IN
STORAGE CABINET EMERGENCY VEH	2	1AN; 22 WIPER BLADE
WIPER BLADES	1	FIL; NAPA GOLD OIL FILTER
OIL	1	FIL; NAPAGOLD OIL FILTER
IGNITION SWITCH KEY-LOCK ASSE	26	4PC; 15W40 PREMIUM BLUE OIL
SWITCH-ELECTRICAL	1	FIL; NAPAGOLD FUEL FILTER
REPAIR FROM PM - WHEEL SEALS	1	FIL; NAPAGOLD FUEL FILTER
BRAKES	2	8HD; KEY VEHICLE FROM BLANK
DOOR	1	2FL; SWITCH DOOR JAMB
BODY EXTERIOR	2	TWD; SHOE KIT
DOOR LOCKS	-2	TWD; SHOE KIT
HVAC SYSTEM	2	NTL; AXL GSKT
	2	NCB; DEGREASER MULTI PURP
	1	9HD; SEAL
	2	9HD; SEAL
	1	9HD; BEARING
	2	2IH; SHOE KIT
	-1	2FL; SEAL, DOOR
	1	2FL; SEAL, DOOR
	1	FIL; NAPA CABIN AIR FILTER
	4	9XX; AC FREON 10199801
	1	TEM; TEM
	1	TEM; STEEL FILTER DRIER

RADIO-2016-611

Comments: **INSTALLED A NEW GETAC DOCKING STATION ON SR37.**

Date Opened: 10-3-2016

Date Finished

10-3-2016

Meter 1 Reading:

193,187

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

10/02/2016

SERVICE REQUEST / /

SERVICE REQUEST, MDT THAT CAME WITH THE SPARE UNIT IS OUT OF SERVICE, CABLE FROM MODEM TO DOCKING STATION IS CUT.
