Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Total Hours: 11	3.25 Labor: 7,354.70	Parts: 7,364.04	Comm: 192.00		Charged	: 14910.74	
Work Order: 1 Problem: 1	403307 M 061 - Pre Delivery Inspe	leter: 322		In Date:	04/04/2014	Closed:	04/04/2014
Work Comp	leted						
- Pre Deliver	y Inspection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	00	Total:	120.00
Work Order: 1 Problem: F		leter: 5405		In Date:	08/27/2014	Closed:	09/08/2014
Work Comp	leted		Parts Issued			Qı	uantity
- Pm service			5w20 Engine Oil				7.00
- Rotate and	I balance all four tires.		Napagold Oil Filter				1.00
- Shop Supp	lies		Washer Fluid Conce	ntr			1.00
			Shop Supplies				1.00
	Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 25	.51	Total:	205.51
Work Order: 1 Problem: F	409670 M Right front tire flat.	leter: 6363		In Date:	09/26/2014	Closed:	09/30/2014
Work Comp	leted		Parts Issued			Qı	uantity
- Repair flat	and balance right front t	ire.	Shop Supplies				1.00
- Shop Supp	_						
	Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 2.0	00	Total:	62.00
Work Order: 1 Problem: F		leter: 10697		In Date:	01/29/2015	Closed:	03/09/2015
Work Comp	leted		Parts Issued			Qı	uantity
- Pm service			5w20 Engine Oil				7.00
- Rotate and	I balance all four tires.		Napagold Oil Filter				1.00
		er for airbag light staying on.(repl	ace Washer Fluid Conce	ntr			1.00
driver door h	arness)		Shop Supplies				1.00
- Shop Supp	lies						
	Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 25	.58	Total:	325.58

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Problem: P.M. service and tool box hard to close and lock.

Work Completed		Parts Issued		Quantity
- P.m. Service		5w20 Engine Oil		6.00
- Rotate and balance all tires.		Napagold Oil Filter		1.00
- Shop Supplies		Wiper Blade		2.00
		Washer Fluid Conc	entr	1.00
		Used Fire X Refurb	ished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 52.07	Total: 232.07

Work Order: 1600321 Meter: 21831 In Date: 01/11/2016 Closed: 02/08/2016

Problem: Pm service. Tailgate cap damage.

Work Completed	Parts Issued		Quantity
- Pm service.	5w20 Engine Oil		6.00
- Replace damage tailgate cap.	Napagold Oil Filter		1.00
- Rotate and balance all four tires.	Washer Fluid Concent	r	1.00
- Transport vehicle to and from dealer for repairing air bag warning light	on. 22" Wiper Blade		2.00
- Shop Supplies	Stg Wheel Cov - Ford		1.00
	Floor Mat-2pc Rub Bk		1.00
	Taigate Cover Mouldir	ng	1.00
	Shop Supplies		1.00
Hours: 5.50 Comm: 0.00	Labor: 330.00	Parts: 137.08	Total: 467.08

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1606765 Meter: 27290 In Date: 07/05/2016 Closed: 07/12/2016

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		235 75r17 Adventu	ıre	4.00
- Replace and balance four new tires.		5w20 Engine Oil		6.00
- Complete wheel alignment.test drive.		Napagold Oil Filter	ſ	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Conc	entr	1.00
		Used Fire X Refurb	ished	1.00
		Mac Wite Lithium	Gres	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 907.92	Total: 1,297.92

Work Order: 1608118 Meter: 28739 In Date: 08/08/2016 Closed: 08/29/2016

Problem: Left rear tire flat spare on truck and missing spare tire lock.

Work Completed		Parts Issued		Quantity
- Replace and balance left rear tire.fabricate and inst	tall new spare tire lock	235 75r17 Adven	ture	1.00
kit.	·	Clinder Spaer Tire	2	1.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		1.00
Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 360.16	Total: 450.16

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1612766 Meter: 32878 In Date: 12/14/2016 Closed: 01/02/2017

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. Service.	Heater Hose	1.00
- Pressure test and inspect cooling system.replace leaking hose f	rom 5w20 Engine Oil	6.00
reservoir to thermostat housing.refill system.	Napagold Oil Filter	1.00
- Test battery and charging system.recharge and retest battery,fa	ail load Washer Fluid Concentr	1.00
test.replace defective battery.	22" Wiper Blade	2.00
- Repair left rear tire.rotate and balance all four.	Anti Freeze Motorcraft	2.00
- Shop Supplies	Battery 65	1.00
	Shop Supplies	1.00
Hours: 6.50 Comm	: 0.00 Labor: 390.00 Parts: 282.61	Total: 672.61

Work Order: 1705332 Meter: 37993 In Date: 05/31/2017 Closed: 06/06/2017

Problem: P.M. service and check engine light .

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Flush and refill transmission fluid		Napagold Oil Filte	r	1.00
- Diagnoise check engine lamp on.scan test P2196,	p2198.pinpoint	Napagold Air Filte	er	1.00
test.monitor pids.replace leaking purge solenoid.cle	ear codes.perform evap	Used Fire X Refurb	pished	1.00
system test.passed.		22" Wiper Blade		2.00
 Coolant low.inspect for leaks.replace leaking cool coolant. 	ant resevoir.top off	Syn-atf Trans Fluid	I S	12.00
- Replace corroded trailer plug socket.repair wiring	as noodod	trailer plug		1.00
- Replace broken left side seat trim panels.	as needed.	Valva Asy		1.00
·		Coolant Resevoir		1.00
 Resureface front rotors to correct pulsation .clean drive. 	n pads,lube callpers.test	Housing		1.00
- Rotate and balance four tires.nitro fill.		seatpanel shield as	sy	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 12.25	Comm: 0.00	Labor: 735.00	Parts: 545.59	Total: 1,280.59

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1710341 Meter: 40170 In Date: 10/20/2017 Closed: 10/25/2017

Problem: Left rear tail light broken.

Work CompletedParts IssuedQuantity- Replace left rear tail assembly.Lamp Assembly1.00- Shop SuppliesShop Supplies1.00Hours: 0.50Comm: 0.00Labor: 30.00Parts: 161.18Total: 191.18

Work Order: 1711995 Meter: 41660 In Date: 12/07/2017 Closed: 12/07/2017

Problem: Inspect for rust.

Work CompletedParts IssuedQuantity- Transport to and from dealer for rust repair.Shop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Labor: 180.00

Parts: 27.01

Total: 207.01

Work Order: 1712459 Meter: 42269 In Date: 12/19/2017 Closed: 12/21/2017

Problem: PM Service

Hours: 3.00

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	6.00
- Rotate and balance tires.	Napagold Oil Filter	1.00
- Shop Supplies	22" Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1804467 Meter: 47670 In Date: 04/30/2018 Closed: 05/03/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Resurface front brake rotors .replace front pads, service ca	alipers and fluah	Napagold Oil Filte	r	1.00
and bleed brake system.road test.		Used Fire X Refurb	ished	1.00
- Replace and balance all four tires.		22" Wiper Blade		2.00
- Complete alignment and road test.		Brake Pad		1.00
- Shop Supplies		235 75r17 Adventu	ıre	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 10.00 C	omm: 0.00	Labor: 600.00	Parts: 945.51	Total: 1,545.51

Work Order: 1810430 Meter: 53261 In Date: 10/10/2018 Closed: 10/17/2018

Problem: P.M. service and brakes pull left.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Test drive . front brakes pull left . Resurface both front rotors and rep	lace 5w20 Engine Oil	6.00
both front rotor . Flush and bleed brake system . Test drive.	22" Wiper Blade	2.00
- Vehicle drifts left . Perform complete front end alignment. Test drive.	Ford Triton Pvc Swc	1.00
- Rotate and high speed balance all four tires.	Reman/ca	1.00
- Shop Supplies	Reman/ca	1.00
	Non-chlor Brake Clnr	1.00
	B Fluid Dot 3-32oz	1.00
	Shop Supplies	1.00
Hours: 9.00 Comm: 0.00	Labor: 603.00 Parts: 212.15	Total: 815.15

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1813101 Meter: 55964 In Date: 12/31/2018 Closed: 01/07/2019

Problem: Towed in for brakes locked up .

Work Completed		Parts Issued		Quantity
- Diagnose brake locking up . Replace right front bra	ke caliper . Replace	Center Cap		1.00
both front brake hoses . Flush and bleed brake system . Road test. Replace melted right front center cap . - Diagnose trailer warning on dash . Replace trailer plug connector and rewire as needed.		Rf Brake Hose		1.00
		Lf Brake Hose		1.00
		trailer plug		1.00
- Shop Supplies		Reman/ca		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 3.60	Comm: 0.00	Labor: 241.20	Parts: 157.83	Total: 399.03

Work Order: 1813114 Meter: 55661 In Date: 12/30/2018 Closed: 12/31/2018

Problem: Brakes locked up

Work Completed

- Tow From: 14200 Us1 Juno Beach (loggerhead park) To: lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1904054 Meter: 59291 In Date: 04/15/2019 Closed: 04/18/2019

Problem: P.M. service and tailgate needs to be adjusted.

Work Completed		Parts Issued		Quantity	
P.m. service. Adjust tailgate stricker.Rotate and high speed bal;ance all four tires . Nitrofill all.Shop Supplies		Napagold Oil Filter		1.00	
		5w20 Engine Oil		6.00	
		22" Wiper Blade Washer Fluid Concentr		2.00	
				1.00	
		Used Fire X Refurbished		1.00	
		Shop Supplies		1.00	
Hours: 3.00 Co	mm: 0.00	Labor: 201.00	Parts: 43.59	Total: 244.59	

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 1905766 Meter: 60558 In Date: 05/31/2019 Closed: 06/10/2019

Problem: Towed in for battery light and stalled ,no start.

Nork Completed F		Parts Issued		Quantity
- Computer diagnose battery light . perform alt	Alternator Assy		1.00	
defective alternator assembly and belt and repla	V Belt		1.00	
- Shop Supplies		V Belt		1.00
		Shop Supplies		1.00
Hours: 2.70	Comm: 0.00	Labor: 180.90	Parts: 764.61	Total: 945.51

Work Order: 1905791 Meter: 60473 In Date: 05/21/2019 Closed: 05/31/2019

Problem: No start

Work Completed

- Tow From: 825 Ave P (north Parks Maintenance) To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1910399 Meter: 64918 In Date: 10/08/2019 Closed: 10/21/2019

Problem: P.M. service and check brake noise .

Work Completed	Parts Issued		Quantity
- P.m. service.	Napagold Oil Filter		1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill a	5w20 Engine Oil		6.00
- Shop Supplies	22" Wiper Blade		2.00
	Washer Fluid Concentr		1.00
	Tire Crayon		1.00
	Hankook P235 75r17 Dp At Shop Supplies		2.00
			1.00
	Tire Disposal Fee		2.00
Hours: 4.00 Comm: 0.00	Labor: 292.00	Parts: 496.43	Total: 788.43

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 2001823 Meter: 70012 In Date: 02/24/2020 Closed: 03/05/2020

Problem: P.M. service.

Hours: 17.60

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitrofill all.	5w20 Engine Oil	6.00
- Diagnose miss fire . Perform complete tune up . Replace all six spark plugs	22" Wiper Blade	2.00
. Clear codes and retest .	Washer Fluid Concentr	1.00
- Perform complete air intake decarb and cleaning . Flush injectors . Clean	Used Fire X Refurbished	1.00
	Hankook P235 75r17 Dp At	2.00
- Remove bench seat to repaired and reinstall after and clear airbag light .	Spark Plugs	6.00
,thermostat and gasket . Flush coolant and refill . Retest .	Motor Tune-up 16oz	1.00
- Perform complete front end alignment and road test .	Intake Cleaner Kit	1.00
- Shop Supplies	Throttle Body Cleaner	1.00
- Snop Supplies	Housing	1.00
	seatpanel shield asy	1.00
	Seat R And R	1.00
	Anti Freeze Motorcraft	2.00
	Gasket	1.00
	Gasket	1.00
	Thermostat Gasket	1.00
	Water Pump	1.00
	Thermostat	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Comm: 0.00

Labor: 1,284.80

Parts: 1,383.61

Total: 2,668.41

Palm Beach County Fleet Management Asset Maintenance History 10194203 2014 FORD F150 Pickup, 1/2 Ton

Work Order: 2008938 Meter: 75226 In Date: 09/04/2020 Closed: 09/17/2020

Problem: P.M. service and check brake noise

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		7.00
 Load test battery . Battery failed . R&r defective battery . Test and replace left side tool box strut . Resurface both rear brake rotors . Replace calipers and brake hoses and pads . Flush and bleed brake system . Road test . 		Napagold Oil Filter		1.00
		Washer Fluid Concentr		1.00
		22" Wiper Blade		2.00
		Starter		1.00
- Rotate and balance all four wheels .nitrofill and reset Tpn	ms .	Support		1.00
- Diagnose start not engaging . R&r defective starter .		Housing		1.00
- Shop Supplies		Housing		1.00
		Brake Pad		1.00
		Napagold Air Filter Caliper Washer		1.00
				4.00
		Non-chlor Brake Clnr		1.00
		Brk Fluid Dot 4-32oz		1.00
		Brake Hose		1.00
		Brake Hose		1.00
		Battry Motorcraft		1.00
		Shop Supplies		1.00
Hours: 9.60	Comm: 0.00	Labor: 700.80	Parts: 831.64	Total: 1,532.44

Work Order: 2107124 Meter: 77835 In Date: 06/29/2021 Closed:

Problem: PM Service . Tire light on .

Work Completed

- Preventive Maint. Service

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Palm Beach County Fleet Management Asset Maintenance History

2014 FORD F150 Pickup, 1/2 Ton 10194203

Work Order: 2107190 Meter: 77835 In Date: 06/30/2021 **Closed:** 06/30/2021

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 113.25 **Total Labor: 7,354.70** Total Comm: 192.00 **Total Parts: 7,364.04**