

1/3/2022
12:33:00 PM

10203142 Palm Beach County Fleet Management Asset Maintenance History
2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 70.50 Labor: 4,867.50 Parts: 8,619.28 Comm: 0.00 Charged: 13486.78

Work Order: 1700149 **Meter:** 1 **In Date:** 01/05/2017 **Closed:** 01/24/2017

Problem: install hitch ext, under coat frame

Work Completed

- Undercoat frame, install hitch extension
- Shop Supplies

Hours: 1.00 Comm: 0.00

Parts Issued

Quantity

Receiver Extension	1.00
Ball Mount 3/4"	1.00
Pin W/clip 5/8 For Hitch	2.00
Rubberized Undercoat	1.00
Shop Supplies	1.00

Labor: 60.00 Parts: 99.80 Total: 159.80

Work Order: 1700710 **Meter:** 1 **In Date:** 01/24/2017 **Closed:** 01/24/2017

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1801438 **Meter:** 758 **In Date:** 02/06/2018 **Closed:** 03/28/2018

Problem: pm/ no parking brakes

Work Completed

- pm with drive line service
- replace parking brake caliper assy and adjust
- Shop Supplies

Hours: 6.00 Comm: 0.00

Parts Issued

Quantity

Napagold Air Filter	1.00
Napagold Oil Filter	1.00
Fuel Filter	1.00
Napa Qt 15w40	3.00
Locking Diff Fluid Cc Only	2.00
Caliper Mech Park Brake	1.00
Shop Supplies	1.00
Freight Charge	1.00

Labor: 360.00 Parts: 301.46 Total: 661.46

1/3/2022
12:33:00 PM

10203142

Palm Beach County Fleet Management Asset Maintenance History
2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1904919

Meter: 1633

In Date: 05/06/2019 **Closed:** 05/20/2019

Problem: pm/ see list

Work Completed

- Pm Service w/drive train service
- Repl. parking brake & adjust
- Repl. front and rear brake pads & rotors
- Pressure test cooling system; repl. radiator & cooling pipe assy.; flush & bleed system
- Repl. battery & terminal end on wire to alternator
- Repl. 4 wheels, tires, valve stems & nitro fill
- Repl. front drive shaft
- Repl. both rear tail lamp assy's
- Wash cart & apply rubberized undercoating
- Fab & weld aluminum for tailgate latch
- Shop Supplies

Parts Issued

Quantity

Napa Qt 15w40	3.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Mobil 424 Fluid	4.00
Caliper Mech Park Brake	1.00
Front Brake Pad Set	1.00
Brake Rotor	4.00
Non-chlor Brake Clnr	3.00
1gal Rtu Antifreeze	1.00
Battery	1.00
25 X 11.00 X 12 Tire Kenda	4.00
propshaft	1.00
Led Rh S T T Lamp	1.00
Led Lh S T T W Lic	1.00
Blk/ct	2.00
Ptex Extend Rust Spry	1.00
295 Rear Brake Pad Kit	1.00
Radiator	1.00
Coolant Pipes	1.00
Pri112 Coolant Condit	1.00
wheel blk	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 22.00

Comm: 0.00

Labor: 1,474.00

Parts: 3,176.20

Total: 4,650.20

1/3/2022
12:33:00 PM

10203142

Palm Beach County Fleet Management Asset Maintenance History
2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1909498

Meter: 1772

In Date: 09/16/2019 **Closed:** 09/27/2019

Problem: trailing arms rusted out

Work Completed

- R/r inner outer front Cv axle boots (heavy rust)
- R/r lower link bars & hardwar and undercoat
- Shop Supplies

Parts Issued

Quantity

Cv Boot	1.00	
Cv Boot	1.00	
Wear Clip	4.00	
Nut	4.00	
Bolt	4.00	
Trailing Link Assy	2.00	
Blk/ct	1.00	
Shop Supplies	1.00	
Labor: 335.00	Parts: 280.34	Total: 615.34

Hours: 5.00

Comm: 0.00

1/3/2022
12:33:00 PM

Palm Beach County Fleet Management Asset Maintenance History
10203142 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2004991 **Meter:** 2087 **In Date:** 05/18/2020 **Closed:** 06/11/2020

Problem: pm service, no park brake, also brakes, squeeks when driving, frt end make noise out of 4x4

Work Completed

- pm service
- replace parking brake assy and rotor
- replace drive belt
- replace Lr axle bearing
- replace both front Cv axles
- replace worn leaking frnt differential
- replace worn front drive shaft
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	3.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Mobil 424 Fluid	4.00
Caliper Mech Park Brake	1.00
Bearings	1.00
Ring Retaining	1.00
Washer	1.00
Hux Nut	1.00
Locking Cap	1.00
Rotor Park Brake	1.00
Belt	1.00
propshaft	1.00
Front Diff	1.00
Washer	2.00
Nut	2.00
Front Halfshaft Awd	2.00
Blaster Penetrant	1.00
Shop Supplies	1.00

Hours: 14.00

Comm: 0.00

Labor: 1,022.00

Parts: 2,750.12

Total: 3,772.12

1/3/2022
12:33:00 PM

Palm Beach County Fleet Management Asset Maintenance History
10203142 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2100030 **Meter:** 2330 **In Date:** 01/04/2021 **Closed:** 01/29/2021
Problem: Coming in for broken tie bar/ axle bar on passenger side, dr shft broke, lift gate no tilt, park brake not working, strg

Work Completed

Parts Issued

Quantity

- Replace Rear Drive Shaft, (was seized / rusted to rear diff)	Glos Blk	2.00
- Fabricate New Mounts For Rear Axle & Weld On (old Rusted & Broke Off)	Rubberized Undercoat	2.00
- Replace Both Rear Wheel Bearings & Hubs	Bearings	2.00
- Replace Rear Brake Pads, Rotors, Service Calipers	Wheel Hub	2.00
- Replace Parking Brake Assembly	Non-chlor Brake Clnr	2.00
- Replace Electric Bed Lift Motor	Brake Rotor	2.00
- Replace Left Rear Taillamp Assembly & Fabricate Mount For Both Lamps And Install (rust & missing)	295 Rear Brake Pad Kit	1.00
- Secure Rear Fenders	Caliper Mech Park Brake	1.00
- Shop Supplies	Led Lh S T T W Lic	1.00
	Led Rh S T T Lamp	1.00
	Alum/cln	1.00
	Rear Propshaft	1.00
	Actuator Bed Lift	1.00
	Shop Supplies	1.00
Hours: 18.50 Comm: 0.00	Labor: 1,350.50 Parts: 2,011.38	Total: 3,361.88

Work Order: 2112800 **Meter:** 2330 **In Date:** 12/02/2021 **Closed:** 12/02/2021
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge		
Hours: 2.00 Comm: 0.00	Labor: 146.00 Parts: 0.00	Total: 146.00

Total Hours: 70.50 Total Labor: 4,867.50 Total Comm: 0.00 Total Parts: 8,619.28