Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 107.25 Labor: 7,068.70 Parts: 5,771.73 Comm: 38.16 Charged: 12878.58

Work Order: 1509703 Meter: 333 In Date: 09/25/2015 Closed: 09/25/2015

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1511097 Meter: 755 In Date: 10/29/2015 Closed: 11/04/2015

Problem: check trailer plug, charging message

 Work Completed
 Parts Issued
 Quantity

 - Replace and rewire trailer plug connection
 Female Conn Socket
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 1.50
 Comm: 0.00
 Labor: 90.00
 Parts: 13.12
 Total: 103.12

Work Order: 1601965 Meter: 6216 In Date: 02/25/2016 Closed: 03/07/2016

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		Napagold Oil Filter		1.00
- Rotate and balance all four tires	5.	5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Con-	centr	1.00
		Used Fire X Refurb	oished	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 43.34	Total: 223.34

Work Order: 1605758 Meter: 10704 In Date: 06/03/2016 Closed: 06/03/2016

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1606146 Meter: 11650 In Date: 06/15/2016 Closed: 06/29/2016

Problem: P.M. service and install strobe lights.

Work Completed	Parts Issued	Quantity
- P.m. Service.	Napagold Oil Filter	1.00
- Install four corner strobe lights.fabricate and install wiring and sv	itch. 5w20 Engine Oil	6.00
- Rotate and balance tires.	Napagold Air Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Vtx609c Led Strobe Cl	2.00
	Vtx609a Led Strobe Am	2.00
	Fuse Holder	1.00
	Rocker Led Blk Ambe	1.00
	Clr Rtv Silcn Sealant	1.00
	Fab Loom-split Poly	30.00
	Shop Supplies	1.00
Hours: 11.00 Comm:	.00 Labor: 660.00 Parts: 521.36	Total: 1,181.36

Work Order: 1610389 Meter: 16556 In Date: 10/04/2016 Closed: 10/20/2016

Problem: P.M. service and trailer not charging warming light on.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Replace and rewire corroded trailer connector.		Napagold Oil Filte	r	1.00
- Rotate and balance all tires.		22" Wiper Blade		2.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		trailer plug		1.00
		Shop Supplies		1.00
Hours: 4.25	Comm: 0.00	Labor: 255.00	Parts: 37.97	Total: 292.97

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1701604 Meter: 21635 In Date: 02/15/2017 Closed: 02/23/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Rotate and balance tires.		5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filte	er	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 34.24	Total: 214.24

Work Order: 1705868 Meter: 26558 In Date: 06/13/2017 Closed: 06/15/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Replaced all four ties.high speed balance all ti	placed all four ties.high speed balance all tires.nitro filled.			7.00
- Complete four wheel alignment.		22" Wiper Blade	22" Wiper Blade	
- Shop Supplies		Washer Fluid Concentr		1.00
		Used Fire X Refurb	oished	1.00
		183114470 P245-	-70r17	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 866.17	Total: 1,256.17

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1710204 Meter: 31388 In Date: 10/18/2017 Closed: 10/25/2017

Problem: P.M. service and change wiper blades.

Work Completed		Parts Issued		Quantity
P.m. service.Rotate and high speed balance all four tires.		5w20 Engine Oil		6.00
		Napagold Oil Filter		1.00
- Shop Supplies		22" Wiper Blade Washer Fluid Concentr		2.00
				1.00
		Used Fire X Refurb	oished	1.00
		Wd40 Spr		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 49.13	Total: 229.13

Work Order: 1803993 Meter: 35513 In Date: 04/17/2018 Closed: 04/23/2018

Problem: P.M. service and right rear tire going flat.

Work Completed		Parts Issued		Quantity
- P.m. service.				6.00
- Check battery and charging system .after fully charging battery ,battery		Napagold Oil Filte	r	1.00
failed load test .replace defective battery .	, , , , , , , , , , , , , , , , , , , ,			2.00
- Check and replace high mounted brake light be	eck and replace high mounted brake light bulb and retest.			1.00
- Resurface both rear rotors .replace brake pads ,service calipers and fglush		Rpl Bulb		1.00
and bleed brake system. Test drive.		Brake Pad		1.00
- Repair right rear tire and balance and rotate all	four tires.	Battry Motorcra		1.00
- Shop Supplies		lube		1.00
		Shop Supplies		1.00
Hours: 9.00	Comm: 0.00	Labor: 540.00	Parts: 437.26	Total: 977.26

Work Order: 1807634 Meter: 39776 In Date: 07/27/2018 Closed: 07/31/2018

Problem: needs spare key

Work Completed		Parts Issued		Quantity
- order and program one spare key		ford side key		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 60.00	Parts: 84.29	Total: 144.29

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1808441 Meter: 40890 In Date: 08/16/2018 Closed: 08/28/2018

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	6.00
- Replace two tires. Rotate and balance all four tires. Replace left front Tpm	Tpms Napagold Oil Filter	1.00
sensor . Nitrogen fill tires. Reset Tpms.	Used Fire X Refurbished	1.00
- Perform four wheel aligment and road test.	22" Wiper Blade	2.00
- Shop Supplies	Floor Mat-2pc Rub Bk	1.00
	Ford Triton Pvc Swc	1.00
	183114470 P245-70r17	2.00
	Tpms Sens Kit	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 6.50 Comm: 0.00	Labor: 390.00 Parts: 574.77	7 Total: 964.77

Work Order: 1809211 Meter: 41131 In Date: 09/07/2018 Closed: 09/07/2018

Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1901795 Meter: 45533 In Date: 02/15/2019 Closed: 02/27/2019

Problem: P.M. service and check engine light on.

Work Completed		Parts Issued		Quantity
- P.m. service.	5w20 Engine Oil		6.00	
- Replace two worn tires . Rotate and balance all four tires .	Napagold Oil Filte	ſ	1.00	
reset Tpms.	22" Wiper Blade		2.00	
- Computer diagnose check engine light , code P1450. Perfo	Napagold Air Filte	r	1.00	
	r&r defective stuck open purge valve . Clear code and retest .			2.00
 Perform complete front end alignment and road test. Shop Supplies 		Purge Valve		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 9.00 C	omm: 0.00	Labor: 603.00	Parts: 571.03	Total: 1,174.03

Problem: Wipers not clearing windshield.

Work Completed		Parts Issued		Quantity
- Test and clean windshield . Replace wiper blades	s and refill washer fluid .	Washer Fluid Con	centr	1.00
		22" Wiper Blade		2.00
Hours: 0.30	Comm: 0.00	Labor: 20.10	Parts: 8.79	Total: 28.89

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1907342 Meter: 50807 In Date: 07/16/2019 Closed: 07/25/2019

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service .	5w20 Engine Oil	7.00
- Resurface both front brake rotors and service calipers . Replace brake pad	e pads Napagold Oil Filter	1.00
and flush and bleed brake system . Road test .	22" Wiper Blade	2.00
- Service and inspect rear differential .	Used Fire X Refurbished	1.00
- Rotate and balance all four tires . Nitrofill all and reset Tpms.	Non-chlor Brake Clnr	1.00
- Shop Supplies	Brake Pad	1.00
	Dif Oil	2.00
	Brk Fluid Dot 4-12oz	2.00
	Washer Fluid Concentr	1.00
	Shop Supplies	1.00
Hours: 7.50 Comm: 0.00	Labor: 502.50 Parts: 214.61	Total: 717.11

Work Order: 1911963 Meter: 56663 In Date: 11/19/2019 Closed: 12/04/2019

Problem: P.M. Service.

Work Completed		Parts Issued	Quantity
- P.m. Service		Napagold Oil Filter	1.00
- Replace two tires,rotate and balance all four.		5w20 Engine Oil	7.00
- Shop Supplies		22" Wiper Blade	2.00
		Washer Fluid Concentr	1.00
		245/70/17 Tire Mich	2.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours: 4.00	Comm: 0.00	Labor: 292.00 Parts: 506.09	Total: 798.09

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2001904 Meter: 60892 In Date: 02/25/2020 Closed: 03/11/2020

Problem: Request spare key .

 Work Completed
 Parts Issued
 Quantity

 - Cut and program one spare key .
 ford side key
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 0.50
 Comm: 0.00
 Labor: 36.50
 Parts: 86.29
 Total: 122.79

Work Order: 2002215 Meter: 60552 In Date: 03/03/2020 Closed: 03/09/2020

Problem: need a spare key

Work CompletedParts IssuedQuantity- order and program 1 spare keyford side key1.00- Shop SuppliesShop Supplies1.00Hours: 1.00Comm: 0.00Labor: 73.00Parts: 86.29Total: 159.29

Work Order: 2003205 Meter: 61790 In Date: 03/30/2020 Closed: 04/06/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
Replace cabin air filter and clean fresh air intake .Rotate and balance all four tires . Nitrofill all.		5w20 Engine Oil		7.00
		Washer Fluid Concentr		1.00
- Shop Supplies		22" Wiper Blade Napagold Air Filter Cabin Air Filter		2.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 60.36	Total: 315.86

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2007574 Meter: 67245 In Date: 08/03/2020 Closed: 08/12/2020

Problem: P.M. Service.Recall.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Replace two tires . Rotate and balance all four tires . Nitrofill all.	5w20 Engine Oil	6.00
- Inspect and service rear differential . Remove rear pan to clean a	and reseal 22" Wiper Blade	2.00
due leaking . Refill with gear lube .	Washer Fluid Concentr	1.00
- Transport to and from dealer for recall 17s33 and 18s27 .	Used Fire X Refurbished	1.00
- Shop Supplies	Non-chlor Brake Clnr	1.00
	Px Grey Rtv Silicone	1.00
	1qt Syngear Oil 75-90	2.00
	245/70/17 Tire Mich	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.00 Comm:	0.00 Labor: 511.00 Parts: 562	2.42 Total: 1,073.42

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2102874 Meter: 77458 In Date: 03/15/2021 Closed: 03/23/2021

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Oil Filter		1.00
- Replace two tires, new on front, rotate and speed balance all four tires		5w20 Engine Oil		6.00
nitro fill		Washer Fluid Concentr		1.00
- Check all brks. R &i new rear pads, resurface both rotors, service an	tors, service and lube	22" Wiper Blade		2.00
 caliper slide pins, bleed brakes. Road test . Diagnose engine misfire . Check engine, Perform major tune-up R & I new plugs. and intake gasket . Perform Injector flush cleaning, Clean throttle body , Perform decarb 		245/70/17 Tire Mich		2.00
		Brk Fluid Dot 4-12oz		1.00
		Non-chlor Brake Clnr		1.00
		Brake Pad		1.00
 Perform complete front end alignment and road test. Shop Supplies 	t.	Spark Plugs		6.00
		Motor Tune-up 160)Z	1.00
		Throttle Body Cleaner Intake Cleaner Kit Shop Supplies		1.00
				1.00
				1.00
		Tire Disposal Fee		2.00
Hours: 16.20	Comm: 0.00	Labor: 1,182.60	Parts: 779.35	Total: 1,961.95

Work Order: 2109983 Meter: 85867 In Date: 09/15/2021 Closed: 09/23/2021

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service - Inspect All Tires Rotate And Balance With Nitro Fill		22" Wiper Blade		2.00
		Washer Fluid Concentr		1.00
- Shop Supplies		5w20 Engine Oil		6.00
		Napagold Oil Filter		1.00
		Used Fire X Refurbished		1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 219.00	Parts: 37.22	Total: 256.22

Palm Beach County Fleet Management Asset Maintenance History 10198937 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2110806 Meter: 86030 In Date: 10/05/2021 Closed: 10/06/2021

Problem: Had to jump start

Work Completed

- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Hook up lds to reset Bsm .

- Charge battery fully . Test battery and charging system . Battery failed load Shop Supplie

Battry Motorcraft 1.00
Shop Supplies 1.00

Quantity

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 139.86 Total: 249.36

Work Order: 2111781 Meter: 87346 In Date: 11/01/2021 Closed: 11/02/2021

Problem: Left rear tire going flat

Work CompletedParts IssuedQuantity- Repair left rear tire and balance . Replace defective Tpms sensor in left rearKit Tpms Sensor1.00. Nitro fill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 57.79 Total: 130.79

Work Order: 2200080 Meter: 89770 In Date: 01/04/2022 Closed: 01/04/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 107.25 Total Labor: 7,068.70 Total Comm: 38.16 Total Parts: 5,771.73