10203046

Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Total Hours: 65.50 Labor: 4,559.00 Parts: 5,138.22 Comm: 0.00 Charged: 9697.22

Work Order: 1700085 Meter: 1 In Date: 01/04/2017 Closed: 01/06/2017

Problem: install hitch ext

Work Completed Parts Issued Quantity Receiver Extension 1.00 - Install Hitch Extension Ball Mount 3/4" 1.00 - Shop Supplies Pin W/clip 5/8 For Hitch 2.00 **Shop Supplies** 1.00 Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 96.00 Total: 96.00

Work Order: 1700092 Meter: 1 In Date: 01/04/2017 Closed: 01/04/2017

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1800612 Meter: 378 In Date: 01/18/2018 Closed: 02/21/2018

Problem: pm service, need rear tires, park brake need adj, hard to start in am, idle to hi

Work Completed		Parts Issued		Quantity
- Pm- Replace 2 tires- Replace parking brake caliper assembly and adj		Napagold Air Filter		1.00
		Napagold Oil Filte	Napagold Oil Filter	
		Fuel Filter		1.00
- Shop Supplies		15-40 Oil		3.00
		Mobil 424 Fluid		4.00
		25 X 11.00 X 12 Tire Kenda		2.00
		Caliper Mech Park	: Brake	1.00
	Shop Supplies Tire Disposal Fee		1.00	
			2.00	
		Freight Charge		1.00
Hours: 7.50	Comm: 0.00	Labor: 450.00	Parts: 732.83	Total: 1,182.83

10203046

Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 1901782 Meter: 890 In Date: 02/14/2019 Closed: 02/28/2019

Problem: pm/ P brake

Work Completed		Parts Issued		Quantity
- Pm & Diff service		Napagold Air Filte	er	1.00
- Wash - Replace parking brake and disk rotor R&i drive shaft - Replace battery		Napagold Oil Filter		1.00
		Fuel Filter Napa Qt 15w40		1.00 3.00
		Pm-22-a Additive	Dies	1.00
		Mobil 424 Fluid		4.00
		Caliper Mech Park	Brake	1.00
		Rotor Park Brake		1.00
		Battery		1.00
		Shop Supplies		1.00
Hours: 9.00	Comm: 0.00	Labor: 603.00	Parts: 423.69	Total: 1,026.69

Work Order: 1907500 Meter: 1103 In Date: 07/19/2019 Closed: 07/31/2019

Problem: possible clutch/ see notes

Vork Completed Parts Issued			Quantity	
- r/r rear diff, found worn out clutch diska in locker assy. replace assy and		Carrier Locker Assy		1.00
test run		Px Grey Rtv Silicon	ne	1.00
- replace torn Rf outer Cv boot		Cv Boot		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 7.50	Comm: 0.00	Labor: 502.50	Parts: 1.629.56	Total: 2.132.06

10203046

Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2002232 Meter: 1426 In Date: 03/03/2020 Closed: 04/29/2020

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service		Napagold Oil Filter		1.00
- R&r alt. belt		Napa Qt 15w40		3.00
- R&r parking brake assembly and rotor		Napagold Air Filter		1.00
- R&r front lower a-arm bushings		Fuel Filter		1.00
- R&r front driveshaft		Non-chlor Brake Cl	nr	1.00
- R&r right front axle		Mobil 424 Fluid		4.00
- R&r horn		Caliper Mech Park I	Brake	1.00
- wash equipment		Bolt		2.00
- repair right rear taillight		Flg Nut		2.00
- cooling system service		Lower Arm Sleeve		2.00
- Shop Supplies		Lower Arm Bushing		4.00
		Horn		1.00
		Boxed Miniatures		1.00
		rad cap		1.00
		Rotor Park Brake		1.00
		propshaft		1.00
		Front Halfshaft Awd	d	1.00
		Rotell Elc Antifeerze	9	2.00
		V-belt		1.00
		Shop Supplies		1.00
Hours: 15.50	Comm: 0.00	Labor: 1,131.50	Parts: 993.46	Total: 2,124.9

10203046

Hours: 2.00

Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2012142 **Meter:** 1916 12/07/2020 **Closed:** 12/29/2020 In Date: **Problem:** pm/ 4x4/ rear axle/ front ball joints/ tires/ see comments **Parts Issued** Quantity **Work Completed** Napa Qt 15w40 3.00 - Preventive Maint, Service 1.00 Napagold Oil Filter - Replace 2 Tires Napagold Air Filter 1.00 - Replace Rear Light Bulbs Fuel Filter 1.00 - Replace Rear Brake Pads & Rotors, Service Calipers Mobil 424 Fluid 4.00 - Replace Drivers Front & Rear Wheel Bearings, Lr Hub Assembly (rear Bearing Was Seized In Axle Tube) **Boxed Miniatures** 2.00 - Wash Utility Cart Non-chlor Brake Clnr 2.00 - Shop Supplies **Brake Rotor** 2.00 295 Rear Brake Pad Kit 1.00 2.00 Bearings Wheel Hub 1.00 25 X 11.00 X 12 Tire Kenda 2.00 16.5 Oz Aero Kroil 1.00 **Shop Supplies** 1.00 Tire Disposal Fee 2.00 Hours: 20.00 Comm: 0.00 Labor: 1,460.00 Parts: 1,212.88 Total: 2,672.88 Work Order: 2113078 Meter: 2309 **In Date:** 12/10/2021 **Closed:** 01/07/2022 Problem: PM Service. **Work Completed Parts Issued** Quantity Belt 1.00 - evaluate equipment no pm completed, replacement arriving

 Work Completed
 Parts Issued
 Quantity

 - evaluate equipment no pm completed. replacement arriving
 Belt
 1.00

 - replace drive belt
 Shop Supplies
 1.00

 - Shop Supplies
 1.00

Labor: 146.00

Parts: 49.82

Total: 195.82

Comm: 0.00

10203046

Palm Beach County Fleet Management Asset Maintenance History 2017 CLUB CAR CARRYALL 1500 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)

Work Order: 2200392 Meter: 2309 In Date: 01/12/2022 Closed: 01/12/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 65.50 Total Labor: 4,559.00 Total Comm: 0.00 Total Parts: 5,138.22