Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Total Hours:	120.70	Labor: 8,113	.20	Parts: 5,434.67 Comm: 60.00			Charged: 13607.87		
Work Order: Problem:		e Delivery Ins	Meter:	337		In Date:	10/23/2015	Closed:	10/23/2015
Work Com	npleted								
- Pre Deliv	ery Inspec	tion							
		Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:		t, back of park	Meter: king lot fo		ard tower and will see him	In Date:	01/28/2016	Closed:	01/29/2016
Work Com	npleted								
- Tow Fror	m: 9301 s j	og rd							
	,	Hours: 0.00		Comm: 60.00	Labor: 0.00	Parts: 0.0	0	Total:	60.00
Work Order: Problem:		vice.	Meter:	5048		In Date:	02/22/2016	Closed:	02/29/2016
Work Com	pleted				Parts Issued			Qı	ıantity
- Pm servi	ce.				5w20 Engine Oil				7.00
- Rotate a	nd balance	all four tires.			Napagold Oil Filter				1.00
- Shop Su	pplies				Washer Fluid Concer	ntr			1.00
					Stg Wheel Cov - Ford	d			1.00
					Floor Mat-2pc Rub B	k			1.00
					Shop Supplies				1.00
		Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 66.	32	Total:	246.32
Work Order: Problem:		r tire going fla	Meter: t.	8824		In Date:	04/27/2016	Closed:	04/29/2016
Work Com	pleted				Parts Issued			Qı	ıantity
- Repair ar	nd balance	right rear tire	<u>.</u>		Shop Supplies				1.00
- Shop Su		J							
		Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Meter: 10269 Work Order: 1605102 In Date: 05/17/2016 **Closed:** 05/27/2016 Problem: P.M. Service.Install strobe lights. **Parts Issued** Quantity **Work Completed** 5w20 Engine Oil 7.00 - P.m. Service. 1.00 Napagold Oil Filter - Fabricate and install four corner strobes and wiring. Washer Fluid Concentr 1.00 - Rotate and balance all tires. Used Fire X Refurbished 1.00 - Shop Supplies Vtx609c Led Strobe Cl 2.00 Vtx609a Led Strobe Am 2.00 Fuse Holder 1.00 Ds-364 Rocker Switch 1.00 Fab Loom-split Poly 10.00 Clr Rtv Silcn Sealant 1.00 **Shop Supplies** 1.00 Hours: 11.00 Comm: 0.00 Labor: 660.00 Parts: 526.25 Total: 1.186.25 Work Order: 1608960 Meter: 14983 In Date: 08/29/2016 **Closed:** 08/31/2016 Problem: P.M. Service. Quantity **Work Completed Parts Issued** 5w20 Engine Oil 7.00 - P.m. Service. Napagold Oil Filter 1.00 - Rotate and balance all tires. Washer Fluid Concentr 1.00 - Shop Supplies **Shop Supplies** 1.00 Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 22.10 Total: 202.10 Work Order: 1612686 Meter: 19058 In Date: 12/12/2016 **Closed:** 01/06/2017 Problem: Connect and install GPS system. **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Install costomer supplied Gps. - Shop Supplies Hours: 1.00 Parts: 2.00 Total: 62.00 Comm: 0.00 Labor: 60.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	1700579 P.M. Service.	Meter:	20085		In Date:	01/19/2017	Closed:	01/31/2017
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. Serv	ice.			5w20 Engine Oil				7.00
- Rotate an	nd balance tires.			Napagold Oil Filter				1.00
- Shop Sup	pplies			Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
				Used Fire X Refurbisl	hed			1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 44.	72	Total:	224.72
Work Order: Problem:	1701303 Right front tire going flat.	Meter:	20901		In Date:	02/08/2017	Closed:	02/22/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair an	d balance right front tire.			Shop Supplies				1.00
- Shop Sup	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:	1702529 Right front tire flat .Spare on truck.	Meter:	22271		In Date:	03/13/2017	Closed:	03/27/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair an	d balance right front tire.			Shop Supplies				1.00
- Shop Sup	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:	1702740 Flat tire; Lake worth ROad, west of	Meter: 441. Bey		d gate, can see vehicle fr	In Date: rom gate.	03/10/2017	Closed:	03/17/2017
Work Com	pleted							
	ce Wycliff Country Club; - Flat tire; Lacliff guard gate, can see vehicle from		Road, west of 44	41.				

Comm: 0.00

Labor: 0.00

Parts: 0.00

Hours: 0.00

Total: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1704137 Meter: 23353 In Date: 04/25/2017 Closed: 04/28/2017

Problem: Right rear tire going flat.

Work CompletedParts IssuedQuantity- Repair right rear flat tire.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1706386 Meter: 25476 In Date: 06/28/2017 Closed: 07/10/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Tpms12 Sensor Tir	1.00	
- Four new tires mounted, nitorgen fill, and high speed b	alanced.right rear	Kit Tpms Sensor		1.00
tire pressure sensor failed R&r with new.		Stg Wheel Cov - Fo	1.00	
- Complete front end alignment.		5w20 Engine Oil	6.00	
- Shop Supplies		Napagold Oil Filte	1.00	
		22" Wiper Blade		2.00
		Mac Wite Lithium	1.00	
		P245/70 Tire Gdy Napagold Air Filter Shop Supplies Tire Disposal Fee		4.00
				1.00
				1.00
				4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 978.58	Total: 1,368.58

Work Order: 1711897 Meter: 30357 In Date: 12/05/2017 Closed: 12/18/2017

Problem: P.M. service.

Work Completed	Parts Issued	Quantity		
- P.m. service.	5w20 Engine Oil	7.00		
- Rotate and balanced all four tires.nitrogen fill tires.	Napagold Oil Filte	1.00		
- Shop Supplies		Washer Fluid Concentr		1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 29.18	Total: 209.18

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1712128 Meter: 30357 In Date: 12/11/2017 Closed: 12/12/2017

Problem: weld tool box lid

Work CompletedParts IssuedQuantity- Reweld Broke toolbox LidShop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1804976 Meter: 35144 In Date: 05/14/2018 Closed: 05/21/2018

Problem: P.M. service, Tool box lid broken, left rear tire flat and trailer warning on.

Work Completed	Parts Issued		Quantity	
- P.m. service.	5w20 Engine Oil		6.00	
- Diagnoise trailer warning light on with scan to	Napagold Oil Filter		1.00	
and clean connections .reseal socket and retest of	Washer Fluid Concentr		1.00	
- Repair left rear tire .rotate and balance all four	22" Wiper Blade Used Fire X Refurbished		2.00	
- Repair and weld tool box lid .				
- Shop Supplies		Shop Supplies		1.00
Hours: 5.80	Comm: 0.00	Labor: 348.00	Parts: 41.36	Total: 389.36

Work Order: 1810671 Meter: 40408 In Date: 10/16/2018 Closed: 10/22/2018

Problem: P.M. service.

Work Completed	Parts Issued		Quantity	
- P.m. service.	Napagold Oil Filte	r	1.00	
- Resurface rear brake rotors . Replace brake pads and servic	5w20 Engine Oil		6.00	
Flush and bleed brake system . Test drive.	Napagold Air Filter		1.00	
- Repair two leaks in left rear tire and rotate and balance all f	Washer Fluid Concentr		1.00	
Nitrogen fill tires .		22" Wiper Blade		2.00
- Shop Supplies		Brake Pad Non-chlor Brake Clnr Shop Supplies		1.00
				1.00
				1.00
Hours: 7.50 Co	mm: 0.00	Labor: 502.50	Parts: 118.80	Total: 621.30

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1812481 Meter: 41927 12/07/2018 **Closed**: 12/10/2018 In Date: Problem: Battery low, Low pressure light on right front tire. Parts Issued **Work Completed** Quantity Battry Motorcraft 1.00 - Charge battery fully . Battery failed load test . R&r defective battery . Retest starting and charging systems. **Shop Supplies** 1.00 - Repair right front tire and balance . Nitrofill all. - Shop Supplies Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 176.39 Total: 310.39 Work Order: 1903496 Meter: 45306 In Date: 04/01/2019 **Closed:** 04/10/2019 Problem: P.M. service. **Work Completed Parts Issued** Quantity 1.00 Napagold Oil Filter - P.m. service and replace steering wheel cover. 5w20 Engine Oil 6.00 - Computer diagnose check engine light, code P1450. R&r defective evap canister and purge valve. Clear codes and retest. Road test. Washer Fluid Concentr 1.00 - Rotate and high speed balance all four tires . Nitrofill all. 22" Wiper Blade 2.00 - Shop Supplies Mac Wite Lithium Gres 1.00 Ford Triton Pvc Swc 1.00 Used Fire X Refurbished 1.00 Purge Valve 1.00 1.00 Cannister **Shop Supplies** 1.00 Hours: 6.00 Comm: 0.00 Labor: 402.00 Parts: 191.87 Total: 593.87 Work Order: 1904606 Meter: 45913 In Date: 04/29/2019 **Closed**: 04/30/2019 **Problem:** Right rear passenger tire. **Work Completed Parts Issued** Quantity **Shop Supplies** 1.00 - Repair right rear tire and balance. Nitrofill all tires. - Shop Supplies

Comm: 0.00

Labor: 67.00

Parts: 3.00

Total: 70.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1907434 Meter: 49623 In Date: 07/18/2019 Closed: 07/23/2019

Problem: Left rear tire leaking.

Work Completed Parts Issued Quantity
- Repair left rear tire and balance . Nitrofill all. Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

Work Order: 1908011 Meter: 50490 In Date: 08/02/2019 Closed: 08/15/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. Service.	Napagold Oil Filte	1.00		
- Pressure test and inspect cooling system.flush ar	5w20 Engine Oil	6.00		
- Rotate and balance tires.	22" Wiper Blade	2.00		
- Shop Supplies	Brk Fluid Dot 4-12	1.00		
		Anti Freeze Motorcraft		2.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 335.00	Parts: 90.14	Total: 425.14

Work Order: 1910671 Meter: 53597 In Date: 10/17/2019 Closed: 10/21/2019

Problem: Both front tires slow leak.

Work Completed	Parts Issued	Quantity		
- Replace both front tires and balance . Nitrofill a	245/70/17 Tire M	2.00		
- Shop Supplies	Shop Supplies	1.00		
	Tire Disposal Fee		2.00	
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 473.72	Total: 546.72

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1912296 Meter: 55621 In Date: 12/02/2019 Closed: 12/18/2019

Problem: P.M. service and right rear tire going flat .

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Inspect and service transmission . Flush and refill transmission and re	place 5w20 Engine Oil	6.00
filter .	Napagold Air Filter	1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitr	ofill all. 22" Wiper Blade	2.00
- Perform complete front end alignment and road test .	Screen Asy	1.00
- Repair right rear tire and balance all four tires . Nitrofill .	oil auto	16.00
- Shop Supplies	245/70/17 Tire Mich	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 10.00 Comm: 0.00	Labor: 730.00 Parts: 675.40	Total: 1,405.40

Work Order: 1913152 Meter: 56853 In Date: 12/30/2019 Closed: 01/08/2020

Problem: Right front tire going flat .

Work Completed	Parts Issued		Quantity	
- Repair right front tire and balance . Nitrofill all tires .	Shop Supplies	1.00		
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Problem: P.M. service.

Work Completed	Parts Issued		Quantity
- P.m. service.	Napagold Oil Filter		1.00
- Replace cabin air filter and clean fresh air intake .	5w20 Engine Oil		6.00
- Resurface both front brake rotors and service calipers . Replace brake pad	Washer Fluid Concentr		1.00
. Flush and bleed brake system . Road test .	22" Wiper Blade		2.00
- Rotate and high speed balance all four tires . Nitrofill all.	Used Fire X Refurbished	l	1.00
- Shop Supplies	Ford Triton Pvc Swc		1.00
	Brake Pad		1.00
	Cabin Air Filter		1.00
	Shop Supplies		1.00
Hours: 7.00 Comm: 0.00	Labor: 511.00	Parts: 141.37 Tota	al: 652.37

Work Order: 2006652 Meter: 66433 In Date: 07/07/2020 Closed: 07/16/2020

Problem: P.M. service and recalls 17S33 and 18S27.

Work Completed	Parts Issued		Quantity	
- P.m. service.	5w20 Engine Oil		7.00	
- Rotate and balance all four tires . Nitrofill all.		Napagold Oil Filte	r	1.00
- Transport to and from dealer for recalls 17s33 an	Washer Fluid Cond	centr	1.00	
- Shop Supplies		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 365.00	Parts: 36.39	Total: 401.39

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2010512 Problem: P.M. Service and rear tires going		71223		In Date:	10/20/2020	Closed:	10/22/2020								
Work Completed		Parts Issued			Qı	uantity									
Performed Pm serviceRepair both rear tire flats; rotate, balance and relearn four tires.Shop Supplies			Napagold Oil Filter 5w20 Engine Oil Washer Fluid Concentr			7.00 1.00									
											22" Wiper Blade				2.00
											Steering Wheel Co	over Large			1.00
			Shop Supplies				1.00								
Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 62.	85	Total:	354.85								
Work Order: 2010634 Problem: Front right tire low.	Meter:	71457		In Date:	10/23/2020	Closed:	10/26/2020								
Work Completed			Parts Issued			Qı	uantity								
- Tire Repair, Balance & Nitro Service			Shop Supplies				1.00								
- Shop Supplies															
Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00								
Work Order: 2100804 Problem: Left front tire going flat .	Meter:	75532		In Date:	01/25/2021	Closed:	01/25/2021								
Work Completed			Parts Issued		Qı	uantity									
- Repair left front tire and balance . Nitro fill a	ıll.		Shop Supplies				1.00								
- Shop Supplies															
Hours: 1.00		Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00								

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2101928 Meter: 77179 In Date: 02/22/2021 Closed: 03/03/2021

Problem: P.M. Service check tire for nails, spare on vehicle.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Replaced cabin filter. Cleaned debris from fresh air intake.	5w20 Engine Oil	7.00
- Performed tune-up. Replace all six spark plugs	22" Wiper Blade	2.00
- Performed air intake decarb and cleaning and fuel system flush.	Used Fire X Refurbished	1.00
- Replaced 2 tires due to damage beyond repair. Rotated and balanced all	Cabin Filter	1.00
tires. Nitrogen filled all tires.	Gasket	1.00
- Shop Supplies	Spark Plugs	6.00
	Motor Tune-up 16oz	1.00
	Intake Cleaner Kit	1.00
	245/70/17 Tire Mich	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 9.70 Comm: 0.00	Labor: 708.10 Parts	. 761.78 Total: 1,469.88

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2106221 Meter: 83146 In Date: 06/08/2021 Closed: 06/14/2021

Problem: P.M. Service

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Washer Fluid Concentr	1.00
- Resurface Front Rotors Due To Pulsation; R&r Brake Pads, Lube Ca	iper 22" Wiper Blade	2.00
Slide Pins, Bleed Brakes And Road Test To Verify Repair.	Napagold Oil Filter	1.00
- Mount Two New Tires, R&r Valve Stems, Nitrogen Fill; Rotate And	Balance 5w20 Engine Oil	6.00
Four.	Non-chlor Brake Clnr	1.00
- Load Test Battery, Recharge And Retest. R&r Failed Battery And Re	set Bms Brk Fluid Dot 4-32oz	1.00
With Scan Tool.	Tire Pressure Monitoring System Sensor	2.00
- Shop Supplies	245/70/17 Tire Mich	2.00
	Battry Motorcraft	1.00
	Brake Pad	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 9.00 Comm: 0.0	00 Labor: 657.00 Parts: 876.91	Total: 1,533.9

Work Order: 2107947 Meter: 84935 In Date: 07/22/2021 Closed: 07/28/2021

Problem: Please check GPS connections. GPS reported not working.

Work Completed

- Reattach Gps to Dlc connector and wire tie together .

Hours: 0.20 Comm: 0.00 Labor: 14.60 Parts: 0.00 Total: 14.60

Palm Beach County Fleet Management Asset Maintenance History 10198943 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2111268 Meter: 89769 In Date: 10/20/2021 Closed: 11/09/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity	
- Preventive Maint. Service	Napagold Oil Filter		1.00		
- Rotate and speed balance, nitro fill, R	5w20 Engine Oil		6.00		
does not Program - Shop Supplies		Washer Fluid Concentr		1.00	
		22" Wiper Blade		2.00	
		Napagold Air Filter		1.00	
		Tpms Sens Kit		1.00	
		Shop Supplies		1.00	
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 90.57	Total: 382.57	

Work Order: 2201407 Meter: 94397 In Date: 02/08/2022 Closed: 02/08/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 120.70 Total Labor: 8,113.20 Total Comm: 60.00 Total Parts: 5,434.67