Hours: 1.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Total Hours:	Total Hours: 107.50 Labor: 7,337.50 Parts: 6,348.72		Comm: 5,248.98		Charged: 18935.20		
Work Order: Problem:	1700296 N 1061 - Pre Delivery Insp	Meter: 332 ection		In Date:	01/10/2017	Closed:	01/10/2017
Work Con	npleted						
- Pre Deliv	very Inspection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	00	Total:	120.00
Work Order: Problem:		Meter: 5426 ning light on.Driver door panel loose		In Date:	05/01/2017	Closed:	05/11/2017
Work Con	ıpleted		Parts Issued			Qı	uantity
- P.m. serv	vice.		5w20 Engine Oil				6.00
- Replace	defective trailer pug and r	einstall drivers door panel that came	Napagold Oil Filter				1.00
loose at fa	steners.retest	·	Floor Mat-2pc Rub	Bk			1.00
- Rotate a	nd high speed balance all	four tires.	Stg Wheel Cov - Fo	rd			1.00
- Shop Su	pplies		trailer plug				1.00
			Clr Rtv Silcn Sealant	t			1.00
			Shop Supplies				1.00
	Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 80	.33	Total:	350.33
Work Order: Problem:	1707039 Number 1707039 Left rear tire has screw.	Meter: 10110		In Date:	07/19/2017	Closed:	07/31/2017
Work Con	npleted		Parts Issued			Qı	uantity
- Repair a	nd balance left rear tire,fla	t.	Shop Supplies				1.00
- Shop Su	pplies						
-							

Labor: 60.00

Parts: 2.00

Total: 62.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	1708451 P.M. Service.Left front tire pr	Meter: ressure low.Body			In Date:	08/28/2017	Closed:	09/07/2017
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Repair le	ft front tire,flat.rotate and bala	ance four tires.		Napagold Oil Filter				1.00
- Shop Sup				Washer Fluid Concer	ntr			1.00
				22" Wiper Blade				2.00
				Used Fire X Refurbish	ned			1.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 40.	.81	Total:	280.81
Work Order: Problem:	1709679 Dents in right side of cab & c	Meter: door, black marks			In Date:	09/05/2017	Closed:	10/03/2017
Work Com	pleted							
- Dents in	right side of cab & door, blac	k marks on all rig	ht side					
	Hours: 0.00		Comm: 900.00	Labor: 0.00	Parts: 0.0	00	Total:	900.00
Work Order: Problem:	1710638 replace tail light damaged from	Meter: om	13572		In Date:	10/27/2017	Closed:	10/31/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Replace t	ail light			Lamp Assy				1.00
- Shop Sup	3			Ptex Ultra Black 30z				1.00
' '	•			Shop Supplies				1.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 90.	.04	Total:	150.04
Work Order: Problem:	1711524 Left rear tire going flat.	Meter:	15248		In Date:	11/22/2017	Closed:	11/29/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair le	ft rear tire and balance .nitro s	service.		Shop Supplies				1.00
- Shop Sup								
1 121	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	00	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1712152 Meter: 16179 In Date: 12/12/2017 Closed: 12/18/2017

Problem: Right rear tire going flat.

Work CompletedParts IssuedQuantity- Repair right rear tire.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1712648 Meter: 16659 In Date: 12/22/2017 Closed: 12/28/2017

Problem: Had to jump start.

Work CompletedParts IssuedQuantity- Charge battery fully .test battery and charging system.battery failed load
test .r&r defective battery.Battry Motorcraft1.00Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 173.54 Total: 233.54

Work Order: 1800010 Meter: 17205 In Date: 01/02/2018 Closed: 01/16/2018

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. Service.		183114470 P245-7	70r17	4.00
- Replace and balance four new tires.		5w20 Engine Oil		6.00
- Complete wheel alignment.test drive.	Napagold Oil Filter	•	1.00	
- Shop Supplies		22" Wiper Blade		2.00
		Napagold Air Filte	r	1.00
		Used Fire X Refurbished Ford Triton Pvc Swc Shop Supplies		1.00
				1.00
				1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 893.55	Total: 1,283.55

Hours: 3.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

2.30.17 11	10202	2130 2017	FORD FISH FICK	.up, 1/2 10Π				
Work Order:		Meter:	18578		In Date:	02/05/2018	Closed:	02/06/2018
Problem:	Right rear tire flat ,spare on truc	k.						
Work Com	pleted			Parts Issued			Qı	uantity
- Replace	right rear tire and balance .nitrog	en fill tires an	d remount spare.	183114470 P245-70	Or17			1.00
- Shop Su			·	Shop Supplies				1.00
	•			Tire Disposal Fee				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 208	8.72	Total:	238.72
Work Order:	1801842	Meter:	19460		In Date:	02/16/2018	Closed:	02/21/2018
Problem:	Screw in tire, right rear.							
Work Com	pleted			Parts Issued			Qı	uantity
- Replace	right rear tire and balance .			183114470 P245-70	Or17			1.00
- Shop Su	3			Shop Supplies				1.00
' '				Tire Disposal Fee				1.00
	Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 208	8.72	Total:	238.72
Work Order:	1803947	Meter:	22599		In Date:	04/17/2018	Closed:	04/23/2018
Problem:	needs 2 toll box keys							
Work Com	pleted			Parts Issued			Qı	uantity
- secure ke	eys for dept			Tool Box Key				2.00
	Hours: 0.00		Comm: 0.00	Labor: 0.00	Parts: 27.	.24	Total:	27.24
Work Order:	1804067	Meter:	23011		In Date:	04/19/2018	Closed:	04/25/2018
Problem:	P.M. service.							
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	rice.			5w20 Engine Oil				6.00
- Rotate a	nd balance all four tires .nitrogen	fill tires.		Napagold Oil Filter				1.00
- Shop Su	oplies			22" Wiper Blade				2.00
	•							

Comm: 0.00

Shop Supplies

Labor: 180.00

Parts: 25.18

1.00

Total: 205.18

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1808534 Meter: 28887 In Date: 08/20/2018 Closed: 08/28/2018

Problem: P.M. service and right rear tire flat.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Rotate and high speed balance all four tires . Repair right rear tire	5w20 Engine Oil	6.00
Nitrogen fill all.	Napagold Air Filter	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Ford Triton Pvc Swc	1.00
	Shop Supplies	1.00
Hours: 4.00 Comm: 0.	00 Labor: 240.00 Parts: 68.98	Total: 308.98

Work Order: 1812503 Meter: 34762 In Date: 12/10/2018 Closed: 12/13/2018

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
Rotate and balance all four tires. Nitrofill all.Shop Supplies		Napa Quart 5w20	7.00	
		22" Wiper Blade		2.00
		Washer Fluid Concentr 183114470 P245-70r17 Shop Supplies Tire Disposal Fee		1.00
				2.00
				1.00
				2.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 457.45	Total: 658.45

Work Order: 1901464 Meter: 37794 In Date: 02/07/2019 Closed: 02/07/2019

Problem: Right rear tire going flat .

Work Completed		Parts Issued		Quantity
- Repair right rear tire and balance . Nitrogen fill all.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 3.00	Total: 70.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1903102 Meter: 39936 In Date: 03/21/2019 Closed: 03/22/2019

Problem: Left rear tire flat.

Work CompletedParts IssuedQuantity- Repair and balance left rear tire.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 3.00 Total: 70.00

Work Order: 1903421 Meter: 40540 In Date: 03/29/2019 Closed: 04/08/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	1.00	
- Replace two worn tires . Rotate and balance all four tires .	5w20 Engine Oil		7.00	
- Shop Supplies		22" Wiper Blade		2.00
		Washer Fluid Concentr		1.00
		245/70/17 Tire Mich Shop Supplies		2.00
				1.00
		Tire Disposal Fee		2.00
Hours: 4.00 Co	omm: 0.00	Labor: 268.00	Parts: 520.89	Total: 788.89

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 1909595 Meter: 47208 In Date: 09/18/2019 Closed: 09/27/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter	ſ	1.00
- Resurface both front and rear rotors and service calipers	s . Replace brake	5w20 Engine Oil		6.00
pads . Flush and bleed brake system . Road test .		22" Wiper Blade		2.00
- Check battery and charging system after fully charging b	Napagold Air Filter Used Fire X Refurbished lube		1.00	
failed load test . R&r defective battery .			1.00	
- Balance and rotate all four tires . Nitrofill all.			1.00	
- Shop Supplies		Brk Fluid Dot 4-32oz Brake Pad Brake Pad Battry Motorcraft		1.00
				1.00
				1.00
				1.00
		Shop Supplies		1.00
Hours: 11.00	Comm: 0.00	Labor: 737.00	Parts: 416.90	Total: 1,153.90

Work Order: 1910036 Meter: 47208 In Date: 09/30/2019 Closed: 10/07/2019

Problem: replace cracked windsheild

Work Completed		Parts Issued		Quantity
- set up repairs & reasset		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 598.07	Labor: 73.00	Parts: 4.00	Total: 675.07

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2000480 Meter: 52634 In Date: 01/15/2020 Closed: 01/24/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Replace two worn tires and valve stems . Rotate and	5w20 Engine Oil		7.00	
all four tires . Nitrofill all.	22" Wiper Blade		2.00	
- Complete front end alignment and road test .	Washer Fluid Concentr		1.00	
- Shop Supplies		Tire Pressure Monitoring System Sensor (245/70/17 Tire Mich Shop Supplies Tire Disposal Fee		2.00
				2.00
				1.00
				2.00
Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 630.23	Total: 1,104.73

Work Order: 2004772 Meter: 58700 In Date: 05/12/2020 Closed: 05/26/2020

Problem: P.M. service and recalls 17S33 and 18S27.

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	6.00
- Replace cabin air filter and clean fresh air intake .	Napagold Oil Filter	1.00
- Service and inspect transmission . Replace filter and flush and refill	Washer Fluid Concentr	1.00
transmission fluid .	22" Wiper Blade	2.00
- Pressure test and inspect cooling system . Flush and refill colling syste	em . Napagold Air Filter	1.00
- Repair left rear tire . Rotate and balance all four tires . Nitrofill all and	reset A/fresh	1.00
Tpms .	Cabin Air Filter	1.00
- Road test . Measure rotor runout on all four rotors . Resurface all four brake rotors and service calipers . Road test .	Screen Asy	1.00
- Transport to and from dealer for recalls 17s33 and 18s27 .	oil auto	16.00
·	Anti Freeze Motorcraft	2.00
- Shop Supplies	Shop Supplies	1.00
Hours: 15.00 Comm: 0.00	Labor: 1,095.00 Parts: 269.71	Total: 1,364.71

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2006609 Meter: 60381 In Date: 07/06/2020 Closed: 07/07/2020

Problem: Right rear tire low

Work CompletedParts IssuedQuantity- Repair right rear tire and balance . Nitrofill all.Shop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2010412 Meter: 64676 In Date: 10/16/2020 Closed: 10/21/2020

Problem: P.M. service.

Work Completed		Parts Issued		Quantity	
- P.m. service.		5w20 Engine Oil		7.00	
- Replace two tires and repair left rear tire . Replace right tire pressure		Napagold Oil Filter		1.00	
sensor . Rotate and balance all four tires . Nitrofill all and	l reset Tpms .	22" Wiper Blade		2.00	
- Test and replace defective strobe light switch . Retest .		Used Fire X Refurb	ished	1.00	
	ngine misfire . Perform complete tune up . Replace all six spark				2.00
plugs and intake gaskets . Clear codes and retest .		Tpms Sens Kit Led Rocker Switch Round Spark Plugs		1.00	
- Perform complete air intake decarb and cleaning . Flush injectors .- Perform front end alignment and road test .	1.00				
	6.00				
- Shop Supplies		Intake Clea			1.00
			Motor Tune-up 16oz		
		Boot Ing Gasket Gasket Shop Supplies		2.00	
				1.00	
				1.00	
				1.00	
		Tire Disposal Fee		2.00	
Hours: 12.70	Comm: 0.00	Labor: 927.10	Parts: 713.02	Total: 1,640.12	

Work Order: 2011440 Meter: 64710 In Date: 10/20/2020 Closed: 11/16/2020

Problem: damage to right front door

Work Completed

- damage to right front door

Hours: 0.00 Comm: 501.00 Labor: 0.00 Parts: 0.00 Total: 501.00

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2103086 Meter: 70235 In Date: 03/19/2021 Closed: 03/23/2021

Problem: Right rear tire going low.

Work Completed		Parts Issued		Quantity
- Replaced Rr tire due to hole in side wall.		245/70/17 Tire Mich Shop Supplies Tire Disposal Fee		1.00
- Shop Supplies				1.00
				1.00
Hours: 0.50	Comm: 0.00	Labor: 36.50	Parts: 285.84	Total: 322.34

Work Order: 2103296 Meter: 70487 In Date: 03/24/2021 Closed: 04/01/2021

Problem: P.M. Service

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	5w20 Engine Oil	7.00
- Rotate And Balance All Tires With Nitro Fill	Napagold Oil Filter	1.00
- Pressure Test Cooling System Drain Coolant Replace Water Pump &	22" Wiper Blade	2.00
Thremastat Housing Flush and refill coolant . Replace A/c belt and main	Napagold Air Filter	1.00
drive belt .	Anti Freeze Motorcraft	1.00
- Shop Supplies	Gasket	1.00
	Tmermostat Housing	1.00
	Water Pump	1.00
	V Belt	1.00
	V Belt	1.00
	Shop Supplies	1.00
Hours: 9.00 Comm: 0.00	Labor: 657.00 Parts: 599.86	Total: 1,256.86

Work Order: 2107592 Meter: 75504 In Date: 07/13/2021 Closed: 07/14/2021

Problem: Towed in right rear tire flat . Tire Blow out

Work Completed		Parts Issued		Quantity
- Replace both rear tires and balance . Nitro fill all.		245/70/17 Tire Mi	ich	2.00
- Shop Supplies		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 417.08	Total: 490.08

Palm Beach County Fleet Management Asset Maintenance History 10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2107821 Meter: 75671 In Date: 07/13/2021 Closed: 07/19/2021

Problem: Tire Blow out

Work Completed

- Tow From: Turnpike s/b just s of Southern blvd To:

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2109603 Meter: 78183 In Date: 09/02/2021 Closed: 09/15/2021

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	5w20 Engine Oil	7.00
- Check and R & I new Rr tail lamp asm, broken. Reinstall strobe I	amp Napagold Oil Filter	1.00
- Check all brakes, R & I new front brakes, Resurface both rotors,	Service Washer Fluid Concentr	1.00
caliper slide pins , bleed brakes Road test	22" Wiper Blade	2.00
- Rotate and speed balance all wheels, nitro fill	Steering Wheel Cover Large	1.00
- Check and replace cabin filter and clean fresh air intake .	Used Fire X Refurbished	1.00
- Shop Supplies	Brk Fluid Dot 4-12oz	1.00
	Non-chlor Brake Clnr	1.00
	Brake Pad	1.00
	Cabin Air Filter	1.00
	Lamp Assy	1.00
	Shop Supplies	1.00
Hours: 7.80 Comm:	0.00 Labor: 569.40 Parts: 198.02	Total: 767.42

Work Order: 2200053 Meter: 81937 In Date: 01/04/2022 Closed: 01/05/2022

Problem: leaking tire (drivers side rear, front end damage accident 12.39.21. report pending, rear bumper, unknown cause....

Work Completed		Parts Issued		Quantity
- Repair left rear tire and balance . Nitro fill all.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History

10202150 2017 FORD F150 Pickup, 1/2 Ton

Work Order: 2201451 Meter: 81937 In Date: 01/04/2022 Closed: 02/08/2022

Problem: Description of repairs: Damage to rear bumper, tail gate, front bumper, right front fender, right head light & bezel

Work Completed

- Description of repairs: Damage to rear bumper, tail gate, front bumper, right front fender, right head light & bezel

Hours: 0.00 Comm: 3,159.51 Labor: 0.00 Parts: 0.00 Total: 3,159.51

Work Order: 2201759 Meter: 81937 In Date: 02/16/2022 Closed: 02/16/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 107.50 Total Labor: 7,337.50 Total Comm: 5,248.98 Total Parts: 6,348.72