

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Total Hours: 106.35 Labor: 6,999.55 Parts: 3,790.93 Comm: 1,529.63 Charged: 12320.11

Work Order: 1007559 **Meter:** 118 **In Date:** 07/19/2010 **Closed:** 07/19/2010
Problem: Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1107423 **Meter:** 5666 **In Date:** 07/14/2011 **Closed:** 07/22/2011
Problem: P.M. service .

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00
Ch10358 Oil Filter Lbf P980 Wix 57064 1.00
75-540 0w/20 Motor Oil 5.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 42.17 Total: 222.17

Work Order: 1205672 **Meter:** 12666 **In Date:** 06/14/2012 **Closed:** 06/27/2012
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00
Ch10358 Oil Filter Lbf P980 Wix 57064 1.00
75-540 0w/20 Motor Oil 5.00
Nb-18 Wiper Blades 18" Anco 31-18 1.00
31-24 Wiper Blades 24" Blade 1.00
8524247030 Rear Wiper Blade (2010 Prius) 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 55.92 Total: 235.92

Work Order: 1209128 **Meter:** 13053 **In Date:** 09/21/2012 **Closed:** 09/24/2012
Problem: No start (sheduled to be towed 9/24/12 am)

Work Completed

- Tow From: 810 Datura St, Wpb To: Lv Shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1209225 **Meter:** 13298 **In Date:** 09/26/2012 **Closed:** 09/28/2012
Problem: Towed in for no start.

Work Completed

- Recharge battery and test system.good.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1212380 **Meter:** 16781 **In Date:** 12/28/2012 **Closed:** 01/16/2013
Problem: Pm service.

Work Completed

- P.m. Service.
- Replace rear asset #
- Recharge and test battery.good.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

0w-20 Motor Oil	5.00
Ch10358 Oil Filter Lb	1.00
31-18 Wiper Blades 18	1.00
31-24 Wiper Blades 2	1.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 57.05 Total: 297.05

Work Order: 1304035 **Meter:** 21951 **In Date:** 04/24/2013 **Closed:** 05/02/2013
Problem: Pm service.

Work Completed

- Perform pm service.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

Syn0w20	4.00
Napagold Oil Filter	1.00
Washer Fl	1.00
cabin air filter fp51	1.00
cabin air filter cf10285	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 53.89 Total: 233.89

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1400069 **Meter:** 28575 **In Date:** 01/03/2014 **Closed:** 01/24/2014
Problem: Pm service.Battery for remote and check all tires.

Work Completed

- P.m. Service.
- Test and replace key fob battery.
- Replace and balance four new tires.
- Complete wheel alignment.test drive.
- Shop Supplies

Parts Issued

Quantity

Syn0w20	4.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
31-24 Wiper Blades 2	1.00
Rear Composite Blade	1.00
Lithium Coin Cell	1.00
738274571 195-65r15 A	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 7.00

Comm: 0.00

Labor: 420.00 Parts: 435.13 Total: 855.13

Work Order: 1410263 **Meter:** 31151 **In Date:** 10/14/2014 **Closed:** 10/31/2014
Problem: Pm service.Safety rercall.

Work Completed

- Pm service.
- Inspect and replace missing jack and tools and secure.
- Rotate and balance all four tires.
- Transport vehicle to and from dealer for safety recall#ssc Eoe Reprogram motor generator and power management control Ecus
- Shop Supplies

Parts Issued

Quantity

Jack Sub Assy	1.00
Hub Nut Wrench	1.00
Pantog Handle	1.00
Syn0w20	4.00
Napagold Oil Filter	1.00
31-24 Wiper Blades 2	1.00
Wiper Blade	1.00
Rear Composite Blade	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00 Parts: 357.22 Total: 687.22

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1503991 **Meter:** 31165 **In Date:** 04/16/2015 **Closed:** 04/17/2015
Problem: Will not start (to be towed 4/17/15 am)

Work Completed

- Tow From: 810 Datura To: Lv shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

Work Order: 1504035 **Meter:** 31258 **In Date:** 04/20/2015 **Closed:** 04/30/2015
Problem: P.M. service and towed in for no start.

Work Completed

- Pm service.

- Test starting and charging system.battery failed loadtet after recharge.replace defective battery.

- Rotate and balance all four tires.

- Shop Supplies

Parts Issued

Quantity

Syn0w20 4.00

Napagold Oil Filter 1.00

Washer Fluid Concentr 1.00

31-24 Wiper Blades 2 1.00

Wiper Blade 1.00

Accufit Rear 1.00

Agm Battery 1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 256.33 Total: 496.33

Work Order: 1507992 **Meter:** 33195 **In Date:** 08/10/2015 **Closed:** 08/18/2015
Problem: Tow in,dead battery.

Work Completed

- Recharge battery and check charging system.good.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1508003 **Meter:** 33195 **In Date:** 08/10/2015 **Closed:** 08/11/2015
Problem: No start

Work Completed

- Tow From: 810 Datura To: Lv shop

Hours: 0.00 Comm: 104.15 Labor: 0.00 Parts: 0.00 Total: 104.15

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1511555 **Meter:** 35038 **In Date:** 11/12/2015 **Closed:** 11/24/2015
Problem: Pm service.Towed in for no start.

Work Completed

Parts Issued

Quantity

- Pm service.
- Diagnose no start condition.charge and test battery.ok.draw test Ok.charge rate at specs.test drive to recharge hybrid battery.
- Rotate and balance all four tires.
- Shop Supplies

Syn0w20	5.00
Napagold Oil Filter	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 42.86 Total: 282.86

Work Order: 1511573 **Meter:** 34765 **In Date:** 11/10/2015 **Closed:** 11/12/2015
Problem: No start

Work Completed

- Tow From: 810 Datura (human Servies parking lot) To: Lv shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1603634 **Meter:** 37224 **In Date:** 04/06/2016 **Closed:** 05/31/2016
Problem: Car starts only after trying a few times.Radio sometimes cut out.

Work Completed

Parts Issued

Quantity

- Scan for no codes,none present.test drive vehicle.test starting and charging system.good.unable to duplicate complain.
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1700763 **Meter:** 39440 **In Date:** 01/25/2017 **Closed:** 01/31/2017
Problem: P.M. service and tire pressure light on.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Syn0w20	5.00
Napagold Oil Filter	1.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Accufit Rear	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 49.06 Total: 229.06

Work Order: 1704383 **Meter:** 41060 **In Date:** 05/01/2017 **Closed:** 05/02/2017
Problem: Left rear tire has screw.

Work Completed

- Repair and balance left rear tire.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 2.00 Total: 62.00

Work Order: 1706815 **Meter:** 42281 **In Date:** 07/12/2017 **Closed:** 07/31/2017
Problem: P.M. service and recall 16V487.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires.
- Transport to and from dealer for recall 16v487.
- Shop Supplies

Parts Issued

Quantity

Syn0w20	5.00
Napagold Oil Filter	1.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
Accufit Rear	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 49.40 Total: 349.40

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1801652 **Meter:** 46306 **In Date:** 02/12/2018 **Closed:** 02/21/2018
Problem: P.M. service and spare on right rear .

Work Completed

- P.m. service.
- Replace all four tires ,due to damage and dry rot and age .balance and nitrogen fill all tires.
- Perform full front end alignment.
- Shop Supplies

Parts Issued

Quantity

Syn0w20	5.00
Napagold Oil Filter	1.00
Wiper Blades 24"	1.00
18" wiper blades	1.00
14in Exactfit-rear	1.00
Cabin Air Filter	1.00
738274571 195-65r15 A	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 545.20 Total: 935.20

Work Order: 1801754 **Meter:** 46134 **In Date:** 02/12/2018 **Closed:** 02/14/2018
Problem: Flat tire

Work Completed

- Tire Service 1000 45th (health) - Flat tire

Hours: 0.00

Comm: 70.25

Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 1808551 **Meter:** 48749 **In Date:** 08/20/2018 **Closed:** 08/29/2018
Problem: P.M. Service.

Work Completed

- P.m. service.
- Rotate and balance all four tires. Nitrogen fill tires and reset Tpms.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 49.06 Total: 229.06

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1901480 **Meter:** 50512 **In Date:** 02/07/2019 **Closed:** 02/20/2019
Problem: P.M. service and tire pressure light on .

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires .nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Tire Crayon	2.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 201.00

Parts: 52.82

Total: 253.82

Work Order: 1907203 **Meter:** 52688 **In Date:** 07/12/2019 **Closed:** 07/18/2019
Problem: P.M. service and detail .

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 201.00

Parts: 53.46

Total: 254.46

Work Order: 1907344 **Meter:** 52685 **In Date:** 07/16/2019 **Closed:** 07/16/2019
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00

Comm: 90.00

Labor: 0.00

Parts: 0.00

Total: 90.00

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 1913193 **Meter:** 55610 **In Date:** 12/31/2019 **Closed:** 01/08/2020
Problem: P.M. service , tire light on and detail .

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Resurface both front brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Repair left front tire . Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Washer Fluid Concentr	1.00
Cabin Air Filter	1.00
lube	1.00
Non-chlor Brake Clnr	2.00
Brake Pads	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 584.00 Parts: 145.41 Total: 729.41

Work Order: 2000163 **Meter:** 55601 **In Date:** 01/07/2020 **Closed:** 01/07/2020
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 2001308 **Meter:** 55876 **In Date:** 02/06/2020 **Closed:** 02/11/2020
Problem: Tire sensor fault light .

Work Completed

- Diagnose Tpms light on . Replace left front tire pressure sensor and balance tire . Retrain all four sensors . Retest .
- Shop Supplies

Parts Issued

Quantity

Sensor	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 126.06 Total: 199.06

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2004111 **Meter:** 60864 **In Date:** 04/24/2020 **Closed:** 05/05/2020
Problem: PM Service

Work Completed

- P.m. service.
- Replace two tires . Rotate and balance all four tires . Nitrofill all and reset Tpms .
- Replace rear brake rotors and pads . Service calipers . Flush and bleed brake system . Road test .
- Test and replace key fob battery . Replace missing front asset number .
- Perform complete four wheel alignment and road test .
- Shop Supplies

Parts Issued

Quantity

Syn0w20	5.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Tire Mic 195/65/15	2.00
B Fluid Dot 3-32oz	1.00
Brake Pad	1.00
Brake Rotor	2.00
Lithium Coin Cell	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.70

Comm: 0.00

Labor: 781.10 Parts: 620.00 Total: 1,401.10

Work Order: 2006424 **Meter:** 64835 **In Date:** 06/29/2020 **Closed:** 07/07/2020
Problem: P.M. service

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Both headlights discolored . Resurface and condition both headlight lens .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
14in Exactfit-rear	1.00
18" wiper blades	1.00
Wiper Bleade Anco	1.00
Cabin Air Filter	1.00
3m Tm Headlight Lens	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50 Parts: 88.98 Total: 490.48

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2006629 **Meter:** 64559 **In Date:** 07/06/2020 **Closed:** 07/06/2020
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.00 Labor: 0.00 Parts: 0.00 Total: 90.00

Work Order: 2008702 **Meter:** 66752 **In Date:** 08/05/2020 **Closed:** 08/31/2020
Problem: Damage to front bumper & right front fender liner

Work Completed

- Damage to front bumper & right front fender liner

Hours: 0.00 Comm: 666.00 Labor: 0.00 Parts: 0.00 Total: 666.00

Work Order: 2011267 **Meter:** 69823 **In Date:** 11/10/2020 **Closed:** 11/25/2020
Problem: P.M. service.

Work Completed

- Preventive Maint. Service
- Inspect all tires, r & l two new tires on front, rotate and speed balance all four, nitro fill all
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
18" wiper blades	1.00
14in Exactfit-rear	1.00
Wiper Blades 24"	1.00
Washer Fluid Concentr	1.00
Tire Mic 195/65/15	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 306.77 Total: 598.77

Work Order: 2012332 **Meter:** 70400 **In Date:** 12/11/2020 **Closed:** 12/17/2020
Problem: Warning lights on dash

Work Completed

- Scan computer, no active codes, visual inspection oil low. Found oil cooler leaking, Replace seals and filter, add oil, Clean excess oil from under carriage . test drive.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	4.00
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 30.31 Total: 139.81

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2012468 **Meter:** 70367 **In Date:** 08/26/2020 **Closed:** 12/16/2020
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34

Work Order: 2104553 **Meter:** 73777 **In Date:** 01/25/2021 **Closed:** 04/23/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 8.34 Labor: 0.00 Parts: 0.00 Total: 8.34

Work Order: 2105480 **Meter:** 73948 **In Date:** 05/14/2021 **Closed:** 05/26/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance all, nitro fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
18" wiper blades	1.00
Wiper Blades 24"	1.00
14in Exactfit-rear	1.00
Air Filter (gold)	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 67.89 Total: 286.89

Work Order: 2107249 **Meter:** 74350 **In Date:** 07/02/2021 **Closed:** 07/06/2021
Problem: key fob battery

Work Completed

- Replace key fob battery

Parts Issued

Quantity

Lithium Coin Cell	1.00
-------------------	------

Hours: 0.20 Comm: 0.00 Labor: 14.60 Parts: 3.97 Total: 18.57

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2107289 **Meter:** 74385 **In Date:** 07/06/2021 **Closed:** 07/08/2021
Problem: Towed in for NO START

Work Completed

- Charge battery fully . Test battery and charging system . R&r defective battery . Perform draw test dome lights left on
- Shop Supplies

Parts Issued

Quantity

Agm Battery	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 165.78 Total: 238.78

Work Order: 2107617 **Meter:** 74398 **In Date:** 07/13/2021 **Closed:** 07/14/2021
Problem: wipers not cleaning

Work Completed

- Check wiper operation . Replace wiper blades and retest.

Parts Issued

Quantity

Wiper Blades 24"	1.00
18" wiper blades	1.00

Hours: 0.20 Comm: 0.00 Labor: 14.60 Parts: 6.12 Total: 20.72

Work Order: 2107818 **Meter:** 74905 **In Date:** 07/06/2021 **Closed:** 07/19/2021
Problem: NO START

Work Completed

- Tow From: 225 S Congress Ave, Delray Bch To: Lv Shop

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2110075 **Meter:** 75249 **In Date:** 05/25/2021 **Closed:** 09/16/2021
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 7.85 Labor: 0.00 Parts: 0.00 Total: 7.85

4/3/2022
3:06:46 PM

Palm Beach County Fleet Management Asset Maintenance History
10180937 2010 TOYOTA PRIUS Car, Mid-Size, Hybrid

Work Order: 2113124 **Meter:** 75960 **In Date:** 12/13/2021 **Closed:** 12/16/2021
Problem: PM Service. Brakes feel soft

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Tpms Light On, Front Right Sensor Not Reading R&r Sensor Balance And Rotate All Tires With Nitro Fill
- Operator Complaint Soft Brake, Test Drove Vehicle Normal Operation, Cant Dublicate Concern At This Time
- Shop Supplies

Washer Fluid Concentr	1.00	
Wiper Blades 24"	1.00	
18" wiper blades	1.00	
14in Exactfit-rear	1.00	
Napagold Oil Filter	1.00	
Syn0w20	3.00	
Sensor	1.00	
Shop Supplies	1.00	
Labor: 328.50	Parts: 119.50	Total: 448.00

Hours: 4.50

Comm: 0.00

Work Order: 2201401 **Meter:** 76678 **In Date:** 02/07/2022 **Closed:** 02/11/2022
Problem: Bad battery in remote.Had to drive to 345 South Congress Ave. to jump start and drive back vehicle to SR Shop

Work Completed

Parts Issued

Quantity

- Drive to 345 s congress ave to jump start & drive back vehicle to shop for repairs.
- Fully recharge battery, test battery & charging system. charging system & battery are ok at this time. Replace dead battery in Key Fob.
- Shop Supplies

Lithium Coin Cell	1.00	
Shop Supplies	1.00	
Labor: 200.75	Parts: 6.62	Total: 207.37

Hours: 2.75

Comm: 0.00

Work Order: 2202868 **Meter:** 77758 **In Date:** 03/16/2022 **Closed:** 03/16/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 106.35

Total Labor: 6,999.55

Total Comm: 1,529.63

Total Parts: 3,790.93