

4/4/2022
10:29:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10192544 2013 FORD F150 Pickup, 1/2 Ton

Total Hours: 110.55 Labor: 7,401.30 Parts: 4,817.19 Comm: 1,421.45 Charged: 13639.94

Work Order: 1305171 **Meter:** 335 **In Date:** 05/28/2013 **Closed:** 05/28/2013
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1400140 **Meter:** 4646 **In Date:** 01/07/2014 **Closed:** 02/10/2014
Problem: Pm service

Work Completed

- P.m. Service.

- Rotate and balance all tires.

- Transport vehicle to dealer for air bag light.(connector.)

- Shop Supplies

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 48.97 Total: 348.97

Work Order: 1407915 **Meter:** 9077 **In Date:** 08/11/2014 **Closed:** 08/27/2014
Problem: Pm service.

Work Completed

- Pm service.

- Rotate and balance all four tires.

- Transport vehicle to and from dealer for airbag warning light on intermittent.repair fretting in C219 conecctor.apply electric grease.

- Shop Supplies

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 37.22 Total: 337.22

Parts Issued	Quantity
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Floor Mat-2pc Rub Bk	1.00
Shop Supplies	1.00

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

4/4/2022
10:29:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10192544 2013 FORD F150 Pickup, 1/2 Ton

Work Order: 1812239 **Meter:** 44542 **In Date:** 11/30/2018 **Closed:** 12/10/2018
Problem: PM Service, Wipers stay on.

Work Completed

- P.m. service.
- Replace two tires . Rotate and high speed balance all four tires. Nitrofill all.
- Test and replace wiper switch assembly . Retest wiper operation .
- Replace front brake rotors and pads . resurface rear brake rotors and replace pads . Service all four brake calipers and parking brake shoes . Flush and bleed brake system . Road test.
- Complete front end alignment and road test.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Hankook P235 75r17 Dp At	2.00
Switch Asy	1.00
Brake Pad	1.00
Brake Pad	1.00
Brake Rotor	2.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 14.30

Comm: 0.00

Labor: 958.10

Parts: 983.41

Total: 1,941.51

4/4/2022
10:29:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10192544 2013 FORD F150 Pickup, 1/2 Ton

Work Order: 2007043 **Meter:** 58242 **In Date:** 07/20/2020 **Closed:** 07/29/2020

Problem: P.M. service , towed in for wrench light and recall 19S07 .

Work Completed

- P.m. service.
- Test and replace right side camper door struts . R&r defective hood latch assembly.
- Test and replace right side tag light bulb .
- Computer diagnose wrench light , code P2111 . Perform pinpoint test . R&r defective throttle body . Fabricate and install fuse 27 relocation kit . Per Tsb 15-0137 . Clear all codes and retrest .
- Pressure test and inspect cooling system . R&r leaking water pump and thermostat . Flush cooling system and refill . Replace water pump belt and A/c belt . Road test .
- Balance and rotate all four tires . Nitrofill all.
- Transport to and from dealer for recall19s07 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Latch Assy	1.00
Support	2.00
Boxed Miniatures	1.00
Fuse Relocate Kit	1.00
Throttle Body	1.00
Anti Freeze Motorcraft	1.00
V Belt	1.00
V Belt	1.00
Gasket	1.00
Gasket	1.00
Tmermostat Housing	1.00
Water Pump	1.00
Shop Supplies	1.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 745.71

Total: 1,950.21

Work Order: 2007134 **Meter:** 58158 **In Date:** 07/20/2020 **Closed:** 07/21/2020

Problem: No start/ PM

Work Completed

- Tow From: Jpp Next to Fuel Island To: Lv shop

Hours: 0.00

Comm: 96.00

Labor: 0.00

Parts: 0.00

Total: 96.00

4/4/2022
10:29:00 AM

Palm Beach County Fleet Management Asset Maintenance History
10192544 2013 FORD F150 Pickup, 1/2 Ton

Work Order: 2108537 **Meter:** 69768 **In Date:** 08/06/2021 **Closed:** 08/17/2021
Problem: PM Service. AC not cold

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Replaced left tail light assembly due to leak. Fabricate and install strobe into new light.
- Diagnose Ac not cooling. Found evaporator to be leaking. Replaced leaking evap, and condenser assemblies. Charged Freon to factory spec.
- Diagnose no start. Found to have faulty starter. R and R bad starter.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Engine Oil Stop Leak	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Freon Lv Shop 1	2.00
A/c Condenser	1.00
A/c Evaporator	1.00
Seal Kits	2.00
Kit O	1.00
Lamp Assembly	1.00
Starter	1.00
Shop Supplies	1.00

Hours: 16.90

Comm: 0.00

Labor: 1,233.70

Parts: 973.82

Total: 2,207.52

Work Order: 2202681 **Meter:** 76921 **In Date:** 03/10/2022 **Closed:**
Problem: PM Service.

Work Completed

- Preventive Maint. Service

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Work Order: 2203160 **Meter:** 76921 **In Date:** 03/23/2022 **Closed:** 03/23/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 110.55

Total Labor: 7,401.30

Total Comm: 1,421.45

Total Parts: 4,817.19