Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Total Hours: 1	107.80 Labor: 7,193.80	Parts: 4,490.24	Comm: 2,346.76		Charged		
Work Order: Problem:	1510754 M 1061 - Pre Delivery Inspe	eter: 338 ction		In Date: 10)/23/2015	Closed:	10/23/2015
Work Com	pleted						
- Pre Delive	ery Inspection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00		Total:	120.00
Work Order: Problem:	1601801 M P.M. service and tailgate	eter: 5211 liner loose.		In Date: 02	2/22/2016	Closed:	03/02/2016
Work Com	pleted		Parts Issued			Qı	ıantity
- P.m. Servi	ice.		5w20 Engine Oil				6.00
- Inspect ar	nd replace corroded traile	plud.fabricate and rewire.	Napagold Oil Filter	r			1.00
•	nd balance tires.	•	Washer Fluid Cond	entr			1.00
- Shop Sup	pplies		Used Fire X Refurb	ished			1.00
			Female Conn Sock	et			1.00
			Shop Supplies				1.00
	Hours: 4.50	Comm: 0.00	Labor: 270.00	Parts: 50.51		Total:	320.51
Work Order: Problem:	1601816 M 1 - Wash ticket(s) issued	eter: 5067		In Date: 02	2/22/2016	Closed:	02/22/2016
Work Com	pleted						
- 1 - Wash	ticket(s) issued						
	Hours: 0.00	Comm: 9.54	Labor: 0.00	Parts: 0.00		Total:	9.54
Work Order: Problem:	1604721 M damage to frt bumper	eter: 7463		In Date: 04	/08/2016	Closed:	05/04/2016
Work Com	pleted						
- damage t	to frt bumper						
3	Hours: 0.00	Comm: 989.42	Labor: 0.00	Parts: 0.00		Total:	989.42

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1606469 Meter: 9107 In Date: 06/24/2016 Closed: 06/24/2016

Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1607048 Meter: 9107 In Date: 07/13/2016 Closed: 07/20/2016

Problem: needs spare key

Work CompletedParts IssuedQuantity- Supply and program one keyford side key1.00- Shop SuppliesShop Supplies1.00Hours: 0.50Comm: 0.00Labor: 30.00Parts: 84.29Total: 114.29

Work Order: 1608549 Meter: 10913 In Date: 08/17/2016 Closed: 08/31/2016

Problem: P.M. service and install strobe lights.

Work Completed	Parts Issued	Quantity
- P.m. Service.	5w20 Engine Oil	6.00
- Install four corner strobe lights.fabricate and install wiring and switch	Napagold Oil Filter	1.00
- Replace damaged left head light assemble.	22" Wiper Blade	2.00
- Rotate and balance all tires.	Vtx609a Led Strobe Am	2.00
- Shop Supplies	Vtx609c Led Strobe Cl	2.00
- Shop Supplies	Fuse Holder	1.00
	Rocker Led Blk Ambe	1.00
	Headlamp Assy	1.00
	Floor Mat-2pc Rub Bk	1.00
	Shop Supplies	1.00
Hours: 11.50 Comm: 0.00	Labor: 690.00 Parts: 740.	60 Total: 1,430.60

Work Order: 1609656 Meter: 10913 In Date: 08/25/2016 Closed: 09/15/2016

Problem: damage to frt bumper & valance

Work Completed

- damage to frt bumper & valance

Hours: 0.00 Comm: 467.46 Labor: 0.00 Parts: 0.00 Total: 467.46

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Vork Order: 1700620	Meter:	16307		In Date:	01/20/2017	Closed:	01/31/2017
Problem: P.M. service.							
Work Completed			Parts Issued			Qı	uantity
- P.m. Service.			5w20 Engine Oil				7.00
- Rotate and balance tires.			Napagold Oil Filter				1.00
- Shop Supplies			22" Wiper Blade				2.00
			Used Fire X Refurbish	hed			1.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 42.	88	Total:	222.88
Nork Order: 1701975	Meter:	17997		In Date:	02/27/2017	Closed:	03/07/201
Problem: Left rear tire going flat.							
Work Completed			Parts Issued			Qı	ıantity
- Repair and balance left rear tire.			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: 1704948	Meter:	21266		In Date:	05/17/2017	Closed:	05/22/201
Problem: P.M. service.							
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter				1.00
- High speed balance tires.nitro filled tires.			5w20 Engine Oil				6.00
- Shop Supplies			Washer Fluid Concer	ntr			1.00
			22" Wiper Blade				2.00
			Shop Supplies				1.00
Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 27.	11	Total:	207.11
Work Order: 1706220 Problem: Right front tire has nail.	Meter:	23010		In Date:	06/23/2017	Closed:	06/30/2017
Work Completed			Parts Issued			Qı	uantity
- Repair and balance right front tire.			Shop Supplies				1.00
- Shop Supplies							
Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

				-				
Work Order: Problem:	1706543 Left front tire going flat.	Meter:	23199		In Date:	07/03/2017	Closed:	07/07/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair le	ft front tire and balance.nitrogen fill t	ires.		Shop Supplies				1.00
- Shop Sup	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:	1708863 PM Service.	Meter:	26041		In Date:	09/14/2017	Closed:	09/18/2017
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Rotate ar	nd high speed balance all four tires.			Napagold Oil Filter				1.00
- Shop Sup				Napagold Air Filter				1.00
	1			22" Wiper Blade				2.00
				Used Fire X Refurbisl	hed			1.00
				Shop Supplies				1.00
	Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 48.	20	Total:	228.20
Work Order: Problem:	1709223 Repair right rear tire.	Meter:	26291		In Date:	09/22/2017	Closed:	09/27/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair ric	ght rear tire ,rebalance. Nitro service.			Shop Supplies				1.00
- Shop Sup								
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:	1711642 Left rear tire going flat.	Meter:	28660		In Date:	11/28/2017	Closed:	11/29/2017
Work Com	pleted			Parts Issued			Qı	uantity
- Repair le	ft rear tire and balance .nitrogen fill ti	res.		Shop Supplies				1.00
- Shop Sup	•							
1	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00

Hours: 1.00

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: Problem:	1801392 P.M. service.	Meter:	31512		In Date:	02/05/2018	Closed:	02/08/2018
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. servi	ce.			5w20 Engine Oil				6.00
- Check all	tire sensors .replace right fr	ont sensors. progr	am all sensors and	Napagold Oil Filter				1.00
rotate and h	high speed balance all four	wheels.nitrofill.		22" Wiper Blade				2.00
- Shop Sup	pplies			Washer Fluid Conce	entr			1.00
				Tpms12 Sensor Tire	e Pr			1.00
				Tpms Sens Kit				1.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 18	1.79	Total:	421.79
	1804584 Left front tire going flat.	Meter:	34556		In Date:	05/02/2018	Closed:	05/04/2018
Work Com	pleted			Parts Issued			Qı	uantity
- Repair lef	t front tire and balance .nitr	ogen fill tires.		Shop Supplies				1.00
- Shop Sup	pplies							
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 2.0	0	Total:	62.00
Work Order: Problem:	1804987 Left rear tire flat.Check all t	Meter: ire pressures.	35417		In Date:	05/14/2018	Closed:	05/21/2018
Work Com	pleted			Parts Issued			Qı	uantity
- Repair lef	t rear tire and check all tires			Shop Supplies				1.00
- Shop Sup	pplies							

Labor: 60.00

Parts: 2.00

Total: 62.00

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1806223 Meter: 36737 In Date: 06/18/2018 Closed: 06/27/2018

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Replace four tires . High speed balance and nitroger	n fill all .	5w20 Engine Oil		6.00
- Complete front end alignment.		Used Fire X Refurb	ished	1.00
- Shop Supplies		Wd40 Spr		1.00
		22" Wiper Blade		2.00
		183114470 P245-	70r17	4.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 6.50	Comm: 0.00	Labor: 390.00	Parts: 874.54	Total: 1,264.54

Work Order: 1811350 Meter: 42108 In Date: 11/02/2018 Closed: 11/08/2018

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter	r	1.00
essure test cooling system. Replace water pump and thermostat. ace A/c belt and water pump belt. Flush and refill cooling system.test es. btate and balance all four tires. Nitrogen fill all.	Napa Quart 5w20		6.00	
·	ng system .test	22" Wiper Blade		2.00
drive.		V Belt		1.00
- Rotate and balance all four tires. Nitrogen fill all .	ystem . Replace water pump and thermostat . ter pump belt . Flush and refill cooling system .test four tires. Nitrogen fill all .	V Belt		1.00
- Shop Supplies		Gasket		1.00
		Tmermostat Housi	ng	1.00
		Anti Freeze Motor	craft	1.00
		Water Pump		1.00
		Shop Supplies		1.00
Hours: 8.10 Co	omm: 0.00	Labor: 542.70	Parts: 378.05	Total: 920.75

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1902991 Meter: 47593 In Date: 03/18/2019 Closed: 03/28/2019

Problem: PM Service

Work Completed	Parts Issued		Quantity
- P.m. service.	5w20 Engine Oil		7.00
P.m. service. Charge battery fully .test battery and charging system . Battery failed lot t . R&r defective battery . Rotate and balance all four tires . Nitrofill all tires and reset Tpms.	Napagold Oil Filter		1.00
test . R&r defective battery .	22" Wiper Blade		2.00
- Rotate and balance all four tires . Nitrofill all tires and reset Tpms.	Used Fire X Refurbish	ned	1.00
- Shop Supplies	Napagold Air Filter		1.00
	Battry Motorcraft		1.00
	Ford Triton Pvc Swc		1.00
	Shop Supplies		1.00
Hours: 4.00 Comm: 0.00	Labor: 268.00	Parts: 248.54	Total: 516.54

Work Order: 1907715 Meter: 53120 In Date: 07/25/2019 Closed: 07/30/2019

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	er	1.00
- Rotate and balance all four tires . Nitrofill all.		5w20 Engine Oil		6.00
- Shop Supplies		Washer Fluid Con-	centr	1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 201.00	Parts: 31.34	Total: 232.34

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 1912776 Meter: 59115 In Date: 12/13/2019 Closed: 12/18/2019

Problem: P.m. service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Replace cabin air filter and clean fresh air intake .		5w20 Engine Oil		6.00
- Replace two tires . Rotate and balance all four tires . Nitrofill	l all and reset	22" Wiper Blade		2.00
Tpms .		Washer Fluid Conc	entr	1.00
- Perform complete front end alignment and road test .		Napagold Air Filte	r	1.00
- Shop Supplies		Cabin Air Filter		1.00
		245/70/17 Tire Mic	ch	2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.00 Cor	mm: 0.00	Labor: 511.00	Parts: 527.42	Total: 1,038.42

Work Order: 2003287 Meter: 63417 In Date: 03/31/2020 Closed: 04/13/2020

Problem: Left rear tire flat.Left tail lamp bulb inop.

Work Completed		Parts Issued		Quantity
- Repair and balance left rear tire.nitrogen fill all.		Boxed Miniatures		3.00
- Test and replace left taillamp bulbs.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 6.30	Total: 115.80

10:39:21 AM

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Problem: P.M. Service. Work Completed - P.m. service Replace two tires . Balance and rotate all four tires . Nitrofi Tpms .	ill all and rocot	Parts Issued 5w20 Engine Oil			Qı	uantity
- Replace two tires . Balance and rotate all four tires . Nitrofi	ill all and roset	5w20 Engine Oil				,
•	ill all and rocot	9				7.00
•	o tires . Balance and rotate all four tires . Nitrofill all and reset					1.00
ipins.					2.00	
- Inspect and service rear differentail .		Used Fire X Refurbi	shed			1.00
- Diagnose engine misfire . Perform complete tune up . Rep	lace upper	245/70/17 Tire Mic	h			2.00
intake gaskets and all six spark plugs . Clear codes and retes						2.00
- Perform complete air intake decarb and cleaning , clean th Flush injectors .						1.00
- Perform complete front end alignment and road test .		Spark Plugs				6.00
- Shop Supplies		Intake Cleaner Kit			1.00	
- Shop Supplies		Motor Tune-up 16d	DΖ			1.00
		Throttle Body Clear	ner			1.00
		Shop Supplies				1.00
		Tire Disposal Fee				2.00
Hours: 13.20 Co	omm: 0.00	Labor: 963.60	Parts: 688	3.31	Total:	1,651.91

Problem: Left rear tire flat.

Work Completed		Parts Issued		Quantity
- Repair and balance left rear tire.		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 4.00	Total: 77.00

Hours: 2.50

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2009316 Problem: P.M. service and		70713		In Date:	09/16/2020	Closed:	09/22/2020
Work Completed			Parts Issued			Qı	uantity
- P.m. service.			Napagold Oil Filter	r			1.00
Check for leaks in tires . Rotate and balance all four tires . Nitrofill all.Shop Supplies		5w20 Engine Oil				6.00	
		22" Wiper Blade				2.00	
			Washer Fluid Conc	entr			1.00
			Shop Supplies				1.00
Hours:	3.00	Comm: 0.00	Labor: 219.00	Parts: 33.	85	Total:	252.85
Work Order: 2011967 Problem: Right rear tire go Work Completed		73618	Parts Issued	In Date:	12/02/2020		12/02/2020 uantity
•	palance . Nitro fill all and rese	et Toms .	Shop Supplies				1.00
- Shop Supplies							
Hours:	1.00	Comm: 0.00	Labor: 73.00	Parts: 4.0	0	Total:	77.00
Work Order: 2012098 Problem: Hesitates when		73798		In Date:	12/04/2020	Closed:	12/14/2020
Work Completed			Parts Issued			Qı	uantity
- Computer diagnose hesitation on accel . Computer diagnose . Perform power balance test . R&r defective spark plug and coil on number six		Ignition Coil				1.00	
		Spark Plugs				1.00	
cylinder . Clear codes and re	test . Road test .		Shop Supplies				1.00
- Shop Supplies							

Labor: 182.50

Parts: 142.02

Total: 324.52

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2101413 Meter: 76572 In Date: 02/05/2021 Closed: 02/16/2021

Problem: P.M. Service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		5w20 Engine Oil		6.00
- Check and replace cabin filter. Clean fresh air intake .		Napagold Oil Filte	er	1.00
- Rotate and speed balance all four, nitro fill		Used Fire X Refurb	oished	1.00
- Shop Supplies		Washer Fluid Cond	centr	1.00
		22" Wiper Blade		2.00
		Cabin Filter		1.00
		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 98.53	Total: 354.03

Work Order: 2103095 Meter: 76572 In Date: 02/12/2021 Closed: 03/19/2021

Problem: Damage to right front fender, right front door & rear bumper.

Work Completed

- Damage to right front fender, right front door & rear bumper.

Hours: 0.00 Comm: 870.79 Labor: 0.00 Parts: 0.00 Total: 870.79

Work Order: 2107985 Meter: 82046 In Date: 07/23/2021 Closed: 08/17/2021

Problem: P.M. Service

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- check,replaced defective trailer plug connector and fabricated wires	5w20 Engine Oil	6.00
needed	22" Wiper Blade	2.00
- check, found loose tool box due to missing screws, drilled holes in other	ner to Napagold Air Filter	1.00
resecure tool box	Steering Wheel Cover Large	1.00
- balance and rotate all 4 tires	Steering Wheel Cover Large	1.00
- Shop Supplies	trailer plug	1.00
	Napagold Air Filter	1.00
	Shop Supplies	1.00
Hours: 5.00 Comm: 0.00	Labor: 365.00 Parts: 85.52	Total: 450.52

Palm Beach County Fleet Management Asset Maintenance History 10199062 2015 FORD F150 Pickup, 1/2 Ton

Work Order: 2113360 Meter: 87744 12/17/2021 Closed: 12/23/2021 In Date: **Problem:** PM Service, Passenger mirror fell out. **Parts Issued** Quantity **Work Completed** Used Fire X Refurbished 1.00 - Preventive Maint, Service 2.00 22" Wiper Blade - rotate and balance all 4 tires nitro fill all Filter 1.00 - Mirror fell due to fatigue clips R&r mirror glass 5w20 Engine Oil 6.00 - R&i new brake pads, cut rotors, service calipers, flush and bleed brake system Test drive after completion Non-chlor Brake Clnr 1.00 - Shop Supplies Brk Fluid Dot 4-32oz 1.00 **Brake Pad** 1.00 1.00 seal **Shop Supplies** 1.00 Hours: 7.00 Comm: 0.00 Parts: 156.28 Total: 667.28 Labor: 511.00 Work Order: 2200139 **In Date:** 01/06/2022 **Closed:** 01/10/2022 **Meter:** 87800 Problem: NO BRAKE LIGHTS, NO TURN SIGNAL **Parts Issued Work Completed** Quantity **Boxed Miniatures** 2.00 - Inspect Rear Brake And Turnsignal Light Not Working; R&r Faulty Sockets And Bulbs. Recheck Lamps Ok And Repair Complete. 1.00 Socket Asy - Shop Supplies Stp Trn Tl Lgt Socket 1.00 **Shop Supplies** 1.00 Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 22.19 Total: 95.19 Work Order: 2202692 Meter: 90274 In Date: 03/11/2022 **Closed:** 03/11/2022 **Problem:** Transition Prep Charge **Work Completed** - Transition Prep Charge

Total Hours: 107.80 Total Labor: 7,193.80 Total Comm: 2,346.76 Total Parts: 4,490.24

Labor: 146.00

Parts: 0.00

Total: 146.00

Comm: 0.00

Hours: 2.00