- Inspect and service wrench.

Hours: 4.75

Comm: 0.00

- Shop Supplies

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 99.80 Labor: 6,526.50	Parts: 4,625.01	Comm: 90.40		Charged	: 11241.91	
Work Order: 1307101 Me Problem: 1061 - Pre Delivery Inspec	ter: 346		In Date:	07/16/2013	Closed:	07/16/2013
Work Completed						
- Pre Delivery Inspection						
- Wash Vehicle						
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 0.0	00	Total:	180.00
Work Order: 1400500 Me Problem: P.M. service.	ter: 4807		In Date:	01/15/2014	Closed:	01/29/2014
Work Completed		Parts Issued			Qı	uantity
- Perform pm service.		5w20 Engine Oil				6.00
- Rotate and balance all four tires.		Napagold Oil Filter				1.00
- Shop Supplies		Used Fire X Refurbis	shed			1.00
		Shop Supplies				1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 39	.37	Total:	264.37
Work Order: 1408226 Me Problem: Pm service.	ter: 9924		In Date:	08/19/2014	Closed:	08/29/2014
Work Completed		Parts Issued			Qı	uantity
- Pm service.		Napagold Oil Filter				1.00
- Rotate and balance all four tires.		5w20 Engine Oil				6.00

Napagold Air Filter

Wiper Blade

Brake Cleaner

Shop Supplies

Labor: 285.00

Parts: 42.29

1.00

2.00

1.00

1.00

Total: 327.29

Hours: 8.25

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1502879 Problem: Pm service.	Meter:	14336		In Date:	03/19/2015	Closed:	03/31/201
Work Completed			Parts Issued			Q	uantity
- Pm service.			5w20 Engine Oil				6.00
- Inspect and service winch.			Napagold Oil Filter				1.00
- Rotate and balance all four tires.			Wiper Blade				2.00
- Shop Supplies			Brake Cleaner				1.00
			Used Fire X Refurbis	shed			1.00
			Shop Supplies				1.00
Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 50.	.74	Total:	335.74
Work Order: 1510277 Problem: Pm service.	Meter:	20141		In Date:	10/09/2015	Closed:	10/27/201
Work Completed			Parts Issued			Q	uantity
- Pm service.			5w20 Engine Oil				6.00
- Inspect and service front winch.			Napagold Oil Filter				1.00
- Rotate and balance all four wheels.			Wiper Blade				2.00
- Shop Supplies			Washer Fluid Conce	ntr			1.00
			Shop Supplies				1.00
Hours: 4.75		Comm: 0.00	Labor: 285.00	Parts: 31.	.91	Total:	316.91
Work Order: 1605133 Problem: P.M. Service.	Meter:	25416		In Date:	05/17/2016	Closed:	05/27/2016
Work Completed			Parts Issued			Q	uantity
- P.m. Service.			5w20 Engine Oil				6.00
- Replace and balance four new tires.			22" Wiper Blade				2.00
- Inspect and service winch.			Napagold Oil Filter				1.00
- Complete wheel alignment.test drive.			Washer Fluid Conce	ntr			1.00
- Shop Supplies			P265 70r17 At/s				4.00
			Shop Supplies				1.00
			Tire Disposal Fee				4.00
H 0.05		0 000	1 1 405.00	D . 70	0.00	-	4 005 00

Comm: 0.00

Labor: 495.00

Parts: 790.02

Total: 1,285.02

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Problem: P.M. service and winch controler inop.

Work Completed		Parts Issued		Quantity
- P.m. Service.		Winch Remote		1.00
- Replace front brake rotors, calipers and pads.flu:	sh and bleed system.	5w20 Engine Oil		6.00
- Inspect and service winch.	·	Napagold Oil Filte	r	1.00
- Test battery and chargiong system.replace bad	battery.	Napagold Air Filte	er	1.00
- Rotate and balance tires.	•	22" Wiper Blade		2.00
- Shop Supplies		Used Fire X Refurb	pished	1.00
		B Fluid Dot 3-32o	Z	1.00
		Non-chlor Brake C	Clnr	2.00
		Brake Rotor		2.00
		Battery		1.00
		Front Caliper Mot	orcraft	1.00
		Front Caliper Motorcraft		1.00
		Brake Pads		1.00
		Winch Remote Co	ntrol	1.00
		Caliper Washer		4.00
		Shop Supplies		1.00
		Freight Charge		1.00
Hours: 9.75	Comm: 0.00	Labor: 585.00	Parts: 833.70	Total: 1,418.7

Work Order: 1710892 Meter: 36475 In Date: 11/02/2017 Closed: 11/16/2017

Problem: P.M. service.

Work Completed		Parts Issued		Qι	ıantity
- P.m. service.		5w20 Engine Oil			6.00
- Inspect and service power winch.		Napagold Oil Filter			1.00
- Rotate and balance four tires.		22" Wiper Blade			2.00
- Shop Supplies		Washer Fluid Concentr			1.00
		Shop Supplies			1.00
Hours: 4.75	Comm: 0.00	Labor: 285.00 F	Parts: 27.01	Total:	312.01

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1807664 Meter: 41465 In Date: 07/27/2018 Closed: 08/06/2018

Problem: PM Service, Strobe lights inop.

Work Completed		Parts Issued		Quantity
- P.m. service.	Macs Chain Cable	1.00		
- Test and replace defective trailer plug connector a	and wire as needed.	Napagold Oil Filte	r	1.00
- Replace missing pintle pin.		5w20 Engine Oil		6.00
- Inspect and service winch.		Used Fire X Refurb	oished	1.00
- Balance and rotate all four tires.		22" Wiper Blade		2.00
- Test strobe lights . Replace missing fuse . retest fo	r normal operation.	Socket		1.00
- Shop Supplies		Pintle Pin W/clip		1.00
		Shop Supplies		1.00
Hours: 6.55	Comm: 0.00	Labor: 393.00	Parts: 58.16	Total: 451.16

Work Order: 1812735 Meter: 44674 In Date: 12/14/2018 Closed: 12/31/2018

Problem: Replace tire.P.M. service.

Work Completed	Parts Issued	Quantity
- Replace two tires . Rotate and high speed balance all four tire:	. Nitrofill all. 265 70 R17 Tire	2.00
- P.m. service.	Napagold Oil Filter	1.00
- Inspect and service winch .	Napa Quart 5w20	6.00
- Perform complete front end alignment. Road test.	22" Wiper Blade	2.00
- Shop Supplies	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 8.25 Comr	0.00 Labor: 552.75 F	Parts: 525.40 Total: 1,078.15

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1908202 Meter: 49346 In Date: 08/07/2019 Closed: 08/19/2019

Problem: PM Service, Battery dead.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Charge battery fully . Test battery and charging system . Battery failed load	5w20 Engine Oil	6.00
test . R&r defective battery .	Washer Fluid Concentr	1.00
- Computer diagnose airbag light , code B0091 . Perform pinpoint test . R&r	22" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
- Computer diagnose airbag light , code B0091 . Perform pinpoint test . R&r 2 defective left front door harness . Clear code and retest . - Replace two worn tires . Rotate and balance all four tires . Nitrofill all . - Inspect and service winch .	Battery	1.00
- Inspect and service winch .	Wire Asy	1.00
- Shop Supplies	265 70 R17 Tire	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 9.25 Comm: 0.00	Labor: 619.75 Parts: 685.90	Total: 1,305.65

Work Order: 2003585 Meter: 52412 In Date: 04/09/2020 Closed: 04/15/2020

Problem: P.M. service and recall 19S07

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Rotate and balance all four tires . Nitrofill all		5w20 Engine Oil		6.00
- Transport to and from dealer for recall 19s07 .		22" Wiper Blade		2.00
- Shop Supplies		Ford Triton Pvc Sw	VC .	1.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 419.75	Parts: 51.49	Total: 471.24

Work Order: 2100351

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

01/12/2021 **Closed:** 01/21/2021

In Date:

Meter: 54315

Problem: This vehicle will come in for PM Service today. Thank you! **Parts Issued** Quantity **Work Completed** Used Fire X Refurbished 1.00 - Preventive Maint, Service 22" Wiper Blade 2.00 - Rotate and balance all four wheels and tires. Nitrogen fill all tires and reset Tpms. Napagold Oil Filter 1.00 - Front brake job. Front pads worn below min spec. Front rotors grooved. 5w20 Engine Oil 7.00 Replace front brake rotors, calipers, and pads. Lube slide pins, guides, pads Brk Fluid Dot 4-32oz 1.00 and caliper. Bleed air from brake system and top off fluid. Test drive to verify Non-chlor Brake Clnr 2.00 brakes. Front Caliper Motorcraft 1.00 - Steps rusting off on both sides. Remove old steps and mounts. Use diegrinder to cut 1 rusted bolt off. Install new step hardware and properly Front Caliper Motorcraft 1.00 secure steps to truck. Verify all bolts aretight and steps are sturdy. Front Brake Pad 1.00 - Shop Supplies 2.00 Front Rotor Motorcraft Step Asy 1.00 **Shop Supplies** 1.00 Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 1,125.96 Total: 1,837.71

Work Order: 2108641 Meter: 55618 In Date: 08/10/2021 Closed: 08/17/2021

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection.	ned P.m. Service & Inspection.		er	1.00
- Performed Tire Rotation Balance Reset Tpms.		Napagold Oil Filter		1.00
- Performed Service & Inspection On Winch.		5w20 Engine Oil		6.00
- Shop Supplies		22" Wiper Blade		2.00
		Shop Supplies		1.00
Hours: 4.75	Comm: 0.00	Labor: 346.75	Parts: 33.54	Total: 380.29

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2200414 Meter: 55634 In Date: 01/12/2022 Closed: 01/18/2022

Problem: Towed in for no start

Work CompletedParts IssuedQuantity- Diagnose, bad battery, replace battery, service cables and check for draws.Battery1.00OkShop Supplies1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 111.79 Total: 184.79

Work Order: 2200528 Meter: 55618 In Date: 01/12/2022 Closed: 01/18/2022

Problem: no start

Work Completed

- Tow From: Jpp next to fuel Island To: Lv shop

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2202677 Meter: 55634 In Date: 03/10/2022 Closed: 03/17/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Performed P.m. Service & Inspection.	Napagold Oil Filter		1.00	
- Performed Tire Rotation Balance.		5w20 Engine Oil		6.00
- Performed Service & Inspection On Winch.		22" Wiper Blade		2.00
- Removed Both Rear Brake Pads, Rotors & Calipers. Resurfaced Both Rear Brake Rotors, Replaced Both Rear Brake Calipers And Pads. Bleed & Flush	Used Fire X Refurbished Non-chlor Brake Clnr		1.00 1.00	
				Entire Brakes, Test Drove Vehicle And Burnish Bra
- Shop Supplies		Brake Pads		1.00
		Brake Caliper Brake Caliper		1.00
				1.00
		Shop Supplies		1.00
Hours: 8.75	Comm: 0.00	Labor: 638.75	Parts: 217.76	Total: 856.51

Palm Beach County Fleet Management Asset Maintenance History 10192576 2013 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2203213 Meter: 55634 In Date: 03/25/2022 Closed: 03/25/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 99.80 Total Labor: 6,526.50 Total Comm: 90.40 Total Parts: 4,625.01