Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Total Hours: 106.65	Labor: 6,910.75	Parts: 5,104.89	Comm: 2,695.43	Charged: 14711.07

Work Order: 1405461 Meter: 350 In Date: 06/04/2014 Closed: 06/04/2014

Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1411102 Meter: 5083 In Date: 11/05/2014 Closed: 11/18/2014

Problem: Pm service.

Work Completed		Parts Issued		Quantity
- Pm service.		5w20 Engine Oil		6.00
- Rotate and balance all four tires.		Napagold Oil Filter		1.00
- Shop Supplies		Washer Fluid Conce	entr	1.00
		Floor Mat-2pc Rub	Bk	1.00
		Stg Wheel Cov - Fo	rd	1.00
		Used Fire X Refurbi	shed	1.00
		Shop Supplies		1.00
Hours: 3.75	Comm: 0.00	Labor: 225.00	Parts: 85.94	Total: 310.94

Work Order: 1504680 Meter: 11080 In Date: 05/07/2015 Closed: 05/20/2015

Problem: P.M. Service.Recall #14C10/14V-710.

Work Completed			Parts Issued		Quantity
- Pm service.			5w20 Engine Oil		6.00
- Inspect and service winch	٦.		Napagold Oil Filte	er	1.00
- Rotate and balance all fo	ur tires.		Wiper Blade		2.00
- Transport vehicle to and	from deale	r for safety recall #14c10	Shop Supplies		1.00
- Shop Supplies					
Hours	: 6.75	Comm: 0.00	Labor: 405.00	Parts: 30.19	Total: 435.19

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1512018 Meter: 17097 In Date: 11/24/2015 Closed: 11/30/2015

Problem: FLat tire on Right Front

Work Completed

- Tire Service 195 North Off of Congress Off Ramp (boca Raton) - Flat tire on

Right Front

Hours: 0.00 Comm: 66.34 Labor: 0.00 Parts: 0.00 Total: 66.34

Work Order: 1512867 Meter: 17850 In Date: 12/21/2015 Closed: 01/19/2016

Problem: Pm service.Check tires.

Work Completed		Parts Issued		Quantity
- Pm service.- Repair right front tire.rotate and balance all four.- Inspect and service winch.		5w20 Engine Oil	5w20 Engine Oil Napagold Oil Filter	
		Napagold Oil Filte		
		Napagold Air Filter		1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	oished	2.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 70.31	Total: 415.31

Work Order: 1608243 Meter: 24845 In Date: 08/10/2016 Closed: 08/30/2016

Problem: P.M. service and body damage to rear of truck and detail.

Work Completed		Parts Issued		Quantity
- P.m. Service.		5w20 Engine Oil		6.00
- Replace broken left rear lamp assemble.fabricate and inst	tall strobe.	Napagold Oil Filte	r	1.00
- Inspecat and service winch.		Used Fire X Refurbished		1.00
- Rotate and balance all tires.		Washer Fluid Cond	centr	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Lamp Assembly		1.00
		Shop Supplies		1.00
Hours: 5.75	Comm: 0.00	Labor: 345.00	Parts: 201.83	Total: 546.83

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1609414 Meter: 24845 In Date: 08/18/2016 Closed: 09/09/2016

Problem: Damage to left rear fender, tail gate & rear bumper

Work Completed

- Damage to left rear fender, tail gate & rear bumper

Hours: 0.00 Comm: 1,831.30 Labor: 0.00 Parts: 0.00 Total: 1,831.30

Work Order: 1703184 Meter: 31196 In Date: 03/30/2017 Closed: 04/12/2017

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. Service.	Napagold Oil Filter	1.00
- Test battery and charging systemrecharge and retest battery, fail	load 5w20 Engine Oil	7.00
test.replace defective battery.	22" Wiper Blade	2.00
- Replace both leaking front struts.	Napagold Air Filter	1.00
- Replace and balance four new tires.	Washer Fluid Concentr	1.00
- Complete wheel alignment.test drive.	Battery 65	1.00
- Inspect and service winch.	235 75r17 Adventure	4.00
- Shop Supplies	Front Shok Asober	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours: 11.25 Comm:	0.00 Labor: 675.00 Parts: 1,233.25	Total: 1,908.25

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1708580 Meter: 35375 In Date: 08/30/2017 Closed: 09/07/2017

Problem: P.M. service.

Work Completed		Parts Issued		Quantity
- P.m. service. Install new hitch pin with locking pin ,due to n	nissing .	5w20 Engine Oil		7.00
- Rotate and balance four tires.		Napagold Oil Filter		1.00
- Inspect and service power winch.		Used Fire X Refurb	ished	1.00
- Shop Supplies		Washer Fluid Conc	entr	1.00
		22" Wiper Blade		2.00
		Hitch Pin Lock		1.00
		Stg Wheel Cov - Fo	ord	1.00
		Floor Mat-2pc Rub	Bk	1.00
		Shop Supplies		1.00
Hours: 4.75 Co	omm: 0.00	Labor: 285.00	Parts: 100.94	Total: 385.94

Work Order: 1804250 Meter: 42879 In Date: 04/24/2018 Closed: 05/03/2018

Problem: P.M. service and left rear tire has nail in it.

Work Completed	Parts Issued	Quantity
- P.m. service.	5w20 Engine Oil	6.00
- Pressure test and inspect cooling system .flush and refill with new	Napagold Oil Filter	1.00
antifreeze.	22" Wiper Blade	2.00
- Replace rear differential pinion seal .inspect and service rear different	al. Used Fire X Refurbished	1.00
- Remove left front seat for repair and reinstall .	Tire Crayon	1.00
- Rotate and high speed balance all four tires. Repair right front tire.	Napagold Air Filter	1.00
- Shop Supplies	Anti Freeze Motorcraft	2.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	1.00
	Ptex Ultra Grey 3oz	1.00
	Seal Asy	1.00
	Seat R And R	1.00
	Shop Supplies	1.00
Hours: 10.65 Comm: 0.00	Labor: 639.00 Parts: 458.56	Total: 1,097.56

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Problem: P.M. service and drivers door ajar light staying on .

Work Completed	Parts Issued	Quantity
- P.m. service .	Napagold Oil Filter	1.00
- Pinpoint test door ajar light. Remove left front door panel to replace	e door 5w20 Engine Oil	6.00
harness assembly.	22" Wiper Blade	2.00
- Resurface front rotors .replace brake pads and service calipers . Flus	h and Washer Fluid Concentr	1.00
bleed brake system .road test.	Wire Asy	1.00
- Inspect and service winch.	Brake Pad	1.00
- Rotate and balance all four tires.	Non-chlor Brake Clnr	1.00
- Shop Supplies	B Fluid Dot 3-32oz	1.00
	Brk Fluid Dot 4-12oz	1.00
	Shop Supplies	1.00
Hours: 10.75 Comm: 0.00	Labor: 645.00 Parts: 126.91	Total: 771.91

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1902788 Meter: 52997 In Date: 03/13/2019 Closed: 04/03/2019

Problem: P.M. service and damage to left front fender and door .

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	r	1.00
- Inspect and service winch.replace damaged ca	able.	5w20 Engine Oil		6.00
- Resurface rear brake rotors, service and lube c	alipers.replace rear	Napagold Air Filte	er	1.00
pads.flush and bleed system.		22" Wiper Blade		2.00
- Replace two gtires,rotate and balance all four.		Used Fire X Refurb	ished	1.00
- Completerv wheel alignment.test drive.		Clevis Slip Hk W Lt	tch	1.00
- Shop Supplies		Non-chlor Brake Clnr		1.00
		B Fluid Dot 3-32oz	7	1.00
		Fron Brake Pad		1.00
		Hankook P235 75r	17 Dp At	2.00
		235/75/17tire Grap	opler	2.00
		Winch Cable Fabri	cation	1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 12.75	Comm: 0.00	Labor: 854.25	Parts: 1,202.44	Total: 2,056.69

Work Order: 1904530 Meter: 52997 In Date: 03/28/2019 Closed: 04/26/2019

Problem: Damage to left front fender & door

Work Completed

- Damage to left front fender & door

Hours: 0.00 Comm: 707.40 Labor: 0.00 Parts: 0.00 Total: 707.40

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 1911557 Meter: 59727 In Date: 11/06/2019 Closed: 11/14/2019

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filte	r	1.00
- Test and replace defective trailer plug connector ar	nd rewire as needed .	5w20 Engine Oil		6.00
- Check battery and charging system after fully charg	ging battery . Battery	22" Wiper Blade		2.00
failed load test . R&r defective battery . Reset Bms wit	th scan tool .	Used Fire X Refurb	pished	1.00
- Replace two tires . Rotate and balance all four tires	. Nitrofill all.	trailer plug		1.00
- Diagnose slow to start . Inspect burnt fuse 27 . Insta	Battery		1.00	
per Tsb 15-0137 . Retest .		235/75/17tire Grap	ppler	2.00
- Shop Supplies		Fuse Relocate Kit		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 9.25	Comm: 0.00	Labor: 675.25	Parts: 658.40	Total: 1,333.65

Work Order: 2004836 Meter: 64502 In Date: 05/13/2020 Closed: 05/26/2020

Problem: P.M. service and wipers stay on at times .

Work Completed		Parts Issued		Quantity					
- P.m. service.		Napagold Oil Filter 5w20 Engine Oil Washer Fluid Concentr 22" Wiper Blade Switch Asy		1.00 6.00 1.00 2.00 1.00					
- Computer diagnose wipers steying on . R&r defective wiper									
wiper motor assembly . Retest and clear codes . - Rotate and balance all four tires . Nitrofill all. - Shop Supplies									
							Wiper Motor		1.00
							Shop Supplies		1.00
Hours: 6.75 Coi	mm: 0.00	Labor: 492.75	Parts: 281.17	Total: 773.92					

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2100709 Meter: 75981 In Date: 01/20/2021 Closed: 01/28/2021

Problem: This truck is coming in for PM Service. The AM / FM radio is also not working. Thank you for your help!

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Check all tires, R & I two new tires, rotate and speed balance all, nitro f	5w20 Engine Oil	6.00
- Check radio operation, R & I both front door speakers	Washer Fluid Concentr	1.00
- Inspect and service winch	22" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	235/75/17tire Grappler	2.00
	Speaker	2.00
	Drain Plug	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.25 Comm: 0.00	Labor: 529.25 Parts: 578.03	Total: 1,107.28

Work Order: 2109351 Meter: 80980 In Date: 08/27/2021 Closed: 09/08/2021

Problem: PM Service.left rear turning bulb out Left rear tire low 2 ignition keys made, detail

Work Completed	Parts Issued		Quantity
- Performed P.m. Service & Inspection.	rformed P.m. Service & Inspection. 5w20 Engine Oil		6.00
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.	Napagold Oil Filte	r	1.00
- L/r Turn Signal Bulb Inop, Check Power Signal & Ground. Power & Ground	Washer Fluid Concentr		1.00
Ok. Bulb Filament Broken Removed And Replaced.	22" Wiper Blade		2.00
- Performed Service & Inspection On Winch.	Napagold Air Filter Boxed Miniatures		1.00
- Program 2 Pats Keys And Check.			
- Shop Supplies	Ford Ignition Key Blank		2.00
	Shop Supplies		1.00
Hours: 6.25 Comm: 0.00	Labor: 456.25	Parts: 74.28	Total: 530.53

Palm Beach County Fleet Management Asset Maintenance History 10195521 2014 FORD F150 Pickup, 1/2 Ton, Ext Cab, 4X4

Work Order: 2109852 Meter: 80997 In Date: 09/08/2021 Closed: 09/13/2021

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 90.40 Labor: 0.00 Parts: 0.00 Total: 90.40

Work Order: 2111086 Meter: 82357 In Date: 10/14/2021 Closed: 10/14/2021

Problem: Drivers side tire keeps losing air. Repair or replacement needed. Requesting to wait at shop for repair.

Work Completed Parts Issued Quantity

- Repair left front tire and balance . Nitro fill all and reset Tpms . Shop Supplies 1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2204211 Meter: 89876 In Date: 04/20/2022 Closed: 04/20/2022

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 106.65 Total Labor: 6,910.75 Total Comm: 2,695.43 Total Parts: 5,104.89