

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 70.60 Labor: 4,796.80 Parts: 2,985.63 Comm: 96.00 Charged: 7878.43

Work Order: 1600519 **Meter:** 331 **In Date:** 01/15/2016 **Closed:** 01/15/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Minor weld repair or machining

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1606736 **Meter:** 4391 **In Date:** 07/01/2016 **Closed:** 07/12/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wd40 16oz	1.00
Shop Supplies	1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 26.62 Total: 206.62

Work Order: 1608157 **Meter:** 5193 **In Date:** 08/09/2016 **Closed:** 08/29/2016
Problem: Towed in no power wench light on.

Work Completed

- Transport vehicle to dealetr for defective throttle body.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1608248 **Meter:** 5012 **In Date:** 08/08/2016 **Closed:** 08/10/2016
Problem: Slow starting

Work Completed

- Tow From: Ocean Inlet Park (6990 N Ocean Blvd) To: Lv Shop

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1700702 **Meter:** 9214 **In Date:** 01/24/2017 **Closed:** 02/06/2017
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 42.58 Total: 222.58

Work Order: 1710648 **Meter:** 15473 **In Date:** 10/27/2017 **Closed:** 11/09/2017
Problem: PM Service, Rear camper hatch lock doesnt work.

Work Completed

- P.m. service.
- Check rear camper hatch lock.replace lock cylinder and key with new cylinder.
- Balance and rotate all four tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
"bolt" Lock Cyl Replacement	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 240.00 Parts: 91.55 Total: 331.55

Work Order: 1804611 **Meter:** 19992 **In Date:** 05/02/2018 **Closed:** 05/09/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and balance all four tires .
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 180.00 Parts: 26.71 Total: 206.71

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1812595 **Meter:** 25365 **In Date:** 12/11/2018 **Closed:** 01/17/2019
Problem: PM Service, Drivers door outside lock inop, Camper locks hard to open w/key, Side step missing piece

Work Completed

Parts Issued

Quantity

- P.m. service.
- Diagnose camper topper locks . Replace one lock and key . Lube and clean two other lock cylinders and retest . Replace missing end cap on left running board .
- Diagnose left front door lock cylinder binding lube . R&r binding ignition lock cylinder and key to truck . Retest .
- Test starting and charging systems . After fully charging battery ,battery failed load test . R&r defective battery.
- Mount and balance four new tires . Nitrogen fill all tires .
- Perform complete front end alignment . Road test.
- Shop Supplies

Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Step Cap	1.00
Lock Cylinder Ign	1.00
Battry Motorcraft	1.00
245/70/17 Tire Mich	4.00
Lock Cylinder	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 11.50

Comm: 0.00

Labor: 770.50

Parts: 1,306.72

Total: 2,077.22

Work Order: 1908603 **Meter:** 30760 **In Date:** 08/16/2019 **Closed:** 08/28/2019
Problem: P.M. service and topper locks hard to lock . Recalls 17S33 and 18S27 .

Work Completed

Parts Issued

Quantity

- P.m. service.
- Resurface rear brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Balance and rotate all four tires . Nitrofill all.
- Check and lube all three camper topper locks . Working as designed .
- Transport to and from dealer for recalls 17s33 and 18s27 .
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Ford Triton Pvc Swc	1.00
Used Fire X Refurbished	1.00
Brake Pad	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 603.00

Parts: 223.35

Total: 826.35

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2003668 **Meter:** 36298 **In Date:** 04/13/2020 **Closed:** 04/20/2020
Problem: P.M. service and rear camper top will not lock .

Work Completed

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Test and replace defective lock cylinder on camper topper rear door .
Retest and rekey .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00	
5w20 Engine Oil	6.00	
22" Wiper Blade	2.00	
Used Fire X Refurbished	1.00	
Cabin Air Filter	1.00	
Lock Cylinder	1.00	
Shop Supplies	1.00	
Freight Charge	1.00	
Labor: 328.50	Parts: 82.16	Total: 410.66

Hours: 4.50

Comm: 0.00

Work Order: 2011024 **Meter:** 40830 **In Date:** 11/02/2020 **Closed:** 11/12/2020
Problem: P.M. service.

Work Completed

- Preventive Maint. Service
- Cabin Ac Filter
- Rotate and balance all four wheels and tires. Nitrogen fill all tires and reset
tpms.
- Replace front bumper valence/ cover. Remove broken plastic clips and
install new bumper cover/insert.
- Trailer charging message illuminated on dash. replace shorted out trailer
plug with new, rewire and verify functions.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00	
5w20 Engine Oil	7.00	
22" Wiper Blade	2.00	
Washer Fluid Concentr	1.00	
Cabin Air Filter	1.00	
Cover	1.00	
trailer plug	1.00	
Shop Supplies	1.00	
Labor: 350.40	Parts: 147.58	Total: 497.98

Hours: 4.80

Comm: 0.00

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2104757 **Meter:** 44634 **In Date:** 04/28/2021 **Closed:** 05/14/2021

Problem: Coming in for PM Service. Thank you! and check side door locks .

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Reset Tpms.
- Removed And Replaced Both Front Brake Calipers, Brake Caliper Hoses, Front And Rear Brake Pads Then Rotors, Bleed And Flush Entire Brake System, Then Test Drove Vehicle And Burnish Brakes.
- Removed Both Driver And Passenger Side Camper Top Lock Cylinders, Clean Of Dirt And Debris Then Install New.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brk Fluid Dot 4-32oz	1.00
Non-chlor Brake Clnr	1.00
Brake Rotor	2.00
Brake Pad	1.00
Brake Hose	1.00
Brake Hose	1.00
Reman/ca	1.00
Reman/ca	1.00
Brake Rotor	2.00
Brake Pad	1.00
Lock Cylinder	2.00
Shop Supplies	1.00

Hours: 12.00

Comm: 0.00

Labor: 876.00

Parts: 713.29

Total: 1,589.29

Work Order: 2109698 **Meter:** 47732 **In Date:** 09/07/2021 **Closed:** 09/09/2021

Problem: Staff will bring in for battery. Had to jump start this morning, Thank you!

Work Completed

- Test battery, battery failed load test, replace battery, perform starting and charging system analysis, multiple battery voltage codes causing low alternator output, Clear codes, reset Bms. Retest good.

- Shop Supplies

Parts Issued

Quantity

Battry Motorcraft	1.00
Shop Supplies	1.00

Hours: 1.80

Comm: 0.00

Labor: 131.40

Parts: 139.86

Total: 271.26

5/2/2022
10:49:43 AM

Palm Beach County Fleet Management Asset Maintenance History
10199114 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2111676 **Meter:** 49007 **In Date:** 10/28/2021 **Closed:** 11/04/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Inspect Rear View Back Up Camera Blurry. R&r Faulty Rear View Mirror Camera Assembly And Rewire.
- Rotate And Balance Four Tires. Nitro Fill All .
- Shop Supplies

Hours: 7.00 Comm: 0.00

Parts Issued

Quantity

22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Backup Cam Kit w/mirror	1.00
Shop Supplies	1.00

Labor: 511.00 Parts: 183.23 Total: 694.23

Work Order: 2203291 **Meter:** 52443 **In Date:** 03/28/2022 **Closed:** 03/28/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 70.60

Total Labor: 4,796.80

Total Comm: 96.00

Total Parts: 2,985.63